

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 33021

USING DEPT NO:	500201	OPENED DATE:	05/29/2019 13:09:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2019 14:58:06	METER 1 - M:	111	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/30/2019 14:58:07	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	05/29/2019 13:10:40	05/29/2019 13:40:40	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: **243264** **2019 TOYOTA TUNDRA 4X4**

WORK ORDER NO: **33021**

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 33216

USING DEPT NO:	500201	OPENED DATE:	06/24/2019 08:39:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2019 07:28:06	METER 1 - M:	111	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	06/27/2019 07:28:08	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-031	INSTALL TONNEAU/BED COVER	DON	O	N	GARAGE	0.50	\$0.00	\$720.00	\$0.00	\$720.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	720.00	0.00	720.00
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-78-031	INSTALL TONNEAU/BED COVER	11901357	06/24/2019 14:36:16	06/24/2019 15:06:16	0.50	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-78-031	INSTALL TONNEAU/BED COVER	0001634184	TONNEAU COVER TRI-FOLD RIGID	720.00	1	\$720.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	97.50	2	\$195.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	80.60	2	\$161.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	97.50	(2)	(\$195.00)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	80.60	(2)	(\$161.20)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ROUND ROCKER SWITCH	ROUND ROCKER SWITCH	5.00	1	\$5.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ROUND ROCKER SWITCH	ROUND ROCKER SWITCH	5.00	(1)	(\$5.00)
					PARTS	720.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 33216

Work Order Notes

(LISAPATE) Install tonneau cover

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

14-78-031 - INSTALL TONNEAU/BED COVER

(LISAPATE) Tonneau cover installed

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 33331

USING DEPT NO:	500201	OPENED DATE:	07/08/2019 07:21:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/01/2019 11:49:01	METER 1 - M:	111	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2019 11:49:04	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	12.00	\$0.00	\$553.66	\$0.00	\$553.66

JOB COUNT: 1	WORK ORDER TOTAL:	12.00	0.00	553.66	0.00	553.66
--------------	-------------------	-------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	07/30/2019 07:00:00	07/30/2019 19:00:00	12.00	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709213	CABLE TIE 11 IN 100 PC WHT	6.18	(1)	(\$6.18)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709265	CABLE TIE 24 IN HD 50 PCS	28.11	1	\$28.11
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709265	CABLE TIE 24 IN HD 50 PCS	28.11	(1)	(\$28.11)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709222	CABLE TIE 4 IN MINI 100 PC BLK	1.95	1	\$1.95
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709228	CABLE TIE 8 IN 100 PC BLK	5.06	1	\$5.06
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709213	CABLE TIE 11 IN 100 PC WHT	6.18	1	\$6.18
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709265	CABLE TIE 24 IN HD 50 PCS	28.11	1	\$28.11
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1808PT	RING TERM 16-14 GA 5/16 50PCS	6.38	2	\$12.76
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81141S	PRIMARY WIRE 14 GA RED 100'	20.11	1	\$20.11
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81187S	PRIMARY WIRE 18 GA WHITE 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81184S	PRIMARY WIRE 18 GA GREEN 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81183S	PRIMARY WIRE 18 GA BLK 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81181S	PRIMARY WIRE 18 GA RED 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1593KT	ATM FUSE TAP BRASS	2.15	3	\$6.45
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81143S	PRIMARY WIRE 18 GA BLACK 100'	20.11	1	\$20.11
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	20.00	1	\$20.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.38	1	\$0.38
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	4.46	1	\$4.46
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5141A	3/8 CONVOLUTED TUBING 50FT	10.97	1	\$10.97

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ROUND ROCKER SWITCH	ROUND ROCKER SWITCH	5.00	1	\$5.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	97.50	2	\$195.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	80.60	2	\$161.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0963PT	INLINE FUSE HOLDER ATC 12GA	1.49	3	\$4.47
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709213	CABLE TIE 11 IN 100 PC WHT	6.18	1	\$6.18
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709228	CABLE TIE 8 IN 100 PC BLK	5.06	(1)	(\$5.06)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709228	CABLE TIE 8 IN 100 PC BLK	5.06	1	\$5.06
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709222	CABLE TIE 4 IN MINI 100 PC BLK	1.95	(1)	(\$1.95)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709222	CABLE TIE 4 IN MINI 100 PC BLK	1.95	1	\$1.95
					PARTS	553.66

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: **243264** **2019 TOYOTA TUNDRA 4X4**

WORK ORDER NO: **33331**

Work Order Notes

(LISAPATE) Install front and rear strobe lights

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) Installed strobes on front grill and in taillights. Wired up and installed on/off switch and momentary switch into dash.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 34118

USING DEPT NO:	500201	OPENED DATE:	09/16/2019 15:15:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2019 15:09:34	METER 1 - M:	1604	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/19/2019 15:09:36	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.64	\$0.00	\$0.00	\$0.00	\$0.00
14-02-003	INSTALL RUNNING BOARDS	DON	O	N	GARAGE	0.65	\$0.00	\$480.00	\$0.00	\$480.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	2.09	\$0.00	\$769.79	\$0.00	\$769.79

JOB COUNT: 4	WORK ORDER TOTAL:	3.88	0.00	1,249.79	0.00	1,249.79
--------------	-------------------	------	------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11310047	09/18/2019 10:23:47	09/18/2019 11:01:59	0.64	\$0.00
06-15	INSPECT STEERING	11310047	09/18/2019 07:00:00	09/18/2019 07:30:00	0.50	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	09/18/2019 06:04:14	09/18/2019 08:09:46	2.09	\$0.00
14-02-003	INSTALL RUNNING BOARDS	11213180	09/17/2019 06:34:05	09/17/2019 07:13:19	0.65	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23104	TIRE LT245/70R18 BFG KO2 A/T	191.94	4	\$767.76
14-02-003	INSTALL RUNNING BOARDS	T0798CC6TX	STEP BAR SET NFAB PREDATOR	480.00	1	\$480.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.29	7	\$2.03
					PARTS	1249.79

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 34118

Work Order Notes

(LISAPATE) Install special order running boards already here.

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) EH Inspected steering

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

14-02-003 - INSTALL RUNNING BOARDS

(LISAPATE) Installed running boards on both sides

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new A/T tires take off tires were kept

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 34723

USING DEPT NO:	500201	OPENED DATE:	11/01/2019 13:53:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/05/2019 09:40:40	METER 1 - M:	1718	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/05/2019 09:40:42	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.12	\$0.00	\$43.58	\$0.00	\$43.58

JOB COUNT: 1	WORK ORDER TOTAL:	1.12	0.00	43.58	0.00	43.58
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/01/2019 14:24:41	11/01/2019 15:14:46	0.83	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/01/2019 14:37:10	11/01/2019 14:54:32	0.29	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA4	FILTER- OIL	4.37	1	\$4.37
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	9	\$34.92
					PARTS	43.58

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 34723

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/JW. Coolant -34

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 36039

USING DEPT NO:	500201	OPENED DATE:	03/23/2020 10:24:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/24/2020 13:38:34	METER 1 - M:	1856	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2020 14:57:07	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.93	\$0.00	\$39.38	\$0.00	\$39.38

JOB COUNT: 1	WORK ORDER TOTAL:	0.93	0.00	39.38	0.00	39.38
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/24/2020 11:17:51	03/24/2020 11:48:39	0.51	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/24/2020 10:49:14	03/24/2020 11:14:22	0.42	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA4	FILTER- OIL	4.37	1	\$4.37
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	9	\$35.01
					PARTS	39.38

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 36039

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/JW

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 37169

USING DEPT NO:	500201	OPENED DATE:	07/23/2020 10:10:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/23/2020 14:18:05	METER 1 - M:	1954	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/27/2020 08:06:24	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.33	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/23/2020 14:16:52	07/23/2020 14:36:40	0.33	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 37169

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Did not drop oil at this time. Truck has only been 98 miles since last oil change. Checked fluids, battery and tire pressures. Update sticker. Coolant -35' JW/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 38666

USING DEPT NO:	500201	OPENED DATE:	12/15/2020 10:36:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2020 09:21:28	METER 1 - M:	2055	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2020 08:37:10	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.44	\$170.15	\$62.81	\$0.00	\$232.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.10	\$11.77	\$20.91	\$0.00	\$32.68

JOB COUNT: 2 WORK ORDER TOTAL: 1.54 181.92 83.72 0.00 265.64

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2020 14:52:12	12/15/2020 15:48:31	0.94	\$110.76
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	12/15/2020 14:45:54	12/15/2020 14:51:53	0.10	\$11.77
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2020 14:30:00	12/15/2020 14:45:35	0.26	\$30.65
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2020 14:00:23	12/15/2020 14:15:00	0.24	\$28.75
					LABOR	181.93

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.26	9	\$56.30
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA4	FILTER- OIL	6.51	1	\$6.51
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	20.91	1	\$20.91
					PARTS	83.72

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 38666

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 2055 Performed PM top and bottom side, completed checklist, vacuumed, washed and fueled up vehicle. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 39935

USING DEPT NO:	500201	OPENED DATE:	05/12/2021 08:52:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/13/2021 11:10:39	METER 1 - M:	2403	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/17/2021 12:49:04	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.24	\$0.00	\$0.00	\$31.24

JOB COUNT: 1	WORK ORDER TOTAL:	0.26	31.24	0.00	0.00	31.24
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/12/2021 10:58:25	05/12/2021 11:14:18	0.26	\$31.24
					LABOR	31.24

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 39935

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 2403. Vehicle has been driven 348 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH AB

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 41391

USING DEPT NO:	500201	OPENED DATE:	10/20/2021 14:51:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/26/2021 08:00:39	METER 1 - M:	3178	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/26/2021 14:05:58	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$22.62	\$0.00	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.80	\$46.88	\$0.00	\$115.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.73	86.50	69.50	2.00	158.00
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/21/2021 09:23:45	10/21/2021 09:23:45	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/21/2021 09:23:45	10/21/2021 09:23:45	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/21/2021 09:23:45	10/21/2021 09:32:45	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/21/2021 08:40:01	10/21/2021 09:15:00	0.58	\$68.80
				LABOR		86.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	9	\$40.37
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA4	FILTER- OIL	6.51	1	\$6.51
				PARTS		69.50

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 41391

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 3178 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 42784

USING DEPT NO:	500201	OPENED DATE:	03/31/2022 14:57:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2022 11:23:56	METER 1 - M:	3618	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2022 09:47:28	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.20	\$0.00	\$0.00	\$35.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.30	35.20	0.00	2.00	37.20
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/01/2022 08:32:36	04/01/2022 08:50:30	0.30	\$35.20
					LABOR	35.20

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 42784

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 440 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-3618

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 44544

USING DEPT NO:	500201	OPENED DATE:	09/01/2022 09:18:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/02/2022 07:39:26	METER 1 - M:	4438	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 09:17:37	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.44	\$51.95	\$23.19	\$0.00	\$75.14
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.03	\$121.31	\$0.00	\$0.00	\$121.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$41.04	\$65.02	\$0.00	\$106.06
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.28	\$33.27	\$18.75	\$0.00	\$52.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.10	247.57	106.96	5.00	359.53
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11310047	09/01/2022 14:41:35	09/01/2022 14:58:30	0.28	\$33.27
03-51-038	REPLACE NEW WIPER BLADES	11310047	09/01/2022 14:15:10	09/01/2022 14:41:35	0.44	\$51.95
66-PM-PMA	PERFORM OIL CHANGE	11310047	09/01/2022 13:07:31	09/01/2022 13:28:23	0.35	\$41.04
66-79-003	PERFORM SAFETY INSPECTION	11310047	09/01/2022 10:05:19	09/01/2022 11:07:00	1.03	\$121.31
				LABOR		247.57

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	9	\$51.98
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA4	FILTER- OIL	5.40	1	\$5.40
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	18.75	1	\$18.75
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
				PARTS		106.96

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 44544

Work Order Notes

(LISAPATE) PM--replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) Replaced wipers. EH

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Inspected vehicle. No issues found. Rotated tires while they were removed from the vehicle. Relearned tire positions. EH

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Mileage-4438

Topside-EH/JAW

Bottom-EH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EHOWELL) Replaced cabin filter. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 45813

USING DEPT NO:	500201	OPENED DATE:	01/17/2023 15:37:54	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	01/20/2023 10:05:55	METER 1 - M:	4934	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/20/2023 14:27:23	IN-SERVICE DATE:	05/29/2019				
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.79	\$93.78	\$13.58	\$0.00	\$107.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.79	93.78	13.58	5.00	112.36
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	01/19/2023 12:32:14	01/19/2023 13:19:55	0.79	\$93.78
LABOR						93.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-030	PERFORM TIRE PATCH	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.25	1	\$5.25
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	6.96	1	\$6.96
PARTS						13.58

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 45813

Work Order Notes

(EHANNAH) inspect left rear tire

Job Notes

06-17-001 - INSPECT TIRE - ADD AIR

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 4934 Repaired and rebalanced L/R tire. Rechecked for leak, all good. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 45963

USING DEPT NO:	500201	OPENED DATE:	01/27/2023 12:16:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/30/2023 09:24:46	METER 1 - M:	4957	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2023 10:28:46	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$26.94	\$0.00	\$0.00	\$26.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.23	26.94	0.00	5.00	31.94
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2023 14:49:02	01/27/2023 15:02:44	0.23	\$26.94
LABOR						26.94

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 45963

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 517 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 46141

USING DEPT NO:	500201	OPENED DATE:	02/14/2023 08:11:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2023 09:54:25	METER 1 - M:	4957	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/16/2023 10:53:04	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-34-029	RECALL DAYTIME RUNNING BULB/ASS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-34-029	RECALL DAYTIME RUNNING BULB/ASSY	11076422	6193366		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	02/16/2023 07:00:00	02/16/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 46141

Work Order Notes

(EHANNAH) Recall on headlights- transport to Toyota

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Toyota by CW

17-34-029 - RECALL DAYTIME RUNNING BULB/ASSY

(LISAPATE) Tuscaloosa Toyota completed recall installed a wire

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 47217

USING DEPT NO:	500201	OPENED DATE:	05/31/2023 09:00:36	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2023 10:46:17	METER 1 - M:	6697	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2023 08:54:48	IN-SERVICE DATE:	05/29/2019				
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.28	\$24.08	\$0.00	\$29.36
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.10	\$11.64	\$0.00	\$0.00	\$11.64
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.89	\$74.93	\$0.00	\$110.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.26	\$30.94	\$0.00	\$0.00	\$30.94

JOB COUNT: 5	WORK ORDER TOTAL:	0.71	83.75	99.01	5.00	187.76
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/31/2023 14:35:04	05/31/2023 14:37:45	0.04	\$5.28
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/31/2023 14:30:00	05/31/2023 14:34:50	0.08	\$9.51
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/31/2023 14:01:35	05/31/2023 14:15:00	0.22	\$26.39
WA-00	WASH COMPLETE VEHICLE	12201267	05/31/2023 14:37:55	05/31/2023 14:53:39	0.26	\$30.94
06-15	INSPECT STEERING	12201267	05/31/2023 14:53:50	05/31/2023 14:59:45	0.10	\$11.64
LABOR						83.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	9	\$56.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA4	FILTER- OIL	7.74	1	\$7.74
PARTS						99.01

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 47217

Work Order Notes

(EHANNAH) pm- replace wipers - wash, makes noise when turning

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

06-15 - INSPECT STEERING

(GRCOOK) Inspected steering, and test drove and found no issues at this time,-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 6,697

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 48487

USING DEPT NO:	500201	OPENED DATE:	10/10/2023 08:36:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2023 10:07:34	METER 1 - M:	7358	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2023 13:01:59	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	2.18	\$256.81	\$24.08	\$0.00	\$280.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.49	\$0.00	\$0.00	\$22.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.25	\$29.53	\$0.00	\$0.00	\$29.53

JOB COUNT: 4	WORK ORDER TOTAL:	2.62	308.83	24.08	5.00	337.91
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/11/2023 13:00:00	10/11/2023 14:15:00	1.25	\$147.50
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/11/2023 09:30:00	10/11/2023 12:00:00	(2.50)	(\$295.00)
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/11/2023 14:30:00	10/11/2023 17:50:37	3.34	\$394.55
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/11/2023 14:30:00	10/11/2023 17:50:37	(3.34)	(\$394.55)
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/11/2023 09:30:00	10/11/2023 12:00:00	2.50	\$295.00
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/11/2023 08:19:25	10/11/2023 09:15:00	0.93	\$109.31
WA-00	WASH COMPLETE VEHICLE	11074414	10/11/2023 08:06:55	10/11/2023 08:21:56	0.25	\$29.53
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/11/2023 07:57:00	10/11/2023 08:08:26	0.19	\$22.49
					LABOR	308.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	(1)	(\$10.85)
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
					PARTS	24.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 48487

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Fluid check tires pressure and tread fc

(FCONTRER) Fluid check tires pressure and tread fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 49188

USING DEPT NO:	500201	OPENED DATE:	12/08/2023 09:09:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2023 09:34:08	METER 1 - M:	7358	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/18/2023 11:29:46	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$199.98	\$0.00	\$217.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.15	17.70	199.98	5.00	222.68
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11915538	12/08/2023 15:16:52	12/08/2023 15:25:52	0.15	\$17.70
					LABOR	17.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	27F-3	BATTERY AAP SILVER	199.98	1	\$199.98
					PARTS	199.98

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 49188

Work Order Notes

(LISAPATE) Replace battery is dead had to jump off

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EKIMBREL) RC REPLACED BATTERY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 50003

USING DEPT NO:	500201	OPENED DATE:	02/29/2024 08:32:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/01/2024 14:21:19	METER 1 - M:	8277	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2024 15:10:24	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.56	\$81.14	\$0.00	\$130.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.70	\$13.17	\$0.00	\$14.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$44.61	\$0.00	\$0.00	\$44.61

JOB COUNT: 4	WORK ORDER TOTAL:	0.81	95.87	94.31	5.00	195.18
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	03/01/2024 07:37:38	03/01/2024 08:00:19	0.38	\$44.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	03/01/2024 07:36:03	03/01/2024 07:36:55	0.01	\$1.70
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/01/2024 07:35:06	03/01/2024 07:35:40	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/29/2024 15:17:28	02/29/2024 15:42:06	0.41	\$48.45
				LABOR		95.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5667	CABIN FILTER	13.17	1	\$13.17
66-PM-PMA	PERFORM OIL CHANGE	PG5702F	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	9	\$61.83
				PARTS		94.31

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 50003

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) replaced cabin filter

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 51621

USING DEPT NO:	500201	OPENED DATE:	07/29/2024 07:56:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2024 16:19:56	METER 1 - M:	8873	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/31/2024 07:38:44	IN-SERVICE DATE:	05/29/2019	
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.48	\$0.00	\$24.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	24.48	5.00	29.48
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	1	\$11.25
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
PARTS						24.48

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 51621

Work Order Notes

(CHANNELL) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers JAW

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Checked all fluids and tires. JAW
Mileage-8873

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		243264		2019 TOYOTA TUNDRA 4X4			WORK ORDER NO:		52801			
USING DEPT NO:		500201		OPENED DATE:		11/13/2024 12:59:08		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		11/14/2024 09:01:48		METER 1 - M: 8873		METER 2 - H: 0		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		11/15/2024 09:46:06		IN-SERVICE DATE:		05/29/2019		
TECH SPEC NO:		19TOYTUNDRA		2019 Toyota Tundra 4x4			UNIT SERIAL NO:		5TFDW5F10KX833661			
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-53-006		REMOVE WORDMARKS/IDENTIFIERS		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 52801

Work Order Notes

(EHANNAH) remover wordmarks

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(GARAGE) removed wordmarks RC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 53323

USING DEPT NO:	500201	OPENED DATE:	01/08/2025 08:59:34	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2025 14:05:55	METER 1 - M:	8923	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/09/2025 12:39:41	IN-SERVICE DATE:	05/29/2019						
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4									
			UNIT SERIAL NO:	5TFDW5F10KX833661							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$75.45	\$0.00	\$75.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	75.45	5.00	80.45
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5702F	OIL FILTER	9.75	1	\$9.75
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	9	\$58.05
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						75.45

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 53323

Work Order Notes

(EHANNAH) pm- wipers- wash- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed safety inspection, found no issues at this time-GC
brake pads are 8mm front and rear
Miles, 8,923

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm, GC on bottom and JR on top side, FJ just did the air pressure in the tires, changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 8,923

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 54900

USING DEPT NO:	500201	OPENED DATE:	05/28/2025 10:11:55	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	COMPLETED	COMPLETED DATE:	06/02/2025 10:13:56	METER 1 - M:	12715	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	05/29/2019				
TECH SPEC NO:	19TOYTUNDRA	2019 Toyota Tundra 4x4		UNIT SERIAL NO:	5TFDW5F10KX833661				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/03/2025 11:52:00 By User: GLOBETTI

UNIT NO: 243264 2019 TOYOTA TUNDRA 4X4

WORK ORDER NO: 54900

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) rc performed prep for sale

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Jun 03 2025 11:52:00 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '5TFDW5F10KX833661') //Q=