Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

USING DEPT NO: 204902 OPENED DATE: 04/16/2020 08:55:31 LOCATION: GARAGE - University Automotive Services

WO STATUS: CLOSED **COMPLETED DATE:** 05/04/2020 10:55:26 **METER 1 - M:** 241 **METER 2 - H:** 5

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 05/04/2020 10:55:27
 IN-SERVICE DATE:
 04/10/2020

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO:** 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | <u>LABOR</u> | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|-------------|------------|-------------|---------|-----------|--------------|-----------------|------------|------------|
| 03-18-003 | REPLACE NEW WHEELS | DON | 0 | Ν | GARAGE | 1.39 | \$0.00 | \$1,529.84 | \$0.00 | \$1,529.84 |
| 14-52-003 | INSTALL RADIO | DON | 0 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$750.00 | \$750.00 |
| 14-53-035 | INSTALL BRUSH GUARD ASSY | DON | 0 | N | GARAGE | 2.61 | \$0.00 | \$538.79 | \$0.00 | \$538.79 |
| 14-55-040 | INSTALL BED MAT/LINER | DON | 0 | N | GARAGE | 0.00 | \$0.00 | \$109.99 | \$0.00 | \$109.99 |
| 14-78-038 | INSTALL UNDER CARRIAGE SKID PLAT | DON | 0 | N | GARAGE | 1.00 | \$0.00 | \$226.99 | \$0.00 | \$226.99 |
| 16-52-003 | TRANSPORT RADIO | DON | 0 | N | GARAGE | 1.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-00-001 | PERFORM NEW UNIT IN-SERVICE INSF | DON | Р | N | GARAGE | 0.50 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | 0 | N | GARAGE | 3.35 | \$0.00 | \$841.57 | \$0.00 | \$841.57 |

JOB COUNT: 8 WORK ORDER TOTAL: 9.85 0.00 3,247.18 750.00 3,997.18

| <u>Job Code</u> | Job Description | <u>Vendor No.</u> | Invoice No. | Purchase Order No. | | Total Cost |
|-----------------|--|-------------------|---------------------|---------------------|-----------------|------------|
| 14-52-003 | INSTALL RADIO | 11287280 | 002881 | | | \$750.00 |
| | | | | | COMML | 750.00 |
| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | Total Cost |
| 14-78-038 | INSTALL UNDER CARRIAGE SKID PLATES | 11310047 | 04/30/2020 07:00:00 | 04/30/2020 08:00:00 | 1.00 | \$0.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11310047 | 04/24/2020 09:30:00 | 04/24/2020 11:06:33 | 1.61 | \$0.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11310047 | 04/24/2020 07:30:36 | 04/24/2020 09:15:00 | 1.74 | \$0.00 |
| 03-18-003 | REPLACE NEW WHEELS | 11310047 | 04/23/2020 14:35:31 | 04/23/2020 15:58:44 | 1.39 | \$0.00 |
| 14-53-035 | INSTALL BRUSH GUARD ASSY | 11310047 | 04/23/2020 09:30:00 | 04/23/2020 10:11:04 | 0.68 | \$0.00 |
| 14-53-035 | INSTALL BRUSH GUARD ASSY | 11310047 | 04/23/2020 07:19:29 | 04/23/2020 09:15:00 | 1.93 | \$0.00 |
| 66-00-001 | PERFORM NEW UNIT IN-SERVICE INSPECTION | 11310047 | 04/17/2020 07:00:00 | 04/17/2020 07:30:00 | 0.50 | \$0.00 |
| 16-52-003 | TRANSPORT RADIO | 11901357 | 04/16/2020 09:03:48 | 04/16/2020 09:33:48 | 0.50 | \$0.00 |
| 16-52-003 | TRANSPORT RADIO | 11074414 | 04/16/2020 08:59:46 | 04/16/2020 09:29:46 | 0.50 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|------------------------------------|--------------|------------------------------|-------------------|----------|-------------------|
| 03-18-003 | REPLACE NEW WHEELS | 6413400 | WHEEL NUT CAPPED M14 OE GM | 2.67 | 32 | \$85.44 |
| 14-53-035 | INSTALL BRUSH GUARD ASSY | SHIPPING | SHIPPING AND HANDLING | 119.00 | 1 | \$119.00 |
| 14-53-035 | INSTALL BRUSH GUARD ASSY | WSA573785 | GRILLE GUARD WESTIN HDX | 419.79 | 1 | \$419.79 |
| 03-18-003 | REPLACE NEW WHEELS | 9597789 | WHEEL CENTER CAP OE BOWTIE | 50.29 | 4 | \$201.16 |
| 03-18-003 | REPLACE NEW WHEELS | 9597733 | WHEEL OE DESIGN ALMN 18X8 | 310.81 | 4 | \$1,243.24 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BFG A/T KO2 | 207.00 | 4 | \$828.00 |
| 14-78-038 | INSTALL UNDER CARRIAGE SKID PLATES | 23294258 | SKID PLATE/SHIELD KIT Z71 | 226.99 | 1 | \$226.99 |
| 14-55-040 | INSTALL BED MAT/LINER | MSCBEDMAT | BED MAT HD GM 6.6 BED | 109.99 | 1 | \$109.99 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.27 | 3 | \$0.81 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 63001 | 1/4 OZ STICK ON TAPE WEIGHT | 0.04 | 63 | \$2.52 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 2.56 | 4 | \$10.24 |
| | | | | | PARTS | 3247.18 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 36160

Work Order Notes

(IFALLS) Per Doug Phillips request to have satellite radio and cd player added to truck. Truck was not equipped with either (cd player or satellite radio) (IFALLS) Pre delivery inspection

Job Notes

03-18-003 - REPLACE NEW WHEELS

(IFALLS) EH INSTALLED 4 NEW WHEELS (RWINTERS) original 17" replacements 18"

14-52-003 - INSTALL RADIO

(IFALLS) Mobile Electronics installed new radio equipped with satellite radio and cd player

14-53-035 - INSTALL BRUSH GUARD ASSY

(IFALLS) EH/AB INSTALLED NEW FRONT BRUSH GAURD

14-55-040 - INSTALL BED MAT/LINER

(IFALLS) TRUCK SUPPLY INSTALLED BED MAT

14-78-038 - INSTALL UNDER CARRIAGE SKID PLATES

(IFALLS) EH installed new skid plates

16-52-003 - TRANSPORT RADIO

(IFALLS) Doug drove truck to Mobile electronics and SH/AG picked truck up

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(IFALLS) EH performed pre delivery inspection

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(IFALLS) EH MOUNTED AND BALANCED 4 NEW WHEELS AND TIRES

0.00

29.04

Work Order Charge Detail

JOB COUNT: 4

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

| UNIT NO: | 243732 | 2019 CHEVROLET 2500 TRU | CK 4X4 | WORK ORDER NO | : 36850 |
|------------------|---------------|-------------------------------|---------------------|---------------------------|----------------------------------|
| USING DEPT NO: | 204902 | OPENED DATE: | 06/18/2020 07:03:31 | LOCATION: GARAGE | - University Automotive Services |
| WO STATUS: | CLOSED | COMPLETED DATE: | 06/19/2020 15:23:21 | METER 1 - M : 5197 | METER 2 - H: 5 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 06/22/2020 07:47:31 | IN-SERVICE DATE: | 04/10/2020 |
| TECH SPEC NO: | 19CHEV25004X4 | 2019 Chevrolet Silverado 2500 | 4X4 | UNIT SERIAL NO: | 2GC2KREG8K1241891 |

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOR</u> | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|-------------|-----|------|---------|-----------|--------------|----------|------------|------------|
| 01-52-003 | ADJUST RADIO | DON | 0 | Ν | GARAGE | 0.50 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 09-17 | ALIGN TIRES, TUBES, LINERS & VALVE | DON | 0 | Ν | GARAGE | 0.29 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | Р | Ν | GARAGE | 0.34 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | Ν | GARAGE | 0.59 | \$0.00 | \$29.04 | \$0.00 | \$29.04 |

WORK ORDER TOTAL:

| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | Quantity | Total Cost |
|-----------|--------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 01-52-003 | ADJUST RADIO | 11170580 | 06/19/2020 07:00:00 | 06/19/2020 07:30:00 | 0.50 | \$0.00 |
| 09-17 | ALIGN TIRES, TUBES, LINERS & VALVES | 11310047 | 06/18/2020 09:30:00 | 06/18/2020 09:47:16 | 0.29 | \$0.00 |
| 09-17 | ALIGN TIRES, TUBES, LINERS & VALVES | 11310047 | 06/18/2020 09:27:15 | 06/18/2020 09:27:15 | 0.00 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 12052187 | 06/18/2020 07:51:15 | 06/18/2020 08:11:45 | 0.34 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 06/18/2020 07:15:46 | 06/18/2020 07:51:01 | 0.59 | \$0.00 |
| | | | | | LABOR | 0.00 |

1.72

0.00

29.04

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|-------------------|-----------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 3.88 | 7 | \$27.16 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 3.89 | (6) | (\$23.34) |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 3.89 | 6 | \$23.34 |
| 66-PM-PMA | PERFORM OIL CHANGE | 7060 | FILTER-OIL | 1.88 | 1 | \$1.88 |
| | | | | | PARTS | 29.04 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 36850

Work Order Notes

(LISAPATE) PM-rotate tires-align-connect XM radio

Job Notes

01-52-003 - ADJUST RADIO

(LISAPATE) Transferred old XM radio from old truck to the new truck. There was a \$15.00 transfer fee. Updated new credit card info, old CC was expired. Old radio ID E3TCE24M new radio ID DD2G7DWE

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) EH Performed alignment

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(JWRIGHT) Cross rotated tires with SH and adjusted tire pressures. SH torqued all lugs to spec. (jaw)

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Performed pm service AMG,EK,SH/JAW Coolant -35'

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

243732 **UNIT NO:** 2019 CHEVROLET 2500 TRUCK 4X4 **WORK ORDER NO:** 37327 **USING DEPT NO:** 204902 **OPENED DATE:** 08/13/2020 09:01:12 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 08/13/2020 10:59:22 **METER 1 - M:** 11046 WO STATUS: COMPLETED DATE: **METER 2 - H:** 5 **SCHEDULED** 08/14/2020 13:31:24 WO VISIT REASON: **CLOSED DATE: IN-SERVICE DATE:** 04/10/2020 **TECH SPEC NO:** 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO:** 2GC2KREG8K1241891 COMMERCIAL TOTAL COST JOB CODE **MATERIAL** JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS LABOR 31-17 ROTATE TIRES, TUBES, LINERS & VALV DON Ρ **GARAGE** 0.45 \$0.00 \$0.00 \$0.00 \$0.00 Ρ 66-PM-PMA PERFORM OIL CHANGE DON **GARAGE** 0.94 \$0.00 \$31.58 \$0.00 \$31.58 JOB COUNT: 2 **WORK ORDER TOTAL:** 1.39 0.00 31.58 0.00 31.58 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 31-17 ROTATE TIRES, TUBES, LINERS & VALVES 12052187 08/13/2020 10:23:16 08/13/2020 10:50:17 0.45 \$0.00 66-PM-PMA PERFORM OIL CHANGE 12052187 08/13/2020 09:30:00 08/13/2020 10:23:03 0.88 \$0.00 66-PM-PMA PERFORM OIL CHANGE 12052187 08/13/2020 09:11:32 08/13/2020 09:15:00 0.06 \$0.00 **LABOR** 0.00 **Job Code** Unit Price **Job Description** Part No. Description Quantity **Total Cost** 1 66-PM-PMA PERFORM OIL CHANGE C111 RED BRAKE CLEANER 2.47 \$2.47 66-PM-PMA PERFORM OIL CHANGE 5W30T 5W30 SYNTHETIC OIL THOMAS CAM2 3.89 \$27.23 66-PM-PMA PERFORM OIL CHANGE 7060 FILTER-OIL 1.88 \$1.88 **PARTS** 31.58

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 37327

Work Order Notes

(LISAPATE) PM-rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(JWRIGHT) Rotated tires and relearned tpms

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service and completed check list

0.00

Work Order Charge Detail

JOB COUNT: 3

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 37723

USING DEPT NO: 204902 OPENED DATE: 09/24/2020 08:22:02 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 09/24/2020 14:47:21
 METER 1 - M:
 15687
 METER 2 - H:
 5

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 09/25/2020 09:05:51
 IN-SERVICE DATE:
 04/10/2020

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO**: 2GC2KREG8K1241891

WORK ORDER TOTAL:

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|-------------|------------|-------------|---------|-----------|--------------|-----------------|------------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | Р | Ν | GARAGE | 0.62 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | Ν | GARAGE | 0.86 | \$0.00 | \$27.97 | \$0.00 | \$27.97 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC | DON | 0 | Ν | GARAGE | 0.02 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

1.50

0.00

27.97

| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | Quantity | Total Cost |
|-----------|---------------------------------------|--------------|---------------------|---------------------|----------|------------|
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC SYSTEM | 11213180 | 09/24/2020 14:14:53 | 09/24/2020 14:14:53 | 0.00 | \$0.00 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC SYSTEM | 11213180 | 09/24/2020 14:30:00 | 09/24/2020 14:31:16 | 0.02 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 12052187 | 09/24/2020 09:52:55 | 09/24/2020 10:23:42 | 0.51 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11074414 | 09/24/2020 09:53:10 | 09/24/2020 09:59:31 | 0.11 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 09/24/2020 09:15:00 | 09/24/2020 09:52:57 | 0.63 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 09/24/2020 09:13:05 | 09/24/2020 09:13:05 | 0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 09/24/2020 09:30:00 | 09/24/2020 09:43:53 | 0.23 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 09/24/2020 09:25:34 | 09/24/2020 09:25:34 | 0.00 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|-------------------|-----------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | CMP | MOBILE CM-P TUBE GREASE | 2.81 | 1 | \$2.81 |
| 66-PM-PMA | PERFORM OIL CHANGE | 7060 | FILTER-OIL | 1.88 | 1 | \$1.88 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 3.88 | 6 | \$23.28 |
| | | | | | PARTS | 27.97 |

27.97

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 37723

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(SHARBIN) SH JW Rotated tires

(JWRIGHT) Cross rotated tires. Kept tire pressures at 50psi. Torqued all lugs to 140ft lbs JAW,SH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° JAW/SH

(SHARBIN) JW/SH PERFORMED PM

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(MSIDES) Scanned vehicle and found no codes current or stored to the history. Found document number 5241564 on GM service information stated this about a rough idle concern with the 6.0L engine. MS

A dual-pulse injection strategy is utilized during engine cold start to reduce the time required to bring the catalytic converter up to operating temperature. This dual-pulse injection strategy lasts for about 60 seconds on cold start.

This process will cause the customer to see increased black smoke, soot, rough idle, or minimal misfires during cold start and should be considered normal.

To verify that the dual-pulse injection is causing the roughness or misfires with no codes set, you should watch injector pulse width with the scan tool during the concern. Dual pulse injector pulse width will be nearly double that of normal idle. After 20 seconds the pulse width will drop by about 50% and the engine idle will smooth out. This is considered normal operation and no repairs should be attempted.

This cold start strategy is enabled upon start up after the engine has soaked for sufficient time such that the catalytic converter requires rapid reactivation.

The high-pressure fuel pump test will run either, as soon as the dual pulse injection is completed, or during the first stop after the engine is warmed up above about 155 Degrees F (68 C). This can feel like a slight idle roughness as the high-pressure fuel pump is commanded to max pressure and then shut off to measure pressure decay. All of these concerns are considered normal and no repair attempts should be made.

| UNIT NO: | | 243732 20 |)19 CHE | VROLE | T 250 | 00 TRU | ICK 4X4 | | WORK C | ORDER NO | D: 3 | 8612 | |
|---|---------------|--|-----------|-------------------------------------|----------------|---------|----------------------|--|------------|---------------------|----------------------|--|------------|
| USING DEF WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | | OPENE COMPL CLOSE Chevrole | ETED D DATI | DATE: | 12/14/20 12/15/20 | 020 15:41:09 020 14:42:11 020 08:07:42 | | M: 23154 E DATE: | M 04/10/20 | ty Automotive s ETER 2 - H: 020 REG8K124189 | 5 |
| JOB CODE | <u> </u> | JOB DESCRIPTION | | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | R MAT | ERIAL C | OMMERCIAL | TOTAL COST |
| 66-17-033 | PERFOR | M TIRE ROTATION A | ND BRAKE | DON | 0 | Ν | GARAGE | 0.25 | \$29.14 | \$0.00 | \$0 | 0.00 | \$29.14 |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | N | GARAGE | 1.00 | \$118.10 | \$52.51 | \$0 | 0.00 | \$170.61 |
| JOB COUN | IT: 2 | | | | wo | RK ORI | DER TOTAL | .: 1.25 | 5 14 | 7.24 | 52.51 | 0.00 | 199.75 |
| Job Code | | Job Description | L | | <u>Em</u> | nployee | No. | <u>Start</u> | | <u>Finish</u> | | Quantity | Total Cost |
| 66-17-033 | PERFORM 1 | TRE ROTATION AND BR | AKE INSPE | CTION 1 | 2052187 | , | 1 | 2/10/2020 10:33:20 | 12/10/20 | 020 10:48:09 | | 0.25 | \$29.14 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 1: | 2052187 | , | 1 | 2/10/2020 09:33:01 | 12/10/20 | 020 10:33:04 | | 1.00 | \$118.10 |
| | | | | | | | | | | | | LABOR | 147.24 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | <u>Des</u> | scription | | Unit Price | Quantity | Total Cost |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 70 | 060 | | F | ILTER-OIL | | | 2.82 | 2 1 | \$2.82 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 5' | W30T | | 5 | W30 SYNTHETIC | OIL THOMAS | CAM2 | 5.84 | 4 6 | \$35.01 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | Α | NTIFRE | EZE DEX | (COOL A | NTIFREEZE-GM | | | 14.68 | 3 1 | \$14.68 |
| | | | | | | | | | | | | PARTS | 52.51 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 38612

Work Order Notes

(LISAPATE) PM-Rotate tires-Per Doug truck is pulling to the right

Job Notes

09-15 - ALIGN STEERING

(EHOWELL) Performed road test after tires were rotated and air pressures were adjusted. The vehicle is not pulling. Did not perform alignment. EH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Cross rotated tires and adjusted tire pressures. Rear tires were 25lbs low, If was 25lbs low and rf was 30lbs low. Found no leaks in the tires. Relearned tpms. JAW,SH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Greased front end. Topped off coolant found no leaks. Coolant -34°. JAW/JAW MILEAGE-23154

| UNIT NO: | O: 243732 2019 CHEV | | | VROLE | DLET 2500 TRUCK 4X4 | | | | | WORK ORDER NO: | | | |
|-----------|---|-----------------------|----------|------------------|---------------------|---------|---|---|--------------|--|------------|-----------------|------------|
| WO STATUS | WO STATUS: CLOSED COMMO VISIT REASON: SCHEDULED COMMO | | COMPL | MPLETED DATE: 02 | | | 21 14:26:27 21 11:07:29 21 13:07:10 | LOCATION: GARAGE METER 1 - M: 27654 IN-SERVICE DATE: UNIT SERIAL NO: | | E - University Automotive S METER 2 - H: 04/10/2020 2GC2KREG8K124189 | | 5 | |
| JOB CODE | | JOB DESCRIPTION | | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOF</u> | R MATE | ERIAL C | OMMERCIAL | TOTAL COST |
| 14-53-013 | INSTALL | FUEL ADDITIVE | | DON | 0 | N | GARAGE | 0.10 | \$11.80 | \$10.71 | \$0 | 0.00 | \$22.51 |
| 66-17-033 | PERFOR | M TIRE ROTATION AND | D BRAKE | DON | 0 | N | GARAGE | 0.39 | \$45.82 | \$0.00 | \$0 | 0.00 | \$45.82 |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | N | GARAGE | 1.00 | \$118.03 | \$43.67 | \$0 | 0.00 | \$161.70 |
| SO-05 | SCAN O | UT ELECTRONIC ENGI | NE EEC | DON | 0 | N | GARAGE | 0.89 | \$104.69 | \$0.00 | \$0 | 0.00 | \$104.69 |
| JOB COUN | IT: 4 | | | | WC | RK ORI | DER TOTAL: | 2.38 | 28 | 0.34 | 54.38 | 0.00 | 334.72 |
| Job Code | | Job Description | | | <u>En</u> | nployee | No. | <u>Start</u> | | <u>Finish</u> | | Quantity | Total Cost |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 1 | 2052187 | 7 | 02 | /09/2021 08:51:28 | 02/09/20 | 021 08:54:32 | | 0.05 | \$6.03 |
| 14-53-013 | INSTALL FU | EL ADDITIVE | | 1 | 2052187 | 7 | 02 | /09/2021 08:50:17 | 02/09/20 | 021 08:56:17 | | 0.10 | \$11.80 |
| 14-53-013 | INSTALL FU | EL ADDITIVE | | 1 | 2052187 | 7 | 02 | /09/2021 08:50:17 | 02/09/20 | 021 08:50:33 | | 0.00 | (\$0.52) |
| 14-53-013 | INSTALL FU | EL ADDITIVE | | 1 | 2052187 | 7 | 02 | /09/2021 08:50:17 | 02/09/20 | 021 08:50:33 | | 0.00 | \$0.52 |
| SO-05 | SCAN OUT | ELECTRONIC ENGINE EE | C SYSTEM | И 1 | 1213180 |) | 02 | /09/2021 07:21:58 | 02/09/20 | 021 08:15:12 | | 0.89 | \$104.69 |
| 66-17-033 | PERFORM | TIRE ROTATION AND BRA | KE INSPE | CTION 1 | 2052187 | 7 | 02 | /09/2021 07:07:17 | 02/09/20 | 021 07:30:35 | | 0.39 | \$45.82 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 1 | 2052187 | 7 | 02 | /08/2021 14:52:16 | 02/08/20 | 021 15:49:13 | | 0.95 | \$112.00 |
| | | | | | | | | | | | | LABOR | 280.34 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | Des | cription | | Unit Price | Quantity | Total Cost |
| 14-53-013 | INSTALL FU | EL ADDITIVE | | S | F16 | | SE | A FOAM 16OZ | | | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 7 | 060 | | FIL | TER-OIL | | | 2.82 | ! 1 | \$2.82 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 5 | W30T | | 5V | V30 SYNTHETIC (| OIL THOMAS | CAM2 | 5.84 | | \$40.85 |
| | | | | | | | | | | | | PARTS | 54.38 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 39055

Work Order Notes

(LISAPATE) PM-Check engine light on truck is running fine

Job Notes

14-53-013 - INSTALL FUEL ADDITIVE

(JWRIGHT) Added fuel additive

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Brakes are 12mm all around

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW MILEAGE-27654

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(MSIDES) Scanned vehicle with GM MDI scan tool and found code P0330 - Knock Sensor Circuit Bank 2. Noticed in the data history vehicle had been running about 7 minutes and the ECT was reading 163*F meaning the engine was not up to operating temperature. However the RPM reading was at 5881 which is just at the redline. Considering all these factors it is likely the code was caused due to pre-detonation of fuel, recommend adding a dealer recommended fuel additive. Printed a report with codes and all data to be scanned into work order. MS

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

243732 **UNIT NO: 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO:** 39832 **USING DEPT NO:** 204902 **OPENED DATE:** 04/29/2021 11:05:46 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 04/30/2021 15:06:23 COMPLETED DATE: **METER 1 - M**: 33571 **METER 2 - H:** 5 **WO VISIT REASON: SCHEDULED** 05/03/2021 15:02:30 **CLOSED DATE: IN-SERVICE DATE:** 04/10/2020 **TECH SPEC NO:** 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO:** 2GC2KREG8K1241891 JOB CODE **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS LABOR 66-PM-PMA PERFORM OIL CHANGE DON Ρ **GARAGE** 0.92 \$108.27 \$45.17 \$0.00 \$153.44 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.92 108.27 45.17 0.00 153.44 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 11901357 04/29/2021 12:08:49 04/29/2021 13:03:52 0.92 \$108.27 **LABOR** 108.27 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 66-PM-PMA OIL FILTER 4.22 \$4.22 PERFORM OIL CHANGE WIX57060 66-PM-PMA 5W30K 5W30 KENDALL QT 5.85 \$40.95 PERFORM OIL CHANGE **PARTS** 45.17

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 39832

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 33571 Completed PM bottomside, Josh was top side. JW/AMG Completed checklist. AMG

SCHEDULED

WO VISIT REASON:

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

04/10/2020

243732 **UNIT NO: 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO:** 40087

CLOSED DATE:

USING DEPT NO: 204902 **OPENED DATE:** 06/02/2021 13:54:20 **LOCATION:** GARAGE - University Automotive Services

CLOSED WO STATUS: 06/04/2021 09:32:06 **METER 1 - M**: 36223 **METER 2 - H:** 5 **COMPLETED DATE:**

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO:** 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|-------------|------------|-------------|---------|-----------|--------------|-----------------|------------|------------|
| 06-15 | INSPECT STEERING | DON | 0 | Ν | GARAGE | 0.13 | \$14.75 | \$0.00 | \$0.00 | \$14.75 |
| 09-15 | ALIGN STEERING | DON | 0 | N | GARAGE | 0.14 | \$16.98 | \$0.00 | \$0.00 | \$16.98 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | 0 | Ν | GARAGE | 1.16 | \$137.37 | \$1,251.72 | \$0.00 | \$1,389.09 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.74 | \$87.68 | \$48.53 | \$0.00 | \$136.21 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | Р | N | GARAGE | 0.01 | \$1.11 | \$12.36 | \$0.00 | \$13.47 |

06/10/2021 11:35:30

IN-SERVICE DATE:

| JOB COUN | IT: 5 | WORK ORDER TO | TAL: 2.19 | 257.89 | 1,312.61 | 0.00 | 1,570.50 |
|-----------|----------------------------------|---------------|---------------------|---------------------|----------|----------|------------|
| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | <u>(</u> | Quantity | Total Cost |
| 09-15 | ALIGN STEERING | 11310047 | 06/03/2021 14:30:00 | 06/03/2021 14:37:30 | | 0.13 | \$14.75 |
| 09-15 | ALIGN STEERING | 11310047 | 06/03/2021 14:13:52 | 06/03/2021 14:15:00 | | 0.02 | \$2.23 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 12052187 | 06/03/2021 13:00:00 | 06/03/2021 13:38:12 | | 0.64 | \$75.13 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 12052187 | 06/03/2021 12:02:45 | 06/03/2021 12:02:45 | | 0.00 | \$0.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 06/03/2021 11:24:35 | 06/03/2021 11:56:14 | | 0.53 | \$62.25 |
| 06-15 | INSPECT STEERING | 11074414 | 06/02/2021 15:33:37 | 06/02/2021 15:41:07 | | 0.13 | \$14.75 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11074414 | 06/02/2021 15:20:19 | 06/02/2021 15:20:53 | | 0.01 | \$1.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 06/02/2021 14:35:29 | 06/02/2021 15:20:04 | | 0.74 | \$87.68 |
| | | | | | | LABOR | 257.90 |

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|--------------|------------------------------|-------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30K | 5W30 KENDALL QT | 6.33 | 7 | \$44.31 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 4.22 | 1 | \$4.22 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | PA4486 | CABIN AIR ELEMENT | 12.36 | 1 | \$12.36 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 3.92 | 4 | \$15.66 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.48 | 5 | \$2.40 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BFG A/T KO2 | 307.50 | 4 | \$1,230.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 63001 | 1/4 OZ STICK ON TAPE WEIGHT | 0.06 | 61 | \$3.66 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

PARTS

1312.61

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 40087

Work Order Notes

(LISAPATE) PM-Replace 4 tires and align

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering and brakes. SH

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. No adjustments were needed. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced tires and balanced. Aired to spec. Torqued lugs to 140ft lbs. Relearned tpms. JAW,SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 36223. SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

LINIT NO:

243732

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

40828

WORK ORDER NO:

| OIIII IIO. | | ZOTO GITE VICOLET ZOOU TICO | OIX 47X4 | WORK ORDER NO. | 70020 | |
|----------------|--------|-----------------------------|---------------------|----------------------------|------------------------------|--|
| USING DEPT NO: | 204902 | OPENED DATE: | 08/24/2021 11:33:34 | LOCATION: GARAGE - Un | iversity Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/27/2021 09:01:40 | METER 1 - M : 43110 | METER 2 - H : 5 | |

WO VISIT REASON: SCHEDULED **CLOSED DATE:** 08/27/2021 14:11:39 **IN-SERVICE DATE:** 04/10/2020

2019 CHEVROLET 2500 TRUCK 4X4

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 UNIT SERIAL NO: 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|-------------|------------|-------------|---------|-----------|--------------|-----------------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | Р | Ν | GARAGE | 0.07 | \$7.83 | \$20.37 | \$0.00 | \$28.20 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, | DON | 0 | N | GARAGE | 0.40 | \$47.53 | \$0.00 | \$0.00 | \$47.53 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREE | DON | 0 | N | GARAGE | 0.47 | \$55.66 | \$9.92 | \$0.00 | \$65.58 |
| 66-17-017 | PERFORM BALANCE TIRES | DON | Р | N | GARAGE | 0.43 | \$50.71 | \$1.71 | \$0.00 | \$52.42 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE | DON | Р | N | GARAGE | 0.12 | \$14.29 | \$0.00 | \$0.00 | \$14.29 |
| 66-79-003 | PERFORM SAFETY INSPECTION | DON | Υ | N | GARAGE | 0.14 | \$16.91 | \$0.00 | \$0.00 | \$16.91 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.72 | \$85.52 | \$45.02 | \$0.00 | \$130.54 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC | DON | 0 | N | GARAGE | 2.36 | \$278.41 | \$0.00 | \$0.00 | \$278.41 |

JOB COUNT: 9 WORK ORDER TOTAL: 4.72 556.86 77.02 2.00 635.88

| Job Code | Job Description | Vendor No. | | Invoice No. | Purchase Order No. | | Total Cost |
|----------|----------------------|------------|---|-------------|--------------------|-------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | | | \$2.00 |
| | | | | | | COMML | 2.00 |

| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | Quantity | Total Cost |
|-----------|--|--------------|---------------------|---------------------|----------|------------|
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | 11170580 | 08/25/2021 15:12:07 | 08/25/2021 15:40:25 | 0.47 | \$55.66 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, VENT | 11170580 | 08/25/2021 14:47:41 | 08/25/2021 15:11:51 | 0.40 | \$47.53 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC SYSTEM | 11170580 | 08/25/2021 09:30:00 | 08/25/2021 11:51:34 | 2.36 | \$278.41 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC SYSTEM | 11170580 | 08/25/2021 09:21:30 | 08/25/2021 09:21:30 | 0.00 | \$0.00 |
| 66-79-003 | PERFORM SAFETY INSPECTION | 12052187 | 08/25/2021 07:25:43 | 08/25/2021 07:29:24 | 0.06 | \$7.24 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 08/25/2021 07:06:18 | 08/25/2021 07:25:33 | 0.32 | \$37.86 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 08/24/2021 15:17:14 | 08/24/2021 15:41:28 | 0.40 | \$47.66 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 12052187 | 08/24/2021 15:13:04 | 08/24/2021 15:17:03 | 0.07 | \$7.83 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | N 12052187 | 08/24/2021 15:05:36 | 08/24/2021 15:12:52 | 0.12 | \$14.29 |

| <u>Job Code</u> 66-17-017 | Job Description PERFORM BALANCE TIRES | Employee No. 12052187 | <u>Start</u> 08/24/2021 14:39:34 | <u>Finish</u> 08/24/2021 15:05:21 | | Quantity 0.43 | <u>Total Cost</u> \$50.71 |
|------------------------------|---------------------------------------|------------------------------|--|--------------------------------------|------------|------------------|------------------------------|
| 66-79-003 | PERFORM SAFETY INSPECTION | 12052187 | 08/24/2021 13:00:00 | 08/24/2021 13:04:55 | | 0.08 | \$9.67 |
| 66-79-003 | PERFORM SAFETY INSPECTION | 12052187 | 08/24/2021 12:40:01 | 08/24/2021 12:40:01 | | 0.00 | \$0.00 |
| | | | | | | LABOR | 556.86 |
| Job Code | Job Description | Part No. | Descr | iption | Unit Price | Quantity | Total Cost |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | RECYCLED FREON OZ | RECLAIMED FREON C |)Z | 0.14 | 10 | \$1.35 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 1 | 10.19 | 2 | \$20.37 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | R134AOZ | R134A FREON-OUNCE | Ē | 0.29 | 23 | \$6.56 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | ESTER OIL | A/C ESTER OIL OUNC | E | 1.01 | 2 | \$2.01 |
| 66-17-017 | PERFORM BALANCE TIRES | 63001 | 1/4 OZ STICK ON TAPE | E WEIGHT | 0.06 | 12 | \$0.72 |
| 66-17-017 | PERFORM BALANCE TIRES | WHEEL WEIGHT | WHEEL WEIGHT KNOO | CK ON | 0.50 | 2 | \$0.99 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | | 4.28 | 1 | \$4.28 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL | THOMAS CAM2 | 5.82 | 7 | \$40.74 |
| | | | | | | PARTS | 77.02 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 40828

Work Order Notes

(LISAPATE) replace wipers-Do annual SI-PM-Check engine light been coming on and off-Check a/c-rotate and balance tires

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(ABLACK) AB evacuated ac system and found it was 13 ounces low.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(ABLACK) AB performed evac and recharge. Found system was 13 ounces low. Vacuumed and passed the leak test. Used 2 ounces of ester oil with dye. Charged system back up to spec. Let vehicle run for a while and checked for leaks with a black light. Found no leaks.

66-17-017 - PERFORM BALANCE TIRES

(JWRIGHT) Balanced all 4 tires JAW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Relearned tpms sensors. Adjusted tire pressures and torqued lug nuts to spec. Front pads and rear pads are 12mm. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. No issues found. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. J

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(ABLACK) AB scanned out and found the ECM had no codes present and no freeze frame codes at all. Check engine light is not on. Scanned out the rest of the truck and found no codes

| UNIT NO: | NO: 243732 2019 CHI | | | | T 250 | 0 TRU | CK 4X4 | | WORK ORDER NO: 41 | | | 1516 | | |
|---|---------------------|---|--|-------------|---------------------|---------|----------------|-------------------|--|-------------|------------|-----------------|------------|----------|
| USING DEF WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED PREVENTIVE MAINT 19CHEV25004X4 | COMPLETED DATE: 11/08/2021 13:59:02 N CLOSED DATE: 11/09/2021 08:23:55 II | | | | | METER 1 - I | LOCATION: GARAGE - University METER 1 - M: 49823 ME IN-SERVICE DATE: 04/10/202 UNIT SERIAL NO: 2GC2KRI | | | 5 | | |
| JOB CODE | <u> </u> | JOB DESCRIPTION | | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATE | RIAL C | OMMERCIAL | TOTAL COST | <u> </u> |
| 03-51-038 | REPLAC | E NEW WIPER BLADES | | DON | Р | Ν | GARAGE | 0.05 | \$5.77 | \$20.37 | \$0 | 0.00 | \$26.14 | |
| 66-17-033 | PERFOR | M TIRE ROTATION AND | BRAKE | DON | 0 | Ν | GARAGE | 0.38 | \$44.45 | \$0.00 | \$0 | 0.00 | \$44.45 | |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0.88 | \$103.87 | \$77.12 | \$0 | 0.00 | \$180.99 | |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2 | 00 | \$2.00 | |
| JOB COUN | IT: 4 | | | | WO | RK ORI | DER TOTAL | : 1.31 | 154 | .09 | 97.49 | 2.00 | 253. | 58 |
| Job Code CH-SP | CHARGE SI | Job Description nop Supplies | | 50 | V o 03163 | endor N | o. 1 | Invoice No. | <u>Purcha</u> | se Order No | <u>o.</u> | COMML | | 2.00 |
| Job Code | | Job Description | | | Em | ployee | No. | Start | | Finish | | Quantity | Total Cost | _ |
| 66-17-033 | PERFORM | TIRE ROTATION AND BRA | KE INSPEC | CTION 1 | 1074414 | - | 11 | /04/2021 15:23:12 | 11/04/202 | 21 15:45:48 | | 0.38 | \$44. | .45 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 12 | 2052187 | | 11 | /04/2021 14:43:19 | 11/04/202 | 21 15:14:38 | | 0.52 | \$61. | .59 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 11 | 1074414 | | 11 | /04/2021 15:08:28 | 11/04/202 | 21 15:11:24 | | 0.05 | \$5. | .77 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 1 | 1074414 | | 11 | /04/2021 14:46:47 | 11/04/202 | 21 15:08:17 | | 0.36 | \$42. | .28 |
| | | | | | | | | | | | | LABOR | 154. | 09 |
| Job Code | | Job Description | | | , | Part No | <u> </u> | Des | cription | <u>!</u> | Unit Price | Quantity | Total Cost | |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 5\ | W30T | | 5\ | V30 SYNTHETIC | OIL THOMAS C | AM2 | 5.88 | 7 | \$41 | .16 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | W | /IX57060 |) | O | IL FILTER | | | 5.87 | 1 | \$5 | .87 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 19 | 9220 | | W | IPER 22 IN OE BE | AM | | 10.19 | 2 | \$20 | .37 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 42 | 2488 | | FI | LTER-AIR | | | 30.09 | | \$30 | |
| | | | | | | | | | | | | PARTS | 97. | 49 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 41516

Work Order Notes

(IFALLS) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires relearned tire positions adjusted tire pressure and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

| UNIT NO: | O: 243732 2019 CH | | | | ET 250 | 0 TRU | CK 4X4 | ļ | | WORK C | RDER NO |): 4 | 42071 | | |
|-------------------|-------------------|------------------|--------------|-------------------------|-------------------|---------|----------|---|---------------|------------|---------------------|-----------|--------------|----------------|-------------|
| WO STATUS | | | • | COMPLETED DATE: 01/14/2 | | | | 8/2022 09:49:16 LOCATION: GAR 8/2022 13:48:54 METER 1 - M: 56 8/2022 08:05:32 IN-SERVICE DATI UNIT SERIAL NO | | | M: 56118 E DATE: | 04/10/2 | METER 2 - H: | 5 | |
| JOB CODE | | JOB DESCRIPT | <u>ION</u> | STAT | RSN | WRTY | JOB LO | C L | ABOR HRS | LABOR | MATI | ERIAL | COMMERCIAL | TOTAL (| COST |
| 03-21-002 | REPLAC | E NEW CV AXLES | S/SEALS | DON | 0 | Ν | GARAGE | E | 0.90 | \$106.66 | \$192.90 |) 5 | 80.00 | \$299.56 | |
| 66-17-033 | PERFOR | RM TIRE ROTATIO | N AND BRAKE | DON | Р | Ν | GARAGE | E | 0.15 | \$17.37 | \$0.00 | 9 | 80.00 | \$17.37 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | N | GARAGE | E | 0.27 | \$31.50 | \$89.61 | 9 | 80.00 | \$121.11 | |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | N | GARAGE | E | 0.00 | \$0.00 | \$0.00 | 9 | \$2.00 | \$2.00 | |
| JOB COUN | IT: 4 | | | | wo | RK ORI | DER TOTA | AL: | 1.32 | 15 | 5.53 | 282.51 | 2.00 | ı | 440.04 |
| Job Code CH-SP | CHARGE SI | Job Descrip | otion | 50 | V 03163 | endor N | | 1 | Invoice No. | Purch | ase Order N | lo. | COMML | <u>Total (</u> | \$2.00 |
| Job Code | | Job Descrip | otion | | Fm | ployee | No. | | Start | | Finish | | Quantity | Total (| |
| 66-17-033 | PERFORM T | TIRE ROTATION AN | | CTION 1 | | - | | 01/14/ | 2022 10:07:53 | 01/14/20 |)22 10:16:43 | | 0.15 | | \$17.37 |
| 03-21-002 | REPLACE N | IEW CV AXLES/SEA | ALS | 1 | 1310047 | | | 01/14/ | 2022 08:06:24 | 01/14/20 | 022 09:00:38 | | 0.90 | | \$106.66 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 1: | 2052187 | | | 01/14/ | 2022 07:08:58 | 01/14/20 |)22 07:24:59 | | 0.27 | | \$31.50 |
| | | | | | | | | | | | | | LABOR | | 155.53 |
| Job Code | | Job Descrip | <u>otion</u> | | | Part No | <u>.</u> | | <u>Des</u> | cription | | Unit Pric | e Quantity | Total (| <u>Cost</u> |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 5 | W30T | | | 5W30 | SYNTHETIC C | OIL THOMAS | CAM2 | 7.1 | 6 7 | | \$50.09 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | V | /IX57060 |) | | OIL FI | LTER | | | 9.1 | 4 1 | | \$9.14 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | Α | NTIFRE | EZE DEX | COOL | ANTIF | REEZE-GM | | | 18.5 | 59 1 | | \$18.59 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | С | 111 | | | RED E | BRAKE CLEAN | IER | | 5.9 | 90 2 | | \$11.79 |
| 03-21-002 | REPLACE N | IEW CV AXLES/SEA | ALS | V | ONGM8 | 356 | | CV AX | (LE | | | 192.9 | 901 | | \$192.90 |
| | | | | | | | | | | | | | PARTS | | 282.51 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 42071

Work Order Notes

(LISAPATE) PM-replace wipers-Rotate tires and check brakes

Job Notes

03-21-002 - REPLACE NEW CV AXLES/SEALS

(EHOWELL) CV axle boot had a hole in it. Replaced left front CV axle assembly and cleaned up grease. EH

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(EHOWELL) Tires were rotated. Front brakes - 8mm. Rear brakes - 8mm.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,EH,MS,RC,CW/EH

CH-SP - CHARGE Shop Supplies

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 42923

USING DEPT NO: 204902 OPENED DATE: 04/13/2022 15:47:48 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 04/18/2022 09:21:14
 METER 1 - M:
 56118
 METER 2 - H:
 5

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 04/18/2022 14:40:08
 IN-SERVICE DATE:
 04/10/2020

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 UNIT SERIAL NO: 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | <u>LAB</u> | OR MATE | RIAL COMM | <u>ERCIAL</u> <u>TOTAL</u> | <u>COST</u> |
|-----------|------------------------------------|-------------|------------|-------------|------------|-----------|------------|---------|-----------|----------------------------|-------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | Р | N | GARAGE | 0.05 | \$5.41 | \$20.37 | \$0.00 | \$25.78 | |
| 06-01 | INSPECT AIR CONDITIONING, HEAT, VE | DON | 0 | N | GARAGE | 0.50 | \$59.00 | \$0.00 | \$0.00 | \$59.00 | |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE | DON | 0 | N | GARAGE | 0.30 | \$35.73 | \$0.00 | \$0.00 | \$35.73 | |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.83 | \$98.14 | \$77.67 | \$0.00 | \$175.81 | |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEME! | DON | Р | Ν | GARAGE | 0.12 | \$14.16 | \$12.96 | \$0.00 | \$27.12 | |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 | |
| JOB COUNT | : 6 | | wo | RK ORI | DER TOTAL: | 1.80 | | 212.44 | 111.00 | 2.00 | 325.44 |

Job CodeJob DescriptionVendor No.Invoice No.Purchase Order No.Total CostCH-SPCHARGE Shop Supplies5031631\$2.00COMML2.00

| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | Quantity | Total Cost |
|-----------|--|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11074414 | 04/15/2022 07:00:00 | 04/15/2022 07:07:12 | 0.12 | \$14.16 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | 11074414 | 04/14/2022 09:30:00 | 04/14/2022 09:45:17 | 0.25 | \$30.06 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | 11074414 | 04/14/2022 09:12:07 | 04/14/2022 09:15:00 | 0.05 | \$5.67 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 11074414 | 04/14/2022 09:03:12 | 04/14/2022 09:05:57 | 0.05 | \$5.41 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 04/14/2022 08:13:06 | 04/14/2022 09:03:00 | 0.83 | \$98.14 |
| 06-01 | INSPECT AIR CONDITIONING, HEAT, VENT | 11074414 | 04/14/2022 14:30:00 | 04/14/2022 14:36:22 | (0.11) | (\$12.52) |
| 06-01 | INSPECT AIR CONDITIONING, HEAT, VENT | 11074414 | 04/14/2022 14:30:00 | 04/14/2022 14:36:22 | 0.11 | \$12.52 |
| 06-01 | INSPECT AIR CONDITIONING, HEAT, VENT | 11074414 | 04/14/2022 14:30:00 | 04/14/2022 15:00:00 | 0.50 | \$59.00 |
| 06-01 | INSPECT AIR CONDITIONING, HEAT, VENT | 11074414 | 04/14/2022 14:29:48 | 04/14/2022 14:29:48 | 0.00 | \$0.00 |
| 03-PM-PMC | REPLACE NEW CABIN FILTER REPLACEMENT | 11074414 | 04/14/2022 09:06:10 | 04/14/2022 09:11:55 | 0.10 | \$11.31 |
| 03-PM-PMC | REPLACE NEW CABIN FILTER REPLACEMENT | 11074414 | 04/14/2022 09:06:10 | 04/14/2022 09:11:55 | (0.10) | (\$11.31) |
| | | | | | LABOR | 212.44 |

Work Order Charge Detail

The University of Alabama

Work Order Charge Detail

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------------|-------------------|-----------------|------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | PA4486 | CABIN AIR ELEMENT | 12.96 | 1 | \$12.96 |
| 66-PM-PMA | PERFORM OIL CHANGE | PA5314F | AIR FILTER | 18.51 | 1 | \$18.51 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 10.44 | 1 | \$10.44 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 6.96 | 7 | \$48.72 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.19 | 2 | \$20.37 |
| | | | | | PARTS | 111.00 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 42923

Work Order Notes

(LISAPATE) PM-replace wipers-replace cabin filter and air filter-rotate tires and inspect brakes-check a/c freon make sure it is good

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(IFALLS) Did a performance check on the A/C in the truck. Found no issues A/C is cooling good. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires adjusted tire pressure relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) replaced cabin filter

CH-SP - CHARGE Shop Supplies

243732

UNIT NO:

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

43581

WORK ORDER NO:

| 2010 011211 2010 111211 2010 111211 2010 111211 | | | | | | | | | | | | | |
|---|-----------|---|-------------|---------------------|---------|------------|---|---|---------------|---|----------|--------------|---------|
| USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO: | | 204902 CLOSED SCHEDULED 19CHEV25004X4 2019 | COMPL | COMPLETED DATE: 06/ | | | 22 09:12:08 22 14:33:21 22 08:41:10 | LOCATION: GARAGI METER 1 - M: 67455 IN-SERVICE DATE: UNIT SERIAL NO: | | E - University Automotive METER 2 - H: 04/10/2020 2GC2KREG8K124189 | | 5 | |
| JOB CODE | <u> </u> | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOR</u> | MATE | RIAL CC | MMERCIAL | TOTAL | COST |
| 03-01-100 | REPLAC | E NEW BELT, AIR CONDITION | INOD 1 | 0 | Ν | GARAGE | 0.45 | \$53.49 | \$37.19 | \$0.0 | 00 | \$90.68 | |
| 03-34-001 | REPLAC | E NEW HEADLAMPS | DON | 0 | N | GARAGE | 0.16 | \$18.78 | \$10.95 | \$0.0 | 00 | \$29.73 | |
| 03-50-100 | REPLAC | E NEW BELT, SERPENTINE OF | R DON | 0 | N | GARAGE | 0.10 | \$11.80 | \$69.06 | \$0.0 | 00 | \$80.86 | |
| 35-42 | DIAGNO | SE COOLING SYSTEM | DON | 0 | N | GARAGE | 0.37 | \$43.86 | \$0.00 | \$0.0 | 00 | \$43.86 | |
| 66-17-033 | PERFOR | RM TIRE ROTATION AND BRAK | E DON | Р | Ν | GARAGE | 0.49 | \$58.08 | \$0.00 | \$0.0 | 00 | \$58.08 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | DON | Р | Ν | GARAGE | 0.65 | \$76.54 | \$71.54 | \$0.0 | 00 | \$148.08 | |
| CH-SP | CHARGI | E Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.0 | 00 | \$2.00 | |
| JOB COUN | IT: 7 | | | WC | RK ORI | DER TOTAL: | 2.23 | 262 | .55 | 188.74 | 2.00 | | 453.29 |
| Job Code | | Job Description | | <u>v</u> | endor N | <u>lo.</u> | Invoice No. | Purcha | se Order No | <u>).</u> | | <u>Total</u> | Cost |
| CH-SP | CHARGE S | hop Supplies | 5 | 03163 | | 1 | | | | | | \$2.00 | |
| | | | | | | | | | | | COMML | | 2.00 |
| Job Code | | Job Description | | <u>En</u> | nployee | No. | <u>Start</u> | <u>!</u> | <u>Finish</u> | | Quantity | <u>Total</u> | Cost |
| 03-50-100 | REPLACE N | NEW BELT, SERPENTINE OR MISC | . 1 | 1310047 | 7 | 06/ | 10/2022 07:00:00 | 06/10/202 | 22 07:06:00 | | 0.10 | | \$11.80 |
| 03-01-100 | REPLACE N | NEW BELT, AIR CONDITIONING | 1 | 1310047 | 7 | 06/ | 10/2022 07:00:00 | 06/10/202 | 22 07:06:00 | | 0.10 | | \$11.80 |
| 66-17-033 | PERFORM | TIRE ROTATION AND BRAKE INSP | ECTION 1 | 1074414 | 1 | 06/ | 10/2022 09:34:18 | 06/10/202 | 22 10:03:50 | | 0.49 | | \$58.08 |
| 03-34-001 | REPLACE N | NEW HEADLAMPS | 1 | 1074414 | 1 | 06/ | 10/2022 09:22:59 | 06/10/202 | 22 09:22:59 | | 0.00 | | \$0.00 |
| 03-34-001 | REPLACE N | NEW HEADLAMPS | 1 | 1074414 | 1 | 06/ | 10/2022 08:44:37 | 06/10/202 | 22 08:54:10 | | 0.16 | | \$18.78 |
| 66-PM-PMA | PERFORM | OIL CHANGE | 1 | 1901357 | 7 | 06/ | 10/2022 07:40:51 | 06/10/202 | 22 08:19:46 | | 0.65 | | \$76.54 |
| 03-01-100 | REPLACE N | NEW BELT, AIR CONDITIONING | 1 | 1310047 | 7 | 06/ | 10/2022 07:49:43 | 06/10/202 | 22 08:10:55 | | 0.35 | | \$41.69 |
| 35-42 | DIAGNOSE | COOLING SYSTEM | 1 | 1310047 | 7 | 06/ | 06/09/2022 11:03:26 | | | 2022 11:25:44 | | | \$43.86 |
| | | | | | | | | | | | LABOR | | 262.55 |
| Job Code | | Job Description | | | Part No | <u>.</u> | Des | cription | <u>.</u> | Jnit Price | Quantity | <u>Total</u> | Cost |
| | | NEW BELT, SERPENTINE OR MISC | | ATK060 | | | LT | | | 69.06 | 1 | | \$69.06 |

2019 CHEVROLET 2500 TRUCK 4X4

The University of Alabama

Work Order Charge Detail

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|------------------------------------|--------------|--------------------------------|-------------------|----------|------------|
| 03-01-100 | REPLACE NEW BELT, AIR CONDITIONING | GATK040355SF | BELT | 37.19 | 1 | \$37.19 |
| 03-34-001 | REPLACE NEW HEADLAMPS | 1255H11 | BULB-HALOGEN | 10.95 | 1 | \$10.95 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 7.49 | 7 | \$52.40 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 7.89 | 1 | \$7.89 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 11.25 | 1 | \$11.25 |
| | | | | | PARTS | 188.74 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 43581

Work Order Notes

(LISAPATE) PM-replace wipers-rotate tires-Check water pump and belts for wear. Get quotes for body damage. Can wiper fluid be adjusted to spray higher on windshield? (EHOWELL) The washer nozzles are mounted in their factory locations. EH

Job Notes

01-34-001 - ADJUST HEADLAMPS

03-01-100 - REPLACE NEW BELT, AIR CONDITIONING

(EHOWELL) Replaced AC belt and serpentine belt. No extra labor needed for serpentine belt. EH

03-34-001 - REPLACE NEW HEADLAMPS

(HHARBIN) Replaced the right side low beam head light bulb. SH

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(LISAPATE) Replaced AC belt and serpentine belt. No extra labor needed for serpentine belt. EH

03-51-038 - REPLACE NEW WIPER BLADES

35-42 - DIAGNOSE COOLING SYSTEM

(EHOWELL) Inspected water pump for leaks and excessive play. EH

66-17-029 - PERFORM ROTATE AND BALANCE TIRES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(HHARBIN) Cross rotated tire adjusted tire pressure relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 67455 Completed PM bottomside, Josh was topside. Completed checklist. JW/AMG

CH-SP - CHARGE Shop Supplies

| UNIT NO: | 243732 2019 CHEVROLET 2500 TRUCK 4X4 | | | | WORK ORDER NO: 43725 | | | | | | | |
|-------------------------|--|-----------------|---|-----------|--|------------|--|---------|---------------------|-----------|------------|------------|
| WO STATUS WO VISIT R | USING DEPT NO: 204902 WO STATUS: CLOSED WO VISIT REASON: SCHEDULED TECH SPEC NO: 19CHEV25004X4 | | COMPLETED DATE: 06/28/2022 14:47:43 ME CLOSED DATE: 06/29/2022 08:33:23 IN: | | LOCATION: GARAGE - METER 1 - M: 67455 IN-SERVICE DATE: UNIT SERIAL NO: | | - University Automotive 3 METER 2 - H: 04/10/2020 2GC2KREG8K124189 | | 5 | | | |
| JOB CODE | <u>:</u> | JOB DESCRIPTION | ST/ | T RS | N WRTY | JOB LOC | LABOR HRS | LABO | OR MATE | RIAL | COMMERCIAL | TOTAL COST |
| 16-71 | TRANSP | ORT BODY | DC | N 0 | Ν | GARAGE | 0.50 | \$59.00 | \$0.00 | | \$0.00 | \$59.00 |
| 24-71 | REPAIR I | BODY | DO | DON A N G | | GARAGE | 0.00 | \$0.00 | | : | \$2,497.10 | \$2,497.10 |
| CH-SP | CHARGE | Shop Supplies | DC | N 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | : | \$2.00 | \$2.00 |
| JOB COUN | T: 3 | | | ٧ | ORK OR | DER TOTAL: | 0.50 | 1 | 59.00 | 0.00 | 2,499.10 | 2,558.10 |
| Job Code | | Job Description | <u>.</u> | | Vendor N | <u>lo.</u> | Invoice No. | Purc | hase Order No | <u>).</u> | | Total Cost |
| 24-71 | REPAIR BOI | DY | | 111506 | 05 | 16 | 96884 | | | | | \$2,497.10 |
| CH-SP | CHARGE Sh | nop Supplies | | 503163 | | 1 | | | | | | \$2.00 |
| | | | | | | | | | | | COMML | 2499.10 |
| Job Code | | Job Description | ļ | <u> </u> | Employee | No. | <u>Start</u> | | <u>Finish</u> | | Quantity | Total Cost |
| 16-71 | TRANSPOR | T BODY | | 119155 | 38 | 06 | 06/28/2022 00:00:00 | | 06/28/2022 00:30:00 | | 0.50 | \$59.00 |
| | | | | | | | | | | | LABOR | 59.00 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 43725

Work Order Notes

(LISAPATE) Repair Body damage to right front fender per the Body Shop estimate

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by RC

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired RF fender per the estimate. PD by CC

CH-SP - CHARGE Shop Supplies

| UNIT NO: 243732 20° | | | 2019 CHEVROL | ET 25 | 00 TRU | ICK 4X4 | | WORK O | RDER NO | D: 4 | 3813 | |
|---|---------------|--|--|-------------------|-------------|------------------------|---|---|---------------------|----------------------|---|--------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | OPENI COMPI CLOSE 2019 Chevrole | ETED | DATE: E: | 07/07/202 07/11/202 | 22 11:47:01 22 13:43:21 22 10:07:04 | LOCATION METER 1 - IN-SERVICI UNIT SERIA | M: 68058 E DATE: | M 04/10/20 | ty Automotive S IETER 2 - H: D20 REG8K124189 | 5 |
| JOB CODE | Ī | JOB DESCRIPTIO | N STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATE | ERIAL C | OMMERCIAL | TOTAL COST |
| 66-17-017 | PERFOR | RM BALANCE TIRES | DON | 0 | N | GARAGE | 0.81 | \$96.01 | \$3.83 | \$ | 0.00 | \$99.84 |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$ | 2.00 | \$2.00 |
| JOB COUN | IT: 2 | | | WC | RK ORI | DER TOTAL: | 0.81 | 96 | 5.01 | 3.83 | 2.00 | 101.8 |
| Job Code CH-SP | CHARGE SI | Job Description op Supplies | | <u>V</u> 03163 | endor N | lo. 1 | Invoice No. | <u>Purcha</u> | ise Order N | lo. | | Total Cost \$2. |
| | | | | | | | | | | | COMML | 2.0 |
| Job Code | | Job Description | <u>on</u> | <u>En</u> | nployee | No. | <u>Start</u> | | <u>Finish</u> | | Quantity | Total Cost |
| 66-17-017 | PERFORM I | BALANCE TIRES | 1 | 1074414 | 1 | 07/ | /01/2022 13:14:50 | 07/01/20 | 22 14:03:39 | | 0.81 | \$96. |
| | | | | | | | | | | | LABOR | 96.0 |
| Job Code | | Job Description | o <u>n</u> | | Part No | <u>.</u> | Des | cription | | Unit Price | Quantity | Total Cost |
| 66-17-017 | PERFORM I | BALANCE TIRES | 5 | 8121 | | .50 | OZ WHEEL WEI | GHT | | 0.43 | 3 1 | \$0. |
| 66-17-017 | PERFORM I | BALANCE TIRES | 5 | 8122 | | .75 | OZ WHEEL WEI | GHT | | 0.43 | 3 1 | \$0. |
| 66-17-017 | PERFORM I | BALANCE TIRES | 5 | 8123 | | 1.0 | 0 OZ WHEEL WE | IGHT | | 0.50 |) 1 | \$0. |
| 66-17-017 | PERFORM I | BALANCE TIRES | 5 | 8125 | | 1.5 | 0 OZ WHEEL WE | IGHT | | 0.6 | 5 1 | \$0. |
| 66-17-017 | PERFORM I | BALANCE TIRES | 6 | 3001 | | 1/4 | OZ STICK ON TA | APE WEIGHT | | 0.17 | 711 | \$1. |
| | | | | | | | | | | | PARTS | 3.8 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 43813

Work Order Notes

(LISAPATE) Balance tires, truck is shaking at 70MPH

Job Notes

66-17-017 - PERFORM BALANCE TIRES

(HHARBIN) Balanced all 4 tires and test drove did not experience any shaking. SH

CH-SP - CHARGE Shop Supplies

UNIT NO:

243732

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

44211

WORK ORDER NO:

| WO STATUS | SING DEPT NO: 204902 O STATUS: CLOSED O VISIT REASON: SCHEDULED ECH SPEC NO: 19CHEV25004X4 2019 | | OPENED DATE: 08/08/2022 13:2 COMPLETED DATE: 08/17/2022 11:3 CLOSED DATE: 08/18/2022 13:4 Chevrolet Silverado 2500 4X4 | | | 22 11:31:09 | LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL | 71416 P ATE: 04 | MET 4/10/2020 | TER 2 - H: | 5 | |
|------------------------------|--|----------------------------------|--|-----------------------|--------------|-------------|---|---------------------------|--------------------------------|------------------|------------------|------------------------------|
| JOB CODE | <u> </u> | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOR</u> | MATERIA | AL CO | MMERCIAL | TOTAL COST |
| 03-51-038 | REPLAC | E NEW WIPER BLADES | DON | Р | N | GARAGE | 0.04 | \$4.16 | \$20.79 | \$0.0 | 0 | \$24.95 |
| 06-15 | INSPEC | T STEERING | DON | 0 | N | GARAGE | 0.16 | \$18.36 | \$0.00 | \$0.0 | 0 | \$18.36 |
| 09-15 | ALIGN S | TEERING | DON | 0 | Ν | GARAGE | 0.69 | \$81.42 | \$0.00 | \$0.0 | 0 | \$81.42 |
| 66-17-028 | PERFOR | RM MOUNT AND BALANCE TIRE | DON | 0 | N | GARAGE | 1.52 | \$179.36 | \$1,358.64 | \$0.0 | 0 | \$1,538.00 |
| 66-79-003 | PERFOR | RM SAFETY INSPECTION | DON | Υ | N | GARAGE | 0.57 | \$67.72 | \$0.00 | \$0.0 | 0 | \$67.72 |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | DON | Р | N | GARAGE | 0.24 | \$28.84 | \$68.42 | \$0.0 | 0 | \$97.26 |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.0 | 0 | \$2.00 |
| JOB COUN | T: 7 | | | WC | RK ORI | DER TOTAL: | 3.22 | 379.86 | 5 1,447 | 7.85 | 2.00 | 1,829.71 |
| Job Code | 0 | Job Description | _ | _ | endor N | | Invoice No. | <u>Purchase</u> | Order No. | | | Total Cost |
| CH-SP | CHARGE SI | nop Supplies | 5 | 03163 | | 1 | | | | - | COMML | \$2.00 2.00 |
| Job Code | | lab Description | | | | No | Ctout | - Ein | iah | | | |
| 09-15 | ALIGN STE | Job Description ERING | 1 | <u>EII</u> 1310047 | nployee , | | <u>Start</u> /09/2022 10:19:55 | | <u>iish</u> 11:01:19 | | Quantity 0.69 | <u>Total Cost</u> \$81.42 |
| 66-17-028 | PERFORM I | MOUNT AND BALANCE TIRES | 1 | 1074414 | ļ | 08/ | /09/2022 09:30:00 | 08/09/2022 (| 09:32:27 | | 0.04 | \$4.82 |
| 66-17-028 | PERFORM I | MOUNT AND BALANCE TIRES | 1 | 1074414 | ļ | 08/ | /09/2022 07:46:15 | 08/09/2022 09:15:00 | | | 1.48 | \$174.54 |
| 66-79-003 | PERFORM | SAFETY INSPECTION | 1 | 1074414 | ļ | 08/ | /09/2022 07:08:24 | 08/09/2022 (| 07:42:50 | | 0.57 | \$67.72 |
| 06-15 | INSPECT S | TEERING | 1 | 1074414 | ļ | 08/ | /08/2022 15:35:34 | 08/08/2022 1 | 15:44:54 | | 0.16 | \$18.36 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | 1 | 1074414 | ļ | 08/ | /08/2022 15:18:33 | 08/08/2022 1 | 15:20:40 | | 0.04 | \$4.16 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | 1 | 1074414 | ļ | 08/ | /08/2022 15:07:24 | 08/08/2022 1 | 15:18:21 | | 0.18 | \$21.54 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | 1: | 2052187 | 7 | 08/ | /08/2022 15:01:22 | 08/08/2022 1 | 15:05:05 | | 0.06 | \$7.31 |
| | | | | | | | | | | - | LABOR | 379.87 |
| <u>Job Code</u> 03-51-038 | REPLACE N | Job Description IEW WIPER BLADES | 1 | 9220 | Part No | | <u>Des</u> PER 22 IN OE BE | <u>cription</u> AM | <u>Uni</u> | t Price 10.40 | Quantity 2 | Total Cost \$20.79 |
| FleetFocus M5 | - WODETAII | - Work Order Detail v20 0 | | | | | | | | | | Page:1 |

2019 CHEVROLET 2500 TRUCK 4X4

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|---------------------------------|----------|--------------------------------|-------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 7.32 | 7 | \$51.24 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 11.25 | 1 | \$11.25 |
| 66-PM-PMA | PERFORM OIL CHANGE | C111 | RED BRAKE CLEANER | 5.93 | 1 | \$5.93 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 2.61 | 4 | \$10.44 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58121 | .50 OZ WHEEL WEIGHT | 0.43 | 1 | \$0.43 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58122 | .75 OZ WHEEL WEIGHT | 0.43 | 1 | \$0.43 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58123 | 1.00 OZ WHEEL WEIGHT | 0.50 | 3 | \$1.49 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58124 | 1.25 OZ WHEEL WEIGHT | 0.60 | 2 | \$1.20 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58125 | 1.50 OZ WHEEL WEIGHT | 0.65 | 1 | \$0.65 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58126 | 1.75 OZ WHEEL WEIGHT | 0.74 | 3 | \$2.21 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58127 | 2.00 OZ WHEEL WEIGHT | 0.85 | 1 | \$0.85 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BFG A/T KO2 | 335.24 | 4 | \$1,340.94 |
| | | | | | PARTS | 1447.85 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 44211

Work Order Notes

(LRUSHING) PM-REPLACE WIPES DO A SAFETY INSPECTION REPLACE 4 TIRES AND ALIGN

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(HHARBIN) Inspected steering found no issues at this time . SH JW

09-15 - ALIGN STEERING

(EHOWELL) Set front toe and relearned steering angle sensor. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(HHARBIN) SH Mounted and AMG balanced 4 tires. SH

66-79-003 - PERFORM SAFETY INSPECTION

(HHARBIN) Performed a safety inspection found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Performed PM. SH

| UNIT NO: | | 243732 20 | 19 CHE | VROLE | ET 250 | 00 TRU | ICK 4X4 | | WORK | ORDER NO | : 4 | 5190 | | |
|---|----------------------|--|-----------|-------------------------------------|---------------|---------|-----------------------|---|----------|---|------------------------|-------------|--------------|----------|
| USING DEF WO STATUS WO VISIT F TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | 2019 (| OPENE COMPL CLOSE Chevrole | ETED D DAT | DATE: | 11/11/20: 11/14/20 | 22 11:47:29 22 08:54:27 22 07:51:14 | METER 1 | ON: GARAGE - M: 78596 ICE DATE: RIAL NO: | M i 04/10/20 | ETER 2 - H: | 5 | |
| JOB CODE | <u> </u> | JOB DESCRIPTION | | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABO | OR MATE | RIAL C | OMMERCIAL | TOTAL | COST |
| 03-42-004 | REPLAC | E NEW WATER PUMP | | DON | 0 | Ν | GARAGE | 1.64 | \$193.65 | \$254.23 | \$0 | 0.00 | \$447.88 | |
| 03-42-006 | REPLAC | E NEW THERMOSTAT | S | DON | 0 | N | GARAGE | 0.10 | \$11.80 | \$29.85 | \$0 | 0.00 | \$41.65 | |
| 03-50-102 | REPLAC | E NEW IDLER PULLEY | ′ | DON | 0 | N | GARAGE | 1.34 | \$157.92 | \$164.49 | \$0 | 0.00 | \$322.41 | |
| 03-51-038 | REPLAC | E NEW WIPER BLADE | S | DON | Р | N | GARAGE | 0.03 | \$3.05 | \$20.94 | \$0 | 0.00 | \$23.99 | |
| 06-42-004 | INSPECT | T WATER PUMP | | DON | 0 | N | GARAGE | 0.46 | \$54.74 | \$41.55 | \$0 | 0.00 | \$96.29 | |
| 66-17-017 | PERFOR | RM BALANCE TIRES | | DON | 0 | N | GARAGE | 1.38 | \$163.30 | \$5.54 | \$0 | 0.00 | \$168.84 | |
| 66-17-033 | PERFOR | RM TIRE ROTATION AN | D BRAKE | DON | Р | N | GARAGE | 0.34 | \$39.86 | \$0.00 | \$0 | 0.00 | \$39.86 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | N | GARAGE | 0.32 | \$37.50 | \$71.65 | \$0 | 0.00 | \$109.15 | |
| CH-SP | CHARGE | E Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5 | 5.00 | \$5.00 | |
| JOB COUN | IT: 9 | | | | WC | RK ORI | DER TOTAL | .: 5.61 | 6 | 661.82 | 588.25 | 5.00 | | 1,255.07 |
| Job Code | | Job Description | | | V | endor N | l <u>o.</u> | Invoice No. | Puro | hase Order No |) <u>.</u> | | Total | Cost |
| CH-SP | CHARGE SI | hop Supplies | | 5 | 03163 | | 1 | | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | | 5.00 |
| Job Code | | Job Description | | | <u>En</u> | nployee | No. | <u>Start</u> | | <u>Finish</u> | | Quantity | <u>Total</u> | Cost |
| 03-42-006 | | NEW THERMOSTATS | | 1 | 1310047 | 7 | 11 | 1/11/2022 07:00:00 | 11/11/ | 2022 07:06:00 | | 0.10 | | \$11.80 |
| 06-42-004 | INSPECT W | ATER PUMP | | 1 | 1310047 | • | 11 | 1/09/2022 14:59:49 | 11/09/ | 2022 15:27:39 | | 0.46 | | \$54.74 |
| 03-42-004 | REPLACE N | NEW WATER PUMP | | 1 | 1310047 | , | 11 | 1/09/2022 13:59:53 | 11/09/ | 2022 14:59:49 | | 1.00 | | \$117.87 |
| 03-42-004 | REPLACE N | NEW WATER PUMP | | 1 | 1310047 | • | 11 | 1/09/2022 11:17:53 | 11/09/ | 2022 11:56:25 | | 0.64 | | \$75.78 |
| 66-17-017 | PERFORM I | BALANCE TIRES | | 1 | 1901357 | • | 11 | 1/09/2022 09:12:05 | 11/09/ | 2022 10:35:07 | | 1.38 | | \$163.30 |
| 03-50-102 | REPLACE N | NEW IDLER PULLEY | | 1 | 1310047 | • | 11 | 1/09/2022 08:00:17 | 11/09/ | 2022 09:20:35 | | 1.34 | | \$157.92 |
| 66-17-033 | PERFORM ⁷ | TIRE ROTATION AND BRA | AKE INSPE | CTION 1 | 1074414 | ļ | 11 | 1/07/2022 14:30:00 | 11/07/ | 2022 14:50:16 | | 0.34 | | \$39.86 |
| 66-17-033 | PERFORM | TIRE ROTATION AND BRA | AKE INSPE | CTION 1 | 1074414 | ļ | 11 | 1/07/2022 14:17:47 | 11/07/ | 2022 14:17:47 | | 0.00 | | \$0.00 |
| 03-51-038 | REPLACE N | NEW WIPER BLADES | | 1 | 1074414 | ļ | 11 | 1/07/2022 14:13:27 | 11/07/ | 2022 14:15:00 | | 0.03 | | \$3.05 |
| El 4E NAE | . MODETAIL | Westernament | | | | | | | | | | | | 5 4 |

| Job Code 66-PM-PMA | <u>Job Description</u> PERFORM OIL CHANGE | Employee No. 11074414 | <u>Start</u> <u>Finish</u> 11/07/2022 13:54:08 11/07/2022 14:13 | :12 | Quantity 0.32 | Total Cost \$37.50 |
|-----------------------|--|------------------------------|--|------------|------------------|-----------------------|
| | | | | | LABOR | 661.82 |
| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
| 66-17-017 | PERFORM BALANCE TIRES | 58125 | 1.50 OZ WHEEL WEIGHT | 0.65 | 4 | \$2.58 |
| 66-17-017 | PERFORM BALANCE TIRES | 58126 | 1.75 OZ WHEEL WEIGHT | 0.74 | 2 | \$1.47 |
| 66-17-017 | PERFORM BALANCE TIRES | 58123 | 1.00 OZ WHEEL WEIGHT | 0.50 | 3 | \$1.49 |
| 03-42-006 | REPLACE NEW THERMOSTATS | FCT523190 | THERMOSTAT | 29.85 | 1 | \$29.85 |
| 03-42-004 | REPLACE NEW WATER PUMP | 10 CLAMP | CLAMP 9/16-1 1/16 | 0.62 | 1 | \$0.62 |
| 06-42-004 | INSPECT WATER PUMP | ANTIFREEZE DEXCOOL | ANTIFREEZE-GM | 20.78 | 2 | \$41.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 5.30 | 1 | \$5.30 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 7.86 | 1 | \$7.86 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 8.36 | 7 | \$58.49 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.47 | 2 | \$20.94 |
| 03-50-102 | REPLACE NEW IDLER PULLEY | CTL49154 | IDLER PULLEY | 60.03 | 1 | \$60.03 |
| 03-50-102 | REPLACE NEW IDLER PULLEY | CTL49436 | TENSIONER PULLEY ASSEMBLY | 104.91 | 1 | \$104.91 |
| 03-42-004 | REPLACE NEW WATER PUMP | GWP45010 | WATER PUMP | 253.11 | 1 | \$253.11 |
| 03-50-102 | REPLACE NEW IDLER PULLEY | CTL49436 | TENSIONER PULLEY ASSEMBLY | 104.46 | 1 | \$104.46 |
| 03-50-102 | REPLACE NEW IDLER PULLEY | CTL49436 | TENSIONER PULLEY ASSEMBLY | 104.91 | (1) | (\$104.91) |
| 03-42-004 | REPLACE NEW WATER PUMP | 6 CLAMP | HOSE CLAMP | 0.50 | 1 | \$0.50 |
| | | | | | PARTS | 588.25 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 45190

Work Order Notes

(LISAPATE) Per Doug truck is ready for PM-replace wipers and adjust spray nozzles up a little if possible-check water pump is noisy when truck is cold-rotate tires and check brakes are noisy when driving

Job Notes

03-42-004 - REPLACE NEW WATER PUMP

(EHOWELL) Installed a new water pump, thermostat w/gasket, and a new belt tension pulley. No extra labor for thermostat and pulley. Performed a road test after repair and topped off coolant level. EH

03-42-006 - REPLACE NEW THERMOSTATS

(LISAPATE) Replaced thermostat w/gasket. EH

03-50-102 - REPLACE NEW IDLER PULLEY

(IFALLS) Replaced idler pulley. The vehicle is no longer noisy on a cold startup. EH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-42-004 - INSPECT WATER PUMP

(IFALLS) Examined water pump with an inspection mirror. Water pump showed sign of seeping behind water pump pulley. EH

66-17-017 - PERFORM BALANCE TIRES

(EHOWELL) Washed mud from tires and rebalanced. AMG

The steering wheel was shaking excessively while driving after the tires were rotated. EH

(IFALLS) added extra time for washing the mud out of the rims.

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires adjusted tire pressure relearned tire positions and inspected brakes. Front pads are at 8MM. Rear pads are at 10MM. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

Page:1

Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

| UNIT NO: | | 243732 2019 | CHE | /ROLI | ET 250 | 00 TRU | ICK 4X4 | | WORK OR | DER NO | : 46 | 151 | |
|-----------|--|---------------------------|--------|--|-----------|---------|---------------------------|-------------------|---------------------|------------|------------|----------|------------|
| WO STATUS | USING DEPT NO: 204902 WO STATUS: CLOSED WO VISIT REASON: SCHEDULED TECH SPEC NO: 19CHEV25004X4 201 JOB CODE JOB DESCRIPTION | | | OPENED DATE: 02/14/2023 13:18:15 COMPLETED DATE: 02/17/2023 07:45:34 CLOSED DATE: 02/17/2023 07:45:38 9 Chevrolet Silverado 2500 4X4 | | | IN-SERVICE DATE: 04/10/20 | | ME 04/10/202 | TER 2 - H: | 5 | | |
| JOB CODE | <u> </u> | JOB DESCRIPTION | | STAT | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOR</u> | MATE | RIAL CO | MMERCIAL | TOTAL COST |
| 03-17-008 | REPLAC | E NEW VALVE ASSEMBL | Y | DON | 0 | N | GARAGE | 0.30 | \$35.73 | \$2.16 | \$0.0 | 00 | \$37.89 |
| 03-51-038 | REPLAC | E NEW WIPER BLADES | | DON | Р | Ν | GARAGE | 0.02 | \$2.52 | \$20.94 | \$0.0 | 00 | \$23.46 |
| 14-02-013 | INSTALL | FLOOR COVERINGS | | DON | 0 | N | GARAGE | 0.17 | \$20.19 | \$239.70 | \$0.0 | 00 | \$259.89 |
| 31-17 | ROTATE | TIRES, TUBES, LINERS & | & VALV | DON | Р | N | GARAGE | 0.12 | \$14.42 | \$0.00 | \$0.0 | 00 | \$14.42 |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | N | GARAGE | 0.19 | \$22.58 | \$80.44 | \$0.0 | 00 | \$103.02 |
| 66-PM-PMC | PERFOR | RM CABIN FILTER REPLA | CEMEI | DON | Р | N | GARAGE | 0.02 | \$2.66 | \$18.21 | \$0.0 | 00 | \$20.87 |
| CH-SP | CHARGE | E Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.0 | 00 | \$5.00 |
| JOB COUN | IT: 7 | | | | WC | RK ORI | DER TOTAL: | 0.83 | 98.1 | 0 | 361.45 | 5.00 | 464.55 |
| Job Code | | Job Description | | | <u>v</u> | endor N | <u>lo.</u> | Invoice No. | Purchase | e Order No | <u>).</u> | | Total Cost |
| CH-SP | CHARGE S | nop Supplies | | 5 | 03163 | | 1 | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | 5.00 |
| Job Code | | Job Description | | | <u>En</u> | nployee | No. | <u>Start</u> | <u>Fi</u> | nish | | Quantity | Total Cost |
| 14-02-013 | INSTALL FL | OOR COVERINGS | | 1 | 2201267 | 7 | 02 | /15/2023 10:21:42 | 02/15/2023 | 10:31:58 | | 0.17 | \$20.19 |
| 03-17-008 | REPLACE N | NEW VALVE ASSEMBLY | | 1 | 2201267 | 7 | 02 | /15/2023 10:00:25 | 02/15/2023 | 10:18:35 | | 0.30 | \$35.73 |
| 31-17 | ROTATE TIP | RES, TUBES, LINERS & VALV | /ES | 1 | 2201267 | 7 | 02 | /15/2023 08:37:50 | 02/15/2023 | 08:45:10 | | 0.12 | \$14.42 |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLACEME | NT | 1 | 2201267 | 7 | 02 | /15/2023 08:02:54 | 02/15/2023 | 08:04:15 | | 0.02 | \$2.66 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | | 1 | 2201267 | 7 | 02 | /15/2023 08:01:20 | 02/15/2023 | 08:02:37 | | 0.02 | \$2.52 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 2201267 | 7 | 02 | /15/2023 07:49:25 | 02/15/2023 | 08:00:54 | | 0.19 | \$22.58 |
| | | | | | | | | | | | | LABOR | 98.10 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | Des | scription | Ţ | Jnit Price | Quantity | Total Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 9220 | | WI | PER 22 IN OE BE | EAM | | 10.47 | 7 | \$73.29 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | | 1 | 9220 | | WI | PER 22 IN OE BE | AM | | 10.47 | 2 | \$20.94 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | V | VIX5706 | 0 | OI | L FILTER | | | 5.57 | 1 | \$5.57 |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLACEME | NT | V | VP10129 | 9 | CA | ABIN FILTER | | | 18.21 | 1 | \$18.21 |

The University of Alabama

Work Order Charge Detail

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|----------------------------|----------|--------------------------------|-------------------|----------|-------------------|
| 14-02-013 | INSTALL FLOOR COVERINGS | 449651V | FRONT FLOOR MATS CHEVY | 239.70 | 1 | \$239.70 |
| 03-17-008 | REPLACE NEW VALVE ASSEMBLY | 23131 | TPMS SNAP IN VALVE 21060 | 2.16 | 1 | \$2.16 |
| 66-PM-PMA | PERFORM OIL CHANGE | 19220 | WIPER 22 IN OE BEAM | 10.47 | (7) | (\$73.29) |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 10.70 | 7 | \$74.87 |
| | | | | · | PARTS | 361.45 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 46151

Work Order Notes

(EHANNAH) pm- replace wipers- rotate tires- replace cabin filter

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(GRCOOK) Had to replace valve steam. Other valve steam tore. - GC (IFALLS) right rear $\,$

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers- GC

14-02-013 - INSTALL FLOOR COVERINGS

(LISAPATE) Installed new floor Matt's. Had to vacuum all the stuff out of floor. -GC

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(GRCOOK) Rotated tires and inspected brakes. All is good at this time.- GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, Changed oil and oil filter, checked fluids, tires and tire pressure Miles, 85,592

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GRCOOK) Replaced cabin filter- GC

| UNIT NO: | JNIT NO: 243732 2019 CHEV | | | /ROLE | ROLET 2500 TRUCK 4X4 | | | | | WORK ORDER NO: 47 | | | | |
|---|---------------------------|--|---------|-------------------------|----------------------|---------|------------------------|---|--|---------------------|------------------------|---|--------------|---------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | | OPENE COMPL CLOSE | ETED D DAT | DATE: | 05/11/202 05/12/202 | 23 12:51:45 23 14:47:03 23 10:42:02 | LOCATION: METER 1 - I IN-SERVICE UNIT SERIA | M: 90755 E DATE: | ME 04/10/202 | / Automotive : E TER 2 - H: 20 EG8K124189 | 5 | |
| JOB CODE | | JOB DESCRIPTION | | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATE | RIAL CO | OMMERCIAL | TOTAL | COST |
| 03-51-038 | REPLAC | E NEW WIPER BLADES | | DON | Р | N | GARAGE | 0.09 | \$10.03 | \$21.69 | \$0. | 00 | \$31.72 | |
| 06-17 | INSPEC | TTIRES, TUBES, LINERS | S & VAL | DON | 0 | N | GARAGE | 0.78 | \$92.17 | \$0.00 | \$0. | 00 | \$92.17 | |
| 31-17 | ROTATE | TIRES, TUBES, LINERS | & VALV | DON | 0 | N | GARAGE | 0.33 | \$38.84 | \$0.00 | \$0. | 00 | \$38.84 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | N | GARAGE | 0.60 | \$70.93 | \$59.19 | \$0. | 00 | \$130.12 | |
| CH-SP | CHARGI | Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5. | 00 | \$5.00 | |
| WA-00 | WASH C | OMPLETE VEHICLE | | DON | Р | N | GARAGE | 0.66 | \$77.81 | \$0.00 | \$0. | 00 | \$77.81 | |
| JOB COUN | IT: 6 | | | | wo | RK ORI | DER TOTAL: | 2.46 | 289 | .78 | 80.88 | 5.00 | | 375.66 |
| Job Code | | Job Description | | | <u>v</u> | endor N | <u>o.</u> | Invoice No. | <u>Purcha</u> | se Order No | <u>o.</u> | | <u>Total</u> | Cost |
| CH-SP | CHARGE S | nop Supplies | | 5 | 03163 | | 1 | | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | | 5.00 |
| Job Code | | Job Description | | | <u>En</u> | nployee | No. | <u>Start</u> | <u> </u> | Finish | | Quantity | <u>Total</u> | Cost |
| WA-00 | WASH COM | PLETE VEHICLE | | 1 | 2201267 | 7 | 05 | /11/2023 08:30:55 | 05/11/202 | 23 09:10:29 | | 0.66 | | \$77.81 |
| 31-17 | ROTATE TIE | RES, TUBES, LINERS & VAL | VES | 1 | 2201267 | 7 | 05 | /11/2023 08:09:03 | 05/11/202 | 23 08:28:48 | | 0.33 | | \$38.84 |
| 06-17 | INSPECT T | RES, TUBES, LINERS & VA | LVES | 1 | 2201267 | 7 | 05 | /11/2023 07:21:58 | 05/11/202 | 23 08:08:50 | | 0.78 | | \$92.17 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | | 1 | 2201267 | 7 | 05. | /10/2023 15:19:44 | 05/10/202 | 23 15:24:50 | | 0.09 | | \$10.03 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 2201267 | 7 | 05. | /10/2023 14:43:22 | 05/10/202 | 23 15:19:26 | | 0.60 | | \$70.93 |
| | | | | | | | | | | | | LABOR | | 289.78 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | Des | cription | <u> </u> | Unit Price | Quantity | <u>Total</u> | Cost |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | | 1 | 9220 | | WI | PER 22 IN OE BE | AM | | 10.85 | 2 | | \$21.69 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 5 | W30T | | 5V | /30 SYNTHETIC (| OIL THOMAS C | AM2 | 7.65 | 7 | | \$53.55 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | V | VIX5706 | 0 | OI | L FILTER | | | 5.64 | 1 | - | \$5.64 |
| | | | | | | | | | | | | PARTS | | 80.88 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 47006

Work Order Notes

(EHANNAH) pm- replace wipers- wash- RR tire has slow leak inspect tire

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GRCOOK) Pulled tire while rotating tires to check for leak, found that valve core that I put on last time must have been defected because it had a tear in the bottom side of the core and was leaking slowly. Talked to Issac and he said replace the core and make sure it seats good. Replaced with new valve core and had no problems. No charge for job, per Issac. GRC

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(GRCOOK) Rotated all 4 tires-GC

(GARAGE) Also inspected brake pads, all brake pads are 8mm on all four wheels.-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure. Miles, 90,755

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

| UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER | ₹ NO: 47721 |
|--|-------------|
|--|-------------|

 USING DEPT NO:
 204902
 OPENED DATE:
 07/24/2023 14:06:21
 LOCATION:
 GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 08/02/2023 14:30:04
 METER 1 - M:
 95448
 METER 2 - H:
 5

WO VISIT REASON: SCHEDULED CLOSED DATE: 08/02/2023 15:02:57 IN-SERVICE DATE: 04/10/2020

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO:** 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|-------------|------------|-------------|---------|-----------|--------------|-----------------|------------|------------|
| 03-18-001 | REPLACE NEW FRONT AXLE HUBS & B | DON | Ν | Ν | GARAGE | 2.60 | \$306.73 | \$392.92 | \$0.00 | \$699.65 |
| 03-32-002 | REPLACE NEW BATTERY | DON | 0 | N | GARAGE | 0.13 | \$15.08 | \$221.08 | \$0.00 | \$236.16 |
| 03-33-004 | REPLACE NEW SPARK PLUGS | DON | N | N | GARAGE | 0.12 | \$14.55 | \$216.96 | \$0.00 | \$231.51 |
| 03-34-017 | REPLACE NEW HEADLIGHT/TAILIGHT S | DON | 0 | N | GARAGE | 0.65 | \$76.63 | \$17.56 | \$0.00 | \$94.19 |
| 06-22-014 | INSPECT REAR AXLE BEARING | DON | N | N | GARAGE | 19.38 | \$2,286.84 | \$244.70 | \$0.00 | \$2,531.54 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREE | DON | 0 | N | GARAGE | 0.25 | \$29.50 | \$0.00 | \$0.00 | \$29.50 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRE | DON | 0 | N | GARAGE | 3.35 | \$395.33 | \$5.42 | \$0.00 | \$400.75 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.26 | \$30.71 | \$58.35 | \$0.00 | \$89.06 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

JOB COUNT: 9 WORK ORDER TOTAL: 26.74 3,155.37 1,156.99 5.00 4,317.36

| Job Code | Job Description | Vendor No. | | Invoice No. | Purchase Order No. | | Total Cost |
|----------|----------------------|------------|---|-------------|--------------------|-------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | | | \$5.00 |
| | | | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | Quantity | Total Cost |
|-----------|---------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | 11310047 | 08/02/2023 07:00:00 | 08/02/2023 07:15:00 | 0.25 | \$29.50 |
| 03-33-004 | REPLACE NEW SPARK PLUGS | 11310047 | 07/28/2023 13:02:44 | 07/28/2023 13:10:08 | 0.12 | \$14.55 |
| 03-32-002 | REPLACE NEW BATTERY | 11310047 | 07/28/2023 09:42:12 | 07/28/2023 09:49:52 | 0.13 | \$15.08 |
| 06-22-014 | INSPECT REAR AXLE BEARING | 11310047 | 07/27/2023 14:30:00 | 07/28/2023 08:37:48 | 18.13 | \$2,139.34 |
| 06-22-014 | INSPECT REAR AXLE BEARING | 11310047 | 07/27/2023 13:00:00 | 07/27/2023 14:15:00 | 1.25 | \$147.50 |
| 06-22-014 | INSPECT REAR AXLE BEARING | 11310047 | 07/27/2023 12:40:10 | 07/27/2023 12:40:10 | 0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12201267 | 07/28/2023 07:32:27 | 07/28/2023 07:48:04 | 0.26 | \$30.71 |
| 03-34-017 | REPLACE NEW HEADLIGHT/TAILIGHT SOCKET | 11310047 | 07/26/2023 11:12:30 | 07/26/2023 11:51:28 | 0.65 | \$76.63 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 11310047 | 07/26/2023 09:30:00 | 07/26/2023 11:12:30 | 1.71 | \$201.58 |

| Job Code 66-17-029 | <u>Job Description</u> PERFORM ROTATE AND BALANCE TIRES | Employee No. 11310047 | <u>Start</u> 07/26/2023 07:36:29 | <u>Finish</u> 07/26/2023 09:15:00 | | Quantity 1.64 | <u>Total Cost</u> \$193.75 |
|---------------------------|---|------------------------------|---|-----------------------------------|------------|------------------|-------------------------------|
| 03-18-001 | REPLACE NEW FRONT AXLE HUBS & BEARINGS | 11310047 | 07/25/2023 14:30:00 | 07/25/2023 15:52:00 | | 1.37 | \$161.27 |
| 03-18-001 | REPLACE NEW FRONT AXLE HUBS & BEARINGS | 11310047 | 07/25/2023 13:01:02 | 07/25/2023 14:15:00 | | 1.23 | \$145.47 |
| | | | | | | LABOR | 3155.38 |
| Job Code | Job Description | Part No. | Descr | <u>iption</u> | Unit Price | Quantity | Total Cost |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL | THOMAS CAM2 | 7.53 | 7 | \$52.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | | 5.64 | 1 | \$5.64 |
| 03-32-002 | REPLACE NEW BATTERY | 94RH7 | BATTERY BCI 94R DIN | I H7 800 CCA | 221.08 | 1 | \$221.08 |
| 03-18-001 | REPLACE NEW FRONT AXLE HUBS & BEARINGS | C111 | RED BRAKE CLEANER | ₹ | 6.32 | 1 | \$6.32 |
| 03-34-017 | REPLACE NEW HEADLIGHT/TAILIGHT SOCKET | 1255H11 | BULB-HALOGEN | | 11.36 | 1 | \$11.36 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58125 | 1.50 OZ WHEEL WEIG | НТ | 0.99 | 1 | \$0.99 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58126 | 1.75 OZ WHEEL WEIG | HT | 0.74 | 4 | \$2.94 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58125 | 1.50 OZ WHEEL WEIG | НТ | 0.99 | (1) | (\$0.99) |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58125 | 1.50 OZ WHEEL WEIG | НТ | 0.99 | 2 | \$1.98 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58121 | .50 OZ WHEEL WEIGH | IT | 0.50 | 1 | \$0.50 |
| 03-34-017 | REPLACE NEW HEADLIGHT/TAILIGHT SOCKET | PIC5340PT | HEADLIGHT SOCKET | | 6.20 | 1 | \$6.20 |
| 03-18-001 | REPLACE NEW FRONT AXLE HUBS & BEARINGS | SKFBR930824 | HUB ASSEMBLY | | 386.60 | 1 | \$386.60 |
| 03-33-004 | REPLACE NEW SPARK PLUGS | ACS41110 | SPARK PLUGS | | 16.64 | 8 | \$133.08 |
| 03-33-004 | REPLACE NEW SPARK PLUGS | STW27873 | SPARK PLUG WIRE SE | ΞT | 83.88 | 1 | \$83.88 |
| 06-22-014 | INSPECT REAR AXLE BEARING | LOP10047 | 75W90 SYN FLUID LU | CAS | 20.93 | 1 | \$20.93 |
| 06-22-014 | INSPECT REAR AXLE BEARING | LUB42851 | LIMITED SLIP ADDITIV | Æ | 11.63 | 1 | \$11.63 |
| 06-22-014 | INSPECT REAR AXLE BEARING | 23337021 | AXLE O-RING | | 24.53 | 1 | \$24.53 |
| 06-22-014 | INSPECT REAR AXLE BEARING | 20889025 | AXLE SEAL | | 117.18 | 1 | \$117.18 |
| 06-22-014 | INSPECT REAR AXLE BEARING | 20920620 | REAR AXLE GASKET | | 28.59 | 1 | \$28.59 |
| 06-22-014 | INSPECT REAR AXLE BEARING | LOP10047 | 75W90 SYN FLUID LU | CAS | 20.93 | (1) | (\$20.93) |
| 06-22-014 | INSPECT REAR AXLE BEARING | LOP10047 | 75W90 SYN FLUID LU | CAS | 20.92 | 3 | \$62.77 |
| | | | | | | PARTS | 1156.99 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 47721

Work Order Notes

(EHANNAH) Tune -up- Pm - rotate and bale tires- charge AC - head lights replaced- noise when driving

Job Notes

03-18-001 - REPLACE NEW FRONT AXLE HUBS & BEARINGS

(EHOWELL) The Right Front hub bearing assembly had a noise that could be heard while turning the hub by hand. Replaced RF wheel hub assembly. EH

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) The battery had low CCA. Installed a new battery. EH/GC

03-33-004 - REPLACE NEW SPARK PLUGS

(EHOWELL) Replaced all spark plugs and spark plug wires. Checked plug gaps using a feeler gauge and applied dielectric grease to plug wires. EH

03-34-017 - REPLACE NEW HEADLIGHT/TAILIGHT SOCKET

(EHOWELL) The left low beam bulb was blown and the connector was black where it had gotten hot. Soldered in a new pigtail connector and installed a new bulb. EH .5 HR

06-22-014 - INSPECT REAR AXLE BEARING

(EHOWELL) Checked for noise related TSBs, but did not find any. The vehicle was driven on the drive on rack by an assistant while the technician listened for a noise using a stethoscope. The noise seems to be coming from the rear end. The right rear axle was removed and the hub bearing was inspected. No signs of damaged was found. Installed a new wheel seal and reassembled hub. Installed a new axle gasket and torqued axle bolts with a torque wrench. Drained rear differential fluid and inspected for metal on the drain plug magnet. No excessive metal was found. Filled differential with Lucas oil as well as a limited slip friction modifier supplement. If this does not quieten down the noise, then the rear differential will need to be rebuilt. EH 2.5 HRS

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Did not perform Evacuation and recharge. The AC is blowing cold at approximately 45 degrees F. EH

66-17-029 - PERFORM ROTATE AND BALANCE TIRES

(EHOWELL) Removed dirty build up from the inside of the wheels. Rotated and balanced tires. Relearned tire positions. EH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

| UNIT NO: | | 243732 2019 | 9 CHE | VROLE | ET 250 | 00 TRU | ICK 4X4 | | WORK OR | DER NO | : 48 | 790 | | |
|---|---------------|--|---------|-------------------------------------|---------------|---------|----------------------|---|---|---------------------------|------------------------|------------|--------------|---------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | | OPENE COMPL CLOSE Chevrole | ETED D DAT | DATE: | 11/02/20 11/03/20 | 23 10:16:13 23 10:45:45 23 07:32:34 | LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL | : 102577 DATE : | ME 04/10/202 | TER 2 - H: | 5 | |
| JOB CODE | 1 | JOB DESCRIPTION | | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOR</u> | MATE | RIAL CO | OMMERCIAL | TOTAL | COST |
| 03-51-038 | REPLAC | E NEW WIPER BLADES | | DON | Р | N | GARAGE | 0.48 | \$56.41 | \$21.69 | \$0. | 00 | \$78.10 | |
| 66-17-033 | PERFOR | RM TIRE ROTATION AND | BRAKE | DON | Р | N | GARAGE | 0.55 | \$64.51 | \$0.00 | \$0. | 00 | \$64.51 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | N | GARAGE | 0.27 | \$31.66 | \$94.05 | \$0. | 00 | \$125.71 | |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5. | 00 | \$5.00 | |
| JOB COUN | IT: 4 | | | | wo | RK ORI | DER TOTAL | : 1.29 | 152. | 58 | 115.74 | 5.00 |) | 273.32 |
| Job Code | | Job Description | | | V | endor N | l <u>o.</u> | Invoice No. | <u>Purchas</u> | e Order No | <u>).</u> | | <u>Total</u> | l Cost |
| CH-SP | CHARGE SI | nop Supplies | | 5 | 03163 | | 1 | | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | | 5.00 |
| Job Code | | Job Description | | | <u>En</u> | nployee | No. | <u>Start</u> | <u>F</u> | <u>inish</u> | | Quantity | <u>Total</u> | l Cost |
| 66-17-033 | PERFORM T | TIRE ROTATION AND BRAK | E INSPE | CTION 1 | 1074414 | ļ | 1 | 1/02/2023 08:09:23 | 11/02/2023 | 3 08:42:11 | | 0.55 | | \$64.51 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | | 1 | 1074414 | ļ | 1 | 1/02/2023 07:19:55 | 11/02/2023 | 3 07:48:36 | | 0.48 | | \$56.41 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 1 | 1074414 | ļ | 1 | 1/02/2023 07:02:41 | 11/02/2023 | 3 07:18:47 | | 0.27 | | \$31.66 |
| | | | | | | | | | | | | LABOR | | 152.58 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | Des | cription | <u> </u> | Jnit Price | Quantity | <u>Total</u> | l Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | Р | A5314F | | Α | IR FILTER | | | 22.16 | 1 | | \$22.16 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | ٧ | /IX5706 | 0 | 0 | IL FILTER | | | 5.64 | 1 | | \$5.64 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | 5 | W30T | | 5' | W30 SYNTHETIC (| OIL THOMAS CA | M2 | 9.46 | 7 | | \$66.25 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | | 1 | 9220 | | W | IPER 22 IN OE BE | AM | | 10.85 | 2 | | \$21.69 |
| | | | | | | | | | | | | PARTS | | 115.74 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 48790

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires adjusted tire pressure relearned tire positions inspected brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

| UNIT NO: | | 243732 2 | 019 CHE | VROLE | ET 250 | 00 TRU | ICK 4X4 | | WORK (| ORDER NO | : 49 | 9056 | |
|---|---------------|--|----------|-------------------------------------|---------------|-------------|-----------------------|---|--------------|-------------------------|-----------------------|--|-------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | | OPENE COMPL CLOSE Chevrole | ETED D DAT | DATE: E: | 11/30/202 12/01/20 | 23 10:35:06 23 09:36:08 23 11:41:16 | | - M: 102577 CE DATE: | MI 04/10/20 | y Automotive S ETER 2 - H: 20 REG8K124189 | 5 |
| JOB CODE | | JOB DESCRIPTION | <u>l</u> | STAT | <u>RSN</u> | WRTY | JOB LOC | LABOR HRS | LABO | R MATE | RIAL C | OMMERCIAL | TOTAL COST |
| 03-17-008 | REPLAC | E NEW VALVE ASSE | MBLY | DON | N | N | GARAGE | 0.40 | \$47.20 | \$5.05 | \$0 | 0.00 | \$52.25 |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5 | 5.00 | \$5.00 |
| JOB COUN | IT: 2 | | | | WC | RK ORI | DER TOTAL | : 0.40 | | 7.20 | 5.05 | 5.00 | 57.25 |
| Job Code | | Job Description | <u>1</u> | | <u>v</u> | endor N | <u>lo.</u> | Invoice No. | <u>Purch</u> | ase Order No | <u>).</u> | | Total Cost |
| CH-SP | CHARGE Sh | op Supplies | | 50 | 03163 | | 1 | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | 5.00 |
| Job Code | | Job Description | <u>1</u> | | <u>En</u> | nployee | No. | <u>Start</u> | | <u>Finish</u> | | Quantity | Total Cost |
| 03-17-008 | REPLACE N | EW VALVE ASSEMBLY | | 1: | 2395904 | 1 | 11 | /30/2023 07:00:00 | 11/30/2 | 023 07:24:00 | | 0.40 | \$47.20 |
| | | | | | | | | | | | | LABOR | 47.20 |
| Job Code | | Job Description | <u>1</u> | | | Part No | <u>.</u> | <u>Des</u> | cription | <u>!</u> | <u> Unit Price</u> | Quantity | Total Cost |
| 03-17-008 | REPLACE N | EW VALVE ASSEMBLY | | 5 | 8127 | | 2. | 00 OZ WHEEL WE | EIGHT | | 0.85 | 1 | \$0.85 |
| 03-17-008 | REPLACE N | EW VALVE ASSEMBLY | | 5 | 8121 | | .5 | O OZ WHEEL WEI | GHT | | 0.50 | 1 | \$0.50 |
| 03-17-008 | REPLACE N | EW VALVE ASSEMBLY | | 5 | 8120 | | .2 | 5 OZ WHEEL WEI | GHT | | 0.29 | 1 | \$0.29 |
| 03-17-008 | REPLACE N | EW VALVE ASSEMBLY | | 2 | 3131 | | TF | PMS SNAP IN VAL | VE 21060 | | 3.41 | 1 | \$3.41 |
| | | | | | | | | | | | | PARTS | 5.05 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 49056

Work Order Notes

(EHANNAH) inspect tire pressure

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(LISAPATE) FC installed 4 new valve stems.

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

| UNIT NO: | | 243732 201 | 19 CHEVROLE | ET 25 | 00 TRU | CK 4X4 | | WORK OF | RDER NO: | 49 | 9315 | | |
|---|--------------|--|--|---------------|----------|------------------------|---|--|--------------------|-----------------------|---|---------|---------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: EASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | OPENE COMPL CLOSE 2019 Chevrole | ETED D DAT | DATE: | 01/04/202 01/05/202 | 23 13:49:23 24 09:37:53 24 07:57:43 | LOCATION: METER 1 - M IN-SERVICE UNIT SERIA | M: 102577 DATE: | MI 04/10/20 | y Automotive S ETER 2 - H: 20 REG8K124189 | 5 | |
| JOB CODE | | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATER | RIAL C | OMMERCIAL | TOTAL C | COST |
| 03-34-001 | REPLAC | E NEW HEADLAMPS | DON | Ν | N | GARAGE | 0.01 | \$1.64 | \$11.67 | \$0 | 0.00 | \$13.31 | |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5 | 5.00 | \$5.00 | |
| JOB COUN | T: 2 | | | wc | ORK ORE | DER TOTAL: | 0.01 | 1. | .64 | 11.67 | 5.00 | | 18.31 |
| Job Code | | Job Description | | <u>7</u> | /endor N | <u>o.</u> | Invoice No. | <u>Purchas</u> | se Order No. | <u>.</u> | | Total C | ost |
| CH-SP | CHARGE SI | nop Supplies | 50 | 03163 | | 1 | | | | | | | \$5.00 |
| | | | | | | | | | | | COMML | | 5.00 |
| Job Code | | Job Description | | <u>E</u> r | nployee | No. | <u>Start</u> | <u> </u> | inish . | | Quantity | Total C | ost |
| 03-34-001 | REPLACE N | IEW HEADLAMPS | 1: | 205218 | 7 | 12/ | 20/2023 14:06:09 | 12/20/202 | 3 14:06:59 | | 0.01 | | \$1.64 |
| | | | | | | | | | | | LABOR | | 1.64 |
| Job Code | | Job Description | | | Part No | <u>.</u> | Des | <u>cription</u> | <u>U</u> | nit Price | Quantity | Total C | ost |
| 03-34-001 | REPLACE N | IEW HEADLAMPS | 1: | 255H11 | | BU | LB-HALOGEN | | | 11.67 | 1 | | \$11.67 |
| | | | | | | | | | | | PARTS | | 11.67 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 49315

Work Order Notes

(EHANNAH) replace new headlamps

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

(GARAGE) Replaced passenger low beam headlight. JAW

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

| UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 | WORK ORDER NO: | 49703 |
|---|----------------|-------|
|---|----------------|-------|

USING DEPT NO: 204902 OPENED DATE: 02/06/2024 07:09:53 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 02/09/2024 15:00:28
 METER 1 - M:
 108760
 METER 2 - H:
 5

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 02/12/2024 07:47:58
 IN-SERVICE DATE:
 04/10/2020

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 02/12/2024 07:47:58
 IN-SERVICE DATE:
 04/10/2020

 TECH SPEC NO:
 19CHEV25004X4
 2019 Chevrolet Silverado 2500 4X4
 UNIT SERIAL NO:
 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | <u>LABOR</u> | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|-----------------------------------|-------------|------|------|-----------|-----------|--------------|------------|------------|------------|
| 03-34-002 | REPLACE NEW LAMPS-REAR, TAIL, STO | DON | N | N | GARAGE | 0.11 | \$12.72 | \$1.71 | \$0.00 | \$14.43 |
| 03-35-010 | REPLACE NEW FUSE BLOCK | DON | N | N | GARAGE | 0.10 | \$11.64 | \$214.71 | \$0.00 | \$226.35 |
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | Р | N | GARAGE | 0.06 | \$7.24 | \$21.69 | \$0.00 | \$28.93 |
| 06-15 | INSPECT STEERING | DON | N | N | GARAGE | 0.48 | \$56.21 | \$0.00 | \$0.00 | \$56.21 |
| 24-52-003 | REPAIR RADIO | DON | N | N | GARAGE | 0.05 | \$5.38 | \$0.00 | \$0.00 | \$5.38 |
| 66-17-013 | PERFORM ALIGNMENT | DON | N | N | GARAGE | 0.25 | \$30.02 | \$0.00 | \$0.00 | \$30.02 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | N | N | GARAGE | 1.55 | \$183.16 | \$1,494.00 | \$0.00 | \$1,677.16 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.71 | \$83.91 | \$71.79 | \$0.00 | \$155.70 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| IOD COUNT | • | | 14/0 | DI | SED TOTAL | 0.04 | 000.6 | 4 000 0 | | 0.400.40 |

| JOB COUNT: 9 | WORK ORDER TOTAL: | 3.31 | 390.28 | 1,803.90 | 5.00 | 2,199.18 |
|--------------|-------------------|------|--------|----------|------|----------|
| | | | | | | |

| Job Code | Job Description | Vendor No. | | Invoice No. | Purchase Order No. | | Total Cost |
|----------|----------------------|------------|---|-------------|--------------------|-------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | | | \$5.00 |
| | | | | | | COMMI | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---|--------------|---------------------|---------------------|----------|------------|
| 24-52-003 | REPAIR RADIO | 12052187 | 02/08/2024 07:59:37 | 02/08/2024 08:02:21 | 0.05 | \$5.38 |
| 66-17-013 | PERFORM ALIGNMENT | 12052187 | 02/08/2024 07:44:21 | 02/08/2024 07:59:37 | 0.25 | \$30.02 |
| 03-35-010 | REPLACE NEW FUSE BLOCK | 12052187 | 02/07/2024 15:29:39 | 02/07/2024 15:35:34 | 0.10 | \$11.64 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 02/07/2024 10:08:33 | 02/07/2024 10:52:17 | 0.73 | \$86.01 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 02/07/2024 09:30:00 | 02/07/2024 09:43:54 | 0.23 | \$27.34 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 02/07/2024 08:39:30 | 02/07/2024 09:15:00 | 0.59 | \$69.82 |
| 06-15 | INSPECT STEERING | 11074414 | 02/06/2024 08:31:44 | 02/06/2024 09:00:19 | 0.48 | \$56.21 |
| 03-34-002 | REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC | 11074414 | 02/06/2024 08:25:16 | 02/06/2024 08:31:44 | 0.11 | \$12.72 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 11074414 | 02/06/2024 08:06:19 | 02/06/2024 08:10:00 | 0.06 | \$7.24 |

| Job Code 66-PM-PMA | <u>Job Description</u> PERFORM OIL CHANGE | Employee No. 11074414 | <u>Start</u> 02/06/2024 07:23:39 | <u>Finish</u> 02/06/2024 08:06:19 | | Quantity 0.71 | Total Cost \$83.91 |
|-----------------------|---|------------------------------|---|--------------------------------------|------------|------------------|-----------------------|
| | | | | | | LABOR | 390.29 |
| Job Code | Job Description | Part No. | Descri | <u>iption</u> | Unit Price | Quantity | Total Cost |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 1 | 10.85 | 2 | \$21.69 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL | THOMAS CAM2 | 9.45 | 7 | \$66.15 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | | 5.64 | 1 | \$5.64 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BF0 | A/T KO2 | 368.10 | 4 | \$1,472.40 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BF0 | A/T KO2 | 368.10 | (4) | (\$1,472.40) |
| 03-34-002 | REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC | 7443 | BULB- TAILLIGHT | | 1.71 | 1 | \$1.71 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58120 | .25 OZ WHEEL WEIGHT | | 0.29 | 2 | \$0.57 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58122 | .75 OZ WHEEL WEIGH | Т | 0.84 | 1 | \$0.84 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58124 | 1.25 OZ WHEEL WEIGI | HT | 0.60 | 1 | \$0.60 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58125 | 1.50 OZ WHEEL WEIGI | HT | 0.99 | 1 | \$0.99 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58127 | 2.00 OZ WHEEL WEIGI | HT | 1.38 | 3 | \$4.14 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE | 21060 | 3.62 | 4 | \$14.46 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BF0 | A/T KO2 | 368.25 | 4 | \$1,473.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BF0 | A/T KO2 | 368.25 | (4) | (\$1,473.00) |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 40855 | TIRE LT265/70R18 BF0 | A/T KO2 | 368.10 | 4 | \$1,472.40 |
| 03-35-010 | REPLACE NEW FUSE BLOCK | 23443946 | FUSE BLOCK | | 214.71 | 1 | \$214.71 |
| | | | | | | PARTS | 1803.90 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 49703

Work Order Notes

(EHANNAH) pm- radio went to black screen he wants it replaced, should be under warranty at electronic store on Hargrove., talk to Joe - mount and balance tires

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(GARAGE) Replaced the bottom left rear tail light bulb. Rechecks good. SH

03-35-010 - REPLACE NEW FUSE BLOCK

(GARAGE) Replaced fuse panel on passenger side. Radio is now working again. JAW .5 hr

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering. Found no issues at this time. SH

24-52-003 - REPAIR RADIO

(GARAGE) inspected and found no power coming from fuse panel on passenger side. checked fuses and all are good. Removed fuse panel and determined the panel is bad. Needs new fuse panel. JAW

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. Adjusted both front toe. Test drove and found no issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 4 tires. Inflated and deflated all 4 tires before setting to placard pressure. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

| UNIT NO: | | 243732 2019 (| CHEVROLE | T 250 | 00 TRU | CK 4X4 | | WORK O | RDER NO | : 50 | 599 | |
|--|--------------|--|--|---------------|-------------|------------------------|--|---|----------------------|---------------------|--|------------|
| USING DEP WO STATUS WO VISIT RI TECH SPEC | S: EASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | OPENE COMPL CLOSE 2019 Chevrole | ETED D DAT | DATE: E: | 04/17/202 04/18/202 | 4 11:42:53 4 15:01:29 4 07:21:12 | LOCATION METER 1 - IN-SERVIC UNIT SERI | M: 108760 E DATE: | ME 04/10/202 | Automotive S TER 2 - H: 20 EG8K124189 | 5 |
| JOB CODE | <u>.</u> | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATE | RIAL CO | MMERCIAL | TOTAL COST |
| 03-17-008 | REPLAC | E NEW VALVE ASSEMBLY | DON | N | Ν | GARAGE | 0.00 | \$0.00 | \$3.50 | \$0.0 | 00 | \$3.50 |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$3.: | 50 | \$3.50 |
| JOB COUN | T: 2 | | | WC | RK ORE | DER TOTAL: | 0.00 | (| 0.00 | 3.50 | 3.50 | 7.00 |
| Job Code | | Job Description | | <u>v</u> | endor N | <u>o.</u> | Invoice No. | <u>Purcha</u> | ase Order No | <u>).</u> | | Total Cost |
| CH-SP | CHARGE SI | nop Supplies | 50 | 03163 | | 1 | | | | | | \$3.50 |
| | | | | | | | | | | | COMML | 3.50 |
| Job Code | | Job Description | | | Part No | <u>-</u> | Des | <u>cription</u> | <u>।</u> | Jnit Price | Quantity | Total Cost |
| 03-17-008 | REPLACE N | IEW VALVE ASSEMBLY | 23 | 3131 | | TP | MS SNAP IN VAL | VE 21060 | | 3.50 | 1 | \$3.50 |
| | | | | | | | | | | | PARTS | 3.50 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 50599

Work Order Notes

(LRUSHING) Replace valve stem right rear

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(LRUSHING) Scott replaced the right rear valve stem

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

| UNIT NO: | 243732 | 2019 CHEVROLET 2500 TRUCK 4X4 | WORK ORDER NO: | 50853 | |
|----------|--------|-------------------------------|----------------|-------|--|
|----------|--------|-------------------------------|----------------|-------|--|

USING DEPT NO: 204902 OPENED DATE: 05/15/2024 10:09:31 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 05/17/2024 08:04:41
 METER 1 - M:
 116174
 METER 2 - H:
 5

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 05/17/2024 09:50:13
 IN-SERVICE DATE:
 04/10/2020

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 05/17/2024 09:50:13
 IN-SERVICE DATE:
 04/10/2020

 TECH SPEC NO:
 19CHEV25004X4
 2019 Chevrolet Silverado 2500 4X4
 UNIT SERIAL NO:
 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | WRTY | JOB LOC | LABOR HRS | <u>LAB</u> | OR MATERIA | L COMMERCIA | L TOTAL COST |
|-----------|-----------------------------------|-------------|------------|--------|------------|-----------|------------|------------|-------------|--------------|
| 03-34-002 | REPLACE NEW LAMPS-REAR, TAIL, STO | DON | Р | Ν | GARAGE | 0.03 | \$3.34 | \$1.71 | \$0.00 | \$5.05 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRE | DON | Р | Ν | GARAGE | 0.01 | \$1.38 | \$4.25 | \$0.00 | \$5.63 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | Ν | GARAGE | 0.01 | \$0.92 | \$73.74 | \$0.00 | \$74.66 |
| CH-01 | CHARGE AIR CONDITIONING, HEAT, VE | DON | N | Ν | GARAGE | 0.61 | \$71.95 | \$0.00 | \$0.00 | \$71.95 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| WA-00 | WASH COMPLETE VEHICLE | DON | Р | N | GARAGE | 0.01 | \$1.11 | \$0.00 | \$0.00 | \$1.11 |
| JOB COUNT | : 6 | | WO | RK ORE | DER TOTAL: | 0.67 | • | 78.70 79 | .70 5.0 | 00 163.40 |

| Job Code | Job Description | Vendor No. | | Invoice No. | Purchase Order No. | | Total Cost |
|----------|----------------------|------------|---|-------------|--------------------|-------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | | | \$5.00 |
| | | | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | <u>Start</u> | <u>Finish</u> | Quantity | Total Cost |
|-----------|---|--------------|---------------------|---------------------|-----------------|-------------------|
| CH-01 | CHARGE AIR CONDITIONING, HEAT, VENT | 11310047 | 05/15/2024 15:15:43 | 05/15/2024 15:52:18 | 0.61 | \$71.95 |
| 03-34-002 | REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC | 12395904 | 05/15/2024 14:50:18 | 05/15/2024 14:52:00 | 0.03 | \$3.34 |
| WA-00 | WASH COMPLETE VEHICLE | 12395904 | 05/15/2024 14:49:20 | 05/15/2024 14:49:54 | 0.01 | \$1.11 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 12395904 | 05/15/2024 14:48:13 | 05/15/2024 14:48:55 | 0.01 | \$1.38 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 05/15/2024 14:47:12 | 05/15/2024 14:47:40 | 0.01 | \$0.92 |
| | | | | | LABOR | 78.70 |

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|---|----------|--------------------------------|-------------------|-----------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 7.76 | 7 | \$54.29 |
| 66-PM-PMA | PERFORM OIL CHANGE | PA4486 | CABIN AIR ELEMENT | 13.79 | 1 | \$13.79 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 5.66 | 1 | \$5.66 |
| 03-34-002 | REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC | 7443 | BULB- TAILLIGHT | 1.71 | 1 | \$1.71 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 63001 | 1/4 OZ STICK ON TAPE WEIGHT | 0.23 | 5 | \$1.13 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58103 | 1.00 OZ WHEEL WEIGHT | 0.51 | 1 | \$0.51 |
| | | | | | | |

The University of Alabama Work Order Charge Detail

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------|-------------------|----------|-------------------|
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 58122 | .75 OZ WHEEL WEIGHT | 0.84 | 1 | \$0.84 |
| 66-17-029 | PERFORM ROTATE AND BALANCE TIRES | 61133 | LT1 2.00 OZ WHEEL WEIGHT | 1.77 | 1 | \$1.77 |
| | | | | | PARTS | 79.70 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 50853

Work Order Notes

(EHANNAH) pm- wash- rotate and balance tires- charge AC

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(IFALLS) replaced new led bulb stop LR FC

66-17-029 - PERFORM ROTATE AND BALANCE TIRES

(IFALLS) rotate tires and 4 balanced FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-01 - CHARGE AIR CONDITIONING, HEAT, VENT

(EHOWELL) The AC is cooling at 42 degrees F. No problem found. EH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

| UNIT NO: | | 243732 2019 CH | IEVROLE | T 250 | 00 TRU | CK 4X4 | | WORK O | RDER NO | : 51 | 1496 | |
|---|---------------|---|-------------------------|---------------|-------------|----------------------|---|---------------|----------------------|--------------------|---|------------|
| USING DEF WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 20 ⁻² | OPENE COMPL CLOSE | ETED D DAT | DATE: E: | 07/22/20 07/22/20 | 24 11:09:26 24 08:03:38 24 08:03:41 | | M: 116174 E DATE: | ME 04/10/20 | y Automotive : ETER 2 - H: 20 EG8K124189 | 5 |
| JOB CODE | <u> </u> | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATE | RIAL C | OMMERCIAL | TOTAL COST |
| 03-17-008 | REPLAC | E NEW VALVE ASSEMBLY | DON | Ν | Ν | GARAGE | 0.03 | \$3.15 | \$3.33 | \$0 | .00 | \$6.48 |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5 | .00 | \$5.00 |
| JOB COUN | IT: 2 | | | WC | RK ORI | DER TOTAL | : 0.03 | 3 | 3.15 | 3.33 | 5.00 | 11.48 |
| Job Code | | Job Description | | <u>v</u> | endor N | <u>o.</u> | Invoice No. | <u>Purcha</u> | se Order No | <u>).</u> | | Total Cost |
| CH-SP | CHARGE SI | nop Supplies | 5 | 03163 | | 1 | | | | | - | \$5.00 |
| | | | | | | | | | | | COMML | 5.00 |
| Job Code | | Job Description | | <u>En</u> | nployee | No. | <u>Start</u> | | Finish | | Quantity | Total Cost |
| 03-17-008 | REPLACE N | IEW VALVE ASSEMBLY | 1: | 2201267 | 7 | 07 | 7/16/2024 15:38:57 | 07/16/20 | 24 15:40:33 | | 0.03 | \$3.15 |
| | | | | | | | | | | | LABOR | 3.15 |
| Job Code | | Job Description | | | Part No | <u>.</u> | Des | cription | <u> </u> | Jnit Price | Quantity | Total Cost |
| 03-17-008 | REPLACE N | IEW VALVE ASSEMBLY | 2 | 3131 | | TF | PMS SNAP IN VAL | VE 21060 | | 3.33 | 1 | \$3.33 |
| | | | | | | | | | | | PARTS | 3.33 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 51496

Work Order Notes

(LRUSHING) left rear tire is low

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(GRCOOK) Pulled tire and broke down one side of tire and replaced valve steam on rim. Installed new valve steam and aired tire back up and checked new valve steam for leaks, found no issues. -GC

66-17-030 - PERFORM TIRE PATCH

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

| UNIT NO: | 243732 | 2019 CHEVROLET 2500 TRUCK 4X4 | WORK ORDER NO: | 51937 | |
|----------|--------|-------------------------------|----------------|-------|--|
| | | | | | |

USING DEPT NO: 204902 OPENED DATE: 08/26/2024 10:50:41 LOCATION: GARAGE - University Automotive Services

WO STATUS: CLOSED **COMPLETED DATE:** 08/29/2024 08:23:37 **METER 1 - M:** 116174 **METER 2 - H:** 5

WO VISIT REASON: SCHEDULED **CLOSED DATE:** 08/29/2024 11:41:16 **IN-SERVICE DATE:** 04/10/2020

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 UNIT SERIAL NO: 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABO | R MATERI | AL COMME | RCIAL TOTAL | _COST |
|-----------|-----------------------------------|-------------|------------|-------------|------------|-----------|--------|----------|----------|-------------|--------|
| 03-34-003 | REPLACE NEW SIGNAL, PARKING, & BA | DON | Ν | Ν | GARAGE | 0.00 | \$0.00 | \$6.84 | \$0.00 | \$6.84 | |
| 03-34-010 | REPLACE NEW TAG LIGHT | DON | N | Ν | GARAGE | 0.00 | \$0.00 | \$0.39 | \$0.00 | \$0.39 | |
| 03-34-020 | REPLACE NEW THIRD BRAKE LIGHT BI | DON | Ν | N | GARAGE | 0.00 | \$0.00 | \$1.13 | \$0.00 | \$1.13 | |
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | Р | N | GARAGE | 0.00 | \$0.00 | \$22.50 | \$0.00 | \$22.50 | |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.00 | \$0.00 | \$85.80 | \$0.00 | \$85.80 | |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 | |
| JOB COUNT | : 6 | | wo | RK ORI | DER TOTAL: | 0.00 | | 0.00 11 | 6.66 | 5.00 | 121.66 |

Job CodeJob DescriptionVendor No.Invoice No.Purchase Order No.Total CostCH-SPCHARGE Shop Supplies5031631\$5.00COMML5.00

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|--|--------------------|--------------------------------|-------------------|----------|------------|
| 03-34-003 | REPLACE NEW SIGNAL, PARKING, & BACKUP LAMP | S 7443 | BULB- TAILLIGHT | 1.71 | 4 | \$6.84 |
| 03-34-020 | REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY | 912 | BULB-BRAKE-3RD | 1.13 | 1 | \$1.13 |
| 03-34-010 | REPLACE NEW TAG LIGHT | 194 | BULB-TAG/MARKER | 0.39 | 1 | \$0.39 |
| 66-PM-PMA | PERFORM OIL CHANGE | ANTIFREEZE DEXCOOL | ANTIFREEZE-GM | 23.45 | 1 | \$23.45 |
| 03-51-038 | REPLACE NEW WIPER BLADES | XC22 | 22" WIPER | 11.25 | 2 | \$22.50 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30BT | 5W30 BULK | 7.01 | 7 | \$49.04 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 5.66 | 1 | \$5.66 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 7.65 | 1 | \$7.65 |
| | | | | | PARTS | 116.66 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 51937

Work Order Notes

(EHANNAH) PM- WIPERS- WASH

Job Notes

03-34-003 - REPLACE NEW SIGNAL, PARKING, & BACKUP LAMPS

(EHOWELL) Replaced 4 front turn signal bulbs. It was necessary to partially remove the grille and head lamps. EH/CM

03-34-010 - REPLACE NEW TAG LIGHT

(EHOWELL) Replaced tag light bulb.

03-34-020 - REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY

(EHOWELL) Replaced third brake light bulb.

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) Wipers were replaced.

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) PM was performed. CM checked tire pressures. Battery checked good.

| UNIT NO: | | 243732 201 | 9 CHE | VROLE | ET 250 | 00 TRU | CK 4X4 | | WORK O | RDER NO | : 52 | 097 | |
|---|---------------------|--|-------|-------------------------------------|---------------|----------------|------------------------|--|-----------------|--------------|---------------------|------------|------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | | OPENE COMPL CLOSE Chevrole | ETED D DAT | DATE: | 09/11/202 09/11/202 | 4 10:40:16 4 15:51:03 4 15:51:03 | | | ME 04/10/202 | TER 2 - H: | 5 |
| JOB CODE | _ | JOB DESCRIPTION | | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATE | RIAL CO | MMERCIAL | TOTAL COST |
| 03-34-001 | REPLAC | E NEW HEADLAMPS | | DON | N | Ν | GARAGE | 0.00 | \$0.00 | \$11.82 | \$0.0 | 00 | \$11.82 |
| 06-34-017 | INSPEC ⁻ | T HEADLIGHT/TAILIGHT | SOCKE | DON | Ν | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.0 | 00 | \$0.00 |
| CH-SP | CHARGE | E Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.0 | 00 | \$5.00 |
| JOB COUN | IT: 3 | | | | WC | RK ORI | DER TOTAL: | 0.00 | (| 0.00 | 11.82 | 5.00 | 16.82 |
| Job Code | | Job Description | | | <u>v</u> | <u>endor N</u> | <u>o.</u> | Invoice No. | <u>Purcha</u> | ase Order No | <u>).</u> | | Total Cost |
| CH-SP | CHARGE SI | nop Supplies | | 5 | 03163 | | 1 | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | 5.00 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | <u>Des</u> | <u>cription</u> | <u> </u> | Jnit Price | Quantity | Total Cost |
| 03-34-001 | REPLACE N | IEW HEADLAMPS | | 1: | 255H11 | | BU | LB-HALOGEN | | | 11.82 | 1 | \$11.82 |
| 06-34-017 | INSPECT H | EADLIGHT/TAILIGHT SOCI | KET | 1: | 255H11 | | BU | LB-HALOGEN | | | 11.82 | (1) | (\$11.82) |
| 06-34-017 | INSPECT H | EADLIGHT/TAILIGHT SOCI | KET | 1: | 255H11 | | BU | LB-HALOGEN | | | 11.82 | 1 | \$11.82 |
| | | | | | | | | | | | | PARTS | 11.82 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 52097

Work Order Notes

(EHANNAH) inspect headlights and taillights- wiring for both- this is a repeat problem. Please see if there is an issue with the wiring or a fuse.

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

(EHOWELL) Replaced top/left head lamp bulb. This bulb was not replaced during the previous visit. The connector was not burnt. Verified operation of all lights after repair. EH/CM

06-34-017 - INSPECT HEADLIGHT/TAILIGHT SOCKET

(EHOWELL) Found left head lamp bulb not illuminating.

| UNIT NO: | | 243732 2019 | CHEVROLE | T 25 | 00 TRU | ICK 4X4 | | WORK | ORDER NO |): 52 | 2577 | |
|---|---------------|--|--|---------------|-------------|------------------------|--|------------|--------------|--------------------------|-------------|------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | OPENE COMPL CLOSE 2019 Chevrole | ETED D DAT | DATE: E: | 10/24/202 10/24/202 | 4 10:36:51 4 07:44:03 4 08:36:28 | METER 1 | ICE DATE: | 3 M I 04/10/20 | ETER 2 - H: | 5 |
| JOB CODE | <u> </u> | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABO | OR MATE | RIAL C | OMMERCIAL | TOTAL COST |
| 66-79-003 | PERFOR | M SAFETY INSPECTION | DON | Υ | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0 | .00 | \$0.00 |
| 66-PM-PMA | PERFOR | M OIL CHANGE | DON | Р | N | GARAGE | 0.00 | \$0.00 | \$68.35 | \$0 | .00 | \$68.35 |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5 | .00 | \$5.00 |
| JOB COUN | IT: 3 | | | WC | RK ORI | DER TOTAL: | 0.00 | | 0.00 | 68.35 | 5.00 | 73.35 |
| Job Code | | Job Description | | <u>\</u> | endor N | lo. | Invoice No. | Purc | hase Order N | <u>o.</u> | | Total Cost |
| CH-SP | CHARGE Sh | op Supplies | 50 | 03163 | | 1 | | | | | | \$5.00 |
| | | | | | | | | | | | COMML | 5.00 |
| Job Code | | Job Description | | | Part No | <u>.</u> | <u>Des</u> | cription | | Unit Price | Quantity | Total Cost |
| 66-PM-PMA | PERFORM (| OIL CHANGE | 5\ | N30T | | 5W | 30 SYNTHETIC C | OIL THOMAS | S CAM2 | 8.96 | 7 | \$62.69 |
| 66-PM-PMA | PERFORM (| DIL CHANGE | 5\ | N30BT | | 5W | /30 BULK | | | 7.01 | (7) | (\$49.04) |
| 66-PM-PMA | PERFORM (| OIL CHANGE | W | /IX5706 | 0 | OII | FILTER | | | 5.66 | 1 | \$5.66 |
| 66-PM-PMA | PERFORM (| DIL CHANGE | 5\ | N30BT | | 5W | /30 BULK | | | 7.01 | 7 | \$49.04 |
| | | | | | | | | | | | PARTS | 68.35 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 52577

Work Order Notes

(CWIGLEY) PM

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed safety inspection, found no issues at this time, also rotated tires while doing safety inspection. FJ,GC Miles, 130,718

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm-GC, changed oil and oil filter, checked fluids, filters good, tires and tire pressure. Miles, 130,718

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

| UNIT NO: | 243732 | 2019 CHEVROLET 2500 TRUCK 4X4 | WORK ORDER NO: | 53302 |
|----------|--------|-------------------------------|----------------|-------|
| | | | | |

 USING DEPT NO:
 204902
 OPENED DATE:
 01/07/2025 10:29:02
 LOCATION:
 GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 01/08/2025 07:24:05
 METER 1 - M: 134484
 METER 2 - H: 5

WO VISIT REASON: SCHEDULED **CLOSED DATE:** 01/08/2025 08:37:56 **IN-SERVICE DATE:** 04/10/2020

TECH SPEC NO: 19CHEV25004X4 2019 Chevrolet Silverado 2500 4X4 **UNIT SERIAL NO:** 2GC2KREG8K1241891

| JOB CODE | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | <u>LABO</u> | R MATER | RIAL COMME | RCIAL TOTAL | COST |
|-----------|------------------------------------|-------------|------------|-------------|------------|-----------|-------------|---------|------------|-------------|-------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | Р | Ν | GARAGE | 0.00 | \$0.00 | \$21.69 | \$0.00 | \$21.69 | |
| 06-15 | INSPECT STEERING | DON | N | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | |
| 06-17 | INSPECT TIRES, TUBES, LINERS & VAL | DON | N | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | |
| 66-17-017 | PERFORM BALANCE TIRES | DON | Α | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | Р | N | GARAGE | 0.00 | \$0.00 | \$67.72 | \$0.00 | \$67.72 | |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 | |
| JOB COUNT | : 6 | | wo | RK ORE | DER TOTAL: | 0.00 | | 0.00 | 89.41 | 5.00 | 94.41 |

| Job Code | Job Description | Vendor No. | | Invoice No. | Purchase Order No. | | Total Cost |
|----------|------------------------|------------|---|-------------|--------------------|-------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | | | \$5.00 |
| | | | | | | COMML | 5.00 |

| Job Code | Job Description | Part No. | <u>Description</u> | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30T | 5W30 SYNTHETIC OIL THOMAS CAM2 | 8.87 | 7 | \$62.06 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30BT | 5W30 BULK | 6.40 | (7) | (\$44.83) |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.85 | 2 | \$21.69 |
| 66-PM-PMA | PERFORM OIL CHANGE | 22-1 | WIPER BLADE 22" TRICO EXACT | 8.33 | (2) | (\$16.65) |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30BT | 5W30 BULK | 6.40 | 7 | \$44.83 |
| 66-PM-PMA | PERFORM OIL CHANGE | WIX57060 | OIL FILTER | 5.66 | 1 | \$5.66 |
| 66-PM-PMA | PERFORM OIL CHANGE | 22-1 | WIPER BLADE 22" TRICO EXACT | 8.33 | 2 | \$16.65 |
| | | | | | PARTS | 89.41 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 53302

Work Order Notes

(EHANNAH) pm- wipers- wash- inspect tires and steering- Doug states there is a shimmy and wobble in the steering and front end (EHOWELL) Someone ran the customer off the road. A wrecker was called.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades.

06-15 - INSPECT STEERING

(GARAGE) CM- Inspected steering & front suspension. No damage at this time.

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) FJ- Inspected tires & wheels. Inner lip on LR** wheel is bent.

66-17-017 - PERFORM BALANCE TIRES

(GARAGE) FJ- Balanced & rotated tires.

wheel that is now on the LR is bent

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Oil change, set tire pressure, checked filters, recorded date codes & tread depths.

| UNIT NO: | | 243732 20 | 19 CHEVROLI | ET 25 | 00 TRU | CK 4X4 | | WORK | ORDER NO | 54 | 510 | |
|---|----------------------|--|--|---------------|-------------|------------------------|--|---------------------|---|---------------------|------------|------------|
| USING DEF WO STATUS WO VISIT F TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | OPENE COMPI CLOSE 2019 Chevrole | ETED D DAT | DATE: E: | 04/17/202 04/18/202 | 5 15:11:25 5 15:49:42 5 09:15:25 | METER 1 IN-SERVI | ON: GARAGE - M: 134484 ICE DATE: RIAL NO: | ME 04/10/202 | TER 2 - H: | 5 |
| JOB CODE | <u> </u> | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABC | <u>MATE</u> | RIAL CO | MMERCIAL | TOTAL COST |
| 66-17-030 | PERFOR | RM TIRE PATCH | DON | В | N | GARAGE | 0.00 | \$0.00 | \$2.90 | \$0.0 | 00 | \$2.90 |
| CH-SP | CHARGE | Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.9 | 90 | \$2.90 |
| JOB COUN | IT: 2 | | | WC | RK ORI | DER TOTAL: | 0.00 | | 0.00 | 2.90 | 2.90 | 5.80 |
| Job Code | | Job Description | | <u>v</u> | endor N | <u>o.</u> | Invoice No. | <u>Purc</u> | hase Order No | <u>.</u> | | Total Cost |
| CH-SP | CHARGE SI | nop Supplies | 5 | 03163 | | 1 | | | | | | \$2.90 |
| | | | | | | | | | | | COMML | 2.90 |
| Job Code | | Job Description | | | Part No | <u>.</u> | <u>Des</u> | <u>cription</u> | <u> </u> | Init Price | Quantity | Total Cost |
| 66-17-030 | PERFORM T | TIRE PATCH | 2 | 3131 | | TP | MS SNAP IN VAL | VE 21060 | | 2.90 | 1 | \$2.90 |
| 66-17-030 | PERFORM ⁻ | TIRE PATCH | 2 | 3131 | | TP | MS SNAP IN VAL | VE 21060 | | 2.90 | (1) | (\$2.90) |
| 66-17-030 | PERFORM ⁷ | TIRE PATCH | 2 | 3131 | | TP | MS SNAP IN VAL | VE 21060 | | 2.90 | 1 | \$2.90 |
| | | | | | | | | | | | PARTS | 2.90 |

The University of Alabama

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 54510

Work Order Notes

(EHANNAH) inspect tire going flat possible valve stem

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) CM & JR- patched RR tire, was not leaking

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) CM & JR- patched RR tire, was not leaking

| UNIT NO: | | 243732 | 2019 CHE | VROLE | ET 250 | 00 TRU | CK 4X4 | | WORK O | RDER NO |): 547 | 793 | |
|---|---------------|--|------------|-------------------------------------|-------------------|----------|------------------------|---|------------------|-------------|---------------------------|---------------|-------------------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 204902 CLOSED SCHEDULED 19CHEV25004X4 | 2019 (| OPENE COMPL CLOSE Chevrole | ETED D DAT | DATE: | 05/16/202 05/19/202 | 25 10:13:38 25 15:25:48 25 09:48:39 | | | ME [*] 04/10/202 | TER 2 - H: | 5 |
| JOB CODE | <u> </u> | JOB DESCRIPTION | <u>ON</u> | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | R MATE | RIAL CO | MMERCIAL | TOTAL COST |
| 03-21-002 | REPLAC | E NEW CV AXLES/ | SEALS | DON | N | N | GARAGE | 0.00 | \$0.00 | \$192.90 | \$0.0 | 00 | \$192.90 |
| 03-51-038 | REPLAC | E NEW WIPER BLA | ADES | DON | Р | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.0 | 00 | \$0.00 |
| 06-17 | INSPECT | Γ TIRES, TUBES, LI | NERS & VAL | DON | Р | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.0 | 00 | \$0.00 |
| 66-13-001 | PERFOR | RM FRONT BRAKES | S & ROTORS | DON | N | N | GARAGE | 0.00 | \$0.00 | \$288.70 | \$0.0 | 00 | \$288.70 |
| 66-13-130 | PERFOR | RM Burnish Brakes | | DON | N | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.0 | 00 | \$0.00 |
| 66-17-015 | | RM TIRE ROTATION | ı | DON | P | N | GARAGE | | \$0.00 | \$0.00 | \$0.0 | | \$0.00 |
| | | | | | | | | | | | | | |
| 66-17-017 | | RM BALANCE TIRES | 5 | DON | N | N | GARAGE | | \$0.00 | \$0.00 | \$0.0 | | \$0.00 |
| 66-PM-PMA | | RM OIL CHANGE | | DON | Р | N | GARAGE | | \$0.00 | \$82.09 | \$0.0 | | \$82.09 |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.0 | 00 | \$5.00 |
| JOB COUN | IT: 9 | | | | wo | RK ORI | DER TOTAL: | 0.00 | (| 0.00 | 563.69 | 5.00 | 568.69 |
| Job Code CH-SP | CHARGE SI | Job Descriptinop Supplies | <u>ion</u> | 5 | <u>V</u> 03163 | endor N | <u>o.</u> 1 | Invoice No. | Purch | ase Order N | <u>o.</u> | COMML | **Total Cost \$5.00 |
| Joh Codo | | Joh Dogovinti | ian . | | | Dort No. | | Doo | a win ti a n | | Unit Drice | Quantity | |
| Job Code 03-21-002 | DEDI ACE N | Job Descript IEW CV AXLES/SEAL | | ١٨ | /ONGM | Part No | | <u>Des</u> AXLE | <u>scription</u> | | Unit Price 192.90 | Quantity 1 | <u>Total Cost</u> \$192.90 |
| 66-PM-PMA | | OIL CHANGE | O | | A5314F | | | R FILTER | | | 25.86 | 1 | \$25.86 |
| 66-PM-PMA | | OIL CHANGE | | | W30BT | | | /30 BULK | | | 6.40 | 7 | \$44.83 |
| 66-PM-PMA | PERFORM (| OIL CHANGE | | ٧ | /IX5706 | 0 | OII | L FILTER | | | 11.40 | 1 | \$11.40 |
| 66-13-001 | PERFORM I | FRONT BRAKES & RO | OTORS | С | :111 | | RE | D BRAKE CLEAN | IER | | 6.44 | 1 | \$6.44 |
| 66-13-001 | PERFORM I | FRONT BRAKES & RO | OTORS | Р | WR171 | 565 | FR | ONT BRAKE PAD | S | | 87.23 | 1 | \$87.23 |
| 66-13-001 | PERFORM I | FRONT BRAKES & RO | OTORS | F | BRSB58 | 30875 | FR | ONT ROTORS | | | 97.52 | 2 | \$195.03 |
| | | | | | | | | | | | | PARTS | 563.69 |

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

UNIT NO: 243732 2019 CHEVROLET 2500 TRUCK 4X4 WORK ORDER NO: 54793

Work Order Notes

(EHANNAH) pm- wipers- wash- tire rotation- inspect front tires for mud and wobble.

Job Notes

03-21-002 - REPLACE NEW CV AXLES/SEALS

(GARAGE) replaced cv axle on front driver side, old unit was busted an leaking oil, cm 141748 miles, 1 hour labor

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Not needed at this time.

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) FJ- Inspected tires. Tire rotation performed due to wear. Tires balanced.

66-13-001 - PERFORM FRONT BRAKES & ROTORS

(GARAGE) test drove truck rotors were warped causing steering wheel to shack, replaced both front brake pads and rotors test drove checked ok, cm 2 hours labor (GARAGE) pad level was 4 mm

66-13-130 - PERFORM Burnish Brakes

(GARAGE) burnish brakes cm test drove checked ok, .5 labor

66-17-015 - PERFORM TIRE ROTATION

(GARAGE) FJ- Rotated tires due to excessive shoulder wear.

(EHOWELL) EH informed Doug that he had a bent wheel. We put the bent wheel on the rear of the vehicle. It sounds like Doug is leaning towards buying a new truck.

66-17-017 - PERFORM BALANCE TIRES

(EHOWELL) FJ balanced tires.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Mileage: 141,748. Oil change, checked filters (air filter replaced), topped off fluids, set tire pressure, recorded date codes & tread depths.

Report Printed: 06/09/2025 13:34:41 By User: GLOBETTI

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Mon Jun 09 2025 13:34:41 Report User: GLOBETTI

TZ: Central Standard Time

DLL Version: 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'243732') //Q=