

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 41342

USING DEPT NO:	500201	OPENED DATE:	10/15/2021 14:44:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2021 13:45:09	METER 1 - M:	281	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2021 13:45:14	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.10	\$11.80	\$72.43	\$0.00	\$84.23
14-55-041	INSTALL LADDER RACK	DON	O	N	GARAGE	2.00	\$236.00	\$209.40	\$0.00	\$445.40
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	1.13	\$132.85	\$9.75	\$0.00	\$142.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 5	WORK ORDER TOTAL:	4.23	498.65	291.58	2.00	792.23
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-55-041	INSTALL LADDER RACK	12052187	12/10/2021 07:00:00	12/10/2021 09:00:00	2.00	\$236.00
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	10208562	12/10/2021 07:00:00	12/10/2021 07:06:00	0.10	\$11.80
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11310047	12/10/2021 07:00:00	12/10/2021 08:00:00	1.00	\$118.00
14-78-044	INSTALL TOOLBOX ASSY	11213180	11/16/2021 14:30:00	11/16/2021 14:41:05	0.18	\$21.80
14-78-044	INSTALL TOOLBOX ASSY	11213180	11/16/2021 13:18:32	11/16/2021 14:15:00	0.94	\$111.05
				LABOR		498.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-55-041	INSTALL LADDER RACK	5/8" WASHER	5/8" WASHERS	0.68	8	\$5.40
14-55-041	INSTALL LADDER RACK	5/8" WASHER	5/8" WASHERS	0.68	(8)	(\$5.40)
14-78-044	INSTALL TOOLBOX ASSY	DORBOLT	BOLT	2.25	2	\$4.50
14-78-044	INSTALL TOOLBOX ASSY	DORBOLT	BOLT	2.63	2	\$5.25
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45405	RECEIVER REDUCER 2.5 TO 2 IN	18.57	1	\$18.57
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT40074	2 X 1 X 3 HITCH BALL	15.17	1	\$15.17
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45840	2" BALL MOUNT	19.94	1	\$19.94

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-55-041	INSTALL LADDER RACK	5/8" WASHER	5/8" WASHERS	0.68	8	\$5.40
14-55-041	INSTALL LADDER RACK	STEEL LADDER RACK	250LB LADDER RACK	204.00	1	\$204.00
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT23021	BRASS COUPLER LOCK W/KEYS	18.75	1	\$18.75
					PARTS	291.58

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 41342

Work Order Notes

(LISAPATE) New unit do PDI and install ladder rack assy

Job Notes

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(LISAPATE) EK installed receiver

14-55-041 - INSTALL LADDER RACK

(LISAPATE) JW installed ladder rack assy

14-78-044 - INSTALL TOOLBOX ASSY

(MSIDES) Installed toolbox in bed of truck. MS 1.0hrs

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) EH completed PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42512

USING DEPT NO:	500201	OPENED DATE:	03/01/2022 13:22:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2022 14:33:23	METER 1 - M:	2221	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2022 07:23:22	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.29	\$34.48	\$14.70	\$0.00	\$49.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.29	34.48	14.70	2.00	51.18
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	11074386	100633491		\$0.00
14-02-013	INSTALL FLOOR COVERINGS	11074386	100633491		\$0.00
14-02-013	INSTALL FLOOR COVERINGS	11074386	110633491		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	11901357	03/01/2022 14:45:30	03/01/2022 14:57:02	0.19	\$22.68
14-02-013	INSTALL FLOOR COVERINGS	10208562	03/01/2022 13:23:27	03/01/2022 13:29:27	0.10	\$11.80
LABOR						34.48

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	4410541V	FORD F250 FLOOR MATS	0.00	1	\$0.00
14-02-013	INSTALL FLOOR COVERINGS	FLOOR MAT CLIPS	FLOOR MAT CLIPS	3.68	4	\$14.70
PARTS						14.70

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42512

Work Order Notes

(EKIMBREL) INSTALL FLOOR MATS

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(EKIMBREL) WEATHER TECH FLOOR MATS NO LABOR. BILLED THROUGH LEASE PROGRAM.

(EKIMBREL) miles: 2221 Installed front floor mats w/ 4 floor clips. AMG

(EKIMBREL) shipping on commercial tab build to lease.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42867

USING DEPT NO:	500201	OPENED DATE:	04/08/2022 12:56:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2022 10:54:24	METER 1 - M:	2828	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2022 09:53:26	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$63.00	\$56.40	\$0.00	\$119.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.53	63.00	56.40	2.00	121.40
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/11/2022 08:09:36	04/11/2022 08:29:32	0.33	\$39.20
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/11/2022 07:09:31	04/11/2022 07:21:37	0.20	\$23.80
LABOR						63.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	6.96	7	\$48.72
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.68	1	\$7.68
PARTS						56.40

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 42867

Work Order Notes

(CHANNELL) pm replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 2828 Completed PM bottom and top side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 44565

USING DEPT NO:	500201	OPENED DATE:	09/02/2022 14:31:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2022 10:21:38	METER 1 - M:	5118	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 14:13:55	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.05	\$15.63	\$0.00	\$20.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.63	\$57.66	\$0.00	\$107.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.46	54.68	73.29	5.00	132.97
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/02/2022 15:08:04	09/02/2022 15:10:38	0.04	\$5.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/02/2022 14:42:35	09/02/2022 15:07:49	0.42	\$49.63
LABOR						54.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	6.63	1	\$6.63
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.29	7	\$51.03
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
PARTS						73.29

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 44565

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 45940

USING DEPT NO:	500201	OPENED DATE:	01/26/2023 15:27:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2023 12:57:40	METER 1 - M:	6963	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/31/2023 14:04:24	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-51-043	RECALL WIPER ARM	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-51-043	RECALL WIPER ARM	11099772	100605739		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: **244459** **2021 FORD F250 SERVICE BODY** **WORK ORDER NO:** **45940**

Work Order Notes

(CWIGLEY) Recall 22s26 for wiper assembly.

Job Notes

17-51-043 - RECALL WIPER ARM

(CWIGLEY) Long Lewis Ford Mobile Unit completed recall.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 46368

USING DEPT NO:	500201	OPENED DATE:	03/06/2023 08:47:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/09/2023 07:27:27	METER 1 - M:	7807	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/09/2023 08:36:03	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.54	\$15.63	\$0.00	\$19.17
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.14	\$16.00	\$0.00	\$0.00	\$16.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.74	\$87.25	\$0.00	\$0.00	\$87.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$13.21	\$56.97	\$0.00	\$70.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.02	120.00	72.60	5.00	197.60
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/08/2023 08:06:08	03/08/2023 08:14:16	0.14	\$16.00
66-79-003	PERFORM SAFETY INSPECTION	11074414	03/08/2023 07:20:18	03/08/2023 08:04:40	0.74	\$87.25
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/06/2023 13:08:29	03/06/2023 13:10:17	0.03	\$3.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/06/2023 13:01:35	03/06/2023 13:08:18	0.11	\$13.21
LABOR						120.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.29	7	\$51.03
PARTS						72.60

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 46368

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires the tires and inspected the brakes. Found no issues at this time. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH

(SHARBIN) Front and rear pads measure 10MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 47849

USING DEPT NO:	500201	OPENED DATE:	08/07/2023 15:43:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/08/2023 13:37:04	METER 1 - M:	10229	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2023 08:05:25	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.61	\$16.65	\$0.00	\$20.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.23	\$69.26	\$0.00	\$132.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.40	\$46.61	\$0.00	\$0.00	\$46.61

JOB COUNT: 4	WORK ORDER TOTAL:	0.96	113.45	85.91	5.00	204.36
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	08/08/2023 08:15:48	08/08/2023 08:39:30	0.40	\$46.61
03-51-038	REPLACE NEW WIPER BLADES	12201267	08/08/2023 08:13:58	08/08/2023 08:15:48	0.03	\$3.61
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/08/2023 07:41:49	08/08/2023 08:13:58	0.54	\$63.23
				LABOR		113.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.05	7	\$63.32
				PARTS		85.91

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 47849

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 10,229

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 48809

USING DEPT NO:	500201	OPENED DATE:	11/02/2023 11:00:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/06/2023 15:09:40	METER 1 - M:	11452	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/07/2023 08:33:34	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.38	\$44.97	\$199.64	\$0.00	\$244.61
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.37	\$43.33	\$0.00	\$0.00	\$43.33
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.75	206.30	199.64	5.00	410.94
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2023 07:00:00	11/06/2023 08:00:00	1.00	\$118.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2023 07:00:00	11/06/2023 08:00:00	(1.00)	(\$118.00)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2023 07:00:00	11/06/2023 08:00:00	1.00	\$118.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2023 07:00:00	11/06/2023 08:00:00	(1.00)	(\$118.00)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2023 07:00:00	11/06/2023 08:00:00	1.00	\$118.00
06-32-002	INSPECT BATTERY	11310047	11/02/2023 13:52:58	11/02/2023 14:15:00	0.37	\$43.33
06-32-002	INSPECT BATTERY	11310047	11/02/2023 13:52:58	11/02/2023 14:15:00	(0.37)	(\$43.33)
06-32-002	INSPECT BATTERY	11310047	11/02/2023 13:52:58	11/02/2023 14:15:00	0.37	\$43.33
06-32-002	INSPECT BATTERY	11310047	11/02/2023 13:52:58	11/02/2023 14:15:00	(0.37)	(\$43.33)
06-32-002	INSPECT BATTERY	11310047	11/02/2023 13:52:58	11/02/2023 14:15:00	0.37	\$43.33
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 13:30:06	11/02/2023 13:52:58	0.38	\$44.97

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 13:30:06	11/02/2023 13:52:58	0.38	\$44.97
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 13:30:06	11/02/2023 13:52:58	(0.38)	(\$44.97)
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 13:30:06	11/02/2023 13:52:58	0.38	\$44.97
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 13:30:06	11/02/2023 13:52:58	(0.38)	(\$44.97)
					LABOR	206.30

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	199.64	1	\$199.64
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	199.64	(1)	(\$199.64)
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	199.64	1	\$199.64
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	199.64	(1)	(\$199.64)
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	199.64	1	\$199.64
					PARTS	199.64

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 48809

Work Order Notes

(EHANNAH) inspect battery Driver reports it going dead on him several times over the past few days.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Installed a new battery and reset the battery monitoring system using the Ford scan tool. EH

(IFALLS) Visit Reason Changed On 11/7/2023 8:32 AM By IFALLS

(LRUSHING) Visit Reason Changed On 11/8/2023 2:37 PM By LRUSHING

06-32-002 - INSPECT BATTERY

(EHOWELL) The alternator is charging. Battery tested bad. EH

(IFALLS) Visit Reason Changed On 11/7/2023 8:32 AM By IFALLS

(LRUSHING) Visit Reason Changed On 11/8/2023 2:37 PM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 11/8/2023 2:37 PM By LRUSHING

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) reset the battery monitoring system using the Ford scan tool. EH

(IFALLS) Visit Reason Changed On 11/7/2023 8:32 AM By IFALLS

(LRUSHING) Visit Reason Changed On 11/8/2023 2:37 PM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 49347

USING DEPT NO:	500201	OPENED DATE:	01/05/2024 07:59:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/09/2024 15:00:32	METER 1 - M:	12070	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/10/2024 07:29:34	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-18-001	ADJUST FRONT AXLE HUBS & BEARIN	DON	N	N	GARAGE	1.78	\$210.60	\$0.00	\$0.00	\$210.60
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.33	\$38.38	\$0.00	\$0.00	\$38.38
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.80	\$212.89	\$860.78	\$0.00	\$1,073.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.24	\$0.00	\$0.00	\$29.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.50	\$58.48	\$0.00	\$0.00	\$58.48

JOB COUNT: 7	WORK ORDER TOTAL:	4.91	579.09	860.78	5.00	1,444.87
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
01-18-001	ADJUST FRONT AXLE HUBS & BEARINGS	11310047	01/08/2024 10:05:56	01/08/2024 11:53:01	1.78	\$210.60
WA-00	WASH COMPLETE VEHICLE	12201267	01/08/2024 09:35:08	01/08/2024 10:04:52	0.50	\$58.48
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/05/2024 08:24:04	01/05/2024 08:38:56	0.25	\$29.24
66-17-013	PERFORM ALIGNMENT	11310047	01/08/2024 09:46:25	01/08/2024 10:05:56	0.33	\$38.38
06-15	INSPECT STEERING	12201267	01/08/2024 09:18:38	01/08/2024 09:33:38	0.25	\$29.50
06-15	INSPECT STEERING	12201267	01/08/2024 09:18:38	01/08/2024 09:18:38	0.00	\$0.00
06-15	INSPECT STEERING	12201267	01/08/2024 09:18:38	01/08/2024 09:18:38	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	01/08/2024 07:26:45	01/08/2024 09:15:00	1.80	\$212.89
				LABOR		579.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.50	3	\$1.49

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	(3)	(\$2.34)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.10	1	\$1.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.95	1	\$0.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	3	\$2.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	4	\$14.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002777	TIRE LT245/75R17 TRANSFORCEHT2	210.39	4	\$841.56
					PARTS	860.78

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 49347

Work Order Notes

(EHANNAH) PM- WIPERS- WASH
(EKIMBREL) did not need wipers

Job Notes

01-18-001 - ADJUST FRONT AXLE HUBS & BEARINGS

(EHOWELL) Removed bearing caps and inspected grease. Cleaned and repacked one outer bearing with grease due to moisture intrusion. Tightened both front hub bearings and installed new cotter pins. Applied silicone around bearing caps. EH/GC .3 HR

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(GRCOOK) Inspected steering, found a little play in the wheel bearings, EH inspected and is going to tighten up the wheel bearings, no other issues were found. -GC

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Checked alignment. The vehicle was within specification. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and Balanced 4 new tires on unit 8099B, also inspected brakes, all brake pads are 10mm front and rear. -GC
Miles, 12,070

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 50929

USING DEPT NO:	500201	OPENED DATE:	05/23/2024 10:25:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2024 13:53:41	METER 1 - M:	13632	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2024 07:59:14	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.47	\$22.50	\$0.00	\$25.97
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	P	N	GARAGE	0.01	\$1.54	\$0.00	\$0.00	\$1.54
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.01	\$1.38	\$10.78	\$0.00	\$12.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.05	6.39	33.28	5.00	44.67
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	05/23/2024 11:23:24	05/23/2024 11:24:06	0.01	\$1.38
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	05/23/2024 11:21:42	05/23/2024 11:22:29	0.01	\$1.54
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/23/2024 11:19:56	05/23/2024 11:21:42	0.03	\$3.47
					LABOR	6.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	2	\$22.50
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.51	1	\$0.51
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	6.65	1	\$6.65
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
					PARTS	33.28

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 50929

Work Order Notes

(EHANNAH) tire pressure- washer fluid

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) SH FC Replaced the wipers and filled up washer fluid. SH

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) Screw in right front tire. Can be repaired. SH

66-17-030 - PERFORM TIRE PATCH

(GARAGE) Patched the right front tire. Rechecks good. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 51190

USING DEPT NO:	500201	OPENED DATE:	06/13/2024 15:18:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/14/2024 13:20:36	METER 1 - M:	13869	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/14/2024 14:37:29	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.10	\$54.98	\$0.00	\$57.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.79	\$0.00	\$0.00	\$0.79

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.89	54.98	5.00	62.87
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/14/2024 11:11:29	06/14/2024 11:11:53	0.01	\$0.79
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/14/2024 11:10:25	06/14/2024 11:11:29	0.02	\$2.10
					LABOR	2.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	7	\$49.04
					PARTS	54.98

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 51190

Work Order Notes

(LRUSHING) pm and wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FC Washed. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 51385

USING DEPT NO:	500201	OPENED DATE:	07/03/2024 15:41:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/17/2024 07:43:51	METER 1 - M:	13989	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/18/2024 08:48:43	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-017	REPLACE NEW FUEL TANK CAP	DON	N	N	GARAGE	0.00	\$0.00	\$11.73	\$0.00	\$11.73
03-44-032	REPLACE NEW EVAP VENT VALVE	DON	N	N	GARAGE	0.00	\$0.00	\$48.30	\$0.00	\$48.30
06-02-018	INSPECT DOOR MECHANISM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-44-061	PERFORM SMOKE TEST	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.07	\$8.62	\$0.00	\$0.00	\$8.62

JOB COUNT: 6	WORK ORDER TOTAL:	0.07	8.62	60.03	5.00	73.65
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	07/08/2024 09:10:37	07/08/2024 09:15:00	0.07	\$8.62
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	07/08/2024 09:10:37	07/08/2024 09:15:00	(0.07)	(\$8.62)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	07/08/2024 09:10:37	07/08/2024 09:15:00	0.07	\$8.62
LABOR						8.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-017	REPLACE NEW FUEL TANK CAP	FCTMGC825	FUEL CAP	11.73	1	\$11.73
03-44-032	REPLACE NEW EVAP VENT VALVE	STICVS20	VENT SOLENOID	48.30	1	\$48.30
PARTS						60.03

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 51385

Work Order Notes

(EHANNAH) Scan out- Pass. door sensor keeps going off when door is shut.

Job Notes

03-44-017 - REPLACE NEW FUEL TANK CAP

(GARAGE) Replaced new fuel cap. JAW

03-44-032 - REPLACE NEW EVAP VENT VALVE

(EHOWELL) Replaced canister solenoid and tested good. JAW

06-02-018 - INSPECT DOOR MECHANISM

(EHOWELL) Consulted Francisco and Josh about the door concern. Valid information was not provided.

66-44-061 - PERFORM SMOKE TEST

(GARAGE) Performed smoke test. JAW

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 7/30/2024 1:30 PM By LRUSHING

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(GARAGE) Scanned unit and received code p0455 for large evap leak. inspected with computer and smoke tester and found the canister solenoid is not closing when commanded and also the fuel cap is worn and not locking in place good. JAW

(LRUSHING) Visit Reason Changed On 7/30/2024 1:24 PM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 52809

USING DEPT NO:	500201	OPENED DATE:	11/14/2024 13:31:26	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2024 10:35:51	METER 1 - M:	14752	METER 2 - H:	8				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/21/2024 15:45:43	IN-SERVICE DATE:	10/14/2021						
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-40-451	INSPECT NOISE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 5						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 52809

Work Order Notes

(EHANNAH) pm- wipers- wash- SI- inspect front end noise

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) did not need blades

06-40-451 - INSPECT NOISE

(GARAGE) inspected steering system greased system test run checked ok, cm 14752 miles

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm/ jr checked ok, 14752

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) checked fluids driven 883 miles jr/fj

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed jr

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 54522

USING DEPT NO:	500201	OPENED DATE:	04/18/2025 10:12:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2025 13:07:38	METER 1 - M:	15298	METER 2 - H: 8
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/22/2025 09:09:46	IN-SERVICE DATE:	10/14/2021	
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$58.53	\$0.00	\$58.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	58.53	5.00	63.53
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	7	\$44.94
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						58.53

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 54522

Work Order Notes

(EHANNAH) pm- wipers -wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) CQ,GC,FJ,- performed tire rotation and brake inspection, found no issues at this time.
Brake pads are 8mm front an rear.
Miles, 15,298

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ, bottom side, drained oil and changed oil filter, reset oil life and installed sticker
GC, top side, checked fluids, filters good, tires and tire pressure, filled with oil.
Miles, 15,298

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- washed vehicle

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 54921

USING DEPT NO:	500201	OPENED DATE:	05/29/2025 10:40:55	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2025 09:46:12	METER 1 - M:	15298	METER 2 - H:	8				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/30/2025 12:28:34	IN-SERVICE DATE:	10/14/2021						
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-55-041	REMOVE LADDER RACK	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 54921

Work Order Notes

(EHANNAH) remove ladder rack to new vehilce tag unknown
(EHOWELL) We can open a work order for this vehicle in June for a prep for sale.

Job Notes

25-55-041 - REMOVE LADDER RACK

(GARAGE) GC- removed ladder rack form EHS unit 8099B- 20 min

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(IFALLS) prep unit to be sold

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 54980

USING DEPT NO:	500201	OPENED DATE:	06/04/2025 09:20:56	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2025 07:39:39	METER 1 - M:	15390	METER 2 - H:	8		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2025 09:52:35	IN-SERVICE DATE:	10/14/2021				
TECH SPEC NO:	21FORDF250SVC	2021 Ford F250 Service Body		UNIT SERIAL NO:	1FDBF2A67MED53197				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-51-053	REMOVE TOOLBOX LOCK/ASSY	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PS-00-999	PREP SERVICE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/06/2025 10:39:55 By User: GLOBETTI

UNIT NO: 244459 2021 FORD F250 SERVICE BODY WORK ORDER NO: 54980

Work Order Notes

(EHANNAH) remove toolbox

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

25-51-053 - REMOVE TOOLBOX LOCK/ASSY

(GARAGE) removed bolted down tool box from bed of truck, cm 15390miles, tool box is stored in shop for customers to pick up,
(GARAGE) .25 labor

PS-00-999 - PREP SERVICE PREPARE UNIT FOR DISPOSAL

(GARAGE) performed prep for sale, cm, 15390 mile,
(EHOWELL) We've already charged 1.0 for the prep for sale on work order # 54921.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Jun 06 2025 10:39:55 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FDBF2A67MED53197') //Q=