

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35085

USING DEPT NO:	750101	OPENED DATE:	12/06/2019 14:33:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2019 07:37:20	METER 1 - M:	53	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/10/2019 07:37:25	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1	WORK ORDER TOTAL:					0.50	36.25	0.00	0.00	36.25
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	12/06/2019 14:34:12	12/06/2019 15:04:12	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35085

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36635

USING DEPT NO:	750101	OPENED DATE:	06/01/2020 10:44:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/01/2020 13:37:34	METER 1 - M:	4341	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2020 11:00:52	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$73.81	\$35.68	\$0.00	\$109.49

JOB COUNT: 1	WORK ORDER TOTAL:					1.02	73.81	35.68	0.00	109.49
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/01/2020 11:16:07	06/01/2020 11:54:03	0.63	\$45.84
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/01/2020 11:27:38	06/01/2020 11:50:47	0.39	\$27.97
					LABOR	73.81

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
					PARTS	35.68

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36635

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/JW performed PM. Coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38464

USING DEPT NO:	750101	OPENED DATE:	11/24/2020 07:52:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/24/2020 14:25:28	METER 1 - M:	5499	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2020 08:07:37	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.76	\$89.55	\$0.00	\$0.00	\$89.55

JOB COUNT: 1	WORK ORDER TOTAL:	0.76	89.55	0.00	0.00	89.55
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/24/2020 08:26:37	11/24/2020 09:12:09	0.76	\$89.55
					LABOR	89.55

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38464

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5499. Vehicle has been driven 1158 miles since last PM. Oil was changed last PM. Checked fluids, battery, tire pressure and updated oil change sticker. Washed and vacuumed was full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39798

USING DEPT NO:	750101	OPENED DATE:	04/26/2021 07:25:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/27/2021 11:54:47	METER 1 - M:	6942	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 14:49:53	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$66.97	\$36.63	\$0.00	\$103.60

JOB COUNT: 1	WORK ORDER TOTAL:					0.57	66.97	36.63	0.00	103.60
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/26/2021 08:36:01	04/26/2021 09:10:04	0.57	\$66.97
					LABOR	66.97

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
					PARTS	36.63

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39798

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 6942 Completed PM topside, Josh was bottomside. AMG/JW Completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40904

USING DEPT NO:	750101	OPENED DATE:	09/01/2021 10:12:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2021 08:06:55	METER 1 - M:	12652	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/07/2021 08:24:33	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$31.76	\$0.00	\$55.36
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.60	\$71.23	\$0.00	\$0.00	\$71.23
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.97	\$34.76	\$0.00	\$91.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.29	151.80	66.52	2.00	220.32
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/01/2021 10:48:06	09/01/2021 11:00:06	0.20	\$23.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/01/2021 10:51:32	09/01/2021 11:03:32	0.20	\$23.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/01/2021 11:30:15	09/01/2021 11:54:28	0.40	\$47.63
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/01/2021 10:48:06	09/01/2021 10:48:52	(0.01)	(\$1.51)
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/01/2021 10:48:06	09/01/2021 10:48:52	0.01	\$1.51
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/01/2021 10:18:55	09/01/2021 10:47:53	0.48	\$56.97
				LABOR		151.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.70	1	\$5.70
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.14	1	\$9.14
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
				PARTS		66.52

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40904

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades. JAW,SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires inspected brakes washed and vacuumed. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 12652. SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41920

USING DEPT NO:	750101	OPENED DATE:	12/16/2021 08:41:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2021 14:22:03	METER 1 - M:	18509	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2021 09:06:07	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.49	\$34.32	\$0.00	\$97.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.04	122.49	34.32	2.00	158.81
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12052187	12/16/2021 12:15:26	12/16/2021 12:45:26	0.50	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	12/16/2021 12:15:26	12/16/2021 12:15:26	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	12/16/2021 12:15:26	12/16/2021 12:15:26	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/16/2021 10:58:44	12/16/2021 11:31:01	0.54	\$63.49
				LABOR		122.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
				PARTS		34.32

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41920

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI. No issues found. JAW

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) JW/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41960

USING DEPT NO:	750101	OPENED DATE:	01/04/2022 15:38:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2022 08:22:14	METER 1 - M:	18509	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/06/2022 11:05:06	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.03	\$3.02	\$9.20	\$0.00	\$12.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.22	\$1.22

JOB COUNT: 2	WORK ORDER TOTAL:	0.03	3.02	9.20	1.22	13.44
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$1.22
				COMML	1.22

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11915538	01/05/2022 10:39:19	01/05/2022 10:40:51	0.03	\$3.02
					LABOR	3.02

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.20	1	\$9.20
					PARTS	9.20

Work Order Charge Detail

UNIT NO:	243600	2019 TOYOTA HIGHLANDER	WORK ORDER NO:	41960
----------	--------	------------------------	----------------	-------

Work Order Notes
(LISAPATE) Replace rear wiper

Job Notes
03-51-038 - REPLACE NEW WIPER BLADES
(GARAGE) replaced rear wiper \JAW
CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43060

USING DEPT NO:	750101	OPENED DATE:	04/27/2022 08:26:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2022 11:45:33	METER 1 - M:	24793	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/28/2022 15:02:50	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.26	\$22.62	\$0.00	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.82	\$35.46	\$0.00	\$136.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.91	107.08	58.08	2.00	167.16
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/27/2022 14:04:45	04/27/2022 14:56:01	0.85	\$100.82
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/27/2022 14:01:17	04/27/2022 14:04:28	0.05	\$6.26
				LABOR		107.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	(2)	(\$20.37)
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	(1)	(\$10.19)
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	2	\$20.37
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
					PARTS	58.08

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43060

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 24793 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44027

USING DEPT NO:	750101	OPENED DATE:	07/20/2022 13:32:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2022 09:24:44	METER 1 - M:	29372	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2022 14:24:42	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.61	\$34.54	\$0.00	\$65.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.26	30.61	34.54	2.00	67.15
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/20/2022 14:41:09	07/20/2022 14:56:43	0.26	\$30.61
					LABOR	30.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.90	1	\$6.90
					PARTS	34.54

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44027

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG
MILEAGE-29372

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44900

USING DEPT NO:	750101	OPENED DATE:	10/06/2022 12:57:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/11/2022 07:35:13	METER 1 - M:	35116	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/11/2022 07:35:17	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-71-023	INSTALL WINDSHIELD REPLACEMENT	DON	V	N	GARAGE	0.00	\$0.00	\$0.00	\$770.50	\$770.50
16-71-023	TRANSPORT WINDSHIELD REPLACEMENT	DON	V	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$26.06	\$77.38	\$0.00	\$103.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$1.90	\$20.27	\$0.00	\$22.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.74	86.96	97.65	775.50	960.11
--------------	-------------------	------	-------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-71-023	INSTALL WINDSHIELD REPLACEMENT	11078716	2103365		\$770.50
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					775.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71-023	TRANSPORT WINDSHIELD REPLACEMENT	11915538	10/10/2022 07:00:00	10/10/2022 07:30:00	0.50	\$59.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/07/2022 07:28:08	10/07/2022 07:29:06	0.02	\$1.90
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/07/2022 07:13:54	10/07/2022 07:27:09	0.22	\$26.06
16-71-023	TRANSPORT WINDSHIELD REPLACEMENT	11915538	10/10/2022 07:00:00	10/10/2022 07:30:00	(0.50)	(\$59.00)
16-71-023	TRANSPORT WINDSHIELD REPLACEMENT	11915538	10/10/2022 07:00:00	10/10/2022 07:30:00	0.50	\$59.00
LABOR						86.96

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	35.19	1	\$35.19
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	20.27	1	\$20.27
PARTS						97.65

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44900

Work Order Notes

(CWIGLEY) PM

(CWIGLEY) Install windshield. Transport to Glass Doctor.

Job Notes

14-71-023 - INSTALL WINDSHIELD REPLACEMENT

(LISAPATE) Glass Dr installed a new windshield and recalibrated it. Pd by CC

16-71-023 - TRANSPORT WINDSHIELD REPLACEMENT

(LISAPATE) Taken to Glass Dr by RC

(AJONES) Visit Reason Changed On 10/31/2022 1:56 PM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46000

USING DEPT NO:	750101	OPENED DATE:	01/31/2023 08:36:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/01/2023 13:16:30	METER 1 - M:	39780	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/03/2023 09:49:06	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.72	\$23.26	\$0.00	\$29.98
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.04	\$5.21	\$0.00	\$0.00	\$5.21
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.42	\$49.40	\$0.00	\$0.00	\$49.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.76	\$49.35	\$0.00	\$83.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.81	95.09	72.61	5.00	172.70
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	02/01/2023 07:52:35	02/01/2023 07:55:14	0.04	\$5.21
66-79-003	PERFORM SAFETY INSPECTION	12052187	02/01/2023 07:27:17	02/01/2023 07:52:24	0.42	\$49.40
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/31/2023 10:25:10	01/31/2023 10:28:35	0.06	\$6.72
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/31/2023 10:07:44	01/31/2023 10:24:54	0.29	\$33.76
				LABOR		95.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
				PARTS		72.61

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46000

Work Order Notes

(EHANNAH) pm- replace wiper - preform safety inspection.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Pads are 10mm. Torqued lugs to spec. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Brakes are 10mm. JAW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 39780 Completed PM topside, Josh was bottomside. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46349

USING DEPT NO:	750101	OPENED DATE:	03/03/2023 10:00:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2023 11:39:29	METER 1 - M:	40434	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/10/2023 13:13:53	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.04	\$4.20	\$0.00	\$0.00	\$4.20
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.07	\$8.49	\$0.00	\$0.00	\$8.49
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.06	\$125.28	\$0.00	\$0.00	\$125.28
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.03	\$121.05	\$1,189.99	\$0.00	\$1,311.04
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.20	259.02	1,189.99	5.00	1,454.01
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-13	INSPECT BRAKES	11310047	03/08/2023 13:35:26	03/08/2023 13:37:34	0.04	\$4.20
06-13	INSPECT BRAKES	11310047	03/08/2023 13:35:26	03/08/2023 13:37:34	(0.04)	(\$4.20)
06-13	INSPECT BRAKES	11310047	03/08/2023 13:35:26	03/08/2023 13:37:34	0.04	\$4.20
06-15	INSPECT STEERING	11310047	03/08/2023 13:31:07	03/08/2023 13:35:26	0.07	\$8.49
06-15	INSPECT STEERING	11310047	03/08/2023 13:31:07	03/08/2023 13:35:26	(0.07)	(\$8.49)
06-15	INSPECT STEERING	11310047	03/08/2023 13:31:07	03/08/2023 13:35:26	0.07	\$8.49
66-17-013	PERFORM ALIGNMENT	11310047	03/08/2023 13:00:00	03/08/2023 13:29:03	0.48	\$57.13
66-17-013	PERFORM ALIGNMENT	11310047	03/08/2023 11:25:21	03/08/2023 12:00:00	0.58	\$68.15
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	03/07/2023 14:30:00	03/07/2023 14:56:52	0.45	\$52.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	03/07/2023 13:40:19	03/07/2023 14:15:00	0.58	\$68.21

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

					LABOR	259.02
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.96	4	\$27.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.14	19	\$2.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	5G	5G WHEEL WEIGHT	0.08	1	\$0.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	50G	50G WHEEL WEIGHT	0.06	1	\$0.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	52168	TIRE 245/60R18 MICH DEF LTX	289.86	4	\$1,159.44
					PARTS	1189.99

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46349

Work Order Notes

(LISAPATE) Cayla White 348-1550
customer said while driving the vehicle didn't want to stop as soon as they thought it should, check tires also.

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE)
(EHOWELL) Performed a road test and the vehicle stopped normally. Inspected pads and rotors. The front pad is at 9mm and the rear pad is at 7mm. EH
(AJONES) Visit Reason Changed On 3/23/2023 1:48 PM By AJONES

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH
(AJONES) Visit Reason Changed On 3/23/2023 1:48 PM By AJONES

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed 4 wheel alignment. Reset steering using code link. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) Visit Reason Changed On 3/6/2023 12:20 PM By EKIMBREL
(EHOWELL) Replaced all 4 tires. JAW
(EHOWELL) The outside tread of one tire measured 2/32. The outside edge of the other three tires measured 3/32. The tires were about four years old. EH

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 3/23/2023 1:48 PM By AJONES

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47278

USING DEPT NO:	750101	OPENED DATE:	06/06/2023 10:31:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2023 13:53:20	METER 1 - M:	43933	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2023 13:13:01	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$24.08	\$0.00	\$47.68
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.72	\$84.57	\$0.00	\$0.00	\$84.57
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.89	\$37.67	\$0.00	\$87.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.37	\$43.89	\$0.00	\$0.00	\$43.89

JOB COUNT: 5	WORK ORDER TOTAL:	1.71	201.95	61.75	5.00	268.70
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11399745	06/06/2023 13:53:43	06/06/2023 13:59:43	0.10	\$11.80
WA-00	WASH COMPLETE VEHICLE	12201267	06/06/2023 13:13:16	06/06/2023 13:35:35	0.37	\$43.89
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	06/06/2023 13:00:00	06/06/2023 13:13:00	0.22	\$25.57
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	06/06/2023 12:50:57	06/06/2023 12:50:57	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	06/06/2023 12:50:57	06/06/2023 12:50:57	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	06/06/2023 12:50:57	06/06/2023 13:20:57	0.50	\$59.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	06/06/2023 12:43:09	06/06/2023 12:43:09	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	06/06/2023 12:43:09	06/06/2023 12:43:09	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	06/06/2023 12:43:09	06/06/2023 12:49:09	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/06/2023 11:05:39	06/06/2023 11:31:01	0.42	\$49.89
					LABOR	201.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
					PARTS	61.75

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47278

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers CW did driver side GC done passenger side

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GRCOOK) Rotated tires and inspected brakes-GC

Brake pads are all 7mm on all 4 wheels.

Miles, 43,933

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47945

USING DEPT NO:	750101	OPENED DATE:	08/22/2023 09:20:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2023 11:27:37	METER 1 - M:	45851	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2023 13:48:00	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.23	\$27.70	\$0.00	\$0.00	\$27.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$19.08	\$48.11	\$0.00	\$67.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.29	\$34.55	\$0.00	\$0.00	\$34.55

JOB COUNT: 4	WORK ORDER TOTAL:	0.69	81.33	48.11	5.00	134.44
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	08/22/2023 13:28:13	08/22/2023 13:45:47	0.29	\$34.55
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/22/2023 13:20:12	08/22/2023 13:28:01	0.13	\$15.37
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/22/2023 11:26:52	08/22/2023 11:33:08	0.10	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/22/2023 11:16:55	08/22/2023 11:26:37	0.16	\$19.08
				LABOR		81.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.00	1	\$6.00
					PARTS	48.11

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47945

Work Order Notes

(EHANNAH) pm- wipers- wash- check tire to see if they need to be rotated.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. SH FC

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) FC SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49489

USING DEPT NO:	750101	OPENED DATE:	01/18/2024 10:00:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/22/2024 15:03:33	METER 1 - M:	49395	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/23/2024 07:54:36	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH1KS060293	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.37	\$43.76	\$0.00	\$0.00	\$43.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.29	\$54.25	\$0.00	\$88.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.03	\$3.44	\$13.17	\$0.00	\$16.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.43	\$51.17	\$0.00	\$0.00	\$51.17

JOB COUNT: 5	WORK ORDER TOTAL:	1.12	132.66	67.42	5.00	205.08
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	01/18/2024 11:06:39	01/18/2024 11:32:40	0.43	\$51.17
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/18/2024 10:44:00	01/18/2024 11:06:15	0.37	\$43.76
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	01/18/2024 10:40:05	01/18/2024 10:41:50	0.03	\$3.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/18/2024 10:22:26	01/18/2024 10:39:52	0.29	\$34.29
				LABOR		132.66

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5667	CABIN FILTER	13.17	1	\$13.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	8.12	1	\$8.12
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
				PARTS		67.42

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49489

Work Order Notes

(EHANNAH) pm- wash- check tire pressure- and if needs to rotated.

Job Notes

06-17-001 - INSPECT TIRE - ADD AIR

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) FC Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 51476

USING DEPT NO:	750101	OPENED DATE:	07/15/2024 08:03:34	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2024 17:41:01	METER 1 - M:	54708	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/16/2024 08:12:47	IN-SERVICE DATE:	12/06/2019						
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander									
			UNIT SERIAL NO:	5TDZARFH1KS060293							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-GA-005	RECALL Scheduling and Preparation	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$653.34	\$653.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	0.00	658.34	658.34
--------------	-------------------	--	--	--	--	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5928976	257574		\$653.34
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					658.34

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 51476

Work Order Notes

(EKIMBREL) pm

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

(IFALLS) department wanted to have vehicle serviced out of town

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Dept got oil changed at Firestone in Mt Brook

(EHOWELL) Firestone inspected the complete vehicle, replaced cabin filter, replaced battery, performed fuel induction service, and changed oil.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 53635

USING DEPT NO:	750101	OPENED DATE:	02/05/2025 10:42:49	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/05/2025 13:21:39	METER 1 - M:	62589	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2025 08:12:37	IN-SERVICE DATE:	12/06/2019						
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander									
				UNIT SERIAL NO:	5TDZARFH1KS060293						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$46.58	\$0.00	\$46.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	46.58	5.00	51.58
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.33	1	\$14.33
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	5	\$32.25
PARTS						46.58

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 53635

Work Order Notes

(EHANNAH) PM- WASH- SI- TIRE ROTATION

Job Notes

66-17-015 - PERFORM TIRE ROTATION

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) GC- performed safety inspection, found no issues at this time. also rotated tires
Brake pads are all 6mm front and rear
Miles, 62,589

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
62589 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) GC- wash vehicle

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 55226

USING DEPT NO:	750101	OPENED DATE:	06/30/2025 12:46:50	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	62589	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	12/06/2019				
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander							
			UNIT SERIAL NO:	5TDZARFH1KS060293					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/01/2025 08:36:28 By User: GLOBETTI

UNIT NO: 243600 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 55226

Work Order Notes

(EHANNAH) PREP FOR SALE

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Jul 01 2025 08:36:28 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243600') //Q=