

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35208

USING DEPT NO: 204906	OPENED DATE: 12/16/2019 14:05:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/20/2019 09:26:50	METER 1 - M: 54 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/20/2019 09:26:52	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-031	INSTALL TONNEAU/BED COVER	DON	O	N	GARAGE	1.14	\$0.00	\$720.00	\$0.00	\$720.00
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL: 1.64 0.00 720.00 0.00 720.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-031	INSTALL TONNEAU/BED COVER	11074414	12/19/2019 09:15:00	12/19/2019 09:40:30	0.43	\$0.00
14-78-031	INSTALL TONNEAU/BED COVER	11074414	12/19/2019 08:17:05	12/19/2019 09:00:00	0.72	\$0.00
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11170580	12/18/2019 07:00:00	12/18/2019 07:30:00	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-031	INSTALL TONNEAU/BED COVER	0001635187	TRI-FOLD TONNEAU RIGID 5FT	720.00	1	\$720.00
					PARTS	720.00

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35208

Work Order Notes

(EKIMBREL) PDI

Job Notes

14-78-031 - INSTALL TONNEAU/BED COVER

(EKIMBREL) SH installed tonneau cover. 1 hr labor

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) AB performed PDI

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 36046

USING DEPT NO: 204906	OPENED DATE: 03/24/2020 09:17:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/02/2020 10:00:14	METER 1 - M: 324 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/02/2020 15:09:24	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	7.16	\$0.00	\$605.42	\$0.00	\$605.42

JOB COUNT: 1	WORK ORDER TOTAL:	7.16	0.00	605.42	0.00	605.42
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11901357	04/02/2020 07:00:00	04/02/2020 10:00:00	3.00	\$0.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/01/2020 13:03:40	04/01/2020 15:35:27	2.53	\$0.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/01/2020 10:18:00	04/01/2020 11:55:38	1.63	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81141S	PRIMARY WIRE 14 GA RED 100'	10.29	(1)	(\$10.29)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81181S	PRIMARY WIRE 18 GA RED 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1700PT	22-16GA BUTT CONN VINYL 25PC	4.35	1	\$4.35
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1800PT	16-14GA BUTT CONN VINYL 25PC	3.91	1	\$3.91
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC2250GT	22-16GA HS BUTT CONN 25PC	16.61	1	\$16.61
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709265	CABLE TIE 24 IN HD 50 PCS	29.47	1	\$29.47
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5141A	3/8 CONVOLUTED TUBING 50FT	10.97	1	\$10.97
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	7.51	1	\$7.51
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC2213PT	RING TERM HS 22-16 1/4 25PC	3.30	1	\$3.30
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81141S	PRIMARY WIRE 14 GA RED 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81187S	PRIMARY WIRE 18 GA WHITE 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81184S	PRIMARY WIRE 18 GA GREEN 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81184S	PRIMARY WIRE 18 GA GREEN 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81183S	PRIMARY WIRE 18 GA BLK 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81183S	PRIMARY WIRE 18 GA BLK 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81181S	PRIMARY WIRE 18 GA RED 100'	10.29	1	\$10.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709213	CABLE TIE 11 IN 100 PC WHT	6.52	1	\$6.52

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709228	CABLE TIE 8 IN 100 PC BLK	5.32	1	\$5.32
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709237	CABLE TIE 15IN HD 100PC	20.00	1	\$20.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.38	1	\$0.38
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	4.54	1	\$4.54
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0963PT	INLINE FUSE HOLDER ATC 12GA	1.49	3	\$4.47
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8220A	SHRINK TUBE 3/16 X 4 FT	2.68	(1)	(\$2.68)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8220A	SHRINK TUBE 3/16 X 4 FT	2.68	2	\$5.36
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8220A	SHRINK TUBE 3/16 X 4 FT	2.68	1	\$2.68
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1809KT	16-14GA 3/8 RING TERM 10PCS	2.15	1	\$2.15
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC7095PT	ADHESIVE BACKED TIES	2.37	1	\$2.37
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81143S	PRIMARY WIRE 18 GA BLACK 100'	20.11	1	\$20.11
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	98.60	2	\$197.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	81.70	2	\$163.40
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1705KT	22-16GA RING TERM NO6	2.15	1	\$2.15
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1900PT	12-10GA BUTT CONN VINYL 25PC	3.08	1	\$3.08
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8221A	SHRINK TUBE 1/4 X 4 FT	3.31	3	\$9.93
					PARTS	605.42

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 36046

Work Order Notes

(LISAPATE) Install front and rear strobe lights

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(IFALLS) AG / AB ran wire and mounted front and rear strobe lights

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 36105

USING DEPT NO: 204906	OPENED DATE: 04/06/2020 14:27:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/07/2020 09:02:03	METER 1 - M: 324 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/07/2020 15:35:31	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$0.00	\$31.56	\$0.00	\$31.56

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.66** **0.00** **31.56** **0.00** **31.56**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/06/2020 14:53:56	04/06/2020 15:21:01	0.45	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/06/2020 14:41:37	04/06/2020 14:54:17	0.21	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	7	\$27.23
					PARTS	31.56

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 36105

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH/AG performed pm

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 37611

USING DEPT NO:	204906	OPENED DATE:	09/15/2020 13:25:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/16/2020 10:06:10	METER 1 - M:	3132	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2020 14:53:33	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5AN5LM309104	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.09	\$0.00	\$27.61	\$0.00	\$27.61

JOB COUNT: 1	WORK ORDER TOTAL:	1.09	0.00	27.61	0.00	27.61
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/16/2020 07:11:01	09/16/2020 08:16:15	1.09	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	6	\$23.28
					PARTS	27.61

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 37611

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Removed skid plate to change oil filter. Coolant -34° JAW

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 38965

USING DEPT NO:	204906	OPENED DATE:	01/29/2021 15:00:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/01/2021 10:56:36	METER 1 - M:	4972	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/02/2021 08:51:28	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5AN5LM309104	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.81	\$95.42	\$2.73	\$0.00	\$98.15

JOB COUNT: 1	WORK ORDER TOTAL:					0.81	95.42	2.73	0.00	98.15
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	11170580	01/29/2021 15:10:18	01/29/2021 15:58:49	0.81	\$95.42
					LABOR	95.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.73	1	\$2.73
					PARTS	2.73

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 38965

Work Order Notes

(LISAPATE) Key fob battery dead

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(ABLACK) AB replaced key fob battery

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 39114

USING DEPT NO: 204906	OPENED DATE: 02/17/2021 11:31:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/19/2021 11:22:23	METER 1 - M: 5287 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/19/2021 14:10:05	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.62	\$73.03	\$12.71	\$0.00	\$85.74
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.24	\$145.76	\$0.00	\$0.00	\$145.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.32	\$155.86	\$33.05	\$0.00	\$188.91

JOB COUNT: 3	WORK ORDER TOTAL:	3.18	374.65	45.76	0.00	420.41
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11170580	02/18/2021 13:44:17	02/18/2021 14:21:25	0.62	\$73.03
66-79-003	PERFORM SAFETY INSPECTION	11170580	02/18/2021 10:40:14	02/18/2021 11:54:21	1.24	\$145.76
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/18/2021 07:42:37	02/18/2021 08:24:20	0.70	\$82.04
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/18/2021 07:45:45	02/18/2021 08:23:17	0.63	\$73.82
					LABOR	374.65

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	12.71	1	\$12.71
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.14	1	\$6.14
					PARTS	45.76

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 39114

Work Order Notes

(LISAPATE) PM-Do annual safety inspection

Job Notes

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(ABLACK) AB installed a new cabin air filter.

66-79-003 - PERFORM SAFETY INSPECTION

(ABLACK) AB performed safety inspection.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5287. SH/JW Performed PM.

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 40270

USING DEPT NO: 204906	OPENED DATE: 06/28/2021 09:42:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/29/2021 09:02:43	METER 1 - M: 6790 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2021 07:17:17	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.26	\$30.32	\$0.00	\$0.00	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$60.25	\$0.00	\$0.00	\$60.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.77** **90.57** **0.00** **0.00** **90.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	06/29/2021 07:42:25	06/29/2021 07:57:50	0.26	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2021 07:11:36	06/29/2021 07:42:14	0.51	\$60.25
					LABOR	90.57

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 40270

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Torqued lugs to spec. Front pads are 10mm rear shoes are 8mm.JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1503 miles since last pm service. Updated sticker. Checked all fluids and tires. Coolant -34°. JAW
MILEAGE-6790

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 40815

USING DEPT NO: 204906	OPENED DATE: 08/23/2021 11:50:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2021 10:31:55	METER 1 - M: 7376 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/25/2021 13:50:45	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.19	\$22.78	\$11.09	\$0.00	\$33.87
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.69	81.78	11.09	2.00	94.87
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	08/23/2021 13:00:00	08/23/2021 13:11:35	0.19	\$22.78
66-17-030	PERFORM TIRE PATCH	11901357	08/23/2021 12:25:10	08/23/2021 12:25:10	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	08/23/2021 12:02:03	08/23/2021 12:02:03	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	08/23/2021 12:02:03	08/23/2021 12:02:03	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	08/23/2021 12:02:03	08/23/2021 12:32:03	0.50	\$59.00
LABOR					81.78	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	5.73	1	\$5.73
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.87	1	\$3.87
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	3	\$1.49
PARTS					11.09	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 40815

Work Order Notes

(LISAPATE) Unit has a tire almost flat at EHS per Keon

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 7376 Repaired and balanced L/F tire, rechecked for leak, all good. AMG

66-79-002 - PERFORM SERVICE CALL

(AGUERRA) miles: 7376 Aired up tire and brought vehicle back to shop for repairs. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 41350

USING DEPT NO: 204906	OPENED DATE: 10/18/2021 09:10:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/18/2021 14:27:27	METER 1 - M: 7943 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/19/2021 07:45:15	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$2.98	\$15.18	\$0.00	\$18.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$74.08	\$49.78	\$0.00	\$123.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.65	77.06	64.96	2.00	144.02
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/18/2021 10:21:26	10/18/2021 10:22:57	0.03	\$2.98
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/18/2021 09:43:40	10/18/2021 10:21:20	0.63	\$74.08
LABOR					77.06	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	6	\$37.89
PARTS					64.96	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 41350

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant-34°. JAW
MILEAGE-7943

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 42840

USING DEPT NO:	204906	OPENED DATE:	04/06/2022 09:09:40	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2022 09:25:56	METER 1 - M:	9141	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/14/2022 07:22:47	IN-SERVICE DATE:	12/16/2019		
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5AN5LM309104		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.92	\$15.18	\$0.00	\$18.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$10.82	\$0.00	\$0.00	\$10.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.12	13.74	15.18	2.00	30.92
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/06/2022 09:35:40	04/06/2022 09:37:09	0.02	\$2.92
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/06/2022 09:30:00	04/06/2022 09:35:30	0.09	\$10.82
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/06/2022 09:29:15	04/06/2022 09:29:15	0.00	\$0.00
LABOR					13.74	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
PARTS					15.18	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 42840

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1198 miles. Checked fluids and tires. Coolant -34°. JAW,AMG,SH
MILEAGE-9141

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 43520

USING DEPT NO: 204906	OPENED DATE: 06/03/2022 14:04:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/09/2022 10:04:46	METER 1 - M: 9424 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/10/2022 10:14:36	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.27	\$32.38	\$0.00	\$0.00	\$32.38
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.53	\$63.10	\$0.00	\$0.00	\$63.10
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.14	\$16.23	\$22.68	\$0.00	\$38.91
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.99	\$117.25	\$1,113.42	\$0.00	\$1,230.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.94	228.96	1,136.10	2.00	1,367.06
---------------------	--------------------------	-------------	---------------	-----------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	11915538	06/07/2022 11:17:47	06/07/2022 11:26:02	0.14	\$16.23
09-15	ALIGN STEERING	11310047	06/07/2022 08:30:33	06/07/2022 09:02:38	0.53	\$63.10
06-15	INSPECT STEERING	11074414	06/06/2022 15:15:07	06/06/2022 15:31:35	0.27	\$32.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/06/2022 14:30:00	06/06/2022 15:14:56	0.75	\$88.37
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/06/2022 14:00:19	06/06/2022 14:15:00	0.24	\$28.88
					LABOR	228.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15477	TIRE LT245/75R16 BFG A/T KO2	271.95	4	\$1,087.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	2	\$1.77
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	2	\$0.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.52	4	\$22.08
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT23021	BRASS COUPLER LOCK W/KEYS	22.68	1	\$22.68
					PARTS	1136.10

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 43520

Work Order Notes

(LISAPATE) Install 4 new KO!! tires on truck and align

Job Notes

06-15 - INSPECT STEERING

(HHARBIN) Inspected steering found no issues at this time. SH

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(EKIMBREL) installed tailer hitch and lock pin \RC

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(HHARBIN) Mounted and balanced 4 tires. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 43781

USING DEPT NO:	204906	OPENED DATE:	06/28/2022 14:15:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2022 09:19:25	METER 1 - M:	9424	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/12/2022 07:46:25	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5AN5LM309104	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-32-002	WARRANTY BATTERY	11076422	6165804		\$0.00
COMML					0.00

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 43781

Work Order Notes

(LISAPATE) Battery keeps going dead

Job Notes

03-32-002 - REPLACE NEW BATTERY

15-32-002 - WARRANTY BATTERY

(IFALLS) Department driver took to Toyota to have battery replaced under warranty

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44035

USING DEPT NO: 204906	OPENED DATE: 07/21/2022 09:02:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/28/2022 11:54:44	METER 1 - M: 9424 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/28/2022 12:43:51	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$764.75	\$764.75
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.36	\$13.11	\$0.00	\$19.47
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.87	\$39.02	\$0.00	\$95.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.04	122.23	52.13	766.75	941.11
---------------------	--------------------------	-------------	---------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2101215		\$764.75
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					766.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11915538	07/28/2022 07:00:00	07/28/2022 07:30:00	0.50	\$59.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2022 10:47:27	07/21/2022 10:50:41	0.05	\$6.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/21/2022 10:18:20	07/21/2022 10:47:15	0.48	\$56.87
LABOR					122.23	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.90	1	\$6.90
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	6.57	1	\$6.57
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	6.54	1	\$6.54
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
PARTS					52.13	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44035

Work Order Notes

(LISAPATE) PM-replace wipers-Windshield has a crack running-get pics and estimate for body damage

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield and recalibrated. PD by CC

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by RC

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44642

USING DEPT NO: 204906	OPENED DATE: 09/09/2022 13:03:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/29/2022 13:28:25	METER 1 - M: 9424 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/29/2022 15:00:29	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	A	N	GARAGE	2.17	\$256.06	\$0.00	\$0.00	\$256.06
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,300.00	\$2,300.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	2.17	256.06	0.00	2,300.00	2,556.06
---------------------	--------------------------	-------------	---------------	-------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	1697083		\$2,300.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					2300.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11915538	09/26/2022 11:10:00	09/26/2022 13:20:12	2.17	\$256.06
16-71	TRANSPORT BODY	11915538	09/26/2022 11:10:00	09/26/2022 13:20:12	(2.17)	(\$256.06)
16-71	TRANSPORT BODY	11915538	09/26/2022 11:10:00	09/26/2022 13:20:12	2.17	\$256.06
LABOR					256.06	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44642

Work Order Notes

(CWIGLEY) Take to body shop to repair damage left side.
(LISAPATE)

Job Notes

16-71 - TRANSPORT BODY

(AJONES) Visit Reason Changed On 9/30/2022 8:19 AM By AJONES
(LISAPATE) Taken to Andrews by RC

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired Body damage. State Auto paid Ck# 1001105950 \$2546.16 9-30-22 also supplement for \$ 415.90. UA pd \$2000.00 ded. Invoice 1697083

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 45063

USING DEPT NO: 204906	OPENED DATE: 10/24/2022 09:55:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/26/2022 11:13:05	METER 1 - M: 17907 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/27/2022 07:30:36	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.47	\$20.91	\$0.00	\$26.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.81	\$95.51	\$54.09	\$0.00	\$149.60
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.05	\$6.10	\$14.58	\$0.00	\$20.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.91	107.08	89.58	5.00	201.66
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/24/2022 10:02:06	10/24/2022 10:09:21	0.12	\$14.26
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	10/24/2022 10:09:39	10/24/2022 10:12:45	0.05	\$6.10
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/24/2022 10:13:01	10/24/2022 10:15:48	0.05	\$5.47
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/24/2022 10:16:01	10/24/2022 10:57:20	0.69	\$81.26
					LABOR	107.09

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.44	1	\$10.44
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	14.58	1	\$14.58
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
					PARTS	89.58

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 45063

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 17907 Completed PM top and bottom side. AMG/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 45872

USING DEPT NO: 204906	OPENED DATE: 01/23/2023 09:35:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/24/2023 07:37:57	METER 1 - M: 23437 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/24/2023 09:26:58	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.03	\$20.94	\$0.00	\$26.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.01	\$67.22	\$0.00	\$102.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$8.36	\$49.88	\$0.00	\$58.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.42	49.40	138.04	5.00	192.44
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/23/2023 10:13:14	01/23/2023 10:16:18	0.05	\$6.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	01/23/2023 10:08:50	01/23/2023 10:13:05	0.07	\$8.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/23/2023 09:50:52	01/23/2023 10:08:40	0.30	\$35.01
					LABOR	49.40

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	1	\$10.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WA10085	AIR FILTER	49.88	1	\$49.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
66-PM-PMA	PERFORM OIL CHANGE	24871	CABIN FILTER-TACOMA	11.78	1	\$11.78
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
					PARTS	138.04

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 45872

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 46370

USING DEPT NO: 204906	OPENED DATE: 03/06/2023 10:03:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/07/2023 11:54:07	METER 1 - M: 23437 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2023 13:25:59	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.10	\$11.80	\$3.41	\$0.00	\$15.21
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.10** **11.80** **3.41** **5.00** **20.21**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	11399745	03/06/2023 10:06:18	03/06/2023 10:12:18	0.10	\$11.80
03-51-042	REPLACE NEW KEY FOB BATTERY	11399745	03/06/2023 10:06:18	03/06/2023 10:12:18	(0.10)	(\$11.80)
03-51-042	REPLACE NEW KEY FOB BATTERY	11399745	03/06/2023 10:06:18	03/06/2023 10:12:18	0.10	\$11.80
LABOR						11.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.41	1	\$3.41
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.41	(1)	(\$3.41)
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.41	1	\$3.41
PARTS						3.41

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 46370

Work Order Notes

(EKIMBREL) REPLACE KEY FOB BATTERY

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(EKIMBREL) CW REPLACED KEY FOB BATTERY
(AJONES) Visit Reason Changed On 4/2/2023 7:02 PM By AJONES

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 4/2/2023 7:02 PM By AJONES

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 46461

USING DEPT NO: 204906	OPENED DATE: 03/20/2023 10:00:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/23/2023 15:35:49	METER 1 - M: 27583 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/24/2023 08:31:27	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.47	\$52.17	\$0.00	\$79.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.02	\$2.16	\$0.00	\$0.00	\$2.16

JOB COUNT: 3	WORK ORDER TOTAL:	0.25	29.63	52.17	5.00	86.80
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	03/20/2023 10:32:17	03/20/2023 10:33:23	0.02	\$2.16
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/20/2023 10:18:05	03/20/2023 10:32:03	0.23	\$27.47
LABOR					29.63	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
PARTS					52.17	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 46461

Work Order Notes

(EHANNAH) pm- replace wipers- wash truck

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC-SH, Changed oil and oil filter, checked fluids, tires and tire pressure, filters are good
Miles, 27,583

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Wash Bay is closed, GC

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 47329

USING DEPT NO: 204906	OPENED DATE: 06/12/2023 09:59:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/13/2023 13:27:58	METER 1 - M: 32121 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/14/2023 09:23:08	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.85	\$21.32	\$0.00	\$26.17
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.47	\$54.94	\$0.00	\$0.00	\$54.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$80.40	\$54.70	\$0.00	\$135.10
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.03	\$3.87	\$11.79	\$0.00	\$15.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.21	\$24.81	\$0.00	\$0.00	\$24.81

JOB COUNT: 6	WORK ORDER TOTAL:	1.43	168.87	87.81	5.00	261.68
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/13/2023 08:24:23	06/13/2023 08:37:00	0.21	\$24.81
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/13/2023 07:56:07	06/13/2023 08:24:03	0.47	\$54.94
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/13/2023 07:09:38	06/13/2023 07:50:31	0.68	\$80.40
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/12/2023 15:04:06	06/12/2023 15:06:34	0.04	\$4.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/12/2023 15:01:50	06/12/2023 15:03:48	0.03	\$3.87
					LABOR	168.87

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	11.79	1	\$11.79

Work Order Charge Detail

PARTS

87.81

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 47329

Work Order Notes

(EHANNAH) pm- replace wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 48167

USING DEPT NO: 204906	OPENED DATE: 09/12/2023 07:27:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/14/2023 11:18:20	METER 1 - M: 36844 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/14/2023 13:13:07	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-029	PERFORM ROTATE AND BALANCE TIRE	DON	P	N	GARAGE	0.37	\$44.12	\$8.93	\$0.00	\$53.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$19.18	\$54.28	\$0.00	\$73.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.54	63.30	63.21	5.00	131.51
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	09/12/2023 09:18:49	09/12/2023 09:18:49	0.00	\$0.00
66-17-029	PERFORM ROTATE AND BALANCE TIRES	11074414	09/12/2023 08:52:34	09/12/2023 09:15:00	0.37	\$44.12
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/12/2023 08:37:49	09/12/2023 08:43:34	0.10	\$11.31
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/12/2023 08:02:38	09/12/2023 08:06:38	0.07	\$7.87
					LABOR	63.30

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	2	\$1.80
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.31	4	\$5.22
					PARTS	63.21

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 48167

Work Order Notes

(EHANNAH) pm-wash- tires balance and rotate.

Job Notes

66-17-029 - PERFORM ROTATE AND BALANCE TIRES

(SHARBIN) Cross rotated and balanced the tires. Also inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Wash bay is closed. SH

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 48842

USING DEPT NO: 204906	OPENED DATE: 11/06/2023 09:32:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/10/2023 13:54:46	METER 1 - M: 36844 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2023 14:37:22	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$770.50	\$770.50
16-00	TRANSPORT COMPLETE VEHICLE	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	775.50	834.50
---------------------	--------------------------	-------------	--------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2113569		\$770.50
COMML					775.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-00	TRANSPORT COMPLETE VEHICLE	11915538	11/10/2023 07:00:00	11/10/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 48842

Work Order Notes

(LRUSHING) Crack in windshield - transport to Glass Doctor

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr could not repair had to install new windshield. Pd by CC

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) Taken to Glass Dr by RC/CW

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 11/16/2023 3:30 PM By LRUSHING

(LRUSHING) Visit Reason Changed On 11/16/2023 3:31 PM By LRUSHING

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 49616

USING DEPT NO: 204906	OPENED DATE: 01/29/2024 09:21:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/29/2024 13:16:45	METER 1 - M: 41785 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/29/2024 15:22:52	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.39	\$21.70	\$0.00	\$28.09
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.38	\$44.71	\$0.00	\$0.00	\$44.71
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.52	\$60.83	\$0.00	\$89.35
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.06	\$7.44	\$11.79	\$0.00	\$19.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.70	\$0.00	\$0.00	\$1.70

JOB COUNT: 6	WORK ORDER TOTAL:	0.75	88.76	94.32	5.00	188.08
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	01/29/2024 10:19:50	01/29/2024 10:20:42	0.01	\$1.70
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/29/2024 09:57:06	01/29/2024 10:19:50	0.38	\$44.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	01/29/2024 09:53:19	01/29/2024 09:57:06	0.06	\$7.44
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/29/2024 09:50:04	01/29/2024 09:53:19	0.05	\$6.39
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2024 09:35:34	01/29/2024 09:50:04	0.24	\$28.52
					LABOR	88.76

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.83	1	\$7.83

Work Order Charge Detail

PARTS

94.32

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 49616

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) SH FC Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires and inspected the brakes. Front outer pads are at 4MM. Need to check at next PM. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Did not wash. SH

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50038

USING DEPT NO: 204906	OPENED DATE: 03/04/2024 08:16:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/04/2024 08:19:50	METER 1 - M: 41785 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/04/2024 14:13:07	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$742.41	\$742.41
16-02	TRANSPORT CAB & SHEET METAL	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	747.41	806.41
---------------------	--------------------------	-------------	--------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2115978		\$742.41
03-02-061	REPLACE NEW WINDSHIELD	11078716	2115978		(\$742.41)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2115978		\$742.41
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					747.41

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11399745	03/04/2024 08:17:58	03/04/2024 08:47:58	0.50	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	11399745	03/04/2024 08:17:58	03/04/2024 08:47:58	0.50	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	11399745	03/04/2024 08:17:58	03/04/2024 08:47:58	(0.50)	(\$59.00)
LABOR						59.00

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50038

Work Order Notes

(LISAPATE) Windshield is cracked

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield. PD by CC
(LRUSHING) Visit Reason Changed On 3/27/2024 8:25 AM By LRUSHING

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass DR by CW/RC
(LRUSHING) Visit Reason Changed On 3/27/2024 8:26 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 3/27/2024 8:26 AM By LRUSHING

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50363

USING DEPT NO: 204906	OPENED DATE: 04/01/2024 08:58:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/02/2024 07:44:04	METER 1 - M: 46615 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/02/2024 12:36:22	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.77	\$53.00	\$0.00	\$70.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.14	\$16.16	\$0.00	\$0.00	\$16.16

JOB COUNT: 3	WORK ORDER TOTAL:	0.29	33.93	53.00	5.00	91.93
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	04/01/2024 09:39:02	04/01/2024 09:47:15	0.14	\$16.16
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/01/2024 09:30:00	04/01/2024 09:39:02	0.15	\$17.77
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/01/2024 09:25:06	04/01/2024 09:25:06	0.00	\$0.00
LABOR					33.93	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
PARTS					53.00	

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50363

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Wash bay down for service gas pumps down. SH

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50729

USING DEPT NO: 204906	OPENED DATE: 05/02/2024 13:34:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/06/2024 07:31:16	METER 1 - M: 46615 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/06/2024 07:31:19	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$707.96	\$707.96
16-02-061	TRANSPORT WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.00 0.00 0.00 707.96 707.96

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2118108		\$707.96
				COMML	707.96

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50729

Work Order Notes

(EHANNAH) windshield replaced by Glass DR

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(IFALLS) Visit Reason Changed On 5/6/2024 7:30 AM By IFALLS

16-02-061 - TRANSPORT WINDSHIELD

(IFALLS) chad performed transport

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50831

USING DEPT NO: 204906	OPENED DATE: 05/13/2024 14:41:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/14/2024 10:45:17	METER 1 - M: 50617 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/14/2024 12:59:48	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-029	PERFORM ROTATE AND BALANCE TIRE	DON	P	N	GARAGE	0.01	\$1.64	\$1.64	\$0.00	\$3.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.57	\$72.89	\$0.00	\$74.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.03	3.21	74.53	5.00	82.74
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/14/2024 07:30:22	05/14/2024 07:31:10	0.01	\$1.57
66-17-029	PERFORM ROTATE AND BALANCE TIRES	11074414	05/14/2024 08:05:04	05/14/2024 08:05:54	0.01	\$1.64
66-17-029	PERFORM ROTATE AND BALANCE TIRES	11074414	05/14/2024 08:05:04	05/14/2024 08:05:54	(0.01)	(\$1.64)
66-17-029	PERFORM ROTATE AND BALANCE TIRES	11074414	05/14/2024 08:05:04	05/14/2024 08:05:54	0.01	\$1.64
LABOR					3.21	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	8.91	6	\$53.46
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.51	1	\$0.51
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.50	(1)	(\$0.50)
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.51	(1)	(\$0.51)
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	(1)	(\$0.63)
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.51	1	\$0.51

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-029	PERFORM ROTATE AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
PARTS						74.53

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50831

Work Order Notes

(EHANNAH) pm- wash - rotate and balance tires

Job Notes

66-17-029 - PERFORM ROTATE AND BALANCE TIRES

(GARAGE) Cross rotated and balanced the tires per customer request. SH
(LRUSHING) Visit Reason Changed On 5/31/2024 10:18 AM By LRUSHING

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 51767

USING DEPT NO: 204906	OPENED DATE: 08/12/2024 09:17:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/21/2024 10:18:26	METER 1 - M: 55599 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/21/2024 11:11:28	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$1.82	\$0.00	\$1.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$80.78	\$0.00	\$80.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$11.79	\$0.00	\$11.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	94.39	5.00	99.39
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	19.71	1	\$19.71
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.57	1	\$11.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-79-003	PERFORM SAFETY INSPECTION	SANDPAPER	VAR GRIT SINGLE SHEET SANDPAPE	1.82	1	\$1.82
					PARTS	94.39

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 51767

Work Order Notes

(EHANNAH) pm- wipers- SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SAFETY INSPECTION CEHCKED OK, CM

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PERFORMED PM CM CHANGED MOTOR OIL AND FILTER, CHECEKD ALL FLUIDS, CHECKED OK, AIR FILTER CHECKED OK,

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) REPLACED CABIN AIR FILTER

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) WASHED VEHICLE

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52543

USING DEPT NO: 204906	OPENED DATE: 10/21/2024 10:37:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/22/2024 07:33:31	METER 1 - M: 59500 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/22/2024 07:46:04	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$21.70	\$0.00	\$21.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.45	\$0.00	\$63.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	85.15	5.00	90.15
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	13.77	1	\$13.77
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
PARTS						85.15

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52543

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced blades cm

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm cm/gc 59500 miles, changed motor oil and filter checked all fluids filter, tires checked ok,

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed cm

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52935

USING DEPT NO: 204906	OPENED DATE: 12/02/2024 09:09:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/03/2024 14:56:18	METER 1 - M: 59500 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/06/2024 13:52:27	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-008	REPLACE NEW VALVE ASSEMBLY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52935

Work Order Notes

(EHANNAH) driver rear has leak at the valve steam- plans changed and they will bring it in on Friday of this week. 12/6/2024.

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 53279

USING DEPT NO: 204906	OPENED DATE: 01/06/2025 11:04:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/08/2025 13:52:02	METER 1 - M: 63394 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/09/2025 12:41:04	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$842.34	\$0.00	\$842.34
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.57	\$0.00	\$60.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	902.91	5.00	907.91
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.58	4	\$18.30
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.22	1	\$14.22
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	6	\$38.70
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	F000181	TIRE LT245/75R16 FS TFORCE AT2	206.01	4	\$824.04
PARTS						902.91

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 53279

Work Order Notes

(EHANNAH) pm- tire patch
(EHANNAH) FOUR NEW TIRES MOUNT AND BALANCE

Job Notes

66-17-013 - PERFORM ALIGNMENT

(GARAGE) aligned vehicle test drove checked ok, cm

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) mounted and balanced 4 tires checked ok, cm 63394 miles,

66-17-030 - PERFORM TIRE PATCH

(GARAGE) LR tire had screw in it and was unable to be patched, swapped it with the spare, customer was unable to leave vehicle here
LF tire has nail in it but was not leaking air, edges were approaching 3/32
RF tire edge was approaching 2/32
RR tire was fine and needs to be saved to use as a spare
quoted 4 new tires, customer will need to bring vehicle back to get the new set

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside
CM- pit
perform pM, changed oil and filter, checked air filters, checked fluids, checked tires and tire pressures changed sticker, reset oil light
63394 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 54476

USING DEPT NO: 204906	OPENED DATE: 04/14/2025 09:50:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/14/2025 10:20:03	METER 1 - M: 68417 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/14/2025 13:48:58	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4	2020 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$49.32	\$0.00	\$49.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	49.32	5.00	54.32
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.80	1	\$10.80
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
PARTS						49.32

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 54476

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside

FJ- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid

68417 miles

waiter

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) JR- washed vehicle

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 55278

USING DEPT NO: 204906	OPENED DATE: 07/07/2025 09:40:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/07/2025 14:47:57	METER 1 - M: 73663 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/08/2025 12:43:11	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	0.00	\$0.00	\$69.60	\$0.00	\$69.60
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$56.69	\$0.00	\$56.69
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$18.14	\$0.00	\$18.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	144.43	5.00	149.43
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR17976	BRAKE PADS	69.60	1	\$69.60
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	31.64	1	\$31.64
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	31.64	(1)	(\$31.64)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	18.14	1	\$18.14
					PARTS	144.43

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 55278

Work Order Notes

(EHANNAH) pm- wipers- wash- SI

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(GARAGE) removed front brake pads and hardware, pads where 1mm on the front. installed new pads and hardware. cq 1.0hr

66-13-130 - PERFORM Burnish Brakes

(GARAGE) burnished brakes.cq 0.5 hr

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ/JR- Performed SI. All steering/suspension checked ok at this time. Front brakes are 1mm. Rear brakes (shoes) 5mm.
CQ installed new front pads

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 73,663 miles

PM
FJ- Added oil & verified level, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.
JR- Oil change
CQ- Changed cabin air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) fj replaced cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 55641

USING DEPT NO: 204906	OPENED DATE: 07/29/2025 10:58:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/06/2025 08:47:51	METER 1 - M: 74971 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/07/2025 09:05:01	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOM4X4 2020 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TMCZ5AN5LM309104

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243615 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 55641

Work Order Notes

(CWIGLEY) Prep for sale.

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) JR- prepped vehicle for sale, no gps

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Aug 08 2025 11:18:42 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243615') //Q=