

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 34382

USING DEPT NO:	750101	OPENED DATE:	10/08/2019 14:43:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/09/2019 10:50:12	METER 1 - M:	53	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/09/2019 10:50:14	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	10/08/2019 14:43:53	10/08/2019 15:13:53	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 34382

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36937

USING DEPT NO:	750101	OPENED DATE:	06/24/2020 07:27:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/24/2020 13:14:18	METER 1 - M:	14164	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/24/2020 13:58:21	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$0.00	\$23.78	\$0.00	\$23.78

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	23.78	0.00	23.78
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/24/2020 10:14:57	06/24/2020 10:44:45	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
					PARTS	23.78

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36937

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) performed pm service. found no issues at this time (EK,RC/JAW) coolant -34°

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38238

USING DEPT NO:	750101	OPENED DATE:	11/02/2020 11:17:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/03/2020 07:37:23	METER 1 - M:	16645	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/03/2020 10:18:44	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.44	\$35.68	\$0.00	\$51.12

JOB COUNT: 1	WORK ORDER TOTAL:					0.13	15.44	35.68	0.00	51.12
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2020 11:49:45	11/02/2020 11:57:36	0.13	\$15.44
					LABOR	15.44

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
					PARTS	35.68

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38238

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH RC/SH PERFORMED PM.

(SHARBIN) Vacuumed out vehicle, unable to wash, carwash down, no fuel needed. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39763

USING DEPT NO:	750101	OPENED DATE:	04/21/2021 09:47:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2021 15:09:56	METER 1 - M:	22596	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 08:18:16	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$41.30	\$30.07	\$0.00	\$71.37

JOB COUNT: 1	WORK ORDER TOTAL:	0.35	41.30	30.07	0.00	71.37
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2021 12:41:13	04/22/2021 12:41:13	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2021 12:41:13	04/22/2021 12:41:13	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2021 12:41:13	04/22/2021 12:47:13	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/22/2021 12:11:05	04/22/2021 12:11:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/22/2021 12:11:05	04/22/2021 12:11:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/22/2021 12:11:05	04/22/2021 12:26:05	0.25	\$29.50
					LABOR	41.30

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
					PARTS	30.07

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39763

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 22596 Completed PM topside, Josh was bottomside. AMG/JW Completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40905

USING DEPT NO:	750101	OPENED DATE:	09/01/2021 10:20:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2021 08:08:03	METER 1 - M:	28274	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/07/2021 08:23:16	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$93.52	\$34.76	\$0.00	\$128.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.79	93.52	34.76	2.00	130.28
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/01/2021 12:02:22	09/01/2021 12:24:04	0.36	\$42.68
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/01/2021 12:02:36	09/01/2021 12:28:27	0.43	\$50.84
LABOR						93.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.70	1	\$5.70
PARTS						34.76

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40905

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 28274 Completed PM topside, Josh was bottomside. Completed checklist. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42478

USING DEPT NO:	750101	OPENED DATE:	02/25/2022 08:28:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/28/2022 15:04:19	METER 1 - M:	34200	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2022 07:23:42	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.11	\$22.62	\$0.00	\$31.73
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.03	\$3.64	\$0.00	\$0.00	\$3.64
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.90	\$28.48	\$0.00	\$91.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.64	75.65	51.10	2.00	128.75
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-015	PERFORM TIRE ROTATION	12052187	02/25/2022 13:47:34	02/25/2022 13:49:25	0.03	\$3.64
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/25/2022 13:42:28	02/25/2022 13:42:37	0.00	\$0.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/25/2022 13:42:28	02/25/2022 13:42:37	0.00	(\$0.30)
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2022 12:15:51	02/25/2022 12:46:45	0.52	\$60.77
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2022 13:41:03	02/25/2022 13:42:08	0.02	\$2.13
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/25/2022 13:42:47	02/25/2022 13:47:25	0.08	\$9.11
				LABOR		75.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	(6)	(\$26.91)
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
				PARTS		51.10

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42478

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades. JAW,RC

66-17-015 - PERFORM TIRE ROTATION

(JWRIGHT) Rotated tires. Front pads are 10mm rear pads are 11mm

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/JAW
MILEAGE-28350

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44547

USING DEPT NO:	750101	OPENED DATE:	09/01/2022 10:29:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/02/2022 09:38:15	METER 1 - M:	39547	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 09:34:33	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$10.36	\$23.19	\$0.00	\$33.55
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.41	\$47.79	\$0.00	\$0.00	\$47.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.94	\$77.17	\$0.00	\$134.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.98	115.09	100.36	5.00	220.45
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11901357	09/01/2022 12:46:56	09/01/2022 13:11:14	0.41	\$47.79
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/01/2022 10:43:50	09/01/2022 10:51:19	0.12	\$14.72
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/01/2022 12:19:38	09/01/2022 12:41:06	0.36	\$42.22
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/01/2022 12:41:22	09/01/2022 12:46:38	0.09	\$10.36
				LABOR		115.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	35.19	1	\$35.19
				PARTS		100.36

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44547

Work Order Notes

(LISAPATE) PM--replace wipers-DO SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) Completed safety inspection, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 39547 Completed PM topside, Josh was bottomside. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46148

USING DEPT NO:	750101	OPENED DATE:	02/14/2023 10:12:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2023 11:43:20	METER 1 - M:	46973	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2023 07:28:00	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.69	\$0.00	\$0.00	\$2.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.62	\$61.72	\$0.00	\$80.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.18	21.31	61.72	5.00	88.03
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/14/2023 13:00:00	02/14/2023 13:09:28	0.16	\$18.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/14/2023 12:58:04	02/14/2023 12:58:04	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/14/2023 11:53:02	02/14/2023 11:54:24	0.02	\$2.69
LABOR					21.31	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	8.01	1	\$8.01
PARTS					61.72	

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46148

Work Order Notes

(EHANNAH) Pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47193

USING DEPT NO:	750101	OPENED DATE:	05/30/2023 09:55:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/31/2023 15:38:19	METER 1 - M:	46973	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2023 15:38:20	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$730.25	\$730.25
16-00	TRANSPORT COMPLETE VEHICLE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	735.25	794.25
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2108918		\$730.25
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					735.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-00	TRANSPORT COMPLETE VEHICLE	11399745	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47193

Work Order Notes

(EHANNAH) replace new windshield- and transport to vendor

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield PD by CC

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) Taken to Glass Dr by CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47562

USING DEPT NO:	750101	OPENED DATE:	07/11/2023 07:12:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/12/2023 11:18:29	METER 1 - M:	52242	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/12/2023 14:04:17	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.77	\$34.15	\$0.00	\$39.92
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.31	\$36.81	\$0.00	\$0.00	\$36.81
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.97	\$114.53	\$0.00	\$0.00	\$114.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.76	\$48.22	\$0.00	\$99.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
CU-13-001	CUT FRONT BRAKES & ROTORS	DON	N	N	GARAGE	1.09	\$128.72	\$0.00	\$0.00	\$128.72
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$2.95	\$0.00	\$0.00	\$2.95

JOB COUNT: 7	WORK ORDER TOTAL:	2.89	340.54	82.37	5.00	427.91
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12052187	07/11/2023 14:39:10	07/11/2023 14:40:40	0.03	\$2.95
66-13-130	PERFORM Burnish Brakes	12052187	07/11/2023 14:40:40	07/11/2023 15:38:54	0.97	\$114.53
CU-13-001	CUT FRONT BRAKES & ROTORS	12052187	07/11/2023 14:30:00	07/11/2023 14:39:10	0.15	\$18.03
CU-13-001	CUT FRONT BRAKES & ROTORS	12052187	07/11/2023 13:18:43	07/11/2023 14:15:00	0.94	\$110.69
06-13	INSPECT BRAKES	12052187	07/11/2023 13:00:00	07/11/2023 13:18:43	0.31	\$36.81
06-13	INSPECT BRAKES	12052187	07/11/2023 12:40:28	07/11/2023 12:40:28	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/11/2023 11:44:42	07/11/2023 11:47:38	0.05	\$5.77
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/11/2023 11:18:23	07/11/2023 11:44:42	0.44	\$51.76
					LABOR	340.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	10.07	1	\$10.07
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.11	1	\$6.11
					PARTS	82.37

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47562

Work Order Notes

(EHANNAH) pm- replace wipers- wash- inspect brakes- driver reports shutters when brakes are applied.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

06-13 - INSPECT BRAKES

(GARAGE) inspected brakes. front pads are 6mm and rear pads are 8mm. test drove and felt a little pulsing in brakes. Discussed with IF and going to cut front rotors and reuse pads. JAW

66-13-130 - PERFORM Burnish Brakes

(GARAGE) burnished brakes and unit drove good no pulsating. delivered unit to customer after burnishing. JAW

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

CU-13-001 - CUT FRONT BRAKES & ROTORS

(GARAGE) Cut front rotors to 27.66 left side and 27.69mm right side. minimum spec is 25mm. JAW

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) hand washed unit. JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49254

USING DEPT NO:	750101	OPENED DATE:	12/14/2023 07:11:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2023 09:53:53	METER 1 - M:	52242	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/18/2023 11:27:17	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.03	\$3.44	\$0.00	\$0.00	\$3.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$4.46	\$43.21	\$0.00	\$47.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.64	\$0.00	\$0.00	\$3.64

JOB COUNT: 4	WORK ORDER TOTAL:	0.10	11.54	43.21	5.00	59.75
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12201267	12/14/2023 13:24:36	12/14/2023 13:26:21	0.03	\$3.44
WA-00	WASH COMPLETE VEHICLE	12201267	12/14/2023 13:20:54	12/14/2023 13:22:45	0.03	\$3.64
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/14/2023 13:18:27	12/14/2023 13:20:43	0.04	\$4.46
				LABOR		11.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.29	5	\$31.43
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
					PARTS	43.21

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49254

Work Order Notes

(EHANNAH) pm- wash- FD tire is low

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GRCOOK) Inspected tires, front tire was low on air pressure, SH added air during the PM and tire light went off. -GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- SH, GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-CW

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 50966

USING DEPT NO:	750101	OPENED DATE:	05/30/2024 07:40:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/31/2024 10:31:13	METER 1 - M:	52242	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2024 10:31:16	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.02	\$2.66	\$0.00	\$0.00	\$2.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.28	\$85.12	\$0.00	\$86.40
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.25	\$13.17	\$0.00	\$14.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.25	\$0.00	\$0.00	\$1.25

JOB COUNT: 5	WORK ORDER TOTAL:	0.05	6.44	98.29	5.00	109.73
--------------	-------------------	------	------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	05/30/2024 11:39:45	05/30/2024 11:40:23	0.01	\$1.25
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/30/2024 11:39:07	05/30/2024 11:39:45	0.01	\$1.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/30/2024 11:38:28	05/30/2024 11:39:07	0.01	\$1.28
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/30/2024 11:41:11	05/30/2024 11:42:32	0.02	\$2.66
				LABOR		6.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	5	\$34.88
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.67	1	\$11.67
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	AIR FILTER	30.92	1	\$30.92
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5667	CABIN FILTER	13.17	1	\$13.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
				PARTS		98.29

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 50966

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires and inspected the brakes. Suggest a set of tires at the next PM. Found no other issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/GC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed Gas pumps were down. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 53196

USING DEPT NO:	750101	OPENED DATE:	12/18/2024 11:30:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2024 15:45:56	METER 1 - M:	79125	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2024 07:33:02	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$46.34	\$0.00	\$46.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	46.34	5.00	51.34
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.09	1	\$14.09
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	5	\$32.25
					PARTS	46.34

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 53196

Work Order Notes

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- PM. Oil change, set tire pressure, recorded date codes & tread depths, checked filters

FJ- ***only added oil and verified oil level

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Wash bay is still INOP as of 12:20 p.m.

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 54740

USING DEPT NO:	750101	OPENED DATE:	05/12/2025 07:15:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/13/2025 12:31:38	METER 1 - M:	82652	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/13/2025 14:14:19	IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	0.00	\$0.00	\$187.71	\$0.00	\$187.71
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$864.72	\$0.00	\$864.72
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$55.16	\$0.00	\$55.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	1,107.59	5.00	1,112.59
--------------	-------------------	------	------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	8.91	5	\$44.55
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04493640000	TIRE 245/60R18 GEN GRAB	211.82	4	\$847.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.37	4	\$17.46
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR171324	FRONT BRAKE PADS	78.03	1	\$78.03
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	FBR5B980636	FRONT ROTORS	54.84	2	\$109.68
					PARTS	1107.59

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 54740

Work Order Notes

(EHANNAH) pm-wash- SI

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(GARAGE) FOUND FRONT BRAKE PADS WHERE 2MM AND ROTOR THICKNESS OUT OF SPEC. ORDERED FRONT BRAKE PADS AND ROTORS. REMOVED CALIPERS, PADS AND ROTORS, INSTALLED NEW ROTORS PADS AND CALIPERS. INSTALLED TIRES AND OPERATED BRAKES, CHECKED FOR BRAKE PRESSURE ON PEDAL AND FOUND GOOD, FOUND BRAKE FLUID LEVEL GOOD, ROAD TESTED AND BURNISHED BRAKES ALL CHECKED OUT GOOD, RETURNED TO SERVICE. 1.5HR CQ.

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) ROAD TESTED AND BURNISHED BRAKES ALL CHECKED OUT GOOD, RETURNED TO SERVICE. CQ

66-17-013 - PERFORM ALIGNMENT

(GARAGE) CUSTOMER WILL BRING VEHICLE BY FOR ALIGNMENT AT A LATER DATE. CQ

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) FJ- Mounted/balanced 4 new tires. 21030 valve stem kit used (x4).

(EHOWELL) CUSTOMER WILL BRING VEHICLE BY FOR ALIGNMENT AT A LATER DATE. CQ

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) JR- perform SI per SI sheet, needs front pads and rotors, rear pads may need to be changed next pm, needs tires all the way around, everything else checked OK

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
82652 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 55214

USING DEPT NO:	750101	OPENED DATE:	06/26/2025 09:50:51	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/26/2025 15:38:35	METER 1 - M:	82977	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2025 09:04:56	IN-SERVICE DATE:	10/08/2019				
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander							
			UNIT SERIAL NO:	5TDZARFH5KS056568					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	0.00	\$0.00	\$197.01	\$0.00	\$197.01
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$3.23	\$0.00	\$3.23
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-40-419	INSPECT OIL PAN/GASKET	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
CU-13-001	CUT FRONT BRAKES & ROTORS	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 8						WORK ORDER TOTAL:		0.00	0.00	200.24
									5.00	205.24

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWR171391	REAR PADS	82.26	1	\$82.26
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBR5B980757	REAR ROTORS	57.38	2	\$114.75
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.23	1	\$3.23
					PARTS	200.24

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 55214

Work Order Notes

(EHANNAH) pm- inspect oil pan to be sure it gets tighten correctly, after last service there appeared to be a leak- inspect brakes due to shaking badly when stopping- replace battery in fob.

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EKIMBREL) removed rear tires and removed brake pads and rotors, cleaned up guide pins. guide pins where seized in housing and had to be beat out. and greased=cm. installed new rotors and brake pads and installed rear tires and burnished brakes. cq 1hr brakes 0.5 remove guide pins and clean.

03-51-042 - REPLACE NEW KEY FOB BATTERY

(GARAGE) replaced new battery and fob worked correctly. gc

06-13 - INSPECT BRAKES

(EKIMBREL) test drove and found front brakes grabbing, brought in shop and put on lift.

06-40-419 - INSPECT OIL PAN/GASKET

(GARAGE) GC,CM- jacked up unit on drive on rack, and had JR in the unit, raised unit up and me and GC,CM inspected the oil filter and the oil pan and had JR rev the engine and hold the RPMs and saw no leaks.

Miles, 82,977

66-13-130 - PERFORM Burnish Brakes

(EKIMBREL) cq burnished brakes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- PM, Fluid check only, checked fluids, filters good, tires and tire pressure, reset oil life and changed oil sticker

Miles, 82,977

CH-SP - CHARGE Shop Supplies

CU-13-001 - CUT FRONT BRAKES & ROTORS

(EKIMBREL) removed tires and calipers and cut both front rotors, found left front rotor warped. installed all that was removed and test drove found to check ok. returned to service. cq,cm. 1.0hr

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 55864

USING DEPT NO:	750101	OPENED DATE:	08/11/2025 09:00:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	82977	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	10/08/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH5KS056568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/12/2025 10:13:54 By User: GLOBETTI

UNIT NO: 243473 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 55864

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Aug 12 2025 10:13:54 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243473') //Q=