

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 35000

USING DEPT NO:	504191	OPENED DATE:	11/27/2019 08:06:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/06/2019 06:40:12	METER 1 - M:	256	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/06/2019 06:40:14	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.43	\$0.00	\$0.00	\$0.00	\$0.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.93	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	11/27/2019 13:00:49	11/27/2019 13:26:28	0.43	\$0.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	11/27/2019 08:07:09	11/27/2019 08:37:09	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 35000

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) Installed 4G GPS serial# 5041372840

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 37761

USING DEPT NO:	504191	OPENED DATE:	09/25/2020 10:13:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2020 10:47:35	METER 1 - M:	1055	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2020 13:40:41	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.17	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/25/2020 10:18:47	09/25/2020 10:29:06	0.17	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 37761

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1055 miles since last pm. Updated sticker and checked all fluids and tires. Coolant -34° JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 39206

USING DEPT NO:	504191	OPENED DATE:	02/25/2021 09:04:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/26/2021 07:13:04	METER 1 - M:	1410	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2021 15:30:58	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.99	\$116.72	\$33.36	\$0.00	\$150.08

JOB COUNT: 1	WORK ORDER TOTAL:	0.99	116.72	33.36	0.00	150.08
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2021 11:09:52	02/25/2021 11:13:16	0.06	\$6.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2021 09:59:11	02/25/2021 10:55:08	0.93	\$110.04
					LABOR	116.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
					PARTS	33.36

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 39206

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 1411. SH/AMG Performed PM. SH Washed vacuumed and filled with gas.

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 41473

USING DEPT NO:	504191	OPENED DATE:	11/01/2021 09:49:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 07:34:23	METER 1 - M:	2385	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/04/2021 07:34:26	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.59	\$15.18	\$0.00	\$19.77
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.29	\$34.45	\$0.00	\$0.00	\$34.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$40.38	\$35.34	\$0.00	\$75.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.67	79.42	50.52	2.00	131.94
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/02/2021 08:08:45	11/02/2021 08:26:16	0.29	\$34.45
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/02/2021 08:05:15	11/02/2021 08:07:35	0.04	\$4.59
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2021 07:44:31	11/02/2021 08:05:03	0.34	\$40.38
				LABOR		79.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.43	1	\$8.43
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
					PARTS	50.52

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 41473

Work Order Notes

(IFALLS) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 42665

USING DEPT NO:	504191	OPENED DATE:	03/21/2022 09:01:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2022 09:43:26	METER 1 - M:	2731	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2022 13:33:54	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.54	\$63.92	\$237.69	\$0.00	\$301.61
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.74	87.52	237.69	2.00	327.21
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	03/25/2022 07:00:00	03/25/2022 07:12:00	0.20	\$23.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	03/22/2022 10:09:09	03/22/2022 10:28:30	0.32	\$38.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	03/22/2022 07:53:25	03/22/2022 08:06:34	0.22	\$25.86
66-17-030	PERFORM TIRE PATCH	11901357	03/21/2022 09:25:49	03/21/2022 09:25:49	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	11901357	03/21/2022 09:30:00	03/21/2022 09:38:14	(0.14)	(\$16.19)
66-17-030	PERFORM TIRE PATCH	11901357	03/21/2022 09:30:00	03/21/2022 09:38:14	0.14	\$16.19
66-17-030	PERFORM TIRE PATCH	11901357	03/21/2022 09:25:49	03/21/2022 09:25:49	0.00	\$0.00
					LABOR	87.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	232.50	1	\$232.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.36	(1)	(\$0.36)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.36	1	\$0.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.36	1	\$0.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.83	1	\$4.83
					PARTS	237.69

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 42665

Work Order Notes

(LISAPATE) Front left tire has a nail in it

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) miles: 2731 Replaced and balanced L/F tire. AMG

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) Unable to repair, nail to close to sidewall. Replace tire. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 42822

USING DEPT NO:	504191	OPENED DATE:	04/05/2022 08:28:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/05/2022 10:45:51	METER 1 - M:	2783	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2022 09:31:15	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.08	\$15.18	\$0.00	\$18.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.36	42.02	15.18	2.00	59.20
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/05/2022 09:30:00	04/05/2022 09:31:34	0.03	\$3.08
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/05/2022 09:29:57	04/05/2022 09:29:57	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/05/2022 09:20:13	04/05/2022 09:20:13	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/05/2022 09:20:13	04/05/2022 09:20:13	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/05/2022 09:20:13	04/05/2022 09:40:01	0.33	\$38.94
				LABOR		42.02

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
					PARTS	15.18

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 42822

Work Order Notes

(CHANSELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 391 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-2776

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 44526

USING DEPT NO:	504191	OPENED DATE:	08/31/2022 08:15:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/01/2022 15:26:56	METER 1 - M:	3269	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 09:21:06	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.92	\$15.62	\$0.00	\$18.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$40.29	\$0.00	\$79.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.35	41.86	55.91	5.00	102.77
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/01/2022 07:00:00	09/01/2022 07:19:48	0.33	\$38.94
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/01/2022 07:00:00	09/01/2022 07:18:00	(0.30)	(\$35.40)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/01/2022 07:00:00	09/01/2022 07:18:00	0.30	\$35.40
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/31/2022 09:13:31	08/31/2022 09:15:00	0.02	\$2.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2022 08:48:11	08/31/2022 09:13:18	0.42	\$49.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2022 08:48:11	08/31/2022 09:13:18	(0.42)	(\$49.40)
				LABOR		41.86

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.64	1	\$5.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.80	1	\$7.80
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
				PARTS		55.91

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 44526

Work Order Notes

(CWIGLEY) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. JW/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) cancel

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 46021

USING DEPT NO:	504191	OPENED DATE:	02/01/2023 10:58:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2023 09:49:05	METER 1 - M:	3601	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2023 10:13:56	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.42	\$48.97	\$0.00	\$0.00	\$48.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.47	\$0.00	\$0.00	\$15.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.55	64.44	0.00	5.00	69.44
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12052187	02/01/2023 12:20:42	02/01/2023 12:45:36	0.42	\$48.97
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/01/2023 12:12:39	02/01/2023 12:20:31	0.13	\$15.47
					LABOR	64.44

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 46021

Work Order Notes

(EHANNAH) pm- replace wipers- perform safety inspections

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Found no issues. Brake pads are 11mm all around. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 332 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-3601

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 46322

USING DEPT NO:	504191	OPENED DATE:	03/01/2023 12:12:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/03/2023 14:26:09	METER 1 - M:	3625	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2023 07:42:59	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-34-001	TRANSPORT HEADLAMPS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-34-001	RECALL HEADLAMPS	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
17-34-001	RECALL HEADLAMPS	11076422	6195261		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-34-001	TRANSPORT HEADLAMPS	11399745	03/03/2023 07:00:00	03/03/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 46322

Work Order Notes

(CWIGLEY) Recall on headlights. Transport

Job Notes

16-34-001 - TRANSPORT HEADLAMPS

(LISAPATE) Visit Reason Changed On 3/3/2023 2:22 PM By LISAPATE

(LISAPATE) Taken to Toyota by CW

17-34-001 - RECALL HEADLAMPS

(LISAPATE) Tuscaloosa Toyota completed recall for water leak center hight mounted stop lamp-water leak

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 47589

USING DEPT NO:	504191	OPENED DATE:	07/13/2023 08:38:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2023 11:30:56	METER 1 - M:	4041	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2023 12:27:54	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.05	\$16.66	\$0.00	\$21.71
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.95	\$43.82	\$0.00	\$60.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.09	\$10.10	\$0.00	\$0.00	\$10.10

JOB COUNT: 4	WORK ORDER TOTAL:	0.27	32.10	60.48	5.00	97.58
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	07/13/2023 11:07:04	07/13/2023 11:12:12	0.09	\$10.10
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/13/2023 11:04:30	07/13/2023 11:07:04	0.04	\$5.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/13/2023 11:03:02	07/13/2023 11:04:30	0.02	\$2.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/13/2023 08:58:10	07/13/2023 09:05:19	0.12	\$14.06
				LABOR		32.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	OW20BT	BULK OIL OW20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.20	1	\$6.20
				PARTS		60.48

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 47589

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH GC/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 49611

USING DEPT NO:	504191	OPENED DATE:	01/29/2024 08:20:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2024 08:37:05	METER 1 - M:	4806	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/13/2024 09:30:14	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.15	\$21.70	\$0.00	\$22.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$27.86	\$0.00	\$0.00	\$27.86
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.28	\$11.79	\$0.00	\$13.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.44	\$0.00	\$0.00	\$3.44

JOB COUNT: 5	WORK ORDER TOTAL:	0.29	33.73	33.49	5.00	72.22
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	01/29/2024 14:13:15	01/29/2024 14:15:00	0.03	\$3.44
03-51-038	REPLACE NEW WIPER BLADES	12395904	01/29/2024 14:12:17	01/29/2024 14:12:52	0.01	\$1.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	01/29/2024 14:11:08	01/29/2024 14:11:47	0.01	\$1.28
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/29/2024 13:56:18	01/29/2024 14:10:28	0.24	\$27.86
				LABOR		33.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
				PARTS		33.49

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 49611

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check FC

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) cabin filter fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) was fc

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 52060

USING DEPT NO:	504191	OPENED DATE:	09/09/2024 10:44:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2024 09:26:06	METER 1 - M:	5682	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2024 09:26:06	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.30	\$0.00	\$48.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	48.30	5.00	53.30
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
					PARTS	48.30

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 52060

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL)
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated tires and inspected brakes-GC
Brakes are Front 10mm and Rear shoes are 8mm
Miles, 5,682

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 5,682

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-RC

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 53734

USING DEPT NO:	504191	OPENED DATE:	02/12/2025 09:52:40	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/12/2025 14:16:57	METER 1 - M:	6230	METER 2 - H:	0				
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	02/12/2025 15:07:44	IN-SERVICE DATE:	11/25/2019						
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma									
			UNIT SERIAL NO:	5TFAX5GN8KX161737							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.66	\$0.00	\$16.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	16.66	5.00	21.66
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
PARTS						16.66

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 53734

Work Order Notes

(GARAGE) safety inspection canceled

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR- replaced wipers

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- PM, fluid check only, vehicle driven 548 miles, checked fluids, filters good, tires and tire pressure, updated oil change sticker
Miles, 6,230

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 55829

USING DEPT NO:	504191	OPENED DATE:	08/08/2025 07:11:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	COMPLETED	COMPLETED DATE:	08/13/2025 08:24:53	METER 1 - M:	6798	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8KX161737	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$40.44	\$0.00	\$40.44

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	40.44	0.00	40.44
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	40.44	1	\$40.44
					PARTS	40.44

Work Order Charge Detail

The University of Alabama

Report Printed: 08/13/2025 08:56:29 By User: GLOBETTI

UNIT NO: 243574 2019 TOYOTA TACOMA

WORK ORDER NO: 55829

Work Order Notes

(EKIMBREL) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) cm removed gps
#87U030640156

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm performed prep for sale unit checked ok, 6753 miles,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Aug 13 2025 08:56:29 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243574') //Q=