

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 35206

USING DEPT NO:	750101	OPENED DATE:	12/16/2019 14:01:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2019 06:51:01	METER 1 - M:	100	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2019 06:51:05	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	12052187	12/16/2019 14:02:30	12/16/2019 14:32:30	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 35206

## Work Order Notes

(EKIMBREL) PDI

## Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) JW performed PDI

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 35826

USING DEPT NO:	750101	OPENED DATE:	02/28/2020 10:20:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2020 15:08:11	METER 1 - M:	5094	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/02/2020 15:08:12	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$0.00	\$24.38	\$0.00	\$24.38

JOB COUNT: 1	WORK ORDER TOTAL:	0.47	0.00	24.38	0.00	24.38
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/28/2020 10:22:03	02/28/2020 10:37:59	0.27	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/28/2020 10:22:48	02/28/2020 10:35:12	0.21	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	4.01	5	\$20.05
					PARTS	24.38

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 35826

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW  
Coolant -50'

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 36542

USING DEPT NO:	750101	OPENED DATE:	05/21/2020 11:49:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/22/2020 09:39:05	METER 1 - M:	9318	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/22/2020 09:39:05	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.01	\$0.00	\$24.03	\$0.00	\$24.03

JOB COUNT: 1	WORK ORDER TOTAL:	1.01	0.00	24.03	0.00	24.03
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11310047	05/21/2020 13:19:50	05/21/2020 13:53:41	0.56	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/21/2020 13:03:09	05/21/2020 13:29:46	0.44	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.94	5	\$19.70
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					PARTS	24.03

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 36542

---

## Work Order Notes

(EKIMBREL) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) EH/JW performed pm. Coolant -34

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 37298

USING DEPT NO:	750101	OPENED DATE:	08/10/2020 13:57:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/11/2020 14:51:45	METER 1 - M:	14323	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/12/2020 12:28:40	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$0.00	\$28.12	\$0.00	\$28.12

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.18</b>	<b>0.00</b>	<b>28.12</b>	<b>0.00</b>	<b>28.12</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2020 14:15:00	08/10/2020 14:25:42	0.18	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2020 14:14:36	08/10/2020 14:14:36	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/10/2020 14:14:07	08/10/2020 14:14:07	0.00	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.90	5	\$19.50
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					<b>PARTS</b>	<b>28.12</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 37298

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) performed PM topside. AMG  
(SHARBIN) Performed PM bottom side. SH

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 38649

USING DEPT NO:	750101	OPENED DATE:	12/14/2020 12:44:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2020 14:27:36	METER 1 - M:	19359	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/15/2020 08:12:55	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.79	\$42.54	\$0.00	\$143.33

JOB COUNT: 1	WORK ORDER TOTAL:	0.85	100.79	42.54	0.00	143.33
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/14/2020 13:00:00	12/14/2020 13:37:58	0.63	\$74.67
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/14/2020 12:48:27	12/14/2020 12:48:27	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/14/2020 13:00:00	12/14/2020 13:13:17	0.22	\$26.12
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/14/2020 12:48:32	12/14/2020 12:48:32	0.00	\$0.00
					<b>LABOR</b>	<b>100.79</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.86	1	\$6.86
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					<b>PARTS</b>	<b>42.54</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 38649

---

## Work Order Notes

(EKIMBREL) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Adjusted air pressures and reset tpms. All tires were 5-10lbs low due to cold weather. Coolant -34°JAW/AMG

MILEAGE-19359

Washed and vacuumed

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 38923

USING DEPT NO:	750101	OPENED DATE:	01/27/2021 09:02:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/29/2021 08:56:30	METER 1 - M:	21721	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/29/2021 10:44:39	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.10	\$11.70	\$241.70	\$0.00	\$253.40

JOB COUNT: 1	WORK ORDER TOTAL:	0.10	11.70	241.70	0.00	253.40
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	01/28/2021 07:11:09	01/28/2021 07:17:06	0.10	\$11.70
					LABOR	11.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	1	\$3.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	240.63	1	\$240.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21097	TPMS NICKEL VALVE CORE	0.29	1	\$0.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	(1)	(\$3.32)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	1	\$0.42
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	6	\$0.36
					PARTS	241.70

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI*

**UNIT NO:**                    **243620**                    **2020 TOYOTA CAMRY**

**WORK ORDER NO:**                    **38923**

---

## Work Order Notes

(LISAPATE) Per Candace LR tire keeps going low on air  
(LISAPATE) Nail is in sidewall tire cannot be repaired.

---

## Job Notes

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced LR tire with new and balanced. Aired and torqued to spec. JAW

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 39505

USING DEPT NO:	750101	OPENED DATE:	03/29/2021 08:40:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2021 14:16:28	METER 1 - M:	24856	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2021 07:31:38	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.18	\$20.91	\$0.00	\$0.00	\$20.91
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$5.28	\$42.24	\$0.00	\$47.52

JOB COUNT: 3	WORK ORDER TOTAL:	0.22	26.19	42.24	46.00	114.43
--------------	-------------------	------	-------	-------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	286179		\$46.00
				COMML	46.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/29/2021 09:05:45	03/29/2021 09:08:26	0.04	\$5.28
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	03/29/2021 09:11:33	03/29/2021 09:22:11	0.18	\$20.91
				LABOR		26.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
				PARTS		42.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 39505

## Work Order Notes

(LISAPATE) PM-Repair ding in the windshield

## Job Notes

### **24-02-061 - REPAIR WINDSHIELD**

(LISAPATE) Glass Dr repaired windshield. Driver went to Glass Dr no transport needed.

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(AGUERRA) rotated tires and inspected brakes, no issues found. AMG SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -35°. AMG,SH/JAW  
MILEAGE-24856

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 40264

USING DEPT NO:	750101	OPENED DATE:	06/28/2021 08:24:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2021 15:13:57	METER 1 - M:	30214	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/29/2021 08:54:42	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.02	\$2.23	\$15.99	\$0.00	\$18.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.99	\$116.39	\$73.37	\$0.00	\$189.76

JOB COUNT: 2	WORK ORDER TOTAL:	1.01	118.62	89.36	0.00	207.98
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/28/2021 08:39:58	06/28/2021 09:01:53	0.37	\$43.10
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/28/2021 09:17:55	06/28/2021 09:17:55	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/28/2021 08:37:44	06/28/2021 09:15:00	0.62	\$73.29
03-51-038	REPLACE NEW WIPER BLADES	11901357	06/28/2021 09:28:55	06/28/2021 09:28:55	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	06/28/2021 09:30:00	06/28/2021 09:31:08	0.02	\$2.23
PA-78-036	PAINTED TOUCH UP PAINT	11901357	06/28/2021 09:31:29	06/28/2021 09:34:28	(0.05)	(\$5.87)
PA-78-036	PAINTED TOUCH UP PAINT	11901357	06/28/2021 09:31:29	06/28/2021 09:34:28	0.05	\$5.87
					LABOR	118.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	1	\$9.23
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.32	1	\$7.32
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	8.67	1	\$8.67
66-PM-PMA	PERFORM OIL CHANGE	17801F0050	AIR FILTER 2018 CAMRY	29.79	1	\$29.79
					PARTS	89.36

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 40264

## Work Order Notes

(LISAPATE) PM-touch up scratch on LR door

(LISAPATE) Body Shop is doing quote for scratch in door

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Ethan replaced wipers, checked for proper operation, all good. EH

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 30214 Completed PM topside, Ethan assisted, Scott was bottomside. Completed checklist and vacuumed out vehicle. AMG EH/SH

### **PA-78-036 - PAINTED TOUCH UP PAINT**

(AGUERRA) Ronny carried vehicle to Andrews for an estimate on repairing damage. RC



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 40808

USING DEPT NO:	750101	OPENED DATE:	08/23/2021 09:09:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2021 13:47:20	METER 1 - M:	30214	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/07/2021 08:05:20	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-44-003	RECALL FUEL PUMP	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,601.49	\$1,601.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.00	118.00	0.00	1,601.49	1,719.49
--------------	-------------------	------	--------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-44-003	RECALL FUEL PUMP	11076422	6129866		\$0.00
24-71	REPAIR BODY	11150605	16906507		\$1,601.49
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
					COMML 1601.49

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-44	TRANSPORT FUEL SYSTEM	11915538	09/03/2021 07:30:00	09/03/2021 08:00:00	0.50	\$59.00
16-71	TRANSPORT BODY	11915538	09/03/2021 07:00:00	09/03/2021 07:30:00	0.50	\$59.00
					LABOR	118.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 40808

## Work Order Notes

(LISAPATE) Take to Andrews to repair body damage left rear quarter panel area. Repairs are dept pay  
Unit also needs to go to Toyota for recall 20V-682 low pressure fuel pump may stop operating.

## Job Notes

### **16-44 - TRANSPORT FUEL SYSTEM**

(LISAPATE) Taken to Toyota by RC

### **16-71 - TRANSPORT BODY**

(LISAPATE) Taken to Andrews by RC

### **17-44-003 - RECALL FUEL PUMP**

(LISAPATE) Tuscaloosa Toyota performed recall replaced fuel pump kit

### **24-71 - REPAIR BODY**

(LISAPATE) Andrews repaired scratch in paint to Left rear panel. Pd by CC

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 41545

USING DEPT NO:	750101	OPENED DATE:	11/08/2021 11:12:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/09/2021 10:34:49	METER 1 - M:	36469	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2021 07:22:39	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.11	\$27.13	\$0.00	\$30.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.53	\$36.11	\$0.00	\$87.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.46	54.64	63.24	2.00	119.88
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/08/2021 13:53:00	11/08/2021 13:54:35	0.03	\$3.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/08/2021 13:26:38	11/08/2021 13:52:50	0.44	\$51.53
				LABOR		54.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.91	5	\$29.55
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.58	1	\$7.58
03-51-038	REPLACE NEW WIPER BLADES	WIX51394	OIL FILTER	9.24	1	\$9.24
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	63.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 41545

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/JAW  
MILEAGE-36469

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 41745

USING DEPT NO:	750101	OPENED DATE:	11/30/2021 15:19:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2021 09:18:35	METER 1 - M:	36469	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/09/2021 13:35:06	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$186.77	\$186.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>188.77</b>	<b>188.77</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	195121		\$186.77
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>188.77</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 41745

## Work Order Notes

(IFALLS) Per Candace Beers  
she had a flat tire in Selma AL and had firestone install a new tire.  
(IFALLS) Issac paid with his credit card.

## Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(IFALLS) Firestone replaced tire

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 42254

USING DEPT NO:	750101	OPENED DATE:	02/02/2022 08:38:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2022 11:32:31	METER 1 - M:	41454	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/03/2022 14:25:49	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.79	\$17.90	\$0.00	\$22.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$19.18	\$44.70	\$0.00	\$63.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.20	23.97	62.60	2.00	88.57
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/02/2022 09:00:14	02/02/2022 09:02:40	0.04	\$4.79
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/02/2022 08:49:53	02/02/2022 08:59:38	0.16	\$19.18
					LABOR	23.97

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.10	1	\$11.10
					PARTS	62.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 42254

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH EW/JW Performed PM.

**CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 42995

USING DEPT NO:	750101	OPENED DATE:	04/21/2022 08:09:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2022 10:56:50	METER 1 - M:	46432	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/25/2022 08:04:50	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.18	\$17.90	\$0.00	\$25.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.45	\$49.09	\$0.00	\$77.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	35.63	66.99	2.00	104.62
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/21/2022 08:27:43	04/21/2022 08:31:22	0.06	\$7.18
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/21/2022 08:17:53	04/21/2022 08:28:12	0.17	\$20.29
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/21/2022 08:23:22	04/21/2022 08:27:31	0.07	\$8.16
				LABOR		35.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.43	5	\$37.13
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.40	1	\$5.40
				PARTS		66.99

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 42995

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH JW/AMG Performed PM.

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 43566

USING DEPT NO:	750101	OPENED DATE:	06/08/2022 08:47:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/13/2022 14:50:02	METER 1 - M:	48233	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/14/2022 07:39:42	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-17-014	INSTALL SPARE TO GROUND	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.15	\$17.31	\$175.58	\$0.00	\$192.89
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.76	\$89.71	\$0.00	\$0.00	\$89.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.16	136.52	175.58	2.00	314.10
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-17-014	INSTALL SPARE TO GROUND	11074414	06/14/2022 07:00:00	06/14/2022 07:09:00	(0.15)	(\$17.70)
14-17-014	INSTALL SPARE TO GROUND	11074414	06/14/2022 07:00:00	06/14/2022 07:09:00	0.15	\$17.70
14-17-014	INSTALL SPARE TO GROUND	11074414	06/14/2022 07:00:00	06/14/2022 07:15:00	0.25	\$29.50
66-79-002	PERFORM SERVICE CALL	11074414	06/08/2022 09:30:00	06/08/2022 10:04:24	0.57	\$67.65
66-79-002	PERFORM SERVICE CALL	11074414	06/08/2022 09:03:47	06/08/2022 09:15:00	0.19	\$22.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/10/2022 08:11:55	06/10/2022 08:20:43	0.15	\$17.31
				LABOR		136.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	5	\$0.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	COATED 30G	COATED 30G WHEEL WEIGHT	0.06	1	\$0.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	9.63	1	\$9.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	165.06	1	\$165.06
				PARTS		175.58

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 43566

## Work Order Notes

(LISAPATE) Candace ran over something in the road tire is blown out.

## Job Notes

06-15 - INSPECT STEERING

09-15 - ALIGN STEERING

14-17-014 - INSTALL SPARE TO GROUND

(IFALLS) SH installed spare tire, brought flat tire back to shop and mounted new tire and reinstalled on car 2 days later.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(HHARBIN) Mounted and balanced 1 tire. SH

(HHARBIN) Reinstalled new tire on the vehicle and put the spare back in the trunk. SH

66-79-002 - PERFORM SERVICE CALL

(HHARBIN) Performed a service call to the Dollar General on highway 82 East for a flat tire. Put the spare tire on the vehicle. The tire can't be fixed it was ran flat. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 44128

USING DEPT NO:	750101	OPENED DATE:	08/01/2022 08:27:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/02/2022 11:38:33	METER 1 - M:	51336	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2022 14:30:22	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.39	\$45.44	\$0.00	\$73.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.24	28.39	45.44	2.00	75.83
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/01/2022 08:42:11	08/01/2022 08:54:19	0.20	\$23.86
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/01/2022 10:05:12	08/01/2022 10:07:30	0.04	\$4.52
				LABOR		28.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.49	5	\$37.43
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.01	1	\$8.01
					PARTS	45.44

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 44128

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 44546

USING DEPT NO:	750101	OPENED DATE:	09/01/2022 09:43:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2022 10:15:12	METER 1 - M:	51336	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 14:40:42	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$695.75	\$695.75
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	700.75	759.75
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2102385		\$695.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					700.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	09/06/2022 07:00:00	09/06/2022 07:30:00	0.50	\$59.00
LABOR						59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 44546

## Work Order Notes

(LISAPATE) Take to Glass Dr for a windshield cracked and running

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(LISAPATE) Glass Dr installed a new windshield and recalibrated. PD by CC

### **16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) Taken to Glass Dr by RC

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 44924

USING DEPT NO:	750101	OPENED DATE:	10/10/2022 08:04:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2022 15:18:36	METER 1 - M:	52986	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2022 07:22:59	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.64	\$18.40	\$0.00	\$24.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.83	\$41.34	\$0.00	\$75.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	39.47	59.74	5.00	104.21
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/10/2022 08:15:42	10/10/2022 08:32:54	0.29	\$33.83
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/10/2022 08:33:10	10/10/2022 08:36:02	0.05	\$5.64
					LABOR	39.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.81	5	\$34.05
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.58	1	\$10.58
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.29	1	\$7.29
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.29	(1)	(\$7.29)
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.29	1	\$7.29
					PARTS	59.74

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 44924

## Work Order Notes

(LISAPATE) PM-replace wipers-TPMS light keeps going on and off

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades. JAW

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/SH  
MILEAGE-52986

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 45362

USING DEPT NO:	750101	OPENED DATE:	11/28/2022 08:11:18	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2022 14:15:17	METER 1 - M:	60635	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2022 08:46:54	IN-SERVICE DATE:	12/16/2019						
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry									
			UNIT SERIAL NO:	4T1C11AKXLU863820							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.28	\$33.60	\$0.00	\$0.00	\$33.60
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.91	\$225.61	\$0.00	\$0.00	\$225.61
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.02	\$2.75	\$327.95	\$0.00	\$330.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.41	\$80.50	\$0.00	\$97.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.37	279.37	408.45	5.00	692.82
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	11/28/2022 08:37:09	11/28/2022 08:52:19	0.25	\$29.83
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	11/28/2022 08:37:09	11/28/2022 08:52:19	(0.25)	(\$29.83)
66-17-013	PERFORM ALIGNMENT	11310047	11/28/2022 14:30:00	11/29/2022 07:06:07	(16.60)	(\$1,959.03)
66-17-013	PERFORM ALIGNMENT	11310047	11/28/2022 14:30:00	11/29/2022 07:06:07	16.60	\$1,959.03
66-17-013	PERFORM ALIGNMENT	11310047	11/28/2022 14:30:00	11/28/2022 15:30:00	1.00	\$118.00
66-17-013	PERFORM ALIGNMENT	11310047	11/28/2022 13:20:17	11/28/2022 14:15:00	0.91	\$107.61
06-15	INSPECT STEERING	12052187	11/28/2022 13:01:36	11/28/2022 13:18:41	0.28	\$33.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	11/28/2022 13:00:00	11/28/2022 13:01:24	0.02	\$2.75
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	11/28/2022 12:38:41	11/28/2022 12:38:41	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/28/2022 08:28:00	11/28/2022 08:36:51	0.15	\$17.41
LABOR						279.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	1	\$33.12
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	5.93	1	\$5.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.31	2	\$4.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	10G	10G WHEEL WEIGHT	0.08	1	\$0.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	12	\$1.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	160.64	2	\$321.27
					<b>PARTS</b>	<b>408.45</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 45362

## Work Order Notes

(LISAPATE) PM-Rotate tires and check brakes-Both right side tires keep going low have added air a few times.

## Job Notes

### **06-15 - INSPECT STEERING**

(JWRIGHT) Steering good. Brakes are 10mm all around. JAW,RC,GC

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Performed alignment. EH/JAW 1.0 HR

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced lf and rr tires. Aired and balanced both. Put both new tires on front. Torqued all lug nuts to spec. Brake pads are 10 mm all around. JAW

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/GC  
MILEAGE-60636

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 45986

USING DEPT NO:	750101	OPENED DATE:	01/30/2023 08:49:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/01/2023 09:03:34	METER 1 - M:	66377	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/03/2023 09:38:23	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.48	\$75.14	\$0.00	\$107.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.28	32.48	75.14	5.00	112.62
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/30/2023 08:53:21	01/30/2023 09:09:52	0.28	\$32.48
					LABOR	32.48

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.58	5	\$67.88
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	1	\$7.26
					PARTS	75.14

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 45986

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 46564

USING DEPT NO:	750101	OPENED DATE:	03/30/2023 08:23:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/30/2023 13:50:15	METER 1 - M:	71610	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2023 13:57:37	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.88	\$23.53	\$0.00	\$26.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$7.01	\$41.40	\$0.00	\$48.41
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.04	\$4.52	\$22.73	\$0.00	\$27.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.28	\$0.00	\$0.00	\$3.28

JOB COUNT: 5	WORK ORDER TOTAL:	0.15	17.69	87.66	5.00	110.35
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/30/2023 08:47:44	03/30/2023 08:51:18	0.06	\$7.01
03-51-038	REPLACE NEW WIPER BLADES	12201267	03/30/2023 08:51:35	03/30/2023 08:53:03	0.02	\$2.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	03/30/2023 08:53:15	03/30/2023 08:55:33	0.04	\$4.52
WA-00	WASH COMPLETE VEHICLE	12201267	03/30/2023 08:55:46	03/30/2023 08:57:26	0.03	\$3.28
				LABOR		17.69

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.74	1	\$10.74
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.85	1	\$5.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
				PARTS		87.66



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 46564

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GRCOOK) Replaced wipers-GC

### **66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM-JW,SH-Changed oil and oil filter, checked fluids, tires and tire pressure air filter good.  
Miles, 71,610

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GRCOOK) Replaced cabin filter-GC

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GRCOOK) Vehicle was clean-GC

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 46829

USING DEPT NO:	750101	OPENED DATE:	04/25/2023 08:37:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2023 08:51:44	METER 1 - M:	71610	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2023 11:04:06	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$661.25	\$661.25
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	666.25	725.25
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-107871		\$661.25
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	666.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11399745	04/27/2023 07:00:00	04/27/2023 07:30:00	0.50	\$59.00
					LABOR	59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 46829

## Work Order Notes

(LISAPATE) transport body - replace windowshield

## Job Notes

### 03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr removed and installed a new windshield. PD by CC

### 16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by CW

### 16-71 - TRANSPORT BODY

### 24-78-021 - REPAIR WINDOWS

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 47181

USING DEPT NO:	750101	OPENED DATE:	05/26/2023 08:14:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2023 10:05:40	METER 1 - M:	77346	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2023 11:33:02	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.07	\$8.78	\$0.00	\$0.00	\$8.78
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.48	\$56.05	\$933.84	\$0.00	\$989.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$38.06	\$41.79	\$0.00	\$79.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.87	102.89	975.63	5.00	1,083.52
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/26/2023 08:37:18	05/26/2023 08:56:39	0.32	\$38.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	05/26/2023 09:16:34	05/26/2023 09:16:34	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	05/26/2023 09:30:00	05/26/2023 09:58:30	0.48	\$56.05
06-15	INSPECT STEERING	11074414	05/26/2023 09:59:52	05/26/2023 10:04:20	0.07	\$8.78
				LABOR		102.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.20	5	\$36.00
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.13	23	\$3.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	12.15	4	\$48.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	5G	5G WHEEL WEIGHT	0.08	1	\$0.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	17537	TIRE 215/55R17 MICH DEF2	220.52	4	\$882.06
				PARTS		975.63

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 47181

## Work Order Notes

(CHANNELL) pm replace wipers  
(EKIMBREL) cancelled wiper job, got wipers in March

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**06-15 - INSPECT STEERING**

(SHARBIN) Inspected the steering. Found no issues at this time. SH

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) SH Mounted and JW balanced 4 tires.

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/GC Performed PM. RR Tire was slick on the outer shoulder other tire have shoulder wear. Suggest 4 tires. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(LISAPATE) SH washed

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 47248

USING DEPT NO:	750101	OPENED DATE:	06/02/2023 10:05:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2023 10:10:50	METER 1 - M:	77346	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2023 09:02:36	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI*

**UNIT NO:**                    **243620**                    **2020 TOYOTA CAMRY**

**WORK ORDER NO:**                    **47248**

---

## Work Order Notes

(LISAPATE) Candace had a dead battery while at home over the Holiday weekend in Selma, AL.

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Driver took to O'Reilly's and had new battery installed. She will file for reimbursement thru her dept. Copy of receipt attached for warranty purpose

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 47691

USING DEPT NO:	750101	OPENED DATE:	07/21/2023 08:47:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/21/2023 13:26:46	METER 1 - M:	81799	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/24/2023 09:29:46	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.54	\$24.08	\$0.00	\$29.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.95	\$55.88	\$0.00	\$72.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.15	\$18.13	\$0.00	\$0.00	\$18.13

JOB COUNT: 4	WORK ORDER TOTAL:	0.34	40.62	79.96	5.00	125.58
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/21/2023 09:06:48	07/21/2023 09:09:37	0.05	\$5.54
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/21/2023 08:58:11	07/21/2023 09:06:48	0.14	\$16.95
WA-00	WASH COMPLETE VEHICLE	11074414	07/21/2023 09:05:47	07/21/2023 09:15:00	0.15	\$18.13
				LABOR		40.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.93	1	\$11.93
					PARTS	79.96



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 47691

## Work Order Notes

(LISAPATE) PM-wash

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC,EH

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,EH,-SH on bottom, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 81,799

### CH-SP - CHARGE Shop Supplies

### WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Visit Reason Changed On 7/21/2023 8:47 AM By LISAPATE

(GARAGE) Washed Vehicle-SH

(GARAGE) Washed the vehicle. SH

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 48080

USING DEPT NO:	750101	OPENED DATE:	09/05/2023 08:30:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 15:36:30	METER 1 - M:	86498	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 11:46:47	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.27	\$53.64	\$0.00	\$76.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	23.27	53.64	5.00	81.91
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	09/05/2023 08:40:14	09/05/2023 08:52:04	0.20	\$23.27
					LABOR	23.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	5	\$42.30
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.34	1	\$11.34
					PARTS	53.64

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 48080

## Work Order Notes

(EHANNAH) pm

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 86,498

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 48605

USING DEPT NO:	750101	OPENED DATE:	10/17/2023 12:57:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2023 11:03:15	METER 1 - M:	89946	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2023 15:45:17	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$7.70	\$87.51	\$0.00	\$95.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.07	7.70	87.51	62.50	157.71
--------------	-------------------	------	------	-------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	2113151		\$57.50
24-02-061	REPAIR WINDSHIELD	11078716	2113151		(\$57.50)
24-02-061	REPAIR WINDSHIELD	11078716	2113151		\$57.50
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					62.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/17/2023 13:18:58	10/17/2023 13:22:53	0.07	\$7.70
LABOR						7.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	5	\$40.35
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	35.61	1	\$35.61
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.55	1	\$11.55
PARTS						87.51

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 48605

## Work Order Notes

(EHANNAH) pm and waiting on glass Dr.

## Job Notes

### **24-02-061 - REPAIR WINDSHIELD**

(LISAPATE) Glass Dr came to the shop and repaired ding in windshield. pd by cc  
(IFALLS) Visit Reason Changed On 10/19/2023 3:44 PM By IFALLS

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 49262

USING DEPT NO:	750101	OPENED DATE:	12/14/2023 08:15:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2023 09:33:21	METER 1 - M:	95524	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/18/2023 11:31:01	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$687.70	\$687.70
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.94	\$49.81	\$0.00	\$98.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.91	107.94	49.81	692.70	850.45
--------------	-------------------	------	--------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2114243		\$687.70
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	692.70

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11915538	12/18/2023 07:00:00	12/18/2023 07:30:00	0.50	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2023 11:20:04	12/14/2023 11:44:57	0.41	\$48.94
					LABOR	107.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.48	5	\$42.38
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	49.81

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 49262

## Work Order Notes

(EHANNAH) install new wind shield - transport to vendor- pm

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(EHANNAH) Visit Reason Changed On 12/14/2023 8:43 AM By EHANNAH  
(LISAPATE) Glass Dr installed and recalibrated a new windshield, pd by CC

### **16-71 - TRANSPORT BODY**

(LISAPATE) Taken to Glass Dr by RC/CW

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 49915

USING DEPT NO:	750101	OPENED DATE:	02/23/2024 08:30:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2024 10:17:21	METER 1 - M:	100422	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2024 13:09:59	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.54	\$24.08	\$0.00	\$25.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$4.39	\$42.53	\$0.00	\$46.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$4.00	\$0.00	\$0.00	\$4.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.08	9.93	66.61	5.00	81.54
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	02/23/2024 09:04:41	02/23/2024 09:06:43	0.03	\$4.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	02/23/2024 09:03:54	02/23/2024 09:04:41	0.01	\$1.54
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/23/2024 09:01:40	02/23/2024 09:03:54	0.04	\$4.39
				LABOR	9.93	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
				PARTS	66.61	



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 49915

## Work Order Notes

(EHANNAH) pm- wipers- wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced wipers-FC,GC

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM- FC,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 100,422

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed vehicle-FC

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 50703

USING DEPT NO:	750101	OPENED DATE:	04/30/2024 08:13:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/30/2024 10:02:37	METER 1 - M:	100422	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2024 10:20:46	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.50	\$44.33	\$0.00	\$73.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.25	29.50	44.33	5.00	78.83
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/30/2024 10:02:27	04/30/2024 10:17:27	0.25	\$29.50
					LABOR	29.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
					PARTS	44.33

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 50703

---

## Work Order Notes

(EHANNAH) pm- wash

---

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed pm service. Coolant -34. JAW/SH  
Mileage-105564

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) SH washed unit.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 51175

USING DEPT NO:	750101	OPENED DATE:	06/13/2024 08:08:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/13/2024 08:59:00	METER 1 - M:	105565	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2024 10:17:03	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.95	\$24.11	\$0.00	\$25.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.21	\$43.83	\$0.00	\$45.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.98	\$0.00	\$0.00	\$0.98

JOB COUNT: 4	WORK ORDER TOTAL:	0.03	3.14	67.94	5.00	76.08
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	06/13/2024 08:49:55	06/13/2024 08:50:25	0.01	\$0.98
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/13/2024 08:48:44	06/13/2024 08:49:13	0.01	\$0.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/13/2024 08:48:07	06/13/2024 08:48:44	0.01	\$1.21
				LABOR		3.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
				PARTS		67.94

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 51175

---

## Work Order Notes

(LRUSHING) pm and wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced the wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) SH/FC Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed and filled with gas. SH

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 51944

USING DEPT NO:	750101	OPENED DATE:	08/27/2024 08:25:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/27/2024 13:27:36	METER 1 - M:	115556	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/28/2024 08:57:17	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.37	\$0.00	\$43.37
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.00	\$0.00	\$22.73	\$0.00	\$22.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	66.10	5.00	71.10
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.31	5	\$36.53
					PARTS	66.10

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 51944

---

## Work Order Notes

### Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-CM,GC, Changed oil and oil filter, checked fluids, changed cabin filter, air filter good, tires and tire pressure.  
Miles, 115,556

### 66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced cabin filter-CM

### CH-SP - CHARGE Shop Supplies

### WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed vehicle-CM

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 52479

USING DEPT NO:	750101	OPENED DATE:	10/15/2024 09:02:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2024 13:26:42	METER 1 - M:	119571	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2024 15:38:18	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$50.88	\$0.00	\$50.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	50.88	5.00	55.88
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.56	1	\$9.56
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.26	5	\$41.32
					PARTS	50.88



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 52479

## Work Order Notes

(EHANNAH) pm- PASS FOR DETAILING

## Job Notes

### **66-79-003 - PERFORM SAFETY INSPECTION**

(EKIMBREL) GC performed SI

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm-CM,GC, changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 119,571

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 52980

USING DEPT NO:	750101	OPENED DATE:	12/05/2024 08:35:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2024 10:44:24	METER 1 - M:	124786	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2024 12:38:36	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.08	\$0.00	\$51.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	75.16	5.00	80.16
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.30	5	\$41.48
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	75.16

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 52980

## Work Order Notes

(EHANNAH) pm- wipers- wash- inspect all tires- PR tire has been going low

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) fj replaced wipers

### 06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

### 66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) fl performed pm

### CH-SP - CHARGE Shop Supplies

### WA-00 - WASH COMPLETE VEHICLE

(EKIMBREL) fj washed vehicle

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 53726

USING DEPT NO:	750101	OPENED DATE:	02/12/2025 08:41:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/19/2025 12:38:17	METER 1 - M:	130162	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	02/20/2025 14:19:36	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$804.94	\$804.94
06-02-061	INSPECT WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02-061	TRANSPORT WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$834.60	\$0.00	\$834.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$52.51	\$0.00	\$52.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 8	WORK ORDER TOTAL:	0.00	0.00	887.11	809.94	1,697.05
--------------	-------------------	------	------	--------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2125014		\$804.94
03-02-061	REPLACE NEW WINDSHIELD	11078716	2125014		\$804.94
03-02-061	REPLACE NEW WINDSHIELD	11078716	2125014		(\$804.94)
COMML					809.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15579630000	TIRE 215/55ZR17 GEN G-MAX	205.76	4	\$823.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15579630000	TIRE 215/55ZR17 GEN G-MAX	210.26	(4)	(\$841.02)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15579630000	TIRE 215/55ZR17 GEN G-MAX	210.26	4	\$841.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.90	4	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.42	5	\$42.08
PARTS						887.11

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 53726

## Work Order Notes

(IFALLS) PM, INSPECT WINDSHIELD, CHECK RR TIRE FOR LEAK, TEST DRIVE CUSTOMER COMPLANING OF ROUGH RIDE

## Job Notes

### 03-02-061 - REPLACE NEW WINDSHIELD

(EHOWELL) Glass Doctor replaced windshield.

### 06-02-061 - INSPECT WINDSHIELD

(GARAGE) wind shield need replacing need to go to glass doctor

### 06-15 - INSPECT STEERING

(GARAGE) inspected steering checked ok, cm

### 06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

### 16-02-061 - TRANSPORT WINDSHIELD

### 66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment cm test drove checked ok,

### 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) mounted and balanced tires, replaced valve steams checked ok, cm

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside

FJ- pit

perform PM, changed oil and filters, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid  
130162 miles

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 54570

USING DEPT NO:	750101	OPENED DATE:	04/23/2025 08:50:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/23/2025 09:43:55	METER 1 - M:	135462	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2025 07:33:35	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
					PARTS	48.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 54570

## Work Order Notes

(EHANNAH) pm- wipers- wash

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC,CQ,- top side, checked fluids, filters good, tires and tire pressure, CQ- filled with oil  
JR- bottom side, drained oil and changed oil filter  
Miles, 135,462

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) CQ- washed vehicle

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 55246

USING DEPT NO:	750101	OPENED DATE:	07/02/2025 08:51:05	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	07/02/2025 09:31:13	METER 1 - M:	141416	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/02/2025 12:20:19	IN-SERVICE DATE:	12/16/2019						
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry									
				UNIT SERIAL NO:	4T1C11AKXLU863820						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$19.61	\$0.00	\$19.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	68.51	5.00	73.51
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	1	\$17.72
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	(1)	(\$17.72)
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	(1)	(\$15.04)
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.28	1	\$11.28
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
PARTS						68.51



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 55246

## Work Order Notes

(EHANNAH) pm- wipers- wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- replaced wipers

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) GC- top side, checked fluids, filters good, tires and tire pressure, reset oil life and changed oil sticker, checked oil level

FJ- bottom side, drained oil and changed oil filter

Miles, 141,416

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) FJ- washed vehicle

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 55697

USING DEPT NO:	750101	OPENED DATE:	07/31/2025 14:37:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2025 12:03:39	METER 1 - M:	141416	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2025 09:07:11	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AKXLU863820	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/08/2025 11:22:04 By User: GLOBETTI

UNIT NO: 243620 2020 TOYOTA CAMRY

WORK ORDER NO: 55697

---

## Work Order Notes

(EHANNAH) Prep for sale

---

## Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) JR- prepped vehicle for sale, no gps

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Aug 08 2025 11:22:04 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243620') //Q=