

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 45584

USING DEPT NO:	507301	OPENED DATE:	12/14/2022 14:15:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/20/2023 10:53:01	METER 1 - M:	8	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/20/2023 14:15:56	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	5.00	123.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12052187	12/14/2022 14:18:21	12/14/2022 15:18:21	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 45584

Work Order Notes

(EHANNAH) New unit do PDI
(LISAPATE) Unit came with just 1 key

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(EHANNAH) PDI done by JW

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 46723

USING DEPT NO:	507301	OPENED DATE:	04/14/2023 08:36:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2023 15:06:46	METER 1 - M:	4424	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2023 10:08:32	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$54.08	\$0.00	\$93.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.94	54.08	5.00	98.02
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/14/2023 12:55:24	04/14/2023 12:55:24	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/14/2023 12:55:24	04/14/2023 12:55:24	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/14/2023 12:55:24	04/14/2023 13:15:12	0.33	\$38.94
	LABOR					38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.70	1	\$10.70
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	(1)	(\$6.78)
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.85	1	\$5.85
	PARTS					54.08

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 46723

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-CW,GC- Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles,4,424

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 47501

USING DEPT NO:	507301	OPENED DATE:	06/30/2023 14:38:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/06/2023 09:54:59	METER 1 - M:	8523	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2023 10:31:32	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.70	\$49.55	\$0.00	\$77.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.23	27.70	49.55	5.00	82.25
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/03/2023 07:03:37	07/03/2023 07:17:42	0.23	\$27.70
					LABOR	27.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.93	1	\$11.93
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
					PARTS	49.55

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 47501

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 48020

USING DEPT NO:	507301	OPENED DATE:	08/29/2023 08:11:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2023 08:22:39	METER 1 - M:	12068	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/31/2023 09:44:21	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$43.40	\$0.00	\$82.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.33	38.94	43.40	5.00	87.34
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	08/31/2023 07:00:00	08/31/2023 07:19:48	0.33	\$38.94
LABOR						38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.78	1	\$5.78
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
PARTS						43.40

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 48020

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 49134

USING DEPT NO:	507301	OPENED DATE:	12/04/2023 07:20:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2023 10:09:56	METER 1 - M:	17338	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2023 13:17:47	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.27	\$45.23	\$0.00	\$92.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.40	47.27	45.23	5.00	97.50
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2023 10:25:52	12/04/2023 10:49:54	0.40	\$47.27
LABOR						47.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	6	\$37.80
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
PARTS						45.23

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 49134

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50230

USING DEPT NO:	507301	OPENED DATE:	03/25/2024 08:43:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/28/2024 14:24:35	METER 1 - M:	21204	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2024 07:23:38	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.07	\$7.67	\$0.00	\$0.00	\$7.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$72.87	\$68.36	\$0.00	\$141.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.68	80.54	68.36	5.00	153.90
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	03/25/2024 14:30:00	03/25/2024 14:31:54	0.03	\$3.74
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	03/25/2024 14:13:00	03/25/2024 14:15:00	0.03	\$3.93
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/25/2024 13:35:34	03/25/2024 14:12:37	0.62	\$72.87
				LABOR		80.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	19.71	1	\$19.71
					PARTS	68.36

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50230

Work Order Notes

(EHANNAH) pm

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) rotate the tires and check Brakes f 10 R 8 m FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50886

USING DEPT NO:	507301	OPENED DATE:	05/20/2024 07:19:38	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2024 10:36:43	METER 1 - M:	24909	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2024 15:52:00	IN-SERVICE DATE:	12/13/2022				
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander	UNIT SERIAL NO:	5TDKDRAH1PS007911					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.03	\$3.11	\$11.17	\$0.00	\$14.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.03	3.11	11.17	5.00	19.28
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12395904	05/20/2024 07:57:31	05/20/2024 07:59:06	0.03	\$3.11
LABOR						3.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.46	1	\$5.46
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.58	1	\$4.58
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	5	\$1.13
PARTS						11.17

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50886

Work Order Notes

(EHANNAH) tire patch on left rear

Job Notes

66-17-030 - PERFORM TIRE PATCH

(FCONTRER) Perform patch tire Lf -R and balanced fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 51316

USING DEPT NO:	507301	OPENED DATE:	06/26/2024 10:19:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/26/2024 15:50:46	METER 1 - M:	25872	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2024 08:41:14	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.98	\$79.63	\$0.00	\$80.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.01	0.98	79.63	5.00	85.61
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/26/2024 14:48:11	06/26/2024 14:48:41	0.01	\$0.98
					LABOR	0.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	AIR FILTER	30.92	1	\$30.92
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.86	1	\$6.86
					PARTS	79.63

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 51316

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 52653

USING DEPT NO:	507301	OPENED DATE:	10/30/2024 14:29:39	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/31/2024 09:25:47	METER 1 - M:	29536	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/31/2024 13:37:36	IN-SERVICE DATE:	12/13/2022						
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander									
				UNIT SERIAL NO:	5TDKDRAH1PS007911						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$22.85	\$0.00	\$22.85
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$112.00	\$0.00	\$112.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$31.23	\$0.00	\$31.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	166.08	5.00	171.08
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	31.23	1	\$31.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	AIR FILTER	27.92	1	\$27.92
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	14.90	5	\$74.48
03-51-038	REPLACE NEW WIPER BLADES	XC28	28" WIPER	12.00	1	\$12.00
PARTS						166.08

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 52653

Work Order Notes

(EHANNAH) pm- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) JR REPLACED WIPERS

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ & JR- perform SI

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ & JR- perform PM, changed oil and filter, changed air and cabin air filters, checked fluids, checked tires and tire pressures
29536 miles

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) JR REPLACED CABIN FILTER

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		245141		2023 TOYOTA HIGHLANDER				WORK ORDER NO:		52717		
USING DEPT NO:		507301		OPENED DATE:		11/05/2024 11:50:03		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		11/06/2024 09:49:29		METER 1 - M: 29537		METER 2 - N: 0		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		11/06/2024 10:41:13		IN-SERVICE DATE:		12/13/2022		
TECH SPEC NO:		23TOYHIGHLNDR		2023 Toyota Highlander				UNIT SERIAL NO:		5TDKDRAH1PS007911		
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-01		INSPECT AIR CONDITIONING, HEAT, VE		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 52717

Work Order Notes

(EHANNAH) inspect AC

Job Notes

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(GARAGE) checked over vehicle found ac was turned off turned on unit tested checked ok, vehicle cooled and heated correctly cm 29537 miles cm

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 54157

USING DEPT NO:	507301	OPENED DATE:	03/26/2025 08:24:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2025 09:31:01	METER 1 - M:	33204	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2025 12:48:44	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.82	\$0.00	\$48.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	48.82	5.00	53.82
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.26	5	\$41.32
PARTS						48.82

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 54157

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Top

CM- Bottom

FJ- Added new oil & verified oil level, checked filters, set tire pressure, topped off fluids, recorded date codes & tread depths.

CM- Oil change.

(GARAGE) Mileage is 33204

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 55639

USING DEPT NO:	507301	OPENED DATE:	07/29/2025 09:32:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2025 08:37:14	METER 1 - M:	38549	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/30/2025 09:37:46	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.28	5	\$41.40
PARTS						48.90

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 55639

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, reset oil life and changed oil sticker.

CW, filled with oil

Miles, 38,549

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56036

USING DEPT NO:	507301	OPENED DATE:	08/21/2025 08:53:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/22/2025 10:56:40	METER 1 - M:	39313	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2025 07:08:44	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.25	\$30.63	\$350.36	\$0.00	\$380.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.25	30.63	350.36	5.00	385.99
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11779687	08/22/2025 09:30:00	08/22/2025 09:44:42	0.25	\$30.63
					LABOR	30.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.06	1	\$3.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.06	(1)	(\$3.06)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	302160	TIRE 235\65R18 TOYO A43	347.30	1	\$347.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	302160	TIRE 235\65R18 TOYO A43	341.30	(1)	(\$341.30)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.06	1	\$3.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	302160	TIRE 235\65R18 TOYO A43	341.30	1	\$341.30
					PARTS	350.36

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56036

Work Order Notes

(CWIGLEY) Low tire light is on.

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) 39,313 miles

FJ- Replaced RR tire. Nil too close to the shoulder. Could not safely repair. 21029 TPMS kit used

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56884

USING DEPT NO:	507301	OPENED DATE:	10/21/2025 08:22:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/21/2025 09:04:28	METER 1 - M:	41488	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/21/2025 13:04:14	IN-SERVICE DATE:	12/13/2022	
TECH SPEC NO:	23TOYHIGHLNDR	2023 Toyota Highlander		UNIT SERIAL NO:	5TDKDRAH1PS007911	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	150.00	0.00	5.00	155.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	10/21/2025 09:03:16	10/21/2025 10:03:16	1.00	\$150.00
					LABOR	150.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 10:16:52 By User: GLOBETTI

UNIT NO: 245141 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56884

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) CQ COMPLETED PREP FOR SALE.

(EHOWELL) The Master key in the system was key # 103. When we pulled the master, key #103 was not for this vehicle. Denise contacted Mario about an additional key and he said that the key they turned in was the only key that they had.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Oct 22 2025 10:16:52 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '245141') //Q=