

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 18789

USING DEPT NO:	600203	OPENED DATE:	11/17/2014 13:02:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2014 06:54:45	METER 1 - M:	513	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/18/2014 06:54:46	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11255091	11/17/2014 13:03:27	11/17/2014 13:33:27	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 18789

Work Order Notes

(LPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 21300

USING DEPT NO:	600203	OPENED DATE:	09/03/2015 08:47:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2015 14:53:21	METER 1 - M:	1561	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/03/2015 14:53:22	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.80	\$103.47	\$40.56	\$0.00	\$144.03

JOB COUNT: 1	WORK ORDER TOTAL:	1.80	103.47	40.56	0.00	144.03
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/03/2015 09:30:00	09/03/2015 11:17:58	1.80	\$103.47
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/03/2015 09:20:40	09/03/2015 09:20:40	0.00	\$0.00
					LABOR	103.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	6	\$33.84
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.72	1	\$6.72
					PARTS	40.56

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 21300

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY GM,RS/GM

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 23584

USING DEPT NO:	600203	OPENED DATE:	06/02/2016 10:49:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2016 07:53:22	METER 1 - M:	2226	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/08/2016 07:53:23	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$7.65	\$40.29	\$0.00	\$47.94

JOB COUNT: 1	WORK ORDER TOTAL:	0.13	7.65	40.29	0.00	47.94
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/02/2016 13:57:41	06/02/2016 14:05:40	0.13	\$7.65
					LABOR	7.65

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	6	\$33.84
					PARTS	40.29

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 23584

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 25084

USING DEPT NO:	600203	OPENED DATE:	11/23/2016 13:26:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/28/2016 07:52:18	METER 1 - M:	43073	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/28/2016 08:14:38	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$21.24	\$40.29	\$0.00	\$61.53

JOB COUNT: 1	WORK ORDER TOTAL:	0.37	21.24	40.29	0.00	61.53
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/26/2016 11:35:04	11/26/2016 11:57:14	0.37	\$21.24
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2016 13:29:29	11/23/2016 13:48:05	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2016 13:29:29	11/23/2016 13:48:05	(0.31)	(\$17.83)
					LABOR	21.24

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	OW20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	6	\$33.84
					PARTS	40.29

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 25084

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH PERFORMED PM

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 27392

USING DEPT NO:	600203	OPENED DATE:	09/08/2017 15:34:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/13/2017 09:58:02	METER 1 - M:	3781	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/13/2017 09:58:04	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$20.92	\$0.00	\$38.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	20.92	0.00	38.75
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	09/11/2017 07:00:00	09/11/2017 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	2.77	6	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	4.30	1	\$4.30
					PARTS	20.92

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 27392

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB
COOLANT -45'

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 29632

USING DEPT NO:	600203	OPENED DATE:	05/01/2018 08:38:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2018 08:46:03	METER 1 - M:	4287	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/14/2018 08:46:05	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$22.66	\$0.00	\$40.49

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	22.66	0.00	40.49
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/10/2018 07:00:00	05/10/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.06	6	\$18.36
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	4.30	1	\$4.30
					PARTS	22.66

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 29632

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS/AG
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 30959

USING DEPT NO:	600203	OPENED DATE:	09/26/2018 14:43:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2018 16:20:21	METER 1 - M:	4942	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2018 16:20:23	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$0.00	\$27.58	\$0.00	\$27.58
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$0.00	\$9.06	\$0.00	\$9.06

JOB COUNT: 2	WORK ORDER TOTAL:	0.91	0.00	36.64	0.00	36.64
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/27/2018 06:29:31	09/27/2018 06:50:38	0.35	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	10208562	09/27/2018 07:00:00	09/27/2018 07:18:00	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/27/2018 06:29:49	09/27/2018 06:45:09	0.26	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	6	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	4.30	1	\$4.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	9.06	1	\$9.06
					PARTS	36.64

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 30959

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,EK/SH

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 31978

USING DEPT NO:	600203	OPENED DATE:	01/18/2019 14:06:02	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/04/2019 10:44:37	METER 1 - M:	9893	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/04/2019 10:44:38	IN-SERVICE DATE:	11/14/2014						
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA			UNIT SERIAL NO:	5TFTX4CN2FX051071					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	2.02	\$0.00	\$0.00	\$0.00	\$0.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,569.06	\$1,569.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$0.00	\$27.64	\$0.00	\$27.64

JOB COUNT: 3	WORK ORDER TOTAL:	2.75	0.00	27.64	1,569.06	1,596.70
--------------	-------------------	------	------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	167070	0046726	\$1,569.06
COMML					1569.06

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/28/2019 08:25:17	01/28/2019 08:47:17	0.37	\$0.00
16-71	TRANSPORT BODY	10208562	01/22/2019 08:53:19	01/22/2019 09:52:30	0.99	\$0.00
16-71	TRANSPORT BODY	11915538	01/22/2019 07:51:17	01/22/2019 08:53:32	1.04	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/28/2019 08:26:00	01/28/2019 08:47:45	0.36	\$0.00
LABOR						0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	4.30	1	\$4.30
PARTS						27.64

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 31978

Work Order Notes

(LISAPATE) Take to the Body Shop to repair left rear bumper and taillight area. Dept pay
(LISAPATE) PM due

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by EK

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage to rear bumper and and left taillight. Pd by CC see attached

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG
Coolant -50'

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 33462

USING DEPT NO:	600203	OPENED DATE:	07/17/2019 08:22:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/18/2019 10:10:28	METER 1 - M:	7098	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/18/2019 10:10:30	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$27.62	\$0.00	\$27.62

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	0.00	27.62	0.00	27.62
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/18/2019 06:00:00	07/18/2019 06:18:36	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.34	1	\$4.34
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	6	\$23.28
					PARTS	27.62

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 33462

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC/SH, coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 34444

USING DEPT NO:	600203	OPENED DATE:	10/14/2019 13:39:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/15/2019 09:54:41	METER 1 - M:	7545	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/15/2019 09:54:42	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.40	\$0.00	\$17.06	\$0.00	\$17.06

JOB COUNT: 1	WORK ORDER TOTAL:					0.40	0.00	17.06	0.00	17.06
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	10208562	10/14/2019 13:48:50	10/14/2019 14:13:01	0.40	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	1	\$8.53
					PARTS	17.06

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 34444

Work Order Notes

(LISAPATE) Driver requested wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 35341

USING DEPT NO:	600203	OPENED DATE:	01/08/2020 09:57:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/16/2020 06:50:05	METER 1 - M:	8152	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/16/2020 06:50:06	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$0.00	\$31.87	\$0.00	\$31.87
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.07	\$0.00	\$9.06	\$0.00	\$9.06

JOB COUNT: 2	WORK ORDER TOTAL:	0.62	0.00	40.93	0.00	40.93
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/09/2020 07:15:07	01/09/2020 07:32:06	0.28	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/09/2020 07:16:06	01/09/2020 07:31:39	0.26	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	01/09/2020 07:11:38	01/09/2020 07:16:06	0.07	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	9.06	1	\$9.06
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.24	1	\$4.24
					PARTS	40.93

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 35341

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/AG. Coolant -25

Checked tires, found no wear and no cracking, will recheck at the next pm.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) JW replaced cabin filter.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 37713

USING DEPT NO:	600203	OPENED DATE:	09/23/2020 13:52:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2020 12:07:29	METER 1 - M:	9569	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2020 13:45:18	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.39	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.23	\$0.00	\$253.04	\$0.00	\$253.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.21	0.00	253.04	0.00	253.04
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	09/24/2020 09:37:01	09/24/2020 09:50:59	0.23	\$0.00
09-15	ALIGN STEERING	11213180	09/24/2020 09:51:07	09/24/2020 10:14:46	0.39	\$0.00
06-15	INSPECT STEERING	11213180	09/24/2020 09:36:15	09/24/2020 09:36:44	(0.01)	\$0.00
06-15	INSPECT STEERING	11213180	09/24/2020 09:36:15	09/24/2020 09:36:44	0.01	\$0.00
06-15	INSPECT STEERING	11213180	09/24/2020 09:36:15	09/24/2020 10:06:15	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/23/2020 14:04:13	09/23/2020 14:09:10	0.08	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.28	9	\$2.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	4	\$8.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	14294	TIRE 215/70R15 UNI TP TOUR A/S	60.42	4	\$241.68
					PARTS	253.04

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 37713

Work Order Notes

(LISAPATE) PM

Job Notes

06-15 - INSPECT STEERING

(MSIDES) All steering and suspension components checked ok. MS

09-15 - ALIGN STEERING

(MSIDES) Performed alignment. MS

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(MSIDES) Mounted and balanced 4 new tires. MS

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1200 miles. Updated pm sticker. Checked all fluids and tires. Will need a full set of tires replaced at next pm service due to age. Coolant -34°
JAW,EK,MS

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 39101

USING DEPT NO:	600203	OPENED DATE:	02/12/2021 10:43:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2021 10:08:28	METER 1 - M:	10110	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2021 12:27:19	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$0.00	\$22.26	\$0.00	\$22.26

JOB COUNT: 1	WORK ORDER TOTAL:	0.12	0.00	22.26	0.00	22.26
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/12/2021 14:45:18	02/12/2021 14:52:33	0.12	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	2.99	6	\$17.94
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.32	1	\$4.32
					PARTS	22.26

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 39101

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. RC/JAW
MILEAGE-10110

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 40471

USING DEPT NO:	600203	OPENED DATE:	07/19/2021 09:42:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/20/2021 14:55:43	METER 1 - M:	10667	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/21/2021 09:11:26	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$0.00	\$9.78	\$0.00	\$9.78
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.15	0.00	9.78	0.00	9.78
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/19/2021 10:19:55	07/19/2021 10:21:50	0.03	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/19/2021 10:12:46	07/19/2021 10:19:46	0.12	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	4.89	2	\$9.78
					PARTS	9.78

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 40471

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 557 miles since last pm. Updated sticker. Checked all fluids and tires. Coolant -34°. JAW
MILEAGE-10667

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 41901

USING DEPT NO:	600203	OPENED DATE:	12/15/2021 08:49:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/15/2021 15:13:01	METER 1 - M:	11237	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/16/2021 07:40:22	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.07	\$0.00	\$75.70	\$0.00	\$75.70
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.05	\$0.00	\$0.57	\$0.00	\$0.57
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.00	\$10.12	\$0.00	\$10.12
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$0.00	\$20.99	\$0.00	\$20.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.06	0.00	107.38	2.00	109.38
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	12052187	12/15/2021 13:41:26	12/15/2021 13:44:29	0.05	\$0.00
03-32-002	REPLACE NEW BATTERY	12052187	12/15/2021 13:37:18	12/15/2021 13:41:18	0.07	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2021 13:08:17	12/15/2021 13:37:35	0.49	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	12/15/2021 13:36:46	12/15/2021 13:37:09	0.01	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/15/2021 13:09:35	12/15/2021 13:36:36	0.45	\$0.00
				LABOR		0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.57	1	\$0.57
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	5.06	2	\$10.12
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	2.99	6	\$17.94
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	3.05	1	\$3.05
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	75.70	1	\$75.70
				PARTS		107.38

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 41901

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery due to testing bad. Alternator charging at 14.3 volts

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(JWRIGHT) Replaced left brake light bulb

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 43113

USING DEPT NO:	600203	OPENED DATE:	05/03/2022 10:55:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2022 11:08:29	METER 1 - M:	11602	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2022 12:44:52	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$0.00	\$10.12	\$0.00	\$10.12
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$0.00	\$13.88	\$0.00	\$13.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$0.00	\$7.47	\$0.00	\$7.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.78	0.00	31.47	2.00	33.47
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	05/03/2022 12:49:20	05/03/2022 12:49:20	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	05/03/2022 12:49:20	05/03/2022 12:49:20	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	05/03/2022 12:49:20	05/03/2022 13:07:20	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/03/2022 12:04:50	05/03/2022 12:04:50	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/03/2022 12:04:50	05/03/2022 12:04:50	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/03/2022 12:04:50	05/03/2022 12:24:38	0.33	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	05/03/2022 12:02:02	05/03/2022 12:02:02	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	05/03/2022 12:02:02	05/03/2022 12:02:02	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	05/03/2022 12:02:02	05/03/2022 12:11:02	0.15	\$0.00
				LABOR		0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	13.88	1	\$13.88
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	5.06	2	\$10.12
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	7.47	1	\$7.47
				PARTS		31.47

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 43113

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 11602 Vehicle has been 365 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 44361

USING DEPT NO:	600203	OPENED DATE:	08/17/2022 10:00:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/26/2022 08:13:46	METER 1 - M:	11967	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2022 09:24:36	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	08/23/2022 09:53:22	08/23/2022 09:56:51	(0.06)	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	08/23/2022 09:53:22	08/23/2022 09:56:51	0.06	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 44361

Work Order Notes

(CWIGLEY) Prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC

(IFALLS) no gps

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 44476

USING DEPT NO:	600203	OPENED DATE:	08/26/2022 08:14:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2022 08:34:56	METER 1 - M:	11849	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2022 10:01:29	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNEI	DON	5	N	GARAGE	1.24	\$0.00	\$96.68	\$0.00	\$96.68
14-44-012	INSTALL TANK - FUEL, GASEOUS	DON	O	N	GARAGE	1.60	\$0.00	\$37.76	\$0.00	\$37.76
14-51-067	INSTALL TRAILER BALL	DON	5	N	GARAGE	1.55	\$0.00	\$52.28	\$0.00	\$52.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	4.40	0.00	186.72	5.00	191.72
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	11213180	08/26/2022 08:52:19	08/26/2022 09:15:00	(0.38)	\$0.00
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	11213180	08/26/2022 09:30:00	08/26/2022 10:21:52	(0.86)	\$0.00
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	11213180	08/26/2022 08:52:19	08/26/2022 09:15:00	0.38	\$0.00
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	11213180	08/26/2022 09:30:00	08/26/2022 10:21:52	0.86	\$0.00
14-51-067	INSTALL TRAILER BALL	11213180	08/26/2022 10:22:02	08/26/2022 10:55:37	(0.56)	\$0.00
14-51-067	INSTALL TRAILER BALL	11213180	08/26/2022 10:22:02	08/26/2022 10:55:37	0.56	\$0.00
14-51-067	INSTALL TRAILER BALL	11213180	08/26/2022 10:22:02	08/26/2022 10:55:37	0.56	\$0.00
14-51-067	INSTALL TRAILER BALL	11213180	08/26/2022 12:29:16	08/26/2022 13:28:52	0.99	\$0.00
14-51-067	INSTALL TRAILER BALL	11213180	08/26/2022 12:29:16	08/26/2022 13:28:52	(0.99)	\$0.00
14-51-067	INSTALL TRAILER BALL	11213180	08/26/2022 12:29:16	08/26/2022 13:28:52	0.99	\$0.00
14-44-012	INSTALL TANK - FUEL, GASEOUS	11310047	08/30/2022 07:00:00	08/30/2022 08:36:00	1.60	\$0.00
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	11213180	08/26/2022 09:30:00	08/26/2022 10:21:52	0.86	\$0.00
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	11213180	08/26/2022 08:52:19	08/26/2022 09:15:00	0.38	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-51-067	INSTALL TRAILER BALL	BRASS BUSHING	BUSHING	3.00	(4)	(\$12.00)
14-51-067	INSTALL TRAILER BALL	BRASS BUSHING	BUSHING	4.50	4	\$18.00
14-51-067	INSTALL TRAILER BALL	FWS61385	3/8" EYE BOLT	5.31	(2)	(\$10.62)
14-44-012	INSTALL TANK - FUEL, GASEOUS	BOX66187	2X27' 10,000LB STRAP	37.76	1	\$37.76
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	96.68	(1)	(\$96.68)
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	96.68	1	\$96.68
14-51-067	INSTALL TRAILER BALL	FWS61385	3/8" EYE BOLT	7.97	2	\$15.93
14-44-012	INSTALL TANK - FUEL, GASEOUS	BOX66187	2X27' 10,000LB STRAP	25.17	(1)	(\$25.17)
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	64.45	(1)	(\$64.45)
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	96.68	1	\$96.68
14-51-067	INSTALL TRAILER BALL	BRASS BUSHING	BUSHING	3.00	4	\$12.00
14-51-067	INSTALL TRAILER BALL	FWS61385	3/8" EYE BOLT	5.31	2	\$10.62
14-51-067	INSTALL TRAILER BALL	BRASS BUSHING	BUSHING	3.00	(4)	(\$12.00)
14-51-067	INSTALL TRAILER BALL	FWS61385	3/8" EYE BOLT	5.31	(2)	(\$10.62)
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	64.45	1	\$64.45
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	64.45	(1)	(\$64.45)
14-51-067	INSTALL TRAILER BALL	BRASS BUSHING	BUSHING	3.00	4	\$12.00
14-51-067	INSTALL TRAILER BALL	FWS61385	3/8" EYE BOLT	5.31	2	\$10.62
14-44-012	INSTALL TANK - FUEL, GASEOUS	BOX66187	2X27' 10,000LB STRAP	25.17	1	\$25.17
14-44-012	INSTALL TANK - FUEL, GASEOUS	BOX66187	2X27' 10,000LB STRAP	25.17	(1)	(\$25.17)
14-44-012	INSTALL TANK - FUEL, GASEOUS	BOX66187	2X27' 10,000LB STRAP	25.17	1	\$25.17
14-37-024	INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR	CRT55513	WIRING HARNESS	64.45	1	\$64.45
14-51-067	INSTALL TRAILER BALL	CRT40074	2 X 1 X 3 HITCH BALL	12.23	(1)	(\$12.23)
14-51-067	INSTALL TRAILER BALL	CRT40074	2 X 1 X 3 HITCH BALL	18.35	1	\$18.35
14-51-067	INSTALL TRAILER BALL	CRT40074	2 X 1 X 3 HITCH BALL	12.23	1	\$12.23
14-51-067	INSTALL TRAILER BALL	CRT40074	2 X 1 X 3 HITCH BALL	12.23	(1)	(\$12.23)
14-51-067	INSTALL TRAILER BALL	CRT40074	2 X 1 X 3 HITCH BALL	12.23	1	\$12.23
					PARTS	186.72

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 44476

Work Order Notes

(LISAPATE) Swap aux fuel tank from 1889B to this truck. Also add a trailer ball and 4 wire flat

Job Notes

14-37-024 - INSTALL 4 WIRE FLAT OR 7PIN CONNECTOR

(MSIDES) Installed 4 wire flat trailer connector adaptor harness. MS 1.0HRS

(AJONES) Visit Reason Changed On 8/30/2022 10:00 AM By AJONES

14-44-012 - INSTALL TANK - FUEL, GASEOUS

(LISAPATE) Removed the fuel tank out of the bed of this vehicle using the forklift. Installed the fuel tank in S9693B. Ran power and ground wires to the battery and ran another ground wire to a bracket on the frame. Secured tank to the bed of the truck using a heavy-duty ratchet strap. EH 1.6 HRS

14-51-067 - INSTALL TRAILER BALL

(MSIDES) Installed trailer ball and eye bolts for safety chains into bumper. MS 1.5HRS

(AJONES) Visit Reason Changed On 8/30/2022 10:00 AM By AJONES

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 45071

USING DEPT NO:	600203	OPENED DATE:	10/25/2022 09:55:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/26/2022 11:05:04	METER 1 - M:	12664	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/27/2022 07:53:15	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.13	\$15.90	\$15.63	\$0.00	\$31.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.27	\$40.37	\$0.00	\$61.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.32	37.17	56.00	5.00	98.17
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/25/2022 10:42:05	10/25/2022 10:50:10	0.13	\$15.90
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/25/2022 10:30:56	10/25/2022 10:41:45	0.18	\$21.27
					LABOR	37.17

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.72	1	\$5.72
					PARTS	56.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 45071

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 46230

USING DEPT NO:	600203	OPENED DATE:	02/21/2023 12:42:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2023 13:51:58	METER 1 - M:	14075	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/10/2023 07:57:14	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-010	REPLACE NEW STARTER	DON	N	N	GARAGE	0.82	\$96.30	\$167.96	\$0.00	\$264.26
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.04	\$4.85	\$0.00	\$0.00	\$4.85
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.67	\$78.67	\$0.00	\$0.00	\$78.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.70	\$0.00	\$0.00	\$11.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.25	\$29.96	\$0.00	\$0.00	\$29.96

JOB COUNT: 6	WORK ORDER TOTAL:	1.88	221.48	167.96	5.00	394.44
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/06/2023 11:27:43	04/06/2023 11:30:11	0.04	\$4.85
WA-00	WASH COMPLETE VEHICLE	11074414	04/06/2023 11:30:25	04/06/2023 11:45:39	0.25	\$29.96
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/06/2023 09:36:19	04/06/2023 10:16:19	0.67	\$78.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/06/2023 09:30:00	04/06/2023 09:35:57	0.10	\$11.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/06/2023 09:24:20	04/06/2023 09:24:20	0.00	\$0.00
03-32-010	REPLACE NEW STARTER	11074414	04/06/2023 07:17:48	04/06/2023 07:24:26	0.11	\$13.05
03-32-010	REPLACE NEW STARTER	11074414	04/06/2023 07:17:48	04/06/2023 07:24:26	(0.11)	(\$13.05)
03-32-010	REPLACE NEW STARTER	11074414	04/06/2023 07:17:48	04/06/2023 07:24:26	0.11	\$13.05
03-32-010	REPLACE NEW STARTER	11074414	04/05/2023 15:09:30	04/05/2023 15:51:50	0.71	\$83.26
03-32-010	REPLACE NEW STARTER	11074414	04/05/2023 15:09:30	04/05/2023 15:51:50	0.71	\$83.26
03-32-010	REPLACE NEW STARTER	11074414	04/05/2023 15:09:30	04/05/2023 15:51:50	(0.71)	(\$83.26)
				LABOR		221.49

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-010	REPLACE NEW STARTER	REM17213	STARTER	167.96	1	\$167.96
03-32-010	REPLACE NEW STARTER	REM17213	STARTER	167.96	(1)	(\$167.96)
03-32-010	REPLACE NEW STARTER	REM17213	STARTER	167.96	1	\$167.96
					PARTS	167.96

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 46230

Work Order Notes

(EHANNAH) starter issues- replace new starter
(LISAPATE) Due for PM-SI-replace wipers-wash

Job Notes

03-32-010 - REPLACE NEW STARTER

(SHARBIN) Installed a new starter. Rechecks good. SH
(AJONES) Visit Reason Changed On 5/1/2023 9:54 AM By AJONES

03-51-038 - REPLACE NEW WIPER BLADES

06-32-010 - INSPECT STARTER

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front pads measure 5.5MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1411 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 47982

USING DEPT NO:	600203	OPENED DATE:	08/24/2023 13:17:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2023 10:54:59	METER 1 - M:	15484	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 15:36:37	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-44-003	REPAIR FUEL PUMP	DON	N	N	GARAGE	1.26	\$148.61	\$14.34	\$0.00	\$162.95
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.26	148.61	14.34	5.00	167.95
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-44-003	REPAIR FUEL PUMP	12052187	08/25/2023 14:30:00	08/25/2023 14:40:26	0.17	\$20.52
24-44-003	REPAIR FUEL PUMP	12052187	08/25/2023 14:00:24	08/25/2023 14:15:00	0.24	\$28.71
24-44-003	REPAIR FUEL PUMP	12052187	08/25/2023 08:24:28	08/25/2023 09:15:00	0.84	\$99.38
LABOR						148.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-44-003	REPAIR FUEL PUMP	PIC5577PT	TOGGLE SWITCH	7.50	1	\$7.50
24-44-003	REPAIR FUEL PUMP	C111	RED BRAKE CLEANER	6.36	1	\$6.36
24-44-003	REPAIR FUEL PUMP	ATO30	FUSE-30 AMP	0.48	1	\$0.48
PARTS						14.34

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 47982

Work Order Notes

(EHANNAH) scan out - driver reports fuel pump might be bad or a bad connection because it blows fuses.

Job Notes

24-44-003 - REPAIR FUEL PUMP

(GARAGE) Inspected rear fuel pump in bed and found wires corroded inside pump and on the switch. replaced switch and cleaned inside of electrical panel. sealed both panels with silicone. JAW 1.5hr labor

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 9/28/2023 3:44 PM By AJONES

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) cancel

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 48214

USING DEPT NO:	600203	OPENED DATE:	09/14/2023 12:31:00	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2023 08:36:47	METER 1 - M:	15631	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2023 13:59:38	IN-SERVICE DATE:	11/14/2014						
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA			UNIT SERIAL NO:	5TFTX4CN2FX051071					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-35-006	REPLACE NEW FUSE(S)	DON	N	N	GARAGE	1.83	\$215.91	\$32.82	\$0.00	\$248.73
03-44-003	REPLACE NEW FUEL PUMP	DON	N	N	GARAGE	0.44	\$51.46	\$561.43	\$0.00	\$612.89
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.23	\$16.65	\$0.00	\$18.88
06-44-003	INSPECT FUEL PUMP	DON	N	N	GARAGE	0.03	\$3.61	\$0.00	\$0.00	\$3.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.46	\$43.83	\$0.00	\$52.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.39	281.67	654.73	5.00	941.40
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-44-003	REPLACE NEW FUEL PUMP	12052187	09/21/2023 13:04:13	09/21/2023 13:30:23	0.44	\$51.46
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/14/2023 13:57:48	09/14/2023 13:58:56	0.02	\$2.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2023 13:53:05	09/14/2023 13:57:23	0.07	\$8.46
06-44-003	INSPECT FUEL PUMP	12052187	09/21/2023 13:30:55	09/21/2023 13:32:45	0.03	\$3.61
06-44-003	INSPECT FUEL PUMP	12052187	09/21/2023 13:30:55	09/21/2023 13:32:45	(0.03)	(\$3.61)
06-44-003	INSPECT FUEL PUMP	12052187	09/21/2023 13:30:55	09/21/2023 13:32:45	0.03	\$3.61
03-35-006	REPLACE NEW FUSE(S)	12052187	09/21/2023 13:32:45	09/21/2023 14:15:00	0.70	\$83.09
03-35-006	REPLACE NEW FUSE(S)	12052187	09/21/2023 14:30:00	09/21/2023 15:37:32	1.13	\$132.82
LABOR						281.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-003	REPLACE NEW FUEL PUMP	BALBF956	FUEL FILTER	15.56	1	\$15.56
03-35-006	REPLACE NEW FUSE(S)	LITACB30BP	CIRCUIT BREAKER FUSE	32.82	1	\$32.82
03-44-003	REPLACE NEW FUEL PUMP	38NH81	FUEL TRANSFER PUMP	545.87	1	\$545.87
					PARTS	654.73

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 48214

Work Order Notes

(CWIGLEY) PM. Inspect fuel pump on the tank in the bed.

Job Notes

03-35-006 - REPLACE NEW FUSE(S)

(GARAGE) Replaced fuse to fuel pump in bed. JAW

03-44-003 - REPLACE NEW FUEL PUMP

(GARAGE) Replaced fuel pump in bed. Wired in and sealed. Sealed threads with tape. Installed new filter. JAW 1hr labor

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

06-44-003 - INSPECT FUEL PUMP

(GARAGE) fuel pump bad needs replaced.

(AJONES) Visit Reason Changed On 9/28/2023 9:26 PM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 49534

USING DEPT NO:	600203	OPENED DATE:	01/23/2024 07:56:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/23/2024 15:37:19	METER 1 - M:	16988	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/24/2024 07:28:20	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.08	\$0.00	\$0.00	\$21.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$44.81	\$0.00	\$0.00	\$44.81

JOB COUNT: 3	WORK ORDER TOTAL:	0.56	65.89	0.00	5.00	70.89
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	01/23/2024 08:37:06	01/23/2024 08:59:53	0.38	\$44.81
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/23/2024 08:25:32	01/23/2024 08:36:15	0.18	\$21.08
					LABOR	65.89

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 49534

Work Order Notes

(LISAPATE) PM-replace wipers
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) driven 1190 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 51023

USING DEPT NO:	600203	OPENED DATE:	06/05/2024 07:12:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2024 10:36:10	METER 1 - M:	18448	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2024 12:28:13	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.51	\$48.30	\$0.00	\$49.81
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.18	\$11.79	\$0.00	\$12.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.62	\$0.00	\$0.00	\$0.62

JOB COUNT: 4	WORK ORDER TOTAL:	0.03	3.31	60.09	5.00	68.40
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	06/05/2024 09:12:17	06/05/2024 09:12:36	0.01	\$0.62
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	06/05/2024 09:11:20	06/05/2024 09:11:56	0.01	\$1.18
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/05/2024 09:10:14	06/05/2024 09:11:00	0.01	\$1.51
				LABOR		3.31

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
				PARTS		60.09

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 51023

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed sh - fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced cabin filter fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 52968

USING DEPT NO:	600203	OPENED DATE:	12/04/2024 10:45:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2024 10:54:46	METER 1 - M:	20732	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2024 12:24:05	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$45.15	\$0.00	\$45.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	45.15	5.00	50.15
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	6	\$38.70
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
	PARTS					45.15

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 52968

Work Order Notes

(CHANNELL) pm
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ-topside
JR-pit
perform PM, changed oil and filter, checked air filters, checked fluids, checked tires and tire pressures
20597 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 54531

USING DEPT NO:	600203	OPENED DATE:	04/21/2025 08:49:17	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2025 12:12:24	METER 1 - M:	22261	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/22/2025 14:40:22	IN-SERVICE DATE:	11/14/2014				
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	0.00	\$0.00	\$58.03	\$0.00	\$58.03
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 7	WORK ORDER TOTAL:	0.00	0.00	58.03	5.00	63.03
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR17906B	FRONT BRAKES	51.59	1	\$51.59
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	6.44	1	\$6.44
PARTS						58.03

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 54531

Work Order Notes

(EHANNAH) pm- wipers- wash - SI

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(GARAGE) FOUND FRONT BRAKE PADS WHERE 3MM IN THICKNESS DURNING SAFETY INSPECTION. CHECKED ROTORS AND FOUND THEY WHERE 25.00MM SAME A NEW ONES. ORDERED BRAKE PADS, REMOVED CALIPERS AND PADS, INSTALLED PADS AND NEW HARDWEAR, INSTALLED CALIPERS AND TIRES. 1.0HR CQ

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) DID NOT NEED WIPERS.CQ

66-13-130 - PERFORM Burnish Brakes

(GARAGE) BURNISHED BRAKES. 0.5HR CQ

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SAVETY INSPECTION PER SI SHEET, FOUND EVERYTHING CHECKED OUT OK EXCEPRT FRONT BRAKES THAT MESSURED 3MM. ORDERED FRONT BRAKES. CQ

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) DRIVEN ONLY 1664 MILES THE TRUCK WAS A CHECKER. CHECKED AND TOPPED OFF ALL FLUIDS. RECORDED TREAD DEPTH AND BUILD DATES AND SET TIRE PRESSURES, INSTALLED NEW STICKER. CQ

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) DID NOT NEEDED WASHED. CQ

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 56517

USING DEPT NO:	600203	OPENED DATE:	09/24/2025 07:05:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2025 15:06:52	METER 1 - M:	24753	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2025 07:13:25	IN-SERVICE DATE:	11/14/2014	
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA		UNIT SERIAL NO:	5TFTX4CN2FX051071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.03	\$0.00	\$16.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.98	\$0.00	\$51.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	68.01	5.00	73.01
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	21-1	21" WIPER	7.70	1	\$7.70
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	13.64	1	\$13.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.39	6	\$38.34
					PARTS	68.01

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 56517

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) 24,753 miles

PM

JR- Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths

FJ- Oil change, added oil & checked level

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(EKIMBREL)

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 56891

USING DEPT NO:	600203	OPENED DATE:	10/21/2025 09:46:54	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	COMPLETED	COMPLETED DATE:	10/21/2025 11:06:55	METER 1 - M:	24799	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	11/14/2014				
TECH SPEC NO:	15TOYTACOMA	2015 TOYOTA TACOMA							
			UNIT SERIAL NO:	5TFTX4CN2FX051071					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-44-001	REMOVE TANK - FUEL, LIQUID	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 11:45:00 By User: GLOBETTI

UNIT NO: 240981 2015 TOYOTA TACOMA

WORK ORDER NO: 56891

Work Order Notes

(EKIMBREL) prep for sale. remove fuel tank from bed of truck

Job Notes

25-44-001 - REMOVE TANK - FUEL, LIQUID

(GARAGE) cm removed fuel tank and wiring harness from vehicle tank will be installed in new unit, 1 hour labor,

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm performed per for sale unit had 25072 miles,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Oct 21 2025 11:45:00 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '240981') //Q=