

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 34999

USING DEPT NO:	504107	OPENED DATE:	11/27/2019 08:04:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/06/2019 06:39:37	METER 1 - M:	254	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/06/2019 06:39:38	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.27	\$0.00	\$0.00	\$0.00	\$0.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.77	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	11/27/2019 13:26:28	11/27/2019 13:42:45	0.27	\$0.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	11/27/2019 08:05:38	11/27/2019 08:35:38	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 34999

Work Order Notes

(LISAPATE) New unit do PDI
(LISAPATE) Install 4G GPS system

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) Installed 4G GPS serial# 5041374844

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 37763

USING DEPT NO:	504107	OPENED DATE:	09/25/2020 10:18:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2020 11:44:56	METER 1 - M:	781	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2020 13:27:34	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$0.00	\$27.66	\$0.00	\$27.66

JOB COUNT: 1	WORK ORDER TOTAL:	0.45	0.00	27.66	0.00	27.66
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/25/2020 10:32:02	09/25/2020 10:59:02	0.45	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.32	1	\$4.32
					PARTS	27.66

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 37763

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH AB/ AMG PERFORMED PM

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 39205

USING DEPT NO:	504107	OPENED DATE:	02/25/2021 08:44:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2021 13:39:16	METER 1 - M:	976	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2021 15:34:10	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.75	\$0.00	\$0.00	\$61.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.52	61.75	0.00	0.00	61.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/25/2021 09:38:54	02/25/2021 10:10:18	0.52	\$61.75
					LABOR	61.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 39205

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 976 Vehicle has been 195 miles, oil was changed at last PM, checked fluids, battery and tires. Update oil change sticker. Completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 40113

USING DEPT NO:	504107	OPENED DATE:	06/07/2021 08:06:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2021 11:00:46	METER 1 - M:	1556	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2021 11:49:00	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-44-003	RECALL FUEL PUMP	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.50	59.00	0.00	0.00	59.00
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-44-003	RECALL FUEL PUMP	11076422	6119539		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-44	TRANSPORT FUEL SYSTEM	11915538	06/15/2021 07:00:00	06/15/2021 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 40113

Work Order Notes

(LISAPATE) Take to Tuscaloosa Toyota for recall NHTSA recall No 20V-682 Vehicle may stall while driving

Job Notes

16-44 - TRANSPORT FUEL SYSTEM

(LISAPATE) Taken to Toyota by drivers

17-44-003 - RECALL FUEL PUMP

(LISAPATE) Tuscaloosa Toyota installed new fuel pump kit

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 40498

USING DEPT NO:	504107	OPENED DATE:	07/21/2021 10:44:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2021 09:58:46	METER 1 - M:	1675	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/22/2021 14:19:36	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.59	\$14.66	\$0.00	\$19.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$93.52	\$35.80	\$0.00	\$129.32

JOB COUNT: 2	WORK ORDER TOTAL:					0.83	98.11	50.46	0.00	148.57
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/21/2021 13:49:12	07/21/2021 14:13:44	0.41	\$48.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/21/2021 13:57:50	07/21/2021 14:20:51	0.38	\$45.27
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/21/2021 14:21:09	07/21/2021 14:23:29	0.04	\$4.59
					LABOR	98.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.40	1	\$4.40
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	7	\$31.40
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.33	1	\$7.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.33	1	\$7.33
					PARTS	50.46

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 40498

Work Order Notes

(IFALLS) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 1675 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 41864

USING DEPT NO:	504107	OPENED DATE:	12/13/2021 09:48:02	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2021 09:43:52	METER 1 - M:	2040	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/15/2021 11:18:00	IN-SERVICE DATE:	11/25/2019						
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma			UNIT SERIAL NO:	5TFAX5GN6KX153569					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.62	\$15.18	\$0.00	\$19.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$58.38	\$0.00	\$0.00	\$58.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.53	63.00	15.18	2.00	80.18
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/14/2021 07:38:30	12/14/2021 07:40:51	0.04	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2021 07:08:38	12/14/2021 07:38:19	0.49	\$58.38
LABOR						63.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
PARTS						15.18

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 41864

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 365 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 43119

USING DEPT NO:	504107	OPENED DATE:	05/03/2022 13:02:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2022 10:54:18	METER 1 - M:	2412	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2022 12:51:25	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.69	\$15.18	\$0.00	\$19.87
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$41.40	\$31.97	\$0.00	\$73.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.39	46.09	47.15	2.00	95.24
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/03/2022 15:02:42	05/03/2022 15:05:05	0.04	\$4.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/03/2022 14:41:28	05/03/2022 15:02:31	0.35	\$41.40
					LABOR	46.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
					PARTS	47.15

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 43119

Work Order Notes

(CHANNELL) pm replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) CW RC Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 44733

USING DEPT NO:	504107	OPENED DATE:	09/20/2022 10:59:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2022 10:52:15	METER 1 - M:	3099	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/21/2022 12:28:14	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.85	\$0.00	\$0.00	\$18.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.16	18.85	0.00	5.00	23.85
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/20/2022 11:44:07	09/20/2022 11:53:42	0.16	\$18.85
					LABOR	18.85

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 44733

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 687 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 46289

USING DEPT NO:	504107	OPENED DATE:	02/27/2023 10:19:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/28/2023 07:29:01	METER 1 - M:	3996	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/28/2023 08:28:00	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.64	\$0.00	\$33.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$42.80	\$0.00	\$81.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.48	56.64	58.44	5.00	120.08
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	02/27/2023 12:42:43	02/27/2023 12:42:43	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	02/27/2023 12:42:43	02/27/2023 12:42:43	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	02/27/2023 12:42:43	02/27/2023 12:51:43	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/27/2023 12:23:34	02/27/2023 12:43:22	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/27/2023 12:23:34	02/27/2023 12:23:34	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/27/2023 12:23:34	02/27/2023 12:23:34	0.00	\$0.00
				LABOR		56.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.17	1	\$6.17
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.11	6	\$36.63
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
				PARTS		58.44

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 46289

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers,-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, tires, and tire pressure
Miles, 3,996

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 47639

USING DEPT NO:	504107	OPENED DATE:	07/19/2023 08:42:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/20/2023 10:38:19	METER 1 - M:	4943	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2023 13:22:58	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.72	\$0.00	\$0.00	\$6.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.11	\$13.14	\$0.00	\$0.00	\$13.14

JOB COUNT: 3	WORK ORDER TOTAL:	0.17	19.86	0.00	5.00	24.86
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	07/19/2023 09:30:00	07/19/2023 09:36:41	0.11	\$13.14
WA-00	WASH COMPLETE VEHICLE	12201267	07/19/2023 09:20:30	07/19/2023 09:20:30	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/19/2023 09:11:35	07/19/2023 09:15:00	0.06	\$6.72
				LABOR		19.86

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 47639

Work Order Notes

(EHANNAH) pm- replace wipers- wash
(EKIMBREL) did not need wipers yet

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Fluid check only, vehicle driven 947 miles, filters good, tires and tire pressure, updated oil change sticker.
Miles, 4,943

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 49213

USING DEPT NO:	504107	OPENED DATE:	12/11/2023 10:17:52	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2023 10:31:21	METER 1 - M:	5665	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2023 13:03:01	IN-SERVICE DATE:	11/25/2019						
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma			UNIT SERIAL NO:	5TFAX5GN6KX153569					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.77	\$16.66	\$0.00	\$20.43
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.64	\$75.75	\$0.00	\$0.00	\$75.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.81	\$43.92	\$0.00	\$72.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.31	\$36.58	\$0.00	\$0.00	\$36.58

JOB COUNT: 5	WORK ORDER TOTAL:	1.23	144.91	60.58	5.00	210.49
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/11/2023 15:03:01	12/11/2023 15:04:56	0.03	\$3.77
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/11/2023 14:47:59	12/11/2023 15:02:38	0.24	\$28.81
66-79-003	PERFORM SAFETY INSPECTION	11074414	12/12/2023 07:38:51	12/12/2023 08:17:22	0.64	\$75.75
WA-00	WASH COMPLETE VEHICLE	11074414	12/12/2023 08:17:54	12/12/2023 08:36:30	0.31	\$36.58
LABOR						144.91

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.29	6	\$37.71
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	(1)	(\$8.33)
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
PARTS						60.58

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 49213

Work Order Notes

(EHANNAH) pm- wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front brake pads measure 8MM. Rear brake shoes measure 5MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 50700

USING DEPT NO:	504107	OPENED DATE:	04/29/2024 15:07:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/30/2024 09:54:31	METER 1 - M:	6225	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2024 10:25:15	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.11	\$0.00	\$0.00	\$1.11

JOB COUNT: 3	WORK ORDER TOTAL:	0.21	24.71	0.00	5.00	29.71
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	04/29/2024 15:31:33	04/29/2024 15:32:07	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/29/2024 15:30:17	04/29/2024 15:31:33	(0.02)	(\$2.49)
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/29/2024 15:30:17	04/29/2024 15:31:33	0.02	\$2.49
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/29/2024 15:30:17	04/29/2024 15:42:17	0.20	\$23.60
				LABOR		24.71

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 50700

Work Order Notes

(CWIGLEY) PM. Wipers. Wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 560 miles. Checked fluids tire pressure and updated the oil change sticker. SH FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed was full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 51827

USING DEPT NO:	504107	OPENED DATE:	08/15/2024 10:08:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2024 10:28:49	METER 1 - M:	6225	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/17/2024 11:07:19	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$822.35	\$822.35
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	0.00	827.35	827.35
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	120888		\$822.35
				COMML	827.35

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 51827

Work Order Notes

(EHANNAH) WIPERS- TRANSPORT TO GLASS DR. FOR NEW WINDSHIELD

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EKIMBREL) Glass DR replaced windshield

03-51-038 - REPLACE NEW WIPER BLADES

16-71 - TRANSPORT BODY

(EKIMBREL) rc/cw transported vehicle to and from glass dr

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 52306

USING DEPT NO:	504107	OPENED DATE:	09/27/2024 12:33:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2024 13:40:34	METER 1 - M:	6911	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2024 15:28:12	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.48	\$0.00	\$48.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	48.48	5.00	53.48
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
	PARTS					48.48

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 52306

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-CM,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 6,911

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 53967

USING DEPT NO:	504107	OPENED DATE:	03/04/2025 13:17:38	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2025 08:50:23	METER 1 - M:	7165	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/17/2025 15:05:27	IN-SERVICE DATE:	11/25/2019						
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma			UNIT SERIAL NO:	5TFAX5GN6KX153569					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$25.90	\$0.00	\$25.90
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$824.28	\$0.00	\$824.28
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	850.18	5.00	855.18
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.06	4	\$12.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04493400000	TIRE 245/75R16 GEN GRAB HT	203.01	4	\$812.04
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.86	1	\$10.86
PARTS						850.18

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 53967

Work Order Notes

(EHANNAH) pm- wipers- wash- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR- replaced wiper blades

66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment cm test drove checked ok,

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) cq mounted tires, cm balanced tires,

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SI PER SAFETY INSPECTION SHEET, EVERYTHING CHECKED GOOD. BRAKE PADS 8MM ALL AROUND. CQ

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) perform PM, fluid check only

JR-

(GARAGE) JR & CQ- checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 55703

USING DEPT NO:	504107	OPENED DATE:	08/01/2025 07:18:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2025 08:54:53	METER 1 - M:	7530	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/05/2025 09:20:13	IN-SERVICE DATE:	11/25/2019	
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN6KX153569	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$50.39	\$0.00	\$50.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	50.39	5.00	55.39
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	11.96	1	\$11.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
					PARTS	50.39

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 55703

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- topside

JR- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
7530 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 56738

USING DEPT NO:	504107	OPENED DATE:	10/09/2025 08:46:20	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/10/2025 09:06:05	METER 1 - M:	7731	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/10/2025 13:12:18	IN-SERVICE DATE:	11/25/2019						
TECH SPEC NO:	19TOYTACOMA	2019 Toyota Tacoma			UNIT SERIAL NO:	5TFAX5GN6KX153569					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.20	\$29.71	\$0.00	\$0.00	\$29.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$3.42	\$0.29	\$0.00	\$3.71

JOB COUNT: 3	WORK ORDER TOTAL:	0.22	33.13	0.29	5.00	38.42
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-52-021	REMOVE GPS SYSTEM	11779687	10/09/2025 08:47:20	10/09/2025 08:59:13	0.20	\$29.71
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	10/10/2025 08:11:41	10/10/2025 08:13:03	0.02	\$3.42
LABOR						33.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.15	2	\$0.29
PARTS						0.29

Work Order Charge Detail

The University of Alabama

Report Printed: 10/20/2025 10:14:26 By User: GLOBETTI

UNIT NO: 243573 2019 TOYOTA TACOMA

WORK ORDER NO: 56738

Work Order Notes

(EHOWELL) Prep for sale.

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) FJ- Removed GPS. S/N: 87U030640218. Installed in 7592B

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks and tag 2854C. No GPS. No vanity plate. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Oct 20 2025 10:14:26 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243573') //Q=