

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 43876

USING DEPT NO:	507301	OPENED DATE:	07/07/2022 15:08:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2022 15:09:49	METER 1 - M:	8	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 09:51:31	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	2.00	120.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12052187	07/07/2022 15:09:15	07/07/2022 16:09:15	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 43876

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed by JW

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 44529

USING DEPT NO:	507301	OPENED DATE:	08/31/2022 08:59:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/01/2022 15:33:36	METER 1 - M:	3961	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 09:18:14	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.11	\$0.00	\$0.00	\$23.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.20	23.11	0.00	5.00	28.11
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2022 11:08:48	08/31/2022 11:20:33	0.20	\$23.11
LABOR						23.11

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 44529

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 3961 miles. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 45402

USING DEPT NO:	507301	OPENED DATE:	12/01/2022 09:13:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2022 09:27:22	METER 1 - M:	10773	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2022 09:56:58	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11076422	6184756		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 45402

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) 10,000-mile oil change completed by Tuscaloosa Toyota at no charge.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 46821

USING DEPT NO:	507301	OPENED DATE:	04/24/2023 15:20:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2023 07:40:49	METER 1 - M:	15290	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2023 11:04:59	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$12.88	\$41.36	\$0.00	\$54.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.11	12.88	41.36	5.00	59.24
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/25/2023 10:08:55	04/25/2023 10:15:28	0.11	\$12.88
					LABOR	12.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.11	5	\$35.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.81	1	\$5.81
					PARTS	41.36

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 46821

Work Order Notes

(EHANNAH) pm- replace wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 47539

USING DEPT NO:	507301	OPENED DATE:	07/06/2023 12:22:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2023 08:10:53	METER 1 - M:	20033	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/10/2023 15:43:13	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	0.00	5.00	43.94
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6210842		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11399745	07/07/2023 07:00:00	07/07/2023 07:19:48	0.33	\$38.94
LABOR						38.94

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 47539

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM for 20,000 miles done by Tuscaloosa Toyota at no charge.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 48004

USING DEPT NO:	507301	OPENED DATE:	08/28/2023 09:15:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2023 10:09:30	METER 1 - M:	25412	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 15:20:05	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.82	\$24.08	\$0.00	\$28.90
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.22	\$25.96	\$0.00	\$0.00	\$25.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.32	\$48.08	\$0.00	\$68.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.43	51.10	72.16	5.00	128.26
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/28/2023 10:53:48	08/28/2023 11:07:00	0.22	\$25.96
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/28/2023 10:49:18	08/28/2023 10:51:45	0.04	\$4.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/28/2023 10:38:13	08/28/2023 10:48:33	0.17	\$20.32
				LABOR		51.10

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.78	1	\$5.78
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.46	5	\$42.30
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
				PARTS		72.16

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 48004

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH Rotated the left side and FC rotated the right side and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) FC SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 48773

USING DEPT NO:	507301	OPENED DATE:	10/31/2023 09:41:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2023 10:10:02	METER 1 - M:	29677	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2023 13:16:51	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.83	\$52.80	\$0.00	\$84.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.27	31.83	52.80	5.00	89.63
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/31/2023 11:11:35	10/31/2023 11:27:46	0.27	\$31.83
					LABOR	31.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	12.45	1	\$12.45
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.07	5	\$40.35
					PARTS	52.80

Work Order Charge Detail

UNIT NO:	244758	2022 TOYOTA CAMRY	WORK ORDER NO:	48773
----------	--------	-------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 49160

USING DEPT NO:	507301	OPENED DATE:	12/06/2023 07:16:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/06/2023 11:53:40	METER 1 - M:	33328	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/06/2023 14:03:25	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.47	\$57.72	\$0.00	\$87.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.25	29.47	57.72	5.00	92.19
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/06/2023 07:34:22	12/06/2023 07:49:21	0.25	\$29.47
					LABOR	29.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.91	5	\$39.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	57.72

Work Order Charge Detail

UNIT NO:	244758	2022 TOYOTA CAMRY	WORK ORDER NO:	49160
----------	--------	-------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed FC - sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 49867

USING DEPT NO:	507301	OPENED DATE:	02/20/2024 11:18:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/29/2024 13:20:06	METER 1 - M:	38007	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/29/2024 15:29:29	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.01	\$85.79	\$0.00	\$124.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	39.01	85.79	5.00	129.80
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/28/2024 08:55:10	02/28/2024 09:15:00	0.33	\$39.01
					LABOR	39.01

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER	35.61	1	\$35.61
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.02	5	\$35.10
					PARTS	85.79

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 49867

Work Order Notes

(LRUSHING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. Installed RFID# SVO1948. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 50733

USING DEPT NO:	507301	OPENED DATE:	05/03/2024 08:28:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2024 12:21:18	METER 1 - M:	42009	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/06/2024 08:18:12	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.40	\$0.00	\$0.00	\$35.40
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.10	\$11.80	\$22.73	\$0.00	\$34.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.40	47.20	22.73	5.00	74.93
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	05/03/2024 11:37:28	05/03/2024 11:43:28	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/03/2024 12:19:28	05/03/2024 12:37:28	0.30	\$35.40
					LABOR	47.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
					PARTS	22.73

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 50733

Work Order Notes

(EHANNAH) pm- wipers
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) fc performed pm

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) fc replaced cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 51320

USING DEPT NO:	507301	OPENED DATE:	06/26/2024 12:52:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2024 12:39:27	METER 1 - M:	44302	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/28/2024 13:20:27	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$879.75	\$879.75
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	0.00	884.75	884.75
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	119535		\$879.75
COMML					884.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 51320

Work Order Notes

(EHANNAH) transport to Glass Dr. for new windshield.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EKIMBREL) Glass Dr replaced windshield

16-71 - TRANSPORT BODY

(EKIMBREL) driver transported vehicle to and from Glass Dr

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 51935

USING DEPT NO:	507301	OPENED DATE:	08/26/2024 08:51:25	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2024 11:23:28	METER 1 - M:	44906	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2024 14:37:22	IN-SERVICE DATE:	07/05/2022						
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry									
				UNIT SERIAL NO:	4T1C11AK5NU065776						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.11	\$0.00	\$24.11
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$594.60	\$0.00	\$594.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.37	\$0.00	\$43.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	0.00	0.00	662.08	5.00	667.08
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.31	5	\$36.53
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	12	\$2.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.33	2	\$6.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	292.80	2	\$585.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	292.80	(2)	(\$585.60)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	292.80	2	\$585.60
PARTS						662.08

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 51935

Work Order Notes

(EHANNAH) wipers- tire pressure light is on- possible DF tire

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

06-15 - INSPECT STEERING

(GARAGE) STEERING CHECKED OK,

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) VEHICLE HAD 2 TIRES DAMAGED WITH METAL IN TIRES

09-15 - ALIGN STEERING

(GARAGE) Performed alignment. Adjusted rear and front toe both sides. Test drove and found no issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) MOUNTED AND BALANCE BOTH FRONT TIRES INSTALLED 2 NEW VALVE CORE AND 12 1/4 STICK ON WEIGHTS

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 44,906

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 52526

USING DEPT NO:	507301	OPENED DATE:	10/18/2024 09:53:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2024 07:39:13	METER 1 - M:	46557	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2024 08:40:30	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-009	REPLACE NEW SUN VISOR	DON	N	N	GARAGE	0.00	\$0.00	\$144.65	\$0.00	\$144.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	144.65	5.00	149.65
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-009	REPLACE NEW SUN VISOR	7432006C72B1	SUN VISOR	144.65	1	\$144.65
PARTS						144.65

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 52526

Work Order Notes

(EHANNAH) repair sun visor

Job Notes

03-02-009 - REPLACE NEW SUN VISOR

(EKIMBREL) replaced broken sun visor cm

24-02-009 - REPAIR SUN VISOR

(GARAGE) replaced broken sun visor cm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 53296

USING DEPT NO:	507301	OPENED DATE:	01/07/2025 08:46:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/09/2025 14:16:19	METER 1 - M:	47456	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/09/2025 15:18:47	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$88.96	\$0.00	\$88.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	113.04	5.00	118.04
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	15.71	5	\$78.53
					PARTS	113.04

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 53296

Work Order Notes

(EHANNAH) pm- wipers- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced wiper blades.

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI. Brakes are 8mm on LF, RF, RR, & LR. Tires are 9/32 in the front, 7/32 in the rear.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Oil change, topped off fluids, set tire pressure, recorded date codes & tread depths, checked filters.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 53882

USING DEPT NO:	507301	OPENED DATE:	02/25/2025 12:30:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2025 14:09:44	METER 1 - M:	47456	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/26/2025 07:46:51	IN-SERVICE DATE:	07/05/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK5NU065776	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$174.00	\$0.00	\$174.00
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	174.00	5.00	179.00
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F-3	BATTERY	174.00	1	\$174.00
					PARTS	174.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 53882

Work Order Notes

(CWIGLEY) Driver said they jumped it off, an let it run a while. but, it still had to be jumped off.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) DISCONNECTED BATTER CABLES AND REMOVED BATTERY. INSTALLED NEW BATTERY AND ALL THAT WAS REMOVED, FOUND TO CRANK CORRECTLY. CQ

06-32-002 - INSPECT BATTERY

(GARAGE) CHECKED BATTERY AND AND DID NOT PASS BATTERY TEST. CQ

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 54837

USING DEPT NO:	507301	OPENED DATE:	05/20/2025 09:11:15	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2025 10:14:10	METER 1 - M:	48257	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/21/2025 07:13:03	IN-SERVICE DATE:	07/05/2022						
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry			UNIT SERIAL NO:	4T1C11AK5NU065776					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/08/2025 09:47:38 By User: GLOBETTI

UNIT NO: 244758 2022 TOYOTA CAMRY

WORK ORDER NO: 54837

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Blades not needed at this time.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Fluid check. Mileage: 48,257. Driven 801 miles since PM. Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Oct 08 2025 09:47:38 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244758') //Q=