

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 35324

USING DEPT NO:	504103	OPENED DATE:	01/07/2020 10:45:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2020 08:35:07	METER 1 - M:	10	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2020 08:35:08	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	12052187	01/07/2020 10:47:01	01/07/2020 11:17:01	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 35324

Work Order Notes

(EKIMBREL) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) JW completed PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 36464

USING DEPT NO:	504103	OPENED DATE:	05/18/2020 08:48:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2020 10:12:48	METER 1 - M:	1827	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2020 13:48:13	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$0.00	\$27.60	\$0.00	\$27.60

JOB COUNT: 1	WORK ORDER TOTAL:	0.44	0.00	27.60	0.00	27.60
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/18/2020 08:50:01	05/18/2020 09:06:01	0.27	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/18/2020 08:49:31	05/18/2020 09:00:00	0.17	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.32	1	\$4.32
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	7	\$27.16
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	(7)	(\$27.16)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	6	\$23.28
					PARTS	27.60

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 36464

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH/JW performed pm. Coolant -20

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 38059

USING DEPT NO:	504103	OPENED DATE:	10/19/2020 13:13:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2020 14:53:56	METER 1 - M:	5634	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/20/2020 07:54:24	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.25	\$29.83	\$0.00	\$0.00	\$29.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$94.96	\$47.33	\$0.00	\$142.29

JOB COUNT: 2	WORK ORDER TOTAL:					1.06	124.79	47.33	0.00	172.12
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/19/2020 13:37:08	10/19/2020 13:52:18	0.25	\$29.83
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/19/2020 13:18:38	10/19/2020 13:49:59	0.52	\$61.66
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2020 13:20:12	10/19/2020 13:37:08	0.28	\$33.30
					LABOR	124.79

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	5.84	7	\$40.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
					PARTS	47.33

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 38059

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH JW ROTATED TIRES AND INSPECTED BRAKES.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° SH/JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 39615

USING DEPT NO:	504103	OPENED DATE:	04/09/2021 08:04:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/09/2021 11:10:32	METER 1 - M:	8523	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/12/2021 08:41:00	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.36	\$33.41	\$0.00	\$88.77

JOB COUNT: 1	WORK ORDER TOTAL:					0.47	55.36	33.41	0.00	88.77
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/09/2021 08:28:54	04/09/2021 08:49:58	0.35	\$41.43
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2021 08:39:48	04/09/2021 08:46:53	0.12	\$13.93
					LABOR	55.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
					PARTS	33.41

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 39615

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 8523 Completed PM top side, Josh was bottomsides. AMG/JW Completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 41199

USING DEPT NO:	504103	OPENED DATE:	10/05/2021 07:33:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/05/2021 11:01:10	METER 1 - M:	11677	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/05/2021 14:05:20	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.59	\$15.18	\$0.00	\$19.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$94.96	\$31.46	\$0.00	\$126.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.84	99.55	46.64	2.00	148.19
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/05/2021 07:43:04	10/05/2021 08:22:48	0.66	\$78.14
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/05/2021 08:18:57	10/05/2021 08:21:17	0.04	\$4.59
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/05/2021 08:10:13	10/05/2021 08:18:46	0.14	\$16.82
				LABOR		99.55

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	6	\$27.00
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.46	1	\$4.46
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
					PARTS	46.64

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 41199

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG
MILEAGE11677

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 42649

USING DEPT NO:	504103	OPENED DATE:	03/11/2022 08:22:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/11/2022 15:02:35	METER 1 - M:	14006	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2022 08:35:47	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.16	\$15.18	\$0.00	\$21.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.60	\$38.53	\$0.00	\$115.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$3.41	\$10.10	\$0.00	\$13.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.73	86.17	63.81	2.00	151.98
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	03/11/2022 09:09:00	03/11/2022 09:10:44	0.03	\$3.41
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/11/2022 09:05:33	03/11/2022 09:08:41	0.05	\$6.16
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/11/2022 08:58:49	03/11/2022 09:05:22	0.11	\$12.88
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/11/2022 08:32:58	03/11/2022 09:05:22	0.54	\$63.72
				LABOR		86.17

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	10.10	1	\$10.10
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
					PARTS	63.81

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 42649

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 43873

USING DEPT NO:	504103	OPENED DATE:	07/07/2022 14:28:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/13/2022 08:25:05	METER 1 - M:	15934	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2022 13:49:10	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$759.00	\$759.00
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
16-02-061	TRANSPORT WINDSHIELD	DON	S	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.70	\$82.93	\$0.00	\$0.00	\$82.93
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.96	\$113.54	\$403.23	\$0.00	\$516.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.42	284.97	403.23	761.00	1,449.20
--------------	-------------------	------	--------	--------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2100739		\$759.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	761.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02-061	TRANSPORT WINDSHIELD	11915538	07/13/2022 07:00:00	07/13/2022 07:30:00	0.50	\$59.00
06-15	INSPECT STEERING	12052187	07/13/2022 07:00:00	07/13/2022 07:15:00	0.25	\$29.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	07/08/2022 13:15:50	07/08/2022 13:42:02	0.44	\$51.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	07/08/2022 09:58:35	07/08/2022 10:30:07	0.53	\$62.02
66-17-013	PERFORM ALIGNMENT	11310047	07/11/2022 07:18:43	07/11/2022 08:00:53	0.70	\$82.93
				LABOR		284.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04504620000	GEN GRABBER 245/75R16	195.75	2	\$391.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.52	2	\$11.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
				PARTS		403.23

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 43873

Work Order Notes

(IFALLS) Replace windshield
replace front tires
perform alignment

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield and recalibrated. Pd by CC

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

06-15 - INSPECT STEERING

(LISAPATE) Checked steering. ok

16-02-061 - TRANSPORT WINDSHIELD

(LISAPATE) Taken to Glass Dr by RC

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Set front toe. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) miles: 15934

(AGUERRA) Mounted and balanced front tires. AMG JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 44314

USING DEPT NO:	504103	OPENED DATE:	08/16/2022 07:18:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/16/2022 14:31:07	METER 1 - M:	16616	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/18/2022 15:04:15	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.22	\$25.53	\$15.10	\$0.00	\$40.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.39	\$76.78	\$0.00	\$105.17
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$3.51	\$12.67	\$0.00	\$16.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.49	57.43	104.55	2.00	163.98
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/16/2022 07:41:51	08/16/2022 07:54:50	0.22	\$25.53
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	08/16/2022 07:40:04	08/16/2022 07:41:51	0.03	\$3.51
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/16/2022 07:25:38	08/16/2022 07:40:04	0.24	\$28.39
				LABOR		57.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.48	1	\$8.48
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.58	1	\$7.58
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.52	1	\$7.52
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	12.67	1	\$12.67
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	1	\$26.39
				PARTS		104.55

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 44314

Work Order Notes

(CWIGLEY) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wiper blade. SH,AMG

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm service. coolant -34. JAW,AMG/SH
MILEAGE-16616

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced cabin filter. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 45206

USING DEPT NO:	504103	OPENED DATE:	11/09/2022 07:34:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2022 09:41:32	METER 1 - M:	18208	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2022 15:47:39	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.05	\$6.23	\$113.55	\$0.00	\$119.78
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.20	\$23.76	\$0.00	\$0.00	\$23.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.25	29.99	113.55	5.00	148.54
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-32-002	INSPECT BATTERY	11074414	11/09/2022 09:30:00	11/09/2022 09:40:57	0.18	\$21.54
06-32-002	INSPECT BATTERY	11074414	11/09/2022 09:13:52	11/09/2022 09:15:00	0.02	\$2.23
03-32-002	REPLACE NEW BATTERY	11074414	11/09/2022 09:10:32	11/09/2022 09:13:42	0.05	\$6.23
LABOR						30.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
PARTS						113.55

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 45206

Work Order Notes

(EKIMBREL) check battery; had to jump off twice

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Replaced battery ALT charging at 13.9 volts. SH

06-32-002 - INSPECT BATTERY

(SHARBIN) Battery tested bad. Factory battery. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 45913

USING DEPT NO:	504103	OPENED DATE:	01/26/2023 07:01:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2023 15:38:52	METER 1 - M:	19213	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2023 07:23:26	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.67	\$15.64	\$0.00	\$19.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$10.72	\$42.63	\$0.00	\$53.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.12	14.39	58.27	5.00	77.66
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/26/2023 07:21:50	01/26/2023 07:23:42	0.03	\$3.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/26/2023 07:14:50	01/26/2023 07:20:17	0.09	\$10.72
LABOR					14.39	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.09	1	\$6.09
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
PARTS					58.27	

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 45913

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) JW Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH JW AMG/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 47260

USING DEPT NO:	504103	OPENED DATE:	06/05/2023 09:09:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2023 12:35:53	METER 1 - M:	21078	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2023 13:02:26	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$3.25	\$0.00	\$0.00	\$3.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$4.00	\$0.00	\$0.00	\$4.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.06	7.25	0.00	5.00	12.25
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	06/05/2023 09:31:50	06/05/2023 09:33:52	0.03	\$4.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/05/2023 09:30:00	06/05/2023 09:31:39	0.03	\$3.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/05/2023 09:20:13	06/05/2023 09:20:13	0.00	\$0.00
				LABOR		7.25

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 47260

Work Order Notes

(EHANNAH) pm- replace wipers- wash
(EKIMBREL) DID NOT NEED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1865 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Donald was detailing a vehicle. Customer was waiting did not wash. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 49046

USING DEPT NO:	504103	OPENED DATE:	11/27/2023 07:42:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2023 09:41:43	METER 1 - M:	23571	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 11:39:00	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.23	\$16.66	\$0.00	\$18.89
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.02	\$2.43	\$0.00	\$0.00	\$2.43
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.40	\$47.20	\$12.49	\$0.00	\$59.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$25.04	\$44.01	\$0.00	\$69.05
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.54	\$11.79	\$0.00	\$13.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 7	WORK ORDER TOTAL:	0.66	78.44	84.95	5.00	168.39
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12395904	11/30/2023 07:00:00	11/30/2023 07:24:00	0.40	\$47.20
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	11/27/2023 08:26:46	11/27/2023 08:27:33	0.01	\$1.54
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	11/27/2023 08:25:19	11/27/2023 08:26:33	0.02	\$2.43
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/27/2023 08:24:00	11/27/2023 08:25:08	0.02	\$2.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/27/2023 08:11:05	11/27/2023 08:23:49	0.21	\$25.04
				LABOR		78.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	6	\$37.80
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.80	1	\$4.80
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.46	1	\$5.46
66-17-030	PERFORM TIRE PATCH	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-030	PERFORM TIRE PATCH	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
PARTS						84.95

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 49046

Work Order Notes

(EHANNAH) pm- wipers- wash- RP tire not hold air

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) Nail in right rear tire. Can be patched. SH

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) FC patched RF tire

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) FC Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) washed by FC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 49452

USING DEPT NO:	504103	OPENED DATE:	01/11/2024 13:24:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/01/2024 12:19:09	METER 1 - M:	24345	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2024 07:26:29	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	N	N	GARAGE	0.04	\$5.28	\$162.50	\$0.00	\$167.78
03-50-102	REPLACE NEW IDLER PULLEY	DON	N	N	GARAGE	1.53	\$181.06	\$96.26	\$0.00	\$277.32
06-40	INSPECT ENGINE / MOTOR SYSTEMS	DON	N	N	GARAGE	0.06	\$6.92	\$0.00	\$0.00	\$6.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.64	193.26	258.76	5.00	457.02
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-40	INSPECT ENGINE / MOTOR SYSTEMS	12052187	01/19/2024 12:52:56	01/19/2024 12:56:27	0.06	\$6.92
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	12052187	01/19/2024 12:50:15	01/19/2024 12:52:56	0.04	\$5.28
03-50-102	REPLACE NEW IDLER PULLEY	12052187	01/19/2024 12:47:35	01/19/2024 12:50:15	0.04	\$5.24
03-50-102	REPLACE NEW IDLER PULLEY	12052187	01/17/2024 09:02:10	01/17/2024 10:31:34	1.49	\$175.82
				LABOR		193.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GAT36174	BELT	108.38	1	\$108.38
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	CTL4070900	BELT	54.12	1	\$54.12
03-50-102	REPLACE NEW IDLER PULLEY	CTL49127	IDLER PULLEY	96.26	1	\$96.26
				PARTS		258.76

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 49452

Work Order Notes

(EHANNAH) driver reports squeaking when he gets to 15-20 mph.

Job Notes

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(GARAGE) Installed new belt with the idler pulleys. Test drove and no more noise heard. JAW

03-50-102 - REPLACE NEW IDLER PULLEY

(GARAGE) Replaced right side idler pulley and buffed the left side idler pulley due to not finding a new one to replace it. No more noise after installing new belt. JAW

06-40 - INSPECT ENGINE / MOTOR SYSTEMS

(GARAGE) inspected and found both idler pulleys was spinning free and belt is squeaking. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 50803

USING DEPT NO:	504103	OPENED DATE:	05/10/2024 07:39:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/10/2024 12:08:18	METER 1 - M:	26264	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/13/2024 12:06:04	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.38	\$47.67	\$0.00	\$49.05
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.25	\$11.79	\$0.00	\$13.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.25	\$0.00	\$0.00	\$1.25

JOB COUNT: 4	WORK ORDER TOTAL:	0.03	3.88	59.46	5.00	68.34
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	05/10/2024 09:57:01	05/10/2024 09:57:39	0.01	\$1.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/10/2024 08:32:32	05/10/2024 08:33:14	0.01	\$1.38
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/10/2024 08:31:54	05/10/2024 08:32:32	0.01	\$1.25
				LABOR		3.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
				PARTS		59.46

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 50803

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 52555

USING DEPT NO:	504103	OPENED DATE:	10/22/2024 07:59:03	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/22/2024 15:38:29	METER 1 - M:	28881	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/23/2024 11:08:06	IN-SERVICE DATE:	01/07/2020						
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.66	\$0.00	\$16.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.39	\$0.00	\$48.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$24.18	\$0.00	\$24.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	89.23	5.00	94.23
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	24.18	1	\$24.18
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.99	6	\$41.94
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
PARTS						89.23

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 52555

Work Order Notes

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR_ replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- performed PM, checked fluids, tires and tire pressure

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) JR_ replaced cabin air filter

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 53506

USING DEPT NO:	504103	OPENED DATE:	01/28/2025 09:55:58	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	01/29/2025 15:23:32	METER 1 - M:	29836	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2025 07:24:36	IN-SERVICE DATE:	01/07/2020						
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma									
				UNIT SERIAL NO:	5TFRX5GN9LX172458						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$767.82	\$0.00	\$767.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:					0.00	0.00	767.82	5.00	772.82
--------------	-------------------	--	--	--	--	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.56	4	\$18.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	187.40	4	\$749.58
PARTS						767.82

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 53506

Work Order Notes

(EHANNAH) pm- SI- wash
(GARAGE) not due for PM until 5/22/25

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) Front end was checked per CM

66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment cm 29917 miles test drove checked ok,

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) GC,CM- mounted and balanced 4 new tires on unit 2908C
Miles, 29,917

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 54794

USING DEPT NO:	504103	OPENED DATE:	05/15/2025 10:39:26	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/15/2025 12:32:51	METER 1 - M:	31443	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/16/2025 10:56:26	IN-SERVICE DATE:	01/07/2020						
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma									
				UNIT SERIAL NO:	5TFRX5GN9LX172458						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$50.39	\$0.00	\$50.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:					0.00	0.00	50.39	5.00	55.39
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	11.96	1	\$11.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
PARTS						50.39

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 54794

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) blades checked ok, cm

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm cm bottom side jr top side, changed motor oil and filter,, topped off all fluids tires filters checked ok, 31443 miles,

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) wash bay down

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 56383

USING DEPT NO:	504103	OPENED DATE:	09/15/2025 10:14:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/17/2025 08:05:34	METER 1 - M:	33077	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/17/2025 12:27:12	IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-001	REPLACE NEW HEADLAMPS	DON	N	N	GARAGE	0.00	\$0.00	\$18.84	\$0.00	\$18.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	18.84	5.00	23.84
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	18.84	1	\$18.84
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	18.84	(1)	(\$18.84)
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	18.84	1	\$18.84
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	18.84	(1)	(\$18.84)
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	18.84	1	\$18.84
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	18.84	(1)	(\$18.84)
03-34-001	REPLACE NEW HEADLAMPS	H11BX	H11 BULB	18.84	1	\$18.84
					PARTS	18.84

Work Order Charge Detail

UNIT NO:	243636	2020 TOYOTA TACOMA	WORK ORDER NO:	56383
----------	--------	--------------------	----------------	-------

Work Order Notes

(EHANNAH) REPLACE NEW HEADLIGHT

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 56882

USING DEPT NO:	504103	OPENED DATE:	10/21/2025 07:24:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	COMPLETED	COMPLETED DATE:	10/21/2025 08:43:17	METER 1 - M:	33530	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	01/07/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN9LX172458	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	150.00	0.00	0.00	150.00
--------------	-------------------	------	--------	------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	10/21/2025 08:43:06	10/21/2025 09:43:06	1.00	\$150.00
					LABOR	150.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/21/2025 12:10:15 By User: GLOBETTI

UNIT NO: 243636 2020 TOYOTA TACOMA

WORK ORDER NO: 56882

Work Order Notes

(EKIMBREL) prep for sale/ remove GPS

Job Notes

25-52-021 - REMOVE GPS SYSTEM

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) CM PERFORMED PREP FOR SALE. NO GPS

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Oct 21 2025 12:10:15 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243636') //Q=