

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 10640

USING DEPT NO:	600202	OPENED DATE:	03/26/2012 14:30:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/29/2012 06:51:09	METER 1 - M:	11068	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2012 06:51:11	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$35.33	\$32.66	\$0.00	\$67.99

JOB COUNT: 1	WORK ORDER TOTAL:	0.61	35.33	32.66	0.00	67.99
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10260422	03/27/2012 09:30:00	03/27/2012 10:28:06	(0.97)	(\$55.68)
66-PM-PMA	PERFORM OIL CHANGE	10260422	03/27/2012 09:30:00	03/27/2012 10:28:06	0.97	\$55.68
66-PM-PMA	PERFORM OIL CHANGE	11413680	03/27/2012 08:15:13	03/27/2012 11:17:36	3.04	\$174.78
66-PM-PMA	PERFORM OIL CHANGE	11413680	03/27/2012 08:15:13	03/27/2012 11:17:36	(3.04)	(\$174.78)
66-PM-PMA	PERFORM OIL CHANGE	11413680	03/27/2012 08:15:13	03/27/2012 08:17:37	0.04	\$2.30
66-PM-PMA	PERFORM OIL CHANGE	10260422	03/27/2012 08:40:32	03/27/2012 09:15:00	0.57	\$33.03
					LABOR	35.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.38	1	\$4.38
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	5	\$28.28
					PARTS	32.66

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 10640

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 160 Cost 0

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1516 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY GM/RT

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 11524

USING DEPT NO:	600202	OPENED DATE:	08/02/2012 08:55:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/03/2012 06:53:23	METER 1 - M:	11302	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2012 06:53:26	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$33.48	\$0.00	\$47.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$32.73	\$43.27	\$0.00	\$76.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.82	47.11	76.75	0.00	123.86
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/02/2012 10:13:21	08/02/2012 10:38:33	0.42	\$24.15
03-51-038	REPLACE NEW WIPER BLADES	11413680	08/02/2012 11:38:35	08/02/2012 11:53:35	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/02/2012 10:13:21	08/02/2012 11:38:35	(1.42)	(\$81.68)
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/02/2012 10:13:21	08/02/2012 11:38:35	1.42	\$81.68
66-PM-PMA	PERFORM OIL CHANGE	11338644	08/02/2012 10:55:02	08/02/2012 11:03:59	0.15	\$8.58
					LABOR	47.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.38	1	\$4.38
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	5	\$28.28
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	1	\$16.74
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	(1)	(\$16.74)
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	2	\$33.48
					PARTS	76.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 11524

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 160 Cost 0

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1516 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY RS-REPLACED OIL DRAIN PLUG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 12855

USING DEPT NO:	600202	OPENED DATE:	01/23/2013 11:28:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2013 09:25:59	METER 1 - M:	12855	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/24/2013 09:26:00	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$55.76	\$0.00	\$73.59

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	55.76	0.00	73.59
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/24/2013 07:00:00	01/24/2013 07:18:36	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.09	1	\$12.09
					PARTS	55.76

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 12855

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.7675

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.24

(LPATE) PM BY SH/RS-REPLACED OIL DRAIN PLUG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 13673

USING DEPT NO:	600202	OPENED DATE:	05/01/2013 09:30:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2013 07:14:37	METER 1 - M:	118456	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2013 07:14:39	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$30.72	\$61.12	\$0.00	\$91.84

JOB COUNT: 1	WORK ORDER TOTAL:	0.53	30.72	61.12	0.00	91.84
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11413680	05/01/2013 09:44:04	05/01/2013 10:16:07	0.53	\$30.72
					LABOR	30.72

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	5	\$28.35
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.19	1	\$5.19
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
					PARTS	61.12

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 13673

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.7675

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.24

(LPATE) PM BY RT/SH-REPLACED OIL DRAIN PLUG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 14709

USING DEPT NO:	600202	OPENED DATE:	08/22/2013 13:45:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2013 11:29:16	METER 1 - M:	12194	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2013 11:29:17	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-42-016	PERFORM FLUSH COOLING SYSTEM	DON	P	N	GARAGE	1.00	\$57.50	\$41.40	\$0.00	\$98.90
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.65	\$45.67	\$0.00	\$81.32

JOB COUNT: 2	WORK ORDER TOTAL:	1.62	93.15	87.07	0.00	180.22
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2013 06:00:00	08/23/2013 06:18:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	10260422	08/23/2013 06:00:00	08/23/2013 06:18:36	0.31	\$17.83
66-42-016	PERFORM FLUSH COOLING SYSTEM	11074414	08/23/2013 06:18:36	08/23/2013 07:18:36	1.00	\$57.50
					LABOR	93.16

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	5	\$28.35
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GREEN	ANTIFREEZE-GREEN	16.80	1	\$16.80
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GREEN	ANTIFREEZE-GREEN	16.80	(1)	(\$16.80)
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GREEN	ANTIFREEZE-GREEN	16.80	1	\$16.80
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GREEN	ANTIFREEZE-GREEN	16.80	(1)	(\$16.80)
66-42-016	PERFORM FLUSH COOLING SYSTEM	ANTIFREEZE GREEN	ANTIFREEZE-GREEN	16.74	2	\$33.48
66-42-016	PERFORM FLUSH COOLING SYSTEM	WATER	DISTILLED WATER	1.32	6	\$7.92
					PARTS	87.07

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 14709

Work Order Notes

(LPATE) PM

Job Notes

66-42-016 - PERFORM FLUSH COOLING SYSTEM

(GMANNING) COOLANT WAS DISCOLORED. FLUSHED RADIATOR 3 TIMES WITH WATER UNTIL CLEAR. FILLED WITH NEW COOLANT. RECHECKED OK.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.7675

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.24

(GMANNING) PM BY GM/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 1487

USING DEPT NO:	600202	OPENED DATE:	06/10/2008 10:46:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2008 10:52:00	METER 1 - M:	7612	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2008 10:52:03	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-06-002	RECALL ACTIVATE/DEACTIVATE SWITC	DON	R	N	GARAGE	0.25	\$11.25	\$0.00	\$0.00	\$11.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$32.76	\$0.00	\$46.71

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	25.20	32.76	0.00	57.96
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11089300	06/10/2008 10:47:00	06/10/2008 11:05:36	0.31	\$13.95
17-06-002	RECALL ACTIVATE/DEACTIVATE SWITCHES	11128904	06/10/2008 10:47:00	06/10/2008 11:02:00	0.25	\$11.25
					LABOR	25.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	160	\$16.80
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	7.02	1	\$7.02
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	8.94	1	\$8.94
					PARTS	32.76

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 1487

Work Order Notes

(RWINTERS) PM AND RECALL ON CRUISE CONTROL FUSED WIRING.

Job Notes

17-06-002 - RECALL ACTIVATE/DEACTIVATE SWITCHES

(RWINTERS) RECALL 05S28 PERFORMED AT GARAGE. MADDEN SUPPLIED PARTS. INSTALLED NEW JUMPER HARNESS.

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) PM BY MS

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 16761

USING DEPT NO:	600202	OPENED DATE:	04/28/2014 10:10:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/29/2014 06:43:00	METER 1 - M:	12330	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2014 06:43:04	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:					1.00	57.50	0.00	0.00	57.50
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11268671	04/28/2014 10:11:22	04/28/2014 11:11:22	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 16761

Work Order Notes

(LPATE) DON REQUESTED A SERVICE CALL TO PAUL BRYANT ACROSS FROM MARTHA PARHAM FOR A DEAD BATTERY

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LPATE) JUMPED OFF TRUCK ALT IS CHARGING DRIVER WILL LEAVE RUNNING AND DRIVE SOME TODAY TO RECHARGE BATTERY.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 16779

USING DEPT NO:	600202	OPENED DATE:	04/29/2014 13:13:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/01/2014 07:02:14	METER 1 - M:	12354	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/01/2014 07:02:16	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.95	\$0.00	\$51.78

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	33.95	0.00	51.78
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11568366	04/30/2014 07:00:00	04/30/2014 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	5	\$28.80
					PARTS	33.95

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 16779

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.78

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.24

(LPATE) PM BY CA

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 17130

USING DEPT NO:	600202	OPENED DATE:	05/29/2014 11:41:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2014 10:25:41	METER 1 - M:	12381	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2014 10:25:41	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$69.31	\$0.00	\$98.06
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	69.31	0.00	126.81
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-32	DIAGNOSE CRANKING SYSTEM	11397026	05/30/2014 07:00:00	05/30/2014 07:30:00	0.50	\$28.75
03-32-002	REPLACE NEW BATTERY	11397026	05/30/2014 07:30:00	05/30/2014 08:00:00	0.50	\$28.75
					LABOR	57.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	58A	BATTERY TOP POST FORD	69.31	1	\$69.31
					PARTS	69.31

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 17130

Work Order Notes

(LPATE) CHECK BATTERY AND STARTER AFTER SITS A FEW DAYS JUST CLICKS EVENTUALLY WILL CRANK

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED THE BATTERY AND RECHECKED EVERYTHING OK

35-32 - DIAGNOSE CRANKING SYSTEM

(LPATE) CHECKED OUT-CHECKED CHARGING SYSTEM, CHECKED GOOD TESTED BATTERY, THE BATTERY TESTED BAD

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 18396

USING DEPT NO:	600202	OPENED DATE:	10/10/2014 14:23:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2014 10:51:08	METER 1 - M:	12537	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2014 10:51:10	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.95	\$0.00	\$51.78

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	33.95	0.00	51.78
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10260422	10/10/2014 14:42:36	10/10/2014 15:01:12	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	10260422	10/10/2014 14:42:36	10/13/2014 07:24:21	(64.70)	(\$3,720.01)
66-PM-PMA	PERFORM OIL CHANGE	10260422	10/10/2014 14:42:36	10/13/2014 07:24:21	64.70	\$3,720.01
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	5	\$28.80
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.15	1	\$5.15
					PARTS	33.95

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 18396

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.78

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.24

(LPATE) PM BY GM

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 1968

USING DEPT NO:	600202	OPENED DATE:	09/11/2008 11:46:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2008 11:51:02	METER 1 - M:	7755	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/11/2008 11:51:04	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	1.00	\$45.00	\$0.00	\$0.00	\$45.00

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	45.00	0.00	0.00	45.00
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11088474	09/11/2008 11:47:00	09/11/2008 12:47:00	1.00	\$45.00
					LABOR	45.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 1968

Work Order Notes

(AJONES) SERVICE CALL TRUCK RAN OUT OF GAS.

Job Notes

66-79-002 - PERFORM SERVICE CALL

(AJONES) JASON RESPONDED TO SERVICE CALL TRUCK RAN OUT OF GAS AT THE INTERSECTION NEAR CALVERY ANNEX

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 20082

USING DEPT NO:	600202	OPENED DATE:	04/22/2015 13:05:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/27/2015 10:05:25	METER 1 - M:	12823	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2015 10:05:29	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	0.60	\$34.50	\$105.41	\$0.00	\$139.91
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$25.44	\$0.00	\$39.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$27.01	\$0.00	\$44.84

JOB COUNT: 3	WORK ORDER TOTAL:	1.16	66.71	157.86	0.00	224.57
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10260422	04/23/2015 06:00:00	04/23/2015 06:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	10260422	04/23/2015 06:18:36	04/23/2015 06:33:36	0.25	\$14.38
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	10337093	04/23/2015 07:00:00	04/23/2015 07:36:00	0.60	\$34.50
					LABOR	66.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.19	1	\$5.19
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	15.90	2	\$31.80
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	3156	BULB-BACK UP	2.04	1	\$2.04
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	3157	BULB-BRAKE/TURN/PARK	0.75	1	\$0.75
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	1L5Z13404BA	RH TAILLAMP ASSY	129.00	1	\$129.00
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.52	5	\$22.62
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	(5)	(\$28.20)
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	12.72	2	\$25.44
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	15.90	(2)	(\$31.80)
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	3156	BULB-BACK UP	1.63	1	\$1.63
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	3156	BULB-BACK UP	2.04	(1)	(\$2.04)
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.19	(1)	(\$5.19)
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.39	1	\$4.39
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	3157	BULB-BRAKE/TURN/PARK	0.58	1	\$0.58

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	3157	BULB-BRAKE/TURN/PARK	0.75	(1)	(\$0.75)
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	1L5Z13404BA	RH TAILLAMP ASSY	103.20	1	\$103.20
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	1L5Z13404BA	RH TAILLAMP ASSY	129.00	(1)	(\$129.00)
					PARTS	157.86

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 20082

Work Order Notes

(LPATE) PM-REPLACE WIEPRS-RIGHT REAR TAILLIGHT ASSY IS BROKEN

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(LPATE) REPLACED RIGHT REAR TAILLIGHT ASSY AND BOTH BULBS. RECHECKED OK

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.78

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.24

(LPATE) PM BY AY,DS/GM

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 20888

USING DEPT NO:	600202	OPENED DATE:	07/24/2015 13:16:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2015 08:37:21	METER 1 - M:	13104	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/28/2015 08:37:22	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.59	\$0.00	\$17.84

JOB COUNT: 1	WORK ORDER TOTAL:					0.30	17.25	0.59	0.00	17.84
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11397026	07/24/2015 13:17:09	07/24/2015 13:35:09	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.59	1	\$0.59
					PARTS	0.59

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 20888

Work Order Notes

(LPATE) LEFT TAILLIGHT OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT TAILLIGHT

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 21341

USING DEPT NO:	600202	OPENED DATE:	09/08/2015 14:02:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/10/2015 08:17:00	METER 1 - M:	13279	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/10/2015 08:17:02	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$23.58	\$25.30	\$0.00	\$48.88

JOB COUNT: 1	WORK ORDER TOTAL:	0.41	23.58	25.30	0.00	48.88
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2015 14:34:34	09/09/2015 05:59:10	15.41	\$886.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2015 14:34:34	09/09/2015 05:59:10	(15.41)	(\$886.08)
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2015 14:34:34	09/08/2015 14:59:10	0.41	\$23.58
					LABOR	23.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.34	1	\$3.34
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.51	5	\$22.56
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.43	1	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.78	1	\$2.78
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.34	(1)	(\$3.34)
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	5	\$18.80
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.51	(5)	(\$22.56)
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	3.72	1	\$3.72
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.43	(1)	(\$4.43)
					PARTS	25.30

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 21341

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.780000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 23177

USING DEPT NO:	600202	OPENED DATE:	04/21/2016 14:10:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/04/2016 11:31:40	METER 1 - M:	14075	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/04/2016 11:31:42	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$46.00	\$2.07	\$0.00	\$48.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$22.53	\$0.00	\$40.36
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$416.67	\$416.67

JOB COUNT: 3	WORK ORDER TOTAL:	1.11	63.83	24.60	416.67	505.10
--------------	-------------------	------	-------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	209325	0033194	\$416.67
				COMML	416.67

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	04/29/2016 07:00:00	04/29/2016 07:18:36	0.31	\$17.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	04/29/2016 07:00:00	04/29/2016 07:48:00	0.80	\$46.00
				LABOR		63.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	5	\$18.80
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	3.73	1	\$3.73
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	5	\$1.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.18	4	\$0.72
				PARTS		24.60

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 23177

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNTED AND BALANCED 4 NEW TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 5 Cost 3.780000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM BY CS

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 4 NEW TIRES FROM FIRESTONE. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 23865

USING DEPT NO:	600202	OPENED DATE:	07/12/2016 08:38:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2016 15:03:17	METER 1 - M:	14271	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2016 15:03:19	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-053	INSPECT WINDOW REGULATOR	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-053	INSPECT WINDOW REGULATOR	10337093	07/13/2016 07:00:00	07/13/2016 07:30:00	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 23865

Work Order Notes

(LISAPATE) DRIVER WINDOW MAKING A LOUD POP WHEN GONG UP AND DOWN

Job Notes

06-02-053 - INSPECT WINDOW REGULATOR

(LISAPATE) FOUND DOOR HANDLE CLIP WAS BROKEN AND CATCHING WHEN ROLLING UP AND DOWN. SECURED LOOSE WIRE WITH TIE STRAP. RECHECKED OK

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 24606

USING DEPT NO:	600202	OPENED DATE:	10/12/2016 13:49:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2016 14:29:23	METER 1 - M:	14839	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2016 14:29:25	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.81	\$46.72	\$26.30	\$0.00	\$73.02

JOB COUNT: 1	WORK ORDER TOTAL:	0.81	46.72	26.30	0.00	73.02
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2016 14:30:00	10/12/2016 15:18:45	0.81	\$46.72
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2016 14:27:12	10/12/2016 14:27:12	0.00	\$0.00
					LABOR	46.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	6253	FILTER- AIR	4.97	1	\$4.97
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	3.73	1	\$3.73
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.11	160	\$17.60
					PARTS	26.30

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 24606

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM BY CS/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 26294

USING DEPT NO:	600202	OPENED DATE:	05/05/2017 08:57:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2017 13:13:32	METER 1 - M:	15565	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/17/2017 13:13:33	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$15.44	\$0.00	\$33.27

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	15.44	0.00	33.27
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	05/05/2017 11:47:20	05/05/2017 12:05:56	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	160	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	3.72	1	\$3.72
					PARTS	15.44

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 26294

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM BY AB

COOLANT -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 27697

USING DEPT NO:	600202	OPENED DATE:	10/05/2017 10:50:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2017 11:28:52	METER 1 - M:	15700	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2017 11:28:53	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.26	\$14.69	\$47.00	\$0.00	\$61.69
03-34-013	REPLACE NEW FLASHER	DON	O	N	GARAGE	0.30	\$17.25	\$16.73	\$0.00	\$33.98
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$36.66	\$15.45	\$0.00	\$52.11

JOB COUNT: 4	WORK ORDER TOTAL:	2.19	126.10	79.18	0.00	205.28
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	10/06/2017 07:39:27	10/06/2017 07:54:47	0.26	\$14.69
66-79-002	PERFORM SERVICE CALL	11268671	10/09/2017 07:00:00	10/09/2017 08:00:00	1.00	\$57.50
03-34-013	REPLACE NEW FLASHER	11170580	10/09/2017 07:00:00	10/09/2017 07:18:00	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/06/2017 07:01:02	10/06/2017 07:39:17	0.64	\$36.66
					LABOR	126.10

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	160	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	3.73	1	\$3.73
03-32-002	REPLACE NEW BATTERY	58	BATTERY BCI 58 550 CCA	47.00	1	\$47.00
03-34-013	REPLACE NEW FLASHER	STIEFL4	FLASHER	16.73	1	\$16.73
					PARTS	79.18

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 27697

Work Order Notes

(LISAPATE) BRETT REQUESTED A SERVICE CALL TO MARTHA PARHAM FOR A DEAD BATTERY-PM DUE

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) REMOVED AND INSTALLED NEW BATTERY

03-34-013 - REPLACE NEW FLASHER

(LISAPATE) FOUND FLASHER RELAY WAS BAD. INSTALLED NEW RELAY. RECHECKED OK

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED JUMPED OFF BROUGHT TO THE GARAGE

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 29355

USING DEPT NO:	600202	OPENED DATE:	04/09/2018 11:21:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2018 13:19:42	METER 1 - M:	15705	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2018 13:19:43	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$13.72	\$0.00	\$31.55
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 3	WORK ORDER TOTAL:	1.81	104.08	13.72	0.00	117.80
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11901357	04/10/2018 08:18:36	04/10/2018 08:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/10/2018 07:00:00	04/10/2018 07:18:36	0.31	\$17.83
66-79-002	PERFORM SERVICE CALL	11901357	04/10/2018 07:18:36	04/10/2018 08:18:36	1.00	\$57.50
					LABOR	104.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	3.72	1	\$3.72
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.00	5	\$10.00
					PARTS	13.72

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 29355

Work Order Notes

(LISAPATE) ALLISON REQUESTED A SERVICE CALL TO MAGNOLIA PARKING DECK FOR A DEAD BATTERY

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED. JUMPED OFF AND DROVE TO THE GARAGE

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM BY RC/AG

COOLANT -35'

CH-32-002 - CHARGE BATTERY

(LISAPATE) CHARGED BATTERY OVERNIGHT. BATTERY CHECKED GOOD. CHARGING SYSTEM CHECKED AT 14.4 VOLTS GOOD

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 31198

USING DEPT NO:	600202	OPENED DATE:	10/17/2018 15:53:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/05/2019 06:15:49	METER 1 - M:	15718	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2019 06:15:55	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	2.26	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	O	N	GARAGE	3.83	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	6.09	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11758845	10/19/2018 11:09:45	10/22/2018 09:15:00	70.09	\$0.00
66-79-002	PERFORM SERVICE CALL	11758845	10/22/2018 09:30:00	10/22/2018 11:45:28	2.26	\$0.00
66-79-002	PERFORM SERVICE CALL	11758845	10/19/2018 11:09:45	10/22/2018 09:15:00	(70.09)	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	10/19/2018 07:01:42	10/19/2018 10:51:20	3.83	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 31198

Work Order Notes

(EKIMBREL) service call dead battery. prep for sale
(EKIMBREL) Safety Inspection

Job Notes

66-79-002 - PERFORM SERVICE CALL

(EKIMBREL) Jumped vehicle off and drove to shop.

66-79-003 - PERFORM SAFETY INSPECTION

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 32521

USING DEPT NO:	600202	OPENED DATE:	04/03/2019 11:09:56	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2019 14:25:10	METER 1 - M:	15726	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2019 14:25:12	IN-SERVICE DATE:	10/01/2001				
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger							
			UNIT SERIAL NO:	1FTYR14V81TA99719					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-065	REPLACE NEW WINDOW SEAL STRIP	DON	O	N	GARAGE	0.40	\$29.00	\$112.74	\$0.00	\$141.74
03-06-002	REPLACE NEW ACTIVATE/DEACTIVATE	DON	O	N	GARAGE	1.68	\$121.80	\$117.57	\$0.00	\$239.37
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.87	\$207.73	\$303.06	\$0.00	\$510.79
03-16-003	REPLACE NEW FRONT SHOCK ABSORBI	DON	O	N	GARAGE	0.36	\$25.98	\$105.60	\$0.00	\$131.58
03-16-006	REPLACE NEW REAR SHOCK ABSORB	DON	O	N	GARAGE	0.77	\$55.87	\$93.66	\$0.00	\$149.53
03-16-011	REPLACE NEW SWAY BAR END LINK(S	DON	O	N	GARAGE	0.70	\$50.75	\$27.00	\$0.00	\$77.75
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$36.25	\$123.60	\$0.00	\$159.85
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	0.30	\$21.75	\$65.05	\$0.00	\$86.80
03-42-002	REPLACE NEW RADIATOR	DON	O	N	GARAGE	0.90	\$65.25	\$213.27	\$0.00	\$278.52
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	O	N	GARAGE	0.50	\$36.25	\$38.29	\$0.00	\$74.54
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-16	ALIGN SUSPENSION	DON	O	N	GARAGE	1.01	\$73.23	\$0.00	\$0.00	\$73.23
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/A	DON	O	N	GARAGE	1.00	\$72.50	\$34.17	\$0.00	\$106.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$27.78	\$0.00	\$50.26

JOB COUNT: 14	WORK ORDER TOTAL:	11.79	855.09	1,261.79	0.00	2,116.88
---------------	-------------------	-------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	11310047	04/12/2019 14:49:09	04/12/2019 15:10:39	0.36	\$25.98
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	11310047	04/15/2019 07:16:35	04/15/2019 08:02:49	0.77	\$55.87
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	04/15/2019 08:03:25	04/15/2019 08:29:07	0.43	\$31.05
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	04/15/2019 08:54:57	04/15/2019 09:22:15	0.46	\$32.99
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	04/15/2019 10:46:10	04/15/2019 11:54:59	1.15	\$83.15
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	04/15/2019 13:00:28	04/15/2019 13:50:34	0.84	\$60.54
03-06-002	REPLACE NEW ACTIVATE/DEACTIVATE SWITCHES	11310047	04/15/2019 13:51:18	04/16/2019 07:31:58	17.68	\$1,281.64

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-06-002	REPLACE NEW ACTIVATE/DEACTIVATE SWITCHES	11310047	04/15/2019 13:51:18	04/16/2019 07:31:58	(17.68)	(\$1,281.64)
03-06-002	REPLACE NEW ACTIVATE/DEACTIVATE SWITCHES	11310047	04/15/2019 13:51:18	04/15/2019 15:32:06	1.68	\$121.80
09-16	ALIGN SUSPENSION	11310047	04/17/2019 13:45:58	04/17/2019 14:46:34	1.01	\$73.23
03-02-065	REPLACE NEW WINDOW SEAL STRIP	11310047	04/19/2019 07:30:00	04/19/2019 07:54:00	0.40	\$29.00
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	11074414	04/19/2019 06:30:00	04/19/2019 06:48:00	0.30	\$21.75
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	11310047	04/19/2019 07:00:00	04/19/2019 07:30:00	0.50	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/19/2019 06:00:00	04/19/2019 06:18:36	0.31	\$22.48
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	11310047	04/19/2019 07:00:00	04/19/2019 08:00:00	1.00	\$72.50
06-15	INSPECT STEERING	11310047	04/19/2019 08:00:00	04/19/2019 08:30:00	0.50	\$36.25
03-32-002	REPLACE NEW BATTERY	11074414	04/19/2019 06:00:00	04/19/2019 06:30:00	0.50	\$36.25
09-16	ALIGN SUSPENSION	11310047	04/17/2019 13:45:58	04/18/2019 08:46:40	(19.01)	(\$1,378.35)
09-16	ALIGN SUSPENSION	11310047	04/17/2019 13:45:58	04/18/2019 08:46:40	19.01	\$1,378.35
03-16-011	REPLACE NEW SWAY BAR END LINK(S)	11310047	04/12/2019 14:34:43	04/12/2019 14:48:44	0.00	\$0.00
03-16-011	REPLACE NEW SWAY BAR END LINK(S)	11310047	04/12/2019 14:34:43	04/12/2019 14:48:44	0.00	\$0.00
03-16-011	REPLACE NEW SWAY BAR END LINK(S)	11310047	04/12/2019 14:34:43	04/12/2019 15:16:43	0.70	\$50.75
03-42-002	REPLACE NEW RADIATOR	11310047	04/12/2019 14:30:00	04/12/2019 14:34:16	0.00	\$0.00
03-42-002	REPLACE NEW RADIATOR	11310047	04/12/2019 14:30:00	04/12/2019 14:34:16	0.00	\$0.00
03-42-002	REPLACE NEW RADIATOR	11310047	04/12/2019 14:30:00	04/12/2019 15:24:00	0.90	\$65.25
03-42-002	REPLACE NEW RADIATOR	11310047	04/12/2019 13:04:31	04/12/2019 14:15:00	0.00	\$0.00

LABOR 855.09

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	58	BATTERY BCI 58 550 CCA	82.40	1	\$82.40
03-32-002	REPLACE NEW BATTERY	58	BATTERY BCI 58 550 CCA	123.60	1	\$123.60
03-32-002	REPLACE NEW BATTERY	58	BATTERY BCI 58 550 CCA	82.40	(1)	(\$82.40)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	3.17	1	\$3.17
03-42-002	REPLACE NEW RADIATOR	ANTIFREEZE GREEN	ANTIFREEZE-GREEN	13.34	3	\$40.01
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABEHT652H	BRAKE PADS	63.97	1	\$63.97
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS19223	OIL SEAL	13.32	2	\$26.64
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB66672R	BRAKE ROTOR/HUB	68.31	2	\$136.62

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR5	FRONT INNER BEARING	11.94	2	\$23.88
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	DOR13973	BEARING DUST CAP	8.87	2	\$17.73
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR2	OUTER WHEEL BEARING	9.87	2	\$19.74
03-16-011	REPLACE NEW SWAY BAR END LINK(S)	TRWJTS653	SWAY BAR LINKS	13.50	2	\$27.00
03-42-002	REPLACE NEW RADIATOR	2557	RADIATOR	183.17	1	\$183.17
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	25060882	BELT	38.29	1	\$38.29
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	344397	SHOCK ABSORBER KYB FRONT	52.80	2	\$105.60
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	344396	SHOCK ABSORBER KYB REAR	46.83	2	\$93.66
03-06-002	REPLACE NEW ACTIVATE/DEACTIVATE SWITCHES	73075621	CRUISE CONTROL ACTIVATE SWITCH	117.57	1	\$117.57
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	6801341	TAIL LAMP ASSEMBLY LH	65.05	1	\$65.05
03-02-065	REPLACE NEW WINDOW SEAL STRIP	6L5Z1021452AA	WEATHERSTRIP	56.31	1	\$56.31
03-02-065	REPLACE NEW WINDOW SEAL STRIP	6L5Z1021453AA	WEATHERSTRIP	56.43	1	\$56.43
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	FBR5B66597	BRAKE ROTOR / HUB ASSY	73.97	2	\$147.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB66672R	BRAKE ROTOR/HUB	68.31	(2)	(\$136.62)
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	2642953	ECCENTRIC CAM BOLT KIT	34.17	1	\$34.17
03-42-002	REPLACE NEW RADIATOR	PIGMAT	OIL ABSORMENT MAT	1.03	1	\$1.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	5	\$22.20
03-42-002	REPLACE NEW RADIATOR	2557	RADIATOR	183.17	(1)	(\$183.17)
03-42-002	REPLACE NEW RADIATOR	2557	RADIATOR	172.23	1	\$172.23
					PARTS	1261.79

Work Order Charge Detail

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 32521

Work Order Notes

(IFALLS) Vehicle purchased by Athletic Main per Jon Dever complete all repairs quoted.

Job Notes

Work Order Charge Detail

03-02-065 - REPLACE NEW WINDOW SEAL STRIP

(LISAPATE) Replaced left and right window moldings

03-06-002 - REPLACE NEW ACTIVATE/DEACTIVATE SWITCHES

(LISAPATE) Replaced steering wheel cruise control switch

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) Repalced front pads and rotors, packed new wheel bearings with grease, installed new wheel seals

03-16-003 - REPLACE NEW FRONT SHOCK ABSORBERS

(LISAPATE) Installed new front shocks

03-16-006 - REPLACE NEW REAR SHOCK ABSORBER

(LISAPATE) Installed new rear shocks

03-16-011 - REPLACE NEW SWAY BAR END LINK(S)

(LISAPATE) Replaced sway bar links

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Installed new battery

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(LISAPATE) Replaced tail light assy

03-42-002 - REPLACE NEW RADIATOR

(LISAPATE) Replaced radiator added new coolant. Rechecked ok

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(LISAPATE) Installed new belt

06-15 - INSPECT STEERING

(LISAPATE) EH Checked front end parts. Time removed due to not quoted to dept on repair

09-16 - ALIGN SUSPENSION

(LISAPATE) EH Performed alignment

14-15-026 - INSTALL CAM/CONTROL ARM BOLT W/WASHER

(LISAPATE) Installed cam bolts while doing the alignment

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) Visit Reason Changed On 4/19/2019 9:14 AM By LISAPATE

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

(RTUNAITI)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM by AG,SH/SH

Coolant 0'

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 32751

USING DEPT NO:	600202	OPENED DATE:	04/26/2019 14:04:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/01/2019 07:48:13	METER 1 - M:	15726	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/01/2019 07:48:15	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EX	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
RS-02-063	RESEAL REAR WINDOW/BACK GLASS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$172.50	\$172.50

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	36.25	0.00	172.50	208.75
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
RS-02-063	RESEAL REAR WINDOW/BACK GLASS	11078716	263379	0047801	\$172.50
				COMML	172.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	10208562	04/30/2019 07:00:00	04/30/2019 07:30:00	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 32751

Work Order Notes

(LISAPATE) Back glass is leaking water

(LISAPATE) Left rear taillight assy was charged on previous WO 32521 was not installed. EK removed and installed.

Job Notes

35-71-032 - DIAGNOSE WATER LEAK INTERIOR/EXTERIOR

(LISAPATE) verified water leaking from seal around back glass call for glass dr

RS-02-063 - RESEAL REAR WINDOW/BACK GLASS

(LISAPATE) Glass Dr came and removed then resealed back glass. Pd by CC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 32898

USING DEPT NO:	600202	OPENED DATE:	05/13/2019 10:02:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2019 14:30:44	METER 1 - M:	15857	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/23/2019 14:30:46	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	1.70	\$123.25	\$175.68	\$0.00	\$298.93
06-02-023	INSPECT HANDLES - INNER & OUTER	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EX	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 3	WORK ORDER TOTAL:	2.70	195.75	175.68	0.00	371.43
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11268671	05/22/2019 07:00:00	05/22/2019 07:54:00	0.90	\$65.25
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11268671	05/22/2019 07:00:00	05/22/2019 07:54:00	(0.90)	(\$65.25)
06-02-023	INSPECT HANDLES - INNER & OUTER	11170580	05/22/2019 07:00:00	05/22/2019 07:30:00	0.50	\$36.25
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11170580	05/22/2019 07:30:00	05/22/2019 08:00:00	0.50	\$36.25
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11170580	05/22/2019 07:00:00	05/22/2019 08:42:00	1.70	\$123.25
					LABOR	195.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	7L5Z1326604AA	HANDLE REAR RH EXT W/CABLE	57.45	1	\$57.45
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	AL5Z13264A26B	LATCH REAR RH UPPER W/CABLE	118.23	1	\$118.23
					PARTS	175.68

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 32898

Work Order Notes

(LISAPATE) Rear window is leaking again-3rd brake light was replaced and glass was resealed a few weeks ago. Also passenger side rear door wont open

Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(LISAPATE) AB Installed new upper latch assy and door handle assy, new upper latch would not stay latched. IF installed another new upper latch . Rechecked ok

06-02-023 - INSPECT HANDLES - INNER & OUTER

(LISAPATE) Found RR door latch broken.

35-71-032 - DIAGNOSE WATER LEAK INTERIOR/EXTERIOR

(LISAPATE) Glass Dr came and resealed rear glass again at not charge. Water tested no other leaks found at this time

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 33572

USING DEPT NO:	600202	OPENED DATE:	07/29/2019 15:40:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2019 13:08:59	METER 1 - M:	16218	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/06/2019 13:09:02	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CU-51-046	CUT KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$59.94	\$0.00	\$59.94
PR-51-046	PROGRAM KEY BLANK(S)	DON	O	N	GARAGE	0.46	\$33.05	\$0.00	\$0.00	\$33.05

JOB COUNT: 2	WORK ORDER TOTAL:	0.46	33.05	59.94	0.00	92.99
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PR-51-046	PROGRAM KEY BLANK(S)	11170580	07/31/2019 10:42:19	07/31/2019 11:09:40	0.46	\$33.05
					LABOR	33.05

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
CU-51-046	CUT KEY BLANK(S)	164R8040	FORD PATS GEN2 KEYBLANK	59.94	1	\$59.94
					PARTS	59.94

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 33572

Work Order Notes

(EKIMBREL) Cut 1 key & program.

Job Notes

CU-51-046 - CUT KEY BLANK(S)

(EKIMBREL) AB cut 1 key.

PR-51-046 - PROGRAM KEY BLANK(S)

(EKIMBREL) AB programmed 1 key.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 34125

USING DEPT NO:	600202	OPENED DATE:	09/17/2019 09:39:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2019 07:35:14	METER 1 - M:	16448	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2019 07:35:15	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$46.68	\$27.71	\$0.00	\$74.39
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.32	\$23.40	\$0.00	\$0.00	\$23.40

JOB COUNT: 2	WORK ORDER TOTAL:	0.97	70.08	27.71	0.00	97.79
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	09/23/2019 08:44:17	09/23/2019 09:03:39	0.32	\$23.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/17/2019 10:53:10	09/17/2019 11:31:48	0.64	\$46.68
					LABOR	70.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	5	\$22.13
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	(7)	(\$31.08)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
					PARTS	27.71

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 34125

Work Order Notes

(LISAPATE) PM-Check engine light on-running ok-came on this morning

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(LISAPATE) PM by SH

Coolant -50'

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan Out- IDS-P0460 Fuel level sensor A current (History)

Found codes stored in history. Checked all connections and scan tool data no issues at this time.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 35713

USING DEPT NO:	600202	OPENED DATE:	02/20/2020 09:44:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2020 15:15:02	METER 1 - M:	17176	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/02/2020 15:15:04	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-71-032	INSPECT WATER LEAK INTERIOR/EXTE	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.03	\$74.94	\$27.71	\$0.00	\$102.65

JOB COUNT: 2	WORK ORDER TOTAL:	1.53	111.19	27.71	0.00	138.90
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-00	INSPECT COMPLETE VEHICLE	11074414	02/26/2020 14:17:09	02/26/2020 15:26:29	1.16	\$83.78
06-71-032	INSPECT WATER LEAK INTERIOR/EXTERIOR	11074414	02/28/2020 06:00:00	02/28/2020 06:30:00	0.50	\$36.25
06-00	INSPECT COMPLETE VEHICLE	11074414	02/26/2020 14:17:09	02/26/2020 15:26:29	(1.16)	(\$83.78)
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/20/2020 14:50:00	02/20/2020 15:52:01	1.03	\$74.94
					LABOR	111.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	5	\$22.13
					PARTS	27.71

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 35713

Work Order Notes

(EKIMBREL) PM, vehicle has leak on driver's side of cab.

Job Notes

06-00 - INSPECT COMPLETE VEHICLE

06-71-032 - INSPECT WATER LEAK INTERIOR/EXTERIOR

(LISAPATE) Found leaves packed in left corner under the cowl panel. Cleared leaves out and dried the carpet. Rechecked with water. Did not find a leak.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 5

Description : HAVOLINE 5W20 FULLSYN OIL BULK

Manufacturer :

Bin :

Part No : FL400S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

Bin : D4D

(LISAPATE) PM by SH

Coolant -50'

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 36810

USING DEPT NO:	600202	OPENED DATE:	06/15/2020 08:37:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2020 13:26:19	METER 1 - M:	17384	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/29/2020 08:24:03	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$34.78	\$0.00	\$0.00	\$34.78

JOB COUNT: 1	WORK ORDER TOTAL:	0.48	34.78	0.00	0.00	34.78
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/15/2020 10:48:58	06/15/2020 11:17:45	0.48	\$34.78
					LABOR	34.78

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 36810

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 5 Cost 0.100000

Part FL400S FILTER-OIL FORD Qty 1 Cost 3.240000

(AGUERRA) Did not change oil , checked fluids and tire pressures , updated oil change sticker. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 38646

USING DEPT NO:	600202	OPENED DATE:	12/14/2020 09:02:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/15/2020 09:31:12	METER 1 - M:	18320	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/15/2020 15:33:57	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.07	\$8.62	\$25.59	\$0.00	\$34.21
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$57.82	\$27.71	\$0.00	\$85.53

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	66.44	53.30	0.00	119.74
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/15/2020 09:20:08	12/15/2020 09:20:08	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/14/2020 15:14:12	12/14/2020 15:18:35	0.07	\$8.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2020 14:44:30	12/14/2020 15:13:54	0.49	\$57.82
					LABOR	66.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	12.80	2	\$25.59
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	5	\$22.13
					PARTS	53.30

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 38646

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers due to normal wear. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 18320. SH Performed PM and vacuumed. EK Washed.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 40095

USING DEPT NO:	600202	OPENED DATE:	06/03/2021 10:17:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2021 08:39:24	METER 1 - M:	19039	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2021 14:12:59	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.21	\$24.85	\$0.00	\$0.00	\$24.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 2	WORK ORDER TOTAL:	0.31	36.65	0.00	0.00	36.65
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	06/03/2021 12:58:29	06/03/2021 12:58:29	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	06/03/2021 13:00:00	06/03/2021 13:08:47	0.15	\$17.27
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	06/03/2021 14:11:09	06/03/2021 14:15:00	0.06	\$7.57
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/03/2021 12:37:03	06/03/2021 12:37:03	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/03/2021 12:37:03	06/03/2021 12:37:03	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/03/2021 12:37:03	06/03/2021 12:43:03	0.10	\$11.80
					LABOR	36.64

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 40095

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 19039 Vehicle has been 719 miles, oil was changed at last PM. Checked fluids, battery and tires, updated oil change sticker. Completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 40501

USING DEPT NO:	600202	OPENED DATE:	07/21/2021 11:52:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2021 10:08:10	METER 1 - M:	19206	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2021 14:17:22	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-52-003	INSPECT RADIO	DON	O	N	GARAGE	0.63	\$74.14	\$0.00	\$0.00	\$74.14

JOB COUNT: 1	WORK ORDER TOTAL:	0.63	74.14	0.00	0.00	74.14
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-52-003	INSPECT RADIO	11213180	07/21/2021 12:26:40	07/21/2021 13:04:22	0.63	\$74.14
					LABOR	74.14

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: **231816** **2001 FORD RANGER**

WORK ORDER NO: **40501**

Work Order Notes

(LISAPATE) Per Jon radio quit-smells like something burning waiting on a/c burning.

Job Notes

06-52-003 - INSPECT RADIO

(MSIDES) Found radio to have internally shorted. Removed radio and removed CD in player placed CD on dash and reinstalled radio but left all connections unplugged. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 4093

USING DEPT NO:	600202	OPENED DATE:	08/13/2009 09:10:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/19/2009 11:39:50	METER 1 - M:	8222	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/19/2009 11:39:52	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-010	REPLACE NEW BALL JOINT	DON	O	N	GARAGE	1.08	\$62.32	\$380.19	\$0.00	\$442.51
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$72.44	\$72.44
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.70	\$97.67	\$0.00	\$0.00	\$97.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	16.13	\$927.51	\$24.21	\$0.00	\$951.72

JOB COUNT: 4	WORK ORDER TOTAL:	18.91	1,087.50	404.40	72.44	1,564.34
--------------	-------------------	-------	----------	--------	-------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11122732	114293	0005540	\$72.44
				COMML	72.44

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-15-010	REPLACE NEW BALL JOINT	11274660	08/13/2009 14:45:44	08/13/2009 15:50:46	1.08	\$62.32
66-PM-PMA	PERFORM OIL CHANGE	11274660	08/13/2009 15:51:00	08/14/2009 07:58:50	16.13	\$927.51
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11274660	08/18/2009 06:58:36	08/18/2009 08:40:31	1.70	\$97.67
				LABOR		1087.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	160	\$16.80
03-15-010	REPLACE NEW BALL JOINT	SPI5021081	UPPER CONTROL ARM	136.47	1	\$136.47
03-15-010	REPLACE NEW BALL JOINT	SPI5021082	UPPER CONTROL ARM	136.47	1	\$136.47
03-15-010	REPLACE NEW BALL JOINT	SPI5051221	LOWER BALL JOINT	53.63	2	\$107.25
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	7.41	1	\$7.41
				PARTS		404.40

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 4093

Work Order Notes

(LPATE) PM-BALL JOINTS ARE WORN OUT-WILL NEED ALIGN AFTER STEERING IS REPAIRED

Job Notes

03-15-010 - REPLACE NEW BALL JOINT

(LPATE) REPLACED UPPER AND LOWER BALL JOINTS W/CONTROL ARM

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LPATE) FIRESTONE ALIGNED TIRES P0023086

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY ANGEL

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 51516
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 160
Description : OIL-MOTOR
Manufacturer :

(LPATE) PM BY TF

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 4145

USING DEPT NO:	600202	OPENED DATE:	08/19/2009 14:14:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2009 07:18:50	METER 1 - M:	8223	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/20/2009 07:18:52	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$24.21	\$0.00	\$42.04

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	24.21	0.00	42.04
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11274660	08/19/2009 17:00:00	08/19/2009 17:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	160	\$16.80
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	7.41	1	\$7.41
					PARTS	24.21

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 4145

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 51516
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 160
Description : OIL-MOTOR
Manufacturer :

(LPATE) PM BY TF

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 41848

USING DEPT NO:	600202	OPENED DATE:	12/10/2021 08:54:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2021 11:19:28	METER 1 - M:	20163	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2021 09:10:20	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-084	REPLACE NEW TAILGATE HANDLE/LAT	DON	O	N	GARAGE	0.10	\$11.83	\$23.03	\$0.00	\$34.86
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.03	\$3.77	\$0.85	\$0.00	\$4.62
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.38	\$15.18	\$0.00	\$20.56
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.53	\$63.03	\$0.00	\$0.00	\$63.03
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.37	\$43.14	\$0.00	\$0.00	\$43.14
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.02	\$120.33	\$503.05	\$0.00	\$623.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.20	\$34.34	\$0.00	\$83.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 8	WORK ORDER TOTAL:	2.51	296.68	576.45	2.00	875.13
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11074414	12/13/2021 14:57:44	12/13/2021 15:29:47	0.53	\$63.03
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	12/13/2021 14:55:37	12/13/2021 14:57:32	0.03	\$3.77
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/13/2021 14:52:40	12/13/2021 14:55:24	0.05	\$5.38
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2021 14:30:00	12/13/2021 14:52:30	0.38	\$44.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2021 14:12:29	12/13/2021 14:15:00	0.04	\$4.95
03-02-084	REPLACE NEW TAILGATE HANDLE/LATCH/STRIKER	11074414	12/15/2021 07:29:37	12/15/2021 07:35:38	0.10	\$11.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/15/2021 07:37:13	12/15/2021 08:38:24	1.02	\$120.33
66-17-013	PERFORM ALIGNMENT	11310047	12/16/2021 07:26:13	12/16/2021 07:48:09	0.37	\$43.14
				LABOR		296.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	5	\$22.20
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.85	1	\$0.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.47	4	\$1.86
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	2	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.47	3	\$1.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.56	1	\$0.56
03-02-084	REPLACE NEW TAILGATE HANDLE/LATCH/STRIKER	ACI60305	DOOR HANDLE	23.03	1	\$23.03
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15502670000	TIRE 225/70R15 GEN ALTIMAX	124.61	4	\$498.42
					PARTS	576.45

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 41848

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-02-084 - REPLACE NEW TAILGATE HANDLE/LATCH/STRIKER

(SHARBIN) Replaced tailgate handle. Working properly. SH

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(SHARBIN) Replaced left rear turn signal/brake light bulb. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering and brakes found no issues. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

(SHARBIN) Tailgate handle is broken tailgate will not open. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 44056

USING DEPT NO:	600202	OPENED DATE:	07/22/2022 13:27:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2022 11:58:53	METER 1 - M:	21581	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/18/2022 13:35:54	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-13-106	ADJUST REAR BRAKE SHOES	DON	O	N	GARAGE	0.36	\$42.61	\$0.00	\$0.00	\$42.61
01-18-001	ADJUST FRONT AXLE HUBS & BEARIN	DON	O	N	GARAGE	0.58	\$68.70	\$5.93	\$0.00	\$74.63
03-02-063	REPLACE NEW REAR WINDOW/BACK C	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$379.50	\$379.50
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.71	\$84.01	\$126.06	\$0.00	\$210.07
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.43	\$51.23	\$60.00	\$0.00	\$111.23
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.57	\$15.54	\$0.00	\$27.11
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.11	\$130.98	\$0.00	\$0.00	\$130.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.78	\$0.00	\$0.00	\$38.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.60	\$189.19	\$0.00	\$0.00	\$189.19

JOB COUNT: 11	WORK ORDER TOTAL:	5.73	676.07	207.53	381.50	1,265.10
---------------	-------------------	------	--------	--------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
03-02-063	REPLACE NEW REAR WINDOW/BACK GLASS	11078716	101266		\$379.50
				COMML	381.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	08/17/2022 07:00:00	08/17/2022 07:30:00	0.50	\$59.00
01-13-106	ADJUST REAR BRAKE SHOES	11310047	07/28/2022 08:32:40	07/28/2022 08:54:20	0.36	\$42.61
66-79-003	PERFORM SAFETY INSPECTION	11310047	07/27/2022 07:54:49	07/27/2022 09:01:25	1.11	\$130.98
03-33-003	REPLACE NEW COIL	11310047	07/26/2022 15:05:59	07/26/2022 15:32:02	0.43	\$51.23
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	07/26/2022 13:04:46	07/26/2022 13:35:48	0.52	\$61.03
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	07/26/2022 10:45:27	07/26/2022 11:50:37	1.09	\$128.16

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/25/2022 11:09:30	07/25/2022 11:29:13	0.33	\$38.78
01-18-001	ADJUST FRONT AXLE HUBS & BEARINGS	11310047	07/28/2022 08:54:20	07/28/2022 09:15:00	0.34	\$40.64
01-18-001	ADJUST FRONT AXLE HUBS & BEARINGS	11310047	07/28/2022 09:30:00	07/28/2022 09:44:16	0.24	\$28.06
03-32-002	REPLACE NEW BATTERY	11310047	07/28/2022 09:48:55	07/28/2022 10:31:38	0.71	\$84.01
03-51-038	REPLACE NEW WIPER BLADES	11310047	07/28/2022 10:59:53	07/28/2022 11:05:46	0.10	\$11.57
					LABOR	676.07

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.77	2	\$15.54
03-33-003	REPLACE NEW COIL	STIFD498T	IGNITION COIL	60.00	1	\$60.00
03-32-002	REPLACE NEW BATTERY	BP19C	BATTERY TERMINAL-TOP POST REG	2.46	1	\$2.46
01-18-001	ADJUST FRONT AXLE HUBS & BEARINGS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
03-32-002	REPLACE NEW BATTERY	58	BATTERY BCI 58 550 CCA	123.60	1	\$123.60
					PARTS	207.53

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 44056

Work Order Notes

(CHANNELL) replace rear window
(CHANNELL) pm\ replace wipers
check engine light on

Job Notes

01-13-106 - ADJUST REAR BRAKE SHOES

(EHOWELL) Cleaned rear brake shoes and adjusted. EH

01-18-001 - ADJUST FRONT AXLE HUBS & BEARINGS

(EHOWELL) Removed outer wheel bearings and cleaned them in the parts washer. Packed with fresh grease and tightened bearings. EH .5 HR

03-02-063 - REPLACE NEW REAR WINDOW/BACK GLASS

(LISAPATE) Glass Dr installed new back glass. PD by CC

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Installed a new battery and a new negative battery terminal. EH

03-33-003 - REPLACE NEW COIL

(EHOWELL) Replaced ignition coil. The vehicle is no longer misfiring. EH

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) Replaced wipers. EH

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by RC

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Performed Safety Inspection. EH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 1418 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0301 Cylinder 1 Misfire Detected. The ignition coil was sending a weak signal to the #1 spark plug. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 45297

USING DEPT NO:	600202	OPENED DATE:	11/17/2022 07:27:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/22/2022 14:18:39	METER 1 - M:	23461	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/30/2022 07:46:04	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.54	\$15.60	\$0.00	\$19.14
06-50-100	INSPECT BELT, SERPENTINE OR MISC.	DON	O	N	GARAGE	0.13	\$15.90	\$5.58	\$0.00	\$21.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$5.15	\$31.20	\$0.00	\$36.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.21	24.59	52.38	5.00	81.97
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	11/21/2022 08:07:26	11/21/2022 08:09:14	0.03	\$3.54
66-PM-PMA	PERFORM OIL CHANGE	12201267	11/21/2022 08:04:49	11/21/2022 08:07:26	0.04	\$5.15
06-50-100	INSPECT BELT, SERPENTINE OR MISC.	12201267	11/21/2022 08:09:14	11/21/2022 08:17:19	0.13	\$15.90
				LABOR		24.59

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.80	2	\$15.60
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	5	\$31.20
06-50-100	INSPECT BELT, SERPENTINE OR MISC.	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
					PARTS	52.38

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 45297

Work Order Notes

(LISAPATE) PM-replace wipers-Check belt is squeaking

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wiper blades- GRC

06-50-100 - INSPECT BELT, SERPENTINE OR MISC.

(GARAGE) inspected belt and found no issues- GRC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm service- coolant -34 GRC/ SH
23461

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 464

USING DEPT NO:	600202	OPENED DATE:	12/03/2007 09:29:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/03/2007 09:31:00	METER 1 - M:	7278	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	12/03/2007 09:31:01	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$20.63	\$0.00	\$34.58

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	13.95	20.63	0.00	34.58
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	12/03/2007 09:30:00	12/03/2007 09:48:36	0.31	\$13.95
					LABOR	13.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	160	\$14.40
66-PM-PMA	PERFORM OIL CHANGE	B243	FILTER-OIL	6.23	1	\$6.23
					PARTS	20.63

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 464

Work Order Notes

(LOBRIEN) PM.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 47369

USING DEPT NO:	600202	OPENED DATE:	06/15/2023 08:23:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/20/2023 12:44:42	METER 1 - M:	25019	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/20/2023 12:44:43	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	0.88	\$104.17	\$16.29	\$0.00	\$120.46
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.57	\$16.26	\$0.00	\$25.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.35	\$0.00	\$0.00	\$24.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.28	\$33.34	\$0.00	\$0.00	\$33.34

JOB COUNT: 5	WORK ORDER TOTAL:	1.45	171.43	32.55	5.00	208.98
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	12201267	06/16/2023 07:38:12	06/16/2023 08:31:10	0.88	\$104.17
WA-00	WASH COMPLETE VEHICLE	12201267	06/16/2023 08:31:42	06/16/2023 08:48:39	0.28	\$33.34
03-51-038	REPLACE NEW WIPER BLADES	12201267	06/16/2023 07:29:25	06/16/2023 07:34:17	0.08	\$9.57
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/16/2023 07:16:50	06/16/2023 07:29:13	0.21	\$24.35
					LABOR	171.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.13	2	\$16.26
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	ACI360308	OUTER DOOR HANDLE-DRIVER	16.29	1	\$16.29
					PARTS	32.55

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 47369

Work Order Notes

(EHANNAH) pm- replace wiper- wash

Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(GRCOOK) Removed door panel and drilled out rivets on old door handle unhooked handle rod and removed old broke handle, installed new handle and hooked rod back up, handle works good. -GC

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, vehicle driven 558 miles, filter good, tires and tire pressure, updated oil change sticker. Miles, 25,019

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 49003

USING DEPT NO:	600202	OPENED DATE:	11/20/2023 07:43:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2023 10:56:35	METER 1 - M:	26407	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 10:56:38	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.24	\$16.65	\$0.00	\$23.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.74	\$87.75	\$37.04	\$0.00	\$124.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.18	\$20.88	\$0.00	\$0.00	\$20.88

JOB COUNT: 4	WORK ORDER TOTAL:	0.98	115.87	53.69	5.00	174.56
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/30/2023 07:25:42	11/30/2023 08:10:19	0.74	\$87.75
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/30/2023 08:38:58	11/30/2023 08:42:39	0.06	\$7.24
WA-00	WASH COMPLETE VEHICLE	11074414	11/30/2023 09:04:23	11/30/2023 09:15:00	0.18	\$20.88
				LABOR		115.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	5	\$31.28
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
				PARTS		53.69

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 49003

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 493

USING DEPT NO:	600202	OPENED DATE:	12/10/2007 10:44:04	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	01/11/2008 07:47:53	METER 1 - M:	7278	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/11/2008 07:47:53	IN-SERVICE DATE:	10/01/2001						
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger			UNIT SERIAL NO:	1FTYR14V81TA99719					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	DON	V	N	GARAGE	0.00	\$0.00	\$22.50	\$0.00	\$22.50
16-71	TRANSPORT BODY	DON	V	N	GARAGE	1.00	\$45.00	\$0.00	\$0.00	\$45.00
24-71	REPAIR BODY	DON	V	N	GARAGE	0.00	\$0.00	\$0.00	\$1,844.96	\$1,844.96

JOB COUNT: 3	WORK ORDER TOTAL:					1.00	45.00	22.50	1,844.96	1,912.46
--------------	-------------------	--	--	--	--	------	-------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	133210	00735	\$1,844.96
COMML					1844.96

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11088474	01/11/2008 07:00:00	01/11/2008 07:30:00	0.50	\$22.50
16-71	TRANSPORT BODY	11088858	01/11/2008 06:00:00	01/11/2008 06:30:00	0.50	\$22.50
16-71	TRANSPORT BODY	11088474	01/04/2008 11:41:43	01/04/2008 11:41:24	(0.01)	(\$0.24)
16-71	TRANSPORT BODY	11088474	01/04/2008 11:41:24	01/04/2008 11:41:43	0.01	\$0.24
16-71	TRANSPORT BODY	11088474	12/11/2007 09:53:30	12/11/2007 09:53:50	0.01	\$0.25
16-71	TRANSPORT BODY	11088474	12/11/2007 09:53:50	12/11/2007 09:53:30	(0.01)	(\$0.25)
LABOR						45.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	WORDMARKS	WORDMARKS	22.50	1	\$22.50
PARTS						22.50

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 493

Work Order Notes

(RWINTERS) TRUCK WAS VANDALIZED AFTER A FOOTBALL GAME. REPAIR PER TRAVLERS ESTIMATE CLAIM # A9G4327001

Job Notes

14-53-006 - INSTALL WORDMARKS/IDENTIFIERS

(LOBRIEN) INSTALLED WORDMARK.

16-71 - TRANSPORT BODY

(RWINTERS) TAKEN TO ANDREWS BODY SHOP.

24-71 - REPAIR BODY

(LOBRIEN) ANDREWS REPAIRED BODY PER TRAVLERS ESTIMATE CLAIM # A9G4327001 { RIGHT BED SIDE, BOTH FRONT DOORS, MIRRORS AND BUFF FENDERS }.
P0011848

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 51007

USING DEPT NO:	600202	OPENED DATE:	06/04/2024 07:40:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2024 15:29:01	METER 1 - M:	27696	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/09/2024 10:58:08	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-16-011	REPLACE NEW SWAY BAR END LINK(S	DON	N	N	GARAGE	0.00	\$0.00	\$43.95	\$0.00	\$43.95
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.64	\$16.65	\$0.00	\$18.29
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.03	\$3.67	\$0.00	\$0.00	\$3.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.18	\$0.00	\$0.00	\$1.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-79-019	SCAN OUT AIR BAG MODULE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.62	\$0.00	\$0.00	\$0.62

JOB COUNT: 7	WORK ORDER TOTAL:	0.06	7.11	60.60	5.00	72.71
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12395904	06/05/2024 15:21:35	06/05/2024 15:23:27	0.03	\$3.67
WA-00	WASH COMPLETE VEHICLE	12395904	06/05/2024 15:20:56	06/05/2024 15:21:15	0.01	\$0.62
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/05/2024 15:19:56	06/05/2024 15:20:32	0.01	\$1.18
03-51-038	REPLACE NEW WIPER BLADES	12395904	06/05/2024 15:18:41	06/05/2024 15:19:31	0.01	\$1.64
				LABOR		7.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.33	2	\$16.65
03-16-011	REPLACE NEW SWAY BAR END LINK(S)	TRWJTS653	SWAY BAR LINKS	21.98	2	\$43.95
					PARTS	60.60

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 51007

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-16-011 - REPLACE NEW SWAY BAR END LINK(S)

(EKIMBREL) replaced sway bar links

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) perform replaced new wipers fc

66-79-003 - PERFORM SAFETY INSPECTION

(FCONTRER) perform safety inspection fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check fc

CH-SP - CHARGE Shop Supplies

SO-79-019 - SCAN OUT AIR BAG MODULE

(EHOWELL) Found DTC: B1877 Safety Belt Driver Retractor Circuit Failure. Observed the resistance for the circuit using the Ford scan tool and found the resistance high. Unplugged the related connector under the seat and found corrosion. Sprayed the connector out with contact cleaner, cleaned corrosion, and applied dielectric grease to the connector. Plugged in connector and verified proper circuit resistance via the scan tool data. The air bag light is no longer illuminated. EH

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 51526

USING DEPT NO:	600202	OPENED DATE:	07/18/2024 09:57:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2024 09:26:14	METER 1 - M:	28044	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2024 09:26:20	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$154.54	\$0.00	\$154.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	154.54	5.00	159.54
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	183482418	TIRE 225/70R15 GDYR WRGLR	151.38	1	\$151.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	1.65	1	\$1.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	1.04	1	\$1.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.47	1	\$0.47
					PARTS	154.54

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 51526

Work Order Notes

(EKIMBREL) RF tire has a nail

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and Balanced 1 new tire on unit 5845A, Unit had a small screw in side wall of tire and couldnt be patched-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 52856

USING DEPT NO:	600202	OPENED DATE:	11/19/2024 15:41:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2024 08:52:59	METER 1 - M:	28876	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/27/2024 09:15:29	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-18-001	ADJUST FRONT AXLE HUBS & BEARIN	DON	N	N	GARAGE	0.00	\$0.00	\$9.12	\$0.00	\$9.12
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$203.99	\$0.00	\$203.99
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.65	\$0.00	\$16.65
06-40-433	INSPECT OIL LEAK	DON	N	N	GARAGE	0.00	\$0.00	\$7.35	\$0.00	\$7.35
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$54.86	\$0.00	\$54.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	0.00	0.00	291.97	5.00	296.97
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
01-18-001	ADJUST FRONT AXLE HUBS & BEARINGS	82180	ULTRA BLACK RTV	9.12	1	\$9.12
03-32-002	REPLACE NEW BATTERY	58	BATTERY BCI 58 550 CCA	203.99	1	\$203.99
06-40-433	INSPECT OIL LEAK	LF2001	LEAKFINDER OIL DYE	7.35	1	\$7.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	5.58	1	\$5.58
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	5W20 FULL SYN QTS	8.33	5	\$41.63
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.33	2	\$16.65
				PARTS		291.97

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 52856

Work Order Notes

(CHANNELL) pm check brakes

Job Notes

01-18-001 - ADJUST FRONT AXLE HUBS & BEARINGS

(GARAGE) FOUND EXCESSIVE SLACK IN LEFT FRONT WHEEL BEARING. PUT TRUCK ON LIFT AND REMOVED CENTER CAP AND GREASE CAP REMOVED COTTER PIN AND ADJUSTED WHEEL BEARINGS. INSTALLED NEW COTTER PIN AND INSTALLED GREASE CAP WITH SILICON AND INSTALLED CENTER CAP. RETURNED TRUCK TO SERVICE. 0.5 HR CQ

03-32-002 - REPLACE NEW BATTERY

(GARAGE) JR- replaced battery, alternator charging
14.57 V

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR-replaced wiper blades

06-40-433 - INSPECT OIL LEAK

(GARAGE) JR- put leak detection dye in engine, will check after a week

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI. Front brakes 6mm. Rear brake shoes (drum brakes), 6mm. No abnormal wear on the pads, rotors, shoes, or drums.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR-perform PM, changed oil and filter, checked air filters, checked tires and tire pressures
28876 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 53122

USING DEPT NO:	600202	OPENED DATE:	12/12/2024 14:13:06	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2024 13:41:18	METER 1 - M:	28887	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2024 14:28:10	IN-SERVICE DATE:	10/01/2001						
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger									
				UNIT SERIAL NO:	1FTYR14V81TA99719						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.00	\$0.00	\$7.65	\$0.00	\$7.65
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
CU-13-002	CUT REAR BRAKES & DRUMS/ROTOR'S	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CU-51-046	CUT KEY BLANK(S)	DON	N	N	GARAGE	0.00	\$0.00	\$75.81	\$0.00	\$75.81
PR-51-046	PROGRAM KEY BLANK(S)	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	83.46	5.00	88.46
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
CU-51-046	CUT KEY BLANK(S)	164R8040	FORD PATS GEN2 KEYBLANK	75.81	1	\$75.81
06-13	INSPECT BRAKES	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						83.46

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 53122

Work Order Notes

(EHANNAH) inspect brakes and tires- SEE ISSAC FOR MORE INFORMATION AND BEFORE TESTING
(EKIMBREL) cut key for master key

Job Notes

06-13 - INSPECT BRAKES

(EHOWELL) PULLED TRUCK IN SHOP AND ON LIFT. REMOVED REAR TIRES AND REMOVED DRUMS. TURNED DRUMS ON LATHE AND INSTALLED WITH TIRES
ADJUSTED REAR BRAKES AND TEST DROVE, FOUND NO PROBLEM WITH BRAKING RETURNED TO SERVICE. CQ

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) INSPECTED TIRES AND FOUND TO CHECK GOOD. CQ

CH-SP - CHARGE Shop Supplies

CU-13-002 - CUT REAR BRAKES & DRUMS/ROTORS

(EHOWELL) PULLED TRUCK IN SHOP AND ON LIFT. REMOVED REAR TIRES AND REMOVED DRUMS. TURNED DRUMS ON LATHE AND INSTALLED WITH TIRES
ADJUSTED REAR BRAKES AND TEST DROVE, FOUND NO PROBLEM WITH BRAKING RETURNED TO SERVICE. CQ
The vehicle was driven by EH and it's stopping great.

CU-51-046 - CUT KEY BLANK(S)

(EHOWELL) EH cut key to be used as our master.

PR-51-046 - PROGRAM KEY BLANK(S)

(EHOWELL) PROGRAMMED NEW KEY TO UNIT USING THE FORD SCAN TOOL. CQ/EH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 54468

USING DEPT NO:	600202	OPENED DATE:	04/14/2025 07:21:36	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2025 15:52:42	METER 1 - M:	29580	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2025 14:52:48	IN-SERVICE DATE:	10/01/2001				
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$17.72	\$0.00	\$17.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	17.72	5.00	22.72
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PA5192F	AIR FILTER	17.72	1	\$17.72
PARTS						17.72

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 54468

Work Order Notes

(EHANNAH) pm- wipers- wash
(GARAGE) ***Waiting on air filter***

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Blades not needed at this time.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Fluid check. Mileage is 29,580. Driven 704 miles since PM. Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.
(GARAGE) FJ- Replaced air filter.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Washed vehicle.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 56736

USING DEPT NO:	600202	OPENED DATE:	10/09/2025 08:30:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/09/2025 08:35:55	METER 1 - M:	30282	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	10/09/2025 12:45:44	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-024	REPLACE NEW GLASS	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$354.14	\$354.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	359.14	359.14
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-024	REPLACE NEW GLASS	11078716	2-131385		\$354.14
				COMML	359.14

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 56736

Work Order Notes

(EHOWELL) The door glass was broken

Job Notes

03-02-024 - REPLACE NEW GLASS

(EHOWELL) Glass Doctor came to our facility and replaced the left front door glass.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 6645

USING DEPT NO:	600202	OPENED DATE:	08/30/2010 15:23:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/01/2010 14:04:16	METER 1 - M:	9340	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/01/2010 14:04:19	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$676.88	\$676.88
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.26	\$15.05	\$0.00	\$0.00	\$15.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$33.13	\$35.63	\$0.00	\$68.76

JOB COUNT: 3	WORK ORDER TOTAL:	0.84	48.18	35.63	676.88	760.69
--------------	-------------------	------	-------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	127575	0008940	\$676.88
				COMML	676.88

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10230946	08/31/2010 08:21:39	08/31/2010 08:56:13	0.58	\$33.13
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10230946	08/31/2010 11:42:24	08/31/2010 11:58:06	0.26	\$15.05
				LABOR		48.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.19	1	\$4.19
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	160	\$19.20
66-PM-PMA	PERFORM OIL CHANGE	6253	FILTER- AIR	12.24	1	\$12.24
				PARTS		35.63

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 6645

Work Order Notes

(LPATE) PM-REPLACE 4 TIRES AND ALIGN

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED, REMOVED AND REPLACED CAM BOLTS-P0030427

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY JM

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1516 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 160 Cost 0

(LPATE) PM BY JM/RS-REPLACED AIR FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 8009

USING DEPT NO:	600202	OPENED DATE:	04/01/2011 09:02:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/13/2011 07:34:49	METER 1 - M:	10123	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/13/2011 07:34:51	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.02	\$0.93	\$74.19	\$0.00	\$75.12
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BI	DON	O	N	GARAGE	0.37	\$21.03	\$1.33	\$0.00	\$22.36
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.47	\$27.12	\$33.48	\$0.00	\$60.60
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.30	\$17.44	\$14.76	\$0.00	\$32.20
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	2.36	\$135.68	\$0.00	\$0.00	\$135.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$15.24	\$23.39	\$0.00	\$38.63

JOB COUNT: 6	WORK ORDER TOTAL:	3.78	217.44	147.15	0.00	364.59
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11274660	04/06/2011 11:31:33	04/06/2011 11:59:51	0.47	\$27.12
06-13	INSPECT BRAKES	11274660	04/06/2011 11:59:56	04/06/2011 12:00:00	0.00	\$0.06
06-13	INSPECT BRAKES	11274660	04/06/2011 13:00:00	04/06/2011 13:18:08	0.30	\$17.38
66-PM-PMA	PERFORM OIL CHANGE	10230946	04/11/2011 13:03:39	04/11/2011 13:19:33	0.27	\$15.24
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	11274660	04/06/2011 11:09:31	04/06/2011 11:31:28	0.37	\$21.03
03-32-002	REPLACE NEW BATTERY	11274660	04/05/2011 15:57:18	04/05/2011 15:58:16	0.02	\$0.93
66-79-003	PERFORM SAFETY INSPECTION	11274660	04/01/2011 13:28:54	04/01/2011 15:50:29	2.36	\$135.68

LABOR 217.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	2	\$33.48
06-13	INSPECT BRAKES	C111	RED BRAKE CLEANER	4.57	1	\$4.57
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	912	BULB-BRAKE-3RD	1.33	1	\$1.33
03-32-002	REPLACE NEW BATTERY	58-6	BATTERY TOP POST	74.19	1	\$74.19
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	160	\$19.20
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.19	1	\$4.19
06-13	INSPECT BRAKES	RABH7295	HARDWARE KIT	10.19	1	\$10.19

Work Order Charge Detail

PARTS147.15

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 8009

Work Order Notes

(LPATE) PM-DO SAFETY INSPECTION

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

03-34-020 - REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY

(LPATE) REPLACED THIRD BRAKE LIGHT BULB

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

06-13 - INSPECT BRAKES

(LPATE) REPLACED REAR SPRING KIT. VERY SLIGHT PULSATION STARTING NO ADDITIONAL WORK NEEDED AT THIS TIME.

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) SAFETY INSPECTION COMPLETE-PM DONE-REPLACED 3RD BRAKE LIGHT BULB-REPLACED WIPERS-ADJUSTED REAR BRAKES-REPLACED BATTERY

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1516 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 160 Cost 0

(LPATE) PM BY JM/RS

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 8977

USING DEPT NO:	600202	OPENED DATE:	08/22/2011 13:04:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/24/2011 06:47:06	METER 1 - M:	10459	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/24/2011 06:47:08	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$1.76	\$23.57	\$0.00	\$25.33

JOB COUNT: 1	WORK ORDER TOTAL:					0.03	1.76	23.57	0.00	25.33
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	08/23/2011 14:06:19	08/23/2011 14:08:09	0.03	\$1.76
					LABOR	1.76

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.37	1	\$4.37
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	160	\$19.20
					PARTS	23.57

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 8977

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1516 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 160 Cost 0

(LPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 9605

USING DEPT NO:	600202	OPENED DATE:	11/04/2011 15:18:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2011 14:40:54	METER 1 - M:	10691	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/08/2011 14:40:56	IN-SERVICE DATE:	10/01/2001	
TECH SPEC NO:	01TKFORDRANG	2001 Ford Ranger		UNIT SERIAL NO:	1FTYR14V81TA99719	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$21.17	\$0.00	\$39.00

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	21.17	0.00	39.00
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11397026	11/07/2011 17:00:00	11/07/2011 17:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL400S	FILTER-OIL FORD	4.37	1	\$4.37
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	160	\$16.80
					PARTS	21.17

Work Order Charge Detail

The University of Alabama

Report Printed: 10/22/2025 11:05:46 By User: GLOBETTI

UNIT NO: 231816 2001 FORD RANGER

WORK ORDER NO: 9605

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 1198
Qty : 1
Description : OIL DRAIN PLUG FORD
Manufacturer :

Part No : 1516
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 160
Description : OIL BOTTLE
Manufacturer :

(LPATE) PM BY BG

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Oct 22 2025 11:05:46 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '231816') //Q=