

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 45583

USING DEPT NO: 507301	OPENED DATE: 12/14/2022 14:12:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/20/2023 10:54:38	METER 1 - M: 8 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/20/2023 14:15:42	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **5.00** **123.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11074414	12/14/2022 14:13:27	12/14/2022 15:13:27	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 45583

Work Order Notes

(EHANNAH) New unit do PDI
(LISAPATE) Unit arrived with only 1 key

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(EHANNAH) PDI done by SH

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 47054

USING DEPT NO: 507301	OPENED DATE: 05/15/2023 10:12:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/16/2023 08:32:15	METER 1 - M: 6317 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/16/2023 10:56:17	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.28	\$33.53	\$0.00	\$0.00	\$33.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.46	\$47.90	\$0.00	\$93.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.67	78.99	47.90	5.00	131.89
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2023 14:21:22	05/15/2023 14:21:22	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2023 14:30:00	05/15/2023 14:53:07	0.39	\$45.46
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/15/2023 15:04:18	05/15/2023 15:21:21	0.28	\$33.53
LABOR					78.99	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
PARTS					47.90	

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 47054

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 47187

USING DEPT NO: 507301	OPENED DATE: 05/30/2023 08:21:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/05/2023 09:34:20	METER 1 - M: 6324 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/05/2023 10:04:23	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-27	INSPECT TRANSMISSION - MAIN, AUTC	DON	O	N	GARAGE	0.17	\$19.96	\$0.00	\$0.00	\$19.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.17** **19.96** **0.00** **5.00** **24.96**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-27	INSPECT TRANSMISSION - MAIN, AUTOMATIC	12052187	06/01/2023 14:35:56	06/01/2023 14:43:38	0.13	\$15.14
06-27	INSPECT TRANSMISSION - MAIN, AUTOMATIC	12052187	05/30/2023 13:35:52	05/30/2023 13:38:19	0.04	\$4.82
LABOR					19.96	

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 47187

Work Order Notes

(IFALLS) Transmission not shifting right.

Job Notes

06-27 - INSPECT TRANSMISSION - MAIN, AUTOMATIC

(JWRIGHT) Found no stored codes. Test drove unit in sport, regular and eco modes and found no shifting issues at this time. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 48456

USING DEPT NO: 507301	OPENED DATE: 10/09/2023 11:26:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/11/2023 07:57:59	METER 1 - M: 10659 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/11/2023 12:00:11	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-PM	TRANSPORT PM SERVICE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	0.00	5.00	43.94
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6222736		\$0.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-PM	TRANSPORT PM SERVICE	11399745	10/11/2023 07:00:00	10/11/2023 07:19:48	0.33	\$38.94
LABOR						38.94

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 48456

Work Order Notes

(LISAPATE) PM

Job Notes

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by Toyota 10,000 mile service.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 49818

USING DEPT NO: 507301	OPENED DATE: 02/15/2024 09:53:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/16/2024 15:02:55	METER 1 - M: 14042 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/19/2024 09:22:37	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.58	\$41.78	\$0.00	\$80.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.58	41.78	5.00	85.36
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/16/2024 07:46:46	02/16/2024 08:06:23	0.33	\$38.58
LABOR					38.58	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
PARTS					41.78	

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 49818

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50136

USING DEPT NO: 507301	OPENED DATE: 03/18/2024 09:58:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/20/2024 11:11:07	METER 1 - M: 15665 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/20/2024 11:51:16	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$13.83	\$0.00	\$0.00	\$13.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.12** **13.83** **0.00** **5.00** **18.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/18/2024 11:07:39	03/18/2024 11:14:41	0.12	\$13.83
LABOR					0.12	13.83

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50136

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50912

USING DEPT NO: 507301	OPENED DATE: 05/22/2024 10:53:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/23/2024 07:27:42	METER 1 - M: 18726 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/23/2024 08:30:42	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-00	TRANSPORT COMPLETE VEHICLE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$6.00	\$0.00	\$0.00	\$6.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.05	6.00	0.00	5.00	11.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11076422	6250598		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11399745	05/22/2024 13:05:44	05/22/2024 13:08:47	0.05	\$6.00
LABOR					6.00	

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 50912

Work Order Notes

(EHANNAH) pm

Job Notes

16-00 - TRANSPORT COMPLETE VEHICLE

(EKIMBREL) cw transport unit to dealer for pm

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Took to Toyota to have the PM done. Miles 18,727 CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 52351

USING DEPT NO: 507301	OPENED DATE: 10/02/2024 13:46:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/03/2024 12:33:56	METER 1 - M: 24473 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/03/2024 15:14:35	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.45	\$0.00	\$43.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	43.45	5.00	48.45
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	8.42	1	\$8.42
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	5	\$35.03
PARTS						43.45

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 52351

Work Order Notes

(EHANNAH) pm

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SAFETY INSPECTION CHECKED OKK, CM

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PERFORMED PM CM 24273 MILES, CHANGED MOTOR OIL AND FILTER, CHECKED ALL FLUIDS AND TIRES CHECKED OK,

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 53711

USING DEPT NO: 507301	OPENED DATE: 02/11/2025 09:01:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/11/2025 14:54:23	METER 1 - M: 27869 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/12/2025 14:35:16	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$28.27	\$0.00	\$28.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$74.83	\$0.00	\$74.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$34.07	\$0.00	\$34.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** 0.00 0.00 137.17 5.00 142.17

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	34.07	1	\$34.07
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	5	\$32.25
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER	32.15	1	\$32.15
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	25-180	18" WIPER	15.04	1	\$15.04
PARTS						137.17

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 53711

Work Order Notes

(EHANNAH) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) FJ REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) fj PERFORMED pm

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) FL REPLACED CABIN FILTER

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 54720

USING DEPT NO: 507301	OPENED DATE: 05/08/2025 15:05:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/09/2025 08:59:54	METER 1 - M: 32264 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2025 11:24:19	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$52.13	\$0.00	\$52.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.00 0.00 52.13 5.00 57.13

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	8.93	5	\$44.63
PARTS						52.13

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 54720

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside

GC- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
32265 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 54743

USING DEPT NO: 507301	OPENED DATE: 05/12/2025 08:35:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/27/2025 13:41:37	METER 1 - M: 32264 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/29/2025 08:06:02	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-79-006	TRANSPORT RECALL	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-05-034	RECALL ECM/ENGINE CONTROL MODL	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-52-005	RECALL TRANSMITTER	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-71-024	RECALL BUMPER(S)	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4 **WORK ORDER TOTAL:** 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-05-034	RECALL ECM/ENGINE CONTROL MODULE	11076422	6294710		\$0.00
17-52-005	RECALL TRANSMITTER	11076422	6294710		\$0.00
17-71-024	RECALL BUMPER(S)	11076422	6294710		\$0.00
COMML					0.00

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 54743

Work Order Notes

(EHANNAH) Transport and Vendor
(EHOWELL) Recall # 24TC05 was also performed.

Job Notes

16-79-006 - TRANSPORT RECALL

(EHOWELL) The vehicle was driven to/from Tuscaloosa Toyota.

17-05-034 - RECALL ECM/ENGINE CONTROL MODULE

(EHOWELL) Tuscaloosa Toyota verified the programming in the Engine Control Computer.

17-52-005 - RECALL TRANSMITTER

(EHOWELL) Tuscaloosa Toyota performed recall # 23TJ01 and installed a transmitter sub-assy.

17-71-024 - RECALL BUMPER(S)

(EHOWELL) Tuscaloosa Toyota performed recall # 23TA12 and installed a screw, a nut, and a retainer.

17-GA-002 - RECALL PARTS CHARGED TO SHOP FOR USE

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56726

USING DEPT NO: 507301	OPENED DATE: 10/08/2025 13:33:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2025 14:48:11	METER 1 - M: 35557 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/09/2025 07:43:34	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$59.75	\$50.32	\$0.00	\$110.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.40 59.75 50.32 5.00 115.07

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	10/08/2025 13:39:21	10/08/2025 13:51:37	0.20	\$30.67
66-PM-PMA	PERFORM OIL CHANGE	11779687	10/08/2025 13:39:34	10/08/2025 13:51:12	0.19	\$29.08
LABOR					59.75	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.83	5	\$34.16
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	8.00	1	\$8.00
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	8.16	1	\$8.16
PARTS					50.32	

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56726

Work Order Notes

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- top side, checked fluids, filters good, tires and tire pressure, reset oil life and changed oil sticker, filled with oil and checked oil level

FJ- bottom side, drained oil and changed oil filter

Miles, 35,557

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56728

USING DEPT NO: 507301	OPENED DATE: 10/08/2025 14:49:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2025 15:42:50	METER 1 - M: 35557 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/09/2025 07:46:10	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.63	\$94.79	\$0.00	\$0.00	\$94.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.63** **94.79** **0.00** **5.00** **99.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12051004	10/08/2025 14:53:50	10/08/2025 15:31:45	0.63	\$94.79
LABOR						94.79

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 56728

Work Order Notes

(EKIMBREL) SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) JR- perform SI per SI sheet, everything checked OK
front pads were 10s, rear pads were 8s

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 57251

USING DEPT NO: 507301	OPENED DATE: 11/18/2025 09:38:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/18/2025 10:55:06	METER 1 - M: 37726 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/19/2025 08:23:36	IN-SERVICE DATE: 12/13/2022
TECH SPEC NO: 23TOYHIGHLNDR 2023 Toyota Highlander	UNIT SERIAL NO: 5TDKDRAH0PS501399	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **150.00** **0.00** **5.00** **155.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/18/2025 09:44:25	11/18/2025 10:16:44	0.54	\$80.79
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/18/2025 09:44:25	11/18/2025 10:16:44	(0.54)	(\$80.79)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/18/2025 09:44:25	11/18/2025 10:44:25	(1.00)	(\$150.00)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/18/2025 09:44:25	11/18/2025 10:44:25	1.00	\$150.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/18/2025 09:44:25	11/18/2025 10:44:25	1.00	\$150.00
LABOR					150.00	

Work Order Charge Detail

UNIT NO: 245140 2023 TOYOTA HIGHLANDER

WORK ORDER NO: 57251

Work Order Notes

(EKIMBREL) PREP 4 SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Performed prep for sale per decommission sheet. CQ

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Nov 21 2025 11:17:31 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '245140') //Q=