

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 45602

USING DEPT NO:	750202	OPENED DATE:	12/16/2022 07:47:58	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2022 07:57:39	METER 1 - M:	9	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/16/2022 12:33:06	IN-SERVICE DATE:	08/16/2022				
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 45602

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) Driver had oil changed while in Birmingham will not be back in Tuscaloosa in the foreseen future. Documentation attached

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46765

USING DEPT NO:	750202	OPENED DATE:	04/19/2023 09:18:43	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2023 08:25:09	METER 1 - M:	11560	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/26/2023 08:43:03	IN-SERVICE DATE:	08/16/2022						
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander									
			UNIT SERIAL NO:	5TDZZRAH4NS131071							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60

JOB COUNT: 4	WORK ORDER TOTAL:					0.53	62.54	0.00	5.00	67.54
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11076422	6201158		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11399745	04/26/2023 07:00:00	04/26/2023 07:12:00	0.20	\$23.60
16-PM	TRANSPORT PM SERVICE	11399745	04/25/2023 07:00:00	04/25/2023 07:19:48	0.33	\$38.94
LABOR						62.54

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46765

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) 10,000 mile service done by Tuscaloosa Toyota at no charge

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed-CW

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 47839

USING DEPT NO:	750202	OPENED DATE:	08/07/2023 07:32:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2023 07:37:35	METER 1 - M:	11560	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2023 09:47:56	IN-SERVICE DATE:	08/16/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	6211859	01901924627		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-PM-PMA	TRANSPORT OIL CHANGE	11399745	08/07/2023 09:47:00	08/07/2023 10:06:48	(0.33)	(\$38.94)
16-PM-PMA	TRANSPORT OIL CHANGE	11399745	08/07/2023 09:47:00	08/07/2023 10:06:48	0.33	\$38.94
LABOR						0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 47839

Work Order Notes

(LISAPATE) Bill Cummings works out of town and would not be back up here soon. Went to Express oil change paid with Wright Express card.

Job Notes

16-PM-PMA - TRANSPORT OIL CHANGE

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM done by Express Oil 7-31--23

Work Order Charge Detail

UNIT NO:		244862		2022 TOYOTA HIGHLANDER				WORK ORDER NO:		49515		
USING DEPT NO:		750202		OPENED DATE:		01/22/2024 09:20:07		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		02/14/2024 13:43:48		METER 1 - M:		24311 METER 2 - N: 0		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		02/15/2024 08:36:12		IN-SERVICE DATE:		08/16/2022		
TECH SPEC NO:		22TOYHIGHLNDR		2022 Toyota Highlander				UNIT SERIAL NO:		5TDZZRAH4NS131071		
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA		PERFORM OIL CHANGE		DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 49515

Work Order Notes

(EHANNAH) pm- vendor

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM was done by Express Oil in Daphne AL while driver was traveling

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52420

USING DEPT NO:	750202	OPENED DATE:	10/08/2024 10:56:20	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/10/2024 11:12:38	METER 1 - M:	37683	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/10/2024 13:29:23	IN-SERVICE DATE:	08/16/2022						
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$810.69	\$810.69
16-00	TRANSPORT COMPLETE VEHICLE	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$74.65	\$0.00	\$74.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:		0.00	0.00	74.65	815.69	890.34
--------------	-------------------	--	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2122171		\$810.69
03-02-061	REPLACE NEW WINDSHIELD	11078716	2122171		(\$810.69)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2122171		\$810.69
COMML					815.69

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	13.54	1	\$13.54
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	8.91	5	\$44.55
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	8.91	(5)	(\$44.55)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	8.91	6	\$53.46
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						74.65

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52420

Work Order Notes

(CWIGLEY) PM

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EHOWELL) Glass Doctor replaced windshield.

(EHOWELL) Visit Reason Changed On 10/10/2024 11:09 AM By EHOWELL

16-00 - TRANSPORT COMPLETE VEHICLE

(EHOWELL) The vehicle was driven to/picked up from Glass Doctor.

(EHOWELL) Visit Reason Changed On 10/10/2024 11:09 AM By EHOWELL

66-17-015 - PERFORM TIRE ROTATION

(GARAGE) performed tire rotation cm 37683 miles

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm 37683 gc changed oils and filter, checked ok,

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 53656

USING DEPT NO:	750202	OPENED DATE:	02/06/2025 13:28:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/24/2025 10:53:35	METER 1 - M:	37683	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/24/2025 14:16:24	IN-SERVICE DATE:	08/16/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 53656

Work Order Notes

(EHANNAH) Bill requested to have the oil change done on his vehicle while he was out of town. Due to his traveling, he was unable to come to the shop. the invoice is attached.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Express oil changed performed PM. The department paid for the service.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 55538

USING DEPT NO:	750202	OPENED DATE:	07/22/2025 09:00:52	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2025 14:37:44	METER 1 - M:	47161	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/23/2025 12:25:31	IN-SERVICE DATE:	08/16/2022				
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$32.76	\$0.00	\$32.76
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$3.60	\$0.00	\$3.60
06-51-044	INSPECT KEY FOB/REMOTE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$49.01	\$0.00	\$49.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	85.37	5.00	90.37
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	25-180	18" WIPER	15.04	1	\$15.04
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2032	BUTTON CELL BATTERY 3V	3.60	1	\$3.60
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.58	1	\$10.58
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	1	\$17.72
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
PARTS						85.37

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 55538

Work Order Notes

(EHANNAH) PM- WASH- SI- ONE OF HER FOBS IS NOT WORKING I TAG THE ONE NOT WORKING NOT SURE IF IT'S THE BATTERY OR SOMETHING IS WRONG WITH IT.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades.

03-51-042 - REPLACE NEW KEY FOB BATTERY

(EKIMBREL) FJ REPLACED KEY FOB BATTERY

06-51-044 - INSPECT KEY FOB/REMOTE

(GARAGE) FJ- Replaced key fob battery in 1 fob. Both fobs functioning properly.

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PM

47,161 miles

FJ- Added oil & verified oil level, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths

JR- Oil change

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 55549

USING DEPT NO:	750202	OPENED DATE:	07/22/2025 14:38:04	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	07/24/2025 08:20:20	METER 1 - M:	47161	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/24/2025 10:22:10	IN-SERVICE DATE:	08/16/2022						
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 55549

Work Order Notes

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) Cancelled from Work Order# 55538. By User ID EKIMBREL on 7/22/2025 2:37 PM.

(GARAGE) 47,161 miles

Damage noticed on RR, and rear bumper

FJ- Performed SI. All steering/suspension components checked ok at this time. Front brakes are 8mm, rear brakes are 6mm. All tires are 6/32.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 57059

USING DEPT NO:	750202	OPENED DATE:	11/03/2025 13:06:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/03/2025 13:58:47	METER 1 - M:	48439	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2025 07:02:24	IN-SERVICE DATE:	08/16/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH4NS131071	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	150.00	0.00	5.00	155.00
--------------	-------------------	--	--	--	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/03/2025 16:08:15	11/03/2025 17:08:15	1.00	\$150.00
LABOR						150.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/05/2025 12:59:04 By User: GLOBETTI

UNIT NO: 244862 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 57059

Work Order Notes

(EHOWELL) Prep for sale.

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) Pulled vehicle in shop and performed prep for sale per decommission sheet. CQ

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Nov 05 2025 12:59:04 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244862') //Q=