

# Work Order Charge Detail

**UNIT NO: 245002 2022 TOYOTA HIGHLANDER**

**WORK ORDER NO: 44770**

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 09/23/2022 09:10:52	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/23/2022 09:54:11	<b>METER 1 - M:</b> 9 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/26/2022 07:37:14	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR      2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

**JOB COUNT: 2      WORK ORDER TOTAL:      1.00      118.00      0.00      5.00      123.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML      5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11915538	09/23/2022 09:39:23	09/23/2022 10:39:23	1.00	\$118.00
					<b>LABOR</b>	<b>118.00</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 44770

---

**Work Order Notes**

(CWIGLEY) PDI

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed by RC

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 46164

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 02/15/2023 09:50:49	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/16/2023 11:43:59	<b>METER 1 - M:</b> 4121 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/17/2023 07:27:22	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.20	\$0.00	\$0.00	\$47.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.40** **47.20** **0.00** **5.00** **52.20**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/15/2023 09:51:33	02/15/2023 10:15:33	0.40	\$47.20
<b>LABOR</b>						<b>47.20</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 46164

---

**Work Order Notes**

(EKIMBREL) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) GC PERFORMED PM SERVICE

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 46676

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 04/11/2023 09:34:47	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/31/2023 15:15:26	<b>METER 1 - M:</b> 4601 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/31/2023 15:15:27	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$787.75	\$787.75
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR	DON	5	N	GARAGE	5.98	\$705.67	\$450.06	\$0.00	\$1,155.73
14-02-013	INSTALL FLOOR COVERINGS	DON	5	N	GARAGE	0.50	\$59.00	\$256.50	\$0.00	\$315.50
16-02	TRANSPORT CAB & SHEET METAL	DON	5	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>6.98</b>	<b>823.67</b>	<b>706.56</b>	<b>792.75</b>	<b>2,322.98</b>
---------------------	--------------------------	-------------	---------------	---------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2107522		\$787.75
03-02-061	REPLACE NEW WINDSHIELD	11078716	2107522		(\$787.75)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2107522		\$787.75
03-02-061	REPLACE NEW WINDSHIELD	11078716	2107522		(\$787.75)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2107522		\$787.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00

**COMML 792.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	10208562	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00
14-02-013	INSTALL FLOOR COVERINGS	10208562	05/31/2023 07:00:00	05/31/2023 07:30:00	(0.50)	(\$59.00)
14-02-013	INSTALL FLOOR COVERINGS	10208562	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	11399745	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	11399745	05/31/2023 07:00:00	05/31/2023 07:30:00	(0.50)	(\$59.00)
16-02	TRANSPORT CAB & SHEET METAL	11399745	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/14/2023 07:13:51	04/14/2023 11:36:59	4.39	\$517.50
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/14/2023 07:13:51	04/14/2023 11:36:59	4.39	\$517.50
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/14/2023 07:13:51	04/14/2023 11:36:59	(4.39)	(\$517.50)
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 15:22:32	04/13/2023 15:50:53	0.47	\$55.76
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 15:22:32	04/13/2023 15:50:53	0.47	\$55.76
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 15:22:32	04/13/2023 15:50:53	(0.47)	(\$55.76)
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 15:01:49	04/13/2023 15:11:08	0.16	\$18.32
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 15:01:49	04/13/2023 15:11:08	0.16	\$18.32
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 15:01:49	04/13/2023 15:11:08	(0.16)	(\$18.32)
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 13:15:26	04/13/2023 14:03:40	0.80	\$94.86
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 13:15:26	04/13/2023 14:03:40	0.80	\$94.86
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 13:15:26	04/13/2023 14:03:40	(0.80)	(\$94.86)
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 11:19:30	04/13/2023 11:29:17	0.16	\$19.24
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 11:19:30	04/13/2023 11:29:17	0.16	\$19.24
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	11310047	04/13/2023 11:19:30	04/13/2023 11:29:17	(0.16)	(\$19.24)
					<b>LABOR</b>	<b>823.68</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	PT9084820020	FLOOR MATS	256.50	1	\$256.50
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	13533423	STROBE KIT	225.03	2	\$450.06
14-02-013	INSTALL FLOOR COVERINGS	PT9084820020	FLOOR MATS	256.50	(1)	(\$256.50)
14-02-013	INSTALL FLOOR COVERINGS	PT9084820020	FLOOR MATS	256.50	1	\$256.50
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	13533423	STROBE KIT	225.03	(2)	(\$450.06)
06-34-022	INSPECT STROBE LIGHT/BULB/MOTOR/ASSY	13533423	STROBE KIT	225.03	2	\$450.06
					<b>PARTS</b>	<b>706.56</b>

# Work Order Charge Detail

UNIT NO: 245002 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46676

---

## Work Order Notes

(EKIMBREL) install windshield, floor mats, and strobes

---

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(LISAPATE) Glass Dr installed a new windshield and recal. PD by CC

(AJONES) Visit Reason Changed On 6/1/2023 9:04 AM By AJONES

(AJONES) Visit Reason Changed On 6/1/2023 9:05 AM By AJONES

### **06-34-022 - INSPECT STROBE LIGHT/BULB/MOTOR/ASSY**

(EHOWELL) Drilled holes in front fascia. Soldered in extra wires for length and ran them to the battery and a body ground. Ran wires inside vehicle. Soldered in extra wires for length. Drilled a hole to mount the switch in. Connected wires to switch terminals. Ran wires to the rear of the vehicle. Measured location for holes and drilled holes. Installed an I-let and bolted it to a ground. Soldered in extra wires for length and secured with zip ties. Verified operation of strobe lights. EH 5.0 HRS

(AJONES) Visit Reason Changed On 6/1/2023 9:05 AM By AJONES

### **14-02-013 - INSTALL FLOOR COVERINGS**

(LISAPATE) Installed floor mats

(AJONES) Visit Reason Changed On 6/1/2023 9:05 AM By AJONES

### **16-02 - TRANSPORT CAB & SHEET METAL**

(AJONES) Visit Reason Changed On 6/1/2023 9:05 AM By AJONES

### **CH-SP - CHARGE Shop Supplies**

(AJONES) Visit Reason Changed On 6/1/2023 9:05 AM By AJONES

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 47478

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 06/29/2023 14:44:36	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/03/2023 10:24:06	<b>METER 1 - M:</b> 4857 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/05/2023 08:16:07	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR	2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.15	\$54.49	\$0.00	\$104.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.29	\$34.68	\$0.00	\$0.00	\$34.68

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.72</b>	<b>84.83</b>	<b>54.49</b>	<b>5.00</b>	<b>144.32</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	06/30/2023 08:18:39	06/30/2023 08:36:17	0.29	\$34.68
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/30/2023 07:52:24	06/30/2023 08:17:54	0.43	\$50.15
<b>LABOR</b>					<b>84.83</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.11	1	\$6.11
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
<b>PARTS</b>					<b>54.49</b>	

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 47478

---

**Work Order Notes**

(EHANNAH) pm- replace wipers- wash  
(EKIMBREL) doesn't need wipers yet, new vehicle

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 4,857

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(GRCOOK) Washed vehicle-GC

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 48223

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 09/15/2023 09:04:55	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/18/2023 10:19:25	<b>METER 1 - M:</b> 5289 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/18/2023 11:46:28	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	5	N	GARAGE	0.15	\$17.70	\$656.72	\$0.00	\$674.42
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.15 17.70 656.72 5.00 679.42

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11399745	09/18/2023 07:00:00	09/18/2023 07:09:00	0.15	\$17.70
					<b>LABOR</b>	<b>17.70</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ECC5585AVM	LED MINI AMBER STROBE LIGHT	656.72	1	\$656.72
					<b>PARTS</b>	<b>656.72</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 48223

---

**Work Order Notes**

(EKIMBREL) INSTALL LIGHT BAR

---

**Job Notes**

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

**CH-SP - CHARGE Shop Supplies**

(AJONES) Visit Reason Changed On 9/28/2023 3:37 PM By AJONES

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 49925

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 02/23/2024 13:18:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/27/2024 14:21:00	<b>METER 1 - M:</b> 7664 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/28/2024 08:09:05	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.61	\$60.67	\$0.00	\$99.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 2	<b>WORK ORDER TOTAL:</b>	<b>0.33</b>	<b>38.61</b>	<b>60.67</b>	<b>5.00</b>	<b>104.28</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/23/2024 13:55:22	02/23/2024 14:15:00	0.33	\$38.61
<b>LABOR</b>						<b>38.61</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.67	1	\$7.67
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
<b>PARTS</b>						<b>60.67</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 49925

---

**Work Order Notes**

(EHANNAH) pm-

---

**Job Notes**

**14-52-021 - INSTALL GPS SYSTEM**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 50832

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 05/13/2024 14:52:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/14/2024 08:15:56	<b>METER 1 - M:</b> 8253 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/14/2024 10:03:55	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander		<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$40.58	\$0.00	\$0.00	\$40.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.34** **40.58** **0.00** **5.00** **45.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/13/2024 15:29:53	05/13/2024 15:50:31	0.34	\$40.58
<b>LABOR</b>						<b>40.58</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 50832

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM, GC, Fluid check only, vehicle driven 609 miles, checked fluids, filters, tires and tire pressure, updated oil change sticker.  
Miles, 8,253

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 51841

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 08/16/2024 09:07:10	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/17/2024 08:58:22	<b>METER 1 - M:</b> 9165 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/17/2024 09:06:36	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$61.07	\$0.00	\$61.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.00 0.00 61.07 5.00 66.07

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.57	1	\$11.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
<b>PARTS</b>						<b>61.07</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 51841

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 9,165

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52170

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 09/19/2024 08:51:52	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/19/2024 14:33:13	<b>METER 1 - M:</b> 9676 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/20/2024 07:48:37	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 1</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52170

---

**Work Order Notes**

(EHANNAH) install GPS- 87U030640022

---

**Job Notes**

**14-52-021 - INSTALL GPS SYSTEM**

(GARAGE) Installed GPS SN: 87U030640022 into unit 1347C-GC

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52338

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 10/02/2024 08:13:22	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/02/2024 15:42:44	<b>METER 1 - M:</b> 10001 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 10/03/2024 07:31:20	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$290.63	\$0.00	\$290.63
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.00 0.00 290.63 5.00 295.63

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	08008	TIRE 235/65R18 MICHELIN LTX	288.68	1	\$288.68
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	10	\$1.95
<b>PARTS</b>						<b>290.63</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52338

---

**Work Order Notes**

(EHOWELL) The previous work order (52310) was closed due to year end. 1 Tire has been ordered.

---

**Job Notes**

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) MOUNTED AND BALANCED NEW TIRE CM 10001 MILE  
(EKIMBREL) reused valve stem, looked basically new.

**CH-SP - CHARGE Shop Supplies**

(AJONES) Visit Reason Changed On 10/23/2024 9:15 AM By AJONES

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52701

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 11/05/2024 07:25:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/05/2024 11:54:57	<b>METER 1 - M:</b> 10681 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/05/2024 16:09:25	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.45	\$0.00	\$63.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>63.45</b>	<b>5.00</b>	<b>68.45</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	13.77	1	\$13.77
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
<b>PARTS</b>						<b>63.45</b>

# Work Order Charge Detail

UNIT NO: 245002 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52701

---

## Work Order Notes

(EHANNAH) pm- SI

---

## Job Notes

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) performed safety inspection, found no issues at this time, steering good, rotated tires also  
brake pads are 8mm front and rear  
Miles, 10,681

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm-JR,GC, changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 10,681

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52767

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 11/08/2024 14:17:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/13/2024 08:45:43	<b>METER 1 - M:</b> 10681 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/13/2024 14:44:24	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$295.67	\$0.00	\$295.67
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.00 0.00 295.67 5.00 300.67

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	08008	TIRE 235/65R18 MICHELIN LTX	288.68	1	\$288.68
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21102	TPMS SERVICE KIT 6-108	6.99	1	\$6.99
<b>PARTS</b>						<b>295.67</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 52767

---

**Work Order Notes**

(EHANNAH) screw in PR tire

---

**Job Notes**

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) JR-mounted and balanced tire

**66-17-030 - PERFORM TIRE PATCH**

**CH-SP - CHARGE Shop Supplies**

(JWEATHER) Visit Reason Changed On 11/15/2024 11:20 AM By JWEATHER

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 53479

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 01/27/2025 08:24:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/30/2025 14:34:11	<b>METER 1 - M:</b> 11848 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/30/2025 15:06:18	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-PM-PMA	TRANSPORT OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-14-002	RECALL BUMPERS & ATTACHING PART	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$103.44	\$103.44

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>108.44</b>	<b>108.44</b>
---------------------	--------------------------	-------------	-------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
17-14-002	RECALL BUMPERS & ATTACHING PARTS	11076422	6281276/2		\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11076422	6281276/2		\$103.44
66-PM-PMA	PERFORM OIL CHANGE	11076422	6281276/2		\$0.00
				<b>COMML</b>	<b>108.44</b>

# Work Order Charge Detail

UNIT NO: 245002 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 53479

---

## Work Order Notes

(EHANNAH) pm- check engine light is on- Collion brake light is on

---

## Job Notes

### **16-PM-PMA - TRANSPORT OIL CHANGE**

(EHOWELL) The vehicle was driven to Tuscaloosa Toyota.

### **17-14-002 - RECALL BUMPERS & ATTACHING PARTS**

(EHOWELL) Tuscaloosa Toyota performed safety recall 23TA12.

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) OIL WILL BE CHANGED AT TOYOTA. CQ

### **CH-SP - CHARGE Shop Supplies**

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(GARAGE) PULLED IN SHOP AND HOOKED SCAN TOOL FOR DIAGNOSTICS. FOUND CODES FOR ROUGH IDLE, CYLINDER 2 MISFIRE, RANDOM MULTIPLE CYLINDER MISFIRE DETECTED OVER TEMP SIGNAL ABOVE ALLOWABLE RANGE, RANDOM MULTIPLE MISFIRE DETECTED EMISSION SIGNAL RATE OF CHANGE ABOVE THREHC UNIT IS STILL UNDER WARRANTY, TOOK TO TOYOTA FOR REPAIRS. CQ

(EHOWELL) Spoke with Paul and Chuck at Tuscaloosa Toyota. Paul stated that it's hard to get the manufacturer to cover a warranty diagnosis if there is no failed part. They think the problem may have been related to bad fuel, but they're uncertain. They swapped the suspect coil/spark plug to a different cylinder. If the misfire occurs again and there is a failed part, then Paul will try to reimburse us the diagnostic fee.

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 54255

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 04/01/2025 15:03:36	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/02/2025 07:47:09	<b>METER 1 - M:</b> 12895 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/02/2025 12:58:58	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$57.18	\$0.00	\$57.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>57.18</b>	<b>5.00</b>	<b>62.18</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.01	1	\$11.01
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
<b>PARTS</b>						<b>57.18</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 54255

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm cm top side fj bottom side, 12895 miles, cm needs tire rotated, fj changed motor oil and filter, cm filled oil topped off all tires filter fluids checked ok,

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 55306

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 07/08/2025 09:11:54	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/10/2025 09:57:09	<b>METER 1 - M:</b> 14513 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/10/2025 14:06:41	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$32.76	\$0.00	\$32.76
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$360.47	\$0.00	\$360.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$7.65	\$0.00	\$7.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.00	\$0.00	\$26.71	\$0.00	\$26.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>427.59</b>	<b>5.00</b>	<b>432.59</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21864	TIRE 235/65R18 MICH PREM LTX	356.10	1	\$356.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.37	1	\$4.37
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	1	\$17.72
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	26.71	1	\$26.71
03-51-038	REPLACE NEW WIPER BLADES	25-180	18" WIPER	15.04	1	\$15.04
<b>PARTS</b>						<b>427.59</b>

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 55306

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Not needed at this time.

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) FJ- Mounted/balanced 1tire LR (21030 valve stem)

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- Fluid check. 14,513 miles. Driven 1,618 miles since PM. Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GARAGE) FJ- Replaced cabin filter.

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 55661

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 07/30/2025 10:07:43	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/31/2025 08:09:27	<b>METER 1 - M:</b> 14792 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/31/2025 09:06:45	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR      2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 1</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 245002 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 55661

---

## Work Order Notes

(EHANNAH) tire patch on FP tire

---

## Job Notes

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

(GARAGE) GC- inspected the right front tire that was said to have a leak, checked the tire for any objects in the tire, found nothing, and tire pressures were the same. sprayed the tire down while on the unit inside and out and valve stem and found no issues.

Note all tire pressures were actually 40 psi and that could have caused the light to be on.

Set all tire pressure correctly and inspected them this morning since it was at the end of the day yesterday, all tire pressures checked the same this morning, 7-31-25 and no issues.

### **66-17-030 - PERFORM TIRE PATCH**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 56779

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 10/10/2025 14:49:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/10/2025 15:06:56	<b>METER 1 - M:</b> 15988 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/13/2025 09:38:45	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$18.88	\$59.30	\$0.00	\$78.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.13** **18.88** **59.30** **5.00** **83.18**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11779687	10/10/2025 14:58:44	10/10/2025 15:02:42	0.07	\$9.92
66-PM-PMA	PERFORM OIL CHANGE	12201267	10/10/2025 14:59:00	10/10/2025 15:02:35	0.06	\$8.96
<b>LABOR</b>					<b>18.88</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.83	6	\$40.99
66-PM-PMA	PERFORM OIL CHANGE	92006	WASHER FLUID	7.01	1	\$7.01
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.30	1	\$11.30
<b>PARTS</b>					<b>59.30</b>	

# Work Order Charge Detail

UNIT NO: 245002 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 56779

---

## Work Order Notes

### Job Notes

#### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) 15,998

PM

CW- Added oil & checked oil level, checked filters

FJ- Topped off fluids, set tire pressure, recorded date codes & tread depths

GC- Oil change

#### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 57105

<b>USING DEPT NO:</b> 507143	<b>OPENED DATE:</b> 11/06/2025 12:56:41	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/10/2025 09:30:35	<b>METER 1 - M:</b> 16321 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/11/2025 08:08:13	<b>IN-SERVICE DATE:</b> 09/20/2022
<b>TECH SPEC NO:</b> 22TOYHIGHLNDR 2022 Toyota Highlander	<b>UNIT SERIAL NO:</b> 5TDZZRAH3NS556572	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.50	\$75.00	\$0.00	\$0.00	\$75.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.50</b>	<b>225.00</b>	<b>0.00</b>	<b>5.00</b>	<b>230.00</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	11/10/2025 07:00:00	11/10/2025 08:00:00	1.00	\$150.00
25-52-021	REMOVE GPS SYSTEM	12051004	11/11/2025 07:00:00	11/11/2025 07:30:00	0.50	\$75.00
<b>LABOR</b>					<b>225.00</b>	

# Work Order Charge Detail

**UNIT NO:** 245002 2022 TOYOTA HIGHLANDER

**WORK ORDER NO:** 57105

---

**Work Order Notes**

(CWIGLEY) Prep for sale.

---

**Job Notes**

**25-52-021 - REMOVE GPS SYSTEM**

(GARAGE) GPS was previously removed from this vehicle. EH had a note on his desk to add this job when the vehicle was to be sold. JR removed the GPS from this vehicle and installed it into an OIT Chevy Trax.

(GARAGE) Chevy Trax was for Security Resources, not OIT

**CH-SP - CHARGE Shop Supplies**

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(EKIMBREL) JR PERFORMED PREP FOR SALE

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Wed Nov 12 2025 11:56:06 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '245002') //Q=