

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 42909

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 04/13/2022 09:31:58	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/13/2022 09:33:05	<b>METER 1 - M:</b> 13 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/30/2022 08:57:43	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA	2022 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-051	INSTALL SEAT COVER	DON	O	N	GARAGE	1.00	\$118.00	\$984.72	\$34.50	\$1,137.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.00</b>	<b>236.00</b>	<b>984.72</b>	<b>39.50</b>	<b>1,260.22</b>
---------------------	--------------------------	-------------	---------------	---------------	--------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-02-051	INSTALL SEAT COVER	11074386	100645175		\$34.50
14-02-051	INSTALL SEAT COVER	11074386	100642630		\$14.95
14-02-051	INSTALL SEAT COVER	11074386	100642630		(\$14.95)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>39.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-051	INSTALL SEAT COVER	11310047	09/30/2022 07:00:00	09/30/2022 08:00:00	1.00	\$118.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11310047	04/13/2022 09:32:23	04/13/2022 10:32:23	1.00	\$118.00
<b>LABOR</b>						<b>236.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-051	INSTALL SEAT COVER	SS8452WFG	SEAT COVER	404.99	1	\$404.99
14-02-051	INSTALL SEAT COVER	SS2509WFG	SEAT COVER	329.99	1	\$329.99
14-02-051	INSTALL SEAT COVER	SS2509WFG	SEAT COVER	329.99	(1)	(\$329.99)
14-02-051	INSTALL SEAT COVER	SS8452WFG	SEAT COVER	404.99	(1)	(\$404.99)
14-02-051	INSTALL SEAT COVER	COVSSC2509CA	FRONT SEAT COVER TACOMA	435.78	1	\$435.78
14-02-051	INSTALL SEAT COVER	COVSSC8452CA	REAR SEAT COVER TACOMA	548.94	1	\$548.94
<b>PARTS</b>						<b>984.72</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 42909

---

**Work Order Notes**

(LISAPATE) New unit do PDI

---

**Job Notes**

**14-02-051 - INSTALL SEAT COVER**

(LISAPATE) Installed seat cover

**CH-SP - CHARGE Shop Supplies**

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LISAPATE) PDI completed by EH

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 44328

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 08/16/2022 10:18:18	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/17/2022 10:49:33	<b>METER 1 - M:</b> 427 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/18/2022 13:57:23	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA	2022 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.19	\$0.00	\$0.00	\$30.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.26** **30.19** **0.00** **2.00** **32.19**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/16/2022 10:43:30	08/16/2022 10:58:51	0.26	\$30.19
					<b>LABOR</b>	<b>30.19</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 44328

---

**Work Order Notes**

(CWIGLEY) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) vehicle has 427 miles on it. checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 45679

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 01/05/2023 07:12:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/06/2023 13:06:32	<b>METER 1 - M:</b> 1408 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 01/06/2023 13:06:36	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA 2022 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.71	\$0.00	\$0.00	\$24.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.21** **24.71** **0.00** **5.00** **29.71**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/05/2023 11:36:58	01/05/2023 11:49:32	0.21	\$24.71
<b>LABOR</b>						<b>24.71</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 45679

---

**Work Order Notes**

(IFALLS) PM  
(GARAGE) Performed PM- GC Fluid check only, battery good fluids good, tires and tire pressure good  
Miles- 1,408

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Fluid check only-GC

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 47376

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 06/16/2023 07:02:29	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/20/2023 11:47:51	<b>METER 1 - M:</b> 1751 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/20/2023 11:47:52	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA 2022 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$21.49	\$0.00	\$33.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.20	\$43.94	\$0.00	\$83.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.53</b>	<b>62.80</b>	<b>65.43</b>	<b>5.00</b>	<b>133.23</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/16/2023 09:23:00	06/16/2023 09:29:00	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/16/2023 09:23:00	06/16/2023 09:23:00	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/16/2023 09:23:00	06/16/2023 09:23:00	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/16/2023 08:55:04	06/16/2023 09:15:00	0.33	\$39.20
WA-00	WASH COMPLETE VEHICLE	11074414	06/16/2023 09:25:32	06/16/2023 09:25:32	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	11074414	06/16/2023 09:25:32	06/16/2023 09:25:32	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	11074414	06/16/2023 09:25:32	06/16/2023 09:31:32	0.10	\$11.80
					<b>LABOR</b>	<b>62.80</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.64	1	\$10.64
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
					<b>PARTS</b>	<b>65.43</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 47376

---

**Work Order Notes**

(EHANNAH) pm- replace wipers- wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) CW Washed the vehicle. SH

---

# Work Order Charge Detail

**UNIT NO:** 244593      **2022 TOYOTA TACOMA**      **WORK ORDER NO:** 48829

<b>USING DEPT NO:</b>	504101	<b>OPENED DATE:</b>	11/06/2023 07:19:43	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	11/10/2023 13:49:10	<b>METER 1 - M:</b>	2024	<b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	11/10/2023 14:29:19	<b>IN-SERVICE DATE:</b>	04/05/2022	
<b>TECH SPEC NO:</b>	22TOYTACOMA	2022 Toyota Tacoma		<b>UNIT SERIAL NO:</b>	3TMAZ5CN3NM177306	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.29	\$0.00	\$0.00	\$22.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.20	\$23.73	\$0.00	\$0.00	\$23.73

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>		<b>0.39</b>	<b>46.02</b>	<b>0.00</b>	<b>5.00</b>	<b>51.02</b>
---------------------	--------------------------	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	11/06/2023 13:12:55	11/06/2023 13:24:59	0.20	\$23.73
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/06/2023 13:00:44	11/06/2023 13:12:04	0.19	\$22.29
<b>LABOR</b>					<b>46.02</b>	

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 48829

---

**Work Order Notes**

(EHANNAH) pm- wipers- wash  
(EKIMBREL) DOES NOT NEED WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Driven 273 miles checked fluids tire pressure and updated oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed. SH

---

# Work Order Charge Detail

UNIT NO: 244593 2022 TOYOTA TACOMA

WORK ORDER NO: 50441

USING DEPT NO:	504101	OPENED DATE:	04/05/2024 07:58:22	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/05/2024 13:29:44	METER 1 - M:	2549	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/05/2024 14:23:31	IN-SERVICE DATE:	04/05/2022		
TECH SPEC NO:	22TOYTACOMA	2022 Toyota Tacoma		UNIT SERIAL NO:	3TMAZ5CN3NM177306		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.21	\$21.49	\$0.00	\$22.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.47	\$60.65	\$0.00	\$137.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.25	\$29.27	\$0.00	\$0.00	\$29.27

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.91</b>	<b>106.95</b>	<b>82.14</b>	<b>5.00</b>	<b>194.09</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	04/05/2024 10:42:24	04/05/2024 10:57:17	0.25	\$29.27
03-51-038	REPLACE NEW WIPER BLADES	12395904	04/05/2024 10:41:27	04/05/2024 10:42:04	0.01	\$1.21
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/05/2024 10:02:14	04/05/2024 10:41:07	0.65	\$76.47
					<b>LABOR</b>	<b>106.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.64	1	\$10.64
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
					<b>PARTS</b>	<b>82.14</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 50441

---

**Work Order Notes**

(EHANNAH) pm- wipers- wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(FCONTRER) replaced new wipers fc

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changes fc

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(FCONTRER) Wash fc

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 52088

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 09/11/2024 07:27:15	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/13/2024 13:15:05	<b>METER 1 - M:</b> 3729 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/13/2024 13:15:05	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA 2022 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 244593 2022 TOYOTA TACOMA

WORK ORDER NO: 52088

---

## Work Order Notes

(EHANNAH) pm- wipers- wash  
(EKIMBREL) did not need wipers

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC, Fluid check only vehicle driven 180 miles, checked fluids, filters good, tires and tire pressure, updated oil change sticker.  
Miles, 3,729

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Vehicle is clean, filled with gas-GC

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 53874

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 02/25/2025 07:11:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/26/2025 09:29:19	<b>METER 1 - M:</b> 5712 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/26/2025 15:06:00	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA 2022 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$565.74	\$565.74
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$30.08	\$0.00	\$30.08
16-00	TRANSPORT COMPLETE VEHICLE	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$53.13	\$0.00	\$53.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 7** **WORK ORDER TOTAL:** **0.00** **0.00** **83.21** **570.74** **653.95**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2125228		\$565.74
03-02-061	REPLACE NEW WINDSHIELD	11078716	1125228		(\$671.40)
03-02-061	REPLACE NEW WINDSHIELD	11078716	1125228		\$671.40
<b>COMML</b>					<b>570.74</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.34	1	\$14.34
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.47	6	\$38.79
03-51-038	REPLACE NEW WIPER BLADES	25-220	BEAM WIPER BLADE	15.04	1	\$15.04
<b>PARTS</b>						<b>83.21</b>

# Work Order Charge Detail

UNIT NO: 244593 2022 TOYOTA TACOMA

WORK ORDER NO: 53874

---

## Work Order Notes

(EHANNAH) pm- wipers- wash- SI

---

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(EKIMBREL) GLASS DR REPLACED WINDSHIELD

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) GC- replaced wipers

### **16-00 - TRANSPORT COMPLETE VEHICLE**

(EKIMBREL) RC/CW TRANSPORTED VEHICLE TO AND FROM GLASS DR

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) GC- performed safety inspection, found no issues at this time  
brake pads are 10 mm front and rear shoes are good  
Miles, 5,172

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR- top side, checked fluids, filters good, tire tread depths, filled with oil  
GC, bottom side, drained oil and changed oil filter, also changed wipers and aired up tires.  
Miles, 5,172

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) GC- wash bay was being worked on and filled with gas

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 55798

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 08/07/2025 07:33:07	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/07/2025 10:56:31	<b>METER 1 - M:</b> 5612 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/07/2025 14:29:15	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA      2022 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 55798

---

**Work Order Notes**

(EHANNAH) pm- wipers- wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) GC- Fluid check only vehicle driven 440 miles, checked fluids, filters good, tires and tire pressure, reset oil life, updated oil sticker, checked oil level

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) FJ- washed vehicle

---

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 57153

<b>USING DEPT NO:</b> 504101	<b>OPENED DATE:</b> 11/11/2025 07:13:31	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/11/2025 12:54:48	<b>METER 1 - M:</b> 5612 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/12/2025 07:03:44	<b>IN-SERVICE DATE:</b> 04/05/2022
<b>TECH SPEC NO:</b> 22TOYTACOMA	2022 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 3TMAZ5CN3NM177306

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **1.00** **150.00** **0.00** **5.00** **155.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12478231	11/11/2025 12:54:36	11/11/2025 13:54:36	1.00	\$150.00
					<b>LABOR</b>	<b>150.00</b>

# Work Order Charge Detail

**UNIT NO:** 244593 2022 TOYOTA TACOMA

**WORK ORDER NO:** 57153

---

**Work Order Notes**

(EKIMBREL) prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) prepped vehicle for sale. CQ

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Wed Nov 12 2025 11:52:24 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '244593') //Q=