

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 16244

USING DEPT NO:	206101	OPENED DATE:	02/27/2014 08:04:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2014 14:57:42	METER 1 - M:	82	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2014 14:57:44	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10260422	02/27/2014 08:05:04	02/27/2014 08:35:04	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 16244

Work Order Notes

(LPATE) NEW UNIT DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETE

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 18117

USING DEPT NO:	206101	OPENED DATE:	09/16/2014 14:48:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/18/2014 07:51:00	METER 1 - M:	3751	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/18/2014 07:51:02	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.76	\$0.00	\$47.59

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	29.76	0.00	47.59
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/17/2014 07:00:00	09/17/2014 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.75	4	\$22.98
					PARTS	29.76

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 18117

Work Order Notes

(LPATE) PM
(IFALLS) CAR HOLDS 4.5 OIL .5 WAS ALREADY CHARGED OUT

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY NT/RS

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 18720

USING DEPT NO:	206101	OPENED DATE:	11/12/2014 13:52:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/20/2014 08:27:51	METER 1 - M:	5503	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/20/2014 08:27:52	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.54	\$31.21	\$0.00	\$0.00	\$31.21
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$679.65	\$679.65

JOB COUNT: 2	WORK ORDER TOTAL:	0.54	31.21	0.00	679.65	710.86
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	164270	0026250	\$679.65
				COMML	679.65

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10337093	11/13/2014 10:04:48	11/13/2014 10:37:22	0.54	\$31.21
					LABOR	31.21

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 18720

Work Order Notes

(LPATE) TAKE TO ANDREW'S TO REPAIR BODY DAMAGE TO THE REAR BUMPER PER THE ESTIMATE.

Job Notes

16-71 - TRANSPORT BODY

(LPATE) TAKEN TO ANDREW'S BY AY

24-71 - REPAIR BODY

(LPATE) ANDREW'S REPAIRED BODY DAMAGE PER THE ESTIMATE. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 19988

USING DEPT NO:	206101	OPENED DATE:	04/10/2015 08:47:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2015 10:45:55	METER 1 - M:	7775	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/14/2015 10:45:56	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$37.23	\$0.00	\$51.61
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,133.58	\$1,133.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.65	\$34.53	\$0.00	\$70.18

JOB COUNT: 4	WORK ORDER TOTAL:	1.87	107.53	71.76	1,133.58	1,312.87
--------------	-------------------	------	--------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	\$1,133.58
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	\$0.00
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	\$0.00
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	\$1,133.58
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	(\$1,133.58)
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	\$1,132.98
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	(\$1,132.98)
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11150605	164383	0027835	(\$1,133.58)
24-71	REPAIR BODY	11150605	164383	0027843	\$1,133.58
COMML					1133.58

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	10337093	04/10/2015 15:34:16	04/10/2015 16:34:16	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	10337093	04/10/2015 10:58:04	04/10/2015 11:16:40	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11338644	04/10/2015 10:57:57	04/10/2015 11:16:33	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	10337093	04/10/2015 10:58:07	04/10/2015 11:13:07	0.25	\$14.38
LABOR						107.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	40726	WIPER BLADE 26"	21.33	1	\$21.33
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	15.90	1	\$15.90

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.69	4	\$22.74
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS	71.76

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 19988

Work Order Notes

(GMANNING) PM, REPAIR BODY DAMAGE.

Job Notes

03-02-031 - REPLACE NEW EXTERIOR BODY MOLDINGS

(GMANNING) ANDREWS PERFORMED BODY REPAIR.(REPLACED AND PAINTED FRONT BUMPER COVER)

03-51-038 - REPLACE NEW WIPER BLADES

(GMANNING) REPLACED BOTH WIPER BLADES

16-02 - TRANSPORT CAB & SHEET METAL

(GMANNING) AY TOOK UNIT TO ANDREWS.

24-71 - REPAIR BODY

(GMANNING) ANDREWS REPAIRED BODY PER ESTIMTE. PD BY CC. SEE ATTACHED.

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING) PM BY AY/RS. CAR TAKES 4.5 QTS. USED 1/2 QT 0W20S ALREADY CHARGED OUT.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 20802

USING DEPT NO:	206101	OPENED DATE:	07/15/2015 11:05:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/21/2015 06:41:19	METER 1 - M:	9593	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/21/2015 06:41:21	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	07/20/2015 07:23:04	07/20/2015 07:23:12	0.00	(\$0.13)
66-PM-PMA	PERFORM OIL CHANGE	11338644	07/20/2015 07:23:04	07/20/2015 07:23:12	0.00	\$0.13
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 20802

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM WAS NOT DUE AT THIS TIME. CHECKED FLUIDS AND ADJUSTED TIRE PRESSURES ALL OK

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 21097

USING DEPT NO:	206101	OPENED DATE:	08/12/2015 08:59:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/14/2015 07:45:24	METER 1 - M:	10076	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/14/2015 07:45:26	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.38	\$21.95	\$0.00	\$0.00	\$21.95
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$35.14	\$31.43	\$0.00	\$66.57

JOB COUNT: 2	WORK ORDER TOTAL:	0.99	57.09	31.43	0.00	88.52
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11338644	08/12/2015 11:35:13	08/12/2015 11:58:07	0.38	\$21.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/12/2015 09:25:17	08/12/2015 10:01:57	0.61	\$35.14
					LABOR	57.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.34	1	\$3.34
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.53	1	\$5.53
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	4.51	5	\$22.56
					PARTS	31.43

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 21097

Work Order Notes

(LPATE) PM-ROTATE TIRES

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY RS/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 21969

USING DEPT NO:	206101	OPENED DATE:	11/11/2015 09:35:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/13/2015 07:47:36	METER 1 - M:	14712	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/13/2015 07:47:38	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.99	\$57.00	\$19.65	\$0.00	\$76.65

JOB COUNT: 1	WORK ORDER TOTAL:	0.99	57.00	19.65	0.00	76.65
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/12/2015 10:19:41	11/12/2015 11:19:10	0.99	\$57.00
					LABOR	57.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	4	\$15.04
					PARTS	19.65

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 21969

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 11/11/2015 9:36 AM By LISAPATE

(LISAPATE) PM BY GM

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 22913

USING DEPT NO:	206101	OPENED DATE:	03/25/2016 10:38:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2016 16:00:00	METER 1 - M:	18683	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2016 16:00:00	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$22.38	\$0.00	\$40.21

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	22.38	0.00	40.21
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11268671	03/25/2016 15:26:07	03/25/2016 15:44:43	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA5	FILTER-OIL	4.56	1	\$4.56
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.78	1	\$2.78
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	4	\$15.04
					PARTS	22.38

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 22913

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY IF-USED 1/2QT OF OIL THAT WAS ALREADY CHARGED OUT

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 23981

USING DEPT NO:	206101	OPENED DATE:	07/25/2016 10:15:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2016 18:00:00	METER 1 - M:	22766	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2016 18:00:00	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$27.36	\$31.34	\$0.00	\$58.70

JOB COUNT: 1	WORK ORDER TOTAL:	0.48	27.36	31.34	0.00	58.70
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/25/2016 15:06:20	07/25/2016 15:34:53	0.48	\$27.36
					LABOR	27.36

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	7.92	1	\$7.92
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	5	\$18.80
					PARTS	31.34

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 23981

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 24615

USING DEPT NO:	206101	OPENED DATE:	10/13/2016 09:04:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2016 13:14:49	METER 1 - M:	25387	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2016 13:14:51	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	46.00	46.00
--------------	-------------------	------	------	------	-------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	237084	0035755	\$46.00
COMML					46.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: **240421** **2014 TOYOTA CAMRY**

WORK ORDER NO: **24615**

Work Order Notes

(LISAPATE) DEPT REQUESTED REPAIR WINDSHIELD ON DRIVER SIDE

Job Notes

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) GLASS DR CAME TO GARAGE AND REPAIRED DING IN WINDSHIELD. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 24916

USING DEPT NO:	206101	OPENED DATE:	11/09/2016 08:53:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/14/2016 11:01:51	METER 1 - M:	26164	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/14/2016 11:01:53	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.30	\$0.00	\$41.13

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	23.30	0.00	41.13
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	11/10/2016 07:00:00	11/10/2016 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.50	1	\$4.50
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	5	\$18.80
					PARTS	23.30

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 24916

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 11/9/2016 8:53 AM By LISAPATE

(LISAPATE) PM BY AB

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 25903

USING DEPT NO:	206101	OPENED DATE:	03/03/2017 09:44:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2017 06:21:00	METER 1 - M:	30417	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2017 06:21:02	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$19.31	\$23.47	\$0.00	\$42.78

JOB COUNT: 1	WORK ORDER TOTAL:					0.34	19.31	23.47	0.00	42.78
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/03/2017 14:50:07	03/03/2017 15:10:16	0.34	\$19.31
					LABOR	19.31

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.77	5	\$18.85
					PARTS	23.47

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 25903

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/CS
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 26816

USING DEPT NO:	206101	OPENED DATE:	07/11/2017 15:30:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2017 08:22:07	METER 1 - M:	33840	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2017 08:22:08	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$54.44	\$0.00	\$83.19
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$15.73	\$0.00	\$33.56
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$4.89	\$0.00	\$22.14

JOB COUNT: 4	WORK ORDER TOTAL:	2.11	121.33	75.06	0.00	196.39
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/12/2017 07:00:00	07/12/2017 07:18:36	0.31	\$17.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	07/12/2017 07:18:36	07/12/2017 07:36:36	0.30	\$17.25
66-79-002	PERFORM SERVICE CALL	11213180	07/12/2017 07:00:00	07/12/2017 08:00:00	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11213180	07/12/2017 08:00:00	07/12/2017 08:30:00	0.50	\$28.75
					LABOR	121.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	2.78	4	\$11.12
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	54.44	1	\$54.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
					PARTS	75.06

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 26816

Work Order Notes

(LISAPATE) HALEY REQUESTED A SERVICE CALL TO ALSTON HALL FOR A DEAD BATTERY-PM IS DUE

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) REPLACED BATTERY

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPETED. REPLACED BATTERY AND BROUGHT CAR TO THE SHOP

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY MS

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 28414

USING DEPT NO:	206101	OPENED DATE:	12/13/2017 10:12:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2017 06:44:17	METER 1 - M:	38101	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/18/2017 06:44:18	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.26	\$15.00	\$17.06	\$0.00	\$32.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.66	\$0.00	\$41.49

JOB COUNT: 2	WORK ORDER TOTAL:	0.57	32.83	40.72	0.00	73.55
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11758845	12/14/2017 07:18:28	12/14/2017 07:34:07	0.26	\$15.00
66-PM-PMA	PERFORM OIL CHANGE	11758845	12/14/2017 07:34:07	12/14/2017 07:52:43	0.31	\$17.83
					LABOR	32.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	2.78	4	\$11.12
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	7.92	1	\$7.92
					PARTS	40.72

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 28414

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS/AG -REPLACED AIR FILTER
COOLANT -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 29898

USING DEPT NO:	206101	OPENED DATE:	05/25/2018 13:42:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2018 10:17:34	METER 1 - M:	42990	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2018 10:17:35	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$27.11	\$0.00	\$44.94

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	27.11	0.00	44.94
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/28/2018 06:00:00	05/28/2018 06:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.71	5	\$18.55
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
					PARTS	27.11

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 29898

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 30036

USING DEPT NO:	206101	OPENED DATE:	06/15/2018 15:28:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2018 09:09:02	METER 1 - M:	42990	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	06/27/2018 09:09:04	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-02	TRANSPORT CAB & SHEET METAL	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-02-015	REPAIR REAR QUARTER & DECK PANE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$2,002.82	\$2,002.82

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	0.00	2,002.82	2,060.32
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-015	REPAIR REAR QUARTER & DECK PANELS	11150605	166645	0043940	\$2,002.82
				COMML	2002.82

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	06/18/2018 07:00:00	06/18/2018 08:00:00	1.00	\$57.50
16-02	TRANSPORT CAB & SHEET METAL	10208562	06/18/2018 13:12:09	06/18/2018 14:15:00	(1.05)	(\$60.23)
16-02	TRANSPORT CAB & SHEET METAL	10208562	06/18/2018 14:30:00	06/18/2018 15:38:26	(1.14)	(\$65.58)
16-02	TRANSPORT CAB & SHEET METAL	10208562	06/18/2018 13:12:09	06/18/2018 14:15:00	1.05	\$60.23
16-02	TRANSPORT CAB & SHEET METAL	10208562	06/18/2018 14:30:00	06/18/2018 15:38:26	1.14	\$65.58
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 30036

Work Order Notes

(LISAPATE) REPAIR LR QUARTER PANEL AND TAIL LIGHT. CUSTOMER PAY NOT INSURANCE

Job Notes

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) TAKEN TO ANDREWS BY RC

24-02-015 - REPAIR REAR QUARTER & DECK PANELS

(LISAPATE) ANDREWS REPAIRED BODY DAMAGE PER THE ESTIMATE. PD BY CC. INVOICE AND ESTIMATE ATTACHED

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 31689

USING DEPT NO:	206101	OPENED DATE:	12/07/2018 13:11:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2018 07:15:02	METER 1 - M:	47536	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2018 07:15:04	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.17	\$0.00	\$17.06	\$0.00	\$17.06
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.66	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$0.00	\$9.60	\$0.00	\$9.60
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$0.00	\$23.78	\$0.00	\$23.78
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$349.56	\$349.56

JOB COUNT: 6	WORK ORDER TOTAL:	3.02	0.00	50.44	349.56	400.00
--------------	-------------------	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11078167	11415565	0046200	\$349.56
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11078167	11415565	0046200	(\$349.56)
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11078167	1141565	0046200	\$349.56
COMML					349.56

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/11/2018 10:25:28	12/11/2018 10:48:33	0.38	\$0.00
09-15	ALIGN STEERING	11310047	12/10/2018 11:11:32	12/10/2018 11:50:59	0.66	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/11/2018 10:53:10	12/11/2018 11:03:36	0.17	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	12/11/2018 07:00:00	12/11/2018 07:48:00	0.80	\$0.00
66-79-002	PERFORM SERVICE CALL	11758845	12/11/2018 07:00:00	12/11/2018 08:00:00	1.00	\$0.00
LABOR						0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.26	6	\$1.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	2.01	4	\$8.04
					PARTS	50.44

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 31689

Work Order Notes

(LISAPATE) Kati requested a service call to Stadium Dr deck for a flat tire on LF. Also is due for PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

09-15 - ALIGN STEERING

(LISAPATE) EH performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced 4 new tires

66-17-030 - PERFORM TIRE PATCH

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed added air and drove to the shop.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -50'

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) Purchased 4 new tires from Warren Tire. Pd by CC

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 32826

USING DEPT NO:	206101	OPENED DATE:	05/06/2019 10:04:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2019 11:59:14	METER 1 - M:	53261	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2019 11:59:16	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$0.00	\$33.91	\$0.00	\$33.91
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$0.00	\$4.89	\$0.00	\$4.89

JOB COUNT: 2	WORK ORDER TOTAL:	0.57	0.00	38.80	0.00	38.80
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	10208562	05/07/2019 07:00:00	05/07/2019 07:18:00	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/06/2019 13:24:32	05/06/2019 13:40:36	0.27	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	10.13	1	\$10.13
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	5	\$19.45
					PARTS	38.80

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 32826

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG

Replaced air filter

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 33855

USING DEPT NO:	206101	OPENED DATE:	08/26/2019 09:41:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/28/2019 10:18:28	METER 1 - M:	58484	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/28/2019 10:18:29	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$0.00	\$27.99	\$0.00	\$27.99

JOB COUNT: 1	WORK ORDER TOTAL:					0.48	0.00	27.99	0.00	27.99
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/26/2019 10:15:50	08/26/2019 10:44:37	0.48	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	5	\$19.45
					PARTS	27.99

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 33855

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH

Coolant -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 34117

USING DEPT NO:	206101	OPENED DATE:	09/16/2019 15:12:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/18/2019 07:06:44	METER 1 - M:	58919	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/18/2019 07:06:46	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.27	\$0.00	\$76.54	\$0.00	\$76.54

JOB COUNT: 1	WORK ORDER TOTAL:	0.27	0.00	76.54	0.00	76.54
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11915538	09/16/2019 15:30:04	09/16/2019 15:46:18	0.27	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	75.70	1	\$75.70
					PARTS	76.54

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 34117

Work Order Notes

(LISAPATE) Check battery had to jump off

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery failed, replaced battery checked alt is charging at 13.2 volts

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 34970

USING DEPT NO:	206101	OPENED DATE:	11/25/2019 09:03:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2019 12:57:22	METER 1 - M:	62819	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	12/02/2019 12:57:24	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.99	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	4.29	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$0.00	\$19.89	\$0.00	\$19.89

JOB COUNT: 4	WORK ORDER TOTAL:	6.67	0.00	19.89	0.00	19.89
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11901357	11/25/2019 09:18:23	11/25/2019 11:35:19	2.28	\$0.00
09-15	ALIGN STEERING	11213180	11/27/2019 07:00:00	11/27/2019 08:00:00	1.00	\$0.00
06-13	INSPECT BRAKES	11213180	11/26/2019 14:02:14	11/26/2019 15:01:43	0.99	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/25/2019 15:24:48	11/25/2019 15:48:31	0.40	\$0.00
66-79-002	PERFORM SERVICE CALL	10208562	11/25/2019 09:34:19	11/25/2019 11:34:38	2.01	\$0.00

LABOR 0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.88	(5)	(\$19.40)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	4	\$15.56

PARTS 19.89

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 34970

Work Order Notes

(LISAPATE) Service call to Alston Hall per Kati brakes are scrubbing

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE) All brakes have plenty of material noise was due to oxidation

09-15 - ALIGN STEERING

(LISAPATE) Checked alignment due to abnormal RR tire wear, no issue found switched rear tire position. Rechecked when car returns

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed. Drove to the shop

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH,JW/SH

Coolant -30'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 35837

USING DEPT NO:	206101	OPENED DATE:	03/02/2020 10:15:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/05/2020 08:08:50	METER 1 - M:	67970	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2020 08:08:52	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.19	\$0.00	\$17.06	\$0.00	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$0.00	\$23.78	\$0.00	\$23.78

JOB COUNT: 2	WORK ORDER TOTAL:	0.86	0.00	40.84	0.00	40.84
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	10208562	03/02/2020 11:31:32	03/02/2020 11:43:07	0.19	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/02/2020 10:21:35	03/02/2020 10:46:28	0.41	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/02/2020 10:30:58	03/02/2020 10:45:53	0.25	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
					PARTS	40.84

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 35837

Work Order Notes

(LISAPATE) PM-Replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/SH

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 37044

USING DEPT NO:	206101	OPENED DATE:	07/07/2020 10:30:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2020 14:00:57	METER 1 - M:	69583	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/08/2020 07:51:50	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.92	\$0.00	\$32.00	\$0.00	\$32.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.30	\$0.00	\$4.89	\$0.00	\$4.89

JOB COUNT: 2	WORK ORDER TOTAL:	1.22	0.00	36.89	0.00	36.89
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	07/07/2020 13:59:59	07/07/2020 14:17:59	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/07/2020 13:15:50	07/07/2020 13:47:48	0.53	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/07/2020 13:14:32	07/07/2020 13:37:44	0.39	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	8.22	1	\$8.22
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
					PARTS	36.89

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 37044

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/AG

Coolant -34'

Replaced air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 37504

USING DEPT NO:	206101	OPENED DATE:	09/03/2020 11:11:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/10/2020 11:09:38	METER 1 - M:	70282	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2020 14:28:34	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-044	REPLACE NEW KEY FOB/REMOTE	DON	O	N	GARAGE	0.35	\$0.00	\$42.06	\$0.00	\$42.06
24-51-044	REPAIR KEY FOB/REMOTE	DON	O	N	GARAGE	0.83	\$0.00	\$4.34	\$0.00	\$4.34

JOB COUNT: 2	WORK ORDER TOTAL:	1.19	0.00	46.40	0.00	46.40
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-044	REPLACE NEW KEY FOB/REMOTE	11901357	09/08/2020 10:15:02	09/08/2020 10:36:19	0.35	\$0.00
24-51-044	REPAIR KEY FOB/REMOTE	11901357	09/08/2020 10:13:54	09/08/2020 10:14:44	0.01	\$0.00
24-51-044	REPAIR KEY FOB/REMOTE	11901357	09/04/2020 13:40:39	09/04/2020 14:29:49	0.82	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-044	REPLACE NEW KEY FOB/REMOTE	000163291505	RF TRANSMITTER TOYOPORT	21.03	1	\$21.03
03-51-044	REPLACE NEW KEY FOB/REMOTE	000163291505	RF TRANSMITTER TOYOPORT	21.03	1	\$21.03
24-51-044	REPAIR KEY FOB/REMOTE	KE23A1ZMA	23A 12V FOB BATTERY	2.17	2	\$4.34
					PARTS	46.40

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: **240421** **2014 TOYOTA CAMRY**

WORK ORDER NO: **37504**

Work Order Notes

(LISAPATE) Both key fobs are not working at all

Job Notes

03-51-044 - REPLACE NEW KEY FOB/REMOTE

(AGUERRA) Replaced and reprogrammed 2 key fobs, checked for proper operation, all good. AMG 1/2 HR

24-51-044 - REPAIR KEY FOB/REMOTE

(AGUERRA) Unable to repair ordered new key fob. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 38684

USING DEPT NO:	206101	OPENED DATE:	12/17/2020 07:11:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2021 08:09:02	METER 1 - M:	73481	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2021 09:43:03	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.25	\$30.02	\$0.00	\$0.00	\$30.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.25	\$38.08	\$0.00	\$88.33

JOB COUNT: 2 WORK ORDER TOTAL: 0.68 80.27 38.08 0.00 118.35

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-13	INSPECT BRAKES	11213180	12/18/2020 14:30:00	12/18/2020 14:36:59	0.12	\$13.73
06-13	INSPECT BRAKES	11213180	12/18/2020 14:08:31	12/18/2020 14:15:00	0.11	\$12.75
06-13	INSPECT BRAKES	12052187	12/18/2020 10:48:59	12/18/2020 10:50:47	0.03	\$3.54
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/18/2020 09:30:00	12/18/2020 09:35:55	0.10	\$11.64
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/18/2020 08:55:22	12/18/2020 09:15:00	0.33	\$38.61
					LABOR	80.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	6.32	5	\$31.58
					PARTS	38.08

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 38684

Work Order Notes

(LISAPATE) PM-check brakes are noisy

Job Notes

06-13 - INSPECT BRAKES

(JWRIGHT) Inspected brakes and pads are 8 mm thick still like new and no issues with rotors verified with MS. Test drove and found no issues or any noises heard. Possibly had rust on rotors from sitting and driver heard it scrubbing off. JAW

(MSIDES) Drove vehicle up to 70 mph and applied the brakes very aggressively and the only noise heard that seemed odd was that the ABS pump activates to apply more pressure to the brake system this happens just before the ABS fully activates when tire lock up happens. This event is considered normal under extremely hard braking circumstances. No other issues were found with the brakes there is no indication of wear on the brake rotors or pads and there is no pulsation from the brakes when driving indicating a warped rotor. MS

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Will likely need new tires at next pm. Coolant -34°. JAW/JAW
MILEAGE-79481

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 39863

USING DEPT NO:	206101	OPENED DATE:	05/04/2021 07:44:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/06/2021 15:16:19	METER 1 - M:	76893	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2021 08:14:14	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$54.84	\$36.63	\$0.00	\$91.47

JOB COUNT: 1	WORK ORDER TOTAL:	0.46	54.84	36.63	0.00	91.47
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/04/2021 13:31:56	05/04/2021 13:33:53	0.03	\$3.84
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/04/2021 10:22:13	05/04/2021 10:48:09	0.43	\$51.00
					LABOR	54.84

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	36.63

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 39863

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 76893 Completed PM topside, Josh was bottom side. Completed checklist and vacuumed out vehicle. AMG/JW

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 40771

USING DEPT NO:	206101	OPENED DATE:	08/18/2021 09:01:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2021 14:07:21	METER 1 - M:	82195	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/23/2021 07:46:31	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.67	\$17.77	\$0.00	\$23.44
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.13	\$15.54	\$0.00	\$0.00	\$15.54
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$46.61	\$279.26	\$0.00	\$325.87
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.40	\$34.69	\$0.00	\$68.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
JOB COUNT: 6		WORK ORDER TOTAL:				1.11	130.72	331.72	2.00	464.44

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	11213180	08/18/2021 15:48:32	08/18/2021 15:56:26	0.13	\$15.54
06-15	INSPECT STEERING	11213180	08/20/2021 07:00:00	08/20/2021 07:15:00	0.25	\$29.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	08/18/2021 15:24:19	08/18/2021 15:48:01	0.40	\$46.61
03-51-038	REPLACE NEW WIPER BLADES	11170580	08/18/2021 11:31:32	08/18/2021 11:34:25	0.05	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/18/2021 11:12:14	08/18/2021 11:29:13	0.28	\$33.40
LABOR						130.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	135.02	2	\$270.03
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.46	1	\$7.46
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	3	\$1.49
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.87	2	\$7.74
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.70	1	\$5.70

Work Order Charge Detail

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	331.72

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 40771

Work Order Notes

(IFALLS) PM
pick up at stadium drive parking deck (Annette 348-8953)

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(ABBLACK) AB installed new wiper blades

06-15 - INSPECT STEERING

(LISAPATE) Checked steering

66-17-013 - PERFORM ALIGNMENT

(MSIDES) Performed alignment.MS

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(MSIDES) Mounted and balanced 2 new tires. MS

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 82195. AB/SH Performed PM. Needs 2 rear tires.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 41806

USING DEPT NO:	206101	OPENED DATE:	12/07/2021 07:35:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2021 11:10:52	METER 1 - M:	88075	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/09/2021 13:30:00	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.38	\$17.90	\$0.00	\$23.28
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.16	\$19.01	\$0.00	\$0.00	\$19.01
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.66	\$78.11	\$0.00	\$0.00	\$78.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$44.12	\$58.56	\$0.00	\$102.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.24	146.62	76.46	2.00	225.08
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	12/07/2021 09:30:00	12/07/2021 09:39:40	0.16	\$19.01
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	12/07/2021 09:22:59	12/07/2021 09:22:59	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11074414	12/07/2021 08:35:17	12/07/2021 09:15:00	0.66	\$78.11
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/07/2021 08:32:20	12/07/2021 08:35:04	0.05	\$5.38
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/07/2021 08:09:41	12/07/2021 08:32:07	0.37	\$44.12
				LABOR		146.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.53	1	\$13.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71

Work Order Charge Detail

PARTS	76.46
-------	-------

Work Order Charge Detail

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 41806

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI leaving for Mobile at 12 today

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires inspected brakes washed and vacuumed. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection did not find any issues. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 43076

USING DEPT NO:	206101	OPENED DATE:	04/28/2022 07:09:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2022 10:59:13	METER 1 - M:	92913	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2022 07:45:59	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.72	\$17.90	\$0.00	\$22.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$54.74	\$38.53	\$0.00	\$93.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.46	56.43	2.00	117.89
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/28/2022 11:10:59	04/28/2022 11:13:23	0.04	\$4.72
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2022 10:52:57	04/28/2022 11:10:49	0.30	\$35.14
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2022 10:17:42	04/28/2022 10:27:40	0.17	\$19.60
				LABOR		59.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
				PARTS		56.43

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 43076

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 44425

USING DEPT NO:	206101	OPENED DATE:	08/23/2022 10:27:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2022 15:09:17	METER 1 - M:	98204	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/24/2022 07:22:57	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$23.10	\$0.00	\$46.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$70.58	\$0.00	\$109.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.20	\$23.60	\$29.30	\$0.00	\$52.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.73	86.14	122.98	5.00	214.12
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2022 10:56:02	08/23/2022 11:15:50	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2022 10:56:02	08/23/2022 10:57:07	(0.02)	(\$2.13)
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2022 10:56:02	08/23/2022 10:57:07	0.02	\$2.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/23/2022 10:57:07	08/23/2022 11:09:07	0.20	\$23.60
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/23/2022 10:57:07	08/23/2022 10:57:51	0.01	\$1.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/23/2022 10:57:07	08/23/2022 10:57:51	(0.01)	(\$1.44)
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/23/2022 10:57:51	08/23/2022 11:09:51	0.20	\$23.60
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/23/2022 10:57:51	08/23/2022 10:58:30	0.01	\$1.28
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/23/2022 10:57:51	08/23/2022 10:58:30	(0.01)	(\$1.28)
					LABOR	86.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	29.30	1	\$29.30
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	29.23	1	\$29.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.38	1	\$10.38

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
					PARTS	122.98

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 44425

Work Order Notes

(CWIGLEY) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JW replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JW AMG/SH Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) JW replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 45750

USING DEPT NO:	206101	OPENED DATE:	01/10/2023 11:31:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/13/2023 14:10:34	METER 1 - M:	102741	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/17/2023 09:17:59	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.77	\$23.17	\$0.00	\$34.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.70	\$49.35	\$0.00	\$85.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.40	47.47	72.52	5.00	124.99
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/11/2023 08:41:09	01/11/2023 08:59:18	0.30	\$35.70
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/11/2023 08:21:03	01/11/2023 08:27:02	0.10	\$11.77
					LABOR	47.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.38	1	\$10.38
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
					PARTS	72.52

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 45750

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 102741 Completed PM topside, Gregg was bottomside. AMG/GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 47572

USING DEPT NO:	206101	OPENED DATE:	07/11/2023 12:13:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/13/2023 11:42:23	METER 1 - M:	106068	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/13/2023 12:43:16	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.28	\$24.05	\$0.00	\$27.33
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	2.23	\$262.71	\$0.00	\$0.00	\$262.71
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.99	\$116.69	\$385.16	\$0.00	\$501.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.59	\$37.46	\$0.00	\$83.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.33	\$39.27	\$0.00	\$0.00	\$39.27

JOB COUNT: 7	WORK ORDER TOTAL:	4.21	497.04	446.67	5.00	948.71
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	12052187	07/12/2023 14:30:00	07/12/2023 15:28:35	0.98	\$115.21
66-17-013	PERFORM ALIGNMENT	12052187	07/12/2023 13:00:00	07/12/2023 14:15:00	1.25	\$147.50
66-17-013	PERFORM ALIGNMENT	12052187	07/12/2023 12:59:47	07/12/2023 12:59:47	0.00	\$0.00
06-15	INSPECT STEERING	12201267	07/12/2023 12:16:33	07/12/2023 12:31:33	0.25	\$29.50
06-15	INSPECT STEERING	12201267	07/12/2023 12:16:33	07/12/2023 12:16:33	0.00	\$0.00
06-15	INSPECT STEERING	12201267	07/12/2023 12:16:33	07/12/2023 12:16:33	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	07/12/2023 09:56:24	07/12/2023 10:55:44	0.99	\$116.69
WA-00	WASH COMPLETE VEHICLE	12201267	07/12/2023 07:55:02	07/12/2023 08:15:00	0.33	\$39.27
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/12/2023 07:39:07	07/12/2023 07:40:47	0.03	\$3.28
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/12/2023 07:15:56	07/12/2023 07:39:07	0.39	\$45.59
				LABOR		497.04

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	69099	TIRE 205/65R16 MICH DEFENDER2	185.70	2	\$371.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	1	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.30	2	\$10.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.11	1	\$6.11
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.82	1	\$10.82
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	446.67

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 47572

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-CW

06-15 - INSPECT STEERING

(GARAGE) Inspected steering, found no issues at this time-GC

66-17-013 - PERFORM ALIGNMENT

(LISAPATE) Alignment performed by Jw

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and Balanced 2 new tires, put new tires on front-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, changed air filter, cabin filter good, tires and tire pressure.
Miles, 106,068

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 48198

USING DEPT NO:	206101	OPENED DATE:	09/13/2023 11:49:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/18/2023 09:17:10	METER 1 - M:	106093	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/18/2023 11:56:02	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.45	\$53.30	\$115.56	\$0.00	\$168.86
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.07	\$8.42	\$0.00	\$0.00	\$8.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.52	61.72	115.56	5.00	182.28
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12052187	09/13/2023 13:20:49	09/13/2023 13:47:55	0.45	\$53.30
66-79-002	PERFORM SERVICE CALL	12052187	09/13/2023 13:16:14	09/13/2023 13:20:31	0.07	\$8.42
					LABOR	61.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	115.56	1	\$115.56
					PARTS	115.56

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 48198

Work Order Notes

(LRUSHING) Service call - dead battery Tamiko 205-887-0704

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery. Alternator charging at 14.2 volts. JAW

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Went on service call and jumped unit off. Brought back to shop. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 49377

USING DEPT NO:	206101	OPENED DATE:	01/08/2024 12:23:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/10/2024 10:20:03	METER 1 - M:	107644	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/11/2024 09:06:52	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.24	\$28.48	\$0.00	\$0.00	\$28.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.37	\$0.00	\$0.00	\$33.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.25	\$28.98	\$0.00	\$0.00	\$28.98

JOB COUNT: 4	WORK ORDER TOTAL:	0.77	90.83	0.00	5.00	95.83
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	01/09/2024 09:40:42	01/09/2024 09:55:26	0.25	\$28.98
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/09/2024 09:30:00	01/09/2024 09:38:28	0.14	\$16.65
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/09/2024 09:08:59	01/09/2024 09:15:00	0.10	\$11.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/09/2024 09:07:51	01/09/2024 09:08:44	0.01	\$1.74
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/09/2024 08:43:45	01/09/2024 08:59:50	0.27	\$31.63
				LABOR		90.83

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 49377

Work Order Notes

(EHANNAH) pm- wipers-SI - wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front brake pads measure 8MM. Rear brake pads measure 7MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Driven 1576 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed was full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 51006

USING DEPT NO:	206101	OPENED DATE:	06/04/2024 07:34:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2024 12:40:21	METER 1 - M:	109999	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2024 13:30:10	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.34	\$24.08	\$0.00	\$25.42
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.02	\$54.20	\$0.00	\$55.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.56	\$0.00	\$0.00	\$0.56

JOB COUNT: 4	WORK ORDER TOTAL:	0.02	2.92	78.28	5.00	86.20
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	06/04/2024 11:50:22	06/04/2024 11:50:39	0.00	\$0.56
03-51-038	REPLACE NEW WIPER BLADES	12395904	06/04/2024 11:49:22	06/04/2024 11:50:03	0.01	\$1.34
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/04/2024 11:48:30	06/04/2024 11:49:01	0.01	\$1.02
				LABOR	2.92	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.67	1	\$11.67
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	5	\$34.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
				PARTS	78.28	

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 51006

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Perform replaced new wipers fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 53207

USING DEPT NO:	206101	OPENED DATE:	12/19/2024 07:09:02	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	12/20/2024 08:05:11	METER 1 - M:	112519	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/20/2024 08:54:48	IN-SERVICE DATE:	02/25/2014				
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$58.28	\$0.00	\$58.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	82.36	5.00	87.36
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	4.29	1	\$4.29
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.09	1	\$14.09
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	5	\$32.25
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
PARTS						82.36

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 53207

Work Order Notes

(CWIGLEY) PM. Wash. Wipers. SI Inspection

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR- replaced wiper blades

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI. Front tires: 10/32, Rear tires: 6/32. Front brakes: 7mm, Rear brakes: 6 mm.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid, filled up brake fluid, filled with non inventory coolant
112519 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) vehicle clean

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 54535

USING DEPT NO:	206101	OPENED DATE:	04/22/2025 07:12:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2025 13:45:47	METER 1 - M:	114715	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/22/2025 14:36:24	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$42.90	\$0.00	\$42.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	42.90	5.00	47.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.80	1	\$10.80
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	5	\$32.10
					PARTS	42.90

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 54535

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Blades not needed at this time.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Top Added new oil & verified level, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths)
GC- Oil change

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Washed vehicle.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 56263

USING DEPT NO:	206101	OPENED DATE:	09/08/2025 07:04:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2025 15:26:14	METER 1 - M:	115149	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/09/2025 07:12:53	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$153.56	\$0.00	\$153.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	153.56	5.00	158.56
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F-3	BATTERY	153.56	1	\$153.56
					PARTS	153.56

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 56263

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) JR- replaced battery, alternator charging, 13.8V

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, fluid check only, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
115149 miles, 434 miles driven

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 57165

USING DEPT NO:	206101	OPENED DATE:	11/11/2025 09:58:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2025 12:25:22	METER 1 - M:	115547	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/12/2025 07:05:49	IN-SERVICE DATE:	02/25/2014	
TECH SPEC NO:	14.5TOYCAMRY	2014.5 TOYOTA CAMRY L		UNIT SERIAL NO:	4T1BF1FK9EU784938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$175.00	\$0.00	\$0.00	\$175.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	175.00	0.00	5.00	180.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	11/11/2025 10:00:25	11/11/2025 10:12:26	0.20	\$35.05
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	11/11/2025 10:00:25	11/11/2025 10:12:26	(0.20)	(\$35.05)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	11/11/2025 10:00:25	11/11/2025 11:00:25	1.00	\$175.00
					LABOR	175.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/12/2025 11:38:00 By User: GLOBETTI

UNIT NO: 240421 2014 TOYOTA CAMRY

WORK ORDER NO: 57165

Work Order Notes

(EKIMBREL) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) JR- prepped vehicle for sale, no GPS, no upfittings
115547 miles

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Nov 12 2025 11:38:00 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '240421') //Q=