

Work Order Charge Detail

UNIT NO: 244178 **2021 TOYOTA CAMRY** **WORK ORDER NO:** 40812

USING DEPT NO: 508101	OPENED DATE: 08/23/2021 10:53:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/23/2021 11:00:29	METER 1 - M: 55 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/24/2021 07:21:12	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **2.00** **120.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	08/23/2021 10:59:54	08/23/2021 11:59:54	1.00	\$118.00
LABOR						118.00

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 40812

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY WORK ORDER NO: 41811

USING DEPT NO:	508101	OPENED DATE:	12/07/2021 09:06:14	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	12/22/2021 09:46:33	METER 1 - M:	93	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/04/2022 08:57:32	IN-SERVICE DATE:	08/20/2021		
TECH SPEC NO:	21TOYOTACAMRY	2021 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3MU613417		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,082.07	\$1,082.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	1,084.07	1,143.07
---------------------	--------------------------	-------------	--------------	-------------	-----------------	-----------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	5569647	5584		\$1,082.07
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					1084.07

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11915538	12/22/2021 07:00:00	12/22/2021 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 41811

Work Order Notes

(LISAPATE) Take to Browns to repair front end damage per the estimate. Dept pay under the Ded

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Browns by RC

24-71 - REPAIR BODY

(LISAPATE) Browns repaired damage to the font bumper and grille. Pd by CC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 **2021 TOYOTA CAMRY** **WORK ORDER NO:** 42117

USING DEPT NO: 508101	OPENED DATE: 01/20/2022 08:43:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/21/2022 08:06:53	METER 1 - M: 1578 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/24/2022 09:17:08	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$22.62	\$0.00	\$46.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.89	\$44.70	\$0.00	\$94.59
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.62** **73.49** **67.32** **2.00** **142.81**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/20/2022 09:08:11	01/20/2022 09:20:11	0.20	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/20/2022 09:05:27	01/20/2022 09:08:00	0.04	\$5.02
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/20/2022 09:08:11	01/20/2022 09:08:32	0.01	\$0.69
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/20/2022 09:08:11	01/20/2022 09:08:32	(0.01)	(\$0.69)
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/20/2022 08:47:07	01/20/2022 09:09:56	0.38	\$44.87
LABOR					73.49	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.10	1	\$11.10
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS					67.32	

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 42117

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-1578

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 43418

USING DEPT NO:	508101	OPENED DATE:	05/27/2022 09:54:42	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/27/2022 14:29:43	METER 1 - M:	4486	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/01/2022 14:42:06	IN-SERVICE DATE:	08/20/2021		
TECH SPEC NO:	21TOYOTACAMRY	2021 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3MU613417		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.26	\$30.65	\$0.00	\$0.00	\$30.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$94.04	\$46.70	\$0.00	\$140.74
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.28	\$33.56	\$18.57	\$0.00	\$52.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL: 1.34 158.25 65.27 2.00 225.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11310047	05/27/2022 10:49:31	05/27/2022 11:06:35	0.28	\$33.56
66-PM-PMA	PERFORM OIL CHANGE	11310047	05/27/2022 11:06:35	05/27/2022 11:54:24	0.80	\$94.04
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11310047	05/27/2022 13:02:42	05/27/2022 13:18:17	0.26	\$30.65
					LABOR 158.25	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.47	5	\$37.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.35	1	\$9.35
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	18.57	1	\$18.57
					PARTS 65.27	

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 43418

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(EHOWELL) Rotated tires. EH/SH

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) PM. Miles-4486

Top-EH/JAW

Bottom-AMG

Wipers were ok.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EHOWELL) Replaced cabin filter. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 44523

USING DEPT NO: 508101	OPENED DATE: 08/31/2022 07:07:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/01/2022 15:09:05	METER 1 - M: 8055 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/06/2022 09:24:11	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry		UNIT SERIAL NO: 4T1C11AK3MU613417

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$58.28	\$45.59	\$0.00	\$103.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.49** **58.28** **45.59** **5.00** **108.87**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2022 07:18:17	08/31/2022 07:47:55	0.49	\$58.28
					LABOR	58.28

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.01	5	\$35.03
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	10.56	1	\$10.56
					PARTS	45.59

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 44523

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 **2021 TOYOTA CAMRY** **WORK ORDER NO:** 45991

USING DEPT NO: 508101	OPENED DATE: 01/30/2023 13:33:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/01/2023 08:34:53	METER 1 - M: 12650 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/03/2023 09:50:42	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.03	\$23.26	\$0.00	\$27.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$53.36	\$75.14	\$0.00	\$128.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.49** **57.39** **98.40** **5.00** **160.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/30/2023 14:57:18	01/30/2023 14:59:21	0.03	\$4.03
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/30/2023 14:30:00	01/30/2023 14:57:08	0.45	\$53.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/30/2023 14:18:30	01/30/2023 14:18:30	0.00	\$0.00
LABOR					57.39	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	13.58	5	\$67.88
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	19260	WIPER BLADE 26 IN OE BEAM	12.79	(1)	(\$12.79)
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
PARTS					98.40	

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 45991

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 **2021 TOYOTA CAMRY** **WORK ORDER NO:** 47586

USING DEPT NO: 508101	OPENED DATE: 07/13/2023 07:20:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/14/2023 14:28:22	METER 1 - M: 15567 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/17/2023 08:49:45	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.64	\$24.08	\$0.00	\$29.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.47	\$53.48	\$0.00	\$115.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.77	\$0.00	\$0.00	\$3.77

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.61** **71.88** **77.56** **5.00** **154.44**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/14/2023 07:11:42	07/14/2023 07:43:28	0.53	\$62.47
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/14/2023 07:43:28	07/14/2023 07:46:20	0.05	\$5.64
WA-00	WASH COMPLETE VEHICLE	12201267	07/14/2023 07:46:31	07/14/2023 07:48:26	0.03	\$3.77
					LABOR 71.88	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.31	5	\$41.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.93	1	\$11.93
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
					PARTS 77.56	

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 47586

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replace wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 15,567

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 244178 **2021 TOYOTA CAMRY**

WORK ORDER NO: 49159

USING DEPT NO: 508101	OPENED DATE: 12/05/2023 13:32:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/06/2023 13:19:36	METER 1 - M: 18002 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/06/2023 13:55:49	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$24.08	\$0.00	\$41.78
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.44	\$51.99	\$0.00	\$0.00	\$51.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.74	\$46.96	\$0.00	\$89.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.33	\$38.94	\$22.73	\$0.00	\$61.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.46	\$53.89	\$0.00	\$0.00	\$53.89

JOB COUNT: 6	WORK ORDER TOTAL:	1.74	205.26	93.77	5.00	304.03
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/05/2023 14:32:28	12/05/2023 14:54:12	0.36	\$42.74
66-79-003	PERFORM SAFETY INSPECTION	11074414	12/05/2023 14:55:10	12/05/2023 15:21:36	0.44	\$51.99
WA-00	WASH COMPLETE VEHICLE	11074414	12/05/2023 15:21:49	12/05/2023 15:49:13	0.46	\$53.89
03-51-038	REPLACE NEW WIPER BLADES	12395904	12/06/2023 07:00:00	12/06/2023 07:09:00	0.15	\$17.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	12/06/2023 07:09:00	12/06/2023 07:28:48	0.33	\$38.94
					LABOR	205.26

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.91	5	\$39.53
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
					PARTS	93.77

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 49159

Work Order Notes

(EHANNAH) pm- wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front and rear brake pads measure 8MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 244178 **2021 TOYOTA CAMRY**

WORK ORDER NO: 51417

USING DEPT NO: 508101	OPENED DATE: 07/09/2024 13:42:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/11/2024 09:05:25	METER 1 - M: 21130 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/17/2024 12:47:56	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.08	\$51.02	\$0.00	\$52.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.56	\$0.00	\$0.00	\$0.56

JOB COUNT: 3	WORK ORDER TOTAL:	0.01	1.64	51.02	5.00	57.66
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	07/09/2024 14:35:39	07/09/2024 14:35:56	0.00	\$0.56
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/09/2024 14:34:47	07/09/2024 14:35:20	0.01	\$1.08
LABOR					1.64	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	7.31	5	\$36.53
PARTS					51.02	

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 51417

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers. Will probably need tires at next pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 51747

USING DEPT NO: 508101	OPENED DATE: 08/08/2024 12:39:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/15/2024 11:48:39	METER 1 - M: 21610 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/16/2024 13:22:29	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry		UNIT SERIAL NO: 4T1C11AK3MU613417

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 51747

Work Order Notes

(EHANNAH) PM- WIPERS-BRAKES ARE SQUEAKING- WASH

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-13 - INSPECT BRAKES

(GARAGE) Inspected brakes. heard minor squeaking while driving into shop. All pads are 8mm front and back. No rocks hung up in rotors. Cleaned all brake dust off of rotors and pads. Test drove and found no other issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 53595

USING DEPT NO: 508101	OPENED DATE: 02/03/2025 13:36:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/05/2025 09:14:08	METER 1 - M: 23933 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/05/2025 13:34:10	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry	UNIT SERIAL NO: 4T1C11AK3MU613417	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$893.64	\$0.00	\$893.64
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$56.93	\$0.00	\$56.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	974.65	5.00	979.65
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	17537	TIRE 215/55R17 MICH DEF2	220.50	4	\$882.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.91	4	\$11.64
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	9.30	5	\$46.50
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
PARTS						974.65

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 53595

Work Order Notes

(EHANNAH) pm- wipers- wash SI
(GARAGE) Pending SI.
(GARAGE) customer needs vehicle and will bring it back at 2:00

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades.

66-17-013 - PERFORM ALIGNMENT

(GARAGE) PULLED CAR ON ALIGNMENT LIFT, SET TOE ON THE FRONT AND BACK. ALL CHECKED IN SPEC. CQ, CM

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) GC- mounted and balanced 4 new tires on unit 3784C
Miles, 23,933

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) GC- performed safety inspection, found no issues at this time, other than tires are measuring a 5 they have a good bit of sholder wear, and Issac said to replace all 4.
Brake pads are 7mm front and 6mm rear
miles, 23,933

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC/JR- Top
FJ- Bottom
GC/JR- Added oil, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.
FJ- Oil change.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 55760

USING DEPT NO: 508101	OPENED DATE: 08/05/2025 14:25:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/06/2025 09:15:06	METER 1 - M: 26149 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/06/2025 15:26:25	IN-SERVICE DATE: 08/20/2021
TECH SPEC NO: 21TOYOTACAMRY 2021 Toyota Camry		UNIT SERIAL NO: 4T1C11AK3MU613417

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$32.76	\$0.00	\$32.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$81.05	\$0.00	\$81.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	113.81	5.00	118.81
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	26.71	(1)	(\$26.71)
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER	32.15	1	\$32.15
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 QT	8.28	5	\$41.40
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	26.71	1	\$26.71
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	17.72	1	\$17.72
PARTS						113.81

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 55760

Work Order Notes

(CWIGLEY) PM. Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Changed blades

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 26,149 miles

JR- Checked filters, set tire pressure, recorded date codes & tread depths, topped off fluids

FJ- Oil change, added & checked oil, changed engine air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 57558

USING DEPT NO:	508101	OPENED DATE:	12/11/2025 08:16:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2025 08:53:13	METER 1 - M:	27789	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2025 12:04:49	IN-SERVICE DATE:	08/20/2021	
TECH SPEC NO:	21TOYOTACAMRY	2021 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3MU613417	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2 **WORK ORDER TOTAL: 1.00 150.00 0.00 5.00 155.00**

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	12/11/2025 08:23:04	12/11/2025 09:23:04	1.00	\$150.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	12/11/2025 08:23:04	12/11/2025 08:51:01	0.47	\$69.88
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	12/11/2025 08:23:04	12/11/2025 08:51:01	(0.47)	(\$69.88)
LABOR						150.00

Work Order Charge Detail

UNIT NO: 244178 2021 TOYOTA CAMRY

WORK ORDER NO: 57558

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) CM Perform prep for sale unit had 27789 miles,

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Dec 12 2025 11:47:36 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244178') //Q=