

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 43875

USING DEPT NO: 209317	OPENED DATE: 07/07/2022 15:07:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/07/2022 15:08:19	METER 1 - M: 9 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/11/2022 09:51:44	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **2.00** **120.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	07/07/2022 15:07:45	07/07/2022 16:07:45	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 43875

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed by AG

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 44939

USING DEPT NO: 209317	OPENED DATE: 10/10/2022 15:42:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/14/2022 08:31:35	METER 1 - M: 3904 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2022 08:47:08	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR	2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.09	\$0.00	\$0.00	\$16.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.14** **16.09** **0.00** **5.00** **21.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/11/2022 10:23:30	10/11/2022 10:31:41	0.14	\$16.09
					LABOR	16.09

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 44939

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Checked fluids and tires. Coolant -34°. JAW
MILEAGE-3904

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46337

USING DEPT NO: 209317	OPENED DATE: 03/02/2023 15:11:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/03/2023 11:55:53	METER 1 - M: 8150 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/03/2023 14:13:36	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander		UNIT SERIAL NO: 5TDZZRAH4NS126565

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.08	\$0.00	\$0.00	\$15.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.13** **15.08** **0.00** **5.00** **20.08**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/03/2023 07:27:40	03/03/2023 07:35:20	0.13	\$15.08
					LABOR	15.08

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46337

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, Fluid check only, checked tires and tire pressure, filters are good.
Miles, 8,150

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46966

Work Order Notes

(CHANNELL) pm

Job Notes

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Pm done by Tuscaloosa Toyota for 10,000 mile service no charge.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(IFALLS) did not wash

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48317

USING DEPT NO: 209317	OPENED DATE: 09/25/2023 09:28:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/26/2023 07:41:51	METER 1 - M: 15636 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/26/2023 08:17:22	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$46.67	\$0.00	\$85.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	46.67	5.00	90.61
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/26/2023 07:00:00	09/26/2023 07:19:48	0.33	\$38.94
LABOR					38.94	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	6.80	6	\$40.77
PARTS					46.67	

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48317

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed by FC

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48428

USING DEPT NO: 209317	OPENED DATE: 10/06/2023 10:08:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/09/2023 08:41:21	METER 1 - M: 16280 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/10/2023 09:41:05	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.21	\$24.52	\$0.00	\$0.00	\$24.52
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.54	\$63.46	\$9.65	\$0.00	\$73.11
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.75	87.98	9.65	5.00	102.63
---------------------	--------------------------	-------------	--------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	10/06/2023 13:00:35	10/06/2023 13:23:18	0.38	\$44.68
66-17-030	PERFORM TIRE PATCH	11074414	10/06/2023 13:00:35	10/06/2023 13:23:18	(0.38)	(\$44.68)
66-17-030	PERFORM TIRE PATCH	11074414	10/06/2023 13:00:35	10/06/2023 13:23:18	0.38	\$44.68
66-17-030	PERFORM TIRE PATCH	11074414	10/06/2023 11:09:34	10/06/2023 11:19:07	0.16	\$18.78
66-17-030	PERFORM TIRE PATCH	11074414	10/06/2023 11:09:34	10/06/2023 11:19:07	(0.16)	(\$18.78)
66-17-030	PERFORM TIRE PATCH	11074414	10/06/2023 11:09:34	10/06/2023 11:19:07	0.16	\$18.78
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	10/06/2023 10:55:15	10/06/2023 11:07:43	0.21	\$24.52
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	10/06/2023 10:55:15	10/06/2023 11:07:43	(0.21)	(\$24.52)
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	10/06/2023 10:55:15	10/06/2023 11:07:43	0.21	\$24.52
LABOR					87.98	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.80	1	\$4.80

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	61133	LT1 2.00 OZ WHEEL WEIGHT	1.77	19	\$33.63
66-17-030	PERFORM TIRE PATCH	61133	LT1 2.00 OZ WHEEL WEIGHT	1.77	(19)	(\$33.63)
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	19	\$4.85
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.80	(1)	(\$4.80)
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	(19)	(\$4.85)
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.80	1	\$4.80
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	19	\$4.85
					PARTS	9.65

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48428

Work Order Notes

(EHANNAH) DR tire is low please check it.

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) Inspected tire. Has a nail in it. Can be patched. SH
(LRUSHING) Visit Reason Changed On 10/18/2023 3:18 PM By LRUSHING

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched the left rear tire. Drove vehicle to reset the TPMS light. SH
(LRUSHING) Visit Reason Changed On 10/18/2023 3:18 PM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 10/18/2023 3:18 PM By LRUSHING

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 49759

USING DEPT NO: 209317	OPENED DATE: 02/09/2024 15:28:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/12/2024 12:21:25	METER 1 - M: 21733 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/12/2024 14:10:36	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$65.52	\$53.00	\$0.00	\$118.52
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.41	\$47.82	\$0.00	\$0.00	\$47.82

JOB COUNT: 3	WORK ORDER TOTAL:	0.96	113.34	53.00	5.00	171.34
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	02/12/2024 09:44:30	02/12/2024 10:08:49	0.41	\$47.82
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/12/2024 08:41:41	02/12/2024 09:15:00	0.56	\$65.52
LABOR					113.34	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
PARTS					53.00	

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 49759

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil hanged fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed full of gas. SH

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 51285

USING DEPT NO: 209317	OPENED DATE: 06/24/2024 15:35:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/25/2024 13:55:50	METER 1 - M: 25282 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/25/2024 14:37:07	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander		UNIT SERIAL NO: 5TDZZRAH4NS126565

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.92	\$53.43	\$0.00	\$54.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.95	\$0.00	\$0.00	\$0.95

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	1.87	53.43	5.00	60.30
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/25/2024 10:38:38	06/25/2024 10:39:07	0.01	\$0.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/25/2024 10:17:18	06/25/2024 10:17:46	0.01	\$0.92
					LABOR	1.87

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
					PARTS	53.43

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 51285

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed was full of gas. SH

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 53140

USING DEPT NO: 209317	OPENED DATE: 12/13/2024 10:13:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/17/2024 13:43:59	METER 1 - M: 26703 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/17/2024 14:27:00	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$34.15	\$0.00	\$34.15
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$32.15	\$0.00	\$32.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$34.07	\$0.00	\$34.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	100.37	5.00	105.37
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER	32.15	1	\$32.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	34.07	1	\$34.07
03-51-038	REPLACE NEW WIPER BLADES	10A	10" WIPER	10.07	1	\$10.07
						PARTS 100.37

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 53140

Work Order Notes

(EHANNAH) pm- SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- replaced wiper blades

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm checked ok,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, fluid check only, checked fluids, checked tires and tire pressures

FJ replaced both air filters

26703 miles

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FJ- replaced cabin air filters

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- wash vehicle

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 54546

USING DEPT NO: 209317	OPENED DATE: 04/22/2025 10:10:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/22/2025 13:46:49	METER 1 - M: 31904 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/22/2025 14:35:15	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR	2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$49.32	\$0.00	\$49.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	49.32	5.00	54.32
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.80	1	\$10.80
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
PARTS						49.32

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 54546

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PM. Mileage is 31,904.

JR- Top side (topped off fluids, set tire pressure, recorded date codes & tread depths)

GC- Oil change

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Washed vehicle.

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 56136

USING DEPT NO: 209317	OPENED DATE: 08/28/2025 12:25:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/29/2025 07:38:51	METER 1 - M: 34331 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/29/2025 12:14:58	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$46.63	\$49.02	\$0.00	\$95.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.37	46.63	49.02	5.00	100.65
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11779687	08/29/2025 07:14:10	08/29/2025 07:36:33	0.37	\$46.63
LABOR					46.63	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.59	1	\$10.59
PARTS					49.02	

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 56136

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 34,331 miles

JR- Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths

FJ- Oil change, added oil & checked oil level

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 56759

USING DEPT NO: 209317	OPENED DATE: 10/10/2025 07:48:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/10/2025 09:07:35	METER 1 - M: 34331 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/10/2025 13:15:01	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander	UNIT SERIAL NO: 5TDZZRAH4NS126565	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
CL-01	CLEANED AIR CONDITIONING, HEAT, V	DON	N	N	GARAGE	0.05	\$8.13	\$0.00	\$0.00	\$8.13

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.05** **8.13** **0.00** **5.00** **13.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-01	CLEANED AIR CONDITIONING, HEAT, VENT	12201267	10/10/2025 08:02:04	10/10/2025 08:05:19	0.05	\$8.13
LABOR						8.13

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 56759

Work Order Notes

Job Notes

CH-SP - CHARGE Shop Supplies

CL-01 - CLEANED AIR CONDITIONING, HEAT, VENT

(GARAGE) GC- early college unit came in for passenger side floor board wet, inspected unit and found that the A/C drain coming off the condenser was stopped up. removed the trim pieces and pulled back the flooring and put a fan on unit for 2 days and let dry. pulled the A/C drain off and blew air through it to make sure nothing else was in the line, all is good. put everything back together. 1 hour labor

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 57285

USING DEPT NO: 209317	OPENED DATE: 11/20/2025 13:24:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/20/2025 14:43:34	METER 1 - M: 37551 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/24/2025 07:57:10	IN-SERVICE DATE: 07/05/2022
TECH SPEC NO: 22TOYHIGHLNDR 2022 Toyota Highlander		UNIT SERIAL NO: 5TDZZRAH4NS126565

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **150.00** **0.00** **5.00** **155.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/20/2025 14:12:42	11/20/2025 14:42:42	0.50	\$75.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/20/2025 14:30:00	11/20/2025 15:00:00	0.50	\$75.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/20/2025 14:12:42	11/20/2025 14:15:00	0.04	\$5.75
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/20/2025 14:12:42	11/20/2025 14:15:00	(0.04)	(\$5.75)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/20/2025 14:30:00	11/20/2025 14:40:05	0.17	\$25.21
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	11/20/2025 14:30:00	11/20/2025 14:40:05	(0.17)	(\$25.21)
LABOR						150.00

Work Order Charge Detail

UNIT NO: 244757 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 57285

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm performed prep for sale unit had 37,551 miles

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Dec 04 2025 12:07:08 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244757') //Q=