

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 26148

USING DEPT NO: 505141	OPENED DATE: 04/14/2017 09:28:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/17/2017 07:23:36	METER 1 - M: 333 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 04/17/2017 07:23:39	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA 2017 Toyota Tacoma		UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11792814	04/14/2017 09:29:52	04/14/2017 09:59:52	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 26148

Work Order Notes

(IFALLS) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(IFALLS) TB PERFORMED PDI

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 26331

USING DEPT NO: 505141	OPENED DATE: 05/11/2017 08:14:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/24/2017 10:41:28	METER 1 - M: 503 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/24/2017 10:41:29	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.30	\$17.25	\$287.22	\$0.00	\$304.47
14-51-062	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$900.00	\$0.00	\$928.75

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.80** **46.00** **1,187.22** **0.00** **1,233.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-51-062	INSTALL TOOLBOX ASSY	11758845	05/23/2017 07:00:00	05/23/2017 07:30:00	0.50	\$28.75
14-02-013	INSTALL FLOOR COVERINGS	11237753	05/23/2017 07:00:00	05/23/2017 07:18:00	0.30	\$17.25
					LABOR	46.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	0448671	WEATHERGUARD FLOOR MATS FRONT	163.14	1	\$163.14
14-02-013	INSTALL FLOOR COVERINGS	0448722	WEATHERGUARD FLOOR MATS REAR	108.33	1	\$108.33
14-51-062	INSTALL TOOLBOX ASSY	WEA154001 TOOLBOX	TOOLBOX ASSY	900.00	1	\$900.00
14-02-013	INSTALL FLOOR COVERINGS	SHIPPING	SHIPPING AND HANDLING	15.75	1	\$15.75
					PARTS	1187.22

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 26331

Work Order Notes

(LISAPATE) JAN REQUESTED FLOORMATS AND TOOLBOX FOR TRUCK

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(LISAPATE) INSTALLED 4 FLOOR MATS FOR FRONT AND REAR

14-51-062 - INSTALL TOOLBOX ASSY

(LISAPATE) INSTALLED TOOL BOX ASSY

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 29126

USING DEPT NO:	505141	OPENED DATE:	03/20/2018 08:42:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/23/2018 07:31:21	METER 1 - M:	1700	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/23/2018 07:31:23	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.49	\$0.00	\$51.32

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 33.49 0.00 51.32

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/20/2018 11:02:35	03/20/2018 11:21:11	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.58	1	\$6.58
					PARTS	33.49

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 29126

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/AG
COOLANT -45'

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA WORK ORDER NO: 32771

USING DEPT NO:	505141	OPENED DATE:	04/30/2019 08:40:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2019 09:06:52	METER 1 - M:	3100	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2019 09:06:53	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$8.70	\$41.52	\$0.00	\$50.22

JOB COUNT: 1 WORK ORDER TOTAL: 0.12 8.70 41.52 0.00 50.22

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/30/2019 09:59:20	04/30/2019 10:06:32	0.12	\$8.70
					LABOR	8.70

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	5.84	6	\$35.01
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.51	1	\$6.51
					PARTS	41.52

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 32771

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 242269 **2017 TOYOTA TACOMA** **WORK ORDER NO:** 34440

USING DEPT NO:	505141	OPENED DATE:	10/14/2019 10:46:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/15/2019 09:46:04	METER 1 - M:	3739	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/15/2019 09:46:05	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.07	\$77.82	\$41.12	\$0.00	\$118.94

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.07** **77.82** **41.12** **0.00** **118.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/14/2019 13:00:59	10/14/2019 14:05:23	1.07	\$77.82
					LABOR	77.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	5.82	6	\$34.92
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.20	1	\$6.20
					PARTS	41.12

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 34440

Work Order Notes

(LISAPATE) PM-Low tire light is on

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH
Coolant -35'

Adjusted tire pressures light went off

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA WORK ORDER NO: 35592

USING DEPT NO:	505141	OPENED DATE:	02/06/2020 11:03:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2020 09:29:16	METER 1 - M:	4125	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/14/2020 09:29:17	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.27	\$19.25	\$114.81	\$0.00	\$134.06

JOB COUNT: 1 WORK ORDER TOTAL: 0.27 19.25 114.81 0.00 134.06

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	10208562	02/06/2020 11:05:55	02/06/2020 11:21:51	0.27	\$19.25
					LABOR	19.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.63	2	\$1.26
					PARTS	114.81

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 35592

Work Order Notes

(LISAPATE) Had to jump off-dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery and added corrosion washers.

Work Order Charge Detail

UNIT NO: 242269 **2017 TOYOTA TACOMA** **WORK ORDER NO:** 36503

USING DEPT NO: 505141	OPENED DATE: 05/19/2020 14:19:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/20/2020 11:34:10	METER 1 - M: 4297 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/20/2020 15:33:42	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$21.75	\$41.40	\$0.00	\$63.15

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.30** **21.75** **41.40** **0.00** **63.15**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/20/2020 07:00:00	05/20/2020 07:18:00	0.30	\$21.75
					LABOR	21.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	5.82	6	\$34.92
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	5.82	(7)	(\$40.74)
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	5.82	7	\$40.74
					PARTS	41.40

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 36503

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AB/AG performed pm. Coolant -35

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 38194

USING DEPT NO:	505141	OPENED DATE:	10/28/2020 10:55:17	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2020 13:26:51	METER 1 - M:	5689	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/11/2020 15:05:49	IN-SERVICE DATE:	04/06/2017		
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-34-020	WARRANTY THIRD BRAKE LIGHT BULB	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-34	TRANSPORT LIGHTING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.56	\$0.00	\$0.00	\$47.56
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.10	\$11.80	\$13.59	\$0.00	\$25.39

JOB COUNT: 4	WORK ORDER TOTAL:	1.00	118.36	13.59	0.00	131.95
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-34-020	WARRANTY THIRD BRAKE LIGHT BULB/ASSY	11076422	6098343		\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-34	TRANSPORT LIGHTING SYSTEM	10208562	11/11/2020 07:00:00	11/11/2020 07:30:00	0.50	\$59.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/11/2020 07:00:00	11/11/2020 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/28/2020 13:50:12	10/28/2020 14:14:23	0.40	\$47.56
				LABOR		118.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
					PARTS	13.59

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 38194

Work Order Notes

(LISAPATE) PM

(LISAPATE) Take to Tuscaloosa Toyota to goodwill warranty 3rd brake light leaking water

Job Notes

15-34-020 - WARRANTY THIRD BRAKE LIGHT BULB/ASSY

(LISAPATE) Tuscaloosa Toyota goodwill replaced center rear center brake light

16-34 - TRANSPORT LIGHTING SYSTEM

(LISAPATE) Take n to Ford by RC/EK

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 4586 Vehicle has been 289 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 38455

USING DEPT NO:	505141	OPENED DATE:	11/23/2020 08:34:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/24/2020 13:35:53	METER 1 - M:	4586	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2020 07:42:56	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-79	TRANSPORT SAFETY DEVICES	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-01-004	RECALL BLOWER MOTOR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-22-003	RECALL DIFFERENTIAL CARRIER	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	0.00	59.00
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-01-004	RECALL BLOWER MOTOR	11076422	6100973		\$0.00
				COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-79	TRANSPORT SAFETY DEVICES	11915538	11/24/2020 07:00:00	11/24/2020 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 38455

Work Order Notes

(LISAPATE) Take to Tuscaloosa Toyota to complete recalls

Job Notes

16-79 - TRANSPORT SAFETY DEVICES

(LISAPATE) Taken to Toyota by RC

17-01-004 - RECALL BLOWER MOTOR

(LISAPATE) Completed special service campaign HVAC blower motor

17-22-003 - RECALL DIFFERENTIAL CARRIER

(LISAPATE) Completed safety recall HOG Rear Differential

17-79-001 - RECALL AIR BAG

Work Order Charge Detail

UNIT NO: 242269 **2017 TOYOTA TACOMA** **WORK ORDER NO:** 40233

USING DEPT NO: 505141	OPENED DATE: 06/23/2021 10:53:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/25/2021 10:04:36	METER 1 - M: 5080 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/25/2021 13:26:29	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.19	\$39.93	\$0.00	\$72.12

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.27** **32.19** **39.93** **0.00** **72.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/23/2021 11:39:18	06/23/2021 11:55:40	0.27	\$32.19
					LABOR	32.19

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
					PARTS	39.93

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 40233

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5080 Completed PM bottomside, Andrew was topside. Completed checklist and vacuumed out vehicle. AB/AMG

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 41849

USING DEPT NO: 505141	OPENED DATE: 12/10/2021 09:48:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/13/2021 10:49:18	METER 1 - M: 5503 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/13/2021 13:20:29	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.92	\$15.18	\$0.00	\$20.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.38	\$6.56	\$0.00	\$54.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.45	53.30	21.74	2.00	77.04
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/10/2021 14:04:10	12/10/2021 14:06:40	0.04	\$4.92
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/10/2021 13:35:25	12/10/2021 14:00:01	0.41	\$48.38
LABOR					53.30	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	21-1	21" WIPER	7.59	1	\$7.59
PARTS					21.74	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 41849

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5503 Vehicle has been 423 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 42673

USING DEPT NO: 505141	OPENED DATE: 03/22/2022 09:41:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/25/2022 07:56:36	METER 1 - M: 5674 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/25/2022 13:42:07	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.39	\$45.99	\$10.07	\$0.00	\$56.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.39** **45.99** **10.07** **2.00** **58.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	03/22/2022 09:50:39	03/22/2022 10:14:02	0.39	\$45.99
LABOR					45.99	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	58105	1.50 OZ WHEEL WEIGHT	0.81	1	\$0.81
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.83	1	\$4.83
PARTS					10.07	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 42673

Work Order Notes

(LISAPATE) Nail in LR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched left rear tire. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 **2017 TOYOTA TACOMA** **WORK ORDER NO:** 43088

USING DEPT NO: 505141	OPENED DATE: 04/29/2022 09:12:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/02/2022 11:35:21	METER 1 - M: 5674 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/03/2022 07:56:53	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.77	\$15.18	\$0.00	\$18.95
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$21.93	\$0.00	\$0.00	\$21.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.22	25.70	15.18	2.00	42.88
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/29/2022 13:15:15	04/29/2022 13:17:10	0.03	\$3.77
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/29/2022 13:03:56	04/29/2022 13:15:05	0.19	\$21.93
LABOR					25.70	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	21-1	21" WIPER	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
PARTS					15.18	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 43088

Work Order Notes

(CHANNELL) pm replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 684 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-5754

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 44672

USING DEPT NO:	505141	OPENED DATE:	09/13/2022 09:40:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2022 10:57:57	METER 1 - M:	6019	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/21/2022 12:25:58	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.17	\$137.63	\$0.00	\$0.00	\$137.63
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.28	\$150.94	\$1,049.25	\$0.00	\$1,200.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.09	\$40.34	\$0.00	\$54.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.05	\$12.55	\$0.00	\$13.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.82	333.21	1,102.14	5.00	1,440.35
---------------------	--------------------------	-------------	---------------	-----------------	-------------	-----------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	11310047	09/19/2022 13:00:00	09/19/2022 13:40:57	0.68	\$80.54
66-17-013	PERFORM ALIGNMENT	11310047	09/19/2022 11:30:58	09/19/2022 12:00:00	0.48	\$57.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/19/2022 10:13:35	09/19/2022 11:30:20	1.28	\$150.94
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/19/2022 10:12:50	09/19/2022 10:13:22	0.01	\$1.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/13/2022 14:30:00	09/13/2022 14:31:30	0.03	\$2.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/13/2022 14:09:20	09/13/2022 14:15:00	0.09	\$11.14
06-15	INSPECT STEERING	11074414	09/21/2022 07:00:00	09/21/2022 07:15:00	0.25	\$29.50
					LABOR	333.22

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	12.55	1	\$12.55
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.88	4	\$23.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	3	\$0.77
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.32	3	\$0.95

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.69	1	\$5.69
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	08710	TIRE LT245/75R16 MICH DEFENDER	255.51	4	\$1,022.04
PARTS						1102.14

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 44672

Work Order Notes

(LISAPATE) PM

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) SH checked steering

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. Vehicle needs 4 tires due to DOT dates. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 **2017 TOYOTA TACOMA** **WORK ORDER NO:** 46123

USING DEPT NO:	505141	OPENED DATE:	02/13/2023 09:26:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2023 09:42:33	METER 1 - M:	6613	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2023 11:26:43	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.41	\$47.92	\$0.00	\$0.00	\$47.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$25.14	\$0.00	\$0.00	\$25.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.62** **73.06** **0.00** **5.00** **78.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11074414	02/13/2023 11:17:23	02/13/2023 11:41:45	0.41	\$47.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/13/2023 11:04:24	02/13/2023 11:17:11	0.21	\$25.14
LABOR					73.06	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 46123

Work Order Notes

(EHANNAH) pm- replace wipers, perform safety inspection.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 406 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 46622

USING DEPT NO:	505141	OPENED DATE:	04/05/2023 09:47:40	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2023 07:50:37	METER 1 - M:	6679	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/07/2023 14:36:20	IN-SERVICE DATE:	04/06/2017		
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.04	\$4.75	\$3.41	\$0.00	\$8.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.04 4.75 3.41 5.00 13.16

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-042	REPLACE NEW KEY FOB BATTERY	11074414	04/05/2023 09:53:47	04/05/2023 09:56:12	0.04	\$4.75
					LABOR	4.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.41	1	\$3.41
					PARTS	3.41

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 46622

Work Order Notes

(EHANNAH) replace new key fob battery

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(SHARBIN) Replaced a key fob battery per customer request. Rechecks good. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 47407

USING DEPT NO:	505141	OPENED DATE:	06/22/2023 08:05:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/26/2023 14:20:12	METER 1 - M:	7017	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2023 11:10:44	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.57	\$21.70	\$0.00	\$31.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.70	\$43.85	\$0.00	\$61.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.23	\$27.07	\$0.00	\$0.00	\$27.07

JOB COUNT: 4 **WORK ORDER TOTAL: 0.46 54.34 65.55 5.00 124.89**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	07/26/2023 13:35:09	07/26/2023 13:48:55	0.23	\$27.07
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/26/2023 13:30:17	07/26/2023 13:35:09	0.08	\$9.57
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/26/2023 13:21:17	07/26/2023 13:30:17	0.15	\$17.70
					LABOR 54.34	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.23	1	\$6.23
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
					PARTS 65.55	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 47407

Work Order Notes

(EHANNAH) pm- replace wipers - wash
(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EHANNAH) The job was restored for Work Order# 47407. By User ID EHANNAH on 7/26/2023 9:39 AM.
(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(EHANNAH) The job was restored for Work Order# 47407. By User ID EHANNAH on 7/26/2023 9:39 AM.
(GARAGE) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 49173

USING DEPT NO:	505141	OPENED DATE:	12/07/2023 14:04:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2023 09:21:33	METER 1 - M:	7964	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2023 13:05:55	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.11	\$0.00	\$0.00	\$9.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.63	\$74.27	\$0.00	\$0.00	\$74.27

JOB COUNT: 3	WORK ORDER TOTAL:	0.71	83.38	0.00	5.00	88.38
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	12/08/2023 06:50:17	12/08/2023 07:28:03	0.63	\$74.27
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/07/2023 15:08:09	12/07/2023 15:12:47	0.08	\$9.11
LABOR					83.38	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 49173

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 51360

USING DEPT NO:	505141	OPENED DATE:	07/01/2024 09:24:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/02/2024 14:42:18	METER 1 - M:	8500	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/02/2024 14:42:21	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.02	\$22.50	\$0.00	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.95	\$48.30	\$0.00	\$49.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.52	\$0.00	\$0.00	\$0.52

JOB COUNT: 4 **WORK ORDER TOTAL: 0.02 2.49 70.80 5.00 78.29**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	07/01/2024 10:14:00	07/01/2024 10:14:16	0.00	\$0.52
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/01/2024 10:13:13	07/01/2024 10:13:42	0.01	\$0.95
03-51-038	REPLACE NEW WIPER BLADES	12395904	07/01/2024 10:12:21	07/01/2024 10:12:52	0.01	\$1.02
					LABOR 2.49	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	XC21	21" WIPER	11.25	1	\$11.25
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	1	\$11.25
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
					PARTS 70.80	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 51360

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 52824

USING DEPT NO: 505141	OPENED DATE: 11/15/2024 13:13:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/15/2024 13:34:16	METER 1 - M: 8968 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/18/2024 13:59:20	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 52824

Work Order Notes

(EHANNAH) tire patch in RF tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GARAGE) FJ- Nail in RF tire. Nail did not puncture tire. No leaks found at this time.

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 53066

USING DEPT NO: 505141	OPENED DATE: 12/10/2024 14:50:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/11/2024 14:26:56	METER 1 - M: 9091 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/12/2024 07:25:59	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA 2017 Toyota Tacoma		UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 53066

Work Order Notes

(EHANNAH) pm- wipers- SI- Wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- did not need wipers

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm everything checked ok,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, fluid check only, checked air filters, checked fluids, checked tires and tire pressures
9091 miles

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed cm

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 54656

USING DEPT NO:	505141	OPENED DATE:	05/02/2025 08:54:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2025 07:47:21	METER 1 - M:	9411	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/06/2025 15:44:36	IN-SERVICE DATE:	04/06/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN4HX085801	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$30.08	\$0.00	\$30.08
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$3.23	\$0.00	\$3.23
16-00	TRANSPORT COMPLETE VEHICLE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$45.14	\$0.00	\$45.14
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$24.18	\$0.00	\$24.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PR-51-044	PROGRAM KEY FOB/REMOTE	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$295.68	\$295.68

JOB COUNT: 7 **WORK ORDER TOTAL:** **0.00** **0.00** **102.63** **300.68** **403.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
PR-51-044	PROGRAM KEY FOB/REMOTE	11076422	6293535		\$295.68
COMML					300.68

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.62	1	\$6.62
03-51-038	REPLACE NEW WIPER BLADES	25-210	21" WIPER	15.04	1	\$15.04
03-51-038	REPLACE NEW WIPER BLADES	25-220	BEAM WIPER BLADE	15.04	1	\$15.04
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	24.18	1	\$24.18
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.23	1	\$3.23
PARTS						102.63

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 54656

Work Order Notes

(EHANNAH) pm- wipers- wash- check fob possibly battery

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- replaced wiper blades

03-51-042 - REPLACE NEW KEY FOB BATTERY

(EHOWELL) FJ REPLACED KEY FOB BATTERY, but the remote/fob still did not function.

06-51-044 - INSPECT KEY FOB/REMOTE

16-00 - TRANSPORT COMPLETE VEHICLE

(GARAGE) JR- took vehicle to tuscaloosa toyota for a new key

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
JR- filled with oil, checked oil level
6411 miles

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FJ- replaced cabin air filter

CH-SP - CHARGE Shop Supplies

PR-51-044 - PROGRAM KEY FOB/REMOTE

(GARAGE) JR- tuscaloosa toyota cut and programmed new key

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 56689

USING DEPT NO: 505141	OPENED DATE: 10/07/2025 08:43:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/07/2025 09:02:28	METER 1 - M: 9767 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/07/2025 11:12:13	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$41.00	\$0.00	\$0.00	\$41.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.27** **41.00** **0.00** **5.00** **46.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12480657	10/07/2025 08:44:46	10/07/2025 09:01:10	0.27	\$41.00
LABOR						41.00

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 56689

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) cm performed pm 9767 miles, fluid checked, checked all fluids tires filters checked ok, changed oil change sticker, put insurance sticker in console, unit checked ok,

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 57700

USING DEPT NO: 505141	OPENED DATE: 01/02/2026 08:20:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/02/2026 09:12:17	METER 1 - M: 10077 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/06/2026 10:40:42	IN-SERVICE DATE: 04/06/2017
TECH SPEC NO: 17TOYTACOMA	2017 Toyota Tacoma	UNIT SERIAL NO: 5TFAX5GN4HX085801

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-51-062	REMOVE TOOLBOX ASSY	DON	5	N	GARAGE	0.25	\$37.50	\$0.00	\$0.00	\$37.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.25	187.50	0.00	5.00	192.50
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11779687	01/02/2026 08:29:40	01/02/2026 09:29:40	1.00	\$150.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11779687	01/02/2026 08:29:40	01/02/2026 09:05:40	0.60	\$90.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11779687	01/02/2026 08:29:40	01/02/2026 09:05:40	(0.60)	(\$90.00)
25-51-062	REMOVE TOOLBOX ASSY	11779687	01/05/2026 07:00:00	01/05/2026 07:15:00	0.25	\$37.50
LABOR					187.50	

Work Order Charge Detail

UNIT NO: 242269 2017 TOYOTA TACOMA

WORK ORDER NO: 57700

Work Order Notes

(EKIMBREL) prep for sale

Job Notes

25-51-062 - REMOVE TOOLBOX ASSY

(EHOWELL) FJ removed toolbox.

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) 10,077 miles

FJ- Prep for sale. Removed all UA paperwork, removed lettering/wordmarks, removed RFID & oil change stickers, noted any damage (interior & exterior), removed state tag & stored it w/ w/o.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Jan 06 2026 15:28:07 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242269') //Q=