

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 10455

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 02/27/2012 14:36:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/29/2012 13:23:17	<b>METER 1 - M:</b> 7941 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/29/2012 13:23:19	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.04	\$2.40	\$39.27	\$0.00	\$41.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.07	\$61.46	\$41.25	\$0.00	\$102.71

**JOB COUNT: 2** **WORK ORDER TOTAL:** **1.11** **63.86** **80.52** **0.00** **144.38**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/28/2012 09:35:59	02/28/2012 09:38:29	0.04	\$2.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/28/2012 08:21:40	02/28/2012 09:25:48	1.07	\$61.46
					<b>LABOR</b>	<b>63.86</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.64	2	\$39.27
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
					<b>PARTS</b>	<b>80.52</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 10455

---

## Work Order Notes

(LPATE) PM-REPLACE WIPERS

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY SH/RS-REPLACED OIL DRAIN PLUG

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 12021

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 10/02/2012 10:14:37	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/03/2012 14:27:05	<b>METER 1 - M:</b> 9232 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/03/2012 14:27:08	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$41.88	\$44.78	\$0.00	\$86.66

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.73** **41.88** **44.78** **0.00** **86.66**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	10/02/2012 10:14:29	10/02/2012 10:36:35	0.37	\$21.18
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/02/2012 10:13:59	10/02/2012 10:35:35	0.36	\$20.70
					<b>LABOR</b>	<b>41.88</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.19	1	\$5.19
					<b>PARTS</b>	<b>44.78</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 12021

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 3.16

(LPATE) PM BY GM/SH

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 13273

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 03/12/2013 10:40:06	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/15/2013 06:28:12	<b>METER 1 - M:</b> 9689 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/15/2013 06:28:14	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150	2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$130.50	\$0.00	\$159.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$67.39	\$0.00	\$85.22

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.81** **46.58** **197.89** **0.00** **244.47**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	11338644	03/12/2013 15:47:52	03/12/2013 16:17:52	0.50	\$28.75
03-32-002	REPLACE NEW BATTERY	11338644	03/12/2013 15:47:52	03/12/2013 15:48:02	0.00	(\$0.16)
03-32-002	REPLACE NEW BATTERY	11338644	03/12/2013 15:47:52	03/12/2013 15:48:02	0.00	\$0.16
66-PM-PMA	PERFORM OIL CHANGE	11338644	03/12/2013 15:47:21	03/12/2013 16:05:57	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11338644	03/12/2013 15:47:21	03/12/2013 15:47:31	0.00	(\$0.16)
66-PM-PMA	PERFORM OIL CHANGE	11338644	03/12/2013 15:47:21	03/12/2013 15:47:31	0.00	\$0.16
					<b>LABOR</b>	<b>46.58</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	65-1	BATTERY- FORD TOP POST HD	130.50	1	\$130.50
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.19	1	\$5.19
					<b>PARTS</b>	<b>197.89</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 13273

---

**Work Order Notes**

(LPATE) PM-BATTERY FAILED REPLACE BATTERY

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LPATE) REPLACED BATTERY

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY RS-REPLACED OIL DRAIN PLUG

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 1366

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 05/22/2008 15:05:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/22/2008 15:08:24	<b>METER 1 - M:</b> 181 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 05/22/2008 15:08:25	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
10-51-046	SERVICE KEY BLANK(S)	DON	C	N	GARAGE	0.01	\$0.45	\$3.00	\$0.00	\$3.45
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	DON	C	N	GARAGE	0.50	\$22.50	\$45.00	\$0.00	\$67.50
66-79-004	PERFORM PRE-DELIVERY INSPECTION	DON	C	N	GARAGE	0.50	\$22.50	\$0.00	\$0.00	\$22.50

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.01</b>	<b>45.45</b>	<b>48.00</b>	<b>0.00</b>	<b>93.45</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-79-004	PERFORM PRE-DELIVERY INSPECTION	11088474	05/22/2008 15:06:00	05/22/2008 15:36:00	0.50	\$22.50
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	11088474	05/22/2008 15:36:00	05/22/2008 16:06:00	0.50	\$22.50
10-51-046	SERVICE KEY BLANK(S)	11088474	05/22/2008 16:06:00	05/22/2008 16:06:36	0.01	\$0.45
<b>LABOR</b>						<b>45.45</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	WORDMARKS	WORDMARKS	22.50	2	\$45.00
10-51-046	SERVICE KEY BLANK(S)	KEY BLANK	KEY BLANK	1.50	2	\$3.00
<b>PARTS</b>						<b>48.00</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 1366

---

## Work Order Notes

(LOBRIEN) PDI, WORDMARKS, KEYS.

---

## Job Notes

**10-51-046 - SERVICE KEY BLANK(S)**

(LOBRIEN) CUT TWO KEYS.

**14-53-006 - INSTALL WORDMARKS/IDENTIFIERS**

(LOBRIEN) INSTALLED WORDMARKS.

**66-79-004 - PERFORM PRE-DELIVERY INSPECTION**

(LOBRIEN) PDI BY JASON ELMORE.

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 14332

USING DEPT NO:	204112	OPENED DATE:	07/12/2013 11:29:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/15/2013 13:32:15	METER 1 - M:	10641	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2013 13:32:18	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$2.75	\$0.00	\$2.75

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>2.75</b>	<b>0.00</b>	<b>2.75</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	2.75	1	\$2.75
					<b>PARTS</b>	<b>2.75</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 14332

---

**Work Order Notes**

(LPATE) CATHERINE REQUESTED AN EXTRA KEY CUT FOR VAN

---

**Job Notes**

**03-51-046 - REPLACE NEW KEY BLANK(S)**

(LPATE) CUT 1 KEY. CHECKED OK GAVE TO DRIVER

---



# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 14408

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY RS/RT

---

# Work Order Charge Detail

**UNIT NO:** 237357      **2008 FORD E150**

**WORK ORDER NO:** 16403

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 03/14/2014 14:42:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/17/2014 06:34:25	<b>METER 1 - M:</b> 13159 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/17/2014 06:34:27	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150      2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$33.72	\$0.00	\$48.10

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.25</b>	<b>14.38</b>	<b>33.72</b>	<b>0.00</b>	<b>48.10</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/14/2014 14:44:54	03/14/2014 14:59:54	0.25	\$14.38
<b>LABOR</b>						<b>14.38</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	2	\$33.72
<b>PARTS</b>						<b>33.72</b>

# Work Order Charge Detail

**UNIT NO:**            237357            2008 FORD E150

**WORK ORDER NO:**    16403

---

**Work Order Notes**

(LPATE) DRIVER REQUESTED WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 17213

USING DEPT NO:	204112	OPENED DATE:	06/06/2014 08:24:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/09/2014 10:08:33	METER 1 - M:	12620	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/09/2014 10:08:38	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$45.47	\$0.00	\$63.30

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>17.83</b>	<b>45.47</b>	<b>0.00</b>	<b>63.30</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11568366	06/06/2014 09:53:02	06/06/2014 10:11:38	0.31	\$17.83
<b>LABOR</b>						<b>17.83</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15
<b>PARTS</b>						<b>45.47</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 17213

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(IFALLS) CA/BG PERFORMED PM

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 18823

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 11/19/2014 09:33:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/19/2014 13:58:27	<b>METER 1 - M:</b> 13026 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/19/2014 13:58:28	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$45.47	\$0.00	\$63.30

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.31** **17.83** **45.47** **0.00** **63.30**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	11/19/2014 13:24:33	11/19/2014 13:43:09	0.31	\$17.83

**LABOR** **17.83**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.15	1	\$5.15

**PARTS** **45.47**

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 18823

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY NT/RS

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 1947

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 09/09/2008 09:16:16	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/09/2008 09:20:02	<b>METER 1 - M:</b> 1230 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/09/2008 09:20:04	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.25	\$11.25	\$3.00	\$0.00	\$14.25

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.25</b>	<b>11.25</b>	<b>3.00</b>	<b>0.00</b>	<b>14.25</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	11088474	09/09/2008 09:18:00	09/09/2008 09:33:00	0.25	\$11.25
					<b>LABOR</b>	<b>11.25</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	IDENTIFIERS	IDENTIFIER(S)	1.50	2	\$3.00
					<b>PARTS</b>	<b>3.00</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 1947

---

**Work Order Notes**

(RWINTERS) NEEDS ID'S INSTALLED.

---

**Job Notes**

**14-53-006 - INSTALL WORDMARKS/IDENTIFIERS**

(RWINTERS) INSTALLED ID'S.

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 21064

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/10/2015 08:46:20	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/17/2015 08:30:36	<b>METER 1 - M:</b> 14030 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/17/2015 08:30:38	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-15-010	REPLACE NEW BALL JOINT	DON	O	N	GARAGE	4.29	\$246.75	\$187.08	\$0.00	\$433.83
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$787.05	\$787.05
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.69	\$39.87	\$0.00	\$0.00	\$39.87
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.27	\$73.26	\$36.28	\$0.00	\$109.54

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>6.26</b>	<b>359.88</b>	<b>223.36</b>	<b>787.05</b>	<b>1,370.29</b>
---------------------	--------------------------	-------------	---------------	---------------	---------------	-----------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	163188	0029690	\$787.05
				<b>COMML</b>	<b>787.05</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-15-010	REPLACE NEW BALL JOINT	11397026	08/12/2015 11:38:15	08/12/2015 15:55:44	4.29	\$246.75
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	08/10/2015 14:27:35	08/10/2015 15:09:11	0.69	\$39.87
66-PM-PMA	PERFORM OIL CHANGE	10260422	08/10/2015 11:45:33	08/10/2015 13:02:00	1.27	\$73.26
					<b>LABOR</b>	<b>359.88</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ1030	BALL JOINT	53.22	2	\$106.44
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ7025	BALL JOINT	40.32	2	\$80.64
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.61	1	\$4.61
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.52	7	\$31.67
					<b>PARTS</b>	<b>223.36</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 21064

---

**Work Order Notes**

(LPATE) PM-ONE TIRE HAS A HOLE IN THE SIDEWALL  
(LPATE) NEEDS 4 TIRES AND ALIGN

---

**Job Notes**

**03-15-010 - REPLACE NEW BALL JOINT**

(LPATE) REPALCED BOTH UPPER AND LOWER BALL JOINTS. RECHECKED OK

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) OK TIRE REPLACED 4 TIRES AND ALIGNED. PD BY CC

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO OK TIRE BY AY

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LPATE) PM BY GM

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 21346

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 09/09/2015 13:25:09	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/10/2015 07:57:38	<b>METER 1 - M:</b> 14185 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/10/2015 07:57:39	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$115.00	\$53.03	\$0.00	\$168.03
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 2** **WORK ORDER TOTAL:** **2.50** **143.75** **53.03** **0.00** **196.78**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	11213180	09/09/2015 13:25:52	09/09/2015 13:55:52	0.50	\$28.75
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	09/09/2015 13:25:57	09/09/2015 15:25:57	2.00	\$115.00
<b>LABOR</b>						<b>143.75</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	UP8440M	FRONT BRAKE PADS	63.64	1	\$63.64
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	UP8440M	FRONT BRAKE PADS	53.03	1	\$53.03
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	UP8440M	FRONT BRAKE PADS	63.64	(1)	(\$63.64)
<b>PARTS</b>						<b>53.03</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 21346

---

**Work Order Notes**

(LPATE) CHECK BRAKES ARE SQUEALING

---

**Job Notes**

**03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(LPATE) REPLACED FRONT BRAKE PADS AND TURNED ROTORS ON THE VAN. TEST DROVE OK

**06-13 - INSPECT BRAKES**

(LPATE) CHECKED OUT FRONT BRAKES ARE WORN

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 22328

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/11/2016 15:07:08	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/21/2016 08:58:14	<b>METER 1 - M:</b> 14185 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/21/2016 08:58:15	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-058	INSTALL DOOR LOCK	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$517.50	\$517.50
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.97	\$56.05	\$0.00	\$0.00	\$56.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$37.31	\$30.30	\$0.00	\$67.61

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>2.62</b>	<b>150.86</b>	<b>30.30</b>	<b>517.50</b>	<b>698.66</b>
---------------------	--------------------------	-------------	---------------	--------------	---------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
14-02-058	INSTALL DOOR LOCK	11287280	39436	0031719	\$517.50
					<b>COMML</b> <b>517.50</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	11338644	01/21/2016 07:24:17	01/21/2016 07:24:23	0.00	\$0.10
66-79-003	PERFORM SAFETY INSPECTION	11338644	01/14/2016 15:01:31	01/14/2016 15:59:54	0.97	\$55.95
66-PM-PMA	PERFORM OIL CHANGE	11338644	01/14/2016 14:22:31	01/14/2016 15:01:27	0.65	\$37.31
16-02	TRANSPORT CAB & SHEET METAL	10337093	01/12/2016 15:01:12	01/12/2016 16:01:12	1.00	\$57.50
16-02	TRANSPORT CAB & SHEET METAL	10337093	01/12/2016 15:01:12	01/13/2016 08:05:14	(17.07)	(\$981.37)
16-02	TRANSPORT CAB & SHEET METAL	10337093	01/12/2016 15:01:12	01/13/2016 08:05:14	17.07	\$981.37
					<b>LABOR</b>	<b>150.86</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
					<b>PARTS</b>	<b>30.30</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 22328

---

## Work Order Notes

(LISAPATE) DEPT REQUESTED INSTALL POWER DOOR LOCKS WITH 2 REMOTES. ALSO DUE FOR PM AND SI

---

## Job Notes

### **14-02-058 - INSTALL DOOR LOCK**

(LISAPATE) MOBILE ELECTRONICS INSTALLED POWER DOOR LOCKS WITH 2 REMOTES. PD BY CC

### **16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) TAKEN TO MOBILE ELEC BY AY

### **66-79-003 - PERFORM SAFETY INSPECTION**

(LISAPATE) SAFETY INSPECTION COMPLETED. SEE ATTACHED

### **66-PM-30K - PERFORM 30,000 MILES/3YEAR SERVICE**

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY RS

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 23083

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 04/11/2016 14:27:44	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/14/2016 08:15:06	<b>METER 1 - M:</b> 15448 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/14/2016 08:15:07	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.42	\$24.07	\$0.00	\$0.00	\$24.07
24-02-058	REPAIR DOOR LOCK	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.66	\$95.19	\$30.30	\$0.00	\$125.49

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>2.32</b>	<b>133.64</b>	<b>47.36</b>	<b>0.00</b>	<b>181.00</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	04/13/2016 07:27:45	04/13/2016 08:48:29	1.35	\$77.37
66-PM-PMA	PERFORM OIL CHANGE	10260422	04/13/2016 06:00:00	04/13/2016 06:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	10260422	04/13/2016 06:18:36	04/13/2016 06:33:36	0.25	\$14.38
16-02	TRANSPORT CAB & SHEET METAL	10337093	04/12/2016 11:11:42	04/12/2016 11:36:49	0.42	\$24.07

**LABOR 133.65**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98

**PARTS 47.36**

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 23083

---

## Work Order Notes

(LISAPATE) PM DUE-SIDE AND REAR DOORS WONT OPEN AT ALL

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) REPLACED WIPERS

### **16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) TAKEN TO MOBILE ELECTRONICS BY AY

### **24-02-058 - REPAIR DOOR LOCK**

(RWINTERS) MOBILE ELECTRONICS, ADJUSTED AND RESUPPORTED DOOR LOCKS. NO CHARGE. NO INVOICE

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Visit Reason Changed On 4/13/2016 7:26 AM By GARAGE

(GARAGE)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULL SYN. OIL QT

Manufacturer :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

(LISAPATE) PM BY GM

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 2324

USING DEPT NO:	204112	OPENED DATE:	11/06/2008 15:05:27	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/07/2008 07:18:18	METER 1 - M:	1332	METER 2 - N:	0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/07/2008 07:18:19	IN-SERVICE DATE:	05/21/2008		
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$31.38	\$0.00	\$49.21

JOB COUNT: 2 WORK ORDER TOTAL: 0.56 32.21 62.28 0.00 94.49

JOB CODE	JOB DESCRIPTION	Employee No.	Start	Finish	Quantity	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/06/2008 16:00:00	11/06/2008 16:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11088474	11/06/2008 16:18:36	11/06/2008 16:33:36	0.25	\$14.38
					<b>LABOR</b>	<b>32.21</b>

JOB CODE	JOB DESCRIPTION	Part No.	Description	Unit Price	Quantity	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
					<b>PARTS</b>	<b>62.28</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 2324

---

**Work Order Notes**

(LPATE) PM -REPLACE WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20 MOTOR OIL Qty 224 Cost 0

Part 51372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 24419

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 09/22/2016 14:15:41	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/27/2016 09:49:47	<b>METER 1 - M:</b> 16215 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/27/2016 09:49:49	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-055	REPAIR DOOR LATCH/STRIKER	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$37.70	\$0.00	\$55.53

**JOB COUNT: 2** **WORK ORDER TOTAL: 1.31 75.33 37.70 0.00 113.03**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
24-02-055	REPAIR DOOR LATCH/STRIKER	11397026	09/27/2016 07:00:00	09/27/2016 08:00:00	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	11758845	09/23/2016 10:33:01	09/26/2016 06:19:30	(67.77)	(\$3,897.05)
66-PM-PMA	PERFORM OIL CHANGE	11758845	09/23/2016 10:33:01	09/26/2016 06:19:30	67.77	\$3,897.05
66-PM-PMA	PERFORM OIL CHANGE	11758845	09/23/2016 10:33:01	09/23/2016 10:51:37	0.31	\$17.83
					<b>LABOR</b>	<b>75.33</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.14	1	\$2.14
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.11	224	\$24.64
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
					<b>PARTS</b>	<b>37.70</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 24419

---

## Work Order Notes

(LISAPATE) PM-DRIVER DOOR WONT OPEN FROM OUTSIDE

---

## Job Notes

### **24-02-055 - REPAIR DOOR LATCH/STRIKER**

(LISAPATE) REMOVED DOOR PANEL AND DOOR LATCH TO REMOVE BROKEN CLIP FROM THE LATCH, INSTALLED ANOTHER CLIP AND RECHECKED OK

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS-REPLACED AIR FILTER

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 25272

USING DEPT NO:	204112	OPENED DATE:	12/13/2016 14:49:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2016 06:56:57	METER 1 - M:	16215	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2016 06:56:59	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-024	INSTALL BACK UP CAMERA	DON	O	N	GARAGE	6.00	\$345.00	\$447.11	\$0.00	\$792.11

JOB COUNT: 1	WORK ORDER TOTAL:	6.00	345.00	447.11	0.00	792.11
--------------	-------------------	------	--------	--------	------	--------

JOB CODE	JOB DESCRIPTION	Employee No.	Start	Finish	Quantity	TOTAL COST
14-52-024	INSTALL BACK UP CAMERA	11170580	12/16/2016 07:00:00	12/16/2016 13:00:00	6.00	\$345.00
					<b>LABOR</b>	<b>345.00</b>

JOB CODE	JOB DESCRIPTION	Part No.	Description	Unit Price	Quantity	TOTAL COST
14-52-024	INSTALL BACK UP CAMERA	PIC3460C	BLACK ELECTRICAL TAPE	1.54	1	\$1.54
14-52-024	INSTALL BACK UP CAMERA	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	8.37	1	\$8.37
14-52-024	INSTALL BACK UP CAMERA	SHIPPING	SHIPPING AND HANDLING	13.12	1	\$13.12
14-52-024	INSTALL BACK UP CAMERA	IATV675A	BACK UP CAMERA SYSTEM	415.00	1	\$415.00
14-52-024	INSTALL BACK UP CAMERA	PIC81161PT	16 AWG RED WIRE	4.54	1	\$4.54
14-52-024	INSTALL BACK UP CAMERA	PIC81163PT	16 AWG BLACK WIRE	4.54	1	\$4.54
					<b>PARTS</b>	<b>447.11</b>

# Work Order Charge Detail

**UNIT NO:**            237357            2008 FORD E150

**WORK ORDER NO:**    25272

---

**Work Order Notes**

(LISAPATE) ALMA REQUESTED INSTALL BACK UP CAMERA

---

**Job Notes**

**14-52-024 - INSTALL BACK UP CAMERA**

(LISAPATE) WIRED AND INSTALLED NEW REAR VIEW CAMERA/MIRROR ASSY. RECHECKED OK

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 25575

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/26/2017 08:50:48	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/01/2017 14:55:58	<b>METER 1 - M:</b> 17144 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 02/01/2017 14:55:59	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.62	\$0.00	\$46.45

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.81** **46.58** **28.62** **0.00** **75.20**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11268671	01/31/2017 07:00:00	01/31/2017 07:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 09:30:00	01/30/2017 12:00:00	(2.50)	(\$143.75)
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 09:30:00	01/30/2017 12:00:00	2.50	\$143.75
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/27/2017 10:47:44	01/30/2017 09:15:00	(70.45)	(\$4,051.13)
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 14:30:00	01/30/2017 15:59:33	(1.49)	(\$85.82)
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 13:00:00	01/30/2017 14:15:00	(1.25)	(\$71.88)
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 14:30:00	01/30/2017 15:59:33	1.49	\$85.82
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 13:00:00	01/30/2017 14:15:00	1.25	\$71.88
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/30/2017 09:30:00	01/30/2017 09:48:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/27/2017 10:47:44	01/30/2017 09:15:00	70.45	\$4,051.13

**LABOR** **46.58**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.11	224	\$24.64
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98

**PARTS** **28.62**

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 25575

---

**Work Order Notes**

(IFALLS) PM

---

**Job Notes**

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) ROTATED TIRES

**66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY AB

COOLANT -45'

---

# Work Order Charge Detail

**UNIT NO:** 237357      **2008 FORD E150**

**WORK ORDER NO:** 25862

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 02/27/2017 10:36:43	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/10/2017 11:47:08	<b>METER 1 - M:</b> 17202 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/10/2017 11:47:09	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150      2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.25**      **14.38**      **17.06**      **0.00**      **31.44**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	11758845	03/01/2017 07:00:00	03/01/2017 07:15:00	0.25	\$14.38
<b>LABOR</b>						<b>14.38</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
<b>PARTS</b>						<b>17.06</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 25862

---

**Work Order Notes**

(LISAPATE) REPLACE WIPERS-RESET TIRE PRESSUERS LIGHT IS ON

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(RWINTERS) REPLACED WIPERS-AIRED UP TIRES.RELEARNED TIRE POSITIONS

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 26667

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 06/22/2017 14:54:02	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/29/2017 14:59:53	<b>METER 1 - M:</b> 17490 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/29/2017 15:00:02	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.50 28.75 0.00 0.00 28.75**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11213180	06/29/2017 07:00:00	06/29/2017 07:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 26667

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) VEHICLE HAD ONLY BEEN 350 MILES SINCE LAST SERVICE. PER IF CHECKED FLUIDS AND TIRE PRESSURES DO NOT SERVICE.

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 28277

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 11/29/2017 11:11:45	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/01/2017 07:20:57	<b>METER 1 - M:</b> 18266 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/01/2017 07:20:59	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	P	N	GARAGE	0.50	\$28.75	\$93.63	\$0.00	\$122.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.52	\$87.37	\$17.42	\$0.00	\$104.79

**JOB COUNT: 2** **WORK ORDER TOTAL:** **2.02** **116.12** **111.05** **0.00** **227.17**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	11901357	11/29/2017 15:39:48	11/29/2017 15:40:05	0.00	(\$0.27)
03-32-002	REPLACE NEW BATTERY	11901357	11/29/2017 15:39:48	11/29/2017 15:40:05	0.00	\$0.27
03-32-002	REPLACE NEW BATTERY	11901357	11/29/2017 15:39:48	11/29/2017 16:09:48	0.50	\$28.75
CH-32-002	CHARGE BATTERY	11901357	11/29/2017 15:39:28	11/29/2017 15:39:42	0.00	(\$0.22)
CH-32-002	CHARGE BATTERY	11901357	11/29/2017 15:39:28	11/29/2017 15:39:42	0.00	\$0.22
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/29/2017 14:08:09	11/29/2017 15:39:19	1.52	\$87.37
					<b>LABOR</b>	<b>116.12</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
03-32-002	REPLACE NEW BATTERY	65X	BATTERY-EXTREME-FORD TOP POT	93.63	1	\$93.63
					<b>PARTS</b>	<b>111.05</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 28277

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) CHARGED BATTERY, STILL FAILED. REPLACED BATTERY

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY AG

### **CH-32-002 - CHARGE BATTERY**

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 29585

USING DEPT NO:	204112	OPENED DATE:	04/26/2018 11:24:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/30/2018 10:25:22	METER 1 - M:	19012	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2018 10:25:23	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$18.05	\$0.00	\$35.88

JOB COUNT: 2 WORK ORDER TOTAL: 0.56 32.21 35.11 0.00 67.32

JOB CODE	JOB DESCRIPTION	Employee No.	Start	Finish	Quantity	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/26/2018 15:17:33	04/26/2018 15:36:09	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/26/2018 15:17:45	04/26/2018 15:32:45	0.25	\$14.38
					<b>LABOR</b>	<b>32.21</b>

JOB CODE	JOB DESCRIPTION	Part No.	Description	Unit Price	Quantity	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.01	7	\$14.07
					<b>PARTS</b>	<b>35.11</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 29585

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS/AG

COOLANT -35'

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 30562

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/15/2018 10:44:33	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/04/2018 07:37:47	<b>METER 1 - M:</b> 19425 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/04/2018 07:37:49	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.62	\$0.00	\$0.00	\$0.00	\$0.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$469.60	\$469.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$26.87	\$0.00	\$26.87

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.93</b>	<b>0.00</b>	<b>26.87</b>	<b>469.60</b>	<b>496.47</b>
---------------------	--------------------------	-------------	-------------	--------------	---------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
24-71	REPAIR BODY	5569647	3275	0044817	\$469.60
<b>COMML</b>					<b>469.60</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/28/2018 06:00:00	08/28/2018 06:18:36	0.31	\$0.00
16-71	TRANSPORT BODY	10208562	08/16/2018 11:15:07	08/16/2018 11:52:06	0.62	\$0.00
<b>LABOR</b>						<b>0.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.27	7	\$22.89
<b>PARTS</b>						<b>26.87</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 30562

## Work Order Notes

(LISAPATE) PM

(LISAPATE) TAKE TO BROWNS TO REPAIR BODY DAMAGE AROUND LEFT FRONT HEADLIGHT AND FENDER. DUE TO LESS THAN DED DEPT WILL PAY FOR REPAIRS.

## Job Notes

### **16-71 - TRANSPORT BODY**

(LISAPATE) TAKEN TO BROWNS BY EK

### **24-71 - REPAIR BODY**

(LISAPATE) BROWNS REPAIRED BODY DAMAGE PER ESTIMATE. INVOICE AND ESTIMATE ATTACHED. PD BY CC

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Visit Reason Changed On 8/15/2018 10:44 AM By LISAPATE

(LISAPATE)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULLSYN OIL BULK

Manufacturer :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

(LISAPATE) PM BY SH

COOLANT -40'

# Work Order Charge Detail

**UNIT NO:** 237357      **2008 FORD E150**

**WORK ORDER NO:** 31852

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/07/2019 09:04:57	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/09/2019 14:55:38	<b>METER 1 - M:</b> 19817 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/09/2019 14:55:40	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150      2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$0.00	\$34.34	\$0.00	\$34.34

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.47**      **0.00**      **34.34**      **0.00**      **34.34**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/07/2019 11:18:13	01/07/2019 11:46:27	0.47	\$0.00

**LABOR**      **0.00**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.10	7	\$21.70
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	4.45	1	\$4.45
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98

**PARTS**      **34.34**

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 31852

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by EK/SH

Replaced oil drain plug

Coolant -35'

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 33650

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/07/2019 10:04:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/09/2019 07:52:29	<b>METER 1 - M:</b> 21113 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/09/2019 07:52:30	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-010	INSTALL MIRRORS	DON	O	N	GARAGE	0.15	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.59	\$0.00	\$28.84	\$0.00	\$28.84

**JOB COUNT: 2** **WORK ORDER TOTAL:** **1.74** **0.00** **28.84** **0.00** **28.84**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
14-02-010	INSTALL MIRRORS	11901357	08/07/2019 14:11:24	08/07/2019 14:20:30	0.15	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/07/2019 13:07:47	08/07/2019 14:11:24	1.06	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/07/2019 13:03:49	08/07/2019 13:35:21	0.53	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	7	\$20.65
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
					<b>PARTS</b>	<b>28.84</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 33650

---

## Work Order Notes

(LISAPATE) PM-Rearview mirror fell off again

---

## Job Notes

### **14-02-010 - INSTALL MIRRORS**

(LISAPATE) Reattached rearview mirror and tightened screw

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by JW/AG

Coolant -34'

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 35439

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/17/2020 11:17:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/28/2020 09:15:03	<b>METER 1 - M:</b> 22160 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 01/28/2020 09:15:05	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	DON	O	N	GARAGE	1.80	\$0.00	\$187.51	\$0.00	\$187.51
06-02-023	INSPECT HANDLES - INNER & OUTER	DON	O	N	GARAGE	0.25	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$0.00	\$28.62	\$0.00	\$28.62

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.69</b>	<b>0.00</b>	<b>216.13</b>	<b>0.00</b>	<b>216.13</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	12052187	01/27/2020 07:04:19	01/27/2020 07:51:19	0.78	\$0.00
03-02-018	REPLACE NEW DOOR MECHANISM	12052187	01/24/2020 14:50:18	01/24/2020 15:51:23	1.02	\$0.00
06-02-023	INSPECT HANDLES - INNER & OUTER	12052187	01/21/2020 06:10:38	01/21/2020 06:25:33	0.25	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/17/2020 15:36:15	01/17/2020 15:52:30	0.27	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/17/2020 15:26:36	01/17/2020 15:48:45	0.37	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	3.98	1	\$3.98
03-02-018	REPLACE NEW DOOR MECHANISM	AC2Z15431A02A	DOOR LATCH KIT	50.79	1	\$50.79
03-02-018	REPLACE NEW DOOR MECHANISM	9C2Z15434A20AB	HANDLE / LICENSE FRAME ASSY	136.72	1	\$136.72
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
					<b>PARTS</b>	<b>216.13</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 35439

---

## Work Order Notes

(LISAPATE) PM-Rear doors will not open at all

---

## Job Notes

### **03-02-018 - REPLACE NEW DOOR MECHANISM**

(LISAPATE) Replaced door latch cables and handle assy. Reinstalled back up camera

### **06-02-023 - INSPECT HANDLES - INNER & OUTER**

(LISAPATE) Inspected rear door, needs right rear handle and latch assy

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by SH,JW/SH

Coolant -34'

Replaced air filter

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 35635

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 02/12/2020 08:19:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/10/2020 09:54:13	<b>METER 1 - M:</b> 22256 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/13/2020 07:30:51	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-024	REPLACE NEW BACK UP CAMERA	DON	O	N	GARAGE	2.50	\$0.00	\$432.53	\$0.00	\$432.53
06-52-024	INSPECT BACK UP CAMERA	DON	O	N	GARAGE	0.53	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **3.03** **0.00** **432.53** **0.00** **432.53**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-52-024	REPLACE NEW BACK UP CAMERA	11310047	03/06/2020 13:06:33	03/06/2020 15:36:26	2.50	\$0.00
06-52-024	INSPECT BACK UP CAMERA	11074414	02/13/2020 09:22:33	02/13/2020 09:54:31	0.53	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-52-024	REPLACE NEW BACK UP CAMERA	IATV675A	BACK UP CAMERA SYSTEM	415.00	1	\$415.00
03-52-024	REPLACE NEW BACK UP CAMERA	SHIPPING	SHIPPING AND HANDLING	17.53	1	\$17.53
03-52-024	REPLACE NEW BACK UP CAMERA	SHIPPING	SHIPPING AND HANDLING	17.53	(1)	(\$17.53)
03-52-024	REPLACE NEW BACK UP CAMERA	SHIPPING	SHIPPING AND HANDLING	17.53	1	\$17.53
					<b>PARTS</b>	<b>432.53</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 35635

---

**Work Order Notes**

(EKIMBREL) Back up camera is inop

---

**Job Notes**

**03-52-024 - REPLACE NEW BACK UP CAMERA**

(EKIMBREL) EH replaced backup camera and rearview mirror assembly. Backup camera now working.

**06-52-024 - INSPECT BACK UP CAMERA**

(EKIMBREL) Found back up camera inop.

---



# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 36870

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) Oil change not done at this time. Checked fluids, battery and tire pressures. Installed a new sticker

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 37072

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 07/10/2020 08:17:50	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/13/2020 07:52:27	<b>METER 1 - M:</b> 22425 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/13/2020 12:21:27	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-02-058	ADJUST DOOR LOCK	DON	O	N	GARAGE	0.26	\$0.00	\$0.00	\$0.00	\$0.00
06-02-018	INSPECT DOOR MECHANISM	DON	O	N	GARAGE	0.02	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.28** **0.00** **0.00** **0.00** **0.00**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
06-02-018	INSPECT DOOR MECHANISM	11901357	07/10/2020 14:07:50	07/10/2020 14:08:50	0.02	\$0.00
01-02-058	ADJUST DOOR LOCK	11901357	07/10/2020 14:09:15	07/10/2020 14:24:55	0.26	\$0.00
<b>LABOR</b>						<b>0.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	AC2Z15431A02A	DOOR LATCH KIT	47.07	1	\$47.07
03-02-018	REPLACE NEW DOOR MECHANISM	AC2Z15431A02A	DOOR LATCH KIT	47.07	(1)	(\$47.07)
<b>PARTS</b>						<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 37072

---

## Work Order Notes

(LISAPATE) remote control will not unlock rear doors

---

## Job Notes

### **01-02-058 - ADJUST DOOR LOCK**

(LISAPATE) Found rear door lock actuator out of adjustment. Adjusted the actuator. Rechecked working ok

### **03-02-018 - REPLACE NEW DOOR MECHANISM**

### **06-02-018 - INSPECT DOOR MECHANISM**

(LISAPATE) Checked door mechanism

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 37271

USING DEPT NO:	204112	OPENED DATE:	08/06/2020 09:53:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2020 10:55:45	METER 1 - M:	22481	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2020 11:06:31	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	DON	O	N	GARAGE	1.09	\$0.00	\$91.40	\$0.00	\$91.40

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>1.09</b>	<b>0.00</b>	<b>91.40</b>	<b>0.00</b>	<b>91.40</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	11170580	08/07/2020 08:25:50	08/07/2020 09:31:24	1.09	\$0.00

**LABOR 0.00**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	6C2Z1543286AA	UPPER DOOR LATCH	49.33	1	\$49.33
03-02-018	REPLACE NEW DOOR MECHANISM	8C2Z15431A03A	LOWER LATCH W/HANDLE	42.07	1	\$42.07

**PARTS 91.40**

# Work Order Charge Detail

**UNIT NO:**            237357            2008 FORD E150

**WORK ORDER NO:**    37271

---

**Work Order Notes**

(RTUNAITI) Rear LH cargo door inop

---

**Job Notes**

**03-02-018 - REPLACE NEW DOOR MECHANISM**

(ABLACK) AB found left rear cargo door cables broken. Installed new cables and latches. Rechecked ok.

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 3787

USING DEPT NO:	204112	OPENED DATE:	07/02/2009 08:55:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/02/2009 10:38:43	METER 1 - M:	2668	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2009 06:28:26	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$31.38	\$0.00	\$49.21

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>17.83</b>	<b>31.38</b>	<b>0.00</b>	<b>49.21</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/02/2009 17:00:00	07/02/2009 17:18:36	0.31	\$17.83

<b>LABOR</b>						<b>17.83</b>
--------------	--	--	--	--	--	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52

<b>PARTS</b>						<b>31.38</b>
--------------	--	--	--	--	--	--------------

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 3787

---

## Work Order Notes

(LPATE) PM  
(RWINTERS) MILES 2668

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 51372 FILTER-OIL Qty 1 Cost 0  
Part 5W20 OIL-MOTOR Qty 224 Cost 0  
(LPATE) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 237357      **2008 FORD E150**

**WORK ORDER NO:** 38283

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 11/05/2020 08:34:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/09/2020 14:28:24	<b>METER 1 - M:</b> 22657 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/10/2020 06:59:33	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150      2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.20	\$141.17	\$25.56	\$0.00	\$166.73

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **1.20**      **141.17**      **25.56**      **0.00**      **166.73**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2020 13:07:40	11/09/2020 13:47:02	0.66	\$77.42
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/06/2020 15:14:13	11/06/2020 15:31:11	0.28	\$33.37
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/06/2020 14:30:00	11/06/2020 14:45:27	0.26	\$30.39
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/06/2020 14:15:28	11/06/2020 14:15:28	0.00	\$0.00
					<b>LABOR</b>	<b>141.18</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	25.56	1	\$25.56
					<b>PARTS</b>	<b>25.56</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 38283

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) Miles: 22657 Vehicle has been driven 497 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. Washed, vacuumed and refueled vehicle. AMG

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 39740

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 04/20/2021 09:54:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/20/2021 14:36:11	<b>METER 1 - M:</b> 22962 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/21/2021 08:23:36	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.22	\$36.21	\$0.00	\$70.43

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.29** **34.22** **36.21** **0.00** **70.43**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/20/2021 13:02:29	04/20/2021 13:19:53	0.29	\$34.22
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/20/2021 12:22:21	04/20/2021 12:22:21	0.00	\$0.00
					<b>LABOR</b>	<b>34.22</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					<b>PARTS</b>	<b>36.21</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 39740

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 22962. SH/AMG Performed PM.

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 39787

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 04/23/2021 08:13:31	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/27/2021 11:52:24	<b>METER 1 - M:</b> 22961 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/27/2021 14:52:02	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.43	\$51.23	\$0.00	\$0.00	\$51.23
06-02-055	INSPECT DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.42	\$49.10	\$60.92	\$0.00	\$110.02

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.85** **100.33** **60.92** **0.00** **161.25**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	12052187	04/26/2021 12:17:08	04/26/2021 12:43:11	0.43	\$51.23
06-02-055	INSPECT DOOR LATCH/STRIKER	12052187	04/23/2021 09:30:00	04/23/2021 09:51:53	0.36	\$43.04
06-02-055	INSPECT DOOR LATCH/STRIKER	12052187	04/23/2021 09:11:55	04/23/2021 09:15:00	0.05	\$6.06
					<b>LABOR</b>	<b>100.33</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
06-02-055	INSPECT DOOR LATCH/STRIKER	8C2Z15264A00D	DOOR LATCH CABLE	60.92	1	\$60.92
06-02-055	INSPECT DOOR LATCH/STRIKER	8C2Z15264A00D	DOOR LATCH CABLE	60.92	(1)	(\$60.92)
06-02-055	INSPECT DOOR LATCH/STRIKER	8C2Z15264A00D	DOOR LATCH CABLE	60.92	1	\$60.92
					<b>PARTS</b>	<b>60.92</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 39787

---

## Work Order Notes

(LISAPATE) Per driver side door will not open

---

## Job Notes

### **03-02-055 - REPLACE NEW DOOR LATCH/STRIKER**

(JWRIGHT) Replaced cargo side forward door latch cables. JAW

### **06-02-055 - INSPECT DOOR LATCH/STRIKER**

(JWRIGHT) Found side forward door cables is damaged from age and lock rod is bent. Will need to be replaced. Also found the rear door was hard to unlock, lubricated the lock assy and cables. JAW

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 40478

USING DEPT NO:	204112	OPENED DATE:	07/20/2021 08:50:54	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	07/20/2021 14:53:16	METER 1 - M:	23254	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/21/2021 09:12:18	IN-SERVICE DATE:	05/21/2008		
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.90	\$105.97	\$113.55	\$0.00	\$219.52
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.84	\$98.56	\$0.00	\$0.00	\$98.56

JOB COUNT: 2 WORK ORDER TOTAL: 1.73 204.53 113.55 0.00 318.08

JOB CODE	JOB DESCRIPTION	Employee No.	Start	Finish	Quantity	TOTAL COST
03-32-002	REPLACE NEW BATTERY	11213180	07/20/2021 10:00:48	07/20/2021 10:54:41	0.90	\$105.97
66-79-002	PERFORM SERVICE CALL	11213180	07/20/2021 09:10:32	07/20/2021 10:00:39	0.84	\$98.56
					<b>LABOR</b>	<b>204.53</b>

JOB CODE	JOB DESCRIPTION	Part No.	Description	Unit Price	Quantity	TOTAL COST
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
					<b>PARTS</b>	<b>113.55</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 40478

---

## Work Order Notes

(LISAPATE) Kyle requested a service call to E-Tech van has a dead battery

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(MSIDES) Replaced battery. MS

### **66-79-002 - PERFORM SERVICE CALL**

(MSIDES) Performed service call found battery to be dead due to headlights being left on. MS

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 40856

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/26/2021 09:48:41	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/08/2021 15:26:26	<b>METER 1 - M:</b> 23420 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/10/2021 12:39:14	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	DON	O	N	GARAGE	2.15	\$253.27	\$64.44	\$0.00	\$317.71
03-15-010	REPLACE NEW BALL JOINT	DON	O	N	GARAGE	2.74	\$323.71	\$264.96	\$0.00	\$588.67
03-17-028	REPLACE NEW MOUNT AND BALANCE	DON	O	N	GARAGE	1.21	\$143.30	\$670.70	\$0.00	\$814.00
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$10.06	\$15.18	\$0.00	\$25.24
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.29	\$33.89	\$0.00	\$0.00	\$33.89
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.06	\$125.01	\$201.81	\$0.00	\$326.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$92.89	\$0.00	\$0.00	\$92.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PK-18-001	PACK FRONT AXLE HUBS & BEARINGS	DON	O	N	GARAGE	2.13	\$251.18	\$0.00	\$0.00	\$251.18

**JOB COUNT: 9** **WORK ORDER TOTAL:** **10.45** **1,233.31** **1,217.09** **2.00** **2,452.40**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
	<b>COMML</b>				<b>2.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	11310047	09/03/2021 15:43:26	09/03/2021 15:48:33	0.09	\$10.06
06-15	INSPECT STEERING	11310047	09/03/2021 15:26:12	09/03/2021 15:43:26	0.29	\$33.89
66-17-013	PERFORM ALIGNMENT	11310047	09/03/2021 13:56:43	09/03/2021 15:00:17	1.06	\$125.01
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	11310047	09/03/2021 12:35:13	09/03/2021 13:56:43	1.36	\$160.28
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	11310047	09/03/2021 11:11:44	09/03/2021 11:30:06	0.31	\$36.12
03-15-010	REPLACE NEW BALL JOINT	11310047	09/03/2021 07:06:46	09/03/2021 07:30:15	0.39	\$46.18
03-15-010	REPLACE NEW BALL JOINT	11310047	09/02/2021 13:34:03	09/02/2021 15:55:10	2.35	\$277.53
PK-18-001	PACK FRONT AXLE HUBS & BEARINGS	11310047	09/02/2021 09:47:25	09/02/2021 11:55:08	2.13	\$251.18
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	12052187	09/02/2021 09:20:39	09/02/2021 10:33:31	1.21	\$143.30

# Work Order Charge Detail

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/27/2021 07:58:30	08/27/2021 08:45:44	0.79	\$92.89
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	11310047	08/26/2021 10:20:02	08/26/2021 10:48:57	0.48	\$56.87
					<b>LABOR</b>	<b>1233.31</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-17-013	PERFORM ALIGNMENT	2643950	CAMBER BUSHING	100.91	2	\$201.81
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	165.54	4	\$662.16
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	165.54	(4)	(\$662.16)
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	166.29	4	\$665.16
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	5	\$2.48
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.77	4	\$3.06
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	8C2Z15264A00D	DOOR LATCH CABLE	64.44	1	\$64.44
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ7025	BALL JOINT	48.60	2	\$97.20
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ1030	BALL JOINT	57.20	2	\$114.39
03-15-010	REPLACE NEW BALL JOINT	MOTBRS93	WHEEL SEALS	26.69	2	\$53.37
					<b>PARTS</b>	<b>1217.09</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 40856

---

## Work Order Notes

(LISAPATE) PM-replace wipers-Side door will not open at all

---

## Job Notes

### **03-02-055 - REPLACE NEW DOOR LATCH/STRIKER**

(EHOWELL) The side door mechanism seemed to be binding. Also, the door has an aftermarket electric door lock actuator. Replaced the side door latch and secured aftermarket lock rod to factory lock rod. The door now opens and can be lock/unlocked manually or electrically. EH 1.1 Hours

### **03-15-010 - REPLACE NEW BALL JOINT**

(EHOWELL) Replaced upper and lower ball joints on both sides of the vehicle. Installed adjustable cam bushings during assembly. EH

### **03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced and balanced all 4 tires. Left tires off for front end work to be done. JAW

### **03-51-038 - REPLACE NEW WIPER BLADES**

(EHOWELL) Replaced wipers. EH

### **06-15 - INSPECT STEERING**

(EHOWELL) Checked front end. Wheel bearings loose and has play in upper ball joint. JAW/SH/EH

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Performed Alignment. Performed a wheel off adjustment. 1.5 Hours. EH

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Checked fluids. Unit has only been 351 miles since last pm. Updated sticker. Checked all tires and fluids. Tires are out of date and needs replaced. Coolant -34°. JAW

### **CH-SP - CHARGE Shop Supplies**

### **PK-18-001 - PACK FRONT AXLE HUBS & BEARINGS**

(EHOWELL) Repacked hub bearings on both sides of the vehicle with grease, installed new wheel seals, and adjusted hub bearings. EH

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 42546

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 03/03/2022 07:33:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/03/2022 14:47:29	<b>METER 1 - M:</b> 23901 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/07/2022 07:53:00	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.18	\$15.18	\$0.00	\$22.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.40	\$31.88	\$0.00	\$65.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.34</b>	<b>40.58</b>	<b>47.06</b>	<b>2.00</b>	<b>89.64</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/03/2022 10:24:21	03/03/2022 10:28:00	0.06	\$7.18
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/03/2022 10:07:05	03/03/2022 10:24:04	0.28	\$33.40
<b>LABOR</b>					<b>40.58</b>	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.33	1	\$5.33
<b>PARTS</b>					<b>47.06</b>	

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 42546

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) AMG Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/AMG Performed PM.

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 44413

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/22/2022 12:57:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/26/2022 09:53:09	<b>METER 1 - M:</b> 24347 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/26/2022 13:36:11	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.50	\$59.10	\$170.65	\$0.00	\$229.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$26.68	\$0.00	\$0.00	\$26.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.73</b>	<b>85.78</b>	<b>170.65</b>	<b>5.00</b>	<b>261.43</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/22/2022 13:15:37	08/22/2022 13:29:11	0.23	\$26.68
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	11213180	08/24/2022 13:31:02	08/24/2022 14:01:05	0.50	\$59.10
<b>LABOR</b>						<b>85.78</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	6C2Z15264A01AA	LATCH	101.93	1	\$101.93
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	AC2Z15264A26B	REAR LATCH ASSY	68.72	1	\$68.72
<b>PARTS</b>						<b>170.65</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 44413

---

## Work Order Notes

(LISAPATE) PM-replace wipers

---

## Job Notes

**03-02-055 - REPLACE NEW DOOR LATCH/STRIKER**

(MSIDES) Replaced rear most side barn door latches. MS

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Vehicle has been driven 446 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 45770

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/11/2023 13:52:20	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/13/2023 14:17:44	<b>METER 1 - M:</b> 25137 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/17/2023 09:13:58	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.21	\$15.63	\$0.00	\$22.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.01	\$43.38	\$0.00	\$72.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>36.22</b>	<b>59.01</b>	<b>5.00</b>	<b>100.23</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/12/2023 14:31:57	01/12/2023 14:35:37	0.06	\$7.21
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/12/2023 14:30:00	01/12/2023 14:31:42	0.03	\$3.34
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/12/2023 14:01:57	01/12/2023 14:15:00	0.22	\$25.67
<b>LABOR</b>					<b>36.22</b>	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.85	1	\$5.85
<b>PARTS</b>					<b>59.01</b>	

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 45770

---

## Work Order Notes

(EHANNAH) Department WO Notes: 1664C Contact is Pam Harrell 8-8481  
(EHANNAH) pm- replace wipers

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 25137 Completed PM topside, Gregg was bottomside. AMG/GC

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 47224

USING DEPT NO:	204112	OPENED DATE:	05/31/2023 12:24:04	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2023 09:55:16	METER 1 - M:	25846	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2023 09:06:40	IN-SERVICE DATE:	05/21/2008		
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.13	\$16.65	\$0.00	\$24.78
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.29	\$33.99	\$0.00	\$0.00	\$33.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.65	\$18.51	\$0.00	\$37.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.22	\$26.26	\$0.00	\$0.00	\$26.26

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.74</b>	<b>87.03</b>	<b>35.16</b>	<b>5.00</b>	<b>127.19</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

JOB CODE	JOB DESCRIPTION	Vendor No.	Invoice No.	Purchase Order No.	TOTAL COST	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

JOB CODE	JOB DESCRIPTION	Employee No.	Start	Finish	Quantity	TOTAL COST
WA-00	WASH COMPLETE VEHICLE	11074414	06/01/2023 11:34:25	06/01/2023 11:47:46	0.22	\$26.26
66-79-003	PERFORM SAFETY INSPECTION	11074414	06/01/2023 09:30:00	06/01/2023 09:33:03	0.05	\$6.00
66-79-003	PERFORM SAFETY INSPECTION	11074414	06/01/2023 09:00:46	06/01/2023 09:15:00	0.24	\$27.99
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/01/2023 08:53:43	06/01/2023 08:57:51	0.07	\$8.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/01/2023 08:44:01	06/01/2023 08:53:30	0.16	\$18.65
					<b>LABOR</b>	<b>87.03</b>

JOB CODE	JOB DESCRIPTION	Part No.	Description	Unit Price	Quantity	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	18.51	1	\$18.51
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
					<b>PARTS</b>	<b>35.16</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 47224

---

## Work Order Notes

(EHANNAH) Department WO Notes: 1664C Contact is Pam Harrell 8-8481

(EHANNAH) pm- replace wipers- do SI- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front brake pads measure 10MM. Rear brake pads measure 5MM. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 709 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed the vehicle. SH

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 47632

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 07/18/2023 13:45:03	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/21/2023 13:15:10	<b>METER 1 - M:</b> 26008 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/24/2023 09:33:57	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-01-066	REPLACE NEW VACUUM TANK UNIT	DON	O	N	GARAGE	0.80	\$94.04	\$34.95	\$0.00	\$128.99
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '1	DON	O	N	GARAGE	0.64	\$75.29	\$0.00	\$0.00	\$75.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>1.44</b>	<b>169.33</b>	<b>34.95</b>	<b>5.00</b>	<b>209.28</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-01-066	REPLACE NEW VACUUM TANK UNIT	11310047	07/19/2023 07:20:31	07/19/2023 08:08:20	0.80	\$94.04
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	07/19/2023 08:08:20	07/19/2023 08:46:37	0.64	\$75.29
<b>LABOR</b>					<b>1.44</b>	<b>169.33</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-01-066	REPLACE NEW VACUUM TANK UNIT	DOR47076	VACUUM TANK RESERVOIR	26.36	1	\$26.36
03-01-066	REPLACE NEW VACUUM TANK UNIT	GAT27035	5/32 VACUUM LINE	0.44	4	\$1.74
03-01-066	REPLACE NEW VACUUM TANK UNIT	GAT27041	7/64 VACUUM HOSE	0.41	1	\$0.41
03-01-066	REPLACE NEW VACUUM TANK UNIT	DOR47149	CHECK VALVE	6.44	1	\$6.44
<b>PARTS</b>					<b>34.95</b>	<b>34.95</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 47632

---

## Work Order Notes

(LISAPATE)

(LISAPATE) Per Heather A/C is not working

---

## Job Notes

### **03-01-066 - REPLACE NEW VACUUM TANK UNIT**

(GARAGE) Installed a new vacuum tank unit with a check valve. Secured tank beneath dash and applied cushion tape to help prevent rattling. The AC is now blowing cold out of the vent. EH .7 HR

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(GARAGE) The air was blowing out of the defrost section due to a faulty vacuum tank. EH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 48437

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 10/09/2023 07:15:29	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/13/2023 15:25:16	<b>METER 1 - M:</b> 26258 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/16/2023 07:51:10	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$43.73	\$0.00	\$82.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.22	\$26.16	\$0.00	\$0.00	\$26.16

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.55</b>	<b>65.10</b>	<b>43.73</b>	<b>5.00</b>	<b>113.83</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
WA-00	WASH COMPLETE VEHICLE	11074414	10/11/2023 09:32:12	10/11/2023 09:45:30	0.22	\$26.16
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/11/2023 09:14:24	10/11/2023 09:14:24	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/11/2023 09:14:24	10/11/2023 09:14:24	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/11/2023 09:14:24	10/11/2023 09:34:12	0.33	\$38.94
					<b>LABOR</b>	<b>65.10</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	6.20	1	\$6.20
					<b>PARTS</b>	<b>43.73</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 48437

---

**Work Order Notes**

(EHANNAH) Department WO Notes: 1664C Contact is Pam Harrell 8-8481  
(EHANNAH) pm- wash

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/GC Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed. SH

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 49532

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/23/2024 07:40:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/23/2024 14:37:21	<b>METER 1 - M:</b> 26340 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/24/2024 07:48:02	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.38	\$44.51	\$199.98	\$0.00	\$244.49
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.02	\$2.49	\$0.00	\$0.00	\$2.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.40</b>	<b>47.00</b>	<b>199.98</b>	<b>5.00</b>	<b>251.98</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	11399745	01/23/2024 10:12:45	01/23/2024 10:14:01	0.02	\$2.49
03-32-002	REPLACE NEW BATTERY	12201267	01/23/2024 10:22:09	01/23/2024 10:44:47	0.38	\$44.51
					<b>LABOR</b>	<b>47.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	651	BATTERY BCI 65 750CCA	199.98	1	\$199.98
					<b>PARTS</b>	<b>199.98</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 49532

---

## Work Order Notes

(EHANNAH) Department WO Notes: 1664C Contact is Pam Harrell 8-8481  
(EHANNAH) service call for dead battery

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(GRCOOK) Replaced battery in unit 6767B, unit came in for dead battery, tested battery and battery tested bad. -GC  
Battery volts 14.10 on new battery. -GC

### **06-32-002 - INSPECT BATTERY**

### **66-79-002 - PERFORM SERVICE CALL**

(GARAGE) Jumped vehicle off, brought it back to the shop to have the battery tested. CW/RC

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 50606

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 04/18/2024 07:03:55	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/18/2024 13:52:12	<b>METER 1 - M:</b> 26713 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/18/2024 14:59:49	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 50606

---

**Work Order Notes**

(EHANNAH) pm- wash

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Checked fluids FC

**WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 52606

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 10/28/2024 07:14:09	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/28/2024 17:00:12	<b>METER 1 - M:</b> 27648 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/29/2024 09:37:29	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$15.57	\$0.00	\$15.57
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$46.80	\$0.00	\$46.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>62.37</b>	<b>5.00</b>	<b>67.37</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.79	2	\$15.57
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	5W20 FULL SYN QTS	6.81	6	\$40.86
					<b>PARTS</b>	<b>62.37</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 52606

---

## Work Order Notes

(EHANNAH) pm- wash- check mast key- SI needed

(GARAGE) Key will not release from lock cylinder. Pending SI.

(EHOWELL) There seems to be an issue with our key because the customer was not complaining about the key not being able to be removed from the ignition.

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Replaced wiper blades.

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) performed si cm checked ok 27648 miles,

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- Performed LOF PM service.

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) wash bay down

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 54049

<b>USING DEPT NO:</b>	204112	<b>OPENED DATE:</b>	03/18/2025 07:06:01	<b>LOCATION:</b>	GARAGE - University Automotive Services				
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	03/19/2025 07:39:00	<b>METER 1 - M:</b>	28110	<b>METER 2 - N:</b>	0		
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	03/20/2025 09:18:47	<b>IN-SERVICE DATE:</b>	05/21/2008				
<b>TECH SPEC NO:</b>	08VNFORDE150	2008 FORD E150		<b>UNIT SERIAL NO:</b>	1FTNE14W18DB25153				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 54049

---

## Work Order Notes

(CWIGLEY) Department WO Notes: 1664C Contact is Pam Harrell 8-8481  
(CWIGLEY) PM. Wash

---

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) GC- PM, Fluid check only, vehicle driven 468 miles, checked fluids, filter good, tires and tire pressure, updated the oil change sticker.  
Miles, 28,116

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) GC- wash bay down

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 55938

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/14/2025 08:26:46	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/18/2025 13:29:35	<b>METER 1 - M:</b> 28704 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/18/2025 14:18:00	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-44-003	REPLACE NEW FUEL PUMP	DON	N	N	GARAGE	0.00	\$0.00	\$304.04	\$0.00	\$304.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$47.58	\$0.00	\$47.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>351.62</b>	<b>5.00</b>	<b>356.62</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-44-003	REPLACE NEW FUEL PUMP	SFPPN4014	FUEL PUMP	304.04	1	\$304.04
66-PM-PMA	PERFORM OIL CHANGE	SFFL8010S	FL8010S OIL FILTER - STIVERS	12.39	1	\$12.39
66-PM-PMA	PERFORM OIL CHANGE	SF5W20BT	5W20BT OIL - STIVERS	5.87	6	\$35.19
					<b>PARTS</b>	<b>351.62</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 55938

---

## Work Order Notes

(CHANNELL) Department WO Notes: 1664C Contact is Pam Harrell 8-8481  
(CHANNELL) pm

---

## Job Notes

### **03-44-003 - REPLACE NEW FUEL PUMP**

(GARAGE) cm dropped tank replaced fuel pump/sending unit assembly, reinstalled tank checked for leaks, tested drove checked ok, fuel gauge working unit checked ok, cm 2.8 labor,

(GARAGE) rescan unit after installation, fault was inactive, cm

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid 28708 miles

### **CH-SP - CHARGE Shop Supplies**

### **SO-00 - SCAN OUT COMPLETE VEHICLE**

(GARAGE) cm 28709 miles, scan out vehicle fuel sender circuit open code was active, used scan tool to test gauge unit checked ok wiring harness checked ok tank will have to be dropped and sending unit/fuel pump assembly will have to be replaced,

(GARAGE) charge 1 hour for scan out, cm

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 57798

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 01/09/2026 07:08:38	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/16/2026 14:27:33	<b>METER 1 - M:</b> 29199 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/20/2026 13:22:26	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.00	\$175.00	\$0.00	\$0.00	\$175.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	1.00	\$175.00	\$0.00	\$0.00	\$175.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.00</b>	<b>350.00</b>	<b>0.00</b>	<b>5.00</b>	<b>355.00</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	12480657	01/09/2026 07:31:18	01/09/2026 08:31:18	1.00	\$175.00
66-79-003	PERFORM SAFETY INSPECTION	12480657	01/09/2026 07:31:18	01/09/2026 08:12:58	(0.69)	(\$121.53)
66-79-003	PERFORM SAFETY INSPECTION	12480657	01/09/2026 07:31:18	01/09/2026 08:12:58	0.69	\$121.53
SO-00	SCAN OUT COMPLETE VEHICLE	12480657	01/09/2026 07:21:35	01/09/2026 07:31:18	0.16	\$28.34
SO-00	SCAN OUT COMPLETE VEHICLE	12480657	01/09/2026 07:21:35	01/09/2026 08:21:35	1.00	\$175.00
SO-00	SCAN OUT COMPLETE VEHICLE	12480657	01/09/2026 07:21:35	01/09/2026 07:31:18	(0.16)	(\$28.34)
					<b>LABOR</b>	<b>350.00</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 57798

---

## Work Order Notes

(EKIMBREL) Department WO Notes: 1664C Contact is Pam Harrell 8-8481  
(EKIMBREL) scan out, si

---

## Job Notes

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) CM performed SI, unit had 29119 miles,, unit instrument panel is bad will need replacing, rear brakes are 3 mm front brakes are 8 mm, unit will need rear brakes and rotors, tire build dates are 0621, unit will need tires next Si, unit is due for a PM, everything else checked ok,

### **CH-SP - CHARGE Shop Supplies**

### **SO-00 - SCAN OUT COMPLETE VEHICLE**

(GARAGE) CM scan out unit unit has active fault for instrument panel, checked over vehicle instrument panel will need replacing, 1 hour labor,

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 6630

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 08/27/2010 14:36:32	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/30/2010 08:22:55	<b>METER 1 - M:</b> 4818 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/30/2010 08:22:57	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$7.84	\$45.46	\$0.00	\$53.30

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.14** **7.84** **45.46** **0.00** **53.30**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	08/27/2010 15:30:05	08/27/2010 15:38:16	0.14	\$7.84
					<b>LABOR</b>	<b>7.84</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.07	1	\$14.07
					<b>PARTS</b>	<b>45.46</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 6630

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY JM/TM-REPLACED AIR FILTER

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 6787

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 09/17/2010 07:35:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/17/2010 13:46:55	<b>METER 1 - M:</b> 5173 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/17/2010 13:46:57	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150      2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$1.50	\$0.00	\$1.50

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **1.50**      **0.00**      **1.50**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	1.50	1	\$1.50
					<b>PARTS</b>	<b>1.50</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 6787

---

**Work Order Notes**

(LPATE) ALMA REQUESTED EXTRA EXTRA KEY FOR VAN

---

**Job Notes**

**03-51-046 - REPLACE NEW KEY BLANK(S)**

(LPATE) GAVE ALMA 1 NEW KEY

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 6998

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 10/18/2010 09:25:32	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/19/2010 09:41:03	<b>METER 1 - M:</b> 5673 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/19/2010 09:41:05	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150 2008 FORD E150		<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$148.95	\$148.95
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

**JOB COUNT: 2** **WORK ORDER TOTAL:** **1.00** **57.50** **0.00** **148.95** **206.45**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	129288	0009512	\$148.95
				<b>COMML</b>	<b>148.95</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11338644	10/19/2010 17:00:00	10/19/2010 18:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 6998

---

**Work Order Notes**

(LPATE) RIGHT REAR TIRE HAS A CUT IN SIDEWALL-S/W ALMA WE WILL SWAP AND PUT SPARE TIRE ONTO WHEEL WITH SENSOR THEN INSTALL NEW BRIDGESTONE TIRE TO SPARE TO KEEP MATCHING SET OF TIRES ON VAN DUE TO SUCH LOW MILES.

---

**Job Notes**

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) FIRESTONE REPLACED RIGHT REAR TIRE WITH SPARE INSTALLED TIRE MONITOR, THEN INSTALLED NEW TIRE AS SPARE. P0031666

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO FIRESTONE BY RS

---

# Work Order Charge Detail

**UNIT NO:** 237357 2008 FORD E150

**WORK ORDER NO:** 7238

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 11/24/2010 09:01:47	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/24/2010 14:41:34	<b>METER 1 - M:</b> 6058 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/24/2010 14:41:35	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150	2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-01-004	WARRANTY BLOWER MOTOR	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01-004	TRANSPORT BLOWER MOTOR	DON	O	N	GARAGE	0.17	\$9.53	\$0.00	\$0.00	\$9.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.03	\$0.00	\$45.86

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.48</b>	<b>27.36</b>	<b>28.03</b>	<b>0.00</b>	<b>55.39</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>TOTAL COST</u>	
15-01-004	WARRANTY BLOWER MOTOR	11078175	19792	0010018	\$0.00	
					<b>COMML</b>	<b>0.00</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
16-01-004	TRANSPORT BLOWER MOTOR	11338644	11/24/2010 14:26:10	11/24/2010 14:36:07	0.17	\$9.53
66-PM-PMA	PERFORM OIL CHANGE	10230946	11/24/2010 10:00:00	11/24/2010 10:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>27.36</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.51	1	\$4.51
					<b>PARTS</b>	<b>28.03</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 7238

---

## Work Order Notes

(RWINTERS) PM AND BLOWER MOTOR IS MAKING A NOISE

---

## Job Notes

### **15-01-004 - WARRANTY BLOWER MOTOR**

(RWINTERS) T-FORD REPLACED THE FRONT BLOWER, CAGE AND RESISTOR.

### **16-01-004 - TRANSPORT BLOWER MOTOR**

(RWINTERS) TAKEN TO T-FORD

### **66-PM-PMA - PERFORM OIL CHANGE**

(RWINTERS)

The following parts are included with the standard job:

Part No : 1372  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

Part No : 5W20  
Qty : 224  
Description : OIL BOTTLE  
Manufacturer :

(RWINTERS) PM BY JM/RS/TM

---

# Work Order Charge Detail

**UNIT NO:** 237357      **2008 FORD E150**

**WORK ORDER NO:** 7857

<b>USING DEPT NO:</b> 204112	<b>OPENED DATE:</b> 03/02/2011 15:35:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/04/2011 06:28:05	<b>METER 1 - M:</b> 6487 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/04/2011 06:28:07	<b>IN-SERVICE DATE:</b> 05/21/2008
<b>TECH SPEC NO:</b> 08VNFORDE150      2008 FORD E150	<b>UNIT SERIAL NO:</b> 1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$20.40	\$32.70	\$0.00	\$53.10

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.35**      **20.40**      **32.70**      **0.00**      **53.10**

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	03/03/2011 08:06:00	03/03/2011 08:27:17	0.35	\$20.40
<b>LABOR</b>						<b>20.40</b>

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	4.67	1	\$4.67
<b>PARTS</b>						<b>32.70</b>

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 7857

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

The following parts are included with the standard job:

Part No : 1372  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

Part No : 5W20  
Qty : 224  
Description : OIL BOTTLE  
Manufacturer :

(LPATE) PM BY RS/JM

---

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 8645

USING DEPT NO:	204112	OPENED DATE:	06/29/2011 14:23:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2011 06:30:13	METER 1 - M:	6703	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/30/2011 06:30:15	IN-SERVICE DATE:	05/21/2008	
TECH SPEC NO:	08VNFORDE150	2008 FORD E150		UNIT SERIAL NO:	1FTNE14W18DB25153	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$31.39	\$0.00	\$49.22

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>17.83</b>	<b>31.39</b>	<b>0.00</b>	<b>49.22</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	06/30/2011 07:00:00	06/30/2011 07:18:36	0.31	\$17.83

<b>LABOR</b>						<b>17.83</b>
--------------	--	--	--	--	--	--------------

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	FL820S	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88

<b>PARTS</b>						<b>31.39</b>
--------------	--	--	--	--	--	--------------

# Work Order Charge Detail

UNIT NO: 237357 2008 FORD E150

WORK ORDER NO: 8645

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

The following parts are included with the standard job:

Part No : 1372  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

Part No : 5W20  
Qty : 224  
Description : OIL BOTTLE  
Manufacturer :

(LPATE) PM BY TM

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v25.1  
**Report Author:** FleetFocus M5  
**File Path:** C:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FLEETCRPROD.AdaptiveJobServer\~tmp  
**Data Extracted:** Thu Mar 05 2026 10:00:17 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773 04/30/25 - FFM5-3975

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '237357') //Q=