

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 42517

<b>USING DEPT NO:</b>	504103	<b>OPENED DATE:</b>	03/01/2022 14:48:20	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	03/02/2022 15:40:37	<b>METER 1 - M:</b>	123	<b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	03/03/2022 07:45:07	<b>IN-SERVICE DATE:</b>	02/25/2022	
<b>TECH SPEC NO:</b>	21FORDF1504X4	2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b>	1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.00	\$0.00	\$351.00	\$0.00	\$351.00
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.03	\$3.70	\$159.03	\$0.00	\$162.73
14-51-062	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 6**      **WORK ORDER TOTAL:**      **1.03**      **121.70**      **510.03**      **2.00**      **633.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	12052187	03/02/2022 07:15:00	03/02/2022 07:30:00	0.25	\$29.50
14-52-021	INSTALL GPS SYSTEM	12052187	03/02/2022 07:00:00	03/02/2022 07:30:00	0.50	\$59.00
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	12052187	03/01/2022 15:22:20	03/01/2022 15:24:13	0.03	\$3.70
14-51-062	INSTALL TOOLBOX ASSY	12052187	03/01/2022 15:21:38	03/01/2022 15:22:10	(0.01)	(\$1.05)
14-51-062	INSTALL TOOLBOX ASSY	12052187	03/01/2022 15:21:38	03/01/2022 15:22:10	0.01	\$1.05
14-51-062	INSTALL TOOLBOX ASSY	12052187	03/01/2022 15:21:38	03/01/2022 15:36:38	0.25	\$29.50
					<b>LABOR</b>	<b>121.70</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	WORDMARKS	WORDMARKS	0.00	1	\$0.00
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	WORDMARKS	WORDMARKS	0.00	(1)	\$0.00
14-53-006	INSTALL WORDMARKS/IDENTIFIERS	WORDMARKS	WORDMARKS	0.00	1	\$0.00
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT40083	2" BALL	66.54	1	\$66.54
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT40083	2" BALL	42.60	(1)	(\$42.60)

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45830	HITCH RECEIVER	21.84	1	\$21.84
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	BOL7040474	5/8 RECEIVER LOCK	70.65	1	\$70.65
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT40083	2" BALL	42.60	1	\$42.60
14-51-062	INSTALL TOOLBOX ASSY	CAMKS71MB	TOOLBOX KING SIZE CAMLOCK BLK	0.00	1	\$0.00
14-02-013	INSTALL FLOOR COVERINGS	446972	F150 REAR MATS	142.50	1	\$142.50
14-02-013	INSTALL FLOOR COVERINGS	446971V	FRONT FLOOR MATS	208.50	1	\$208.50
<b>PARTS</b>						<b>510.03</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 42517

---

## Work Order Notes

(EKIMBREL) INSTALL TOOLBOX  
(EKIMBREL) INSTALL HITCH AND BALL

---

## Job Notes

**14-02-013 - INSTALL FLOOR COVERINGS**

**14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK**

(JWRIGHT) Installed reciever

**14-51-062 - INSTALL TOOLBOX ASSY**

(JWRIGHT) Installed toolbox

**14-52-021 - INSTALL GPS SYSTEM**

(LISAPATE) Installed GPS serial# 5041372413 removed from unit 5906B

**14-53-006 - INSTALL WORDMARKS/IDENTIFIERS**

(LISAPATE) added wordmarks on both doors

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 43387

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 05/25/2022 07:09:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/26/2022 11:03:40	<b>METER 1 - M:</b> 862 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/27/2022 14:50:59	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.51	\$60.11	\$0.00	\$0.00	\$60.11
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.58	\$68.93	\$10.47	\$0.00	\$79.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **1.09**      **129.04**      **10.47**      **2.00**      **141.51**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11901357	05/25/2022 07:22:12	05/25/2022 07:52:46	0.51	\$60.11
66-17-030	PERFORM TIRE PATCH	11074414	05/26/2022 07:24:44	05/26/2022 07:59:47	0.58	\$68.93
<b>LABOR</b>					<b>1.09</b>	<b>129.04</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	0.35	1	\$0.35
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	5.73	1	\$5.73
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.82	1	\$3.82
<b>PARTS</b>					<b>1.09</b>	<b>10.47</b>

# Work Order Charge Detail

UNIT NO: 244537 2021 FORD F150 4X4

WORK ORDER NO: 43387

---

## Work Order Notes

(LISAPATE) LR brake light out  
(LISAPATE) Nail in LR tire

---

## Job Notes

### **03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(AGUERRA) miles: 862 Replaced L/R marker/brake light bulb, used non-stock bulb. Checked for proper operation, all good. AMG

### **66-17-030 - PERFORM TIRE PATCH**

(HHARBIN) Patched left rear tire. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 44191

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 08/05/2022 10:13:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/09/2022 08:43:16	<b>METER 1 - M:</b> 1453 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/09/2022 13:06:25	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.49	\$0.00	\$0.00	\$22.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.19**      **22.49**      **0.00**      **2.00**      **24.49**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/05/2022 14:58:28	08/05/2022 15:09:54	0.19	\$22.49
					<b>LABOR</b>	<b>22.49</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 44191

---

**Work Order Notes**

(CHANNELL) pm replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) Vehicle has 1453 miles on it. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 44358

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 08/17/2022 09:36:07	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/09/2022 14:25:58	<b>METER 1 - M:</b> 1453 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/12/2022 07:44:52	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-01	WARRANTY AIR CONDITIONING, HEAT,	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-05-020	WARRANTY PCM/PROCESSOR ASSEM	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-00	TRANSPORT COMPLETE VEHICLE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.65</b>	<b>76.70</b>	<b>0.00</b>	<b>5.00</b>	<b>81.70</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-01	WARRANTY AIR CONDITIONING, HEAT, VENT	11078175	103405		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	09/12/2022 07:00:00	09/12/2022 07:09:00	0.15	\$17.70
16-00	TRANSPORT COMPLETE VEHICLE	11915538	09/09/2022 07:00:00	09/09/2022 07:30:00	0.50	\$59.00
<b>LABOR</b>					<b>76.70</b>	

# Work Order Charge Detail

UNIT NO: 244537 2021 FORD F150 4X4

WORK ORDER NO: 44358

---

## Work Order Notes

(CWIGLEY) diagnose A/C. Driver says its not blowing out of vents

---

## Job Notes

### **15-01 - WARRANTY AIR CONDITIONING, HEAT, VENT**

(CHANNELL) Tuscaloosa ford fixed issue\ under warranty

(LISAPATE) Tuscaloosa Ford. Verified concern, found low side going to the evaporator was freezing up. Monitored pids on FDRS and found evap temp sensor was reading 61 degrees and the vent temp was 31. Performed evac and recharge. Had the right amount of refrigerant in system. Found evap temp sensor was biased. Removed dash and installed a new HVAC case assy. Recharged system. Verified repair.

### **15-05-020 - WARRANTY PCM/PROCESSOR ASSEMBLY**

(LISAPATE) Tuscaloosa Ford completed powertrain control module software update

### **16-00 - TRANSPORT COMPLETE VEHICLE**

(CHANNELL) RC\ transported vehicle to Tuscaloosa ford.

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(LISAPATE) Verified A/c not working take to Ford for warranty repair

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 45755

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 01/11/2023 07:02:52	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/13/2023 14:12:24	<b>METER 1 - M:</b> 2761 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/17/2023 09:16:45	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.92	\$15.63	\$0.00	\$22.55
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.34	\$40.35	\$0.00	\$0.00	\$40.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.44	\$91.52	\$0.00	\$108.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **0.55**      **64.71**      **107.15**      **5.00**      **176.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/11/2023 11:16:12	01/11/2023 11:36:43	0.34	\$40.35
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/11/2023 11:02:10	01/11/2023 11:05:41	0.06	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/11/2023 10:53:06	01/11/2023 11:01:58	0.15	\$17.44
<b>LABOR</b>					<b>64.71</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	1	\$6.08
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	10.68	8	\$85.44
<b>PARTS</b>					<b>107.15</b>	

# Work Order Charge Detail

UNIT NO: 244537 2021 FORD F150 4X4

WORK ORDER NO: 45755

---

## Work Order Notes

(EHANNAH) pm-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires relearned tire positions and inspected the brakes. Found no issues at this time. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/GC Performed PM

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 47144

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 05/23/2023 07:03:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/24/2023 10:55:33	<b>METER 1 - M:</b> 4067 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/24/2023 14:07:49	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.12	\$14.62	\$16.65	\$0.00	\$31.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.24	\$0.00	\$0.00	\$21.24
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.08	\$10.00	\$35.87	\$0.00	\$45.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.23	\$26.91	\$0.00	\$0.00	\$26.91

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.62</b>	<b>72.77</b>	<b>52.52</b>	<b>5.00</b>	<b>130.29</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	05/23/2023 08:38:48	05/23/2023 08:52:29	0.23	\$26.91
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	05/23/2023 08:33:08	05/23/2023 08:38:13	0.08	\$10.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/23/2023 08:17:29	05/23/2023 08:24:55	0.12	\$14.62
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/23/2023 08:06:28	05/23/2023 08:17:16	0.18	\$21.24
					<b>LABOR</b>	<b>72.77</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	35.87	1	\$35.87
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
					<b>PARTS</b>	<b>52.52</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 47144

---

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GRCOOK) Replaced wipers-GC

### **66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM-GC, Fluid check only, vehicle driven 1,306 miles, filters good, tires and tire pressure, updated oil change sticker.  
Miles, 4,067

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GRCOOK) Replaced cabin filter-GC

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GRCOOK) Washed vehicle-GC

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 48703

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 10/25/2023 08:18:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/26/2023 09:49:28	<b>METER 1 - M:</b> 5190 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/26/2023 13:25:59	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.11	\$16.65	\$0.00	\$19.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.52	\$81.60	\$0.00	\$102.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.30	\$34.88	\$0.00	\$0.00	\$34.88

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **0.50**      **58.51**      **98.25**      **5.00**      **161.76**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	10/25/2023 10:56:40	10/25/2023 11:14:24	0.30	\$34.88
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/25/2023 10:45:41	10/25/2023 10:47:16	0.03	\$3.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/25/2023 10:35:02	10/25/2023 10:45:28	0.17	\$20.52
					<b>LABOR</b> <b>58.51</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	9.48	8	\$75.84
					<b>PARTS</b> <b>98.25</b>	

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 48703

---

**Work Order Notes**

(EHANNAH) pm- wipers- wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed. SH

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 48881

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 11/08/2023 08:20:31	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/01/2023 11:06:15	<b>METER 1 - M:</b> 5190 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/01/2023 11:06:20	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-51-039	RECALL WIPER MOTOR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-79-001	RECALL AIR BAG	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **0.00**      **0.00**      **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-51-039	RECALL WIPER MOTOR	11099772	100617982		\$0.00
				<b>COMML</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 48881

---

## Work Order Notes

(EHANNAH) install new wiper motor

---

## Job Notes

### **03-51-039 - REPLACE NEW WIPER MOTOR**

(LRUSHING) Visit Reason Changed On 11/8/2023 11:35 AM By LRUSHING

### **17-51-039 - RECALL WIPER MOTOR**

(LISAPATE) omg Lewis replaced wiper motor

### **17-79-001 - RECALL AIR BAG**

(LISAPATE) Log Lewis resecured harness

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 50483

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 04/09/2024 09:46:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/10/2024 11:08:16	<b>METER 1 - M:</b> 6799 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/10/2024 12:21:52	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.47	\$24.30	\$0.00	\$33.77
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.15	\$18.30	\$0.00	\$19.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.46	\$53.69	\$0.00	\$0.00	\$53.69

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.55</b>	<b>64.31</b>	<b>42.60</b>	<b>5.00</b>	<b>111.91</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	04/09/2024 10:05:01	04/09/2024 10:32:19	0.46	\$53.69
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	04/09/2024 10:03:35	04/09/2024 10:04:10	0.01	\$1.15
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/09/2024 09:58:24	04/09/2024 10:03:13	0.08	\$9.47
					<b>LABOR</b>	<b>64.31</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA5642F	AIR FILTER	24.30	1	\$24.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC8214	CABIN FILTER	18.30	1	\$18.30
					<b>PARTS</b>	<b>42.60</b>

# Work Order Charge Detail

UNIT NO: 244537 2021 FORD F150 4X4

WORK ORDER NO: 50483

---

## Work Order Notes

(EHANNAH) pm- wiper- wash

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) perform fluid check fc

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) replaced cabin filter fc

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(FCONTRER) Wash fc

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 50775

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 05/08/2024 07:04:47	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/08/2024 08:07:21	<b>METER 1 - M:</b> 6888 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/30/2024 14:40:23	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.04	\$4.39	\$6.75	\$0.00	\$11.14
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.04** **4.39** **6.75** **5.00** **16.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	12201267	05/08/2024 07:08:23	05/08/2024 07:10:37	0.04	\$4.39
					<b>LABOR</b>	<b>4.39</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2032	BUTTON CELL BATTERY 3V	6.75	1	\$6.75
					<b>PARTS</b>	<b>6.75</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 50775

---

**Work Order Notes**

(EHANNAH) key fob

---

**Job Notes**

**03-51-042 - REPLACE NEW KEY FOB BATTERY**

(GRCOOK) Replaced key fob battery on unit 4059C -GC

**CH-SP - CHARGE Shop Supplies**

(LRUSHING) Visit Reason Changed On 5/31/2024 8:09 AM By LRUSHING

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 50801

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 05/10/2024 07:14:35	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/14/2024 15:20:04	<b>METER 1 - M:</b> 6888 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/15/2024 07:40:46	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$391.00	\$391.00
16-71-023	TRANSPORT WINDSHIELD REPLACEMI	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>396.00</b>	<b>396.00</b>
---------------------	--------------------------	-------------	-------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	118266		(\$391.00)
03-02-061	REPLACE NEW WINDSHIELD	11078716	118266		\$391.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	118266		\$391.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>396.00</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 50801

---

## Work Order Notes

(EHANNAH) pm-wipes wash  
(EKIMBREL) did not need wipers

---

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(IFALLS) glass dr replaced windshield  
(LRUSHING) Visit Reason Changed On 5/23/2024 2:41 PM By LRUSHING

### **03-51-038 - REPLACE NEW WIPER BLADES**

### **16-71-023 - TRANSPORT WINDSHIELD REPLACEMENT**

(IFALLS) CW performed transport  
(LRUSHING) Visit Reason Changed On 5/23/2024 2:41 PM By LRUSHING

### **66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) fc performed pm

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(EKIMBREL) fc washed car

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 52563

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 10/23/2024 07:13:27	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/24/2024 07:52:53	<b>METER 1 - M:</b> 8011 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/24/2024 08:35:56	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.65	\$0.00	\$16.65
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$77.40	\$0.00	\$77.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>94.05</b>	<b>5.00</b>	<b>99.05</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.96	8	\$71.64
					<b>PARTS</b>	<b>94.05</b>

# Work Order Charge Detail

UNIT NO: 244537 2021 FORD F150 4X4

WORK ORDER NO: 52563

---

## Work Order Notes

(EHANNAH) pm- wipers- wash- PR tire keeps going low  
(EHANNAH) please check master key

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(EHOWELL) Wipers were replaced.

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

### **66-17-030 - PERFORM TIRE PATCH**

(GARAGE) performed tire patch mounted and balanced tire checked ok, cm

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR-performed PM, checked fluids, FJ & JR- checked tires and pressure

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 52869

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 11/21/2024 08:29:36	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/22/2024 09:53:01	<b>METER 1 - M:</b> 8118 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/22/2024 10:50:21	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-063	REPLACE NEW REAR WINDOW/BACK C	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$550.86	\$550.86
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **555.86** **555.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-063	REPLACE NEW REAR WINDOW/BACK GLASS	11078716	2-123142		\$550.86
				<b>COMML</b>	<b>555.86</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 52869

---

**Work Order Notes**

(EHANNAH) back glass replaced by Glass Dr.

---

**Job Notes**

**03-02-063 - REPLACE NEW REAR WINDOW/BACK GLASS**

(EHOWELL) Glass Doctor replaced the vehicle's back glass here at our facility.

**CH-SP - CHARGE Shop Supplies**

(JWEATHER) Visit Reason Changed On 11/26/2024 2:14 PM By JWEATHER

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 54292

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 04/03/2025 07:16:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/03/2025 09:05:27	<b>METER 1 - M:</b> 9369 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/03/2025 12:38:35	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$30.00	\$0.00	\$30.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT:</b> 6	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>30.00</b>	<b>5.00</b>	<b>35.00</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	30.00	1	\$30.00
					<b>PARTS</b>	<b>30.00</b>

# Work Order Charge Detail

UNIT NO: 244537 2021 FORD F150 4X4

WORK ORDER NO: 54292

---

## Work Order Notes

(EHANNAH) pm- wipers- wash - SI

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Blades replaced during last PM.

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) FJ- Performed SI. All steering/suspension components checked ok at this time. No other issues found.

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- Fluid check. Mileage is 9369. Driven 362 miles since last PM. Topped off fluids, checked filters (cabin filter was needed), set tire pressure, recorded date codes & tread depths.

\*\*\*Tire rotation performed\*\*\*

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GARAGE) FJ- Replaced cabin filter.

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) FJ- Washed vehicle.

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**      **WORK ORDER NO:** 54769

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 05/13/2025 12:54:29	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/22/2025 08:42:54	<b>METER 1 - M:</b> 9460 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/22/2025 08:42:54	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PR-05-020	PROGRAM PCM/PROCESSOR ASSEMB	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **0.00**      **0.00**      **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PR-05-020	PROGRAM PCM/PROCESSOR ASSEMBLY	2714700	180800		\$0.00
<b>COMML</b>					<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 54769

---

## Work Order Notes

(EHANNAH) warrenty for software update by Stivers

---

## Job Notes

### **17-GA-005 - RECALL Scheduling and Preparation**

(EHOWELL) Automotive Services opened a work order and documented repairs performed by Stivers Ford.

### **PR-05-020 - PROGRAM PCM/PROCESSOR ASSEMBLY**

(EHOWELL) Stivers performed recall # 25S24B and verified the software of the powertrain control module.

---

# Work Order Charge Detail

**UNIT NO:** 244537      **2021 FORD F150 4X4**

**WORK ORDER NO:** 56171

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 08/29/2025 10:52:06	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/29/2025 14:24:50	<b>METER 1 - M:</b> 10036 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/29/2025 15:01:22	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4      2021 Ford F150 4X4	<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$8.94	\$0.00	\$8.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **8.94**      **5.00**      **13.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	8.94	1	\$8.94
<b>PARTS</b>						<b>8.94</b>

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 56171

---

## Work Order Notes

(EHANNAH) pm- wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) did not need. CQ

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) 10,036 MILES, DRIVEN 1,029, CHECKER. CHECKED ALL FLUIDS AND TOPPED OFF OIL HALF A QUART LOW. SET TIRE PRESSURES, RECORDED BUILD DATES AND TREAD DEPTH AND INSTALLED NEW STICKER. CQ

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) did not need washed.CQ

---

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 57416

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 12/03/2025 07:55:07	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/09/2025 11:39:24	<b>METER 1 - M:</b> 10470 <b>METER 2 - H:</b> 202
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/10/2025 08:13:16	<b>IN-SERVICE DATE:</b> 02/25/2022
<b>TECH SPEC NO:</b> 21FORDF1504X4 2021 Ford F150 4X4		<b>UNIT SERIAL NO:</b> 1FTFW1E58MFD10466

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-51-062	REMOVE TOOLBOX ASSY	DON	5	N	GARAGE	0.25	\$37.50	\$0.00	\$0.00	\$37.50
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.50	\$75.00	\$0.00	\$0.00	\$75.00
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.75</b>	<b>262.50</b>	<b>0.00</b>	<b>5.00</b>	<b>267.50</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	12/09/2025 10:26:58	12/09/2025 11:26:58	1.00	\$150.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	12/09/2025 10:26:58	12/09/2025 11:13:14	0.77	\$115.67
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12480657	12/09/2025 10:26:58	12/09/2025 11:13:14	(0.77)	(\$115.67)
25-51-062	REMOVE TOOLBOX ASSY	12201267	12/10/2025 07:00:00	12/10/2025 07:09:00	0.15	\$22.50
25-51-062	REMOVE TOOLBOX ASSY	12051004	12/10/2025 07:00:00	12/10/2025 07:06:00	0.10	\$15.00
25-52-021	REMOVE GPS SYSTEM	12201267	12/10/2025 07:00:00	12/10/2025 07:30:00	0.50	\$75.00
<b>LABOR</b>					<b>262.50</b>	

# Work Order Charge Detail

**UNIT NO:** 244537 2021 FORD F150 4X4

**WORK ORDER NO:** 57416

---

**Work Order Notes**

(EKIMBREL) PREP FOR SALE, REMOVE GPS AND TOOLBOX

---

**Job Notes**

**25-51-062 - REMOVE TOOLBOX ASSY**

(GARAGE) JR\_ & GC- removed toolbox from 4059c and put it on 8198b

**25-52-021 - REMOVE GPS SYSTEM**

(GARAGE) GC- removed GPS from 4059c and put it into 8198b

(GARAGE) GPS S/N: 87U030640200

**CH-SP - CHARGE Shop Supplies**

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) CM performed prep for sale, unit had 10,470 miles, GPS/TOOLBOX was removed before prep for dispose was done both were transfer to new unit,

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Dec 12 2025 11:40:07 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '244537') //Q=