

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 42910

USING DEPT NO:	510206	OPENED DATE:	04/13/2022 09:57:12	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/13/2022 10:03:30	METER 1 - M:	18	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/30/2022 07:51:17	IN-SERVICE DATE:	04/07/2022		
TECH SPEC NO:	22TOYTACOM4X4	2022 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TYSZ5AN4NT068915		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL: 1.00 118.00 0.00 5.00 123.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	04/13/2022 10:02:32	04/13/2022 11:02:32	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 42910

Work Order Notes

(LISAPATE) new unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 43069

USING DEPT NO: 510206	OPENED DATE: 04/27/2022 09:44:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/14/2022 09:02:25	METER 1 - M: 18 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/16/2022 09:24:50	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4	2022 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.02	\$2.85	\$175.43	\$14.95	\$193.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.85	175.43	16.95	195.23
---------------------	--------------------------	-------------	-------------	---------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	11074386	100647518		\$14.95
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					16.95

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	11915538	04/27/2022 09:48:04	04/27/2022 09:49:31	0.02	\$2.85
LABOR					2.85	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	4412991	FRONT FLOOR MATS TACOMA	175.43	1	\$175.43
PARTS					175.43	

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 43069

Work Order Notes

(EKIMBREL) INSTALL FRONT FLOOR MATS

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(GARAGE) installed two floor mats\RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 44470

USING DEPT NO: 510206	OPENED DATE: 08/26/2022 07:41:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/29/2022 10:16:16	METER 1 - M: 975 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/30/2022 08:56:29	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.60	\$0.00	\$0.00	\$11.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.10** **11.60** **0.00** **5.00** **16.60**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/26/2022 07:52:00	08/26/2022 07:57:54	0.10	\$11.60
					LABOR	11.60

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 44470

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 975 miles. Checked fluids and tires. Coolant -34°. JAW,AMG
MILEAGE-975

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 45102

USING DEPT NO:	510206	OPENED DATE:	10/27/2022 14:44:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2022 10:08:00	METER 1 - M:	1166	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2022 15:45:17	IN-SERVICE DATE:	04/07/2022	
TECH SPEC NO:	22TOYTACOM4X4	2022 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TYSZ5AN4NT068915	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$20.94	\$0.00	\$38.64
16-51	TRANSPORT GENERAL ACCESSORIES	DON	5	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PR-51-046	PROGRAM KEY BLANK(S)	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$92.00	\$92.00
PU-51-046	PURCHASED KEY BLANK(S)	DON	5	N	GARAGE	0.10	\$11.80	\$398.49	\$0.00	\$410.29

JOB COUNT: 5	WORK ORDER TOTAL:	0.75	88.50	419.43	97.00	604.93
---------------------	--------------------------	-------------	--------------	---------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PR-51-046	PROGRAM KEY BLANK(S)	11076422	6180748		\$92.00
PR-51-046	PROGRAM KEY BLANK(S)	11076422	6180748		(\$92.00)
PR-51-046	PROGRAM KEY BLANK(S)	11076422	6180748		\$92.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					97.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-51	TRANSPORT GENERAL ACCESSORIES	11915538	11/10/2022 07:00:00	11/10/2022 07:30:00	0.50	\$59.00
PU-51-046	PURCHASED KEY BLANK(S)	10208562	11/10/2022 07:00:00	11/10/2022 07:06:00	(0.10)	(\$11.80)
PU-51-046	PURCHASED KEY BLANK(S)	10208562	11/10/2022 07:00:00	11/10/2022 07:06:00	0.10	\$11.80
PU-51-046	PURCHASED KEY BLANK(S)	10208562	11/10/2022 07:00:00	11/10/2022 07:06:00	0.10	\$11.80
16-51	TRANSPORT GENERAL ACCESSORIES	11915538	11/10/2022 07:00:00	11/10/2022 07:30:00	0.50	\$59.00
16-51	TRANSPORT GENERAL ACCESSORIES	11915538	11/10/2022 07:00:00	11/10/2022 07:30:00	(0.50)	(\$59.00)
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/31/2022 12:44:40	10/31/2022 12:44:40	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/31/2022 12:44:40	10/31/2022 12:44:40	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/31/2022 12:44:40	10/31/2022 12:53:40	0.15	\$17.70
LABOR					88.50	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
-----------------	------------------------	-----------------	--------------------	-------------------	-----------------	-------------------

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
PU-51-046	PURCHASED KEY BLANK(S)	8907004060	KEY TACOMA	199.25	2	\$398.49
PU-51-046	PURCHASED KEY BLANK(S)	8907004060	KEY TACOMA	199.25	(2)	(\$398.49)
PU-51-046	PURCHASED KEY BLANK(S)	8907004060	KEY TACOMA	199.25	2	\$398.49
PARTS						419.43

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 45102

Work Order Notes

(LISAPATE) Replace wipers-Keith requested 2 keys

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

16-51 - TRANSPORT GENERAL ACCESSORIES

(LISAPATE) Taken to Toyota by RC

(AJONES) Visit Reason Changed On 11/18/2022 1:56 PM By AJONES

CH-SP - CHARGE Shop Supplies

PR-51-046 - PROGRAM KEY BLANK(S)

(LISAPATE) Tuscaloosa Toyota programmed all keys with built in fobs. Pd by CC

(AJONES) Visit Reason Changed On 11/18/2022 1:56 PM By AJONES

PU-51-046 - PURCHASED KEY BLANK(S)

(LISAPATE) Purchased 2 keys per Keith McKnight

(AJONES) Visit Reason Changed On 11/18/2022 1:56 PM By AJONES

Work Order Charge Detail

UNIT NO: 244597 **2022 TOYOTA TACOMA 4X4**

WORK ORDER NO: 45923

USING DEPT NO: 510206	OPENED DATE: 01/26/2023 09:31:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/27/2023 13:46:31	METER 1 - M: 1316 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/27/2023 15:43:29	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TYSZ5AN4NT068915	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.83	\$0.00	\$0.00	\$35.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.30** **35.83** **0.00** **5.00** **40.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/27/2023 07:06:25	01/27/2023 07:24:38	0.30	\$35.83
LABOR						35.83

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 45923

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 1316 New vehicle. Checked fluids, battery and tires. Updated oil change sticker. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 46941

USING DEPT NO:	510206	OPENED DATE:	05/03/2023 10:47:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/04/2023 11:09:15	METER 1 - M:	1487	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2023 15:45:26	IN-SERVICE DATE:	04/07/2022	
TECH SPEC NO:	22TOYTACOM4X4	2022 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TYSZ5AN4NT068915	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$16.61	\$0.00	\$34.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.37	\$43.85	\$0.00	\$79.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.06	\$6.49	\$0.00	\$0.00	\$6.49

JOB COUNT: 4	WORK ORDER TOTAL:	0.50	59.56	60.46	5.00	125.02
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/03/2023 15:27:44	05/03/2023 15:42:49	0.25	\$29.66
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/04/2023 07:40:02	05/04/2023 07:42:56	0.05	\$5.70
WA-00	WASH COMPLETE VEHICLE	12201267	05/04/2023 07:45:28	05/04/2023 07:48:46	0.06	\$6.49
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/04/2023 07:00:00	05/04/2023 07:09:00	0.15	\$17.70
LABOR					59.55	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.28	1	\$8.28
PARTS					60.46	

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 46941

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM- JW,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 1,487

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-CW

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 48615

USING DEPT NO:	510206	OPENED DATE:	10/18/2023 10:14:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2023 10:45:27	METER 1 - M:	2144	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/20/2023 08:41:41	IN-SERVICE DATE:	04/07/2022	
TECH SPEC NO:	22TOYTACOM4X4	2022 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TYSZ5AN4NT068915	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.34	\$21.70	\$0.00	\$33.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.90	\$0.00	\$0.00	\$19.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.27	\$32.19	\$0.00	\$0.00	\$32.19

JOB COUNT: 4	WORK ORDER TOTAL:	0.54	63.43	21.70	5.00	90.13
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	10/19/2023 07:24:43	10/19/2023 07:41:05	0.27	\$32.19
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/19/2023 07:18:32	10/19/2023 07:24:18	0.10	\$11.34
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/19/2023 07:00:00	10/19/2023 07:10:07	0.17	\$19.90
				LABOR		63.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
					PARTS	21.70

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 48615

Work Order Notes

(EHANNAH) pm- wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Ranplacd new wipes fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check tires pressure and tread fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 50218

USING DEPT NO:	510206	OPENED DATE:	03/22/2024 15:48:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/26/2024 07:48:04	METER 1 - M:	2559	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/26/2024 12:46:29	IN-SERVICE DATE:	04/07/2022	
TECH SPEC NO:	22TOYTACOM4X4	2022 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TYSZ5AN4NT068915	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.69	\$16.66	\$0.00	\$21.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.08	\$60.65	\$0.00	\$128.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.45	\$53.56	\$0.00	\$0.00	\$53.56

JOB COUNT: 4 **WORK ORDER TOTAL: 1.07 126.33 77.31 5.00 208.64**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/25/2024 07:45:27	03/25/2024 08:20:04	0.58	\$68.08
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/25/2024 08:20:04	03/25/2024 08:22:27	0.04	\$4.69
WA-00	WASH COMPLETE VEHICLE	11074414	03/25/2024 08:32:57	03/25/2024 09:00:11	0.45	\$53.56
					LABOR 126.33	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
					PARTS 77.31	

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 50218

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 52119

USING DEPT NO: 510206	OPENED DATE: 09/13/2024 08:42:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/16/2024 11:30:01	METER 1 - M: 3115 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/16/2024 12:55:50	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 52119

Work Order Notes

(EHANNAH) pm- wipers- SI- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC
Brake pads are 10mm front and rear.
Miles, 3,115

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Fluid check only, vehicle driven 556 miles, checked fluids, filters good, tires and tire pressure, updated oil change sticker.
Miles, 3,115

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-CM

Work Order Charge Detail

UNIT NO: 244597 **2022 TOYOTA TACOMA 4X4**

WORK ORDER NO: 53881

USING DEPT NO: 510206	OPENED DATE: 02/25/2025 10:02:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/26/2025 07:14:41	METER 1 - M: 3542 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/26/2025 08:45:36	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TYSZ5AN4NT068915	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$30.08	\$0.00	\$30.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.78	\$0.00	\$60.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$24.18	\$0.00	\$24.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	115.04	5.00	120.04
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	(1)	(\$7.65)
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	24.18	1	\$24.18
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.34	1	\$14.34
03-51-038	REPLACE NEW WIPER BLADES	25-200	20" WIPERS	15.04	1	\$15.04
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.47	6	\$38.79
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
03-51-038	REPLACE NEW WIPER BLADES	25-220	BEAM WIPER BLADE	15.04	1	\$15.04
PARTS						115.04

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 53881

Work Order Notes

(CWIGLEY) PM. Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR/CM- Top

FJ- Bottom

CM/JR- Topped off fluids, added new oil & verified oil level, set tire pressure, recorded date codes & tread depths, checked filters.

FJ- Oil change.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FJ- Replaced cabin filter.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 55362

USING DEPT NO: 510206	OPENED DATE: 07/10/2025 14:46:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/15/2025 10:28:32	METER 1 - M: 3814 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 07/15/2025 12:14:56	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 55362

Work Order Notes

(EHOWELL) Send the vehicle to Fleet to be detailed inside and out after it's serviced.
(GARAGE) waiting to get vehicle back from fleet for SI
(GARAGE) fleet released the vehicle back to the department before we could do the SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, fluid check only, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
3814 miles, 272 miles driven

Work Order Charge Detail

UNIT NO: 244597 **2022 TOYOTA TACOMA 4X4**

WORK ORDER NO: 56834

USING DEPT NO: 510206	OPENED DATE: 10/16/2025 07:36:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/16/2025 12:52:15	METER 1 - M: 4144 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2025 07:12:12	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4	2022 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.50	\$75.00	\$162.53	\$0.00	\$237.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$75.00	\$7.01	\$0.00	\$82.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.00	150.00	169.54	5.00	324.54
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12051004	10/16/2025 10:09:21	10/16/2025 10:16:03	(0.11)	(\$16.75)
66-PM-PMA	PERFORM OIL CHANGE	12051004	10/16/2025 10:09:21	10/16/2025 10:16:03	0.11	\$16.75
66-PM-PMA	PERFORM OIL CHANGE	12051004	10/16/2025 10:09:21	10/16/2025 10:39:21	0.50	\$75.00
03-32-002	REPLACE NEW BATTERY	11779687	10/16/2025 12:54:03	10/16/2025 13:19:15	0.42	\$63.00
03-32-002	REPLACE NEW BATTERY	11779687	10/16/2025 12:54:03	10/16/2025 13:19:15	(0.42)	(\$63.00)
03-32-002	REPLACE NEW BATTERY	11779687	10/16/2025 12:54:03	10/16/2025 13:24:03	0.50	\$75.00
					LABOR	150.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F-3	BATTERY	162.53	1	\$162.53
66-PM-PMA	PERFORM OIL CHANGE	92006	WASHER FLUID	7.01	1	\$7.01
					PARTS	169.54

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 56834

Work Order Notes

(EKIMBREL) pm

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) FJ- Replaced battery. Alternator charging @ 14.2 volts

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) 4,144 miles

Fluid check

Driven 602 miles since PM

FJ- Topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 57023

USING DEPT NO: 510206	OPENED DATE: 10/30/2025 09:58:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/31/2025 14:10:08	METER 1 - M: 4148 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/31/2025 15:30:49	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4	2022 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
20-00	TOWING COMPLETE VEHICLE	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$94.30	\$94.30
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$75.00	\$0.00	\$0.00	\$75.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.50	225.00	0.00	99.30	324.30
---------------------	--------------------------	-------------	---------------	-------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
20-00	TOWING COMPLETE VEHICLE	11076249	2523195		\$94.30
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
COMML					99.30

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-00	SCAN OUT COMPLETE VEHICLE	12480657	10/30/2025 10:51:24	10/30/2025 11:34:49	(0.72)	(\$108.54)
SO-00	SCAN OUT COMPLETE VEHICLE	12480657	10/30/2025 10:51:24	10/30/2025 11:34:49	0.72	\$108.54
SO-00	SCAN OUT COMPLETE VEHICLE	12480657	10/30/2025 10:51:24	10/30/2025 11:51:24	1.00	\$150.00
66-79-002	PERFORM SERVICE CALL	12480657	10/31/2025 07:00:00	10/31/2025 07:30:00	0.50	\$75.00
LABOR					225.00	

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 57023

Work Order Notes

(EKIMBREL) WONT START

Job Notes

20-00 - TOWING COMPLETE VEHICLE

(EKIMBREL) BAMBARGER TOWED VEHICLE TO SHOP

66-79-002 - PERFORM SERVICE CALL

(GARAGE) CM/GC performed service call unit had 4148 miles, found battery cable loose on battery, tighten cable, unit had active fault with checked engine light on dash, unit would turn over but would not start checked all fuse relays checked wiring harness for damage or cuts, everything checked ok, checked fuel fuel pressure checked ok, fuel was clean with no issues unit will had to be towed to shop for further test,

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(GARAGE) CM scan out unit unit had 2 active faults unit had active fault with checked engine light on dash, fault was for start ability malfunction, and key malfunction, unit would turn over but would not start checked all fuse relays checked wiring harness for damage or cuts, everything checked ok, checked fuel fuel pressure checked ok, fuel was clean with no issues unit will had to be towed to shop for further test, checked over vehicle further at shop found no issue with unit customer was contacted to bring extra keys to shop for testing, both spare keys started vehicle with no issues. KEY is bad will have to be reprogrammed to vehicle,,

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 57402

USING DEPT NO: 510206	OPENED DATE: 12/02/2025 10:55:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/02/2025 15:05:37	METER 1 - M: 4762 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 12/02/2025 15:09:20	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4		UNIT SERIAL NO: 3TYSZ5AN4NT068915

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 57402

Work Order Notes

(EHOWELL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Deferred from Work Order# 57402. By User ID EHOWELL on 12/2/2025 10:56 AM.

(EHOWELL) The customer was inquiring about the service on this vehicle.

This vehicle is coming due on the PM forecast December 11th. EH pulled the history of the last three services and the vehicle PM service isn't due until March 16, 2026, or 7542 miles. (This is what the oil change sticker currently states in the vehicle)

Feb 26. the oil was changed. 3542 miles

July 11, the oil was checked. 3814 miles

Oct 16. The oil was checked. 4144 miles (This PM wasn't actually due until December 11th) EH and the customer agreed to do the oil change this visit. (Technically the oil should've been dropped on Dec. 11, but we performed the PM 8 weeks early.)

Ben sent a picture of the vehicle's mileage on 12/1/2025 and it was 4762, therefore the vehicle has only been driven 1220 miles since the oil was dropped. EH told the customer that the oil change sticker in the windshield is correct.

We are not charging parts nor labor, we're just using this work order to remove the vehicle from the forecast.

Work Order Charge Detail

UNIT NO: 244597 **2022 TOYOTA TACOMA 4X4**

WORK ORDER NO: 58393

USING DEPT NO: 510206	OPENED DATE: 02/20/2026 09:57:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/20/2026 10:18:16	METER 1 - M: 6208 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/23/2026 07:39:06	IN-SERVICE DATE: 04/07/2022
TECH SPEC NO: 22TOYTACOM4X4 2022 Toyota Tacoma 4X4	UNIT SERIAL NO: 3TYSZ5AN4NT068915	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-999	PERFORM PREPARE UNIT FOR DISPOS	DON	D	N	GARAGE	1.00	\$150.00	\$0.00	\$0.00	\$150.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **150.00** **0.00** **5.00** **155.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-999	PERFORM PREPARE UNIT FOR DISPOSAL	12480657	02/20/2026 09:59:24	02/20/2026 10:59:24	1.00	\$150.00
66-00-999	PERFORM PREPARE UNIT FOR DISPOSAL	12480657	02/20/2026 09:59:24	02/20/2026 10:13:43	0.24	\$35.79
66-00-999	PERFORM PREPARE UNIT FOR DISPOSAL	12480657	02/20/2026 09:59:24	02/20/2026 10:13:43	(0.24)	(\$35.79)
LABOR					150.00	

Work Order Charge Detail

UNIT NO: 244597 2022 TOYOTA TACOMA 4X4

WORK ORDER NO: 58393

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

66-00-999 - PERFORM PREPARE UNIT FOR DISPOSAL

(GARAGE) CM Performed perp for sale unit had 6208 miles,

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Feb 23 2026 14:51:43 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244597') //Q=