

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 20844

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 07/21/2015 10:01:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/22/2015 07:38:31	<b>METER 1 - M:</b> 166 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/22/2015 07:38:33	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPGF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **28.75**      **0.00**      **0.00**      **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10337093	07/21/2015 10:04:32	07/21/2015 10:34:32	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 20844

---

**Work Order Notes**

(LPATE) DO PDI

---

**Job Notes**

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 22473

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	02/04/2016 08:13:22	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	02/08/2016 06:29:56	<b>METER 1 - M:</b>	4695	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	02/08/2016 06:29:57	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$18.18	\$25.86	\$0.00	\$44.04

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.32**      **18.18**      **25.86**      **0.00**      **44.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/05/2016 07:21:36	02/05/2016 07:40:34	0.32	\$18.18
					<b>LABOR</b>	<b>18.18</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	192	\$23.04
					<b>PARTS</b>	<b>25.86</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 22473

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM BY SH

---

# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500 WORK ORDER NO: 24722

USING DEPT NO:	601701	OPENED DATE:	10/24/2016 09:42:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2016 09:18:34	METER 1 - M:	12291	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2016 09:18:35	IN-SERVICE DATE:	07/10/2015	
TECH SPEC NO:	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		UNIT SERIAL NO:	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$42.31	\$0.00	\$60.14

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 42.31 0.00 60.14

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11213180	10/24/2016 09:44:23	10/24/2016 10:02:59	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	46573	FILTER-AIR	10.41	1	\$10.41
66-PM-PMA	PERFORM OIL CHANGE	10W30SSQT	10W30 SEMI SYN QT. BOTTLE	4.85	6	\$29.07
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	5.99	1	\$5.99
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	5.99	(1)	(\$5.99)
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.83	1	\$2.83
					<b>PARTS</b>	<b>42.31</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 24722

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM BY MS/CS-REPLACED AIR FILTER

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 26274

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 05/02/2017 13:50:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/08/2017 06:25:44	<b>METER 1 - M:</b> 16231 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/08/2017 06:25:45	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$22.08	\$0.00	\$39.91

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.81**      **46.58**      **22.08**      **0.00**      **68.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	05/04/2017 07:00:00	05/04/2017 07:18:36	0.31	\$17.83
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11170580	05/04/2017 07:18:36	05/04/2017 07:48:36	0.50	\$28.75
					<b>LABOR</b>	<b>46.58</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30P	PROTECK10W30SEMI SYNTHETIC OIL	3.21	6	\$19.26
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
					<b>PARTS</b>	<b>22.08</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 26274

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) ROTATED TIRES

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM BY TB/AB

---



# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500 WORK ORDER NO: 26333

USING DEPT NO:	601701	OPENED DATE:	05/11/2017 09:53:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2017 06:52:11	METER 1 - M:	16231	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2017 06:52:13	IN-SERVICE DATE:	07/10/2015	
TECH SPEC NO:	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		UNIT SERIAL NO:	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-06	INSTALL CRUISE CONTROL	DON	O	N	GARAGE	1.00	\$57.50	\$352.50	\$0.00	\$410.00

JOB COUNT: 1 WORK ORDER TOTAL: 1.00 57.50 352.50 0.00 410.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-06	INSTALL CRUISE CONTROL	11213180	05/11/2017 09:55:27	05/11/2017 10:55:27	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-06	INSTALL CRUISE CONTROL	ROST2509608	CRUISE CONTROL ASSY	352.50	1	\$352.50
					<b>PARTS</b>	<b>352.50</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 26333

---

**Work Order Notes**

(LISAPATE) FLEET REQUESTED INSTALL CRUISE CONTROL

---

**Job Notes**

**14-06 - INSTALL CRUISE CONTROL**

(LISAPATE) INSTALLED CRUISE CONTROL ASSY. RECHECKED OK

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 27947

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	10/25/2017 14:06:58	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	10/27/2017 07:45:50	<b>METER 1 - M:</b>	21008	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	10/27/2017 07:45:52	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$21.99	\$0.00	\$39.82

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **17.83**      **21.99**      **0.00**      **39.82**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/26/2017 07:00:00	10/26/2017 07:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	10W30P	PROTECK10W30SEMI SYNTHETIC OIL	3.20	6	\$19.17
					<b>PARTS</b>	<b>21.99</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 27947

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM BY CS

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 29225

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	03/28/2018 09:18:02	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	04/03/2018 10:25:46	<b>METER 1 - M:</b>	26874	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	04/03/2018 10:25:47	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$16.86	\$0.00	\$34.69

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **17.83**      **16.86**      **0.00**      **34.69**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	03/29/2018 07:00:00	03/29/2018 07:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.34	6	\$14.04
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
					<b>PARTS</b>	<b>16.86</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 29225

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM BY CS  
COOLANT -47'

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 29546

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 04/24/2018 09:19:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/30/2018 10:08:09	<b>METER 1 - M:</b> 30521 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 04/30/2018 10:08:09	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$23.00	\$6.91	\$0.00	\$29.91
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$27.27	\$0.00	\$45.10

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.71**      **40.83**      **34.18**      **0.00**      **75.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/24/2018 13:56:29	04/24/2018 14:15:05	0.31	\$17.83
66-17-030	PERFORM TIRE PATCH	11074414	04/24/2018 13:56:37	04/24/2018 14:20:37	0.40	\$23.00
					<b>LABOR</b>	<b>40.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.51	1	\$3.51
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.01	1	\$3.01
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.39	1	\$0.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	14041	PATCH 1/4 PILOT WIRE	3.51	(1)	(\$3.51)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.00	(1)	(\$3.00)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.39	(1)	(\$0.39)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	14041	PATCH 1/4 PILOT WIRE	3.51	1	\$3.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.00	1	\$3.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.39	1	\$0.39
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	46573	FILTER-AIR	10.41	1	\$10.41
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.34	6	\$14.04
					<b>PARTS</b>	<b>34.18</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 29546

---

**Work Order Notes**

(RTUNAITI) low tire, PM due, needs wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

**66-17-030 - PERFORM TIRE PATCH**

(RTUNAITI) Found nail in LR tire. Patched tire and rebalanced

**66-PM-PMA - PERFORM OIL CHANGE**

(RTUNAITI)

(RTUNAITI) PM by SH

Coolant -20'

**PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES**

---



# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 31121

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	10/09/2018 10:11:10	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	10/12/2018 09:07:18	<b>METER 1 - M:</b>	37905	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	10/12/2018 09:07:19	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$25.59	\$0.00	\$43.72
06-02-055	INSPECT DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.01	\$0.46	\$0.00	\$0.00	\$0.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$23.38	\$19.92	\$0.00	\$43.30

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.58</b>	<b>41.97</b>	<b>45.51</b>	<b>0.00</b>	<b>87.48</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/10/2018 07:52:44	10/10/2018 08:12:05	0.32	\$23.38
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/10/2018 07:52:44	10/10/2018 08:12:05	(0.32)	(\$23.38)
06-02-055	INSPECT DOOR LATCH/STRIKER	11901357	10/10/2018 08:13:01	10/10/2018 08:13:24	0.01	\$0.46
03-51-038	REPLACE NEW WIPER BLADES	11915538	10/10/2018 07:00:00	10/10/2018 07:15:00	0.25	\$18.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2018 07:52:44	10/10/2018 08:12:05	0.32	\$23.38
					<b>LABOR</b>	<b>41.97</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	12.80	2	\$25.59
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.85	6	\$17.10
					<b>PARTS</b>	<b>45.51</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 31121

---

## Work Order Notes

(LISAPATE) PM-Rear doors wont open

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) Replaced wipers

### **06-02-055 - INSPECT DOOR LATCH/STRIKER**

(LISAPATE) Rear door wouldn't open from the inside, found child safety lock was on. turned off door is working fine now

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by AG,CS/SH

Coolant -37'

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 31889

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 01/10/2019 08:55:02	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/14/2019 07:00:39	<b>METER 1 - M:</b> 41246 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/14/2019 07:00:41	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-018	INSPECT DOOR MECHANISM	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **36.25**      **0.00**      **0.00**      **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-018	INSPECT DOOR MECHANISM	11268671	01/10/2019 10:33:30	01/10/2019 11:03:30	0.50	\$36.25
					<b>LABOR</b>	<b>36.25</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 31889

---

**Work Order Notes**

(LISAPATE) Back doors will not open

---

**Job Notes**

**06-02-018 - INSPECT DOOR MECHANISM**

(LISAPATE) Checked back doors found no issues. customer said doors were opening just wanted us to check and make sure

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 32012

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	01/24/2019 09:52:35	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	01/29/2019 06:37:48	<b>METER 1 - M:</b>	41896	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	01/29/2019 06:37:49	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$58.28	\$22.62	\$0.00	\$80.90

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.80**      **58.28**      **22.62**      **0.00**      **80.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/25/2019 06:34:26	01/25/2019 07:22:40	0.80	\$58.28
					<b>LABOR</b>	<b>58.28</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	3.30	6	\$19.80
					<b>PARTS</b>	<b>22.62</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 32012

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Visit Reason Changed On 1/24/2019 9:52 AM By LISAPATE

(LISAPATE) PM by AG

Coolant -35'

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 32696

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	04/22/2019 09:38:05	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	04/25/2019 12:32:58	<b>METER 1 - M:</b>	45721	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	PREVENTIVE MAINT	<b>CLOSED DATE:</b>	04/25/2019 12:33:00	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.22	\$88.77	\$27.58	\$0.00	\$116.35

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **1.22**      **88.77**      **27.58**      **0.00**      **116.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/22/2019 11:03:36	04/22/2019 11:46:27	0.71	\$51.78
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2019 11:10:29	04/22/2019 11:41:06	0.51	\$37.00
					<b>LABOR</b>	<b>88.78</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	3.08	6	\$18.45
					<b>PARTS</b>	<b>27.58</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 32696

---

**Work Order Notes**

(IFALLS) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by AG/SH  
Coolant -27'

---



# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 32841

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	05/07/2019 14:24:43	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	05/14/2019 13:43:59	<b>METER 1 - M:</b>	45728	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	05/14/2019 13:44:00	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	0.23	\$16.47	\$30.61	\$0.00	\$47.08
06-02-055	INSPECT DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.73**      **52.72**      **30.61**      **0.00**      **83.33**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-055	INSPECT DOOR LATCH/STRIKER	11074414	05/10/2019 08:09:39	05/10/2019 08:39:39	0.50	\$36.25
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11074414	05/10/2019 07:56:01	05/10/2019 08:09:39	0.23	\$16.47
					<b>LABOR</b>	<b>52.72</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	DOR77498	DOOR HANDLE	30.61	1	\$30.61
					<b>PARTS</b>	<b>30.61</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 32841

---

## Work Order Notes

(LISAPATE) Side door left door will not open-Piece is broken off of a/c laying in cup holder

---

## Job Notes

### **03-02-023 - REPLACE NEW HANDLES - INNER & OUTER**

(LISAPATE) Removed and installed left hand right side barn door handle. Rechecked ok  
Found a piece of the floor vent off, reinstalled and clipped back in place.

### **06-02-055 - INSPECT DOOR LATCH/STRIKER**

(LISAPATE) Door handle appears to be stretched and 1 clip is broke holding the upper latch rod.

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 33363

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	07/09/2019 10:28:02	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	07/11/2019 07:00:49	<b>METER 1 - M:</b>	50434	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	07/11/2019 07:00:51	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$20.91	\$0.00	\$43.39

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **22.48**      **20.91**      **0.00**      **43.39**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/10/2019 06:00:00	07/10/2019 06:18:36	0.31	\$22.48
					<b>LABOR</b>	<b>22.48</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	3.02	6	\$18.09
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
					<b>PARTS</b>	<b>20.91</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 33363

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by RC/SH  
Coolant -35'

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 33425

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	07/12/2019 11:54:43	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	07/17/2019 14:40:18	<b>METER 1 - M:</b>	50438	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	UNSCHEDULED	<b>CLOSED DATE:</b>	07/17/2019 14:40:20	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-057	REPLACE NEW DOOR HANDLE EXTERI	DON	O	N	GARAGE	0.70	\$50.75	\$30.62	\$0.00	\$81.37
06-02-055	INSPECT DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.20**      **87.00**      **30.62**      **0.00**      **117.62**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-055	INSPECT DOOR LATCH/STRIKER	11074414	07/16/2019 06:00:00	07/16/2019 06:30:00	0.50	\$36.25
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	11074414	07/16/2019 06:30:00	07/16/2019 07:12:00	0.70	\$50.75
					<b>LABOR</b>	<b>87.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	DOR77498	DOOR HANDLE	30.62	1	\$30.62
					<b>PARTS</b>	<b>30.62</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 33425

---

**Work Order Notes**

(LISAPATE) Side doors will not open

---

**Job Notes**

**03-02-057 - REPLACE NEW DOOR HANDLE EXTERIOR**

(EKIMBREL) SH removed and replaced side rear door handle.

**06-02-055 - INSPECT DOOR LATCH/STRIKER**

(EKIMBREL) Side rear door handle broken.

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 34810

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 11/11/2019 11:54:36	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/15/2019 10:35:24	<b>METER 1 - M:</b> 54839 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/15/2019 10:35:25	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.79	\$57.58	\$0.00	\$0.00	\$57.58
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-16-031	RECALL SUSPENSION SHACKLE BOLT	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$50.15	\$20.82	\$0.00	\$70.97

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.49</b>	<b>107.73</b>	<b>20.82</b>	<b>0.00</b>	<b>128.55</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
17-02-074	RECALL WINDOW SWITCH	11074891	CTCS400122		\$0.00	
					<b>COMML</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	10208562	11/12/2019 10:37:23	11/12/2019 11:25:02	0.79	\$57.58
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/12/2019 08:37:21	11/12/2019 09:18:51	0.69	\$50.15
					<b>LABOR</b>	<b>107.73</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	3.00	6	\$18.00
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
					<b>PARTS</b>	<b>20.82</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 34810

---

## Work Order Notes

(LISAPATE) PM

(LISAPATE) Take to Tuscaloosa Chevrolet for Recall 18155 Power window switches

---

## Job Notes

### **16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) Taken to TC by RC

### **17-02-074 - RECALL WINDOW SWITCH**

(LISAPATE) Tuscaloosa Chevrolet completed Recall 18155 replaced driver window switch

### **17-16-031 - RECALL SUSPENSION SHACKLE BOLT**

(LISAPATE) Tuscaloosa Chevrolet completed recall 31170 Replaced left rear leaf spring shackle bolt to correct possible heater pipe contact

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW/SH

Coolant -10'

---



# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500 WORK ORDER NO: 35393

USING DEPT NO:	601701	OPENED DATE:	01/14/2020 10:21:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/21/2020 13:02:36	METER 1 - M:	56649	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/21/2020 13:02:38	IN-SERVICE DATE:	07/10/2015	
TECH SPEC NO:	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		UNIT SERIAL NO:	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	0.39	\$28.54	\$30.35	\$0.00	\$58.89

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.39 28.54 30.35 0.00 58.89**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11074414	01/15/2020 11:27:11	01/15/2020 11:43:22	0.27	\$19.55
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11074414	01/15/2020 08:52:34	01/15/2020 09:00:00	0.12	\$8.98
					<b>LABOR</b>	<b>28.53</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	DOR77498	DOOR HANDLE	30.35	1	\$30.35
					<b>PARTS</b>	<b>30.35</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 35393

---

## Work Order Notes

(LISAPATE) Side doors-left inside door handle is broken

---

## Job Notes

**03-02-023 - REPLACE NEW HANDLES - INNER & OUTER**

(LISAPATE) Removed and replaced door handle rechecked ok

---

# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500 WORK ORDER NO: 35575

USING DEPT NO:	601701	OPENED DATE:	02/04/2020 13:46:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2020 13:45:30	METER 1 - M:	57222	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/06/2020 13:45:30	IN-SERVICE DATE:	07/10/2015	
TECH SPEC NO:	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		UNIT SERIAL NO:	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.28	\$19.98	\$0.00	\$0.00	\$19.98

JOB COUNT: 1 WORK ORDER TOTAL: 0.28 19.98 0.00 0.00 19.98

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	02/04/2020 14:27:28	02/04/2020 14:44:00	0.28	\$19.98
					<b>LABOR</b>	<b>19.98</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 35575

---

**Work Order Notes**

(LISAPATE) Low tire light on

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(LISAPATE) Found LF tire was 10 pounds lowed. Aired to spec and sprayed to check for leaks. Found not signs of leaks or punctures.

---

# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500 WORK ORDER NO: 35672

USING DEPT NO:	601701	OPENED DATE:	02/17/2020 07:52:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2020 08:14:08	METER 1 - M:	57756	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2020 08:14:09	IN-SERVICE DATE:	07/10/2015	
TECH SPEC NO:	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		UNIT SERIAL NO:	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	0.41	\$29.66	\$10.62	\$0.00	\$40.28

JOB COUNT: 1 WORK ORDER TOTAL: 0.41 29.66 10.62 0.00 40.28

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	11915538	02/17/2020 08:00:30	02/17/2020 08:25:03	0.41	\$29.66
					<b>LABOR</b>	<b>29.66</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	10.62	1	\$10.62
					<b>PARTS</b>	<b>10.62</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 35672

---

## Work Order Notes

(EKIMBREL) Passenger headlight out

---

## Job Notes

**03-34-001 - REPLACE NEW HEADLAMPS**

(EKIMBREL) RC replaced passenger headlight.

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 35757

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	02/24/2020 14:38:39	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	02/27/2020 08:02:13	<b>METER 1 - M:</b>	58442	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	UNSCHEDULED	<b>CLOSED DATE:</b>	02/27/2020 08:02:15	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$73.79	\$48.24	\$0.00	\$122.03

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **1.02**      **73.79**      **48.24**      **0.00**      **122.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/25/2020 10:08:03	02/25/2020 10:20:37	0.21	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2020 10:07:47	02/25/2020 10:28:02	0.34	\$24.47
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2020 09:51:03	02/25/2020 10:19:18	0.47	\$34.14
					<b>LABOR</b>	<b>73.79</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	5.84	6	\$35.01
66-PM-PMA	PERFORM OIL CHANGE	46573	FILTER-AIR	10.41	1	\$10.41
					<b>PARTS</b>	<b>48.24</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 35757

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW,SH/AG

Coolant -34'

Replaced air filter

---



# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 35844

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 03/02/2020 13:58:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/06/2020 06:47:44	<b>METER 1 - M:</b> 58614 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 03/06/2020 06:47:45	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.29	\$20.82	\$0.00	\$0.00	\$20.82
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.74	\$53.61	\$0.00	\$0.00	\$53.61

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.03**      **74.43**      **0.00**      **0.00**      **74.43**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11310047	03/03/2020 07:22:29	03/03/2020 07:39:43	0.29	\$20.82
09-15	ALIGN STEERING	11310047	03/03/2020 07:39:43	03/03/2020 08:24:05	0.74	\$53.61
					<b>LABOR</b>	<b>74.43</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 35844

---

**Work Order Notes**

(LISAPATE) Customer complained out of alignment-per fleet check front end and align if needed

---

**Job Notes**

**06-15 - INSPECT STEERING**

(LISAPATE) Vehicle drove good before alignment, but vehicle was out of spec

**09-15 - ALIGN STEERING**

(LISAPATE) EH Performed road test before alignment. Performed alignment . Performed road test after alignment, all good

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 36928

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	06/23/2020 11:23:14	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	06/24/2020 09:24:57	<b>METER 1 - M:</b>	58788	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	06/24/2020 09:24:58	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$36.25	\$123.71	\$0.00	\$159.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$18.13	\$0.00	\$0.00	\$18.13

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.75**      **54.38**      **123.71**      **0.00**      **178.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10208562	06/24/2020 07:00:00	06/24/2020 07:15:00	0.25	\$18.13
03-32-002	REPLACE NEW BATTERY	11915538	06/24/2020 07:00:00	06/24/2020 07:30:00	0.50	\$36.25
					<b>LABOR</b>	<b>54.38</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	781	BATTERY BCI 78 770 CCA	123.71	1	\$123.71
					<b>PARTS</b>	<b>123.71</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 36928

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Battery failed, Installed a new battery. Rechecked good

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Did not change oil at this time. Checked fluids battery and tires pressures. Updated sticker  
Coolant -35'

---

# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500 WORK ORDER NO: 38171

USING DEPT NO:	601701	OPENED DATE:	10/27/2020 14:26:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/28/2020 12:13:24	METER 1 - M:	60117	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/28/2020 16:00:54	IN-SERVICE DATE:	07/10/2015	
TECH SPEC NO:	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		UNIT SERIAL NO:	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PR-51-046	PROGRAM KEY BLANK(S)	DON	O	N	GARAGE	0.03	\$3.34	\$60.39	\$0.00	\$63.73

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.03 3.34 60.39 0.00 63.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-51-046	PROGRAM KEY BLANK(S)	11170580	10/28/2020 08:07:25	10/28/2020 08:09:07	0.03	\$3.34
					<b>LABOR</b>	<b>3.34</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-51-046	PROGRAM KEY BLANK(S)	23300332	TRANSPONDER KEY LASER PRECUT	60.39	1	\$60.39
					<b>PARTS</b>	<b>60.39</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 38171

---

**Work Order Notes**

(LISAPATE) Purchased a master key needs to be programmed to vehicle

---

**Job Notes**

**PR-51-046 - PROGRAM KEY BLANK(S)**

(ABLACK) AB programmed 1 new key. Did not use scan tool.

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 38320

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	11/09/2020 09:35:22	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	11/16/2020 11:13:00	<b>METER 1 - M:</b>	60873	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	11/16/2020 13:27:59	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$287.50	\$287.50
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	0.11	\$12.85	\$10.62	\$0.00	\$23.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.43	\$20.64	\$0.00	\$66.07

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>					<b>0.49</b>	<b>58.28</b>	<b>31.26</b>	<b>287.50</b>	<b>377.04</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
03-02-061	REPLACE NEW WINDSHIELD	11078716	282167		\$287.50	
					<b>COMML</b>	<b>287.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	11170580	11/10/2020 07:33:26	11/10/2020 07:39:58	0.11	\$12.85
66-PM-PMA	PERFORM OIL CHANGE	11170580	11/10/2020 07:10:07	11/10/2020 07:33:13	0.39	\$45.43
					<b>LABOR</b>	<b>58.28</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	10.62	1	\$10.62
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.97	6	\$17.82
					<b>PARTS</b>	<b>31.26</b>

# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500

WORK ORDER NO: 38320

---

## Work Order Notes

(LISAPATE) PM-Left headlight is out

---

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(LISAPATE) Glass Dr came to the shop and installed a new windshield due to glass had too many dings to repair. PD by CC

### **03-34-001 - REPLACE NEW HEADLAMPS**

(ABLACK) AB installed new drivers side headlight. Rechecked ok

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) AB did top AG did bottom  
60873 mi

---



# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 39631

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	04/12/2021 07:58:56	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	04/14/2021 10:32:26	<b>METER 1 - M:</b>	62501	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	04/14/2021 14:07:56	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.03	\$3.61	\$17.67	\$0.00	\$21.28
06-02-053	INSPECT WINDOW REGULATOR	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.27	\$31.30	\$0.00	\$0.00	\$31.30
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.13	\$14.82	\$10.53	\$0.00	\$25.35
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.32	\$37.66	\$0.00	\$0.00	\$37.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.87	\$102.27	\$28.42	\$0.00	\$130.69

**JOB COUNT: 6**      **WORK ORDER TOTAL:**      **1.71**      **201.46**      **56.62**      **0.00**      **258.08**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	04/13/2021 09:20:33	04/13/2021 09:20:33	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	11074414	04/13/2021 09:30:00	04/13/2021 09:37:32	0.13	\$14.82
06-02-053	INSPECT WINDOW REGULATOR	11310047	04/13/2021 09:46:08	04/13/2021 09:46:25	0.00	\$0.56
06-02-053	INSPECT WINDOW REGULATOR	11310047	04/13/2021 09:46:08	04/13/2021 09:46:25	0.00	(\$0.56)
06-02-053	INSPECT WINDOW REGULATOR	11310047	04/13/2021 09:46:08	04/13/2021 09:52:08	0.10	\$11.80
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/13/2021 08:28:18	04/13/2021 08:47:27	0.32	\$37.66
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	04/13/2021 08:12:09	04/13/2021 08:28:04	0.27	\$31.30
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/13/2021 08:10:02	04/13/2021 08:11:52	0.03	\$3.61
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/13/2021 07:17:47	04/13/2021 08:09:47	0.87	\$102.27

**LABOR**      **201.46**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	4.22	1	\$4.22
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	2.94	6	\$17.64
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	8.84	2	\$17.67
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.84	1	\$3.84

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	5.73	1	\$5.73
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	2	\$0.96
					<b>PARTS</b>	<b>56.62</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 39631

---

## Work Order Notes

(LISAPATE) PM-LR tire is low-Passenger window is slow going up

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers due to normal wear. SH

### **06-02-053 - INSPECT WINDOW REGULATOR**

(EHOWELL) Operated passenger window up and down multiple times. It's operating as designed. EH

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

(SHARBIN) Found a screw in the left rear tire. SH

### **66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Patched left rear tire. SH

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires inspected brakes adjusted tire pressures and relearned tire positions. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 63106. SH/JW Performed PM.

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 40403

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 07/12/2021 07:45:42	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/14/2021 09:59:57	<b>METER 1 - M:</b> 65686 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/28/2021 07:43:34	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.45	\$171.36	\$0.00	\$0.00	\$171.36

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **1.45**      **171.36**      **0.00**      **0.00**      **171.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11213180	07/12/2021 08:00:43	07/12/2021 08:45:04	0.74	\$87.22
66-79-002	PERFORM SERVICE CALL	11170580	07/12/2021 08:00:44	07/12/2021 08:43:31	0.71	\$84.14
					<b>LABOR</b>	<b>171.36</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.50	4	\$13.98
66-79-002	PERFORM SERVICE CALL	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.50	(4)	(\$13.98)
					<b>PARTS</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 40403

---

## Work Order Notes

(LISAPATE) Per Mario when cranking van. Oil pressure keeps dropping says on display to cut vehicle off. Unit is parked in Fleet lot

---

## Job Notes

### **66-79-002 - PERFORM SERVICE CALL**

(ABLACK) AB and MS performed service call and found the oil filter was left loose. Added oil to vehicle before we drove it back to the shop. Inspected oil filter and was ok. Tightened oil filter and topped oil off.

(MSIDES) Performed service call and found vehicle low on oil topped off oil and drove back to shop, once on the lift found the oil filter to be loose and leaking oil. Removed oil filter and cleaned sealing surface and reinstalled letting vehicle run and will recheck later. MS/AB

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 40841

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 08/25/2021 11:23:42	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/27/2021 08:13:36	<b>METER 1 - M:</b> 66672 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/27/2021 14:30:25	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$8.92	\$15.18	\$0.00	\$24.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$38.32	\$25.52	\$0.00	\$63.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.40**      **47.24**      **40.70**      **2.00**      **89.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2021 13:19:10	08/25/2021 13:38:39	0.32	\$38.32
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/25/2021 13:38:52	08/25/2021 13:43:24	0.08	\$8.92
<b>LABOR</b>					<b>47.24</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.54	6	\$21.24
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	4.28	1	\$4.28
<b>PARTS</b>					<b>40.70</b>	

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 40841

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 66672. SH/JW Performed PM.

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 41196

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 10/04/2021 14:48:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/05/2021 07:41:10	<b>METER 1 - M:</b> 67262 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/05/2021 08:10:49	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.10	\$11.80	\$0.75	\$0.00	\$12.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.26	\$1.26

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.10**      **11.80**      **0.75**      **1.26**      **13.81**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$1.26
<b>COMML</b>					<b>1.26</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11915538	10/05/2021 07:00:00	10/05/2021 07:06:00	0.10	\$11.80
<b>LABOR</b>					<b>11.80</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.75	1	\$0.75
<b>PARTS</b>					<b>0.75</b>	



# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 41196

---

## Work Order Notes

(EKIMBREL) replaced brake light bulb

---

## Job Notes

**03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC**

(EKIMBREL) IF replaced bulb

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 42153

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 01/24/2022 09:59:15	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/27/2022 10:50:03	<b>METER 1 - M:</b> 70563 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/28/2022 07:24:54	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$2.95	\$15.18	\$0.00	\$18.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.03	\$31.94	\$0.00	\$39.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.09**      **10.98**      **47.12**      **2.00**      **60.10**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/25/2022 15:23:33	01/25/2022 15:25:03	0.03	\$2.95
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/25/2022 15:19:17	01/25/2022 15:23:22	0.07	\$8.03
<b>LABOR</b>					<b>10.98</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	9.17	1	\$9.17
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.80	6	\$22.77
<b>PARTS</b>					<b>47.12</b>	

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 42153

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34JAW,CW/SH  
MILEAGE-70563

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 42942

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 04/18/2022 07:35:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/19/2022 11:09:45	<b>METER 1 - M:</b> 74071 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/20/2022 08:45:10	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.39	\$15.18	\$0.00	\$21.57
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.78	\$92.01	\$10.65	\$0.00	\$102.66
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.35	\$53.17	\$0.00	\$83.52
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>1.59</b>	<b>187.75</b>	<b>79.00</b>	<b>2.00</b>	<b>268.75</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/18/2022 14:30:00	04/18/2022 14:45:26	0.26	\$30.35
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/18/2022 14:22:24	04/18/2022 14:22:24	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	11074414	04/18/2022 11:00:45	04/18/2022 11:15:53	0.25	\$29.76
66-17-030	PERFORM TIRE PATCH	11074414	04/18/2022 10:11:10	04/18/2022 10:14:53	0.06	\$7.31
66-17-030	PERFORM TIRE PATCH	11074414	04/18/2022 13:06:51	04/18/2022 13:34:47	0.47	\$54.94
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/18/2022 14:45:38	04/18/2022 14:48:53	0.05	\$6.39
66-79-002	PERFORM SERVICE CALL	11074414	04/19/2022 07:00:00	04/19/2022 07:30:00	0.50	\$59.00
					<b>LABOR</b>	<b>187.75</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.60	6	\$21.60
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.98	1	\$7.98
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	10.44	1	\$10.44
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.98	(1)	(\$7.98)

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	5.73	1	\$5.73
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.82	1	\$3.82
66-17-030	PERFORM TIRE PATCH	58107	WHEEL WEIGHT PFE 2.00	0.84	1	\$0.84
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-PM-PMA	PERFORM OIL CHANGE	BALRS4131	BALDWIN AIR FILTER	14.57	1	\$14.57
<b>PARTS</b>						<b>79.00</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 42942

---

## Work Order Notes

(LISAPATE) Per Donald car has a flat tire in the Fleet lot  
(LISAPATE) PM-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Patched right rear tire. SH

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) Service call completed

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/AMG Performed PM.

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 44908

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	10/07/2022 07:03:18	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	10/10/2022 14:44:53	<b>METER 1 - M:</b>	77223	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	10/11/2022 07:16:06	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.39	\$26.63	\$0.00	\$47.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.17**      **20.39**      **26.63**      **5.00**      **52.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/07/2022 10:24:23	10/07/2022 10:34:45	0.17	\$20.39
<b>LABOR</b>					<b>20.39</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	5.30	1	\$5.30
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.56	6	\$21.33
<b>PARTS</b>					<b>26.63</b>	

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 44908

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH  
MILEAGE-77223

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 46202

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 02/20/2023 12:01:22	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/23/2023 11:35:24	<b>METER 1 - M:</b> 79482 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/24/2023 07:34:24	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.60	\$71.03	\$0.00	\$0.00	\$71.03
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.71	\$83.19	\$0.00	\$0.00	\$83.19
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.08	\$9.34	\$525.81	\$0.00	\$535.15
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.54	\$64.11	\$0.00	\$0.00	\$64.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.22	\$26.99	\$0.00	\$69.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 7**      **WORK ORDER TOTAL:**      **2.39**      **281.69**      **552.80**      **5.00**      **839.49**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/21/2023 13:36:26	02/21/2023 13:41:11	0.08	\$9.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/21/2023 13:36:26	02/21/2023 13:41:11	0.08	\$9.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/21/2023 13:36:26	02/21/2023 13:41:11	(0.08)	(\$9.34)
06-15	INSPECT STEERING	12052187	02/21/2023 13:00:00	02/21/2023 13:36:07	0.60	\$71.03
06-15	INSPECT STEERING	12052187	02/21/2023 12:27:16	02/21/2023 12:27:16	0.00	\$0.00
06-15	INSPECT STEERING	12052187	02/21/2023 13:00:00	02/21/2023 13:36:07	0.60	\$71.03
06-15	INSPECT STEERING	12052187	02/21/2023 12:27:16	02/21/2023 12:27:16	0.00	\$0.00
06-15	INSPECT STEERING	12052187	02/21/2023 13:00:00	02/21/2023 13:36:07	(0.60)	(\$71.03)
06-15	INSPECT STEERING	12052187	02/21/2023 12:27:16	02/21/2023 12:27:16	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	12052187	02/20/2023 13:01:26	02/20/2023 13:34:02	0.54	\$64.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/21/2023 13:41:22	02/21/2023 14:02:50	0.36	\$42.22

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	02/21/2023 15:02:38	02/21/2023 15:44:56	(0.71)	(\$83.19)
66-17-013	PERFORM ALIGNMENT	11310047	02/21/2023 15:02:38	02/21/2023 15:44:56	0.71	\$83.19
66-17-013	PERFORM ALIGNMENT	11310047	02/21/2023 15:02:38	02/21/2023 15:44:56	0.71	\$83.19
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	02/23/2023 07:00:00	02/23/2023 07:06:00	(0.10)	(\$11.80)
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	02/23/2023 07:00:00	02/23/2023 07:06:00	0.10	\$11.80
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	02/23/2023 07:00:00	02/23/2023 07:06:00	0.10	\$11.80
					<b>LABOR</b>	<b>281.69</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.57	6	\$21.42
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	5.57	1	\$5.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.16	2	\$4.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	2	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	94262	TIRE 245/75R16 MICH DEF LTX	260.01	2	\$520.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	(2)	(\$0.90)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	(1)	(\$0.57)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.16	(2)	(\$4.32)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	94262	TIRE 245/75R16 MICH DEF LTX	260.01	(2)	(\$520.02)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	2	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.16	2	\$4.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	94262	TIRE 245/75R16 MICH DEF LTX	260.01	2	\$520.02
					<b>PARTS</b>	<b>552.80</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 46202

## Work Order Notes

(EHANNAH) preform service call for flat tire- nail in tire

## Job Notes

### **06-15 - INSPECT STEERING**

(JWRIGHT) Steering good. Brakes at 10mm. JAW  
(AJONES) Visit Reason Changed On 2/28/2023 10:40 AM By AJONES

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

(LISAPATE) needs 2 new tires  
(AJONES) Visit Reason Changed On 2/28/2023 10:40 AM By AJONES

### **24-17 - REPAIR TIRES, TUBES, LINERS & VALVES**

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Set front toe. EH  
(AJONES) Visit Reason Changed On 2/28/2023 10:41 AM By AJONES

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced both front tires. LF was no good due to bolt at side of tread and RF was at 3/32. Balanced both and torqued lug nuts to spec. JAW  
(AJONES) Visit Reason Changed On 2/28/2023 10:41 AM By AJONES

### **66-79-002 - PERFORM SERVICE CALL**

(JWRIGHT) Performed service call. Aired tire and brought unit to shop. Will need both front tires replaced. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. GC/JAW  
MILEAGE-79482

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 47015

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	05/11/2023 09:31:48	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	05/12/2023 14:20:11	<b>METER 1 - M:</b>	79482	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	05/12/2023 15:19:57	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.54	\$63.65	\$265.26	\$0.00	\$328.91
66-17-030	PERFORM TIRE PATCH	DON	U	N	GARAGE	0.43	\$50.84	\$0.00	\$0.00	\$50.84
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.03	\$3.08	\$0.00	\$0.00	\$3.08
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **1.00**      **117.57**      **265.26**      **5.00**      **387.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/12/2023 08:38:31	05/12/2023 09:10:53	0.54	\$63.65
66-79-002	PERFORM SERVICE CALL	11399745	05/11/2023 10:44:32	05/11/2023 10:46:06	0.03	\$3.08
66-79-002	PERFORM SERVICE CALL	11399745	05/11/2023 10:44:32	05/11/2023 10:46:06	(0.03)	(\$3.08)
66-79-002	PERFORM SERVICE CALL	11399745	05/11/2023 10:44:32	05/11/2023 10:46:06	0.03	\$3.08
66-17-030	PERFORM TIRE PATCH	12201267	05/11/2023 10:43:55	05/11/2023 11:09:46	(0.43)	(\$50.84)
66-17-030	PERFORM TIRE PATCH	12201267	05/11/2023 10:43:55	05/11/2023 11:09:46	0.43	\$50.84
66-17-030	PERFORM TIRE PATCH	12201267	05/11/2023 10:43:55	05/11/2023 11:09:46	0.43	\$50.84
66-17-030	PERFORM TIRE PATCH	12201267	05/11/2023 12:14:43	05/11/2023 12:14:43	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	12201267	05/11/2023 12:14:43	05/11/2023 12:14:43	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	12201267	05/11/2023 12:14:43	05/11/2023 12:14:43	0.00	\$0.00
<b>LABOR</b>					<b>117.57</b>	

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.50	1	\$3.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.74	1	\$0.74
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	94262	TIRE 245/75R16 MICH DEF LTX	260.01	1	\$260.01
					<b>PARTS</b>	<b>265.26</b>

# Work Order Charge Detail

UNIT NO: 241434 2015 CHEVROLET EXPRESS 2500

WORK ORDER NO: 47015

---

## Work Order Notes

(EHANNAH) repair RR tire- service call for flat tire

---

## Job Notes

**24-17 - REPAIR TIRES, TUBES, LINERS & VALVES**

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GRCOOK) Mounted and Balanced one new tire, van had flat tired to patch and couldn't. Pulled spare off they put on and installed new tire and put spare back under van.-GC

**66-17-030 - PERFORM TIRE PATCH**

(GRCOOK) Tried to patch tire that had a spot that looked like they ran over something that made what looked like a small hole in tread. Did patch job and put tire back on and found tire was still leaking and it looked like something had cut into the tread and not a hole. Going to have to order one new tire. -GC

(AJONES) Visit Reason Changed On 5/30/2023 2:06 PM By AJONES

**66-79-002 - PERFORM SERVICE CALL**

(GARAGE) Tire was low. We put air in the RR and brought vehicle back to the shop. CW/RC

(AJONES) Visit Reason Changed On 5/30/2023 2:06 PM By AJONES

**CH-SP - CHARGE Shop Supplies**

(AJONES) Visit Reason Changed On 5/30/2023 2:06 PM By AJONES

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 47903

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 08/15/2023 08:10:04	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/23/2023 11:40:31	<b>METER 1 - M:</b> 81597 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/23/2023 13:40:29	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.13	\$14.78	\$199.98	\$0.00	\$214.76
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.75	\$21.69	\$0.00	\$26.44
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.79	\$93.71	\$0.00	\$0.00	\$93.71
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.57	\$45.87	\$0.00	\$47.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.40	\$47.33	\$0.00	\$0.00	\$47.33

**JOB COUNT: 6**      **WORK ORDER TOTAL:**      **1.37**      **162.14**      **267.54**      **5.00**      **434.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/16/2023 08:22:24	08/16/2023 08:24:49	0.04	\$4.75
03-32-002	REPLACE NEW BATTERY	11074414	08/16/2023 07:05:30	08/16/2023 07:13:01	0.13	\$14.78
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/15/2023 15:12:02	08/15/2023 15:12:50	0.01	\$1.57
66-79-003	PERFORM SAFETY INSPECTION	11074414	08/15/2023 15:12:50	08/15/2023 15:15:10	0.04	\$4.59
66-79-003	PERFORM SAFETY INSPECTION	11074414	08/16/2023 07:13:01	08/16/2023 07:58:20	0.76	\$89.12
WA-00	WASH COMPLETE VEHICLE	11074414	08/16/2023 07:58:20	08/16/2023 08:22:24	0.40	\$47.33
					<b>LABOR</b> <b>162.14</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	6.71	6	\$40.23
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	5.64	1	\$5.64
03-32-002	REPLACE NEW BATTERY	781	BATTERY BCI 78 770 CCA	199.98	1	\$199.98
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					<b>PARTS</b> <b>267.54</b>	

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 47903

---

## Work Order Notes

(EHANNAH) pm- do SI- wash

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(GARAGE) Battery tested bad. Replaced the battery ALT charging at 14.5 volts. SH

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced the wipers. SH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) Performed a safety inspection. Found no issues at this time. Front and rear brake pads measure 8MM. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed the vehicle. SH

---



# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 48390

<b>USING DEPT NO:</b> 601701	<b>OPENED DATE:</b> 10/03/2023 11:15:08	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/04/2023 15:31:07	<b>METER 1 - M:</b> 82498 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/05/2023 07:24:47	<b>IN-SERVICE DATE:</b> 07/10/2015
<b>TECH SPEC NO:</b> 15CHEVEXPRS25      2015 CHEVROLET EXPRESS 2500	<b>UNIT SERIAL NO:</b> 1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-057	REPAIR DOOR HANDLE EXTERIOR	DON	N	N	GARAGE	0.31	\$36.12	\$42.38	\$0.00	\$78.50
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.31**      **36.12**      **42.38**      **5.00**      **83.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-057	REPAIR DOOR HANDLE EXTERIOR	11074414	10/04/2023 10:20:40	10/04/2023 10:39:02	0.31	\$36.12
					<b>LABOR</b>	<b>36.12</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-057	REPAIR DOOR HANDLE EXTERIOR	DOR77498	DOOR HANDLE	42.38	1	\$42.38
					<b>PARTS</b>	<b>42.38</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 48390

---

**Work Order Notes**

(LRUSHING) DOOR HANDLE ON PASSENGER SIDE IS NOT WORKING

---

**Job Notes**

**24-02-057 - REPAIR DOOR HANDLE EXTERIOR**

(SHARBIN) Replaced the door handle on the right side left hand double door. Rechecks good. SH .50 labor for inspect and install

**CH-SP - CHARGE Shop Supplies**

(LRUSHING) Visit Reason Changed On 10/18/2023 2:56 PM By LRUSHING

---

# Work Order Charge Detail

**UNIT NO:** 241434      **2015 CHEVROLET EXPRESS 2500**      **WORK ORDER NO:** 48846

<b>USING DEPT NO:</b>	601701	<b>OPENED DATE:</b>	11/06/2023 10:41:32	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	11/10/2023 11:22:10	<b>METER 1 - M:</b>	83019	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	11/10/2023 13:04:58	<b>IN-SERVICE DATE:</b>	07/10/2015	
<b>TECH SPEC NO:</b>	15CHEVEXPRS25	2015 CHEVROLET EXPRESS 2500		<b>UNIT SERIAL NO:</b>	1GAWGPF8F1247541	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$4.36	\$4.36
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.04	\$4.36	\$0.00	\$0.00	\$4.36

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.04**      **4.36**      **0.00**      **4.36**      **8.72**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$4.36
					<b>COMML</b> <b>4.36</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	11/09/2023 15:33:19	11/09/2023 15:35:32	0.04	\$4.36
					<b>LABOR</b>	<b>4.36</b>

# Work Order Charge Detail

**UNIT NO:** 241434 2015 CHEVROLET EXPRESS 2500

**WORK ORDER NO:** 48846

---

**Work Order Notes**

(LRUSHING) Prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) removed wordmarks and tag\RC

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Mon Nov 20 2023 14:54:40 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '241434') //Q=