

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 19892

USING DEPT NO: 504241	OPENED DATE: 03/30/2015 08:56:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/03/2015 11:51:41	METER 1 - M: 10 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2015 11:51:42	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35 2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10260422	03/30/2015 08:56:46	03/30/2015 09:26:46	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 19892

Work Order Notes

(LPATE) PDI NEW UNIT

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 20286

USING DEPT NO: 504241	OPENED DATE: 05/18/2015 15:01:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/25/2015 11:19:47	METER 1 - M: 10 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/25/2015 11:19:49	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-35-019	INSTALL POWER INVERTER	DON	O	N	GARAGE	2.00	\$115.00	\$89.99	\$0.00	\$204.99
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVII	DON	O	N	GARAGE	7.14	\$410.39	\$1,786.50	\$0.00	\$2,196.89

JOB COUNT: 2 **WORK ORDER TOTAL:** **9.14** **525.39** **1,876.49** **0.00** **2,401.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-025	INSTALL LADDER RACK/ASSY	11074414	06/01/2015 13:06:28	06/01/2015 13:21:59	0.26	\$14.87
14-78-025	INSTALL LADDER RACK/ASSY	11074414	06/01/2015 13:06:28	06/01/2015 13:21:59	(0.26)	(\$14.87)
14-35-019	INSTALL POWER INVERTER	11213180	06/24/2015 07:00:00	06/24/2015 09:00:00	2.00	\$115.00
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	11074414	05/19/2015 06:49:08	05/19/2015 13:57:22	7.14	\$410.39
					LABOR	525.39

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	S1M2HC2FSV	METAL PARTITION	347.00	1	\$347.00
14-35-019	INSTALL POWER INVERTER	MMM06480	FASTENERS	5.85	15	\$87.75
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	AD44FP	ADRIAN SHELF UNIT	268.00	2	\$536.00
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	19	ADRIAN 2" DEEP DRAWER	160.00	1	\$160.00
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	9	SHALLOW 4 DRAWER UNIT	247.00	1	\$247.00
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	WKC1FSVG	SOLID WING KIT GM	168.00	1	\$168.00
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	DST21	DOOR STORAGE TRAY	42.50	1	\$42.50
14-78-026	INSTALL METAL CAB DIVIDERS/SHELVING	RKFSVLWB	RAIL KIT	286.00	1	\$286.00
14-35-019	INSTALL POWER INVERTER	CONNECTOR	CONNECTOR-NYLON	0.56	4	\$2.24
					PARTS	1876.49

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 20286

Work Order Notes

(LPATE) INSTALL SHELF AND DIVIDER-INSTALL INVERTOR

Job Notes

14-35-019 - INSTALL POWER INVERTER

(RWINTERS) MOUNTED INVERTOR ON END OF SHELF. INSTALLED CONTINUOUS SOLENOID FOR POWER INVERTOR AND INSTALLED EXTRA GROUND (USED WIRE FROM NON-INVENTORY)

14-78-025 - INSTALL LADDER RACK/ASSY

(LPATE) CANCELLED NO LADDER RACK

14-78-026 - INSTALL METAL CAB DIVIDERS/SHELVING

(LPATE) ASSEMBLED AND INSTALLED 2 SHELVES AND COMPONENTS AND DIVIDER. INSTALLED BAR IN REAR OF VAN TO HANG EQUIPMENT ON ALSO PUT PLASTIC SHEETS ON WALL BEHIND BAR TO CUT DOWN ON NOISE

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 21310

USING DEPT NO: 504241	OPENED DATE: 09/03/2015 14:33:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2015 10:45:57	METER 1 - M: 1092 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/08/2015 10:45:59	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$32.02	\$17.22	\$0.00	\$49.24

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.56** **32.02** **17.22** **0.00** **49.24**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/04/2015 07:15:28	09/04/2015 07:48:53	0.56	\$32.02
					LABOR	32.02

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.08	192	\$15.36
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.86	1	\$1.86
					PARTS	17.22

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 21310

Work Order Notes

(IFALLS) PM / CHECK POWER INVERTER

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) RS PERFORMED PM AND GREG CHECK POWER INVERTER, IT IS OPERATING PROPERLY.

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 21840

USING DEPT NO:	504241	OPENED DATE:	10/28/2015 07:30:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/20/2015 07:08:46	METER 1 - M:	1631	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/20/2015 07:08:47	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-02-060	ADJUST DOOR HINGE(S)	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.45	\$25.89	\$0.00	\$0.00	\$25.89

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.45** **25.89** **0.00** **0.00** **25.89**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	10337093	10/29/2015 08:32:46	10/29/2015 08:59:47	0.45	\$25.89
					LABOR	25.89

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 21840

Work Order Notes

(LISAPATE) TAKE TO BARKLEY ADJUST SIDE AND REAR DOORS OUT OF ADJUSTMENT

Job Notes

01-02-060 - ADJUST DOOR HINGE(S)

(LISAPATE) BARKLEY ADJUSTED REAR DOORS AND REPLACED LATCH. WARRANTY DID NOT PROVIDE INVOICE.

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) TAKEN TO BARKLEY BY AY

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 22465

USING DEPT NO: 504241	OPENED DATE: 02/03/2016 07:36:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/05/2016 09:23:05	METER 1 - M: 2793 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/05/2016 09:23:07	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-55-041	INSTALL LADDER RACK	DON	O	N	GARAGE	1.81	\$104.27	\$19.50	\$0.00	\$123.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$21.72	\$17.24	\$0.00	\$38.96

JOB COUNT: 2 **WORK ORDER TOTAL:** **2.19** **125.99** **36.74** **0.00** **162.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/03/2016 10:37:48	02/03/2016 11:00:28	0.38	\$21.72
14-55-041	INSTALL LADDER RACK	11074414	02/03/2016 11:00:35	02/03/2016 12:00:00	0.99	\$56.94
14-55-041	INSTALL LADDER RACK	11074414	02/03/2016 13:00:00	02/03/2016 13:49:23	0.82	\$47.33
					LABOR	125.99

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.08	192	\$15.36
14-55-041	INSTALL LADDER RACK	DOR BOLT	MISCELLANEOUS HARDWARE	3.25	6	\$19.50
					PARTS	36.74

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 22465

Work Order Notes

(LISAPATE) PM-REINSTALL LADDER RACK

Job Notes

14-55-041 - INSTALL LADDER RACK

(LISAPATE) REASSEMBLED AND REINSTALLED LADDER RACK ASSY

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 2/3/2016 7:37 AM By LISAPATE

(LISAPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 24830

USING DEPT NO: 504241	OPENED DATE: 11/01/2016 15:45:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/03/2016 07:52:13	METER 1 - M: 6414 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/03/2016 07:52:15	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35 2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>		
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75		
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.39	\$0.00	\$41.22		
JOB COUNT: 2						WORK ORDER TOTAL:		0.81	46.58	23.39	0.00	69.97

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11758845	11/02/2016 07:18:36	11/02/2016 07:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11758845	11/02/2016 07:00:00	11/02/2016 07:18:36	0.31	\$17.83
					LABOR	46.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.89	1	\$1.89
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	10W30SSQT	10W30 SEMI SYN QT. BOTTLE	3.23	6	\$19.38
					PARTS	23.39

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 24830

Work Order Notes

(LISAPATE) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500 WORK ORDER NO: 27266

USING DEPT NO:	504241	OPENED DATE:	08/25/2017 13:47:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2017 08:08:21	METER 1 - M:	9099	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2017 08:08:23	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$17.30	\$0.00	\$35.13

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 17.30 0.00 35.13

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/25/2017 13:51:05	08/25/2017 14:09:41	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	2.57	6	\$15.42
					PARTS	17.30

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 27266

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500 WORK ORDER NO: 29122

USING DEPT NO:	504241	OPENED DATE:	03/20/2018 07:35:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/23/2018 08:48:36	METER 1 - M:	10908	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/23/2018 08:48:38	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.49	\$0.00	\$17.74

JOB COUNT: 1 WORK ORDER TOTAL: 0.30 17.25 0.49 0.00 17.74

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11758845	03/20/2018 11:14:24	03/20/2018 11:32:24	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49
					PARTS	0.49

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 29122

Work Order Notes

(LISAPATE) LEFT REAR BLINKER OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) REPLACED LR BLINKER

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 29216

USING DEPT NO: 504241	OPENED DATE: 03/27/2018 15:35:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/03/2018 10:28:35	METER 1 - M: 11308 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2018 10:28:36	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$44.37	\$11.24	\$0.00	\$55.61

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.52** **87.50** **28.30** **0.00** **115.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/28/2018 07:39:14	03/28/2018 08:25:32	0.77	\$44.37
03-51-038	REPLACE NEW WIPER BLADES	11901357	03/28/2018 08:25:36	03/28/2018 08:25:42	0.00	\$0.10
03-51-038	REPLACE NEW WIPER BLADES	11901357	03/28/2018 08:25:36	03/28/2018 08:25:42	0.00	(\$0.10)
03-51-038	REPLACE NEW WIPER BLADES	11901357	03/28/2018 08:25:36	03/28/2018 08:40:36	0.25	\$14.38
06-13	INSPECT BRAKES	11170580	03/29/2018 07:00:00	03/29/2018 07:30:00	0.50	\$28.75
					LABOR	87.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	1.56	6	\$9.36
					PARTS	28.30

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 29216

Work Order Notes

(LISAPATE) PM-CHECK BRAKES ARE SQUEALING AND ROTATE TIRES

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

06-13 - INSPECT BRAKES

(LISAPATE) CHECKED BRAKES ALL GOOD

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
COOLANT -35'

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 31300

USING DEPT NO: 504241	OPENED DATE: 10/26/2018 09:16:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/31/2018 10:24:58	METER 1 - M: 13634 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/31/2018 10:25:00	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.33	\$0.00	\$82.40	\$0.00	\$82.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.41	\$0.00	\$22.08	\$0.00	\$22.08

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.73** **0.00** **104.48** **0.00** **104.48**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/29/2018 06:31:39	10/29/2018 06:59:31	0.46	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/29/2018 06:10:03	10/29/2018 07:00:11	0.84	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	10/29/2018 07:45:27	10/29/2018 08:04:57	0.33	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/29/2018 06:09:49	10/29/2018 06:16:18	0.11	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
03-32-002	REPLACE NEW BATTERY	781	BATTERY BCI 78 770 CCA	82.40	1	\$82.40
66-PM-PMA	PERFORM OIL CHANGE	46573	FILTER-AIR	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.21	6	\$13.26
					PARTS	104.48

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 31300

Work Order Notes

(EKIMBREL) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EKIMBREL) replaced 78 battery and checked charging system, good at 14.7 Volts

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) performed oil change and replaced air filter
coolant -35'

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 31691

USING DEPT NO: 504241	OPENED DATE: 12/07/2018 14:02:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/04/2019 09:02:02	METER 1 - M: 14190 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/04/2019 09:02:05	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$29.99	\$0.00	\$29.99
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$0.00	\$5.38	\$0.00	\$5.38

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.40** **0.00** **35.37** **0.00** **35.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11758845	01/03/2019 07:00:00	01/03/2019 07:24:00	0.40	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-046	REPLACE NEW KEY BLANK(S)	23300334	KEY BLANK GM LASER STYLE	29.99	1	\$29.99
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.51	1	\$2.51
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.33	1	\$2.33
					PARTS	35.37

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 31691

Work Order Notes

(LISAPATE) doc requested 1 new key
(LISAPATE) nail in RR tire

Job Notes

03-51-046 - REPLACE NEW KEY BLANK(S)

(LISAPATE) Purchased 1 laser cut key from Tuscaloosa Chevrolet

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Removed and patched RR tire from the inside. rechecked ok

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500 WORK ORDER NO: 32121

USING DEPT NO:	504241	OPENED DATE:	02/05/2019 10:37:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/08/2019 07:24:13	METER 1 - M:	14389	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/08/2019 07:24:14	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	0.30	\$0.00	\$6.44	\$0.00	\$6.44

JOB COUNT: 1 WORK ORDER TOTAL: 0.30 0.00 6.44 0.00 6.44

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	11915538	02/05/2019 14:01:16	02/05/2019 14:19:16	0.30	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	6.44	1	\$6.44
					PARTS	6.44

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 32121

Work Order Notes

(LISAPATE) RF headlight out

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

(LISAPATE) Replaced RF headlight

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 32612

USING DEPT NO:	504241	OPENED DATE:	04/12/2019 13:12:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2019 06:56:35	METER 1 - M:	15203	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/25/2019 06:56:37	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.59	\$0.00	\$14.18	\$0.00	\$14.18

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.59** **0.00** **14.18** **0.00** **14.18**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/15/2019 08:44:37	04/15/2019 09:44:51	1.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/15/2019 09:35:45	04/15/2019 09:51:24	0.26	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/15/2019 08:26:55	04/15/2019 08:46:37	0.33	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.05	6	\$12.30
					PARTS	14.18

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 32612

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,RC/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 33704

USING DEPT NO:	504241	OPENED DATE:	08/13/2019 07:35:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/22/2019 11:57:15	METER 1 - M:	16422	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/22/2019 11:57:17	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-42-002	REPLACE NEW RADIATOR	DON	O	N	GARAGE	2.84	\$0.00	\$268.28	\$0.00	\$268.28
03-42-006	REPLACE NEW THERMOSTATS	DON	O	N	GARAGE	0.26	\$0.00	\$21.61	\$0.00	\$21.61
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.87	\$0.00	\$0.00	\$0.00	\$0.00
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.21	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.64	\$0.00	\$0.00	\$0.00	\$0.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.71	\$0.00	\$541.40	\$0.00	\$541.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.93	\$0.00	\$13.88	\$0.00	\$13.88

JOB COUNT: 8 **WORK ORDER TOTAL:** **7.97** **0.00** **845.17** **0.00** **845.17**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-42	DIAGNOSE COOLING SYSTEM	11310047	08/21/2019 07:00:00	08/21/2019 07:30:00	0.50	\$0.00
03-42-002	REPLACE NEW RADIATOR	11310047	08/17/2019 13:15:44	08/17/2019 15:09:32	1.90	\$0.00
03-42-006	REPLACE NEW THERMOSTATS	11310047	08/17/2019 12:59:52	08/17/2019 13:15:44	0.26	\$0.00
03-42-002	REPLACE NEW RADIATOR	11310047	08/17/2019 11:08:26	08/17/2019 11:52:47	0.74	\$0.00
03-42-002	REPLACE NEW RADIATOR	11310047	08/17/2019 08:54:27	08/17/2019 09:06:45	0.21	\$0.00
06-15	INSPECT STEERING	12052187	08/14/2019 13:12:50	08/14/2019 13:25:35	0.21	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/14/2019 13:02:57	08/14/2019 13:12:50	0.16	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/14/2019 10:21:20	08/14/2019 11:54:05	1.55	\$0.00
06-13	INSPECT BRAKES	11074414	08/13/2019 11:03:28	08/13/2019 11:55:22	0.87	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/13/2019 09:49:24	08/13/2019 10:25:21	0.60	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/13/2019 10:00:16	08/13/2019 10:20:23	0.34	\$0.00
09-15	ALIGN STEERING	11310047	08/19/2019 07:54:05	08/19/2019 08:32:46	0.64	\$0.00
					LABOR	0.00

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	132.24	4	\$528.96
03-42-002	REPLACE NEW RADIATOR	CU2791	RADIATOR	231.93	1	\$231.93
03-42-002	REPLACE NEW RADIATOR	7031711	CAP, COOLANT RESERVOIR PRESSUR	5.90	1	\$5.90
03-42-006	REPLACE NEW THERMOSTATS	455808	TSTAT OE STYLE W/SEAL 187F	21.61	1	\$21.61
03-42-002	REPLACE NEW RADIATOR	PIGMAT	OIL ABSORMENT MAT	0.73	12	\$8.76
03-42-002	REPLACE NEW RADIATOR	C111	RED BRAKE CLEANER	2.11	1	\$2.11
03-42-002	REPLACE NEW RADIATOR	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	2	\$19.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.28	12	\$3.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.27	4	\$9.08
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.00	6	\$12.00
					PARTS	845.17

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 33704

Work Order Notes

(LISAPATE) PM-Brakes squealing-van is overheating-added water to get it here temp got up to 260'

Job Notes

03-42-002 - REPLACE NEW RADIATOR

(LISAPATE) Installed a new radiator and cap, topped all fluid. Test Drove ok
Vehicle is no longer overheating

03-42-006 - REPLACE NEW THERMOSTATS

(LISAPATE) Installed a new thermostat

06-13 - INSPECT BRAKES

(LISAPATE) Checked brakes all good. no problems found

06-15 - INSPECT STEERING

(LISAPATE) SH Checked front end. No issues found

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

35-42 - DIAGNOSE COOLING SYSTEM

(LISAPATE) Checked found radiator leaking

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 35780

USING DEPT NO: 504241	OPENED DATE: 02/25/2020 15:28:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/28/2020 08:51:03	METER 1 - M: 18084 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/28/2020 08:51:05	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.39	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$0.00	\$34.95	\$0.00	\$34.95

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.18** **0.00** **34.95** **0.00** **34.95**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	11074414	02/26/2020 10:40:20	02/26/2020 11:03:34	0.39	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/26/2020 09:52:50	02/26/2020 10:40:20	0.79	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	3.88	6	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	1	\$9.79
					PARTS	34.95

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 35780

Work Order Notes

(LISAPATE) PM-Update GPS to 4G

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(LISAPATE) Removed 3G Serial# 5014132235
Installed 4G serial# 5041372116

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 37255

USING DEPT NO: 504241	OPENED DATE: 08/05/2020 07:55:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/05/2020 14:10:57	METER 1 - M: 19225 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/06/2020 07:15:53	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35 2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$0.00	\$0.50	\$0.00	\$0.50
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	0.00	0.50	0.00	0.50
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-02-074	RECALL WINDOW SWITCH	11074891	CTCS414084		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11915538	08/05/2020 10:58:47	08/05/2020 10:59:21	(0.01)	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11915538	08/05/2020 10:58:47	08/05/2020 10:59:21	0.01	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11915538	08/05/2020 10:58:47	08/05/2020 11:16:47	0.30	\$0.00
LABOR					0.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.50	1	\$0.50
PARTS					0.50	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 37255

Work Order Notes

(LISAPATE) Take to Tuscaloosa Chevrolet for recall 18155 power window switches

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Replaced RR brake light bulb

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Tuscaloosa Chevrolet by Transit

17-02-074 - RECALL WINDOW SWITCH

(LISAPATE) Tuscaloosa Chevrolet completed recall 18155 replaced driver side window switch

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 37585

USING DEPT NO: 504241	OPENED DATE: 09/14/2020 08:19:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/14/2020 10:49:30	METER 1 - M: 19465 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/14/2020 13:19:15	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-010	REPLACE NEW TAG LIGHT	DON	O	N	GARAGE	0.03	\$0.00	\$0.17	\$0.00	\$0.17
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.42** **0.00** **0.17** **0.00** **0.17**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/14/2020 09:34:29	09/14/2020 09:58:07	0.39	\$0.00
03-34-010	REPLACE NEW TAG LIGHT	12052187	09/14/2020 09:58:20	09/14/2020 10:00:11	0.03	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.18	2	\$0.36
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.18	(2)	(\$0.36)
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.17	1	\$0.17
					PARTS	0.17

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 37585

Work Order Notes

(LISAPATE) PM

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(JWRIGHT) Replaced tag light

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1300 miles since last pm. Updated sticker and checked all fluids and tires. Found no issues at this time.

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 39106

USING DEPT NO: 504241	OPENED DATE: 02/17/2021 07:42:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/22/2021 10:36:46	METER 1 - M: 21224 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 02/24/2021 07:23:19	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.12	\$14.19	\$153.66	\$0.00	\$167.85
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.17	\$20.09	\$0.56	\$0.00	\$20.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.43	\$37.92	\$0.00	\$85.35

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.69** **81.71** **192.14** **0.00** **273.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	12052187	02/19/2021 13:47:13	02/19/2021 13:54:26	0.12	\$14.19
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	12052187	02/17/2021 10:25:50	02/17/2021 10:36:03	0.17	\$20.09
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/17/2021 10:01:30	02/17/2021 10:25:37	0.40	\$47.43
					LABOR	81.71

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	7060	FILTER-OIL	2.82	1	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	5W30K	5W30 KENDALL QT	5.85	6	\$35.10
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.56	1	\$0.56
03-02-010	REPLACE NEW MIRRORS	SHIPPING	SHIPPING AND HANDLING	30.00	1	\$30.00
03-02-010	REPLACE NEW MIRRORS	TYC2320212-1	DOOR MIRROR	123.66	1	\$123.66
					PARTS	192.14

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 39106

Work Order Notes

(IFALLS) PM

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(JWRIGHT) Replaced driver side mirror assy with new. JAW

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(JWRIGHT) Replaced left brake light. No other issues found. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Found left brake light out and left mirror assy broken. Coolant -34°. JAW/SH
MILEAGE-21224

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 40344

USING DEPT NO: 504241	OPENED DATE: 07/06/2021 10:11:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/08/2021 07:50:35	METER 1 - M: 22462 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/09/2021 07:55:08	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35 2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.69	\$14.67	\$0.00	\$19.36
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.69	\$81.06	\$0.00	\$0.00	\$81.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.82	\$0.00	\$0.00	\$8.82

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.80** **94.57** **14.67** **0.00** **109.24**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/07/2021 09:37:54	07/07/2021 10:19:07	0.69	\$81.06
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/07/2021 09:30:00	07/07/2021 09:32:23	0.04	\$4.69
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/07/2021 09:29:09	07/07/2021 09:29:09	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/07/2021 09:10:31	07/07/2021 09:15:00	0.07	\$8.82
					LABOR	94.57

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.34	2	\$14.67
					PARTS	14.67

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 40344

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires adjusted tire pressure relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 22462. Vehicle has been driven 1238 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 40896

USING DEPT NO: 504241	OPENED DATE: 08/31/2021 08:16:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2021 10:05:18	METER 1 - M: 22702 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/31/2021 10:42:19	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-55-041	REMOVE LADDER RACK	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.25** **29.50** **0.00** **2.00** **31.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
25-55-041	REMOVE LADDER RACK	12052187	08/31/2021 08:32:22	08/31/2021 08:35:10	(0.05)	(\$5.51)
25-55-041	REMOVE LADDER RACK	12052187	08/31/2021 08:32:22	08/31/2021 08:35:10	0.05	\$5.51
25-55-041	REMOVE LADDER RACK	12052187	08/31/2021 08:32:22	08/31/2021 08:47:22	0.25	\$29.50
LABOR						29.50

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 40896

Work Order Notes

(LISAPATE) Remove ladder rack assy

Job Notes

25-55-041 - REMOVE LADDER RACK

(JWRIGHT) Removed ladder rack assy. SH,JAW,AMG,MS,IF

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 41856

USING DEPT NO: 504241	OPENED DATE: 12/13/2021 07:36:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/13/2021 15:22:06	METER 1 - M: 239140 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/15/2021 11:23:13	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.62	\$20.37	\$0.00	\$24.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.07	\$50.16	\$0.00	\$83.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.32** **37.69** **70.53** **2.00** **110.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2021 13:20:32	12/13/2021 13:37:21	0.28	\$33.07
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/13/2021 13:37:31	12/13/2021 13:39:52	0.04	\$4.62
LABOR					37.69	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	6.93	6	\$41.58
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	8.58	1	\$8.58
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	(2)	(\$15.18)
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	2	\$20.37
PARTS					70.53	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 41856

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 43245

USING DEPT NO: 504241	OPENED DATE: 05/16/2022 08:41:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2022 10:04:56	METER 1 - M: 25304 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/17/2022 15:23:05	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$7.67	\$15.18	\$0.00	\$22.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.16	\$0.00	\$0.00	\$22.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.25** **29.83** **15.18** **2.00** **47.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/16/2022 11:34:00	05/16/2022 11:37:54	0.07	\$7.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2022 11:22:34	05/16/2022 11:33:50	0.19	\$22.16
LABOR					29.83	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
PARTS					15.18	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 43245

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 44117

USING DEPT NO: 504241	OPENED DATE: 07/29/2022 08:58:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/29/2022 15:43:12	METER 1 - M: 26071 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/09/2022 12:35:37	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.64	\$75.49	\$8.73	\$0.00	\$84.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.64** **75.49** **8.73** **2.00** **86.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	07/29/2022 09:30:00	07/29/2022 10:00:34	0.51	\$60.11
66-17-030	PERFORM TIRE PATCH	11901357	07/29/2022 09:07:11	07/29/2022 09:15:00	0.13	\$15.37
LABOR					75.48	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.61	1	\$2.61
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.31	1	\$4.31
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-030	PERFORM TIRE PATCH	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
PARTS					8.73	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 44117

Work Order Notes

(LISAPATE) Screw in RR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 26071 Repaired and balanced R/R tire. Rechecked for leak, all good. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 44997

USING DEPT NO:	504241	OPENED DATE:	10/17/2022 08:10:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2022 10:42:08	METER 1 - M:	26387	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2022 14:14:16	IN-SERVICE DATE:	03/26/2015	
TECH SPEC NO:	15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500		UNIT SERIAL NO:	1GCZGTCG9F1175900	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.11	\$13.44	\$0.00	\$0.00	\$13.44
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	2.22	\$261.73	\$0.00	\$0.00	\$261.73
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.04	\$122.65	\$447.31	\$0.00	\$569.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.02	\$73.75	\$0.00	\$105.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	3.64	429.84	521.06	5.00	955.90
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11213180	10/20/2022 09:30:00	10/20/2022 09:40:02	0.17	\$19.73
66-17-013	PERFORM ALIGNMENT	11213180	10/20/2022 07:11:57	10/20/2022 09:15:00	2.05	\$242.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/17/2022 10:19:54	10/17/2022 11:22:16	1.04	\$122.65
06-15	INSPECT STEERING	11074414	10/17/2022 09:08:10	10/17/2022 09:15:00	0.11	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/17/2022 08:37:52	10/17/2022 08:54:09	0.27	\$32.02
					LABOR	429.84

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.41	6	\$44.46
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	5.30	1	\$5.30
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
66-PM-PMA	PERFORM OIL CHANGE	BALRS4131	BALDWIN AIR FILTER	16.14	1	\$16.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450718	TIRE GEN GRAB HD LT245/75R16	220.05	2	\$440.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.31	2	\$4.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
					PARTS	521.06

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 44997

Work Order Notes

(LISAPATE) PM

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(MSIDES) Performed alignment add 1.0hrs for adjusting camber and caster with cam bolts. MS

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires. Put new tires on the front. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. Needs 2 front tires due to tread depths of 1/32. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 46422

USING DEPT NO: 504241	OPENED DATE: 03/09/2023 08:43:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/09/2023 14:42:14	METER 1 - M: 27253 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/10/2023 07:35:49	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.40	\$0.00	\$0.00	\$35.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.31	\$36.45	\$0.00	\$0.00	\$36.45

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.11** **130.85** **0.00** **5.00** **135.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12201267	03/09/2023 12:02:00	03/09/2023 12:02:00	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12201267	03/09/2023 12:02:00	03/09/2023 12:02:00	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12201267	03/09/2023 12:02:00	03/09/2023 12:32:00	0.50	\$59.00
WA-00	WASH COMPLETE VEHICLE	12201267	03/09/2023 10:26:39	03/09/2023 10:43:22	0.28	\$32.88
WA-00	WASH COMPLETE VEHICLE	12201267	03/09/2023 10:14:52	03/09/2023 10:16:41	0.03	\$3.57
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/09/2023 09:50:44	03/09/2023 10:08:44	0.30	\$35.40
					LABOR 130.85	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 46422

Work Order Notes

(EHANNAH) pm-replace wipers- preform SI - wash vehicle

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed safety inspection-GC, No issues found at this time

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, Fluid check only, filter OK tires and tire pressure
Miles, 27,253

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Performed wash vehicle-GC

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 47866

USING DEPT NO: 504241	OPENED DATE: 08/09/2023 10:02:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/10/2023 13:26:52	METER 1 - M: 27948 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/10/2023 13:46:51	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.26	\$16.65	\$0.00	\$20.91
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.65	\$59.90	\$0.00	\$123.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.51	\$59.59	\$0.00	\$0.00	\$59.59

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.08** **127.50** **76.55** **5.00** **209.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2023 08:28:39	08/10/2023 08:42:32	0.23	\$27.30
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/09/2023 13:56:31	08/09/2023 14:15:00	0.31	\$36.35
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/10/2023 08:42:32	08/10/2023 08:44:42	0.04	\$4.26
WA-00	WASH COMPLETE VEHICLE	11074414	08/10/2023 08:44:42	08/10/2023 09:15:00	0.51	\$59.59
					LABOR	127.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.05	6	\$54.27
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	BALB160	OIL FILTER	5.63	1	\$5.63
					PARTS	76.55

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 47866

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JW GC/SH Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 48408

USING DEPT NO: 504241	OPENED DATE: 10/04/2023 12:25:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/05/2023 14:40:31	METER 1 - M: 28275 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2023 07:16:35	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.38	\$44.41	\$0.00	\$0.00	\$44.41
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.38** **44.41** **0.00** **5.00** **49.41**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11074414	10/04/2023 14:09:35	10/04/2023 14:15:00	0.09	\$10.65
66-79-002	PERFORM SERVICE CALL	11074414	10/04/2023 14:30:00	10/04/2023 14:47:10	0.29	\$33.76
LABOR					44.41	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 48408

Work Order Notes

(EHANNAH) Service call for dead battery
(IFALLS) customer left ignition key on to charge cell phone and ran the battery down.

Job Notes

06-32-002 - INSPECT BATTERY

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Performed a service call to Presidential 2 for a dead battery. Jumped the vehicle off and let it run for approximately 15 minutes. Restarted vehicle a couple of times. It was cranking good. ALT Charging at 14.5 volts. Called customer to let them know the vehicle was ready. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241247 **2015 CHEVROLET EXPRESS 3500** **WORK ORDER NO:** 48854

USING DEPT NO: 504241	OPENED DATE: 11/06/2023 13:20:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/10/2023 11:23:45	METER 1 - M: 28567 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2023 13:04:26	IN-SERVICE DATE: 03/26/2015
TECH SPEC NO: 15CHEVEXPRS35	2015 CHEVROLET EXPRESS 3500	UNIT SERIAL NO: 1GCZGTCG9F1175900

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	D	N	GARAGE	0.07	\$8.49	\$0.00	\$0.00	\$8.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.06	\$7.41	\$42.14	\$0.00	\$49.55

JOB COUNT: 3	WORK ORDER TOTAL:	0.13	15.90	42.14	5.00	63.04
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	11/09/2023 15:35:32	11/09/2023 15:39:18	0.06	\$7.41
25-52-021	REMOVE GPS SYSTEM	11915538	11/09/2023 15:39:18	11/09/2023 15:43:37	0.07	\$8.49
LABOR					15.90	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	42.00	1	\$42.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	1	\$0.14
PARTS					42.14	

Work Order Charge Detail

UNIT NO: 241247 2015 CHEVROLET EXPRESS 3500

WORK ORDER NO: 48854

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EKIMBREL) removed GPS#5041372116\RC

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) removed wordmarks and tag\RC

(EKIMBREL) milage 28567

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Nov 20 2023 15:27:43 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '241247') //Q=