

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 10740

USING DEPT NO:	200731	OPENED DATE:	04/10/2012 11:15:42	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/16/2012 08:21:58	METER 1 - M:	2684	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/16/2012 08:22:01	IN-SERVICE DATE:	05/18/2011		
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOV	DON	O	N	GARAGE	3.00	\$172.50	\$971.64	\$0.00	\$1,144.14

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>3.00</b>	<b>172.50</b>	<b>971.64</b>	<b>0.00</b>	<b>1,144.14</b>
---------------------	--------------------------	--	--	--	--	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	11074414	04/13/2012 17:00:00	04/13/2012 20:00:00	3.00	\$172.50
					<b>LABOR</b>	<b>172.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	CRT23021	BRASS COUPLER LOCK W/KEYS	16.23	1	\$16.23
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	CRT48190	8 TON BALL & PINTLE COMBO	152.77	1	\$152.77
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	CRT13055	CLASS III RECEIVER	347.65	1	\$347.65
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	PIC8130S	10 GAUGE WIRE	1.70	20	\$33.90
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	TA05020	BRAKE CONTROL KIT	57.84	1	\$57.84
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	HOP47205	ADAPTER	38.87	1	\$38.87
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	CRT48324	PINTLE MOUNT 10.5 LONG	88.15	1	\$88.15
03-59-006	REPLACE NEW HITCH ASSEMBLY - TOWING	RED90885	ELECTRIC BRAKE BOX	236.23	1	\$236.23
					<b>PARTS</b>	<b>971.64</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 10740

---

**Work Order Notes**

(LPATE) INSTALL HITCH ASSY

---

**Job Notes**

**03-59-006 - REPLACE NEW HITCH ASSEMBLY - TOWING**

(RWINTERS) INSTALLED HEAVY DUTY HITCH ASSY WITH WIRING, PINTLE, AND BALL. INSTALLED 7 PIN CONNECTOR, RAN NEW WIRING AND CIRCUIT BREAKER FOR ELECTRIC BRAKE CONTROLLER.

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 11950

USING DEPT NO:	200731	OPENED DATE:	09/21/2012 07:58:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2012 11:00:37	METER 1 - M:	5142	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/21/2012 11:00:39	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$53.67	\$0.00	\$71.50

JOB COUNT: 2 WORK ORDER TOTAL: 0.81 46.58 53.67 0.00 100.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10260422	09/21/2012 17:00:00	09/21/2012 17:18:36	0.31	\$17.83
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	10260422	09/21/2012 17:18:36	09/21/2012 17:48:36	0.50	\$28.75
					<b>LABOR</b>	<b>46.58</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.55	1	\$14.55
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.19	1	\$5.19
					<b>PARTS</b>	<b>53.67</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 11950

---

## Work Order Notes

(LPATE) PM-ROTATE TIRES

---

## Job Notes

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LPATE) ROTATED TIRES, LOOKED AT BRAKES LOOKED GOOD

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY GM/SH-REPLACED AIR FILTER

---



# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 13368

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY RT

---



# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 15400

---

## Work Order Notes

(LPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM,RS/RS

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 16621

USING DEPT NO:	200731	OPENED DATE:	04/14/2014 14:03:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2014 10:57:26	METER 1 - M:	11411	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2014 10:57:27	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$32.02	\$39.71	\$0.00	\$71.73

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.56</b>	<b>32.02</b>	<b>39.71</b>	<b>0.00</b>	<b>71.73</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/14/2014 14:15:00	04/14/2014 14:48:25	0.56	\$32.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/14/2014 14:11:39	04/14/2014 14:11:39	0.00	\$0.00
					<b>LABOR</b>	<b>32.02</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	6	\$34.56
					<b>PARTS</b>	<b>39.71</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 16621

---

## Work Order Notes

(LPATE) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY SH-CLEANED BATTERY CABLES-TIRES FELL UNDER RECALL-USED 1/2QT OF OIL ALREADY CHARGED OUT

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 17234

USING DEPT NO:	200731	OPENED DATE:	06/09/2014 11:13:28	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/12/2014 10:57:41	METER 1 - M:	12243	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2014 10:57:42	IN-SERVICE DATE:	05/18/2011		
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-010	INSTALL MIRRORS	DON	O	N	GARAGE	1.00	\$57.50	\$105.48	\$0.00	\$162.98
14-52-007	INSTALL CAMERA	DON	O	N	GARAGE	1.01	\$57.91	\$176.33	\$0.00	\$234.24

**JOB COUNT: 2** **WORK ORDER TOTAL: 2.01 115.41 281.81 0.00 397.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-007	INSTALL CAMERA	11568366	06/11/2014 09:10:59	06/11/2014 09:11:25	0.01	\$0.41
14-52-007	INSTALL CAMERA	11568366	06/11/2014 08:00:00	06/11/2014 09:00:00	1.00	\$57.50
14-02-010	INSTALL MIRRORS	11568366	06/11/2014 07:00:00	06/11/2014 08:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>115.41</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-007	INSTALL CAMERA	PKC0RG	BACK UP CAMERA	175.49	1	\$175.49
14-52-007	INSTALL CAMERA	CONNECTOR	CONNECTOR-NYLON	0.84	1	\$0.84
14-02-010	INSTALL MIRRORS	GRO28063	8" ROUND CONVEX MIRROR	105.48	1	\$105.48
					<b>PARTS</b>	<b>281.81</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 17234

---

**Work Order Notes**

(LPATE) INSTALL REAR CARGO MIRROR AND REARVIEW MIRROR

---

**Job Notes**

**14-02-010 - INSTALL MIRRORS**

(LPATE) INSTALLED A SPOT MIRROR ON THE DRIVERS REAR SIDE

**14-52-007 - INSTALL CAMERA**

(LPATE) INSTALLED A BACK UP CAMERA

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 18168

USING DEPT NO:	200731	OPENED DATE:	09/19/2014 14:58:31	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2014 07:07:27	METER 1 - M:	13777	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2014 07:07:28	IN-SERVICE DATE:	05/18/2011		
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$31.37	\$45.47	\$0.00	\$76.84

JOB COUNT: 1 WORK ORDER TOTAL: 0.55 31.37 45.47 0.00 76.84

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/22/2014 08:01:52	09/22/2014 08:34:36	0.55	\$31.37
					<b>LABOR</b>	<b>31.37</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
					<b>PARTS</b>	<b>45.47</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 18168

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY SH,NT/SH

---



# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 19513

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM/SH

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 21142

USING DEPT NO:	200731	OPENED DATE:	08/14/2015 13:56:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2015 13:56:35	METER 1 - M:	16171	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/21/2015 13:56:36	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$115.00	\$113.33	\$0.00	\$228.33
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	4.00	\$230.00	\$112.73	\$0.00	\$342.73
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$722.33	\$722.33
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.55	\$31.50	\$0.00	\$0.00	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.13	\$65.01	\$45.47	\$0.00	\$110.48

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>8.18</b>	<b>470.26</b>	<b>271.53</b>	<b>722.33</b>	<b>1,464.12</b>
---------------------	--------------------------	-------------	---------------	---------------	---------------	-----------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	163333	0029820	\$722.33
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	163296	0029820	\$793.40
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	163296	0029820	(\$793.40)
				<b>COMML</b>	<b>722.33</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	08/18/2015 14:30:00	08/18/2015 14:31:43	0.03	\$1.65
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	08/18/2015 13:43:51	08/18/2015 14:15:00	0.52	\$29.85
66-PM-PMA	PERFORM OIL CHANGE	10260422	08/15/2015 10:23:10	08/15/2015 11:31:00	1.13	\$65.01
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11268671	08/20/2015 07:30:00	08/20/2015 09:30:00	2.00	\$115.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	08/20/2015 07:30:00	08/20/2015 09:30:00	2.00	\$115.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	08/20/2015 07:30:00	08/20/2015 09:30:00	(2.00)	(\$115.00)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	08/20/2015 09:30:00	08/20/2015 11:30:00	2.00	\$115.00
06-13	INSPECT BRAKES	11268671	08/20/2015 07:00:00	08/20/2015 07:30:00	0.50	\$28.75
06-13	INSPECT BRAKES	11213180	08/20/2015 07:00:00	08/20/2015 07:30:00	0.50	\$28.75
06-13	INSPECT BRAKES	11213180	08/20/2015 07:00:00	08/20/2015 07:30:00	(0.50)	(\$28.75)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11268671	08/20/2015 07:00:00	08/20/2015 09:00:00	2.00	\$115.00

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.99	1	\$5.99
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABATD1328M	BRAKE PADS	113.33	1	\$113.33
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABATD1329M	BRAKE PADS	112.73	1	\$112.73
					<b>LABOR</b>	<b>470.26</b>
					<b>PARTS</b>	<b>271.53</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 21142

## Work Order Notes

(LPATE) PM-CHECK BRAKES-NEEDS 4 TIRES AND ALIGN

## Job Notes

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(RWINTERS) turned front rotors on van and replaced pads

### **03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(LPATE) REPLACED REAR PADS AND TURNED THE ROTORS ON THE VAN

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) OK TIRE REPLACED 4 TIRES AND ALIGNED. PD BY CC

### **06-13 - INSPECT BRAKES**

(LPATE) CHECKED BRAKES FRONT AND REAR PADS ARE WORN

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO OK TIRE BY AY

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LPATE) PM BY GM

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 22488

USING DEPT NO:	200731	OPENED DATE:	02/05/2016 14:36:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/08/2016 06:49:48	METER 1 - M:	17401	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/08/2016 06:49:50	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$131.87	\$0.00	\$160.62
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

**JOB COUNT: 2** **WORK ORDER TOTAL: 1.50 86.25 131.87 0.00 218.12**

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11074414	02/05/2016 14:36:41	02/05/2016 15:36:41	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11074414	02/05/2016 14:36:47	02/05/2016 15:06:47	0.50	\$28.75
					<b>LABOR</b>	<b>86.25</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	65X	BATTERY-EXTREME-FORD TOP POT	131.87	1	\$131.87
					<b>PARTS</b>	<b>131.87</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 22488

---

**Work Order Notes**

(LISAPATE) MICHAEL REQUESTED A SERVICE CALL TO 600 BLDG FOR A DEAD BATTERY

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) REPLACED BATTERY. RECHECKED OK

**66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) SERVICE CALL COMPLETED

---

# Work Order Charge Detail

**UNIT NO:** 238784      **2011 FORD E150**

**WORK ORDER NO:** 23038

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 04/08/2016 14:04:42	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/11/2016 11:12:26	<b>METER 1 - M:</b> 17908 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/11/2016 11:12:27	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.37	\$0.00	\$17.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$45.45	\$0.00	\$63.28

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.61**      **35.08**      **45.82**      **0.00**      **80.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11758845	04/09/2016 00:18:36	04/09/2016 00:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	04/09/2016 00:00:00	04/09/2016 00:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>35.08</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	912	BULB-BRAKE-3RD	0.37	1	\$0.37
					<b>PARTS</b>	<b>45.82</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 23038

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC**

(LISAPATE) REPLACED RIGHT SIDE 3RD BRAKE LIGHT

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS/GM

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 24289

USING DEPT NO:	200731	OPENED DATE:	09/02/2016 14:16:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2016 07:13:42	METER 1 - M:	19313	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/08/2016 07:13:43	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-074	REPLACE NEW VACUUM VALVE ASSY	DON	O	N	GARAGE	1.50	\$86.25	\$32.69	\$0.00	\$118.94
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$40.29	\$0.00	\$58.12

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.31</b>	<b>132.83</b>	<b>72.98</b>	<b>0.00</b>	<b>205.81</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11397026	09/07/2016 08:06:00	09/07/2016 08:24:36	0.31	\$17.83
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11397026	09/07/2016 07:00:00	09/07/2016 07:30:00	0.50	\$28.75
03-01-074	REPLACE NEW VACUUM VALVE ASSY	11397026	09/07/2016 07:30:00	09/07/2016 09:00:00	1.50	\$86.25
03-01-074	REPLACE NEW VACUUM VALVE ASSY	11397026	09/07/2016 07:30:00	09/07/2016 08:06:00	(0.60)	(\$34.50)
03-01-074	REPLACE NEW VACUUM VALVE ASSY	11397026	09/07/2016 07:30:00	09/07/2016 08:06:00	0.60	\$34.50
					<b>LABOR</b>	<b>132.83</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-01-074	REPLACE NEW VACUUM VALVE ASSY	47076A	VACUUM BALL	32.69	1	\$32.69
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.17	208	\$34.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
					<b>PARTS</b>	<b>72.98</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 24289

---

## Work Order Notes

(LISAPATE) PM-A/C STOPS WHEN GOING UP HILL

---

## Job Notes

### **03-01-074 - REPLACE NEW VACUUM VALVE ASSY**

(LISAPATE) INSTALLED A AFTERMARKET VACUUM BALL AND INSTALLED NEW VACUUM LINE TO THE BALL (VACUUM LINE ALREADY CHARGED OUT) TEST DROVE OK

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(LISAPATE) CHECKED OUT FOUND VEHICLE TO BE LOOSING VACUUM WHILE DRIVING

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY BG/IF

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 25725

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 02/10/2017 07:27:14	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/13/2017 07:47:16	<b>METER 1 - M:</b> 20307 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 02/13/2017 07:47:21	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$14.38	\$25.59	\$0.00	\$39.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$50.70	\$0.00	\$68.53
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	1.00	\$57.50	\$55.74	\$0.00	\$113.24

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.56</b>	<b>89.71</b>	<b>132.03</b>	<b>0.00</b>	<b>221.74</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/10/2017 09:10:11	02/10/2017 14:07:52	4.96	\$285.28
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/10/2017 09:10:11	02/10/2017 14:07:52	(4.96)	(\$285.28)
03-51-038	REPLACE NEW WIPER BLADES	11170580	02/10/2017 14:16:20	02/10/2017 14:31:20	0.25	\$14.38
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	11170580	02/10/2017 14:19:44	02/10/2017 15:19:44	1.00	\$57.50
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	11170580	02/10/2017 14:19:44	02/10/2017 15:19:44	(1.00)	(\$57.50)
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11170580	02/10/2017 15:10:07	02/10/2017 16:10:07	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/10/2017 09:10:11	02/10/2017 09:28:47	0.31	\$17.83
					<b>LABOR</b>	<b>89.71</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.80	2	\$25.59
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	10.41	1	\$10.41
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.17	208	\$34.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	ATPB144	AT TRANS KIT	30.96	1	\$30.96
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	VV322	TRANS FLUID VAL MAXLIFE GAL	24.78	1	\$24.78
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	ATPB144	AT TRANS KIT	30.96	(1)	(\$30.96)
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	ATPB144	AT TRANS KIT	30.96	1	\$30.96
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	VV322	TRANS FLUID VAL MAXLIFE GAL	24.78	(1)	(\$24.78)
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV322	TRANS FLUID VAL MAXLIFE GAL	24.78	1	\$24.78
66-27-036	PERFORM PAN AND SCREEN ASSEMBLY - OIL	ATPB144	AT TRANS KIT	30.96	(1)	(\$30.96)

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMT	PERFORM TRANSMISSION SERVICE	ATPB144	AT TRANS KIT	30.96	1	\$30.96
					<b>PARTS</b>	<b>132.03</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 25725

---

## Work Order Notes

(IFALLS) PM WIPERS TRANSMISSION SERVICE

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(IFALLS) AB REPLACED WIPER BLADES

### **66-27-036 - PERFORM PAN AND SCREEN ASSEMBLY - OIL**

(IFALLS) AB SERVICED TRANSMISSION FILTER AND FLUID

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(IFALLS) AB PERFORMED PM COOLANT CHECKED GOOD TO -45

### **66-PM-PMT - PERFORM TRANSMISSION SERVICE**

(IFALLS) Visit Reason Changed On 2/10/2017 3:09 PM By IFALLS

(IFALLS) AB SERVICED TRANSMISSION FLUID AND FILTER

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 27606

USING DEPT NO:	200731	OPENED DATE:	09/27/2017 11:18:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2017 07:16:39	METER 1 - M:	21929	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2017 07:16:40	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-006	REPLACE NEW NEW TERMINAL(S)	DON	O	N	GARAGE	0.50	\$28.75	\$2.97	\$0.00	\$31.72

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.50</b>	<b>28.75</b>	<b>2.97</b>	<b>0.00</b>	<b>31.72</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-006	REPLACE NEW NEW TERMINAL(S)	11268671	09/27/2017 11:19:35	09/27/2017 11:49:35	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-006	REPLACE NEW NEW TERMINAL(S)	BP19C	BATTERY TERMINAL-TOP POST REG	1.49	2	\$2.97
					<b>PARTS</b>	<b>2.97</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 27606

---

**Work Order Notes**

(LISAPATE) BATTERY IS SMOKING WHEN CRANKING

---

**Job Notes**

**03-32-006 - REPLACE NEW NEW TERMINAL(S)**

(LISAPATE) REMOVED AND INSTALLED NEW TOP POST BATTERY ENDS

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 27801

USING DEPT NO:	200731	OPENED DATE:	10/12/2017 16:12:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2017 07:58:48	METER 1 - M:	22019	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2017 07:58:51	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$24.69	\$0.00	\$42.52

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.31</b>	<b>17.83</b>	<b>24.69</b>	<b>0.00</b>	<b>42.52</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/13/2017 07:00:00	10/13/2017 07:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.09	208	\$18.72
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
					<b>PARTS</b>	<b>24.69</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 27801

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS/SH

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 29268

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 03/30/2018 11:16:46	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/04/2018 14:10:37	<b>METER 1 - M:</b> 23251 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/04/2018 14:10:40	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.41	\$0.00	\$17.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.28	\$0.00	\$51.11

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.61** **35.08** **33.69** **0.00** **68.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/02/2018 07:00:00	04/02/2018 07:18:36	0.31	\$17.83
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	04/02/2018 06:00:00	04/02/2018 06:18:00	0.30	\$17.25
					<b>LABOR</b>	<b>35.08</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	912	BULB-BRAKE-3RD	0.41	1	\$0.41
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	7	\$21.00
					<b>PARTS</b>	<b>33.69</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 29268

---

## Work Order Notes

(LISAPATE) PM

## Job Notes

**03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LISAPATE) REPLACED 3RD BRAKE LIGHT

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY AG

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 30369

USING DEPT NO:	200731	OPENED DATE:	07/25/2018 15:35:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/03/2018 10:06:33	METER 1 - M:	24775	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2018 10:06:35	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-019	REPLACE NEW OXYGEN SENSOR	DON	O	N	GARAGE	1.40	\$80.50	\$242.89	\$0.00	\$323.39
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00

JOB COUNT: 2 WORK ORDER TOTAL: 3.40 195.50 242.89 0.00 438.39

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	07/31/2018 07:00:00	07/31/2018 09:00:00	2.00	\$115.00
03-05-019	REPLACE NEW OXYGEN SENSOR	11170580	07/31/2018 09:00:00	07/31/2018 10:24:00	1.40	\$80.50
					<b>LABOR</b>	<b>195.50</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-05-019	REPLACE NEW OXYGEN SENSOR	DEN2344127	OXYGEN SENSOR	57.60	1	\$57.60
03-05-019	REPLACE NEW OXYGEN SENSOR	DEN2345113	OXYGEN SENSOR	185.29	1	\$185.29
					<b>PARTS</b>	<b>242.89</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 30369

---

## Work Order Notes

(LISAPATE) PER DRIVER DIED WHILE DRIVING WHEN CRANKED BACK UP CHECK ENGINE LIGHT WAS ON. BROUGHT TO THE SHOP

---

## Job Notes

### **03-05-019 - REPLACE NEW OXYGEN SENSOR**

(LISAPATE) INSTALLED NEW O2 SENSORS ON BANK 1 CLEARED CODE AND MONITORED PIDS AGAIN. RECHECKED OK DRIVERS USED TO GO TO BIRMINGHAM. MONITORS CHECKED OFF OK.

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT FORD TOOL-P2096 POST CATALYST FUEL TRIM SYSTEM TOO LEAN BANK 1 MONITORED PIDS FOR O2 SENSORS. B1S2 WAS STUCK.

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 30920

USING DEPT NO:	200731	OPENED DATE:	09/21/2018 15:39:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2018 07:39:12	METER 1 - M:	24685	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	09/25/2018 07:39:13	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$39.42	\$41.64	\$0.00	\$81.06

JOB COUNT: 1	WORK ORDER TOTAL:	0.69	39.42	41.64	0.00	81.06
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/22/2018 12:36:18	09/22/2018 13:17:26	0.69	\$39.42

**LABOR 39.42**

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	740245	BATTERY TERM PROTECTOR WASHER	0.35	1	\$0.35
66-PM-PMA	PERFORM OIL CHANGE	740245	BATTERY TERM PROTECTOR WASHER	0.35	1	\$0.35
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.00	7	\$34.97

**PARTS 41.64**

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 30920

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

(RTUNAITI) PM by SH

Coolant -45'

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 31916

USING DEPT NO:	200731	OPENED DATE:	01/14/2019 13:29:43	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	01/18/2019 07:45:55	METER 1 - M:	35780	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/18/2019 07:45:56	IN-SERVICE DATE:	05/18/2011		
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$41.22	\$38.42	\$0.00	\$79.64

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.57</b>	<b>41.22</b>	<b>38.42</b>	<b>0.00</b>	<b>79.64</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/14/2019 14:33:07	01/14/2019 15:07:14	0.57	\$41.22
					<b>LABOR</b>	<b>41.22</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.64	7	\$32.45
					<b>PARTS</b>	<b>38.42</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 31916

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by SH,EK/SH

Coolant -20'

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 33847

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 08/23/2019 13:18:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/29/2019 08:17:02	<b>METER 1 - M:</b> 28191 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/29/2019 08:17:02	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.82	\$59.25	\$0.00	\$0.00	\$59.25
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.77	\$128.28	\$818.82	\$0.00	\$947.10
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.29	\$20.88	\$0.00	\$0.00	\$20.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$48.23	\$53.68	\$0.00	\$101.91

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>3.54</b>	<b>256.64</b>	<b>872.50</b>	<b>0.00</b>	<b>1,129.14</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/27/2019 07:03:13	08/27/2019 08:49:23	1.77	\$128.28
09-15	ALIGN STEERING	11310047	08/28/2019 07:23:19	08/28/2019 08:12:21	0.82	\$59.25
66-79-003	PERFORM SAFETY INSPECTION	12052187	08/26/2019 08:54:07	08/26/2019 09:11:24	0.29	\$20.88
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/26/2019 07:37:30	08/26/2019 08:17:25	0.67	\$48.23
					<b>LABOR</b>	<b>256.64</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	93775	TIRE LT225/75R16 BFG COMM T/A	200.67	4	\$802.68
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.32	1	\$6.32
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	10.41	1	\$10.41
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	6	\$2.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.41	4	\$13.62
					<b>PARTS</b>	<b>872.50</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 33847

---

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **09-15 - ALIGN STEERING**

(LISAPATE) EH performed alignment

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) Mount and balanced 4 new tires. Found RR rim had curb rash bend but no major issues. All tires balanced out good

### **66-79-003 - PERFORM SAFETY INSPECTION**

(LISAPATE) Safety inspection completed. See attached

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by JW

Coolant -25'

Replaced air filter

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 35431

USING DEPT NO:	200731	OPENED DATE:	01/16/2020 15:57:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/30/2020 07:37:59	METER 1 - M:	29640	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2020 07:38:01	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.08	\$5.96	\$25.59	\$0.00	\$31.55
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.45	\$32.77	\$0.00	\$0.00	\$32.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$37.46	\$32.52	\$0.00	\$69.98

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.05</b>	<b>76.19</b>	<b>58.11</b>	<b>0.00</b>	<b>134.30</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	01/17/2020 11:44:26	01/17/2020 11:48:01	0.06	\$4.33
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	01/17/2020 13:01:11	01/17/2020 13:20:39	0.32	\$23.52
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	01/17/2020 14:47:15	01/17/2020 14:51:19	0.07	\$4.91
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/17/2020 11:12:10	01/17/2020 11:17:06	0.08	\$5.96
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/17/2020 10:41:10	01/17/2020 11:12:10	0.52	\$37.46
					<b>LABOR</b>	<b>76.18</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.79	(1)	(\$12.79)
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.80	2	\$25.59
					<b>PARTS</b>	<b>58.11</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 35431

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) Replaced wipers

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) Rotated tires

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by EK/SH

Coolant -520'

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 36839

USING DEPT NO:	200731	OPENED DATE:	06/17/2020 08:36:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2020 09:54:33	METER 1 - M:	30934	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/18/2020 07:50:28	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.83	\$60.18	\$32.52	\$0.00	\$92.70

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.83</b>	<b>60.18</b>	<b>32.52</b>	<b>0.00</b>	<b>92.70</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/17/2020 08:51:19	06/17/2020 09:00:00	0.14	\$10.49
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/17/2020 09:15:00	06/17/2020 09:41:28	0.44	\$31.98
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/17/2020 09:00:21	06/17/2020 09:15:00	0.24	\$17.70
					<b>LABOR</b>	<b>60.17</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					<b>PARTS</b>	<b>32.52</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 36839

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) SH/JW Performed pm service. Found no issues at this time

Coolant -35'

SH Relearned TPMS

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 37444

USING DEPT NO:	200731	OPENED DATE:	08/27/2020 11:37:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/02/2020 12:16:47	METER 1 - M:	31709	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/03/2020 07:04:04	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-44-003	REPLACE NEW FUEL PUMP	DON	O	N	GARAGE	1.81	\$130.92	\$767.83	\$0.00	\$898.75
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$145.00	\$0.00	\$0.00	\$145.00

**JOB COUNT: 2** **WORK ORDER TOTAL: 3.81 275.92 767.83 0.00 1,043.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	08/27/2020 12:05:46	08/27/2020 12:05:46	0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	08/27/2020 12:05:46	08/27/2020 12:05:46	0.00	\$0.00
03-44-003	REPLACE NEW FUEL PUMP	11213180	08/31/2020 08:55:56	08/31/2020 10:44:17	1.81	\$130.92
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	08/27/2020 12:05:46	08/27/2020 14:05:46	2.00	\$145.00
					<b>LABOR</b>	<b>275.92</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-003	REPLACE NEW FUEL PUMP	MOTPFS573	FUEL PUMP MODULE ASSY	760.37	1	\$760.37
03-44-003	REPLACE NEW FUEL PUMP	DOR800023	FUEL LINE CLIP	7.46	1	\$7.46
					<b>PARTS</b>	<b>767.83</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 37444

---

## Work Order Notes

(LISAPATE) Per driver check engine light is on-van is sputtering-gas gauge not working

---

## Job Notes

### **03-44-003 - REPLACE NEW FUEL PUMP**

(MSIDES) Replaced fuel pump/sender assembly, rechecked ok. MS

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(MSIDES) Used ford IDS to scan vehicle and found code P0463 - Fuel level sensor A circuit high. Test wiring and found wiring to check ok therefore found fuel level sensor in tank to be faulty. MS

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 38313

USING DEPT NO:	200731	OPENED DATE:	11/09/2020 08:34:53	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2020 09:18:03	METER 1 - M:	32423	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/11/2020 13:59:31	IN-SERVICE DATE:	05/18/2011		
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.12	\$14.59	\$0.39	\$0.00	\$14.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.53	\$0.00	\$0.00	\$100.53
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	O	N	GARAGE	0.61	\$71.59	\$66.99	\$0.00	\$138.58

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.58</b>	<b>186.71</b>	<b>67.38</b>	<b>0.00</b>	<b>254.09</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11901357	11/09/2020 12:59:54	11/09/2020 13:07:19	0.12	\$14.59
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11170580	11/11/2020 07:03:56	11/11/2020 07:40:20	0.61	\$71.59
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2020 12:25:37	11/09/2020 12:59:39	0.57	\$66.93
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/09/2020 11:37:26	11/09/2020 11:54:31	0.28	\$33.60
					<b>LABOR</b>	<b>186.71</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	194	BULB-TAG/MARKER	0.63	1	\$0.63
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	912	BULB-BRAKE-3RD	0.39	1	\$0.39
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	194	BULB-TAG/MARKER	0.63	(1)	(\$0.63)
66-PM-PMT	PERFORM TRANSMISSION SERVICE	C111	RED BRAKE CLEANER	3.32	1	\$3.32
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV324	TRANS FLUID QT	6.38	7	\$44.63
66-PM-PMT	PERFORM TRANSMISSION SERVICE	ATPB144	AT TRANS KIT	31.79	1	\$31.79
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV324	TRANS FLUID QT	6.38	(7)	(\$44.63)
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV324	TRANS FLUID QT	6.38	5	\$31.88
66-PM-PMT	PERFORM TRANSMISSION SERVICE	C111	RED BRAKE CLEANER	3.32	(1)	(\$3.32)
66-PM-PMT	PERFORM TRANSMISSION SERVICE	C111	RED BRAKE CLEANER	3.32	1	\$3.32
					<b>PARTS</b>	<b>67.38</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 38313

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC**

(AGUERRA) Replaced right 3rd brake light bulb, checked for proper operation, all good. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by SH and AG

**66-PM-PMT - PERFORM TRANSMISSION SERVICE**

(ABLACK) AB performed transmission service

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 39542

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 04/01/2021 10:09:45	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/05/2021 11:40:58	<b>METER 1 - M:</b> 33892 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/06/2021 07:23:30	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-028	REPLACE NEW MOUNT AND BALANCE	DON	O	N	GARAGE	0.21	\$25.24	\$206.14	\$0.00	\$231.38
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.57	\$66.93	\$0.00	\$0.00	\$66.93

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.78** **92.17** **206.14** **0.00** **298.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	11074414	04/01/2021 11:47:10	04/01/2021 12:00:00	0.21	\$25.24
66-17-030	PERFORM TIRE PATCH	11074414	04/01/2021 11:29:56	04/01/2021 11:46:57	(0.28)	(\$33.47)
66-17-030	PERFORM TIRE PATCH	11074414	04/01/2021 11:29:56	04/01/2021 11:46:57	0.28	\$33.47
66-79-002	PERFORM SERVICE CALL	11074414	04/01/2021 10:21:01	04/01/2021 10:55:03	0.57	\$66.93
					<b>LABOR</b>	<b>92.17</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	93775	TIRE LT225/75R16 BFG COMM T/A	201.34	1	\$201.34
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	2	\$0.96
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.84	1	\$3.84
					<b>PARTS</b>	<b>206.14</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 39542

---

## Work Order Notes

(LISAPATE) Michael Keys requested a service call to West side of Foster Auditorium for a flat tire on LR

Contact Michal 205-579-4883

---

## Job Notes

### **03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 1 tire. SH

### **66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Tire would not patch to close to the sidewall. SH

### **66-79-002 - PERFORM SERVICE CALL**

(SHARBIN) Mileage 33892. SH RC Performed service call aired tire up and drove it back to the shop.

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 39774

USING DEPT NO:	200731	OPENED DATE:	04/22/2021 08:21:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2021 15:07:22	METER 1 - M:	34178	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 08:21:11	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.89	\$36.21	\$0.00	\$70.10

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.29</b>	<b>33.89</b>	<b>36.21</b>	<b>0.00</b>	<b>70.10</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2021 08:57:46	04/22/2021 09:15:00	0.29	\$33.89
					<b>LABOR</b>	<b>33.89</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					<b>PARTS</b>	<b>36.21</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 39774

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 34178 Completed PM bottomside, Scott was topside. SH/AMG Completed checklist and vacuumed out vehicle. AMG

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 41217

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 10/05/2021 12:09:16	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/12/2021 13:36:43	<b>METER 1 - M:</b> 35646 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/13/2021 09:41:19	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-15-009	REPLACE NEW TIE ROD	DON	O	N	GARAGE	0.71	\$83.71	\$222.58	\$0.00	\$306.29
03-15-020	REPLACE NEW DRAG LINK	DON	O	N	GARAGE	0.86	\$101.09	\$96.51	\$0.00	\$197.60
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.15	\$17.70	\$15.18	\$0.00	\$32.88
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.65	\$194.70	\$0.00	\$0.00	\$194.70
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$47.20	\$549.85	\$0.00	\$597.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 7** **WORK ORDER TOTAL: 4.10 483.34 884.12 2.00 1,369.46**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/06/2021 12:11:21	10/06/2021 12:31:09	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/06/2021 12:11:21	10/06/2021 12:11:21	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/06/2021 12:11:21	10/06/2021 12:11:21	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/06/2021 12:15:36	10/06/2021 12:15:36	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/06/2021 12:15:36	10/06/2021 12:15:36	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/06/2021 12:15:36	10/06/2021 12:24:36	0.15	\$17.70
03-15-009	REPLACE NEW TIE ROD	11213180	10/08/2021 10:09:21	10/08/2021 10:51:55	0.71	\$83.71
03-15-020	REPLACE NEW DRAG LINK	11213180	10/08/2021 13:31:31	10/08/2021 14:15:00	0.72	\$85.52
03-15-020	REPLACE NEW DRAG LINK	11213180	10/08/2021 14:30:00	10/08/2021 14:37:55	0.13	\$15.57
09-15	ALIGN STEERING	11170580	10/11/2021 09:20:19	10/11/2021 10:59:14	1.65	\$194.54
09-15	ALIGN STEERING	11170580	10/11/2021 09:20:19	10/11/2021 10:59:14	(1.65)	(\$194.54)

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11170580	10/11/2021 07:00:00	10/11/2021 08:39:00	1.65	\$194.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	10/13/2021 07:00:00	10/13/2021 07:24:00	0.40	\$47.20
					<b>LABOR</b>	<b>483.34</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	93775	TIRE LT225/75R16 BFG COMM T/A	270.00	2	\$540.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.92	2	\$7.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58122	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	2	\$0.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58124	1.25 OZ WHEEL WEIGHT	0.60	1	\$0.60
03-15-009	REPLACE NEW TIE ROD	JTE1557	TIE ROD END	63.95	1	\$63.95
03-15-020	REPLACE NEW DRAG LINK	JTY7006	DRAG LINK	96.51	1	\$96.51
03-15-009	REPLACE NEW TIE ROD	JTE1549	TIE ROD END	41.73	1	\$41.73
03-15-009	REPLACE NEW TIE ROD	JTE1554	TIE ROD END	45.08	1	\$45.08
03-15-009	REPLACE NEW TIE ROD	JSA1025	ADJUSTER SLEEVE TIE ROD	32.85	1	\$32.85
03-15-009	REPLACE NEW TIE ROD	10005	GREASE RED N TACKY NO 2 LUCAS	6.12	1	\$6.12
03-15-009	REPLACE NEW TIE ROD	JSA1025	ADJUSTER SLEEVE TIE ROD	32.85	(1)	(\$32.85)
03-15-009	REPLACE NEW TIE ROD	JSA1025	ADJUSTER SLEEVE TIE ROD	32.85	2	\$65.70
					<b>PARTS</b>	<b>884.12</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 41217

---

## Work Order Notes

(CHANNELL) PM\ Replace wipers

---

## Job Notes

### **03-15-009 - REPLACE NEW TIE ROD**

(MSIDES) Replaced both outer and one inner tie rod. MS

### **03-15-020 - REPLACE NEW DRAG LINK**

(MSIDES) Replaced drag link and both adjuster sleeves. MS

### **03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Installed new wiper blades

### **09-15 - ALIGN STEERING**

(ABLACK) AB performed alignment

### **66-17-013 - PERFORM ALIGNMENT**

(LISAPATE) AB performed alignment

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) MS mount and balanced 2 new tires

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has been 1468 miles since last pm. Updated sticker. Checked all fluids and tires. Coolant -34°. RC,JAW  
MILEAGE-35646

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 42651

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 03/11/2022 08:24:02	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/11/2022 14:59:38	<b>METER 1 - M:</b> 36596 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/21/2022 08:44:41	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.28	\$15.18	\$0.00	\$16.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.50	\$31.82	\$0.00	\$67.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>36.78</b>	<b>47.00</b>	<b>2.00</b>	<b>85.78</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/11/2022 09:30:00	03/11/2022 09:41:10	0.19	\$21.96
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/11/2022 09:12:51	03/11/2022 09:15:00	0.04	\$4.23
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/11/2022 09:34:53	03/11/2022 09:35:32	0.01	\$1.28
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/11/2022 09:30:00	03/11/2022 09:34:44	0.08	\$9.31
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/11/2022 09:17:05	03/11/2022 09:17:05	0.00	\$0.00
<b>LABOR</b>					<b>36.78</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.27	1	\$5.27
<b>PARTS</b>					<b>47.00</b>	

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 42651

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH  
MILEAGE-36596

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 44251

USING DEPT NO:	200731	OPENED DATE:	08/10/2022 10:46:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/16/2022 08:04:06	METER 1 - M:	36597	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/16/2022 12:51:25	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.12	\$13.64	\$113.55	\$0.00	\$127.19
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$7.26	\$0.00	\$66.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$14.82	\$0.00	\$0.00	\$14.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.74</b>	<b>87.46</b>	<b>120.81</b>	<b>2.00</b>	<b>210.27</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML 2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11915538	08/16/2022 07:00:00	08/16/2022 07:30:00	0.50	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/12/2022 09:24:04	08/12/2022 09:24:04	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2022 15:15:43	08/10/2022 15:23:15	0.13	\$14.82
03-32-002	REPLACE NEW BATTERY	11074414	08/10/2022 15:08:16	08/10/2022 15:15:12	0.12	\$13.64
					<b>LABOR</b>	<b>87.46</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
					<b>PARTS</b>	<b>120.81</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 44251

---

**Work Order Notes**

(LRUSHING) PM AND BROKEN DOWN IN OIT PARKING LOT -BATTERY DEAD

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(HHARBIN) Battery tested bad replaced battery ALT charging at 14.5 SH

**66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) jumped off drove to the shop. RC

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) VEHICLE HAS BEEN DRIVEN 1 MILE SINCE THE LAST PM. CHECKED FLUIDS BATTERY TIRE PRESSURE AND UPDATED THE OIL CHANGE STICKER. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 45766

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 01/11/2023 13:04:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/13/2023 14:15:55	<b>METER 1 - M:</b> 38312 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/17/2023 09:15:05	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.63	\$0.00	\$33.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.74	\$43.38	\$0.00	\$80.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.46</b>	<b>54.44</b>	<b>59.01</b>	<b>5.00</b>	<b>118.45</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/11/2023 14:26:14	01/11/2023 14:35:14	0.15	\$17.70
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/11/2023 14:26:14	01/11/2023 14:26:14	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/11/2023 14:26:14	01/11/2023 14:26:14	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/11/2023 14:29:46	01/11/2023 14:29:46	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/11/2023 14:30:00	01/11/2023 14:48:41	0.31	\$36.74
<b>LABOR</b>					<b>54.44</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.85	1	\$5.85
<b>PARTS</b>					<b>59.01</b>	

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 45766

---

**Work Order Notes**

(EHANNAH) pm- replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 38312 Completed PM topside, Gregg was bottomside. AMG/GC

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 47133

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 05/22/2023 10:31:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/30/2023 10:34:35	<b>METER 1 - M:</b> 39989 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/31/2023 11:31:26	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-059	REPLACE NEW WINDSHIELD WASHER	DON	O	N	GARAGE	1.24	\$146.52	\$78.08	\$0.00	\$224.60
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BI	DON	P	N	GARAGE	0.07	\$8.75	\$1.08	\$0.00	\$9.83
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.28	\$33.04	\$0.00	\$0.00	\$33.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.67	\$0.00	\$0.00	\$23.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.27	\$31.76	\$0.00	\$0.00	\$31.76

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>2.07</b>	<b>243.74</b>	<b>79.16</b>	<b>5.00</b>	<b>327.90</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11074414	05/22/2023 13:52:40	05/22/2023 14:09:28	0.28	\$33.04
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2023 13:13:02	05/22/2023 13:25:04	0.20	\$23.67
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	11074414	05/22/2023 13:08:18	05/22/2023 13:12:45	0.07	\$8.75
WA-00	WASH COMPLETE VEHICLE	11074414	05/22/2023 14:09:41	05/22/2023 14:15:00	0.09	\$10.46
WA-00	WASH COMPLETE VEHICLE	11074414	05/22/2023 14:30:00	05/22/2023 14:40:50	0.18	\$21.31
03-02-059	REPLACE NEW WINDSHIELD WASHER RESERVOIR	12201267	05/24/2023 07:51:21	05/24/2023 09:05:51	1.24	\$146.52
03-02-059	REPLACE NEW WINDSHIELD WASHER RESERVOIR	12201267	05/24/2023 09:15:54	05/24/2023 09:15:54	0.00	\$0.00
					<b>LABOR</b>	<b>243.75</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	912	BULB-BRAKE-3RD	1.08	1	\$1.08
03-02-059	REPLACE NEW WINDSHIELD WASHER RESERVOIR	8C2Z17618A	WASHER FLUID RESERVOIR	78.08	1	\$78.08
					<b>PARTS</b>	<b>79.16</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 47133

---

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

---

## Job Notes

### **03-02-059 - REPLACE NEW WINDSHIELD WASHER RESERVOIR**

(GRCOOK) Installed new window washer jug- 1hr -GC  
Miles, 39,989

### **03-34-020 - REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY**

(SHARBIN) Replaced the right side 3RD brake light bulb. SH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front brake pads measure 7 MM rear brake pads measure 5MM. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 1677 miles since the last PM. Checked the fluids battery tire pressure and updated the oil change sticker. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed the vehicle. SH

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 48816

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 11/02/2023 15:46:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/10/2023 11:26:34	<b>METER 1 - M:</b> 41741 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/10/2023 12:59:29	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.29	\$33.93	\$0.00	\$0.00	\$33.93

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.29** **33.93** **0.00** **5.00** **38.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	11/08/2023 07:42:02	11/08/2023 07:59:17	0.29	\$33.93
					<b>LABOR</b>	<b>33.93</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 48816

---

**Work Order Notes**

(EHANNAH) prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 8394

USING DEPT NO:	200731	OPENED DATE:	05/20/2011 11:13:30	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2011 11:41:45	METER 1 - M:	143	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2011 11:41:48	IN-SERVICE DATE:	05/18/2011		
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.06	\$3.32	\$6.12	\$0.00	\$9.44
03-53-006	REPLACE NEW WORDMARKS/IDENTIFI	DON	O	N	GARAGE	0.50	\$28.75	\$45.00	\$0.00	\$73.75
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.06</b>	<b>60.82</b>	<b>51.12</b>	<b>0.00</b>	<b>111.94</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-046	REPLACE NEW KEY BLANK(S)	11328035	05/20/2011 11:26:40	05/20/2011 11:30:08	0.06	\$3.32
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11328035	05/20/2011 18:00:00	05/20/2011 18:30:00	0.50	\$28.75
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	11328035	05/20/2011 17:30:00	05/20/2011 18:00:00	0.50	\$28.75
03-51-046	REPLACE NEW KEY BLANK(S)	11328035	05/20/2011 17:00:00	05/20/2011 17:30:00	0.50	\$28.75
03-51-046	REPLACE NEW KEY BLANK(S)	11328035	05/20/2011 17:00:00	05/20/2011 17:30:00	(0.50)	(\$28.75)
					<b>LABOR</b>	<b>60.82</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	WORDMARK	WORDMARK-CRIMSON/ GRAY	22.50	2	\$45.00
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	1.53	4	\$6.12
					<b>PARTS</b>	<b>51.12</b>

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 8394

---

**Work Order Notes**

(LPATE) PDI-CUT 4 EXTRA KEYS-INSTALL WORDMARKS

---

**Job Notes**

**03-51-046 - REPLACE NEW KEY BLANK(S)**

(LPATE) CUT 4 EXTRA KEYS AS REQUESTED BY DEPT

**03-53-006 - REPLACE NEW WORDMARKS/IDENTIFIERS**

(LPATE) INSTALLED WORDMARKS

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LPATE) PDI COMPLETE-VEHICLE FLUIDS AND TIRE PRESSURES ARE GOOD.

---

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 9240

USING DEPT NO:	200731	OPENED DATE:	09/26/2011 09:20:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2011 07:51:10	METER 1 - M:	1264	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2011 07:51:12	IN-SERVICE DATE:	05/18/2011	
TECH SPEC NO:	11FORDE150	2011 FORD E150 CARGO VAN		UNIT SERIAL NO:	1FTNE1EWXBDA95950	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.58	\$0.00	\$44.41

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.31</b>	<b>17.83</b>	<b>26.58</b>	<b>0.00</b>	<b>44.41</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/26/2011 17:00:00	09/26/2011 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.74	1	\$4.74
					<b>PARTS</b>	<b>26.58</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 9240

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY SH

---

# Work Order Charge Detail

**UNIT NO:** 238784 2011 FORD E150

**WORK ORDER NO:** 9940

<b>USING DEPT NO:</b> 200731	<b>OPENED DATE:</b> 12/21/2011 14:47:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/10/2012 09:36:18	<b>METER 1 - M:</b> 2016 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/10/2012 09:36:20	<b>IN-SERVICE DATE:</b> 05/18/2011
<b>TECH SPEC NO:</b> 11FORDE150	2011 FORD E150 CARGO VAN	<b>UNIT SERIAL NO:</b> 1FTNE1EWXBDA95950

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-53-006	REPLACE NEW WORDMARKS/IDENTIFI	DON	O	N	GARAGE	0.25	\$14.38	\$22.50	\$0.00	\$36.88
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,959.22	\$1,959.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$19.92	\$29.94	\$0.00	\$49.86

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>1.60</b>	<b>91.80</b>	<b>52.44</b>	<b>1,959.22</b>	<b>2,103.46</b>
---------------------	--------------------------	-------------	--------------	--------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	135877	0014403	\$1,959.22
24-71	REPAIR BODY	11150605	135877	0014403	\$0.00
24-71	REPAIR BODY	11150605	135877	0014403	\$0.00
<b>COMML</b>					<b>1959.22</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	01/09/2012 09:01:20	01/09/2012 09:15:00	0.23	\$13.10
66-PM-PMA	PERFORM OIL CHANGE	10260422	01/09/2012 09:30:00	01/09/2012 09:37:07	0.12	\$6.82
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	10260422	01/09/2012 09:15:00	01/09/2012 09:30:00	0.25	\$14.38
16-71	TRANSPORT BODY	10260422	01/09/2012 09:15:00	01/09/2012 10:15:00	1.00	\$57.50
<b>LABOR</b>						<b>91.80</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.71	1	\$4.71
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	5.07	1	\$5.07
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	(224)	(\$23.52)
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	192	\$20.16
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	WORDMARK	WORDMARK-CRIMSON/ GRAY	22.50	1	\$22.50
<b>PARTS</b>						<b>52.44</b>

# Work Order Charge Detail

UNIT NO: 238784 2011 FORD E150

WORK ORDER NO: 9940

---

## Work Order Notes

(LPATE) BILLY ANDREW'S PICKED UP VAN AND TOOK TO REPAIR DAMAGE TO LEFT DOOR AND FRONT FENDER AREA PER ESTIMATE.

---

## Job Notes

### **03-53-006 - REPLACE NEW WORDMARKS/IDENTIFIERS**

(LPATE) ADDED NEW WORDMARK TO LEFT DOOR AFTER BODY DAMAGE WAS REPAIRED.

### **16-71 - TRANSPORT BODY**

(LPATE) PICKED UP FROM ANDREW'S BY SH

### **24-71 - REPAIR BODY**

(LPATE) ANDREW'S REPAIRED DAMAGE TO LEFT DOOR AND FENDER PER ESTIMATE. PD BY CC.

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY RS/GM/RT

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Mon Nov 20 2023 15:03:58 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '238784') //Q=