

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 10284

USING DEPT NO: 504107	OPENED DATE: 02/09/2012 07:29:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/10/2012 07:32:50	METER 1 - M: 9633 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/10/2012 07:32:52	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$36.10	\$28.21	\$0.00	\$64.31

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.63** **36.10** **28.21** **0.00** **64.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	02/09/2012 08:37:20	02/09/2012 09:15:00	0.63	\$36.10
66-PM-PMA	PERFORM OIL CHANGE	10260422	02/09/2012 09:30:00	02/09/2012 13:16:32	3.78	\$217.10
66-PM-PMA	PERFORM OIL CHANGE	10260422	02/09/2012 09:30:00	02/09/2012 13:16:32	(3.78)	(\$217.10)
					LABOR	36.10

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.69	1	\$4.69
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
					PARTS	28.21

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 10284

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 12160

USING DEPT NO: 504107	OPENED DATE: 10/17/2012 08:39:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/19/2012 08:19:28	METER 1 - M: 10898 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/19/2012 08:19:29	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$705.58	\$705.58
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.67	\$0.00	\$62.50

JOB COUNT: 3	WORK ORDER TOTAL:	1.31	75.33	44.67	705.58	825.58
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	D228272	0017699	\$705.58
COMML					705.58

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11413680	10/18/2012 07:00:00	10/18/2012 07:18:36	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11413680	10/18/2012 07:18:36	10/18/2012 08:18:36	1.00	\$57.50
LABOR					75.33	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.19	1	\$5.19
PARTS					44.67	

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 12160

Work Order Notes

(LPATE) PM-REPLACE 4 TIRES AND ALIGN DUE TO AGE TIRES ARE 6 YEARS OLD VERY DRYROTTED.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) GOODYEAR REPLACED 4 TRIES AND ALIGNED.P0042282

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO GOODYEAR BY RT

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 3.16

Part 6418 FILTER-AIR Qty 1 Cost 9.84

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

(LPATE) PM BY RT/GM

(LPATE) BRAKES WERE OK DID NOT HEAR ANY NOISE WHILE DRIVING, GOODYEAR INSPECTED SAID LOOKED OK.

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 13898

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY RT/SH

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 14083

USING DEPT NO:	504107	OPENED DATE:	06/07/2013 08:28:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2013 13:51:58	METER 1 - M:	11994	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2013 13:51:59	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	0.80	\$46.00	\$68.10	\$0.00	\$114.10

JOB COUNT: 1	WORK ORDER TOTAL:					0.80	46.00	68.10	0.00	114.10
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11074414	06/10/2013 06:00:00	06/10/2013 06:48:00	0.80	\$46.00
					LABOR	46.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	8C2Z1522405AD	LEFT OUTSIDE DOOR HANDLE	68.10	1	\$68.10
					PARTS	68.10

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 14083

Work Order Notes

(LPATE) LEFT OUTSIDE DOOR HANDLE IS BROKEN

Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(LPATE) RT. REMOVED THE DOOR HANDLE. SH. RPLACED DOOR HANDLE WORKING PROPERLY. USED 2 RIVETS TO SECURE DOOR HANDLE IN PLACE

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 15651

USING DEPT NO: 504107	OPENED DATE: 12/12/2013 09:16:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/12/2013 13:14:40	METER 1 - M: 13065 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/12/2013 13:14:40	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.65	\$44.84	\$0.00	\$80.49

JOB COUNT: 1	WORK ORDER TOTAL:	0.62	35.65	44.84	0.00	80.49
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11568366	12/12/2013 10:56:22	12/12/2013 11:14:58	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11397026	12/12/2013 10:56:14	12/12/2013 11:14:50	0.31	\$17.83
					LABOR	35.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
					PARTS	44.84

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 15651

Work Order Notes

(GMANNING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

(GMANNING) PM BY CA/BG

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 16999

USING DEPT NO: 504107	OPENED DATE: 05/19/2014 08:54:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/20/2014 06:48:31	METER 1 - M: 13842 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/20/2014 06:48:33	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250	2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.04	\$2.35	\$33.72	\$0.00	\$36.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$50.33	\$0.00	\$68.16

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.35** **20.18** **84.05** **0.00** **104.23**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/19/2014 10:38:24	05/19/2014 10:57:00	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/19/2014 09:27:17	05/19/2014 09:29:44	0.04	\$2.35
					LABOR	20.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	2	\$33.72
					PARTS	84.05

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 16999

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY SH/RS

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 18155

USING DEPT NO:	504107	OPENED DATE:	09/19/2014 10:35:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2014 06:55:44	METER 1 - M:	14466	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2014 06:55:45	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$34.55	\$45.47	\$0.00	\$80.02

JOB COUNT: 1	WORK ORDER TOTAL:					0.60	34.55	45.47	0.00	80.02
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/19/2014 11:21:00	09/19/2014 11:57:03	0.60	\$34.55
					LABOR	34.55

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
					PARTS	45.47

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 18155

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY NT/RS

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 19591

USING DEPT NO:	504107	OPENED DATE:	02/20/2015 08:30:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/24/2015 10:23:15	METER 1 - M:	15129	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/24/2015 10:23:18	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.96	\$112.48	\$45.47	\$0.00	\$157.95

JOB COUNT: 1	WORK ORDER TOTAL:	1.96	112.48	45.47	0.00	157.95
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/20/2015 13:00:00	02/20/2015 13:42:30	0.71	\$40.73
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/20/2015 10:45:08	02/20/2015 12:00:00	1.25	\$71.75
					LABOR	112.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
					PARTS	45.47

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 19591

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY SH/GM

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 20710

USING DEPT NO: 504107	OPENED DATE: 07/07/2015 08:43:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/09/2015 08:40:36	METER 1 - M: 157290 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/09/2015 08:40:37	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.39	\$22.20	\$91.52	\$0.00	\$113.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.98	\$56.32	\$29.53	\$0.00	\$85.85

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.37** **78.52** **121.05** **0.00** **199.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/07/2015 14:15:00	07/07/2015 14:48:12	0.55	\$31.81
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/07/2015 13:34:26	07/07/2015 14:00:00	0.43	\$24.50
03-32-002	REPLACE NEW BATTERY	11074414	07/07/2015 13:11:09	07/07/2015 13:34:19	0.39	\$22.20
					LABOR	78.51

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	65-850	BATTERY- FORD TOP POST HD	91.52	1	\$91.52
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.21	1	\$3.21
					PARTS	121.05

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 20710

Work Order Notes

(LPATE) PM-REPLACE BATTERY

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) BATTERY FAILED REPLACED BATTERY

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 22109

USING DEPT NO:	504107	OPENED DATE:	12/01/2015 08:27:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2015 06:58:40	METER 1 - M:	16528	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2015 06:58:43	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$36.82	\$30.30	\$0.00	\$67.12

JOB COUNT: 1 WORK ORDER TOTAL: 0.64 36.82 30.30 0.00 67.12

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	12/01/2015 08:56:23	12/01/2015 09:34:48	0.64	\$36.82
					LABOR	36.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					PARTS	30.30

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 22109

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 2339

USING DEPT NO:	504107	OPENED DATE:	11/10/2008 09:32:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2008 10:22:45	METER 1 - M:	3323	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/10/2008 10:22:46	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$31.38	\$0.00	\$49.21

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	31.38	0.00	49.21
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11128904	11/10/2008 10:00:00	11/10/2008 10:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
					PARTS	31.38

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 2339

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part FA1632 FILTER-AIR FORD Qty 1 Cost 0

Part 5W20 MOTOR OIL Qty 224 Cost 0

Part 51372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY CM

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 23529

USING DEPT NO: 504107	OPENED DATE: 05/27/2016 08:03:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/30/2016 06:38:25	METER 1 - M: 174483 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/30/2016 06:38:26	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.38	\$0.00	\$44.21

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **43.44** **0.00** **75.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11758845	05/27/2016 14:47:34	05/27/2016 15:02:34	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11758845	05/27/2016 14:46:30	05/27/2016 15:05:06	0.31	\$17.83
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	224	\$22.40
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	(2)	(\$17.06)
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
					PARTS	43.44

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 23529

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 25164

USING DEPT NO: 504107	OPENED DATE: 12/05/2016 08:06:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/09/2016 13:40:36	METER 1 - M: 18532 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/09/2016 13:40:37	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.08	\$62.18	\$48.30	\$0.00	\$110.48

JOB COUNT: 1	WORK ORDER TOTAL:	1.08	62.18	48.30	0.00	110.48
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/05/2016 09:15:00	12/05/2016 09:54:24	0.66	\$37.76
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/05/2016 08:34:31	12/05/2016 09:00:00	0.42	\$24.42
					LABOR	62.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	14.98	1	\$14.98
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	224	\$22.40
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					PARTS	48.30

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 25164

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY SH-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 27468

USING DEPT NO:	504107	OPENED DATE:	09/15/2017 10:59:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2017 08:36:50	METER 1 - M:	19818	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2017 08:36:53	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$19.25	\$17.42	\$0.00	\$36.67

JOB COUNT: 1	WORK ORDER TOTAL:	0.33	19.25	17.42	0.00	36.67
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/18/2017 11:19:17	09/18/2017 11:39:22	0.33	\$19.25
					LABOR	19.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					PARTS	17.42

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 27468

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY SH

CLEANED BATTERY CABLES

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 27625

USING DEPT NO:	504107	OPENED DATE:	09/28/2017 11:00:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/30/2017 08:19:12	METER 1 - M:	19818	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/30/2017 08:19:25	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-15-010	REPLACE NEW BALL JOINT	DON	O	N	GARAGE	3.80	\$218.50	\$131.28	\$0.00	\$349.78
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$68.99	\$68.99
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$46.00	\$4.24	\$0.00	\$50.24
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$589.67	\$589.67

JOB COUNT: 6	WORK ORDER TOTAL:	5.90	339.25	135.52	658.66	1,133.43
---------------------	--------------------------	-------------	---------------	---------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11321046	91101015826	0040573	\$589.67
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11321046	91101015844	0040616	\$68.99
COMML					658.66

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11758845	09/29/2017 07:00:00	09/29/2017 07:18:00	0.30	\$17.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	09/29/2017 07:18:00	09/29/2017 08:06:00	0.80	\$46.00
03-15-010	REPLACE NEW BALL JOINT	11213180	09/29/2017 07:00:00	09/29/2017 10:48:00	3.80	\$218.50
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	09/29/2017 13:46:21	09/29/2017 14:46:21	1.00	\$57.50
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	09/29/2017 13:46:21	09/29/2017 13:46:31	0.00	(\$0.16)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	09/29/2017 13:46:21	09/29/2017 13:46:31	0.00	\$0.16
LABOR					339.25	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ1030	BALL JOINT	35.48	2	\$70.96
03-15-010	REPLACE NEW BALL JOINT	TRWJBJ7025	BALL JOINT	30.16	2	\$60.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.40	4	\$1.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.24	11	\$2.64

Work Order Charge Detail

PARTS

135.52

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 27625

Work Order Notes

(LISAPATE) ARTHUR REQUESTED A SERVICE CALL TO FAC LOT FOR A FLAT TIRE

Job Notes

03-15-010 - REPLACE NEW BALL JOINT

(LISAPATE) MS REPLACED UPPER AND LOWER BALL JOINTS

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) TIRE ENGINEERS PERFORMED ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO TIRE ENGINEERS BY EK

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNTED AND BALANCED 4 NEW TIRES

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED. VAN NEEDS 4 TIRES

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 4 TIRES FROM TIRE ENGINEERS. PD BY CC

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 28525

USING DEPT NO:	504107	OPENED DATE:	01/05/2018 08:00:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/09/2018 07:09:18	METER 1 - M:	20153	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/09/2018 07:09:20	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$28.38	\$17.42	\$0.00	\$45.80

JOB COUNT: 1 WORK ORDER TOTAL: 0.49 28.38 17.42 0.00 45.80

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	01/05/2018 10:27:07	01/05/2018 10:56:44	0.49	\$28.38
					LABOR	28.38

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					PARTS	17.42

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 28525

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS

COOLANT -43'

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 29654

USING DEPT NO:	504107	OPENED DATE:	05/02/2018 08:35:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2018 11:44:55	METER 1 - M:	20615	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/14/2018 11:44:57	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$10.56	\$0.00	\$28.39

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	10.56	0.00	28.39
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/10/2018 07:00:00	05/10/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	0.94	7	\$6.58
					PARTS	10.56

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 29654

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS/AG

COOLANT -37'

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 29981

USING DEPT NO: 504107	OPENED DATE: 06/07/2018 11:19:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/13/2018 10:13:27	METER 1 - M: 20711 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/13/2018 10:13:28	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$23.00	\$4.71	\$0.00	\$27.71

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.65** **37.38** **21.77** **0.00** **59.15**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	06/13/2018 07:15:00	06/13/2018 07:39:00	0.40	\$23.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	06/13/2018 07:00:00	06/13/2018 07:15:00	0.25	\$14.38
					LABOR	37.38

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	3.77	1	\$3.77
66-17-030	PERFORM TIRE PATCH	21601	TR 600 HP WIDE VALVE STEM	0.40	1	\$0.40
					PARTS	21.77

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 29981

Work Order Notes

(RTUNAITI) Nail in LR tire
Wiper blades

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(IFALLS) AG REPLACED WIPER BLADES

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-030 - PERFORM TIRE PATCH

(IFALLS) AG PATCHED LR TIRE AND REBALANCED TIRE

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 30949

USING DEPT NO:	504107	OPENED DATE:	09/26/2018 08:18:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2018 07:42:34	METER 1 - M:	21242	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2018 07:42:36	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$0.00	\$27.29	\$0.00	\$27.29

JOB COUNT: 1	WORK ORDER TOTAL:	0.59	0.00	27.29	0.00	27.29
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/26/2018 09:30:00	09/26/2018 09:46:16	0.27	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/26/2018 08:56:10	09/26/2018 09:15:00	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.33	7	\$23.31
					PARTS	27.29

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 30949

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by AG/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 32759

USING DEPT NO:	504107	OPENED DATE:	04/29/2019 09:01:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/01/2019 08:08:19	METER 1 - M:	21971	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/01/2019 08:08:21	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$24.70	\$0.00	\$24.70

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	0.00	24.70	0.00	24.70
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/30/2019 06:00:00	04/30/2019 06:18:36	0.31	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	7	\$20.72

PARTS 24.70

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 32759

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by RC,EK/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 34138

USING DEPT NO:	504107	OPENED DATE:	09/18/2019 09:36:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2019 15:33:08	METER 1 - M:	22645	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2019 15:33:09	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.39	\$0.00	\$76.54	\$0.00	\$76.54
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.22	\$0.00	\$0.25	\$0.00	\$0.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$0.00	\$24.70	\$0.00	\$24.70
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4 WORK ORDER TOTAL: 3.51 0.00 101.49 0.00 101.49

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	09/21/2019 00:00:00	09/21/2019 02:00:00	2.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/18/2019 11:00:12	09/18/2019 11:31:51	0.53	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	09/18/2019 11:05:28	09/18/2019 11:28:51	0.39	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	09/18/2019 11:04:05	09/18/2019 11:16:59	0.22	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/18/2019 10:41:41	09/18/2019 11:04:05	0.37	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	75.70	1	\$75.70
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	912	BULB-BRAKE-3RD	0.25	1	\$0.25
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	7	\$20.72
					PARTS	101.49

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 34138

Work Order Notes

(LISAPATE) Battery dragging barely cranked-PM due

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery, added corrosion washers. Rechecked ok

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Replaced Left rear brake light

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by AG,SH/JW

Coolant -50'

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan Out- Ford IDS- P1000 Systems not ready. Test drove used as a chase vehicle. Light did not come back on

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 35322

USING DEPT NO:	504107	OPENED DATE:	01/07/2020 09:11:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/09/2020 06:37:51	METER 1 - M:	56024	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/09/2020 06:37:53	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.18	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.18	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	12052187	01/07/2020 09:20:35	01/07/2020 09:31:32	0.18	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 35322

Work Order Notes

(EKIMBREL) Install new 4G GPS

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(EKIMBREL) JW installed New GPS#5041361516
Old GPS#5014687322

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 36235

USING DEPT NO: 504107	OPENED DATE: 04/27/2020 08:35:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/27/2020 11:51:09	METER 1 - M: 23488 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/27/2020 15:10:45	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.30	\$0.00	\$17.06	\$0.00	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.91	\$0.00	\$31.21	\$0.00	\$31.21

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.21** **0.00** **48.27** **0.00** **48.27**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/27/2020 11:49:58	04/27/2020 12:07:58	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/27/2020 11:49:45	04/27/2020 12:08:21	0.31	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/27/2020 09:48:35	04/27/2020 10:24:45	0.60	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.89	7	\$27.23
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.88	(6)	(\$23.28)
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.88	6	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
					PARTS	48.27

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 36235

Work Order Notes

(IFALLS) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(IFALLS) SH replaced both wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULLSYN OIL BULK

Manufacturer :

Bin :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

Bin : D4D3

(IFALLS) SH/JW performed pm

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 37796

USING DEPT NO:	504107	OPENED DATE:	09/28/2020 09:54:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2020 11:28:23	METER 1 - M:	24189	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2020 12:25:54	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.22	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/28/2020 10:28:20	09/28/2020 10:41:27	0.22	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 37796

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 701 miles since last PM. Checked fluids,battery,tire pressure and updated oil change sticker. SH

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 38758

USING DEPT NO: 504107	OPENED DATE: 01/12/2021 09:20:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/13/2021 07:32:17	METER 1 - M: 24525 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/13/2021 14:15:23	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250	2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.55	\$65.33	\$120.41	\$0.00	\$185.74
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.14	\$17.08	\$0.00	\$0.00	\$17.08

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.70** **82.41** **120.41** **0.00** **202.82**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	01/12/2021 14:42:20	01/12/2021 15:15:33	0.55	\$65.33
66-79-002	PERFORM SERVICE CALL	12052187	01/12/2021 10:22:45	01/12/2021 10:31:26	0.14	\$17.08
					LABOR	82.41

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	BP19C	BATTERY TERMINAL-TOP POST REG	2.46	2	\$4.92
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	1.94	1	\$1.94
					PARTS	120.41

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 38758

Work Order Notes

(LISAPATE) Per Paul G unit is at Southlawn parking lot has a dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced new battery. Charging at 13.7 volts. JAW

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Jumped off and brought back to shop. Took battery off and put on charge. JAW

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 39073

USING DEPT NO: 504107	OPENED DATE: 02/10/2021 08:43:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/19/2021 11:00:21	METER 1 - M: 24650 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/19/2021 14:16:32	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-053	REPLACE NEW WINDOW REGULATOR	DON	O	N	GARAGE	1.65	\$194.67	\$106.25	\$0.00	\$300.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.44	\$37.76	\$0.00	\$106.20

JOB COUNT: 2 **WORK ORDER TOTAL:** **2.23** **263.11** **144.01** **0.00** **407.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/19/2021 09:56:02	02/19/2021 10:03:28	0.12	\$14.62
03-02-053	REPLACE NEW WINDOW REGULATOR	11170580	02/11/2021 14:30:00	02/11/2021 15:24:37	0.91	\$107.41
03-02-053	REPLACE NEW WINDOW REGULATOR	11170580	02/11/2021 13:30:38	02/11/2021 14:15:00	0.74	\$87.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2021 13:08:25	02/10/2021 13:35:47	0.46	\$53.82
					LABOR	263.10

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-053	REPLACE NEW WINDOW REGULATOR	ACI83114	POWER WINDOW MOTOR/REG	106.25	1	\$106.25
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
					PARTS	144.01

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 39073

Work Order Notes

(LISAPATE) PM-Driver window fell will not go back up

Job Notes

03-02-053 - REPLACE NEW WINDOW REGULATOR

(ABLACK) AB found drivers window regulator cable was broken. Installed a new drivers window regulator assembly. Rechecked ok.

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 24650 Performed PM top and bottom side, completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 3950

USING DEPT NO: 504107	OPENED DATE: 07/24/2009 14:38:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/24/2009 15:15:06	METER 1 - M: 46309 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/24/2009 15:15:08	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$31.38	\$0.00	\$49.21

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **62.28** **0.00** **94.49**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/24/2009 17:00:00	07/24/2009 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11088474	07/24/2009 17:18:36	07/24/2009 17:33:36	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
					PARTS	62.28

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 3950

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 51372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL-MOTOR Qty 224 Cost 0

Part FA1632 FILTER-AIR FORD Qty 1 Cost 0

(LPATE) PM BY JE

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 40486

USING DEPT NO: 504107	OPENED DATE: 07/21/2021 08:03:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/22/2021 09:52:09	METER 1 - M: 25478 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/22/2021 14:32:14	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.18	\$21.80	\$14.67	\$0.00	\$36.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$26.65	\$0.00	\$0.00	\$26.65

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.41** **48.45** **14.67** **0.00** **63.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/21/2021 08:13:14	07/21/2021 08:26:47	0.23	\$26.65
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2021 08:14:19	07/21/2021 08:25:24	0.18	\$21.80
					LABOR	48.45

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.34	2	\$14.67
					PARTS	14.67

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 40486

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 25478 Vehicle has been 828 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG SH

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 41918

USING DEPT NO: 504107	OPENED DATE: 12/16/2021 08:16:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2021 14:20:29	METER 1 - M: 26294 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/17/2021 09:07:24	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BI	DON	P	N	GARAGE	0.13	\$15.73	\$0.00	\$0.00	\$15.73
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.23	\$15.18	\$0.00	\$17.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.35	\$39.98	\$0.00	\$64.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.36	42.31	55.16	2.00	99.47
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	12052187	12/16/2021 10:18:07	12/16/2021 10:26:07	0.13	\$15.73
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/16/2021 10:02:33	12/16/2021 10:14:56	0.21	\$24.35
03-51-038	REPLACE NEW WIPER BLADES	12052187	12/16/2021 10:01:15	12/16/2021 10:02:23	0.02	\$2.23
					LABOR	42.31

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	8.90	1	\$8.90
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
					PARTS	55.16

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 41918

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-34-020 - REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY

(JWRIGHT) Left 3rd brake light bulb was loose. Fixed connection found no other issue

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° JAW/SH
MILEAGE-26294

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 43131

USING DEPT NO: 504107	OPENED DATE: 05/04/2022 08:21:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/11/2022 14:20:56	METER 1 - M: 26980 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/18/2022 14:03:42	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.83	\$97.84	\$0.00	\$0.00	\$97.84
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.67	\$15.18	\$0.00	\$18.85
06-02-055	INSPECT DOOR LATCH/STRIKER	DON	O	N	GARAGE	0.01	\$1.21	\$378.20	\$0.00	\$379.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.68	\$0.00	\$0.00	\$24.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.08	127.40	393.38	2.00	522.78
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	12052187	05/10/2022 12:14:38	05/10/2022 12:32:54	0.30	\$35.92
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	12052187	05/10/2022 10:18:55	05/10/2022 10:50:24	0.52	\$61.92
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2022 13:26:34	05/04/2022 13:39:07	0.21	\$24.68
06-02-055	INSPECT DOOR LATCH/STRIKER	12052187	05/04/2022 13:41:33	05/04/2022 13:42:10	0.01	\$1.21
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/04/2022 13:39:21	05/04/2022 13:41:13	0.03	\$3.67
					LABOR	127.40

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-055	INSPECT DOOR LATCH/STRIKER	8C2Z15431A03A	LOWER LATCH W/HANDLE	71.82	1	\$71.82
06-02-055	INSPECT DOOR LATCH/STRIKER	AC2Z15264A26B	REAR LATCH ASSY	65.43	1	\$65.43
06-02-055	INSPECT DOOR LATCH/STRIKER	8C2Z15264A00D	DOOR LATCH CABLE	64.62	1	\$64.62
06-02-055	INSPECT DOOR LATCH/STRIKER	6C2Z15264A01AA	LATCH	97.59	1	\$97.59
06-02-055	INSPECT DOOR LATCH/STRIKER	6C2Z1543286AA	UPPER DOOR LATCH	78.74	1	\$78.74
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
					PARTS	393.38

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 43131

Work Order Notes

(LISAPATE) PM-replace wipers-side doors will not open

Job Notes

03-02-055 - REPLACE NEW DOOR LATCH/STRIKER

(JWRIGHT) Replaced cables and latches on both side cargo doors and amg assisted on replacing cables and latches on the rear left door. All doors and locks are operating correctly. JAW

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

06-02-055 - INSPECT DOOR LATCH/STRIKER

(JWRIGHT) Both cargo side door cables are bad and left rear door cables are bad. Ordering all cable kits

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 457 miles since last pm. Updated sticker and checked fluids. Coolant -34°. JAW
MILEAGE-26751

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 4327

USING DEPT NO: 504107	OPENED DATE: 09/18/2009 10:41:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/21/2009 09:19:46	METER 1 - M: 47690 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/21/2009 09:19:48	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-17-011	INSTALL TIRE PLUG	DON	O	N	GARAGE	0.40	\$23.00	\$0.00	\$0.00	\$23.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.40** **23.00** **0.00** **0.00** **23.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-17-011	INSTALL TIRE PLUG	11274660	09/18/2009 17:00:00	09/18/2009 17:24:00	0.40	\$23.00
14-17-015	INSTALL TIRE ROTATION	11274660	09/18/2009 17:00:00	09/18/2009 17:24:00	(0.40)	(\$23.00)
14-17-015	INSTALL TIRE ROTATION	11274660	09/18/2009 17:00:00	09/18/2009 17:24:00	0.40	\$23.00
					LABOR	23.00

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 4327

Work Order Notes

(LPATE) LEFT REAR TIRE HAS A HOLE IN IT

Job Notes

14-17-011 - INSTALL TIRE PLUG

(LPATE) PLUGGED LEFT REAR TIRE

14-17-015 - INSTALL TIRE ROTATION

(LPATE) PLUGGED LEFT REAR TIRE

(LPATE) CANCELLED JOB WRONG DESCRIPTION

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 44297

USING DEPT NO: 504107	OPENED DATE: 08/15/2022 13:00:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/19/2022 11:30:57	METER 1 - M: 268084 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/22/2022 09:01:50	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-32-002	INSPECT BATTERY	DON	P	N	GARAGE	1.20	\$141.93	\$0.00	\$0.00	\$141.93
CH-32-002	CHARGE BATTERY	DON	P	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.35	159.63	0.00	2.00	161.63
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32-002	INSPECT BATTERY	12296277	08/16/2022 08:02:13	08/16/2022 09:14:23	1.20	\$141.93
CH-32-002	CHARGE BATTERY	12296277	08/19/2022 07:00:00	08/19/2022 07:09:00	0.15	\$17.70
LABOR					159.63	

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 44297

Work Order Notes

(LISAPATE) dead battery per dept please check

Job Notes

06-32-002 - INSPECT BATTERY

(CWIGLEY) Check battery. The driver said they keep having to jump it off.

CH-32-002 - CHARGE BATTERY

(EKIMBREL) jm charged battery
(IFALLS) alternator charging at 13.5 volts

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 44631

USING DEPT NO: 504107	OPENED DATE: 09/09/2022 08:22:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/12/2022 10:28:48	METER 1 - M: 268084 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/12/2022 13:08:27	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.27	\$52.49	\$0.00	\$91.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.33** **39.27** **52.49** **5.00** **96.76**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/09/2022 13:41:03	09/09/2022 14:01:01	0.33	\$39.27
LABOR						39.27

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	7	\$42.63
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.86	1	\$9.86
PARTS						52.49

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 44631

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 26835 Completed PM top and bottom side. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 45713

USING DEPT NO: 504107	OPENED DATE: 01/09/2023 08:47:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/09/2023 14:56:07	METER 1 - M: 26903 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/10/2023 08:01:10	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	5	N	GARAGE	0.15	\$17.70	\$113.55	\$0.00	\$131.25
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.46	\$15.63	\$0.00	\$20.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$5.31	\$0.00	\$0.00	\$5.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.23	27.47	129.18	5.00	161.65
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/09/2023 09:34:52	01/09/2023 09:37:08	0.04	\$4.46
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/09/2023 09:30:00	01/09/2023 09:32:42	0.05	\$5.31
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/09/2023 09:14:15	01/09/2023 09:14:15	0.00	\$0.00
03-32-002	REPLACE NEW BATTERY	12201267	01/09/2023 09:16:58	01/09/2023 09:16:58	0.00	\$0.00
03-32-002	REPLACE NEW BATTERY	12201267	01/09/2023 09:16:58	01/09/2023 09:16:58	0.00	\$0.00
03-32-002	REPLACE NEW BATTERY	12201267	01/09/2023 09:16:58	01/09/2023 09:25:58	0.15	\$17.70
LABOR					27.47	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.27	7	\$43.89
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.85	1	\$5.85
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.85	(1)	(\$5.85)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.27	(7)	(\$43.89)
PARTS					129.18	

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 45713

Work Order Notes

(EHANNAH) PM- replace wipers
charge battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) replaced battery-GC 1-9-23

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 26903 Vehicle has been 68 miles, oil was changed at last PM. Checked fluids, battery and tires. UpdATED

(AGUERRA) Updated oil change sticker. AMG

CH-32-002 - CHARGE BATTERY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 46779

USING DEPT NO:	504107	OPENED DATE:	04/20/2023 10:31:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2023 11:14:33	METER 1 - M:	26928	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2023 13:07:31	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.04	\$4.82	\$0.00	\$0.00	\$4.82
CH-32-002	CHARGE BATTERY	DON	P	N	GARAGE	0.07	\$8.62	\$0.00	\$0.00	\$8.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.11	13.44	0.00	5.00	18.44
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11074414	04/21/2023 07:24:40	04/21/2023 07:29:03	0.07	\$8.62
06-32-002	INSPECT BATTERY	11074414	04/21/2023 07:22:01	04/21/2023 07:24:28	0.04	\$4.82
LABOR					13.44	

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 46779

Work Order Notes

(EHANNAH) do SI - wash- dead battery

Job Notes

06-32-002 - INSPECT BATTERY

(SHARBIN) CW Pulled the battery out and put it on charge. SH

66-79-003 - PERFORM SAFETY INSPECTION

CH-32-002 - CHARGE BATTERY

(SHARBIN) Battery was charged and rechecked good. Reinstalled the battery ALT charging at 14.3 volts. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 47565

USING DEPT NO: 504107	OPENED DATE: 07/11/2023 08:07:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/12/2023 14:35:36	METER 1 - M: 26982 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/13/2023 08:09:26	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.08	\$16.65	\$0.00	\$21.73
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.88	\$103.58	\$0.00	\$0.00	\$103.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.27	\$49.62	\$0.00	\$82.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.02	\$2.36	\$0.00	\$0.00	\$2.36

JOB COUNT: 5	WORK ORDER TOTAL:	1.22	144.29	66.27	5.00	215.56
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	07/11/2023 10:48:26	07/11/2023 10:49:38	0.02	\$2.36
66-79-003	PERFORM SAFETY INSPECTION	12201267	07/11/2023 09:55:46	07/11/2023 10:48:26	0.88	\$103.58
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/11/2023 09:52:58	07/11/2023 09:55:33	0.04	\$5.08
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/11/2023 09:30:00	07/11/2023 09:46:55	0.28	\$33.27
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/11/2023 09:24:29	07/11/2023 09:24:29	0.00	\$0.00
LABOR					144.29	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	(6)	(\$37.53)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	7	\$43.68
PARTS					66.27	

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 47565

Work Order Notes

(EHANNAH) pm- replace wipers- wash - Do SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC

Brake pads are Front6mm and Rear 6mm

Note: Tires are out of date , but the tread depts are good, spoke with lisa and going to let it go until next time-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filter good, tires and tire pressure.

Note: Tires are out of date, spoke with Lisa and tread depts are good, going to let it go until next time.

Miles, 26,982

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed vehicle-GC

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 47955

USING DEPT NO: 504107	OPENED DATE: 08/23/2023 07:50:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2023 12:37:39	METER 1 - M: 26982 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/25/2023 12:37:43	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.07	\$8.23	\$188.82	\$0.00	\$197.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.07 8.23 188.82 5.00 202.05

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12201267	08/23/2023 08:15:41	08/23/2023 08:19:52	0.07	\$8.23
LABOR						8.23

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	188.82	1	\$188.82
PARTS						188.82

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 47955

Work Order Notes

(EHANNAH) check battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GRCOOK) Replaced battery on vehicle, tested battery and battery CCA tested low and said replace battery. Installed new battery and checked volts, 13.89 volts-GC

06-32-002 - INSPECT BATTERY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 49175

USING DEPT NO: 504107	OPENED DATE: 12/07/2023 14:18:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/14/2023 07:50:17	METER 1 - M: 27044 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/14/2023 14:20:24	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	O	N	GARAGE	0.02	\$2.23	\$0.00	\$0.00	\$2.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.11	\$13.11	\$0.14	\$0.00	\$13.25

JOB COUNT: 3	WORK ORDER TOTAL:	0.13	15.34	0.14	5.00	20.48
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	12/13/2023 09:31:53	12/13/2023 09:38:33	0.11	\$13.11
25-52-021	REMOVE GPS SYSTEM	11915538	12/13/2023 09:39:57	12/13/2023 09:41:05	0.02	\$2.23
					LABOR	15.34

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	1	\$0.14
					PARTS	0.14

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 49175

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) removed GPS# 5071361516\ CW

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\ CW\RC

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 5944

USING DEPT NO: 504107	OPENED DATE: 06/01/2010 07:30:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/02/2010 07:07:56	METER 1 - M: 52098 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/02/2010 07:07:58	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.70	\$40.25	\$68.93	\$0.00	\$109.18
24-02-023	REPAIR HANDLES - INNER & OUTER	DON	O	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$42.48	\$0.00	\$60.31

JOB COUNT: 3	WORK ORDER TOTAL:	1.31	75.33	111.41	0.00	186.74
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	06/01/2010 17:00:00	06/01/2010 17:18:36	0.31	\$17.83
24-02-023	REPAIR HANDLES - INNER & OUTER	11328035	06/01/2010 18:00:36	06/01/2010 18:18:36	0.30	\$17.25
03-02-010	REPLACE NEW MIRRORS	11328035	06/01/2010 17:18:36	06/01/2010 18:00:36	0.70	\$40.25
					LABOR	75.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	4C2Z17K707C	RH MIRROR GLASS	68.93	1	\$68.93
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.45	1	\$14.45
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
					PARTS	111.41

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 5944

Work Order Notes

(LPATE) RIGHT OUTSIDE LOWER MIRROR BROKEN-PM-REPAIR CARGO DOOR ON RIGHT SIDE

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(LPATE) REPLACED RIGHT OUTSIDE MIRROR

24-02-023 - REPAIR HANDLES - INNER & OUTER

(LPATE) INSTALLED SCREW IN RIGHT CARGO DOOR HANDLE

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 51372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY TM-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 6014

USING DEPT NO:	504107	OPENED DATE:	06/14/2010 14:20:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2010 06:22:52	METER 1 - M:	52098	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2010 06:22:54	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.30	\$17.25	\$63.45	\$0.00	\$80.70

JOB COUNT: 1	WORK ORDER TOTAL:					0.30	17.25	63.45	0.00	80.70
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	11328035	06/14/2010 17:00:00	06/14/2010 17:18:00	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	4C2Z17K707B	LEFT OUTSIDE MIRROR	63.45	1	\$63.45
					PARTS	63.45

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 6014

Work Order Notes

(LPATE) LEFT OUTSIDE MIRROR BROKEN

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(LPATE) REPLACED LEFT OUTSIDE MIRROR

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 6412

USING DEPT NO: 504107	OPENED DATE: 08/03/2010 15:31:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/04/2010 07:09:27	METER 1 - M: 58111 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/04/2010 07:09:29	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250		UNIT SERIAL NO: 1FTNE24W46DB30625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-003	REPLACE NEW RUNNING BOARDS	DON	O	N	GARAGE	1.00	\$57.50	\$609.37	\$0.00	\$666.87

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	609.37	0.00	666.87
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-003	REPLACE NEW RUNNING BOARDS	11328035	08/03/2010 17:00:00	08/03/2010 18:00:00	1.00	\$57.50
03-02-003	REPLACE NEW RUNNING BOARDS	11328035	08/03/2010 17:00:00	08/03/2010 18:30:00	(1.50)	(\$86.25)
03-02-003	REPLACE NEW RUNNING BOARDS	11328035	08/03/2010 17:00:00	08/03/2010 18:30:00	1.50	\$86.25
					LABOR	57.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-003	REPLACE NEW RUNNING BOARDS	2C2Z16450AAA	RUNNING BOARDS	609.37	1	\$609.37
					PARTS	609.37

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 6412

Work Order Notes

(LPATE) MARY REQUESTED RUNNING BOARDS BE INSTALLED ON VAN

Job Notes

03-02-003 - REPLACE NEW RUNNING BOARDS

(LPATE) INSTALLED RUNNING BOARDS ON BOTH SIDES OF VAN

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 6743

USING DEPT NO:	504107	OPENED DATE:	09/13/2010 07:00:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/13/2010 08:05:37	METER 1 - M:	59535	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/13/2010 08:05:39	IN-SERVICE DATE:	10/09/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.02	\$0.00	\$45.85

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	28.02	0.00	45.85
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/13/2010 07:00:00	09/13/2010 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.50	1	\$4.50
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
					PARTS	28.02

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 6743

Work Order Notes

(RWINTERS) PM
(RWINTERS) MILES SHOULD BE 6,030

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0
Part 5W20 OIL BOTTLE Qty 224 Cost 0
Part 6418 FILTER-AIR Qty 1 Cost 0
(RWINTERS) PM BY RS/TM

Work Order Charge Detail

UNIT NO: 237174 **2006 FORD E250**

WORK ORDER NO: 9491

USING DEPT NO: 504107	OPENED DATE: 10/25/2011 08:56:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/26/2011 11:14:32	METER 1 - M: 88506 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/26/2011 11:14:34	IN-SERVICE DATE: 10/09/2006
TECH SPEC NO: 06VNFORDE250 2006 Ford E250	UNIT SERIAL NO: 1FTNE24W46DB30625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$83.52	\$0.00	\$112.27
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$38.22	\$0.00	\$52.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.23	\$0.00	\$46.06

JOB COUNT: 3	WORK ORDER TOTAL:	1.06	60.96	149.97	0.00	210.93
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/25/2011 17:00:00	10/25/2011 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/25/2011 17:00:00	10/25/2011 17:15:00	0.25	\$14.38
03-32-002	REPLACE NEW BATTERY	11074414	10/25/2011 17:15:00	10/25/2011 17:45:00	0.50	\$28.75
					LABOR	60.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.71	1	\$4.71
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.52	1	\$14.52
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.52	(1)	(\$14.52)
03-32-002	REPLACE NEW BATTERY	65A	BATTERY TOP POST FORD	83.52	1	\$83.52
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.11	2	\$38.22
					PARTS	149.97

Work Order Charge Detail

UNIT NO: 237174 2006 FORD E250

WORK ORDER NO: 9491

Work Order Notes

(LPATE) PM-REPLACE WIPERS-REPLACE BATTERY TRIED TO CHARGE STILL FAILED

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY SH

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Dec 14 2023 15:08:12 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no_alt} = 'S5802B') //Q=