

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 10295

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 02/10/2012 08:58:49	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/13/2012 13:14:31	<b>METER 1 - M:</b> 36672 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/13/2012 13:14:31	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$1.56	\$0.00	\$18.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$37.84	\$0.00	\$55.67

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.61** **35.08** **39.40** **0.00** **74.48**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11338644	02/10/2012 17:18:36	02/10/2012 17:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11338644	02/10/2012 17:00:00	02/10/2012 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>35.08</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.69	1	\$4.69
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	1.56	1	\$1.56
					<b>PARTS</b>	<b>39.40</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 10295

---

**Work Order Notes**

(LPATE) PM-LEFT REAR TURN SIGNAL IS OUT

---

**Job Notes**

**03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC**

(LPATE) REPLACED LEFT REAR TURN SIGNAL

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY RS/GM-REPLACED OIL DRAIN PLUG

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 10761

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 04/16/2012 08:47:37	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/18/2012 15:03:02	<b>METER 1 - M:</b> 38092 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/18/2012 15:03:04	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-025	REPLACE NEW GLASS CHANNELS	DON	O	N	GARAGE	3.46	\$199.22	\$111.31	\$0.00	\$310.53
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	0.54	\$31.24	\$190.21	\$0.00	\$221.45
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	0.60	\$34.23	\$0.00	\$0.00	\$34.23
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 4** **WORK ORDER TOTAL:** 5.10 293.44 301.52 0.00 594.96

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	04/17/2012 08:40:45	04/17/2012 09:13:21	0.54	\$31.24
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11397026	04/17/2012 09:13:35	04/17/2012 09:15:00	0.02	\$1.36
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11397026	04/17/2012 09:30:00	04/17/2012 10:04:18	0.57	\$32.87
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/18/2012 07:00:00	04/18/2012 09:00:00	2.00	\$115.00
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/18/2012 07:00:00	04/18/2012 09:00:00	(2.00)	(\$115.00)
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/17/2012 13:35:06	04/17/2012 14:15:00	0.67	\$38.24
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/17/2012 14:30:00	04/17/2012 16:15:00	1.75	\$100.63
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/17/2012 14:30:00	04/18/2012 09:15:00	18.75	\$1,078.13
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/17/2012 14:30:00	04/18/2012 09:15:00	(18.75)	(\$1,078.13)
03-02-025	REPLACE NEW GLASS CHANNELS	11397026	04/18/2012 09:30:00	04/18/2012 10:32:59	1.05	\$60.36
06-13	INSPECT BRAKES	11397026	04/18/2012 07:00:00	04/18/2012 07:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>293.45</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	4.91	1	\$4.91
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	2.64	1	\$2.64
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABATD655M	FRONT BRAKE PADS	94.99	1	\$94.99
03-02-025	REPLACE NEW GLASS CHANNELS	F2UZ15222A01A	GLASS CHANNEL	54.82	1	\$54.82
03-02-025	REPLACE NEW GLASS CHANNELS	F2UZ15222A00A	GLASS CHANNEL	56.49	1	\$56.49

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABATD802M	BRAKE PADS	87.67	1	\$87.67
<b>PARTS</b>						<b>301.52</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 10761

---

## Work Order Notes

(LPATE) BOTH FRONT WINDOWS HEARD TO ROLL UP AND DOWN-BRAKES ARE SCRUBBING BAD.

---

## Job Notes

### **03-02-025 - REPLACE NEW GLASS CHANNELS**

(LPATE) REPLACED BOTH FRONT LOWER WINDOW GLASS CHANNELS.

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(LPATE) REPLACED FRONT PADS AND TURNED ROTORS.

### **03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(LPATE) REPLACED REAR PADS AND TURNED ROTORS

### **06-13 - INSPECT BRAKES**

(LPATE) TEST DROVE CHECKED BRAKES NEEDS FRONT AND REAR PADS.

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 10943

USING DEPT NO:	504104	OPENED DATE:	05/03/2012 09:54:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2012 14:10:11	METER 1 - M:	38343	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2012 14:10:14	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-55-041	REPAIR LADDER RACK	DON	O	N	GARAGE	0.00	\$0.00	\$192.00	\$0.00	\$192.00

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>192.00</b>	<b>0.00</b>	<b>192.00</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-55-041	REPAIR LADDER RACK	856-01	LADDER RACK HINGES	96.00	2	\$192.00
					<b>PARTS</b>	<b>192.00</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 10943

---

**Work Order Notes**

(LPATE) STEVEN REQUESTED 2 NEW LADDER RACK HINGES FOR THIS VAN.

---

**Job Notes**

**24-55-041 - REPAIR LADDER RACK**

(LPATE) GAVE STEVEN 2 LADDER RACK HINGES

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 11552

USING DEPT NO:	504104	OPENED DATE:	08/06/2012 09:13:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2012 07:56:00	METER 1 - M:	40753	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2012 07:56:02	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.33	\$0.00	\$62.16

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 44.33 0.00 62.16

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	08/06/2012 17:00:00	08/06/2012 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
					<b>PARTS</b>	<b>44.33</b>



# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 11552

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

(LPATE) PM BY GM/RS

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12034

USING DEPT NO:	504104	OPENED DATE:	10/03/2012 08:22:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/03/2012 14:21:59	METER 1 - M:	42210	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/03/2012 14:22:02	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$1.57	\$0.00	\$18.82

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.30</b>	<b>17.25</b>	<b>1.57</b>	<b>0.00</b>	<b>18.82</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	10/03/2012 17:00:00	10/03/2012 17:18:00	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	1.57	1	\$1.57
					<b>PARTS</b>	<b>1.57</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12034

---

**Work Order Notes**

(LPATE) PER DRIVER RIGHT BLINKER IS OUT

---

**Job Notes**

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LPATE) REPLACED RIGHT REAR TURN SIGNAL

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 12204

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 10/23/2012 08:01:08	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/25/2012 07:52:48	<b>METER 1 - M:</b> 42785 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/25/2012 07:52:52	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$395.45	\$395.45
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.00</b>	<b>115.00</b>	<b>0.00</b>	<b>395.45</b>	<b>510.45</b>
---------------------	--------------------------	-------------	---------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	D228363	0017757	\$395.45
					<b>COMML 395.45</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11338644	10/23/2012 11:32:20	10/23/2012 12:32:20	1.00	\$57.50
66-79-002	PERFORM SERVICE CALL	11338644	10/23/2012 11:32:14	10/23/2012 12:32:14	1.00	\$57.50
					<b>LABOR</b>	<b>115.00</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12204

---

## Work Order Notes

(LPATE) GLENN REQUESTED SERVICE CALL TO 2ND AVE RIGHT REAR TIRE IS FLAT. INSTALL 2 NEW FRONT TIRES AND ALIGN

---

## Job Notes

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) GOODYEAR INSTALLED 2 NEW TIRES AND ALIGNED. P0042364

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO GODYEAR BY RS

### **66-79-002 - PERFORM SERVICE CALL**

(LPATE) SERVICE CALL TO 2ND AVE INSTALLED SPARE ON VAN DRIVER WILL BRING TO GARAGE TO HAVE TIRE REPLACED.

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12362

USING DEPT NO:	504104	OPENED DATE:	11/12/2012 08:47:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/13/2012 07:39:42	METER 1 - M:	43348	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/13/2012 07:39:44	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-53-024	PURCHASED DISTILLED WATER	DON	O	N	GARAGE	0.00	\$0.00	\$3.96	\$0.00	\$3.96

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>3.96</b>	<b>0.00</b>	<b>3.96</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-53-024	PURCHASED DISTILLED WATER	WATER	DISTILLED WATER	1.32	3	\$3.96
					<b>PARTS</b>	<b>3.96</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 12362

---

**Work Order Notes**

(LPATE) DRIVER REQUESTED 3 GAL DISTILLED WATER

---

**Job Notes**

**PU-53-024 - PURCHASED DISTILLED WATER**

(LPATE) GAVE DRIVER 3 GAL WATER

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 12454

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 11/29/2012 07:57:50	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/30/2012 09:14:21	<b>METER 1 - M:</b> 43553 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/30/2012 09:14:22	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 1</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>



# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12454

---

**Work Order Notes**

(LPATE) PER DRIVER HEARING A GRINDING NOISE FROM FRONT LEFT WHEEL AREA WHEN TURNING

---

**Job Notes**

**06-13 - INSPECT BRAKES**

(LPATE) CHECKED BRAKES, FOUND LEFT FRONT HAS A GRINDING SOUND. BRAKE PEDAL CLIP WASNT SEATED GOOD, ADJUSTED CLIP, RETESTED OK BRAKE PADS LIKE NEW. TEST DROVE OK.

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 12503

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 12/05/2012 09:53:49	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/12/2012 10:05:09	<b>METER 1 - M:</b> 43553 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 12/12/2012 10:05:11	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	0.90	\$51.65	\$623.96	\$0.00	\$675.61
03-15-010	REPLACE NEW BALL JOINT	DON	O	N	GARAGE	1.93	\$110.77	\$255.36	\$0.00	\$366.13
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$73.13	\$73.13
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.01	\$0.53	\$0.00	\$0.00	\$0.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$1.98	\$49.69	\$0.00	\$51.67

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>2.87</b>	<b>164.93</b>	<b>929.01</b>	<b>73.13</b>	<b>1,167.07</b>
---------------------	--------------------------	-------------	---------------	---------------	--------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11075943	D229100	0018259	\$73.13
				<b>COMML</b>	<b>73.13</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-010	REPLACE NEW BALL JOINT	11397026	12/06/2012 07:01:31	12/06/2012 08:57:06	1.93	\$110.77
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	12/06/2012 08:57:13	12/06/2012 09:15:00	0.30	\$17.04
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	12/06/2012 09:30:00	12/06/2012 10:06:07	0.60	\$34.61
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10260422	12/07/2012 14:01:26	12/07/2012 14:01:59	0.01	\$0.53
66-PM-PMA	PERFORM OIL CHANGE	10260422	12/07/2012 14:01:59	12/07/2012 14:04:03	0.03	\$1.98
				<b>LABOR</b>		<b>164.93</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.19	1	\$5.19
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF24000	GREASE SEAL	12.69	2	\$25.38
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB66528	FRONT HUB/ROTOR ASSY	211.23	2	\$422.46
03-15-010	REPLACE NEW BALL JOINT	SPI5001074	UPPER BALLJOINT	45.20	2	\$90.39
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	22.98	2	\$45.96

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-010	REPLACE NEW BALL JOINT	SPI5051160	LOWER BALLJOINT	82.49	2	\$164.97
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	19.02	2	\$38.04
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15245	BEARINGS	7.49	2	\$14.97
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABATD655SV	HEAVY DUTY BRAKE PADS	77.15	1	\$77.15
					<b>PARTS</b>	<b>929.01</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12503

---

## Work Order Notes

(LPATE) PM, REPLACE FRONT BRAKES/ROTORS, REPLACE BALL JOINTS.

---

## Job Notes

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(LPATE) REPLACED NEW FRONT PADS AND ROTORS. ALSO REPLACED BEARINGS AND SEALS ON BOTH SIDES.

### **03-15-010 - REPLACE NEW BALL JOINT**

(LPATE) REPLACED UPPER AND LOWER BALL JOINTS ON BOTH SIDES.

### **09-17 - ALIGN TIRES, TUBES, LINERS & VALVES**

(LPATE) GOODYEAR COMPLETED ALIGNMENT AFTER BALL JOINTS REPLACED. P0042865.

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO GOODGEAR BY BG

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY GM

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12770

USING DEPT NO:	504104	OPENED DATE:	01/14/2013 10:08:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/14/2013 13:32:44	METER 1 - M:	44640	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/14/2013 13:32:45	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-33-004	PURCHASED SPARK PLUGS	DON	O	N	GARAGE	0.00	\$0.00	\$2.77	\$0.00	\$2.77

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>2.77</b>	<b>0.00</b>	<b>2.77</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-33-004	PURCHASED SPARK PLUGS	NGK6535	SPARK PLUG	2.77	1	\$2.77
					<b>PARTS</b>	<b>2.77</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 12770

---

**Work Order Notes**

(GMANNING) NEED SPARK PLUG FOR A PORTABLE GENERATOR.

---

**Job Notes**

**PU-33-004 - PURCHASED SPARK PLUGS**

(GMANNING) PURCHASED SPARK PLUG FOR PORTABLE GENERATOR AND BILLED IT THROUGH THIS VEHICLE.

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 13465

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 04/08/2013 13:22:52	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/09/2013 07:40:16	<b>METER 1 - M:</b> 46685 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/09/2013 07:40:18	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
05-34-011	REPLACE USED TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	0.00	\$0.00	\$37.50	\$0.00	\$37.50

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.00 0.00 37.50 0.00 37.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
05-34-011	REPLACE USED TAILLIGHT ASSEMBLY	USED TAILLIGHT	USED TAILLIGHT	37.50	1	\$37.50
05-34-011	REPLACE USED TAILLIGHT ASSEMBLY	USED TAILLIGHT	USED TAILLIGHT	37.50	(1)	(\$37.50)
05-34-011	REPLACE USED TAILLIGHT ASSEMBLY	USED TAILLIGHT	USED TAILLIGHT	37.50	1	\$37.50
					<b>PARTS</b>	<b>37.50</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 13465

---

**Work Order Notes**

(LPATE) DRIVER TAILLIGHT ON RIGHT SIDE IS BROKEN.

---

**Job Notes**

**05-34-011 - REPLACE USED TAILLIGHT ASSEMBLY**

(LPATE) SWAPPED RIGHT REAR BROKEN TAILLIGHTS WITH DRIVER DUE TO LENS WAS BROKEN. REMOVED FROM 2004 SALVAGE VAN PROPERTY# 234769

---



# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 13760

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 05/07/2013 09:54:48	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/08/2013 09:35:29	<b>METER 1 - M:</b> 47424 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/08/2013 09:35:31	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$22.79	\$57.31	\$0.00	\$80.10

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.90**      **51.54**      **57.31**      **0.00**      **108.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/07/2013 10:57:55	05/07/2013 11:21:42	0.40	\$22.79
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/07/2013 14:49:41	05/07/2013 15:19:41	0.50	\$28.75
					<b>LABOR</b>	<b>51.54</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.53	1	\$5.53
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 20OZ FUEL ADDITIVE	12.09	1	\$12.09
					<b>PARTS</b>	<b>57.31</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 13760

---

**Work Order Notes**

(LPATE) PM-ROTATE TIRES

---

**Job Notes**

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LPATE) ROTATED TIRES

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.46

(LPATE) PM BY SH

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 14552

USING DEPT NO:	504104	OPENED DATE:	08/06/2013 09:48:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/07/2013 06:30:20	METER 1 - M:	49902	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/07/2013 06:30:22	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-17-011	INSTALL TIRE PLUG	DON	O	N	GARAGE	0.40	\$23.00	\$0.00	\$0.00	\$23.00

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.40</b>	<b>23.00</b>	<b>0.00</b>	<b>0.00</b>	<b>23.00</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-17-011	INSTALL TIRE PLUG	11338644	08/06/2013 09:48:53	08/06/2013 10:12:53	0.40	\$23.00
					<b>LABOR</b>	<b>23.00</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 14552

---

**Work Order Notes**

(LPATE) PER DRIVER NAIL IN RF TIRE

---

**Job Notes**

14-17-011 - INSTALL TIRE PLUG

(LPATE) PLUGGED RIGHT FRONT TIRE

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 15026

USING DEPT NO:	504104	OPENED DATE:	10/03/2013 10:57:43	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	10/04/2013 10:59:25	METER 1 - M:	51377	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/04/2013 10:59:27	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$61.81	\$0.00	\$79.64

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 61.81 0.00 79.64

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11338644	10/04/2013 07:00:00	10/04/2013 07:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 20OZ FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
					<b>PARTS</b>	<b>61.81</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 15026

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM/RS

---

# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 15338

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 11/07/2013 09:57:09	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/11/2013 11:05:10	<b>METER 1 - M:</b> 51474 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/11/2013 11:05:14	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$336.71	\$336.71
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$78.19	\$78.19
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.00</b>	<b>115.00</b>	<b>0.00</b>	<b>414.90</b>	<b>529.90</b>
---------------------	--------------------------	-------------	---------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11531907	4341006156	0021798	\$336.71
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11122732	170346	0021799	\$78.19
				<b>COMML</b>	<b>414.90</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11074414	11/08/2013 06:00:00	11/08/2013 08:00:00	2.00	\$115.00
					<b>LABOR</b>	<b>115.00</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 15338

---

**Work Order Notes**

(GMANNING) NEEDS TWO NEW TIRES ON FRONT.

---

**Job Notes**

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(GMANNING) WINGFOOT INSTALLED TWO NEW TIRES ON FRONT. PD BY CC.

**09-17 - ALIGN TIRES, TUBES, LINERS & VALVES**

(GMANNING) FRONT END ALIGNED BY FIRESTONE. PD BY CC.

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(GMANNING) SH TOOK VAN TO WINGFOOT. THEN OVER TO FIRESTONE.

---



# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 16183

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 02/21/2014 15:50:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/25/2014 10:57:47	<b>METER 1 - M:</b> 54146 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/25/2014 10:57:59	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	O	N	GARAGE	0.00	\$0.00	\$44.52	\$0.00	\$44.52
03-50-102	REPLACE NEW IDLER PULLEY	DON	O	N	GARAGE	0.30	\$17.25	\$28.81	\$0.00	\$46.06
03-50-103	REPLACE NEW BELT TENSIONER	DON	O	N	GARAGE	0.70	\$40.25	\$57.75	\$0.00	\$98.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.84	\$0.00	\$62.67

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.31</b>	<b>75.33</b>	<b>175.92</b>	<b>0.00</b>	<b>251.25</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-50-102	REPLACE NEW IDLER PULLEY	10260422	02/24/2014 07:00:36	02/24/2014 07:18:36	0.30	\$17.25
03-50-102	REPLACE NEW IDLER PULLEY	10260422	02/24/2014 07:00:36	02/24/2014 07:42:36	0.70	\$40.25
03-50-102	REPLACE NEW IDLER PULLEY	10260422	02/24/2014 07:00:36	02/24/2014 07:42:36	(0.70)	(\$40.25)
03-50-103	REPLACE NEW BELT TENSIONER	10260422	02/24/2014 06:18:36	02/24/2014 07:00:36	0.70	\$40.25
66-PM-PMA	PERFORM OIL CHANGE	10260422	02/24/2014 06:00:00	02/24/2014 06:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>75.33</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
03-50-102	REPLACE NEW IDLER PULLEY	GAT38001	IDLER PULLEY	28.81	1	\$28.81
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK0602984	BELT	44.52	1	\$44.52
03-50-103	REPLACE NEW BELT TENSIONER	GAT38274	BELT TENSIONER	57.75	1	\$57.75
					<b>PARTS</b>	<b>175.92</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 16183

---

## Work Order Notes

(LPATE) PM-CHECK BELT IS SQUEALING

---

## Job Notes

**03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.**

(LPATE) REPLACED BELT

**03-50-102 - REPLACE NEW IDLER PULLEY**

(LPATE) REPLACED IDLER PULLEY. RECHECKED ALL OK

**03-50-103 - REPLACE NEW BELT TENSIONER**

(LPATE) REPLACED BELT TENSIONER

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 16331

USING DEPT NO:	504104	OPENED DATE:	03/10/2014 07:52:08	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	03/11/2014 09:51:41	METER 1 - M:	54474	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/11/2014 09:51:42	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
04-31-001	REPLACE RBLT ALTERNATOR	DON	O	N	GARAGE	0.33	\$19.23	\$158.40	\$0.00	\$177.63
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2 WORK ORDER TOTAL: 0.83 47.98 158.40 0.00 206.38

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
04-31-001	REPLACE RBLT ALTERNATOR	11074414	03/10/2014 09:17:10	03/10/2014 09:37:14	0.33	\$19.23
35-31	DIAGNOSE CHARGING SYSTEM	11268671	03/10/2014 14:06:05	03/10/2014 14:36:05	0.50	\$28.75
					<b>LABOR</b>	<b>47.98</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
04-31-001	REPLACE RBLT ALTERNATOR	REM23670	ALTERNATOR	158.40	1	\$158.40
					<b>PARTS</b>	<b>158.40</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 16331

---

**Work Order Notes**

(LPATE) ENGINE IS MAKING A LOUD NOISE

---

**Job Notes**

**04-31-001 - REPLACE RBLT ALTERNATOR**

(LPATE) REMOVED AND REPLACED ALT RECHECKED. CHARGING GOOD

**35-31 - DIAGNOSE CHARGING SYSTEM**

(LPATE) CHECKED ALTERNATOR HAS A BAD BEARING

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 16366

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 03/12/2014 10:14:11	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/14/2014 13:11:12	<b>METER 1 - M:</b> 54548 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/14/2014 13:11:13	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-44	DIAGNOSE FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
CL-05-030	CLEANED THROTTLE BODY-CLEAN OR	DON	O	N	GARAGE	1.00	\$57.50	\$4.86	\$0.00	\$62.36

**JOB COUNT: 2** **WORK ORDER TOTAL: 1.50 86.25 4.86 0.00 91.11**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-44	DIAGNOSE FUEL SYSTEM	11568366	03/13/2014 07:00:00	03/13/2014 07:30:00	0.50	\$28.75
CL-05-030	CLEANED THROTTLE BODY-CLEAN OR REPLACE	11568366	03/13/2014 07:30:00	03/13/2014 08:30:00	1.00	\$57.50
					<b>LABOR</b>	<b>86.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-05-030	CLEANED THROTTLE BODY-CLEAN OR REPLACE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
					<b>PARTS</b>	<b>4.86</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 16366

---

**Work Order Notes**

(LPATE) PER DRIVER VAN KEEPS GOING DEAD WILL NOT IDLE DIES WHEN COMING TO A STOP

---

**Job Notes**

**35-44 - DIAGNOSE FUEL SYSTEM**

(LPATE) CHECKED FOUND THROTTLE BODY AND MASS AIR FLOW SENSOR DIRTY

**CL-05-030 - CLEANED THROTTLE BODY-CLEAN OR REPLACE**

(LPATE) REMOVED AIR INTAKE FROM FILTER TO THROTTLE BODY AND CLEANED THROTTLE BODY. REMOVED MASS AIR FLOW SENSOR FROM AIR FILTER HOUSING AND CLEANED. REINSTALLED ALL PARTS. TEST DROVE OK

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 17124

USING DEPT NO:	504104	OPENED DATE:	05/29/2014 09:23:06	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2014 06:36:26	METER 1 - M:	56205	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/30/2014 06:36:28	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.11	\$6.34	\$33.72	\$0.00	\$40.06

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.11** **6.34** **33.72** **0.00** **40.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11338644	05/29/2014 09:26:05	05/29/2014 09:26:05	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11338644	05/29/2014 09:30:00	05/29/2014 09:36:37	0.11	\$6.34
					<b>LABOR</b>	<b>6.34</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	2	\$33.72
					<b>PARTS</b>	<b>33.72</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 17124

---

**Work Order Notes**

(LPATE) DRIVER REQUESTED NEW WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

---



# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 17166

USING DEPT NO:	504104	OPENED DATE:	06/02/2014 10:00:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2014 07:36:12	METER 1 - M:	56205	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2014 07:36:13	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$5.10	\$0.00	\$5.10

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>5.10</b>	<b>0.00</b>	<b>5.10</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	2.55	2	\$5.10
					<b>PARTS</b>	<b>5.10</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 17166

---

**Work Order Notes**

(LPATE) DRIVER REQUESTED 2 NEW KEYS

---

**Job Notes**

03-51-046 - REPLACE NEW KEY BLANK(S)

(LPATE) CUT 2 KEYS

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 17816

USING DEPT NO:	504104	OPENED DATE:	08/15/2014 10:10:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2014 14:03:26	METER 1 - M:	58255	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/15/2014 14:03:28	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$45.47	\$0.00	\$63.30

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.31</b>	<b>17.83</b>	<b>45.47</b>	<b>0.00</b>	<b>63.30</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	08/15/2014 10:10:56	08/15/2014 10:29:32	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
					<b>PARTS</b>	<b>45.47</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 17816

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM/SH

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 18017

USING DEPT NO:	504104	OPENED DATE:	09/09/2014 11:31:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/09/2014 15:00:56	METER 1 - M:	58886	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/09/2014 15:00:58	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$2.16	\$0.00	\$2.16

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>2.16</b>	<b>0.00</b>	<b>2.16</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	2.16	1	\$2.16
					<b>PARTS</b>	<b>2.16</b>

# Work Order Charge Detail

**UNIT NO:**            236915            2006 FORD E250

**WORK ORDER NO:**    18017

---

**Work Order Notes**

(LPATE) GLENN REQUESTED CUT A KEY

---

**Job Notes**

**03-51-046 - REPLACE NEW KEY BLANK(S)**

(LPATE) CUT 1 KEY GAVE TO DRIVER

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 18555

USING DEPT NO:	504104	OPENED DATE:	10/28/2014 14:36:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/29/2014 06:39:12	METER 1 - M:	60095	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/29/2014 06:39:13	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$36.42	\$0.00	\$50.80

JOB COUNT: 1 WORK ORDER TOTAL: 0.25 14.38 36.42 0.00 50.80

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	10260422	10/28/2014 14:38:52	10/28/2014 14:53:52	0.25	\$14.38
					<b>LABOR</b>	<b>14.38</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	18.21	2	\$36.42
					<b>PARTS</b>	<b>36.42</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 18555

---

**Work Order Notes**

(LPATE) WIPERS NEED REPLACEMENT

---

**Job Notes**

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) CLEANED OVERSPRAY FROM WINDSHIELD. REPLACED WIPERS. RECHECKED OK

---



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 1894

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 08/28/2008 08:21:58	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/28/2008 08:47:09	<b>METER 1 - M:</b> 13815 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/28/2008 08:47:11	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	A	N	GARAGE	0.30	\$13.50	\$142.56	\$0.00	\$156.06
24-17	REPAIR TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.40	\$18.00	\$0.00	\$0.00	\$18.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.70** **31.50** **142.56** **0.00** **174.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-17	REPAIR TIRES, TUBES, LINERS & VALVES	11088474	08/28/2008 08:26:00	08/28/2008 08:50:00	0.40	\$18.00
03-02-010	REPLACE NEW MIRRORS	11088474	08/28/2008 08:35:00	08/28/2008 08:53:00	0.30	\$13.50
					<b>LABOR</b>	<b>31.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	3C2Z17683FAA	MIRROR	142.56	1	\$142.56
03-02-010	REPLACE NEW MIRRORS	3C2Z17683FAA	MIRROR	142.56	(1)	(\$142.56)
03-02-010	REPLACE NEW MIRRORS	3C2Z17683FAA	MIRROR	142.56	1	\$142.56
					<b>PARTS</b>	<b>142.56</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 1894

---

## Work Order Notes

### Job Notes

**03-02-010 - REPLACE NEW MIRRORS**

(AJONES) REPLACE BROKEN LF MIRROR

**24-17 - REPAIR TIRES, TUBES, LINERS & VALVES**

(AJONES) FLAT REPAIR RIGHT FRONT TIRE

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 19028

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 12/12/2014 15:50:28	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/15/2014 14:37:38	<b>METER 1 - M:</b> 61131 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/15/2014 14:37:42	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250	2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.37	\$21.11	\$136.63	\$0.00	\$157.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$7.91	\$45.47	\$0.00	\$53.38

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.50** **29.02** **182.10** **0.00** **211.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/15/2014 06:51:14	12/15/2014 06:59:29	0.14	\$7.91
03-32-002	REPLACE NEW BATTERY	11074414	12/15/2014 06:59:37	12/15/2014 07:21:39	0.37	\$21.11
					<b>LABOR</b>	<b>29.02</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	65-850	BATTERY- FORD TOP POST HD	136.63	1	\$136.63
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
					<b>PARTS</b>	<b>182.10</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 19028

---

**Work Order Notes**

(LPATE) PM-BATTERY FAILED, REPLACE BATTERY

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LPATE) REPLACED BATTERY

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY SH/GM

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 20234

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 05/12/2015 09:25:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/12/2015 13:45:51	<b>METER 1 - M:</b> 64288 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/12/2015 13:45:52	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$25.59	\$0.00	\$39.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.29	\$0.00	\$62.12

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.56** **32.21** **69.88** **0.00** **102.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	05/12/2015 09:27:02	05/12/2015 09:45:38	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	10260422	05/12/2015 09:27:36	05/12/2015 09:42:36	0.25	\$14.38
					<b>LABOR</b>	<b>32.21</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.81	1	\$4.81
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.80	2	\$25.59
					<b>PARTS</b>	<b>69.88</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 20234

---

**Work Order Notes**

(LPATE) PM-REPLACE WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.43

(LPATE) PM BY GM

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 21898

USING DEPT NO:	504104	OPENED DATE:	11/05/2015 09:19:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/06/2015 10:38:13	METER 1 - M:	66878	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/06/2015 10:38:15	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.49	\$0.00	\$17.74

JOB COUNT: 1 WORK ORDER TOTAL: 0.30 17.25 0.49 0.00 17.74

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	10260422	11/05/2015 09:20:25	11/05/2015 09:38:25	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49
					<b>PARTS</b>	<b>0.49</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 21898

---

**Work Order Notes**

(LISAPATE) TURN SIGNAL OUT

---

**Job Notes**

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) REPLACED RIGHT REAR TURN SIGNAL BULB

---



# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 21928

USING DEPT NO:	504104	OPENED DATE:	11/06/2015 15:39:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/09/2015 10:41:39	METER 1 - M:	67117	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2015 10:41:41	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$37.86	\$0.00	\$55.69

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>17.83</b>	<b>37.86</b>	<b>0.00</b>	<b>55.69</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	11/09/2015 07:00:00	11/09/2015 07:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	7.56	1	\$7.56
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					<b>PARTS</b>	<b>37.86</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 21928

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(RWINTERS) PM BY RS-REPLACED OIL DRAIN PLUG

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 22058

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 11/20/2015 15:41:59	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/25/2015 06:56:41	<b>METER 1 - M:</b> 67427 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/25/2015 06:56:42	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$410.88	\$410.88
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.86	\$49.55	\$0.00	\$0.00	\$49.55

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>	<b>0.86</b>	<b>49.55</b>	<b>0.00</b>	<b>410.88</b>	<b>460.43</b>
---------------------	--------------------------	-------------	--------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	164556	0031142	\$410.88
				<b>COMML</b>	<b>410.88</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	11/23/2015 08:23:18	11/23/2015 09:15:00	0.86	\$49.55
					<b>LABOR</b>	<b>49.55</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 22058

---

**Work Order Notes**

(LISAPATE) REPLACE 2 REAR TIRES  
(GMANNING) GM/BG CHECKED FRONT END. CHECKED OK.

---

**Job Notes**

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(GMANNING) OK TIRE REPLACED TWO TIRES AND PERFORMED ALIGNMENT. PD BY CC.

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(GMANNING) BG/GM TOOK VAN TO OK TIRE.

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 22928

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 03/28/2016 11:12:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/31/2016 06:36:37	<b>METER 1 - M:</b> 69418 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/31/2016 06:36:38	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-17-011	INSTALL TIRE PLUG	DON	O	N	GARAGE	0.40	\$23.00	\$0.00	\$0.00	\$23.00

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.40</b>	<b>23.00</b>	<b>0.00</b>	<b>0.00</b>	<b>23.00</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-17-011	INSTALL TIRE PLUG	11074414	03/28/2016 11:15:01	03/28/2016 11:39:01	0.40	\$23.00
					<b>LABOR</b>	<b>23.00</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 22928

---

**Work Order Notes**

(GMANNING) SCREW IN LEFT REAR TIRE

---

**Job Notes**

14-17-011 - INSTALL TIRE PLUG

(GMANNING) SH PLUGGED LR TIRE

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 23419

USING DEPT NO:	504104	OPENED DATE:	05/18/2016 08:39:27	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2016 08:49:00	METER 1 - M:	70315	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2016 08:49:01	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	2.00	\$115.00	\$206.52	\$0.00	\$321.52
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$23.00	\$2.04	\$0.00	\$25.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$54.21	\$37.97	\$0.00	\$92.18
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$284.99	\$284.99

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>3.34</b>	<b>192.21</b>	<b>246.53</b>	<b>284.99</b>	<b>723.73</b>
---------------------	--------------------------	-------------	---------------	---------------	---------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11321046	166803	0033467	\$284.99
				<b>COMML</b>	<b>284.99</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/18/2016 09:52:52	05/18/2016 10:49:26	0.94	\$54.21
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11268671	05/23/2016 07:00:00	05/23/2016 09:00:00	2.00	\$115.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11268671	05/23/2016 09:00:00	05/23/2016 09:24:00	0.40	\$23.00
					<b>LABOR</b>	<b>192.21</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	2.05	1	\$2.05
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.60	1	\$2.60
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	224	\$22.40
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PT7673	BRAKE PADS-REAR	54.22	1	\$54.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21597	TIRE VALVE TR 600 HP	0.50	2	\$1.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.26	4	\$1.04
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	BRE09885811	BREMBO ROTOR	76.15	2	\$152.30
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
					<b>PARTS</b>	<b>246.53</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 23419

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(LISAPATE) REPLACED REAR PADS AND ROTORS. TEST DROVE OK

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) MOUNTED AND BALANCED 2 NEW TIRES

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY SH-REPLACED AIR FILTER

**PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES**

(LISAPATE) PURCHASED 2 TIRES FROM OK TIRE. PD BY CC

---



# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 23635

USING DEPT NO:	504104	OPENED DATE:	06/10/2016 08:58:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2016 15:50:17	METER 1 - M:	70576	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2016 15:50:19	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.49	\$0.00	\$17.74

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.30</b>	<b>17.25</b>	<b>0.49</b>	<b>0.00</b>	<b>17.74</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11213180	06/10/2016 08:59:00	06/10/2016 09:17:00	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49
					<b>PARTS</b>	<b>0.49</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 23635

---

**Work Order Notes**

(LISAPATE) LEFT BRAKE LIGHT OUT

---

**Job Notes**

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) REPLACED LEFT BRAKE LIGHT

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 23890

USING DEPT NO:	504104	OPENED DATE:	07/13/2016 10:18:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/15/2016 10:31:48	METER 1 - M:	71116	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2016 10:31:49	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-35-006	REPLACE NEW FUSE(S)	DON	O	N	GARAGE	0.30	\$17.25	\$0.55	\$0.00	\$17.80
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 2 WORK ORDER TOTAL: 1.80 103.50 0.55 0.00 104.05

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-35-006	REPLACE NEW FUSE(S)	11397026	07/13/2016 10:26:34	07/13/2016 10:44:34	0.30	\$17.25
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	07/13/2016 10:26:30	07/13/2016 11:56:30	1.50	\$86.25
					<b>LABOR</b>	<b>103.50</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-35-006	REPLACE NEW FUSE(S)	ATM20	FUSE-20 AMP MINI	0.55	1	\$0.55
					<b>PARTS</b>	<b>0.55</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 23890

---

## Work Order Notes

(LISAPATE) ABS LIGHT CAME ON AND THEN WENT OFF

---

## Job Notes

### **03-35-006 - REPLACE NEW FUSE(S)**

(LISAPATE) REPLACED 20A MINI FUSE TO THE DATA LINK CONNECTOR TO GET POWER TO THE SCAN TOOL. RAN ON DMAND SELF TEST ON ABS SYSTEM NO CODES WERE FOUND AT THIS TME. EVERYTHING CHECKED NORMAL

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT-NO CODES STORED

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 2393

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 11/14/2008 11:02:14	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/14/2008 14:45:36	<b>METER 1 - M:</b> 15421 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/14/2008 14:45:40	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$58.57	\$0.00	\$76.40

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.56** **32.21** **89.47** **0.00** **121.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11088474	11/14/2008 12:18:36	11/14/2008 12:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/14/2008 12:00:00	11/14/2008 12:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>32.21</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	23.83	1	\$23.83
					<b>PARTS</b>	<b>89.47</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 2393

---

**Work Order Notes**

(LPATE) PM-REPLACE WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part FA1632 FILTER-AIR FORD Qty 1 Cost 0

Part 5W20 MOTOR OIL Qty 224 Cost 0

Part 51372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 24794

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 10/28/2016 13:08:22	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/01/2016 06:30:41	<b>METER 1 - M:</b> 73016 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/01/2016 06:30:43	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.38	\$0.00	\$44.21

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.31** **17.83** **26.38** **0.00** **44.21**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/28/2016 13:09:41	10/28/2016 13:28:17	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	224	\$22.40
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					<b>PARTS</b>	<b>26.38</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 24794

---

**Work Order Notes**

(IFALLS) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(IFALLS) PM PERFORMED BY SH

---



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 25706

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 02/08/2017 14:45:57	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/17/2017 06:28:43	<b>METER 1 - M:</b> 74234 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/17/2017 06:28:44	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.60	\$149.50	\$284.20	\$0.00	\$433.70
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 2** **WORK ORDER TOTAL:** **3.10** **178.25** **284.20** **0.00** **462.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	02/16/2017 07:30:00	02/16/2017 10:06:00	2.60	\$149.50
06-13	INSPECT BRAKES	11213180	02/16/2017 07:00:00	02/16/2017 07:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>178.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	2.12	1	\$2.12
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	15.87	2	\$31.74
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	12.22	2	\$24.44
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS24000	GREASE SEALS	10.64	2	\$21.28
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS24000	GREASE SEALS	10.64	(5)	(\$53.20)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP655TRH	BRAKE PADS	57.70	1	\$57.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS24000	GREASE SEALS	10.64	5	\$53.20
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM66528R	FRONT ROTOR	73.46	2	\$146.92
					<b>PARTS</b>	<b>284.20</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 25706

---

**Work Order Notes**

(LISAPATE) CHECK BRAKES-FRONT BRAKES MAKING A GRINDING NOISE

---

**Job Notes**

**03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(LISAPATE) REPLACED ROTORS, PADS, BEARINGS AND SEALS. TEST DROVE OK

**06-13 - INSPECT BRAKES**

(LISAPATE) CHECKED FRONT BRAKES WORN

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 27121

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 08/16/2017 07:12:55	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/17/2017 15:40:33	<b>METER 1 - M:</b> 76853 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/17/2017 15:40:34	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$24.36	\$0.00	\$42.19

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.31** **17.83** **24.36** **0.00** **42.19**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/16/2017 09:59:40	08/16/2017 10:18:16	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
					<b>PARTS</b>	<b>24.36</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 27121

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS

REPLACED AIR FILTER

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 28752

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 01/31/2018 08:13:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/05/2018 08:06:29	<b>METER 1 - M:</b> 79405 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/05/2018 08:06:31	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.19	\$10.85	\$60.99	\$0.00	\$71.84
03-78-026	REPLACE NEW METAL CAB DIVIDERS/S	DON	O	N	GARAGE	4.50	\$258.75	\$3,964.00	\$0.00	\$4,222.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$28.81	\$19.66	\$0.00	\$48.47

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>5.19</b>	<b>298.41</b>	<b>4,044.65</b>	<b>0.00</b>	<b>4,343.06</b>
---------------------	--------------------------	-------------	---------------	-----------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/31/2018 08:30:30	01/31/2018 09:00:34	0.50	\$28.81
03-32-002	REPLACE NEW BATTERY	11901357	01/31/2018 09:01:50	01/31/2018 09:13:09	0.19	\$10.85
03-78-026	REPLACE NEW METAL CAB DIVIDERS/SHELVING	11758845	02/01/2018 07:00:00	02/01/2018 11:30:00	4.50	\$258.75
					<b>LABOR</b>	<b>298.41</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.07	224	\$15.68
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	60.99	1	\$60.99
03-78-026	REPLACE NEW METAL CAB DIVIDERS/SHELVING	33	ADRAIN SHELF RACK	209.00	1	\$209.00
03-78-026	REPLACE NEW METAL CAB DIVIDERS/SHELVING	4318F	HVAC SHELVING UNIT	3755.00	1	\$3,755.00
					<b>PARTS</b>	<b>4044.65</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 28752

---

**Work Order Notes**

(LISAPATE) PM-REMOVE OLD SHELVING AND INSTALL NEW SHELVES

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) BATTERY FAILED REPLACED BATTERY. CHECKED CHARGING SYSTEM AT 14.8 VOLTS

**03-78-026 - REPLACE NEW METAL CAB DIVIDERS/SHELVING**

(LISAPATE) REMOVED OLD BIN PACKAGE. INSTALLED NEW RAIL KIT THEN MOUNTED NEW BIN PACKAGE TO THE RAIL KIT.

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY AG/SH

COOLANT -45'

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 30332

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 07/23/2018 09:14:04	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/22/2018 09:06:00	<b>METER 1 - M:</b> 81646 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/22/2018 09:06:00	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-108	REPLACE NEW WINDOW TRACK	DON	O	N	GARAGE	0.50	\$0.00	\$35.99	\$0.00	\$35.99
06-02-053	INSPECT WINDOW REGULATOR	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$26.87	\$0.00	\$26.87

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.31</b>	<b>0.00</b>	<b>62.86</b>	<b>0.00</b>	<b>62.86</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-108	REPLACE NEW WINDOW TRACK	11758845	08/20/2018 07:48:36	08/20/2018 08:18:36	0.50	\$0.00
06-02-053	INSPECT WINDOW REGULATOR	11758845	08/20/2018 07:18:36	08/20/2018 07:48:36	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/20/2018 07:00:00	08/20/2018 07:18:36	0.31	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.27	7	\$22.89
24-02-053	REPAIR WINDOW REGULATOR	F2UZ15222A00A	GLASS CHANNEL	35.99	1	\$35.99
24-02-053	REPAIR WINDOW REGULATOR	F2UZ15222A00A	GLASS CHANNEL	35.99	(1)	(\$35.99)
03-02-108	REPLACE NEW WINDOW TRACK	F2UZ15222A00A	GLASS CHANNEL	35.99	1	\$35.99
					<b>PARTS</b>	<b>62.86</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 30332

---

**Work Order Notes**

(LISAPATE) PM-PASSENGER WINDOW WILL NOT GO UP AND DOWN PROPERLY

---

**Job Notes**

**03-02-053 - REPLACE NEW WINDOW REGULATOR**

**03-02-108 - REPLACE NEW WINDOW TRACK**

(LISAPATE) REMOVED AND INSTALLED NEW PASSENGER WINDOW TRACK. RECHECKED OK

**06-02-053 - INSPECT WINDOW REGULATOR**

(LISAPATE) FOUND WINDOW TRACK BROKEN

**24-02-053 - REPAIR WINDOW REGULATOR**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM BY CS

COOLANT -36'

---



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 3045

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 03/10/2009 07:58:43	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/10/2009 14:04:12	<b>METER 1 - M:</b> 17123 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 03/10/2009 14:04:14	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$1.50	\$0.00	\$1.50

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.00 0.00 1.50 0.00 1.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-046	REPLACE NEW KEY BLANK(S)	KEY BLANK	KEY BLANK	1.50	1	\$1.50
					<b>PARTS</b>	<b>1.50</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 3045

---

**Work Order Notes**

(LPATE) REQUESTED 1 KEY

---

**Job Notes**

03-51-046 - REPLACE NEW KEY BLANK(S)

(LPATE) CHRIS CUT 1 KEY

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 31349

USING DEPT NO:	504104	OPENED DATE:	10/31/2018 08:05:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/02/2018 10:41:58	METER 1 - M:	82738	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/02/2018 10:42:00	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.20	\$0.00	\$129.68	\$0.00	\$129.68

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.20 0.00 129.68 0.00 129.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	10/31/2018 11:47:25	10/31/2018 11:59:25	0.20	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	128.69	1	\$128.69
					<b>PARTS</b>	<b>129.68</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 31349

---

**Work Order Notes**

(LISAPATE) Nail in RR tire

---

**Job Notes**

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) Mounted and balanced 1 new RR tire screw was too close to the sidewall.  
(IFALLS) CS INSTALLED 1 NEW TIRE

**66-17-030 - PERFORM TIRE PATCH**

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 32318

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 03/01/2019 08:53:33	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/21/2019 15:14:17	<b>METER 1 - M:</b> 84001 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/21/2019 15:14:19	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	0.30	\$0.00	\$33.72	\$0.00	\$33.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$0.00	\$24.77	\$0.00	\$24.77
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.48</b>	<b>0.00</b>	<b>58.49</b>	<b>0.00</b>	<b>58.49</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/07/2019 09:25:01	03/07/2019 10:05:46	0.68	\$0.00
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	11915538	03/18/2019 07:00:00	03/18/2019 07:18:00	0.30	\$0.00
CH-32-002	CHARGE BATTERY	11915538	03/18/2019 07:00:00	03/18/2019 07:30:00	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	7	\$20.79
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	MZFO2800190C	TAIL LAMP ASSEMBLY LH CAPA	23.72	1	\$23.72
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	SHIPPING	SHIPPING AND HANDLING	10.00	1	\$10.00
					<b>PARTS</b>	<b>58.49</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 32318

---

## Work Order Notes

(LISAPATE) LR brake light assy was broken in an accident-PM is due

---

## Job Notes

### **03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY**

(LISAPATE) Installed new LR tail light assy

### **66-PM-PMA - PERFORM OIL CHANGE**

(RTUNAITI)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by RC/AG

Coolant -35'

### **CH-32-002 - CHARGE BATTERY**

(LISAPATE) Removed and charged battery rechecked charging at 14.3 volts. All good

---

# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 33523

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 07/25/2019 07:36:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/25/2019 20:00:00	<b>METER 1 - M:</b> 85393 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 07/25/2019 20:00:00	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-31-001	REPLACE NEW ALTERNATOR	DON	O	N	GARAGE	0.52	\$0.00	\$135.57	\$0.00	\$135.57
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.29	\$0.00	\$0.00	\$0.00	\$0.00
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.31</b>	<b>0.00</b>	<b>135.57</b>	<b>0.00</b>	<b>135.57</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11074414	07/25/2019 07:51:55	07/25/2019 09:09:35	1.29	\$0.00
03-31-001	REPLACE NEW ALTERNATOR	11074414	07/25/2019 09:09:35	07/25/2019 09:40:29	0.52	\$0.00
CH-32-002	CHARGE BATTERY	11074414	07/25/2019 09:09:35	07/25/2019 09:39:35	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-31-001	REPLACE NEW ALTERNATOR	1N3121D	ALTERNATOR	135.57	1	\$135.57
					<b>PARTS</b>	<b>135.57</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 33523

---

**Work Order Notes**

(LISAPATE) Scott requested a service call to the bus hub battery is dead just clicks

---

**Job Notes**

**03-31-001 - REPLACE NEW ALTERNATOR**

(LISAPATE) Removed and installed a new alternator. Charging at 14.2 volts

**66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) Service call completed, jumped off and drove to shop alt is not charging

**CH-32-002 - CHARGE BATTERY**

(IFALLS) SH charged battery

---



# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 33954

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 09/04/2019 09:21:16	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/10/2019 13:54:10	<b>METER 1 - M:</b> 86024 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/10/2019 13:54:12	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$0.00	\$0.25	\$0.00	\$0.25
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.56	\$0.00	\$0.00	\$0.00	\$0.00
14-16-032	INSTALL ADJUSTABLE CAM BUSHINGS	DON	O	N	GARAGE	0.40	\$0.00	\$62.50	\$0.00	\$62.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.91	\$0.00	\$271.94	\$0.00	\$271.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.26	\$0.00	\$31.57	\$0.00	\$31.57

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>4.92</b>	<b>0.00</b>	<b>366.26</b>	<b>0.00</b>	<b>366.26</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/04/2019 09:27:37	09/04/2019 09:52:23	0.41	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/04/2019 09:27:28	09/04/2019 10:18:16	0.85	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/06/2019 13:13:39	09/06/2019 14:08:24	0.91	\$0.00
09-15	ALIGN STEERING	11310047	09/07/2019 08:13:19	09/07/2019 09:46:43	1.56	\$0.00
14-16-032	INSTALL ADJUSTABLE CAM BUSHINGS	11310047	09/07/2019 10:17:07	09/07/2019 10:40:51	0.40	\$0.00
06-15	INSPECT STEERING	11074414	09/07/2019 00:00:00	09/07/2019 00:30:00	0.50	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	09/07/2019 00:00:00	09/07/2019 00:18:00	0.30	\$0.00

**LABOR      0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	912	BULB-BRAKE-3RD	0.25	1	\$0.25
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	135.00	2	\$270.00
14-16-032	INSTALL ADJUSTABLE CAM BUSHINGS	2643950	CAMBER BUSHING	31.25	2	\$62.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	4	\$1.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.43	2	\$0.86

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	7	\$20.65
<b>PARTS</b>						<b>366.26</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 33954

---

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LISAPATE) Replaced Left top mount stop light

### **06-15 - INSPECT STEERING**

(LISAPATE) SH/AG checked the front end no issues found

### **09-15 - ALIGN STEERING**

(LISAPATE) EH Performed alignment

### **14-16-032 - INSTALL ADJUSTABLE CAM BUSHINGS**

(LISAPATE) .5 Needed to install adjustable camber bushings to both sides

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) Mounted and balanced 2 new tires. Installed on the rear

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by SH/AG

Coolant -35'

Replaced air filter

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 34715

USING DEPT NO:	504104	OPENED DATE:	11/01/2019 08:27:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2019 09:20:53	METER 1 - M:	86691	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2019 09:20:56	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.17	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.17</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	11901357	11/01/2019 08:34:16	11/01/2019 08:44:19	0.17	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 34715

---

## Work Order Notes

(EKIMBREL) Remove 3G, install 4G GPS system

---

## Job Notes

### 03-52-021 - REPLACE NEW GPS SYSTEM

(EKIMBREL) Installed new serial#5041373014  
Ols serial#5014687087

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 35234

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 12/18/2019 15:17:41	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/03/2020 06:18:20	<b>METER 1 - M:</b> 87118 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 01/03/2020 06:18:22	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-057	REPLACE NEW DOOR HANDLE EXTERI	DON	O	N	GARAGE	0.63	\$0.00	\$73.13	\$0.00	\$73.13
03-02-070	REPLACE NEW DOOR LATCH SWITCH	DON	O	N	GARAGE	0.90	\$0.00	\$7.33	\$0.00	\$7.33
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>2.03</b>	<b>0.00</b>	<b>80.46</b>	<b>0.00</b>	<b>80.46</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-070	REPLACE NEW DOOR LATCH SWITCH	12052187	12/20/2019 08:01:07	12/20/2019 08:55:08	0.90	\$0.00
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	12052187	12/20/2019 09:41:17	12/20/2019 10:19:19	0.63	\$0.00
66-79-002	PERFORM SERVICE CALL	11915538	12/20/2019 07:00:00	12/20/2019 07:30:00	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-070	REPLACE NEW DOOR LATCH SWITCH	STIDS278T	DOOR JAMB SWITCH	7.33	1	\$7.33
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	8C2Z15264A00D	DOOR LATCH CABLE	42.76	1	\$42.76
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	8C2Z15264A00D	DOOR LATCH CABLE	42.76	(1)	(\$42.76)
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	DOR77534	EXTERIOR DOOR HANDLE	30.37	1	\$30.37
03-02-057	REPLACE NEW DOOR HANDLE EXTERIOR	8C2Z15264A00D	DOOR LATCH CABLE	42.76	1	\$42.76
					<b>PARTS</b>	<b>80.46</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 35234

---

## Work Order Notes

(EKIMBREL) Service Call, dead battery. Driver door faulty. Side entry door broken. Chime when key in ignition inop.

---

## Job Notes

### **03-02-057 - REPLACE NEW DOOR HANDLE EXTERIOR**

(EKIMBREL) Replaced passenger right door handle on outside and the latch.

### **03-02-070 - REPLACE NEW DOOR LATCH SWITCH**

(EKIMBREL) Replaced door jam switch on driver's door.

### **24-02-057 - REPAIR DOOR HANDLE EXTERIOR**

### **66-79-002 - PERFORM SERVICE CALL**

(EKIMBREL) Jumped vehicle off and brought to shop.

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 3549

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 06/02/2009 14:11:59	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/03/2009 06:42:21	<b>METER 1 - M:</b> 18777 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 06/03/2009 06:42:23	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250	2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$66.83	\$0.00	\$84.66

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.56** **32.21** **97.73** **0.00** **129.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	06/02/2009 17:00:00	06/02/2009 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11088474	06/02/2009 17:18:36	06/02/2009 17:33:36	0.25	\$14.38
					<b>LABOR</b>	<b>32.21</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	31.50	1	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	3.95	1	\$3.95
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
					<b>PARTS</b>	<b>97.73</b>



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 3549

---

**Work Order Notes**

(LPATE) PM-REPLACE WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 51372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL-MOTOR Qty 224 Cost 0

Part FA1632 FILTER-AIR FORD Qty 1 Cost 0

(LPATE) PM BY JE

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 35778

USING DEPT NO:	504104	OPENED DATE:	02/25/2020 15:11:15	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2020 11:03:33	METER 1 - M:	88098	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2020 11:03:35	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$0.00	\$21.68	\$0.00	\$21.68

JOB COUNT: 1 WORK ORDER TOTAL: 0.52 0.00 21.68 0.00 21.68

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/26/2020 06:34:58	02/26/2020 07:05:58	0.52	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					<b>PARTS</b>	<b>21.68</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 35778

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

Part FL820S FILTER-OIL FORD Qty 1 Cost 3.430000

(LISAPATE) PM by AG,MS/AG

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 36068

USING DEPT NO:	504104	OPENED DATE:	03/26/2020 13:06:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/26/2020 14:33:48	METER 1 - M:	88166	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2020 11:41:25	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	DON	O	N	GARAGE	1.06	\$0.00	\$160.75	\$0.00	\$160.75

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>1.06</b>	<b>0.00</b>	<b>160.75</b>	<b>0.00</b>	<b>160.75</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-018	REPLACE NEW DOOR MECHANISM	11901357	03/26/2020 13:11:15	03/26/2020 14:15:00	1.06	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-018	REPLACE NEW DOOR MECHANISM	AC2Z15431A02A	DOOR LATCH KIT	48.61	1	\$48.61
03-02-018	REPLACE NEW DOOR MECHANISM	6651125	TRIM RETAINER 13PCS	3.75	1	\$3.75
03-02-018	REPLACE NEW DOOR MECHANISM	6C2Z15434A20AA	OUTSIDE REAR DOOR HANDLE	108.39	1	\$108.39
					<b>PARTS</b>	<b>160.75</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 36068

---

**Work Order Notes**

(RTUNAITI) Right rear cargo door handle is broken

---

**Job Notes**

**03-02-018 - REPLACE NEW DOOR MECHANISM**

(IFALLS) AG replaced rear door outside handle/tag assemble

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 36788

USING DEPT NO:	504104	OPENED DATE:	06/11/2020 13:53:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/12/2020 09:29:36	METER 1 - M:	88881	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2020 08:51:49	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$0.00	\$21.68	\$0.00	\$21.68

JOB COUNT: 1 WORK ORDER TOTAL: 0.29 0.00 21.68 0.00 21.68

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/12/2020 07:27:02	06/12/2020 07:44:17	0.29	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					<b>PARTS</b>	<b>21.68</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 36788

---

## Work Order Notes

(EKIMBREL) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULLSYN OIL BULK

Manufacturer :

Bin :

Part No : FL820S

Qty : 1

Description : FILTER-OIL FORD

Manufacturer : MOTORCRAFT

Bin : D4D3

(EKIMBREL) SH/JW performed pm service, Coolant -34

---

# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 38264

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 11/04/2020 10:30:32	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/05/2020 10:53:39	<b>METER 1 - M:</b> 89916 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/06/2020 08:20:30	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.12	\$13.67	\$114.48	\$0.00	\$128.15
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.04	\$4.75	\$0.59	\$0.00	\$5.34
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.06	\$6.56	\$21.81	\$0.00	\$28.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.08	\$127.28	\$4.43	\$0.00	\$131.71

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.29</b>	<b>152.26</b>	<b>141.31</b>	<b>0.00</b>	<b>293.57</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/04/2020 10:58:34	11/04/2020 12:00:00	1.02	\$120.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/04/2020 13:05:01	11/04/2020 13:08:18	0.05	\$6.46
03-32-002	REPLACE NEW BATTERY	11074414	11/04/2020 13:08:34	11/04/2020 13:15:31	0.12	\$13.67
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	11/04/2020 13:15:48	11/04/2020 13:18:13	0.04	\$4.75
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/04/2020 13:18:30	11/04/2020 13:21:50	0.06	\$6.56

**LABOR      152.26**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	0.93	1	\$0.93
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	10.91	2	\$21.81
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.59	1	\$0.59
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	1	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	5.82	(1)	(\$5.82)
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	5.82	1	\$5.82

**PARTS      141.31**



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 38264

---

**Work Order Notes**

(LISAPATE) PM

WAITING

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(SHARBIN) Battery tested bad. Replaced battery. SH

**03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC**

(SHARBIN) Replaced right rear turn signal bulb. SH

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers due to normal wear. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 89916. Vehicle has been driven 1035 miles since last PM. Checked fluids, replaced battery, tire pressure and updated oil change sticker. Washed, vacuumed and filled with gas. SH

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 38776

USING DEPT NO:	504104	OPENED DATE:	01/13/2021 09:11:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/13/2021 14:12:47	METER 1 - M:	90447	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/14/2021 11:15:07	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-018	REPLACE NEW DOOR MECHANISM	DON	O	N	GARAGE	0.29	\$34.32	\$67.92	\$0.00	\$102.24

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.29</b>	<b>34.32</b>	<b>67.92</b>	<b>0.00</b>	<b>102.24</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-018	REPLACE NEW DOOR MECHANISM	11213180	01/13/2021 09:14:27	01/13/2021 09:14:27	0.00	\$0.00
03-02-018	REPLACE NEW DOOR MECHANISM	11213180	01/13/2021 09:30:00	01/13/2021 09:47:27	0.29	\$34.32
					<b>LABOR</b>	<b>34.32</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-018	REPLACE NEW DOOR MECHANISM	8C2Z15431A03A	LOWER LATCH W/HANDLE	67.92	1	\$67.92
					<b>PARTS</b>	<b>67.92</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 38776

---

**Work Order Notes**

(RTUNAITI) LR cargo door inop

---

**Job Notes**

**03-02-018 - REPLACE NEW DOOR MECHANISM**

(RTUNAITI)

(MSIDES) Replaced door handle and lower latch assembly on driver rear barn door. MS

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 39699

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 04/15/2021 13:41:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/04/2021 14:03:42	<b>METER 1 - M:</b> 91293 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 05/10/2021 08:40:20	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.11	\$249.47	\$463.75	\$0.00	\$713.22
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	0.89	\$104.95	\$235.32	\$0.00	\$340.27
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.22	\$25.63	\$0.00	\$0.00	\$25.63
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.93	\$109.94	\$0.00	\$0.00	\$109.94
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.95	\$112.03	\$206.36	\$0.00	\$318.39
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.09	\$11.08	\$0.00	\$0.00	\$11.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.58	\$36.21	\$0.00	\$66.79

<b>JOB COUNT: 7</b>	<b>WORK ORDER TOTAL:</b>	<b>5.46</b>	<b>643.68</b>	<b>941.64</b>	<b>0.00</b>	<b>1,585.32</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	04/16/2021 07:06:31	04/16/2021 07:22:04	0.26	\$30.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/27/2021 09:00:45	04/27/2021 09:15:00	0.24	\$28.03
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/27/2021 09:30:00	04/27/2021 10:12:43	0.71	\$84.01
66-17-030	PERFORM TIRE PATCH	11074414	04/27/2021 10:14:55	04/27/2021 10:20:33	0.09	\$11.08
06-15	INSPECT STEERING	11074414	04/27/2021 10:20:44	04/27/2021 10:33:46	0.22	\$25.63
66-17-013	PERFORM ALIGNMENT	11213180	04/28/2021 07:55:52	04/28/2021 08:51:46	0.93	\$109.94
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	04/29/2021 08:17:17	04/29/2021 10:24:08	2.11	\$249.47
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	04/29/2021 14:02:44	04/29/2021 14:56:06	0.89	\$104.95

**LABOR 643.69**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	3.29	2	\$6.57
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP655TRH	BRAKE PADS	75.17	1	\$75.17
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	FBRSB66528	BRAKE ROTOR / HUB ASSY	131.10	2	\$262.20

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABSP802TRH	BRAKE PAD SET HD	71.28	1	\$71.28
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB66799R	BRAKE ROTOR REAR	82.02	2	\$164.04
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS24000	GREASE SEALS	12.78	2	\$25.56
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	16.07	2	\$32.13
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	20.85	2	\$41.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11763011	BRAKE BEARING HARDWARE SET	11.93	1	\$11.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.47	5	\$2.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.77	2	\$1.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	202.50	1	\$202.50
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	DOR618033	AXLES SPINDLE WASHER	4.25	2	\$8.49
					<b>PARTS</b>	<b>941.64</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 39699

---

## Work Order Notes

(IFALLS) pm

---

## Job Notes

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(MSIDES) Replaced front brake pads and rotors. Also replaced wheel bearings and seals, found 3 caliper slide boots torn and replaced them also. MS

### **03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(MSIDES) Replaced rear brake pads and rotors.MS

### **06-15 - INSPECT STEERING**

(SHARBIN) Adjusted front wheel bearings and inspected steering. SH

### **09-16 - ALIGN SUSPENSION**

(GARAGE) Job 09-16 was added on-the-fly by 11213180 on 04/28/2021 07:52:27.

### **66-17-013 - PERFORM ALIGNMENT**

(MSIDES) Performed alignment, during test drive noticed very excessive brake pulsation will need full brake job. MS

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 1 tire for the left front. SH

### **66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Found a screw in the right front tire patched tire rechecks good.SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(ABLACK) AB performed top side and MS performed bottom side. Vehicle needs a new LF tire and is coming back to have installed.  
Miles 91293

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 40114

USING DEPT NO:	504104	OPENED DATE:	06/07/2021 09:18:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2021 08:40:00	METER 1 - M:	91454	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/08/2021 13:35:58	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.06	\$6.52	\$0.56	\$0.00	\$7.08

JOB COUNT: 1 WORK ORDER TOTAL: 0.06 6.52 0.56 0.00 7.08

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11213180	06/07/2021 09:31:18	06/07/2021 09:34:37	0.06	\$6.52
					<b>LABOR</b>	<b>6.52</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.56	1	\$0.56
					<b>PARTS</b>	<b>0.56</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 40114

---

**Work Order Notes**

(LISAPATE) Right brake light out

---

**Job Notes**

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(MSIDES) Replaced driver side brake light bulb. MS

---



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 41044

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 09/16/2021 09:58:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/16/2021 13:52:54	<b>METER 1 - M:</b> 92752 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/16/2021 15:08:45	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.54	\$15.18	\$0.00	\$18.72
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.19	\$22.68	\$5.59	\$0.00	\$28.27
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.32	\$37.73	\$0.00	\$0.00	\$37.73
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.47	\$4.44	\$0.00	\$72.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 5	<b>WORK ORDER TOTAL:</b>	<b>1.12</b>	<b>132.42</b>	<b>25.21</b>	<b>2.00</b>	<b>159.63</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/16/2021 10:15:35	09/16/2021 10:17:23	0.03	\$3.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/16/2021 10:01:45	09/16/2021 10:36:34	0.58	\$68.47
66-17-030	PERFORM TIRE PATCH	11901357	09/16/2021 10:39:27	09/16/2021 10:50:59	0.19	\$22.68
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/16/2021 10:39:10	09/16/2021 10:58:21	0.32	\$37.73
					<b>LABOR</b>	<b>132.42</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	1	\$4.44
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	2	\$0.96
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	21601	TR 600 HP WIDE VALVE STEM	0.77	1	\$0.77
					<b>PARTS</b>	<b>25.21</b>

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 41044

---

## Work Order Notes

(LISAPATE) PM-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-17-030 - PERFORM TIRE PATCH**

(AGUERRA) Repaired L/F tire, balanced and rechecked for leak, all good. AMG SH

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires adjusted tire pressure and inspected brakes. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 92752. Vehicle has been driven 1459 miles since last PM. Checked fluids added 1 QT of oil. Checked battery tire pressure found a screw in the left rear tire. Updated oil change sticker. SH AMG

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 42525

USING DEPT NO:	504104	OPENED DATE:	03/02/2022 11:21:23	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2022 11:02:24	METER 1 - M:	94143	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2022 14:09:17	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.26	\$31.14	\$15.18	\$0.00	\$46.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.46	\$38.44	\$0.00	\$99.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.78</b>	<b>92.60</b>	<b>53.62</b>	<b>2.00</b>	<b>148.22</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/02/2022 11:28:32	03/02/2022 11:59:47	0.52	\$61.46
03-51-038	REPLACE NEW WIPER BLADES	11310047	03/02/2022 13:41:05	03/02/2022 13:56:55	0.26	\$31.14
<b>LABOR</b>					<b>92.60</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.33	1	\$5.33
<b>PARTS</b>					<b>53.62</b>	

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 42525

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(EHOWELL) Replaced wipers. EH

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles:94143 Completed PM bottomside, Ethan was topside. Completed checklist. EH/AMG

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 236915      **2006 FORD E250**

**WORK ORDER NO:** 43588

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 06/09/2022 14:27:53	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/14/2022 09:08:52	<b>METER 1 - M:</b> 95315 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/16/2022 09:23:22	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-31-001	REPLACE NEW ALTERNATOR	DON	O	N	GARAGE	0.72	\$85.52	\$164.69	\$0.00	\$250.21
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	O	N	GARAGE	0.31	\$36.12	\$65.21	\$0.00	\$101.33
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.28	\$33.11	\$0.00	\$0.00	\$33.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **1.31**      **154.75**      **229.90**      **2.00**      **386.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-31-001	REPLACE NEW ALTERNATOR	11213180	06/10/2022 09:50:08	06/10/2022 10:33:37	0.72	\$85.52
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	11213180	06/10/2022 10:33:44	06/10/2022 10:52:06	0.31	\$36.12
35-32	DIAGNOSE CRANKING SYSTEM	11213180	06/10/2022 11:59:37	06/10/2022 12:16:27	0.28	\$33.11
					<b>LABOR</b>	<b>154.75</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK060984	BELT	65.21	1	\$65.21
03-31-001	REPLACE NEW ALTERNATOR	REM23827	REBUILT ALTERNATOR	164.69	1	\$164.69
					<b>PARTS</b>	<b>229.90</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 43588

---

## Work Order Notes

(LISAPATE) Gauges and radio were cutting out

---

## Job Notes

### **03-31-001 - REPLACE NEW ALTERNATOR**

(MSIDES) Replaced alternator rechecked ok. MS

### **03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.**

(MSIDES) Replaced belt. MS

### **35-32 - DIAGNOSE CRANKING SYSTEM**

(MSIDES) Found alternator to be over charging at 23.2 volts unit will need alternator replaced. MS

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 44184

USING DEPT NO:	504104	OPENED DATE:	08/05/2022 07:06:58	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	08/08/2022 13:15:16	METER 1 - M:	96014	METER 2 - N:	0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/08/2022 14:03:24	IN-SERVICE DATE:	11/06/2006		
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.98	\$15.03	\$0.00	\$20.01
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.61	\$18.27	\$0.00	\$50.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.32</b>	<b>37.59</b>	<b>33.30</b>	<b>2.00</b>	<b>72.89</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/05/2022 07:15:15	08/05/2022 07:31:50	0.28	\$32.61
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/05/2022 07:32:01	08/05/2022 07:34:33	0.04	\$4.98
<b>LABOR</b>					<b>37.59</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	2	\$12.18
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.52	2	\$15.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	(2)	(\$12.18)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	3	\$18.27
<b>PARTS</b>					<b>33.30</b>	

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 44184

---

## Work Order Notes

(IFALLS) PM

---

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 1871 miles since the last PM, Checked fluids (added 3 quarts of oil did not see any leaks) battery tire pressure and updated the oil change sticker. SH AMG

### CH-SP - CHARGE Shop Supplies

---



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 45865

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 01/23/2023 07:06:09	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/21/2023 08:59:16	<b>METER 1 - M:</b> 97702 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/21/2023 13:23:41	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.77	\$15.63	\$0.00	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.73	\$43.47	\$0.00	\$73.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.28</b>	<b>33.50</b>	<b>59.10</b>	<b>5.00</b>	<b>97.60</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/23/2023 07:10:14	01/23/2023 07:25:21	0.25	\$29.73
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/23/2023 07:25:21	01/23/2023 07:27:16	0.03	\$3.77
<b>LABOR</b>					<b>33.50</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
<b>PARTS</b>					<b>59.10</b>	

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 45865

---

## Work Order Notes

(EHANNAH) pm- replace wipers

(GARAGE) replaced wipers-GC Also needs new front shocks, going to bring back when shocks come in.-GC

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) replaced wipers-GC

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC-AMG checked fluids and tires and tire pressure

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 47368

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 06/15/2023 07:41:59	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/21/2023 09:55:21	<b>METER 1 - M:</b> 99424 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/21/2023 13:07:18	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-16-003	REPLACE NEW FRONT SHOCK ABSORBER	DON	O	N	GARAGE	0.51	\$60.61	\$87.39	\$0.00	\$148.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.93	\$32.09	\$0.00	\$64.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.42	\$49.82	\$0.00	\$0.00	\$49.82

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>1.21</b>	<b>142.36</b>	<b>119.48</b>	<b>5.00</b>	<b>266.84</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/15/2023 07:54:16	06/15/2023 08:10:30	0.27	\$31.93
WA-00	WASH COMPLETE VEHICLE	11074414	06/15/2023 08:07:15	06/15/2023 08:32:35	0.42	\$49.82
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	12052187	07/17/2023 13:05:13	07/17/2023 13:36:02	0.51	\$60.61
					<b>LABOR</b>	<b>142.36</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	10.70	3	\$32.09
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	FCS341577	FRONT SHOCKS	43.70	2	\$87.39
					<b>PARTS</b>	<b>119.48</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 47368

---

## Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash  
(EHANNAH) needs springs- add 3 qtrs. of oil on oil change.  
(EKIMBREL) did not need wipers yet

---

## Job Notes

### **03-16-003 - REPLACE NEW FRONT SHOCK ABSORBERS**

(GARAGE) replaced front shocks. JAW,GC

### **03-51-038 - REPLACE NEW WIPER BLADES**

### **66-79-003 - PERFORM SAFETY INSPECTION**

### **66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM- GC, Fluid check only, vehicle driven 1,586 miles, filter good, tires and tire pressure, updated oil change sticker.

Note- Checked oil and oil was low, SH, had to add 3 quarts of oil to vehicle.

Miles, 99,424

(GARAGE) JAW checked for leaks, found oil seeping front valve covers but no leaks.

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed the vehicle. SH

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 47741

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 07/26/2023 09:13:37	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/26/2023 14:16:57	<b>METER 1 - M:</b> 99986 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 08/07/2023 08:05:54	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.53	\$62.28	\$352.17	\$0.00	\$414.45
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.04	\$5.21	\$0.00	\$0.00	\$5.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.57</b>	<b>67.49</b>	<b>352.17</b>	<b>5.00</b>	<b>424.66</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	12052187	07/26/2023 10:50:01	07/26/2023 10:52:40	0.04	\$5.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	07/26/2023 10:52:59	07/26/2023 11:24:39	0.53	\$62.28
<b>LABOR</b>					<b>67.49</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.72	2	\$1.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	173.63	2	\$347.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	1	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.31	1	\$1.31
<b>PARTS</b>					<b>352.17</b>	

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 47741

---

## Work Order Notes

(EKIMBREL) perform service call

---

## Job Notes

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) Mounted and balanced 2 tires. Put the new tires on the rear moved the right rear to the left front. Installed the spare back under the vehicle. SH

### **66-79-002 - PERFORM SERVICE CALL**

(GARAGE) went on service call and installed spare tire on the lf. Driver brought unit back to shop. Both tires on drivers side needs replaced. JAW

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 47833

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 08/04/2023 11:24:42	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/08/2023 13:47:05	<b>METER 1 - M:</b> 100114 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/09/2023 07:46:30	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.08	\$9.08	\$8.94	\$0.00	\$18.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.08** **9.08** **8.94** **5.00** **23.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	08/04/2023 11:52:08	08/04/2023 11:56:45	0.08	\$9.08
<b>LABOR</b>					<b>9.08</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	6.65	1	\$6.65
66-17-030	PERFORM TIRE PATCH	21601	TR 600 HP WIDE VALVE STEM	0.72	1	\$0.72
66-17-030	PERFORM TIRE PATCH	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-030	PERFORM TIRE PATCH	58107	WHEEL WEIGHT PFE 2.00	1.31	1	\$1.31
<b>PARTS</b>					<b>8.94</b>	

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 47833

---

**Work Order Notes**

(LISAPATE) Nail in LF tire

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(GARAGE) Patched the left front tire. SH

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 49406

USING DEPT NO:	504104	OPENED DATE:	01/09/2024 11:07:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/11/2024 09:40:36	METER 1 - M:	101608	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/17/2024 08:37:31	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.68	\$80.08	\$199.98	\$0.00	\$280.06
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.05	\$5.47	\$0.00	\$0.00	\$5.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.73</b>	<b>85.55</b>	<b>199.98</b>	<b>5.00</b>	<b>290.53</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12201267	01/10/2024 08:12:35	01/10/2024 08:53:18	0.68	\$80.08
66-79-002	PERFORM SERVICE CALL	12201267	01/10/2024 08:56:11	01/10/2024 08:58:58	0.05	\$5.47
<b>LABOR</b>					<b>85.55</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	651	BATTERY BCI 65 750CCA	199.98	1	\$199.98
<b>PARTS</b>					<b>199.98</b>	

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 49406

---

## Work Order Notes

(EHANNAH) service call for dead battery

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(GRCOOK) Had to replace battery in unit, 5874B, did a service call on it for dead battery, tested battery when got it back to shop and it said to replace, installed new battery and tested volts, volts was 14.62. No issues. -GC  
Miles, 101,608

### **06-32-002 - INSPECT BATTERY**

### **66-79-002 - PERFORM SERVICE CALL**

(GRCOOK) Went on service call for dead battery on unit 5874B, jumped unit off and brought back to shop, tested battery and battery tested bad, going to have to replace battery.  
-GC

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 49456

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 01/11/2024 15:15:28	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/25/2024 10:53:38	<b>METER 1 - M:</b> 101608 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/26/2024 07:04:19	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	D	N	GARAGE	0.05	\$5.64	\$0.00	\$0.00	\$5.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.05	\$6.42	\$0.00	\$0.00	\$6.42

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.10</b>	<b>12.06</b>	<b>0.00</b>	<b>5.00</b>	<b>17.06</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	01/25/2024 07:37:17	01/25/2024 07:40:33	0.05	\$6.42
25-52-021	REMOVE GPS SYSTEM	11915538	01/25/2024 07:40:33	01/25/2024 07:43:25	0.05	\$5.64
					<b>LABOR</b>	<b>12.06</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 49456

---

**Work Order Notes**

(EHANNAH) prep for sale

---

**Job Notes**

**25-52-021 - REMOVE GPS SYSTEM**

(GARAGE) removed GPS#5041373014

**CH-SP - CHARGE Shop Supplies**

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) removed wordmarks and tag\RC

---

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 5685

USING DEPT NO:	504104	OPENED DATE:	04/27/2010 10:26:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2010 14:36:43	METER 1 - M:	24301	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2010 14:36:44	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$710.60	\$710.60
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$37.86	\$0.00	\$52.24
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$51.65	\$0.00	\$69.48

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.56</b>	<b>89.71</b>	<b>89.51</b>	<b>710.60</b>	<b>889.82</b>
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	123214	0007625	\$710.60
<b>COMML</b>					<b>710.60</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11046945	04/27/2010 17:18:36	04/27/2010 17:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11046945	04/27/2010 17:00:00	04/27/2010 17:18:36	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11046945	04/30/2010 07:00:00	04/30/2010 08:00:00	1.00	\$57.50
<b>LABOR</b>					<b>89.71</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.34	1	\$5.34
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	16.85	1	\$16.85
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	2.58	1	\$2.58
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	18.93	2	\$37.86
<b>PARTS</b>					<b>89.51</b>	

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 5685

---

## Work Order Notes

(LPATE) PM-REPLACE WIPERS  
(LPATE) NEEDS 4 TIRES AND ALIGN

---

## Job Notes

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED P0027985

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) replaced wipers

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO FIRESTONE BY BB

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 51372 FILTER-OIL Qty 1 Cost 0  
Part 5W20 OIL BOTTLE Qty 224 Cost 0  
Part FA1632 FILTER-AIR Qty 1 Cost 0  
(LPATE) pm-by bb-replaced air filter

# Work Order Charge Detail

UNIT NO: 236915 2006 FORD E250

WORK ORDER NO: 6310

USING DEPT NO:	504104	OPENED DATE:	07/22/2010 14:07:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/23/2010 07:01:51	METER 1 - M:	26008	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/23/2010 07:01:54	IN-SERVICE DATE:	11/06/2006	
TECH SPEC NO:	06VNFORDE250	2006 Ford E250		UNIT SERIAL NO:	1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$15.73	\$31.39	\$0.00	\$47.12

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.27</b>	<b>15.73</b>	<b>31.39</b>	<b>0.00</b>	<b>47.12</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	07/22/2010 14:15:25	07/22/2010 14:31:50	0.27	\$15.73

**LABOR 15.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88

**PARTS 31.39**

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 6310

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY TM

---



# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 703

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 01/22/2008 14:42:31	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/22/2008 14:44:18	<b>METER 1 - M:</b> 9069 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/22/2008 14:44:24	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$30.98	\$0.00	\$30.98

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.00 0.00 30.98 0.00 30.98**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.46	1	\$7.46
					<b>PARTS</b>	<b>30.98</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 703

---

**Work Order Notes**

(RWINTERS) NEEDS PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(RWINTERS) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 7779

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 02/18/2011 13:50:48	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/21/2011 08:25:20	<b>METER 1 - M:</b> 29753 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/21/2011 08:25:21	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$39.09	\$0.00	\$53.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$32.70	\$0.00	\$50.53

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.56** **32.21** **71.79** **0.00** **104.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11338644	02/18/2011 17:18:36	02/18/2011 17:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11338644	02/18/2011 17:00:00	02/18/2011 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>32.21</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.55	2	\$39.09
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	4.67	1	\$4.67
					<b>PARTS</b>	<b>71.79</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 7779

---

**Work Order Notes**

(RWINTERS) pm

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY RS/IF-ADDED ANITFREEZE

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 9084

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 09/09/2011 08:52:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/12/2011 11:19:19	<b>METER 1 - M:</b> 33857 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/12/2011 11:19:22	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250 2006 Ford E250		<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$83.52	\$0.00	\$112.27
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$39.27	\$0.00	\$53.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$60.15	\$0.00	\$77.98

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.06</b>	<b>60.96</b>	<b>182.94</b>	<b>0.00</b>	<b>243.90</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11338644	09/09/2011 17:33:36	09/09/2011 18:03:36	0.50	\$28.75
03-51-038	REPLACE NEW WIPER BLADES	11338644	09/09/2011 17:18:36	09/09/2011 17:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/09/2011 17:00:00	09/09/2011 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>60.96</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.41	1	\$14.41
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	2.64	1	\$2.64
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
03-32-002	REPLACE NEW BATTERY	65A	BATTERY TOP POST FORD	83.52	1	\$83.52
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	5.22	1	\$5.22
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.64	2	\$39.27
					<b>PARTS</b>	<b>182.94</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 9084

---

**Work Order Notes**

(LPATE) PM-REPLACE WIPERS-REPLACE BATTERY FAILED TEST

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LPATE) REPLACED BATTERY

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 6418 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY RS/SH-REPLACED AIR FILTER AND OIL DRAIN PLUG

---

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 9621

<b>USING DEPT NO:</b> 504104	<b>OPENED DATE:</b> 11/07/2011 14:03:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/08/2011 15:23:13	<b>METER 1 - M:</b> 34939 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/08/2011 15:23:15	<b>IN-SERVICE DATE:</b> 11/06/2006
<b>TECH SPEC NO:</b> 06VNFORDE250      2006 Ford E250	<b>UNIT SERIAL NO:</b> 1FTNE24W36DB38571	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.50</b>	<b>28.75</b>	<b>0.00</b>	<b>0.00</b>	<b>28.75</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11413680	11/07/2011 17:00:00	11/07/2011 17:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

# Work Order Charge Detail

**UNIT NO:** 236915 2006 FORD E250

**WORK ORDER NO:** 9621

---

**Work Order Notes**

(LPATE) DRIVER HAD A NAIL IN RIGHT REAR TIRE DID NOT GO ALL THE WAY IN WAS SMALL. NOTICED TIRES NEEDED ROTATED DUE TO WEAR.

---

**Job Notes**

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LPATE) ROTATED TIRES

---



# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Jan 26 2024 15:06:05 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '1FTNE24W36DB38571') //Q=