The University of Alabama

UNIT NO:	NO: 234742 2004 FOF			RD E250					WORK OR		: 10	0273		
WO STATUS WO VISIT R	USING DEPT NO:504191NO STATUS:CLOSEDNO VISIT REASON:SCHEDULEDTECH SPEC NO:04VNFORDE250200JOB CODEJOB DESCRIPTION			OPENE COMPL CLOSE	ETED D DAT	DATE:	02/09/20	012 07:59:15 012 11:35:01 012 11:35:02	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 144615 DATE :	M 02/21/20	ty Automotive S ETER 2 - N: 107 4W74HA60444	0	
	_			<u>STAT</u>	<u>RSN</u>	WRTY				MATE		OMMERCIAL	TOTAL	COST
03-51-038 66-PM-PMA		E NEW WIPER BLA M OIL CHANGE	ADES	DON DON	N P	N N	GARAGE GARAGE		\$14.38 \$17.83	\$39.12 \$36.88).00).00	\$53.50 \$54.71	
JOB COUN	T: 2				wo	RK ORI	DER TOTAL	.: 0.56	6 32.2	21	76.00	0.00		108.21
Job Code		Job Descript	ion		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		1	1413680	1	0	2/08/2012 17:18:36	6 02/08/2012	2 17:33:36		0.25		\$14.38
66-PM-PMA	PERFORM (DIL CHANGE		1	1413680	1	0	2/08/2012 17:00:00	02/08/2012	2 17:18:36		0.31		\$17.83
												LABOR		32.21
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	scription	<u>।</u>	Jnit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (DIL CHANGE		В	ALB329		C	IL FILTER			4.69	1		\$4.69
66-PM-PMA	PERFORM	DIL CHANGE		5	W20		C	DIL BOTTLE			0.12	224		\$26.88
03-51-038	REPLACE N	EW WIPER BLADES		6	0-2040		V	VIPER BLADE			19.56	2		\$39.12
66-PM-PMA	PERFORM	DIL CHANGE		A	NTIFRE	EZE GOL	D A	NTIFREEZE-FOR	C		5.31	1		\$5.31
												PARTS		76.00

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 10273

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 1372 FILTER-OIL Qty 1 Cost 0 Part 5W20 OIL BOTTLE Qty 224 Cost 0 (LPATE) PM BY RT/RS

The University of Alabama

UNIT NO:		234742	2004 FORI	D E250)				WORK OR		: 1	11181	
USING DEPT WO STATUS WO VISIT RE TECH SPEC	ASON:	504191 CLOSED SCHEDULED 04VNFORDE250		OPENE COMPL CLOSE	ETED	DATE:	06/11/201	12 10:12:19 2 07:17:16 12 07:17:17	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 17766 DATE:	N 02/21/2	ity Automotive S /ETER 2 - N: 007 24W74HA60446	0
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	<u>RIAL</u>	COMMERCIAL	TOTAL COST
03-34-002	REPLAC	E NEW LAMPS-RE	AR,TAIL,STO	DON	Ν	Ν	GARAGE	0.30	\$17.25	\$1.57	\$	60.00	\$18.82
JOB COUNT	: 1				WO	RK ORI	DER TOTAL:	0.30) 17.:	25	1.57	0.00	18.82
Job Code		Job Descripti	on		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>F</u>	<u>inish</u>		<u>Quantity</u>	Total Cost
03-34-002	REPLACE N	EW LAMPS-REAR, TA	IL,STOP,TURN	I,ETC 1	0260422	2	06	/08/2012 17:00:00	06/08/2012	2 17:18:00		0.30	\$17.25
												LABOR	17.25
Job Code		<u>Job Descripti</u>	on			Part No	<u>.</u>	Des	scription	<u>l</u>	Jnit Price	<u>Quantity</u>	Total Cost
03-34-002	REPLACE N	EW LAMPS-REAR, TA	IL,STOP,TURN	I,ETC 3	157		BL	JLB-BRAKE/TURN	N/PARK		1.5		\$1.57
												PARTS	1.57

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250
----------	--------	----------------

WORK ORDER NO:

11181

Work Order Notes

(LPATE) PER DRIVER LEFT TURN SIGNAL IS OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT REAR TURN SIGNAL

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR	DER NO:	11	271		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED I D DATE	DATE:	06/22/201	2 07:47:19 2 08:05:20 2 08:05:22	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	17766 DATE: 02	ме 2/21/200		0	
JOB CODE		JOB DESCRIPTION	<u>NO</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIA	<u>L CC</u>	OMMERCIAL	TOTAL C	: <u>OST</u>
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$17.83	\$54.94	\$0.	.00	\$72.77	
JOB COUN	Т: 1				wo	RK ORI	DER TOTAL:	0.31	17.8	3 54	l.94	0.00		72.77
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	nish		Quantity	<u>Total C</u>	ost
66-PM-PMA	PERFORM	DIL CHANGE		1	0260422		06/	21/2012 17:00:00	06/21/2012	17:18:36		0.31		\$17.83
												LABOR		17.83
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	cription	<u>Unit</u>	Price	<u>Quantity</u>	Total C	;ost
66-PM-PMA	PERFORM	DIL CHANGE		5	W20FS		HA	VOLINE 5W20 FL	JLLSYN OIL BULI	<	5.66	7		\$39.59
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		OIL	FILTER			4.74	1		\$4.74
66-PM-PMA	PERFORM	DIL CHANGE		1	198		OIL	DRAIN PLUG FO	ORD		10.61	1		\$10.61
												PARTS		54.94

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	11271
Work Order Note	<u>es</u>			
(LPATE) PM				
Job Notes				
66-PM-PMA - PERF	ORM OIL CHANGE			
(LPATE)				
Parts For Job Includ Part 5W20 OIL BOT Part 1372 FILTER-O	TLE Qty 224 Cost 0)		

(LPATE) PM BY GM/SH-REPLACED OIL DRAIN PLUG

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR	DER NO:	1	3074	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED I	DATE:	02/20/201	3 08:42:51 3 08:08:50 3 08:08:52	LOCATION: METER 1 - M IN-SERVICE I UNIT SERIAL	19770 DATE:	M 02/21/20		0
JOB CODE	L	JOB DESCRIPTIO	<u>NO</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	RIAL C	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$17.83	\$56.78	\$	0.00	\$74.61
JOB COUN	Т: 1				wo	RK ORI	DER TOTAL:	0.31	17.8	3	56.78	0.00	74.
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	<u>nish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		1	0260422	2	02/	19/2013 11:01:59	02/19/2013	11:20:35		0.31	\$17.
												LABOR	17.
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	cription	<u>U</u>	nit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM (DIL CHANGE		т	20		TE	CHRON 200Z FU	IEL ADDITIVE		12.1	1 1	\$12
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		OIL	FILTER			5.19	9 1	\$5.
66-PM-PMA	PERFORM	DIL CHANGE		5	W20FS		HA	VOLINE 5W20 FU	JLLSYN OIL BUL	к	5.64	4 7	\$39
												PARTS	56.

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	13074
Work Order Note	<u>s</u>			
(LPATE) PM				
Job Notes				
66-PM-PMA - PERFO	ORM OIL CHANGE			
(LPATE)				
Parts For Job Include Part 5W20FS HAVOL (LPATE) PM BY GM	-	N. OIL QT Qty 7 Cost 3.7675		

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR	DER NO:	: 1	14254	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED I D DATE	DATE:	07/03/201	3 09:20:04 3 13:23:05 3 13:23:06	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	: 20941 DATE:	N 02/21/2	ity Automotive S /ETER 2 - N: 2007 24W74HA60446	0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTIC	<u>NC</u>	<u>STAT</u> DON	RSN P	WRTY N	JOB LOC	LABOR HRS	LABOR \$17.83	<u>MATEF</u> \$57.33		COMMERCIAL	TOTAL COST \$75.16
JOB COUN	IT: 1				WO	rk ori	DER TOTAL:	0.31	17.8	3	57.33	0.00	75.1
Job Code 66-PM-PMA	PERFORM	Job Descripti DIL CHANGE	on	1	<u>Em</u> 0260422	ployee		<u>Start</u> 02/2013 10:19:40		<u>nish</u> 10:38:16		Quantity 0.31	<u>Total Cost</u> \$17.8 17.8
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	cription	<u>U</u>	Init Price		Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		5	W20FS		HA	VOLINE 5W20 FL	JLLSYN OIL BUL	К	5.6	57 7	\$39.6
66-PM-PMA	PERFORM (DIL CHANGE		В	ALB329		OIL	FILTER			5.5	53 1	\$5.5
66-PM-PMA	PERFORM	DIL CHANGE		T	20		TE	CHRON 200Z FU	IEL ADDITIVE		12.1	1 1	\$12.1
												PARTS	57.3

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO	: 234742	2004 FORD E250	WORK ORDER NO:	14254	
Work Ord	er Notes				
(LPATE) PM					
Job Note	<u>8</u>				

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675 (LPATE) PM BY GM/RS

The University of Alabama

UNIT NO:		234742	2004 FORD	E250					١		DER NO): 14	4972		
USING DEF	PT NO:	504191	0	PENE	D DAT	E:	09/24/201	3 11:40:37	L	LOCATION:	GARAGE	- Universit	y Automotive	Services	
WO STATU	S:	CLOSED	С	OMPL	ETED	DATE:	09/25/201	3 07:51:41	Ν	METER 1 - M:	21806	М	ETER 2 - N:	0	
WO VISIT F	REASON:	SCHEDULED	С	LOSE	D DATI	E:	09/25/201	3 07:51:42	I	IN-SERVICE D	ATE:	02/21/20	07		
TECH SPEC	C NO:	04VNFORDE250	2004 FC	ORD E2	250				ι	UNIT SERIAL	NO:	1FTNE2	4W74HA6044	6	
JOB CODE	E	JOB DESCRIPTIC	<u>)N</u>	STAT	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HI	RS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL CO	OST
03-51-046	REPLAC	E NEW KEY BLANK	((S)	DON	0	Ν	GARAGE	0	.00 \$	\$0.00	\$5.04	\$0	0.00	\$5.04	
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0	.00	0.00)	5.04	0.00)	5.04
Job Code		Job Descripti	<u>on</u>			<u>Part No</u>	<u>.</u>	ļ	Desci	<u>ription</u>		<u>Unit Price</u>	Quantity	Total Co	<u>ost</u>
03-51-046	REPLACE N	IEW KEY BLANK(S)		KE	EY BLAI	NK	KE	Y BLANK				2.52	2		\$5.04
													PARTS		5.04

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	14972
Work Order Note	<u>es</u>			
(LPATE) DRIVER RE	QUESTED 2 KEYS			
Job Notes				
03-51-046 - REPLAC	E NEW KEY BLAN	K(S)		
(LPATE) CUT AND G	AVE DRIVER 2 KEY	/S		

The University of Alabama

UNIT NO:	JNIT NO: 234742 2004 FO			D E250)				WORK O): 1	1560		
WO STATU: WO VISIT R	USING DEPT NO:504191WO STATUS:CLOSEDWO VISIT REASON:SCHEDULEDTECH SPEC NO:04VNFORDE250JOB CODEJOB DESCRIPTION			OPENED DATE: 06/23/2008 10:25: COMPLETED DATE: 06/23/2008 10:28: CLOSED DATE: 06/23/2008 10:28: 2004 FORD E250 Of the second						: GARAGE M: 8623 E DATE: Al NO:	N 02/21/2	iversity Automotive Services METER 2 - N: 0 /21/2007 TNE24W74HA60446		
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL O	COMMERCIAL	TOTAL COST	
03-51-038	REPLAC	E NEW WIPER BLADE	S	DON	Ν	Ν	GARAGE	0.25	\$11.25	\$30.60	\$	60.00	\$41.85	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$13.95	\$30.97	\$	60.00	\$44.92	
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL	.: 0.56	6 25	.20	61.57	0.00	86.77	
Job Code		Job Description			Em	nployee	<u>No.</u>	<u>Start</u>	ļ	Finish		Quantity	Total Cost	
03-51-038	REPLACE N	EW WIPER BLADES		11	1088474		06	6/23/2008 10:44:36	6 06/23/200	08 10:59:36		0.25	\$11.25	
66-PM-PMA	PERFORM (DIL CHANGE		11	1088474		00	6/23/2008 10:26:00	06/23/200	08 10:44:36		0.31	\$13.95	
												LABOR	25.20	
Job Code		Job Description				Part No	<u>.</u>	Des	scription		Unit Price	<u>e</u> <u>Quantity</u>	Total Cost	
66-PM-PMA	PERFORM	DIL CHANGE		5\	N20		0	IL BOTTLE			0.1	1 224	\$23.52	
66-PM-PMA	PERFORM (DIL CHANGE		B	ALB329		0	IL FILTER			7.4	5 1	\$7.45	
03-51-038	REPLACE N	EW WIPER BLADES		60)-2040		W	IPER BLADE			15.3	0 2	\$30.60	
												PARTS	61.57	

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

1560

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:
Work Order Not	tes		
(RWINTERS) PM			
Job Notes			
03-51-038 - REPLA	CE NEW WIPER BL	ADES	
(RWINTERS) REPL	ACED THE WIPER	BLADES.	
66-PM-PMA - PERF	FORM OIL CHANGE		

(RWINTERS) The following parts are included with the standard job:

Part No: 51372Qty: 1Description: FILTER-OILManufacturer :

Part No : 5W20 Qty : 224 Description : MOTOR OIL Manufacturer :

(RWINTERS) PM BY JE

The University of Alabama

UNIT NO:		234742 2	004 FOR	D E250)				WORK OF) :	15953	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED	DATE:	01/31/20	14 11:07:53 14 11:20:30 14 11:20:31	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 22590 DATE:	I 02/21/2	sity Automotive 5 METER 2 - N: 2007 24W74HA6044	0
JOB CODE	L	JOB DESCRIPTION	<u>1</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLAD	ES	DON	0	Ν	GARAGE	0.25	\$14.38	\$26.97	5	\$0.00	\$41.35
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$17.83	\$44.84	9	\$0.00	\$62.67
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	: 0.56	5 32.	21	71.81	0.00	104.0
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		1	0260422	2	01	/27/2014 15:29:47	01/27/201	4 15:48:23		0.31	\$17.8
03-51-038	REPLACE N	EW WIPER BLADES		1	0260422	2	01	/27/2014 15:29:52	2 01/27/201	4 15:44:52		0.25	\$14.3
												LABOR	32.2
Job Code		Job Description	<u>n</u>			Part No	<u>.</u>	Des	scription		Unit Pric	<u>e</u> <u>Quantity</u>	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		4	0720A		W	IPER BLADE 20"			13.4	49 2	\$26.9
66-PM-PMA	PERFORM	DIL CHANGE		5	W20FS		HA	AVOLINE 5W20 FU	ULLSYN OIL BU	LK	5.6	67 7	\$39.6
66-PM-PMA	PERFORM (DIL CHANGE		В	ALB329		OI	L FILTER			5.7	151	\$5.2
												PARTS	71.8

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 15953

Work Order Notes

(LPATE) PM-REPLACED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78 (LPATE) PM BY GM/RS

The University of Alabama

UNIT NO:		234742	2004 FORD E250				WORK OF	DER NO:	1	7263		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	OPENED DA COMPLETEI CLOSED DA 2004 FORD E250	DATE:	06/13/20	14 11:04:14 14 07:00:05 14 07:00:06	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	: 23481 DATE :	M 02/21/20	ty Automotive S ETER 2 - N: 007 4W74HA60446	0	
JOB CODE 66-PM-PMA		JOB DESCRIPTIC	<u>DN STAT RSN</u> DON P	I <u>WRTY</u> N	GARAGE	LABOR HRS 0.33	LABOR \$19.02	<u>MATER</u> \$45.47		COMMERCIAL	TOTAL (\$64.49	<u>COST</u>
JOB COUN	IT: 1		w	ORK OR	DER TOTAL	: 0.33	19.	02	45.47	0.00		64.49
Job Code 66-PM-PMA	PERFORM	Job Descripti DIL CHANGE	<u>on E</u> 110744	mployee 14		<u>Start</u> 5/12/2014 06:37:30		inish 4 06:57:21		Quantity 0.33	<u>Total (</u>	\$19.02
Job Code	PERFORM	Job Descripti DIL CHANGE	on BALB32	Part No	_	Des L FILTER	scription	U	nit Price 5.15		<u>Total (</u>	19.02 Cost \$5.15
66-PM-PMA		DIL CHANGE	5W20F3			AVOLINE 5W20 FU	JLLSYN OIL BUI	_K	5.76			\$40.32 45.47

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 WORK ORDER NO: 2004 FORD E250 17263 UNIT NO: Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78 (LPATE) PM BY SH,GM/SH

The University of Alabama

UNIT NO:		234742 200	4 FOR	D E250					WORK		0: [/]	174	
WO STATUS WO VISIT R				OPENED DATE: 10/03/2007 11:22:56 COMPLETED DATE: 10/04/2007 11:25:00 CLOSED DATE: 10/04/2007 11:30:00 2004 FORD E250 E250						ON: GARAG 1 - M: 6673 /ICE DATE: RIAL NO:	ty Automotive Services I ETER 2 - N: 0 007 24W74HA60446		
JOB CODE	Ē	JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LAB	<u>OR MAT</u>	ERIAL	COMMERCIAL	TOTAL COST
35-32	DIAGNO	SE CRANKING SYSTEM	l	DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00	9	\$0.00	\$0.00
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$13.95	\$27.47	S	\$0.00	\$41.42
JOB COUN	IT: 2				wo		DER TOTAL:	0.31		13.95	27.47	0.00	41.42
Job Code		Job Description			<u>En</u>	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		1	1128904		10	/04/2007 09:00:00	10/04	/2007 09:18:36		0.31	\$13.95
												LABOR	13.95
Job Code		Job Description				Part No	<u>.</u>	Des	cription		Unit Pric	<u>e</u> <u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		5	W20		OI	L BOTTLE			0.0)9 224	\$20.16
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		OI	L FILTER			7.3	31 1	\$7.31
												PARTS	27.47

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

174

Work Order Notes

(LOBRIEN) SLOW/HARD TO CRANK.

Job Notes

35-32 - DIAGNOSE CRANKING SYSTEM

(LOBRIEN) CHECKED CHARGING SYSTEM AND STARTING SYSTEM-ALL WORKING PROPERLY. COULD NOT DUPLICATE PROBLEM.

66-PM-PMA - PERFORM OIL CHANGE

The University of Alabama

UNIT NO:		234742	2004 FORD E25	60			WORK ORD	ER NO:	18826	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	COMP	ED DATE: PLETED DATE: ED DATE: E250	11/20/201	4 09:47:48 4 07:54:24 4 07:54:25		24946 ATE: 02/2 ⁻	ersity Automotive S METER 2 - N: 1/2007 NE24W74HA60446	0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTIC	<u>DN</u> <u>STAT</u> DON		<u>JOB LOC</u> GARAGE	LABOR HRS 0.57	LABOR \$32.63	MATERIAL \$45.47	COMMERCIAL \$0.00	<u>TOTAL COST</u> \$78.10
JOB COUN	IT: 1			WORK ORI	DER TOTAL:	0.57	32.63	45.47	7 0.00	78.10
Job Code 66-PM-PMA	PERFORM	Job Descripti Dil Change		<u>Employee</u> 11338644		<u>Start</u> 19/2014 11:09:18	<u>Fini</u> 11/19/2014 11		Quantity 0.57 LABOR	Total Cost \$32.63 32.63
Job Code		Job Descripti	on	Part No	<u>.</u>	Des	cription	<u>Unit Pr</u>	rice Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE		5W20FS	HA	OLINE 5W20 FU	JLLSYN OIL BULK		5.76 7	\$40.32
66-PM-PMA	PERFORM	DIL CHANGE		BALB329	OIL	FILTER			5.15 1 PARTS	\$5.15 45.47

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250 WORK ORDER NO:

RDER NO: 18826

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78 (LPATE) PM BY RS,NT/RS

The University of Alabama

UNIT NO:	234742	2004 FORD E250					D: 19	680	
USING DEPT N WO STATUS: WO VISIT REAS TECH SPEC NO	CLOSED SON: SCHEDULED	COMPL	D DATE: ETED DATE: D DATE: 250	03/03/2015 08:: 03/04/2015 07:: 03/04/2015 07::	28:38 28:39	LOCATION: GARAGI METER 1 - M: 25571 IN-SERVICE DATE: UNIT SERIAL NO:	ME 02/21/200		0
JOB CODE 03-51-038	JOB DESCRIPTI REPLACE NEW WIPER BL		RSN WRTY	JOB LOC LAE GARAGE	OR HRS 0.25	LABOR MAT \$14.38 \$35.94	ERIAL <u>CC</u> \$0.	DMMERCIAL .00 S	TOTAL COST \$50.32
JOB COUNT:	1		WORK ORI	DER TOTAL:	0.25	14.38	35.94	0.00	50.32
<u>Job Code</u> 03-51-038 RE	Job Descrip EPLACE NEW WIPER BLADES		Employee 213180		<u>Start</u> 5 08:25:24	<u>Finish</u> 03/03/2015 08:40:24		Quantity 0.25 LABOR	<u>Total Cost</u> \$14.38 14.38
Job Code 03-51-038 RE	Job Descrip		<u>Part No</u> 0720A	-	Desc	ription	Unit Price 17.97	Quantity 2	<u>Total Cost</u> \$35.94
03-31-030 RE	EFLAGE NEW WIFER BLADES	5 40	11 ZUA		LADE 20		17.97	PARTS	35.94

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	19680
Work Order Note	<u>es</u>			
(LPATE) DRIVER RE	EQUESTED WIPERS	8		
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(LPATE) REPLACED	WIPERS			

The University of Alabama

UNIT NO:		234742	2004 FORD	E250)				WORK OR	DER NO): 2	0744		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	C	OMPL	ED DATI	DATE:	07/10/202	15 10:00:27 15 10:54:24 15 10:54:25	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 26554 DATE :	M 02/21/20	ity Automotive S I ETER 2 - N: 007 24W74HA60446	0	
JOB CODE	L	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	COMMERCIAL	TOTAL CO	ST
03-32-002	REPLACI	E NEW BATTERY		DON	Ρ	Ν	GARAGE	0.17	\$9.60	\$61.74	\$	0.00	\$71.34	
03-34-002	REPLACI	E NEW LAMPS-RE	AR,TAIL,STO	DON	0	Ν	GARAGE	0.10	\$5.67	\$0.51	\$	0.00	\$6.18	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.51	\$29.47	\$29.53	\$	0.00	\$59.00	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL	0.78	44.7	'4	91.78	0.00	13	86.52
Job Code		Job Descrip	tion		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	<u>nish</u>		Quantity	Total Cos	<u>st</u>
03-32-002	REPLACE N	EW BATTERY		1	1074414		07	/09/2015 10:45:10	07/09/2015	10:55:11		0.17	9	\$9.60
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN,E	TC 1	1074414		07	/09/2015 10:55:17	07/09/2015	11:01:12		0.10	\$	\$5.67
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		07	/09/2015 10:14:17	07/09/2015	10:45:02		0.51	\$2	29.47
												LABOR	4	4.74
Job Code		Job Descrip	tion			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cos	<u>st</u>
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN,E	TC 9	12		BL	JLB-BRAKE-3RD			0.5	1 1	5	\$0.51
03-32-002	REPLACE N	EW BATTERY		6	5-850		BA	ATTERY- FORD TO	OP POST HD		61.74	4 1	\$6	61.74
66-PM-PMA	PERFORM	DIL CHANGE		5	W20FS		HA	VOLINE 5W20 FL	JLLSYN OIL BUL	K	3.76	6 7	\$2	26.32
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		OI	L FILTER			3.2	11		\$3.21
												PARTS	9	91.78

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	20744
Work Order Not	<u>es</u>			
(LPATE) PM-3RD B	RAKE LIGHT OUT-N	EEDS A NEW BATTERY		
Job Notes				
03-32-002 - REPLA	CE NEW BATTERY			
(LPATE) REPLACE	D BATTERY			
03-34-002 - REPLA	CE NEW LAMPS-RE	AR,TAIL,STOP,TURN,ETC		
(LPATE) REPLACE	D LEFT SIDE 3RD BF	RAKE LIGHT		
66-PM-PMA - PERF	ORM OIL CHANGE			

(LPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78 (LPATE) PM BY SH

The University of Alabama

UNIT NO:		234742 2	2004 FOR	D E250)					WORK ORDER N	0:	22388	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004 F	OPENE COMPL CLOSE	ETED D DATI	DATE:	01/21/20	16 14:18:57 16 14:46:58 16 14:46:59	3	LOCATION: GARAG METER 1 - M: 2828 IN-SERVICE DATE: UNIT SERIAL NO:	5 I 02/21/2	sity Automotive S METER 2 - N: 2007 24W74HA60446	0
JOB CODE 03-51-038	_	JOB DESCRIPTION E NEW WIPER BLAD		<u>STAT</u> DON	<u>RSN</u> O	WRTY N	<u>JOB LOC</u> GARAGE		HRS 0.25			COMMERCIAL \$0.00	TOTAL COST \$31.44
JOB COUN	Т: 1				wo	RK ORI	DER TOTAL	:	0.25	14.38	17.06	0.00	31.44
<u>Job Code</u> 03-51-038	REPLACE N	Job Descriptio	<u>n</u>	1	<u>Em</u> 0260422	iployee		<u>Star</u> 1/21/2016 14:	_	<u>Finish</u> 01/21/2016 14:38:02		Quantity 0.25 LABOR	<u>Total Cost</u> \$14.38 14.38
Job Code		Job Descriptio	<u>n</u>			Part No	<u>.</u>		Des	cription	Unit Pric	<u>e Quantity</u>	Total Cost
03-51-038	REPLACE N	IEW WIPER BLADES		V	/W-2000	-PC	W	IPER BLADE	E 20"		8.9	53 2 PARTS	\$17.06 17.06

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	22388
Work Order Note	es			
(LISAPATE) DRIVER	R REQUESTED WIP	PERS		
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(LISAPATE) REPLA	CED WIPERS			

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

The University of Alabama

UNIT NO:	NIT NO: 234742 2004 FORD E) E25(250				WORK ORDER NO: 23			3462			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250		COMPI	ED DAT LETED ED DAT 250	DATE:	05/25/20	016 07:10:17 016 15:25:10 016 15:25:11	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 29226 DATE :	M 02/21/20		0	
JOB CODE	E	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOO	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	<u>TOTAL</u>	COST
03-13-001	REPLAC	E NEW FRONT BF	RAKES & ROT	DON	0	Ν	GARAGE	2.00	\$115.00	\$401.90	\$0).00	\$516.90	
03-13-002	REPLAC	E NEW REAR BRA	AKES & DRUN	DON	0	Ν	GARAGE	2.00	\$115.00	\$200.63	\$0	0.00	\$315.63	
66-17-028	PERFOR	M MOUNT AND B	ALANCE TIRE	DON	0	Ν	GARAGE	0.80	\$46.00	\$5.12	\$0).00	\$51.12	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	2.21	\$126.84	\$26.38	\$0).00	\$153.22	
PU-17	PURCHA	SED TIRES, TUBE	ES, LINERS &	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$5	518.47	\$518.47	
JOB COUN	NT: 5				wo		DER TOTA	L: 7.0'	402.8	34	634.03	518.47		1,555.34
Job Code		Job Descript	tion		v	endor N		Invoice No.	Purchas	e Order N	0			Cost
<u>900 000e</u> PU-17	PURCHASE	D TIRES, TUBES, LII		1	<u>*</u> 1122732			10700	0033495		<u>o.</u>		10101	\$518.47
		, - ,										COMML		518.47
Job Code		Job Descript	tion		En	nployee	No.	Start	F	inish		Quantity	Tota	Cost
66-17-028	PERFORM		CE TIRES	1	0260422			5/25/2016 06:00:00				0.80		\$46.00
03-13-002	REPLACE N	IEW REAR BRAKES	& DRUMS/ROTC	DRS 1	1213180)	C	5/25/2016 09:00:00	05/25/2016	3 11:00:00		2.00		\$115.00
03-13-001	REPLACE N	IEW FRONT BRAKES	S & ROTORS	1	1213180)	C	5/25/2016 07:00:00	0 05/25/2016	8 09:00:00		2.00		\$115.00
66-PM-PMA	PERFORM	OIL CHANGE		1	0260422	2	C	5/20/2016 08:00:49	9 05/20/2016	6 10:13:10		2.21		\$126.84
												LABOR		402.84
Job Code		Job Descript	tion			Part No	<u>.</u>	De	scription		Unit Price	Quantity	Tota	Cost
03-13-001	REPLACE N	IEW FRONT BRAKES	S & ROTORS	S	SKFBR15	5101	-	DUTER WHEEL BE	ARING		12.91	2		\$25.82
03-13-001	REPLACE N	IEW FRONT BRAKES	S & ROTORS	F	PTX2424	0	E	BLUE LOCTITE 1.2	2 OZ		18.99) 1		\$18.99
03-13-001	REPLACE N	IEW FRONT BRAKES	S & ROTORS	7	651831		Γ	DISC BRAKE LUBE			14.99) 1		\$14.99
66-PM-PMA	PERFORM	OIL CHANGE		5	W20FS		ŀ	AVOLINE 5W20 F	ULLSYN OIL BUL	K	0.10) 224		\$22.40
66-PM-PMA	PERFORM	OIL CHANGE		E	BALB329		(DIL FILTER			3.98	3 1		\$3.98
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	V	VHEEL V	VEIGHT	١	VHEEL WEIGHT K	NOCK ON		0.26	6 12		\$3.12
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	2	1597		٦	IRE VALVE TR 600) HP		0.50) 4		\$2.00
03-13-002	REPLACE N	IEW REAR BRAKES	& DRUMS/ROTC	ORS E	8RE0988	5811	E	BREMBO ROTOR			76.15	5 2		\$152.30

The University of Alabama

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	UP7673M	REAR BRAKE PADS	48.33	1	\$48.33
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS24000	GREASE SEALS	10.47	2	\$20.94
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	FT7535	BRAKE PAD SET FLEET HD FRT	54.22	1	\$54.22
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	15.52	2	\$31.04
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRE09801410	ROTORS	117.95	2	\$235.90
					PARTS	634.03

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 23462

Work Order Notes

(LISAPATE) PM-NEEDS 4 TIRES, WORN AND OUT OF DATE

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) BRAKES WERE EXCESSIVELY WORN. REMOVED AND REPLACED FRONT PADS, ROTORS, BEARINGS AND SEALS. PACKED BEARINGS WITH GREASE

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(LISAPATE) REPLACED REAR PADS AND ROTORS. TEST DROVE OK

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNTED AND BALANCED 4 NEW TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (LISAPATE) PM BY GM/SH

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 4 TIRES FROM FIRESTONE. PD BY CC

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR		D: 2	2383		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED UNSCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED	DATE:	11/13/200	08 11:30:12 08 13:19:39 08 13:19:43	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 9801 DATE :	N 02/21/2	ity Automotive \$ 1ETER 2 - N: 007 24W74HA6044	0	
JOB CODE	L	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	<u>ERIAL</u>	COMMERCIAL	TOTAL (COST
03-34-010	REPLAC	E NEW TAG LIGH	Г	DON	Ν	Ν	GARAGE	0.30	\$17.25	\$0.39	\$	0.00	\$17.64	
66-17-015	PERFOR	RM TIRE ROTATION	N	DON	Ν	Ν	GARAGE	0.50	\$28.75	\$0.00	\$	0.00	\$28.75	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$17.83	\$34.74	\$	0.00	\$52.57	
JOB COUNT: 3				WO	RK ORI	DER TOTAL:	1.11	63.8	33	35.13	0.00		98.96	
Job Code		Job Descrip	tion		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>F</u>	inish		<u>Quantity</u>	<u>Total (</u>	<u>Cost</u>
66-PM-PMA	PERFORM	OIL CHANGE		1	1089300)	11/	13/2008 12:00:00	11/13/2008	8 12:18:36		0.31		\$17.83
66-17-015	PERFORM	TIRE ROTATION		1	1089300)	11/	13/2008 12:36:36	11/13/2008	3 13:06:36		0.50		\$28.75
03-34-010	REPLACE N	IEW TAG LIGHT		1	1089300)	11/	/13/2008 12:18:36	11/13/2008	3 12:36:36		0.30		\$17.25
												LABOR		63.83
Job Code		Job Descrip	tion			Part No	<u>.</u>	Des	scription		Unit Price	<u>Quantity</u>	Total C	<u>Cost</u>
66-PM-PMA	PERFORM	OIL CHANGE		5	W20		OI	L BOTTLE			0.1	2 224		\$26.88
03-34-010	REPLACE N	IEW TAG LIGHT		19	94		BL	ILB-TAG/MARKEF	र		0.3	9 1		\$0.39
66-PM-PMA	PERFORM	OIL CHANGE		В	ALB329		OI	L FILTER			7.8	-		\$7.86
												PARTS		35.13

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO: 2383	
Work Order Not	tes			
(LPATE) PM-REPLA	ACE TAG LIGHT BUL	B -ROTATE TIRES		
Job Notes				
03-34-010 - REPLA	CE NEW TAG LIGH	г		
(LPATE) REPLACE	D TAG LIGHT BULB			
66-17-015 - PERFC	ORM TIRE ROTATION	ı		
(LPATE) ROTATED	TIRES			
66-PM-PMA - PERF	FORM OIL CHANGE			
(LPATE)				
Parts For Job Incluc Part 5W20 MOTOR Part 51372 FILTER- (LPATE) PM BY MS	OIL Qty 224 Cost 0 -OIL Qty 1 Cost 0			

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR	DER NO): 23	884	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250		COMPI	D DAT	DATE:	08/05/20	016 09:06:49 016 11:27:58 016 11:28:00	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 29622 DATE:	02/21/200	TER 2 - N:	0
JOB CODE	L	JOB DESCRIPTI	ON	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-15-025	REPLAC	E NEW SHIFT TUE	BE/BUSHINGS	DON	0	Ν	GARAGE	2.00	\$115.00	\$63.03	\$0.	00	\$178.03
03-42-002	REPLAC	E NEW RADIATOF	R	DON	0	Ν	GARAGE	0.59	\$34.15	\$286.81	\$0.	00	\$320.96
04-27-001	REPLACE RBLT CASE ASSEMBLY-AUT(D		DON	0	Ν	GARAGE	9.30	\$534.73	\$1,889.2	7 \$0.	00	\$2,424.00	
66-PM-PMT	PERFORM TRANSMISSION SERVICE		DON	Р	Ν	GARAGE	1.24	\$71.30	\$30.15	\$0.	00	\$101.45	
SO-05	SCAN O	UT ELECTRONIC E	ENGINE EEC	DON	0	Ν	GARAGE	9.78	\$562.13	\$0.55	\$0.	00	\$562.68
JOB COUN	IT: 5				wo		DER TOTAL	.: 22.91	1,317.3	31 2	,269.81	0.00	3,587.12
Job Code		Job Descript	tion		En	nployee	No.	Start	Fi	inish		Quantity	Total Cost
04-27-001		BLT CASE ASSEMB		TRAN: 1				7/28/2016 06:38:23				9.30	\$534.73
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	/ 1	1397026	5	0	7/29/2016 06:11:20	07/29/2016	6 15:57:54		9.78	\$562.13
03-15-025	REPLACE N	IEW SHIFT TUBE/BU	ISHINGS	1	1397026	5	0	8/03/2016 07:00:00	08/03/2016	6 09:00:00		2.00	\$115.00
03-42-002	REPLACE N	IEW RADIATOR		1	1397026	5	0	7/28/2016 06:02:41	07/28/2016	6 06:38:19		0.59	\$34.15
66-PM-PMT	PERFORM ⁻	TRANSMISSION SEF	RVICE	1	1397026	5	0	7/14/2016 14:38:21	07/14/2016	6 15:52:45		1.24	\$71.30
												LABOR	1317.31
Job Code		Job Descript	tion			Part No	<u>-</u>	Des	cription	<u> </u>	Unit Price	<u>Quantity</u>	Total Cost
SO-05	SCAN OUT		NE EEC SYSTEM	A A	TM20		F	USE-20 AMP MINI			0.55	1	\$0.55
03-42-002	REPLACE N	IEW RADIATOR		A	NTIFRE	EZE GOL	_D A	NTIFREEZE-FORD)		14.42	3	\$43.26
04-27-001		BLT CASE ASSEMB	LY-AUTOMATIC	TRAN: \	′V324		т	RANS FLUID QT			4.31	17	\$73.27
66-PM-PMT	PERFORM ⁻	TRANSMISSION SEF	RVICE	C	:111		R	ED BRAKE CLEAN	IER		2.78	1	\$2.78
04-27-001		BLT CASE ASSEMB	LY-AUTOMATIC	TRAN: 5	650160/	933663	4	R70W REMAN TRA	ANSMISSION		1816.00	1	\$1,816.00
03-15-025	REPLACE N	IEW SHIFT TUBE/BU	ISHINGS	4	C2Z7A1	10B	S	HIFT INDICATOR			55.41	1	\$55.41
66-PM-PMT	PERFORM TRANSMISSION SERVICE		1	15930		A	T FILTER KIT PREI	M RSR GASKET		27.37	1	\$27.37	
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS			F	F3TZ7L278A BUSHING					3.81	2	\$7.62	
03-42-002	REPLACE NEW RADIATOR			4	4C2Z7A095EA OIL COOLER					104.66	1	\$104.66	
03-42-002	REPLACE N	Т	YC1994		R	ADIATOR			138.89	1	\$138.89		

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

23884

Work Order Notes

(LISAPATE) VAN DOES NOT HAVE REVERSE

Job Notes

03-15-025 - REPLACE NEW SHIFT TUBE/BUSHINGS

(LISAPATE) REPLACED SHIFT TUBE INDICATOR AND BUSHINGS. RECHECKED OK

03-42-002 - REPLACE NEW RADIATOR

(LISAPATE) INSTALLED NEW RADIATOR AND TRANSMISSION COOLER, FLUSHED THE LINES. ADDED FLUID TEST DROVE OK

04-27-001 - REPLACE RBLT CASE ASSEMBLY-AUTOMATIC TRANS

(LISAPATE) REMOVED AND REPLACED THE TRANSMISSION WITH A REMAN UNIT FROM JASPER.

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(LISAPATE) Visit Reason Changed On 7/13/2016 9:07 AM By LISAPATE (LISAPATE) TRANSMISSION SERVICED THEN RECHECKED VAN WILL NEED TRANSMISSION REPLACED (RWINTERS) REMOVED VALVEBODY AND INSPECTED FOR DAMAGE. NONE FOUND.

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) SCAN OUT NO CODES, REMOVED TRANS PAN, FLUID LOKED BURNT, REMOVED THE VALVE BODY AND INSPECTED, NO ISSUES FOUND WITH THE VALVE BODY.

(LISAPATE) REPLACED 20AMP FUSE TO THE DLC TO SCAN OUT

The University of Alabama

UNIT NO:		234742	2004 FOR	D E25	0				WORK OF	RDER NO): 2	4326	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004 F	COMP	ED DAT LETED ED DAT 250	DATE:	09/14/20	16 11:19:08 16 08:21:02 16 08:21:03	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 29909 DATE:	M 02/21/20	ity Automotive S IETER 2 - N: 007 24W74HA60446	0
JOB CODE	E	JOB DESCRIPTI	ON	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	COMMERCIAL	TOTAL COST
03-34-002	REPLACI	E NEW LAMPS-RE	EAR,TAIL,STO	DON	0	Ν	GARAGE	0.30	\$17.25	\$27.86	\$0	0.00	\$45.11
66-PM-PMT	PERFOR	M TRANSMISSIO	N SERVICE	DON	Р	Ν	GARAGE	1.00	\$57.50	\$21.25	\$0	0.00	\$78.75
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	1.30	74.	75	49.11	0.00	123.86
Job Code		Job Descript	<u>tion</u>		<u>Em</u>	nployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		Quantity	Total Cost
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	I,ETC 1	1758845	i	09	/08/2016 11:20:22	09/08/201	6 11:38:22		0.30	\$17.25
66-PM-PMT	PERFORM T	RANSMISSION SEF	RVICE	1	1758845	i	09	/08/2016 11:19:37	09/08/201	6 12:19:37		1.00	\$57.50
												LABOR	74.75
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	Des	scription	<u> </u>	Unit Price	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMT	PERFORM T	RANSMISSION SEF	RVICE	١	/V324		TF	RANS FLUID QT			4.25	5 5	\$21.25
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	I,ETC 9	912		BL	JLB-BRAKE-3RD			0.49	9 1	\$0.49
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	I,ETC 1	15930		AT	FILTER KIT PRE	M RSR GASKET	г	27.37	7 1	\$27.37
												PARTS	49.11

234742 UNIT NO: 2004 FORD E250

WORK ORDER NO:

24326

Work Order Notes

(LISAPATE) LR 3RD BRAKE LIGHT OUT-SERVICE TRANSMISSION WAS REPLACED 500 MILES AGO

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) REPLACED LR 3RD BRAKE LIGHT

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(LISAPATE) Visit Reason Changed On 9/8/2016 11:19 AM By LISAPATE (LISAPATE) REPLACED TRANSMISSION FILTER AND GASKET. TEST DROVE RECHECKED FLUID OK

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250					WORK OR	DER NO):	25189	
USING DEPT WO STATUS WO VISIT RE TECH SPEC	EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE FORD E2	ETED D D DATE	ATE:	12/09/201	16 11:02:10 16 14:38:51 16 14:38:51	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 30679 DATE :	02/21/	sity Automotive S METER 2 - N: 2007 E24W74HA60446	0
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>		WRTY	JOB LOC	LABOR HRS	LABOR		ERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.31	\$17.83	\$35.44		\$0.00	\$53.27
JOB COUNT	Г: 1				WOF	rk ore	DER TOTAL	0.31	17.8	33	35.44	0.00	53.27
Job Code		Job Descript	ion		Em	oloyee	<u>No.</u>	<u>Start</u>	Fi	inish		<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		11	170580		12	/07/2016 07:00:00	12/07/2016	6 07:18:36		0.31	\$17.83
												LABOR	17.83
Job Code		Job Descript	ion		<u>F</u>	Part No	<u>.</u>	Des	scription		Unit Pric	e Quantity	Total Cost
66-PM-PMA	PERFORM (DIL CHANGE		PA	4878F		Al	R FILTER REPL 6	418		6.	94 1	\$6.94
66-PM-PMA	PERFORM	DIL CHANGE		5\	V20FS		HA	VOLINE 5W20 FU	JLLSYN OIL BUL	K	0.	10 224	\$22.4
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		OI	L FILTER			3.	98 1	\$3.9
66-PM-PMA	PERFORM	DIL CHANGE		C	111		RE	D BRAKE CLEAN	NER		2.	12 1	\$2.1
												PARTS	35.44

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250

WORK ORDER NO: 25189

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (LISAPATE) PM BY AB-REPLACED AIR FILTER 66-PM-PMT - PERFORM TRANSMISSION SERVICE

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR	DER NO):	26714		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004 F	OPENE COMPL CLOSE	ETED	DATE:	08/07/20	17 07:57:54 17 09:09:28 17 09:09:29	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	32439 DATE:	02/21/	rsity Automotive \$ METER 2 - N: 2007 E24W74HA60446	0	
JOB CODE		JOB DESCRIPTI		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL CO	<u>OST</u>
03-02-023	REPLAC	E NEW HANDLES	- INNER & OL	DON	0	Ν	GARAGE	1.00	\$57.50	\$178.18		\$0.00	\$235.68	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$17.83	\$17.42		\$0.00	\$35.25	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	: 1.31	75.3	3	195.60	0.00	2	270.93
Job Code		Job Descript	tion		<u>Em</u>	nployee	<u>No.</u>	<u>Start</u>	<u>Fii</u>	<u>nish</u>		<u>Quantity</u>	Total Co	ost
66-PM-PMA	PERFORM	DIL CHANGE		1	1758845		08	3/03/2017 07:00:00	08/03/2017	07:18:36		0.31	5	\$17.83
03-02-023	REPLACE N	EW HANDLES - INN	ER & OUTER	1	1170580		08	3/03/2017 07:00:00	08/03/2017	08:00:00		1.00	5	\$57.50
												LABOR		75.33
Job Code		Job Descript	tion			Part No	<u>.</u>	Des	scription	-	Unit Pric	<u>ce</u> <u>Quantity</u>	Total Co	<u>ost</u>
03-02-023	REPLACE N	EW HANDLES - INN	ER & OUTER	A	C2Z154	31A02A	D	OOR LATCH KIT			52.	.59 1	:	\$52.59
66-PM-PMA	PERFORM	DIL CHANGE		5	W-20P		P	ROTECK OIL FULI	SYNTHETIC		0.	.06 7		\$0.42
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		0	IL FILTER			3.	.98 1		\$3.98
03-02-023	REPLACE N	EW HANDLES - INN	ER & OUTER	6	C2Z1543	34A20AA	0	UTSIDE REAR DO	OR HANDLE		125.	.59 1	\$	125.59
66-PM-PMA	PERFORM	DIL CHANGE		5	W-20P		P	ROTECK OIL FULI	SYNTHETIC		0.	.06 (7)	((\$0.42)
66-PM-PMA	PERFORM	DIL CHANGE		5	W-20P		P	ROTECK OIL FULI	SYNTHETIC		0.	.06224	:	\$13.44
												PARTS	1	95.60

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

26714

Work Order Notes

(LISAPATE) PM-REAR DOOR WONT OPEN

Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(LISAPATE) FOUND REAR CARGO LATCH CABLES BROKEN. INSTALLED NEW REAR CARGO DOOR LATCH ASSY. RECHECKED OK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (LISAPATE) PM BY CS

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OF	RDER NO	:	2679		
USING DEPT	ΓNO:	504191		OPENE	D DAT	E:	01/05/200	9 09:17:53	LOCATION:	GARAGE	- Unive	rsity Automotive	Services	
WO STATUS	:	CLOSED		COMPL	ETED	DATE:	01/06/200	9 06:47:54	METER 1 - M	/: 10081		METER 2 - N:	0	
WO VISIT RE	EASON:	UNSCHEDULED		CLOSE	D DAT	E:	01/06/200	9 06:47:56	IN-SERVICE	DATE:	02/21	/2007		
TECH SPEC	NO:	04VNFORDE250	2004	FORD E	250				UNIT SERIA	L NO:	1FTN	E24W74HA6044	6	
JOB CODE		JOB DESCRIPTIO	<u>DN</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
03-02-024	REPLAC	E NEW GLASS		DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00		\$145.67	\$145.67	
JOB COUNT	Г: 1				wo	RK OR	DER TOTAL:	0.0	0 0	.00	0.00	145.67	7	145.67
Job Code		Job Descripti	on		v	endor N	<u>lo.</u>	Invoice No.	Purcha	se Order No	<u>o.</u>		Total	Cost
03-02-024	REPLACE N	EW GLASS		1	1070709)	04	1469	0003196					\$145.67
												COMML	-	145.67

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 2679

Work Order Notes

(LPATE) PER JOE THOMAS GLASS ON RIGHT SIDE LEFT SWINGING OPEN DOOR WAS BROKEN BY SOMEONE SLAMMING DOOR TOOK TO ROZAR'S TO HAVE GLASS REPLACED--WE DID NOT TRANSPORT JOE AND ROZAR'S DID

Job Notes

03-02-024 - REPLACE NEW GLASS

(LPATE) ROZAR'S REPLACED RIGHT REAR FRONT SIDE GLASS P0018973

The University of Alabama

UNIT NO:	234742	2004 FORD E250)				WORK ORI	DER NO:	2	27512		
USING DEPT NO:	504191	OPENE	D DAT	E:	09/19/201	7 08:40:47	LOCATION:	GARAGE -	Univers	sity Automotive \$	Services	
WO STATUS:	CLOSED	COMPL	ETED	DATE:	09/21/201	7 06:29:05	METER 1 - M:	32891	ľ	METER 2 - N:	0	
WO VISIT REASON:	SCHEDULED	CLOSE	D DAT	E:	09/21/201	7 06:29:06	IN-SERVICE	DATE:	02/21/2	2007		
TECH SPEC NO:	04VNFORDE250	2004 FORD E	250				UNIT SERIAL	NO:	1FTNE	24W74HA6044	6	
JOB CODE	JOB DESCRIPTIO	<u>ON</u> <u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	RIAL	COMMERCIAL	TOTAL	COST
66-PM-PMA PERFOR	RM OIL CHANGE	DON	Р	Ν	GARAGE	0.00	\$0.00	\$0.00	9	\$0.00	\$0.00	
JOB COUNT: 1			wc		DER TOTAL:	0.00	0.0	0	0.00	0.00		0.00

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 27512

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (LISAPATE) PM NOT DUE DONE ON 8/2/17 ONLY BEEN 452 MILES.

The University of Alabama

UNIT NO:		234742	2004 FORD E250				WORK ORI	DER NO:	28557		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	OPENED COMPLET CLOSED 2004 FORD E250	ED DATE: DATE:	01/11/201	8 08:06:41 8 07:06:52 8 07:06:56	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	DATE: 02/	iversity Automo METER 2 - 21/2007 TNE24W74HA	N:	ervices 0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION		R <mark>SN</mark> <u>WRTY</u> P N	<u>JOB LOC</u> GARAGE	LABOR HRS 0.31	LABOR \$17.83	MATERIAL \$17.42	<u>COMMER</u> \$0.00		TOTAL COST 35.25
JOB COUN	IT: 1			WORK ORE	DER TOTAL:	0.31	17.8	3 17.4	42	0.00	35.2
<u>Job Code</u> 66-PM-PMA	PERFORM	Job Descripti DIL CHANGE		Employee 8845		<u>Start</u> 09/2018 09:51:50		<u>nish</u> 10:10:26	Quar LAB	0.31	<u>Total Cost</u> \$17.8 17.8
Job Code		Job Descripti	on	Part No.	<u>.</u>	Des	cription	<u>Unit l</u>	Price Quar	tity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	5W-2	20P	PR	OTECK OIL FULL	SYNTHETIC		0.06	224	\$13.4
66-PM-PMA	PERFORM	OIL CHANGE	BALI	B329	OIL	FILTER			3.98 PAR	1 TS	\$3.9 17.4

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	28557
Work Order Not	es			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE)				
Parts For Job Includ	le:			

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (LISAPATE) PM BY CS COOLANT -47'

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK () :	30921	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED I	DATE:	09/25/20	18 07:03:29 18 09:16:12 18 09:16:14		- M: 35601 CE DATE:	02/21/2	sity Automotive S METER 2 - N: 2007 E24W74HA60446	0
JOB CODE 03-32-002 66-79-002	REPLAC	JOB DESCRIPTION E NEW BATTERY	<u>NC</u>	<u>STAT</u> DON	RSN O B	WRTY N	JOB LOC GARAGE GARAGE	LABOR HR 0.5	_	<u>R MATI</u> \$76.09 \$0.00		•	TOTAL COST \$76.09 \$0.00
JOB COUN	-			DON		N RK ORI	DER TOTAL	-		0.00	76.09	\$0.00 0.00	\$0.00 76.09
Job Code 66-79-002 66-79-002 66-79-002 66-79-002 66-79-002 03-32-002	PERFORM S PERFORM S PERFORM S	Job Descript Service Call Service Call Service Call Service Call Service Call Service Call	ion	1 1 1 1	<u>Em</u> 1901357 1901357 1901357 1901357 1213180 1213180		20 20 20 20 20	<u>Start</u> /24/2018 07:41: /24/2018 07:41: /24/2018 07:41: /24/2018 07:41: /24/2018 07:41:	18 09/24/2 18 09/24/2 18 09/24/2 18 09/24/2	Finish 018 08:41:18 018 08:41:18 018 08:41:18 018 08:41:18 018 08:41:18 018 08:41:18		Quantity 1.00 (1.00) 1.00 (1.00) 1.00 0.50 LABOR	\$0.00
Job Code	REPLACE N	Job Descript	ion	6	50	Part No	_	D ATTERY BCI 65	escription		Unit Pric		<u>Total Cost</u> \$75.63
03-32-002 03-32-002	REPLACE N	EW BATTERY EW BATTERY		7	40245 40245		BA	ATTERY TERM I	PROTECTOR W		0.	23 1 23 1 PARTS	\$0.23 \$0.23 76.09

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

30921

Work Order Notes

(LISAPATE) Emily requested a service call to Southlawn van has a dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery and checked charging system good at 14.3 volts

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) AG/MS completed service call

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OR	DER NO): :	32634		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED I	DATE:	04/25/201	9 08:16:31 9 06:46:32 9 06:46:34	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 36882 DATE:	l 02/21/2	sity Automotive S METER 2 - N: 2007 24W74HA60446	0	
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL COS	I
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.65	\$0.00	\$25.01	1	\$0.00	\$25.01	
JOB COUN	T: 1				wo		DER TOTAL:	0.65	0.0	0	25.01	0.00	25.	.01
Job Code		Job Descripti	ion		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	<u>nish</u>		<u>Quantity</u>	Total Cost	
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		04/	16/2019 09:02:07	04/16/2019	09:41:07		0.65	\$0	0.00
												LABOR	0.	.00
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	cription		Unit Pric	e <u>Quantity</u>	Total Cost	_
66-PM-PMA	PERFORM C	DIL CHANGE		В	ALB329		OIL	FILTER			3.9	98 1	\$3	3.98
66-PM-PMA	PERFORM C	DIL CHANGE		1	198		OIL	DRAIN PLUG FO	ORD		3.2	27 1	\$3	3.27
66-PM-PMA	M-PMA PERFORM OIL CHANGE			5	W20BT		BU	LK OIL 5W20 SYI	NTHETIC THOM	AS	2.9	96 6	\$17	'.76
												PARTS	25.	.01

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 32634

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (EKIMBREL) Top: RC, Bot: SH Coolant -35 Oil Drain Plug 1198 SH

The University of Alabama

UNIT NO:		234742	2004 FORI	D E250)				WORK OF	RDER NO		32765		
USING DEF	PT NO:	504191		OPENE		E:	04/29/201	9 14:19:08	LOCATION:	GARAGE	- Univer	sity Automotive	Services	
WO STATU	S:	CLOSED		COMPL	ETED	DATE:	05/01/201	9 07:49:53	METER 1 - M	1: 36949	I	METER 2 - N:	0	
WO VISIT F	REASON:	SCHEDULED		CLOSE	D DATI	E:	05/01/201	9 07:49:57	IN-SERVICE	DATE:	02/21/2	2007		
TECH SPEC	C NO:	04VNFORDE250	2004 F	FORD E	250				UNIT SERIA	L NO:	1FTNE	24W74HA6044	6	
JOB CODE	E	JOB DESCRIPTIC	<u>DN</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	<u>TOTAL</u>	COST
03-02-024	REPLAC	E NEW GLASS		DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00		\$197.95	\$197.95	
JOB COUN	NT: 1				wo	RK OR	DER TOTAL:	0.00) 0.	00	0.00	197.95	;	197.95
Job Code		Job Description	on		V	endor N	<u>lo.</u>	Invoice No.	Purchas	se Order No	<u>).</u>		Total	Cost
03-02-024	REPLACE N	IEW GLASS		1	1078716		263	3330	0047794					\$197.95
												COMML	-	197.95

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

32765

Work Order Notes

(LISAPATE) Side barn doors. LEFT side door. Glass was broken out by Grounds. Called for Glass DR

Job Notes

03-02-024 - REPLACE NEW GLASS

(LISAPATE) Glass Dr came to the shop and installed new glass. PD by CC

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)					WORK ORD	ER NO): 3	33137	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED	DATE:	06/21/2	019 09:53:42 019 07:17:29 019 07:17:30		LOCATION: G METER 1 - M: IN-SERVICE DA UNIT SERIAL N	37367 TE :	N 02/21/2	METER 2 - N:	0
JOB CODE	L	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LO		IRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL COST
03-02-018	REPLAC	E NEW DOOR MEG	CHANISM	DON	0	Ν	GARAGE		1.82	\$0.00	\$131.70	9	50.00	\$131.70
06-02-018	INSPECT	DOOR MECHANI	SM	DON	0	Ν	GARAGE		0.50	\$0.00	\$0.00	\$	50.00	\$0.00
JOB COUN	IT: 2				wo	RK ORI	DER TOTA	L:	2.32	0.00		131.70	0.00	131.70
Job Code		Job Descript	ion		<u>Em</u>	ployee	<u>No.</u>	Start	<u>t</u>	<u>Finis</u>	<u>sh</u>		<u>Quantity</u>	Total Cost
03-02-018	REPLACE N	EW DOOR MECHAN	SM	1	1901357		C	06/19/2019 06:	06:06	06/19/2019 06	8:15:34		0.16	\$0.00
03-02-018	REPLACE N	EW DOOR MECHAN	ISM	1	1901357		C	06/19/2019 09:	33:52	06/19/2019 10):37:05		1.05	\$0.00
06-02-018	INSPECT DO	OOR MECHANISM		1	1901357		C	06/19/2019 07:	00:00	06/19/2019 07	2:30:00		0.50	\$0.00
03-02-018	REPLACE N	EW DOOR MECHAN	SM	1	1901357		C	6/18/2019 15:	17:53	06/18/2019 15	5:54:15		0.61	\$0.00
													LABOR	0.00
Job Code		Job Descript	ion			Part No	<u>.</u>		Des	cription		Unit Price	<u>e</u> <u>Quantity</u>	Total Cost
03-02-018	REPLACE N	EW DOOR MECHAN	ISM	А	C2Z154	31A02A	Γ	DOOR LATCH	KIT			49.0)8 1	\$49.08
03-02-018	REPLACE N	EW DOOR MECHAN	ISM	8	C2Z1526	64A00D	Γ	DOOR LATCH	CABL	.E		40.9	90 1	\$40.90
03-02-018	REPLACE N	EW DOOR MECHAN	ISM	8	C2Z1543	31A03A	L	OWER LATCH	HW/H	IANDLE		56.5	58 1	\$56.58
03-02-018	REPLACE N	EW DOOR MECHAN	ISM	6	C2Z1543	3286AA	ι	JPPER DOOR	LATC	Н		34.2	22 1	\$34.22
03-02-018	REPLACE N	EW DOOR MECHAN	SM	А	C2Z154	31A02A	Γ	DOOR LATCH	KIT			49.0	08 (1)	(\$49.08
													PARTS	131.70

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 33137

Work Order Notes

(LISAPATE) Side doors will not open at all- Rear door handle is broken

Job Notes

03-02-018 - REPLACE NEW DOOR MECHANISM

(LISAPATE) Replaced side outer door latch and cable assy. Checked for proper operation, All good Replaced rear inner door handle and cable latch assy. Checked for proper operation. All good

06-02-018 - INSPECT DOOR MECHANISM

(LISAPATE) Found latch and cables broken on both side and rear doors

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK ORI	DER NO):	34431	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004 F	OPENE COMPL CLOSE	ETED	DATE:	10/17/20	019 07:06:29 019 07:29:45 019 07:29:47	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	38339 DATE:	l 02/21/2	sity Automotive S METER 2 - N: 2007 24W74HA6044	0
JOB CODE	<u>.</u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOO	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFOR	M TIRE PATCH		DON	0	Ν	GARAGE	0.79	\$0.00	\$4.86	:	\$0.00	\$4.86
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.46	\$0.00	\$28.92	:	\$0.00	\$28.92
JOB COUN	T: 2				WO	RK ORI	DER TOTA	L: 1.25	5 0.0)	33.78	0.00	33.78
Job Code		Job Descript	ion		<u>Em</u>	nployee	<u>No.</u>	<u>Start</u>	<u>Fir</u>	<u>nish</u>		<u>Quantity</u>	Total Cost
66-17-030	PERFORM	IRE PATCH		1	1074414		1	0/15/2019 07:55:11	10/15/2019	08:42:24		0.79	\$0.00
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		1	0/14/2019 08:59:17	7 10/14/2019	09:26:59		0.46	\$0.00
												LABOR	0.00
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	scription		Unit Pric	e Quantity	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		5	W20BT		E	BULK OIL 5W20 SY	NTHETIC THOMA	S	2.9	95 7	\$20.6
66-17-030	PERFORM	IRE PATCH		2	1601		I	R 600 HP WIDE V	ALVE STEM		0.4	48 1	\$0.4
66-17-030	PERFORM	TRE PATCH		14	4042		F	PATCH 3/8 PILOT V	VIRE		3.8	80 1	\$3.8
66-17-030	PERFORM	IRE PATCH		W	/HEEL V	VEIGHT	V	VHEEL WEIGHT KI	NOCK ON		0.2	29 2	\$0.5
66-PM-PMA	PERFORM	DIL CHANGE		0	5089		E	BRAKE CLEAN NO	N-FLAMMABLE 14	ΙOΖ	4.2	29 1	\$4.2
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		C	DIL FILTER			3.9	981	\$3.9
												PARTS	33.78

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 34431

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Removed and patched RF tire from the inside. Rechecked ok

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000 (LISAPATE) PM by EK/SH Coolant -35' Syn 2.75

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK OF	RDER NO		35039	
USING DEP	T NO:	504191		OPENE	D DAT	E:	12/04/201	9 08:18:38	LOCATION:	GARAGE	- Univer	sity Automotive	Services
WO STATUS	S:	CLOSED		COMPL	ETED	DATE:	12/05/201	9 15:14:20	METER 1 - N	: 38424		METER 2 - N:	0
WO VISIT R	EASON:	SCHEDULED		CLOSE	D DATI	Ξ:	12/05/201	9 15:14:22	IN-SERVICE	DATE:	02/21/	2007	
TECH SPEC	NO:	04VNFORDE250	2004 F	FORD E	250				UNIT SERIA	L NO:	1FTNE	E24W74HA6044	6
JOB CODE		JOB DESCRIPTIO	N	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL COST
03-52-021	REPLAC	E NEW GPS SYSTE	EM	DON	Ν	Ν	GARAGE	0.50	\$0.00	\$0.00		\$0.00	\$0.00
JOB COUN	T: 1				wo	RK ORI	DER TOTAL:	0.50) 0.	00	0.00	0.00	0.0
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		Quantity	Total Cost
03-52-021	REPLACE N	IEW GPS SYSTEM		1	1213180		12/	/04/2019 09:19:00	12/04/201	9 09:49:00		0.50	\$0.
												LABOR	0.

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

35039

Work Order Notes

(LISAPATE) UPGRADE GPS TO 4G

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(LISAPATE) Removed 3G GPS serial# 5014687179 Installed 4G GPS serial# 5041371379

The University of Alabama

UNIT NO:		D E250)				WORK ORDER NO:			36213			
WO STATUS WO VISIT R	O VISIT REASON:SCHEDULEDECH SPEC NO:04VNFORDE25020			COMPLETED DATE: 04				020 08:03:03 020 11:40:24 020 15:36:21	METER 1 - N IN-SERVICE	LOCATION: GARAGE METER 1 - M: 39073 IN-SERVICE DATE: UNIT SERIAL NO:		sity Automotive METER 2 - N: 2007 E24W74HA6044	0
JOB CODE	L	JOB DESCRIP	TION	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LO	LABOR HRS	LABOR	MAT	ERIAL		TOTAL COST
03-34-003	REPLAC	E NEW SIGNAL,	PARKING, & BA	DON	0	Ν	GARAGE	0.19	\$0.00	\$0.57		\$0.00	\$0.57
03-34-011	REPLAC	E NEW TAILLIGH	IT ASSEMBLY	DON	0	Ν	GARAGE	0.81	\$0.00	\$28.56		\$0.00	\$28.56
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	1.06	\$0.00	\$27.32		\$0.00	\$27.32
JOB COUN	IT: 3				WO	RK ORI	DER TOTA	L: 2.05	0 .	00	56.45	0.0) 56.4
Job Code		Job Descri	ption		Em	ployee	<u>No.</u>	<u>Start</u>	E	inish		<u>Quantity</u>	Total Cost
03-34-011	REPLACE N	EW TAILLIGHT AS	SEMBLY	1	1901357		C	4/28/2020 09:52:29	04/28/2020	0 10:40:58		0.81	\$0.
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		C	4/24/2020 13:00:00	04/24/2020	0 13:12:17		0.20	\$0.
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		C	4/24/2020 11:31:26	04/24/2020	0 12:00:00		0.48	\$ \$0.
66-PM-PMA	PERFORM	DIL CHANGE		1	2052187		C	4/24/2020 11:19:06	04/24/2020	0 11:41:36		0.38	\$0.
03-34-003	REPLACE N	EW SIGNAL,PARK	(ING, & BACKUP L	AMPS 1	1901357		C	4/24/2020 11:20:05	04/24/2020	0 11:31:26		0.19	\$0.
												LABOR	0.0
Job Code		Job Descri	ption			Part No	<u>.</u>	Des	scription		Unit Pric	<u>ce</u> <u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		5	W20TQT	-	C	QUART CAM2 SYN	5W20 32OZ		3.	.89 6	\$23.
03-34-011	REPLACE N	EW TAILLIGHT AS	SEMBLY	5	C2Z1340	4AACP	F	RIGHT TAILLIGHT A	SSY		28.	.56 1	\$28.
66-PM-PMA	PERFORM	DIL CHANGE		5	W20BT		E	BULK OIL 5W20 SY	NTHETIC THOM	IAS	2.	.95 6	\$ \$17.
66-PM-PMA	PERFORM	DIL CHANGE		В	ALB329		C	DIL FILTER			3.	.98 1	\$3.
03-34-003	REPLACE N	EW SIGNAL,PARK	(ING, & BACKUP L	AMPS 3	156		E	BULB-BACK UP			0.	.57 1	\$0.
66-PM-PMA	PERFORM	DIL CHANGE		5	W20BT		E	BULK OIL 5W20 SY	NTHETIC THOM	IAS	2.	.95 (6	i) (\$17.7
												PARTS	56.4

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	36213
Work Order No	tes			
(IFALLS) PM				
Job Notes				
03-34-003 - REPLA	CE NEW SIGNAL,P	ARKING, & BACKUP LAMPS		
(IFALLS) AG replac	ed right rear back up:	light bulb		
03-34-011 - REPLA	CE NEW TAILLIGHT	T ASSEMBLY		
(RWINTERS) AG re	eplaced tag light asse	embly		
66-PM-PMA - PER	FORM OIL CHANGE			
(IFALLS) The following parts	are included with the	standard job:		
Part No : 5W2	20FS			
Qty : 7				
Manufacturer :	OLINE 5W20 FULLS	Th OLE BULK		
Bin :				

(IFALLS) AG/JW performed pm

The University of Alabama

UNIT NO:	234742	2004 FORD E250				WORK ORDER NO):	37799	
USING DEPT NO:	504191	OPENED	DATE:	09/28/2020	0 10:09:29	LOCATION: GARAGI	E - Univers	sity Automotive \$	Services
WO STATUS:	CLOSED	COMPLE	ETED DATE:	09/28/2020	0 11:50:19	METER 1 - M: 39674	I	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED	DATE:	09/28/2020	0 12:23:18	IN-SERVICE DATE:	02/21/2	2007	
TECH SPEC NO:	04VNFORDE250	2004 FORD E25	50			UNIT SERIAL NO:	1FTNE	24W74HA6044	6
JOB CODE	JOB DESCRIPTIO	<u>N STAT</u>	RSN WRTY	JOB LOC	LABOR HRS	LABOR MAT	ERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA PERFOR	RM OIL CHANGE	DON	P N	GARAGE	0.17	\$0.00 \$0.00	:	\$0.00	\$0.00
JOB COUNT: 1			WORK ORE	DER TOTAL:	0.17	0.00	0.00	0.00	0.00
Job Code	Job Description	<u>on</u>	Employee	<u>No.</u>	<u>Start</u>	<u>Finish</u>		<u>Quantity</u>	Total Cost
66-PM-PMA PERFORM	OIL CHANGE	120	052187	09/2	28/2020 10:39:41	09/28/2020 10:49:38		0.17	\$0.00
								LABOR	0.00

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

37799

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 601 miles. Checked all fluids and tires. Updated pm sticker. Unit may need a set of tires at next pm due to age. Coolant -34° JAW,SH

The University of Alabama

UNIT NO:		234742	2004 FORI	D E250)					WORK ORD	ER NO	:	39023		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250		OPENE COMPL CLOSE	ETED I D DATE	DATE:	02/08/2	021 11:21:53 021 09:46:20 021 08:53:53		LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL I	40166 ATE:	02/21/	rsity Automotive 3 METER 2 - N: /2007 E24W74HA6044	0	
JOB CODE 66-PM-PMA		JOB DESCRIPTIO	<u>DN</u>	<u>STAT</u> DON	RSN P	WRTY N	JOB LOO GARAGE	_		LABOR \$126.33	<u>MATE</u> \$47.99	RIAL	COMMERCIAL \$0.00	TOTAL \$174.32	COST
JOB COUN	IT: 1				wo	RK ORI	DER TOTA	_: ^	1.07	126.33		47.99	0.00		174.32
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>		<u>Fin</u>	<u>ish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		1′	1901357		(2/04/2021 13:5	9:29	02/04/2021 1	4:02:58		0.06		\$6.85
66-PM-PMA	PERFORM	OIL CHANGE		11	1901357		(2/04/2021 12:0	3:49	02/04/2021 1	3:04:34		1.01		\$119.48
													LABOR		126.33
Job Code		Job Description	on			Part No	<u>-</u>		Des	cription	ļ	Unit Prie	<u>ce</u> <u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	OIL CHANGE		P	A4878F		ŀ	IR FILTER REF	PL 64	18		14	.66 1		\$14.66
66-PM-PMA	PERFORM	OIL CHANGE		B	ALB329		(DIL FILTER				6	.78 1		\$6.78
66-PM-PMA	PERFORM	OIL CHANGE		5	W20BT		E	ULK OIL 5W20	SYN	THETIC THOMAS	S	4	.43 6		\$26.55
													PARTS		47.99

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO:

39023

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 40166 Completed PM bottom side Scott was topside, completed checklist. Vacuumed out vehicle. AMG SH

The University of Alabama

UNIT NO:	JNIT NO: 234742 2004 FOR			D E250)				WORK OR		40446			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004 F	OPENE COMPL CLOSE	ETED	DATE:	07/27/2	021 09:13:45 021 10:50:34 021 15:15:30	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 40398 DATE :	N 02/21/2	5ity Automotive S METER 2 - N: 2007 24W74HA60446	0	
JOB CODE	L	JOB DESCRIPTIO	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LO	LABOR HRS	LABOR	MATE	ERIAL O	COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	Ν	GARAGE	0.00	\$0.39	\$14.67	\$	50.00	\$15.06	
06-15	INSPEC	STEERING		DON	0	Ν	GARAGE	0.20	\$23.93	\$0.00	\$	50.00	\$23.93	
09-15	ALIGN S	TEERING		DON	0	Ν	GARAGE	0.32	\$38.32	\$0.00	S	50.00	\$38.32	
66-17-028	PERFOR	M MOUNT AND BA	LANCE TIRE	DON	Р	Ν	GARAGE	0.71	\$83.75	\$805.65	\$	50.00	\$889.40	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.41	\$47.79	\$0.00	\$	50.00	\$47.79	
JOB COUN	IT: 5				wo		DER TOTA	L: 1.65	194.1	18	820.32	0.00	1	,014.50
Job Code		Job Descripti	ion		Fn	nployee	No	Start	F	inish		Quantity	Total	Cost
06-15	INSPECT S			1	<u></u> 1310047	-		07/20/2021 13:48:15				<u>quuntty</u> 0.20	10141	\$23.93
09-15	ALIGN STEE	ERING		1	1310047	,	(07/20/2021 13:38:32	07/20/2021	13:48:02		0.16		\$18.68
09-15	ALIGN STEE	ERING		1	1310047	,	(07/20/2021 09:05:24	07/20/2021	09:15:23		0.17		\$19.63
03-51-038	REPLACE N	IEW WIPER BLADES		1	2052187	,	(07/20/2021 09:02:17	07/20/2021	09:02:29		0.00		\$0.39
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	1	2052187	,	(07/20/2021 08:11:14	07/20/2021	08:53:49		0.71		\$83.75
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414		(07/15/2021 09:30:00	07/15/2021	09:54:18		0.41		\$47.79
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414		(07/15/2021 09:29:57	07/15/2021	09:29:57		0.00		\$0.00
												LABOR	·	194.17
Job Code		Job Descripti	ion			Part No	<u>.</u>	Des	cription		Unit Price	e <u>Quantity</u>	Total	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		Т	WB20-1		١	VIPER BLADE 20"			7.3	34 2		\$14.67
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	2	1601		Ţ	R 600 HP WIDE VA	LVE STEM		0.7	77 4		\$3.06
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	V	VHEEL V	VEIGHT	١	VHEEL WEIGHT KN	IOCK ON		0.5	51 9		\$4.59
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	0	5485		Ţ	TIRE LT245/75R16 E	BFG COMM T/A		199.5	50 4		\$798.00
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	0	5485		Ţ	TIRE LT245/75R16 E	BFG COMM T/A		199.5	50 (4)	((\$798.00)
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	0	5485		٦	TIRE LT245/75R16 E	BFG COMM T/A		199.5			\$798.00
												PARTS		820.32

234742

(LISAPATE) PM	
Job Notes	
03-51-038 - REPLACE NEW WIPER BLADES	
(JWRIGHT) Installed new wiper blades	
06-15 - INSPECT STEERING	
(EHOWELL) Front end good. JAW/SH	
09-15 - ALIGN STEERING	
(EHOWELL) Performed Alignment. EH	
66-17-028 - PERFORM MOUNT AND BALANCE TIRES	
(JWRIGHT) Replaced all tires. Aired and balanced. Torqued to spec. JAW	
66-PM-PMA - PERFORM OIL CHANGE	
(SHARBIN) Vehicle has been driven 232 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH	

Work Order Notes

UNIT NO:

.

(

(

- 6

6

(SHARBIN) venicle has been driven 232 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

2004 FORD E250

Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

40446

WORK ORDER NO:

The University of Alabama

UNIT NO:		234742	2004 FORD E25	0				WORK OR		: 41	1783		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	COMF	ED DAT LETED ED DAT	DATE:	12/06/202	21 08:34:49 21 07:11:58 21 13:02:41	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 40861 DATE:	MI 02/21/20	y Automotive S ETER 2 - N: 107 4W74HA6044	0	
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u>N STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE		OMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY	DON	0	Ν	GARAGE	0.14	\$16.45	\$113.55	\$0	0.00	\$130.00	
03-51-038	REPLAC	E NEW WIPER BLAD	DES DON	Р	Ν	GARAGE	0.75	\$88.96	\$15.18	\$0	0.00	\$104.14	
66-PM-PMA	PERFOF	M OIL CHANGE	DON	Р	N	GARAGE	0.33	\$38.68	\$31.28	\$0	0.00	\$69.96	
CH-SP		E Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	00	\$2.00	
JOB COUN	IT: 4			wo		DER TOTAL:	1.22	144.0	09	160.01	2.00		306.10
Job Code CH-SP	CHARGE S	Job Descriptio	<u>on</u>	<u>\</u> 503163	/endor N	lo. 1	<u>Invoice No.</u>	Purchas	e Order No	<u>o.</u>		<u>Total</u>	<u>Cost</u> \$2.00
											COMML		2.00
Job Code		Job Descriptio	<u>on</u>	Er	nployee	No.	<u>Start</u>	F	inish		Quantity	Total	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1190135	7	12/	/03/2021 12:40:56	12/03/202	1 13:25:44		0.75		\$88.11
03-51-038	REPLACE N	IEW WIPER BLADES		11074414	4	12/	/03/2021 13:02:26	12/03/202	1 13:02:52		0.01		\$0.85
66-PM-PMA	PERFORM	OIL CHANGE		11074414	4	12/	/03/2021 13:00:00	12/03/202	1 13:02:13		0.04		\$4.36
66-PM-PMA	PERFORM	OIL CHANGE		11074414	4	12/	/03/2021 12:59:25	12/03/202	1 12:59:25		0.00		\$0.00
03-32-002	REPLACE N	IEW BATTERY		1190135	7	12/	/03/2021 12:32:19	12/03/202	1 12:40:41		0.14		\$16.45
66-PM-PMA	PERFORM	OIL CHANGE		1107441	4	12/	/03/2021 11:38:23	12/03/202	1 11:55:50		0.29		\$34.32
											LABOR		144.09
Job Code		Job Descriptio	<u>on</u>		Part No	<u>.</u>	Des	cription	<u> </u>	Unit Price	Quantity	Total	Cost
03-32-002	REPLACE N	IEW BATTERY		650		BA	TTERY BCI 65 65	0 CCA		113.55	1		\$113.55
66-PM-PMA	PERFORM	OIL CHANGE		BALB329)	OII	_ FILTER			4.73	1		\$4.73
03-51-038	REPLACE N	IEW WIPER BLADES		TWB20-1	I	WI	PER BLADE 20"			7.59	2		\$15.18
66-PM-PMA	PERFORM	OIL CHANGE		5W20BT		BU	ILK OIL 5W20 SYN	NTHETIC THOM	AS	4.43			\$26.55
											PARTS		160.01

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

234742 2004 FORD E250 UNIT NO:

WORK ORDER NO: 41783

Work Order Notes

Job Notes

03-32-002 - REPLACE NEW BATTERY

(AGUERRA) Replaced battery and checked charging system, good at 14.2 volts. AMG

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH (AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:		234742	2004 FORI	D E250)				WORK OR	DER NO:	43	308		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250		OPENE COMPL CLOSE	ETED I D DATE	DATE:	09/17/200	9 08:32:44 9 08:55:53 9 08:55:53	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 11898 DATE :	ME 02/21/20	y Automotive S E TER 2 - N: 07 4W74HA60446	0	
JOB CODE 66-PM-PMA		JOB DESCRIPTIO	<u>N</u>	<u>STAT</u> DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.31	LABOR \$17.83	<u>MATEF</u> \$51.85		OMMERCIAL .00	TOTAL C \$69.68	<u>OST</u>
JOB COUN	IT: 1				WO	RK ORI	DER TOTAL:	0.31	17.8	3	51.85	0.00		69.68
Job Code 66-PM-PMA	PERFORM	Job Description DIL CHANGE	<u>on</u>	11	<u>Em</u> 1268671	ployee		<u>Start</u> 16/2009 16:00:00		<u>nish</u> 16:18:36		Quantity 0.31	<u>Total C</u>	<u>ost</u> \$17.83 17.83
Job Code		Job Description	on			Part No	<u>.</u>	Des	scription	<u>U</u>	nit Price	Quantity	Total Co	
66-PM-PMA	PERFORM	OIL CHANGE		5\	W20		OIL	BOTTLE			0.09	224		\$20.16
66-PM-PMA	PERFORM	OIL CHANGE		P	A4878F		AIF	R FILTER REPL 64	418		23.83	1		\$23.83
66-PM-PMA	PERFORM	OIL CHANGE		B	ALB329		OIL	FILTER			7.86	1		\$7.86
												PARTS		51.85

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 4308

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 51372 Qty : 1 Description : FILTER-OIL Manufacturer :

Part No: 5W20Qty: 224Description: OIL BOTTLEManufacturer :

(LPATE) PM BY IF-REPLACED AIR FILTER

The University of Alabama

UNIT NO:		234742	2004 FORD) E250					WORK	ORDER NO	: 4	3096		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250		OPENE COMPL CLOSE	ETED I D DATI	DATE:	05/04/202	22 12:36:29 2 08:25:05 22 08:25:08	METER 1 IN-SERV	DN: GARAGE - M: 409622 ICE DATE: RIAL NO:	M 02/21/20	ETER 2 - N:	0	
JOB CODE	<u> </u>	JOB DESCRIPTIC	<u>DN</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABC	DR MATE	RIAL C	OMMERCIAL	<u>TOTAL</u>	COST
06-32-002	INSPEC ⁻	T BATTERY		DON	0	Ν	GARAGE	0.29	\$34.32	\$0.00	\$0	0.00	\$34.32	
CH-32-002	CHARGE	BATTERY		DON	0	Ν	GARAGE	0.15	\$17.70	\$0.00	\$0	0.00	\$17.70	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	0.44		52.02	0.00	2.00		54.02
Job Code CH-SP	CHARGE SI	Job Descripti nop Supplies	<u>on</u>	50	<u>V</u> 03163	endor N	lo. 1	<u>Invoice No.</u>	<u>Purc</u>	<u>hase Order No</u>	<u>).</u>		<u>Total</u>	<u>Cost</u> \$2.00
												COMML		2.00
Job Code		Job Descripti	<u>on</u>		Em	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
CH-32-002	CHARGE B	ATTERY		12	2052187		05/	05/2022 07:00:00	05/05/	2022 07:09:00		0.15		\$17.70
06-32-002	INSPECT B	ATTERY		12	2052187		04/	29/2022 15:30:26	04/29/	2022 15:47:53		0.29		\$34.32
												LABOR		52.02

UNIT NO: 234742 2004 FORD E250	UNIT NO:	234742	2004 FORD E250
--------------------------------	----------	--------	----------------

WORK ORDER NO: 43096

Work Order Notes

(CHANNELL) inspect battery

Job Notes

06-32-002 - INSPECT BATTERY

(JWRIGHT) Charged battery and tested. Found no issues. Alternator charging at 13.9 volts. JAW

CH-32-002 - CHARGE BATTERY

(LISAPATE) JW charged battery

The University of Alabama

UNIT NO:		234742 2004 FORD E250 WORK ORDER NO			: 43	3133								
WO STATUS WO VISIT R	TECH SPEC NO: 04		JLED		COMPLETED DATE: 05/05 CLOSED DATE: 05/05 2004 FORD E250 05/05			22 08:25:22 22 08:42:13 22 09:40:16	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 40975 DATE:	MI 02/21/20	y Automotive S E TER 2 - N: 07 4W74HA60446	0	
JOB CODE	L	JOB DESCRIPT	ION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL <u>C</u>	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	Ν	GARAGE	0.02	\$2.16	\$15.18	\$0	.00	\$17.34	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.27	\$32.19	\$0.00	\$0	.00	\$32.19	
CH-SP	SP CHARGE Shop Supplies			DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00	
JOB COUN	JOB COUNT: 3				WO	RK ORI	DER TOTAL:	0.29	34.	35	15.18	2.00		51.53
Job Code		Job Descrip	otion		v	endor N	<u>o.</u>	Invoice No.	Purchas	e Order No) <u>.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descrip	otion		En	nployee	<u>No.</u>	<u>Start</u>	<u>F</u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414	ļ	05/	/04/2022 10:15:12	05/04/2022	2 10:31:34		0.27		\$32.19
03-51-038	REPLACE N	EW WIPER BLADE	S	1	1074414		05	/04/2022 10:31:44	05/04/2022	2 10:32:50		0.02		\$2.16
												LABOR		34.35
Job Code		Job Descrip	otion			Part No	<u>.</u>	Des	cription	<u>L</u>	Jnit Price	<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADE	S	Т	WB20-1		WI	PER BLADE 20"			7.59	2		\$15.18
												PARTS		15.18

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 43133

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 29 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

The University of Alabama

UNIT NO:	UNIT NO: 234742 2004 F		004 FORI	D E250	E250					WORK ORDER NO: 44135			
WO STATUS WO VISIT R	O VISIT REASON:SCHEDULEDCH SPEC NO:04VNFORDE250		OPENED DATE: COMPLETED DAT CLOSED DATE: 2004 FORD E250		DATE:	08/02/202	2 10:45:51 2 13:51:51 2 15:07:44		M: 40975 E DATE:	02/21/	sity Automotive S METER 2 - N: 2007 E24W74HA6044	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u> </u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>	RIAL	COMMERCIAL	TOTAL COS
35-32	DIAGNO	SE CRANKING SYSTI	EM	DON	0	Ν	GARAGE	0.15	\$17.60	\$0.00		\$0.00	\$17.60
CH-32-002	CHARGE	BATTERY		DON	0	Ν	GARAGE	0.14	\$17.01	\$0.00		\$0.00	\$17.01
CH-SP	CHARGE Shop Supplies			DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$2.00	\$2.00
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	0.29	3	4.61	0.00	2.00	36.
Job Code		Job Description	<u>1</u>			endor N	<u>o.</u>	Invoice No.	Purch	ase Order No	<u>).</u>		<u>Total Cost</u>
CH-SP	CHARGE SI	nop Supplies		50	03163		1						\$2
												COMML	2.
Job Code		Job Description	<u>1</u>		Em	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	Total Cost
35-32	DIAGNOSE	CRANKING SYSTEM		1′	1915538		08/	02/2022 07:41:09	08/02/20	022 07:50:06		0.15	\$17
CH-32-002	CHARGE B	ATTERY		1′	1915538		08/	02/2022 07:32:30	08/02/20	022 07:41:09		0.14	\$17
												LABOR	34.

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 44135

Work Order Notes

(LISAPATE) Check battery and charging system. Van has been jumped off by dept multiple times

Job Notes

35-32 - DIAGNOSE CRANKING SYSTEM

(IFALLS) battery less than a year old $\$ completely drain down. $\$

CH-32-002 - CHARGE BATTERY

(GARAGE) pulled battery put on charger over night put battery back in check charging system charging at 14.3 volts\\RC

The University of Alabama

UNIT NO:	234742 2004 FORD E250 WORK ORDEF				DER NO): 44	4669							
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPI CLOSE	ETED	DATE:	09/14/20	22 08:29:56 22 11:54:14 22 13:17:47	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 41040 DATE :	M I 02/21/20	y Automotive S E TER 2 - N: 07 4W74HA60446	0	
JOB CODE	L	JOB DESCRIPTIC	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL CO	DST
03-51-038	REPLAC	E NEW WIPER BLA	DES	DON	Ρ	Ν	GARAGE	0.04	\$4.65	\$15.63	\$0	.00	\$20.28	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.65	\$77.26	\$54.17	\$0	.00	\$131.43	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00	
JOB COUN	IT: 3				WC	RK ORI	DER TOTAL	: 0.69	81.9)1	69.80	5.00	15	56.71
Job Code CH-SP	CHARGE SI	Job Descripti	ion	5	<u>⊻</u> 03163	endor N	lo. 1	<u>Invoice No.</u>	Purchase	e Order N	<u>o.</u>		Total Cos	<u>st</u> \$5.00
												COMML		5.00
Job Code		Job Descripti	ion		En	nployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	<u>nish</u>		<u>Quantity</u>	Total Co	st
03-51-038	REPLACE N	IEW WIPER BLADES		1	1901357	,	09	9/13/2022 12:38:23	09/13/2022	12:40:45		0.04		\$4.65
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	,	09	9/13/2022 12:56:30	09/13/2022	13:07:39		0.19	\$	\$21.93
66-PM-PMA	PERFORM	OIL CHANGE		1	1901357	,	09	9/13/2022 12:41:11	09/13/2022	13:09:19		0.47	\$	\$55.33
												LABOR		81.91
Job Code		Job Descripti	ion			Part No	<u>).</u>	Des	scription		Unit Price	<u>Quantity</u>	Total Co	st
66-PM-PMA	PERFORM	OIL CHANGE		5	W20BT		В	ULK OIL 5W20 SYI	NTHETIC THOM	AS	6.09	6	\$	\$36.54
03-51-038	REPLACE N	IEW WIPER BLADES		т	WB20-1		W	IPER BLADE 20"			7.82	2	\$	\$15.63
66-PM-PMA	PERFORM	OIL CHANGE		E	ALB329		0	IL FILTER			9.86	1		\$9.86
66-PM-PMA	PERFORM	OIL CHANGE		0	5089		В	RAKE CLEAN NON	N-FLAMMABLE 1	40Z	7.77	1		\$7.77
												PARTS	e	69.80

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	44669
Work Order Notes				
(CWIGLEY) PM				
Job Notes				
03-51-038 - REPLACE N	EW WIPER BLADI	ES		
(AGUERRA) Replaced wi	ipers. AMG			
66-PM-PMA - PERFORM	OIL CHANGE			
(AGUERRA) miles: 41040) Completed PM bo	ttomside, Josh was topside. JW/AMG		

The University of Alabama

UNIT NO:		234742	2004 FORD E2	50				WORK C	ORDER NO:	4	5474		
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	СОМ	ED DA	DATE:	12/08/202	22 13:25:30 22 11:12:16 22 14:09:56	LOCATION METER 1 - IN-SERVIC UNIT SER	E DATE:	MI 02/21/20	ETER 2 - N:	0	
JOB CODE	<u>E</u>	JOB DESCRIPTIO	<u>n sta</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATER</u>	AL C	OMMERCIAL	TOTAL CO	<u>ost</u>
CH-32-002	CHARGE	BATTERY	DON	I B	Ν	GARAGE	0.22	\$26.42	\$0.00	\$0	0.00	\$26.42	
CH-SP	CHARGE	Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	NT: 2			w	ORK ORI	DER TOTAL:	0.22	2	6.42	0.00	5.00	:	31.42
Job Code		Job Descriptio	<u>on</u>	,	Vendor N	<u>lo.</u>	Invoice No.	Purch	ase Order No.			Total Co	<u>ost</u>
CH-SP	CHARGE SI	nop Supplies		503163		1							\$5.00
											COMML		5.00
Job Code		Job Descriptio	<u>on</u>	<u>E</u>	mployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	Total Co	<u>ost</u>
CH-32-002	CHARGE B	ATTERY		1220126	67	12/	/08/2022 07:12:59	12/08/20	022 07:21:34		0.14	9	\$16.88
CH-32-002	CHARGE B	ATTERY		1220126	57	12/	/07/2022 13:57:55	12/07/20	022 14:02:46		0.08		\$9.54
											LABOR		26.42

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 45474

Work Order Notes

(EHANNAH) charge battery

Job Notes

CH-32-002 - CHARGE BATTERY

(GARAGE) removed battery and charged overnight. tested battery in the morning and battery tested good. reinstalled battery.-GC

The University of Alabama

UNIT NO:		234742	2004 FORI	D E250	1				WORK O	RDER NO	:	46288		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250		OPENE COMPL CLOSE	ETED I D DATE	DATE:	02/27/202	3 09:59:28 3 12:52:09 3 13:35:50	LOCATION METER 1 - IN-SERVICI UNIT SERI/	M: 41213 E DATE:	02/21	rsity Automotive : METER 2 - N: /2007 E24W74HA6044	0	
JOB CODE	<u>.</u>	JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.33	\$38.94	\$0.00		\$0.00	\$38.94	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
JOB COUN	T: 2				WO	RK ORI	DER TOTAL:	0.33	38	3.94	0.00	5.00		43.94
Job Code CH-SP	CHARGE Sh	Job Descriptio	on	50	<u>V</u> 03163	endor N	<u>lo.</u>	Invoice No.	<u>Purcha</u>	ise Order No	<u>D.</u>		<u>Total</u>	<u>Cost</u> \$5.00
611-51	CHARGE SI	oh orbhies		50	5105							COMML		5.00
Job Code		Job Descriptio	<u>on</u>		Em	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		12	2201267		02/	27/2023 12:04:11	02/27/20	23 12:04:11		0.00		\$0.00
66-PM-PMA	PERFORM	DIL CHANGE		12	2201267		02/	27/2023 12:04:11	02/27/20	23 12:04:11		0.00		\$0.00
66-PM-PMA	PERFORM	DIL CHANGE		12	2201267		02/	27/2023 12:04:11	02/27/20	23 12:23:59		0.33		\$38.94
												LABOR		38.94

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 46288

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid Check only, filter is good, tires and tire pressure Miles, 41,213 **CH-SP - CHARGE Shop Supplies**

The University of Alabama

UNIT NO:		234742	2004 FORD E250)				WORK O	RDER NO:	47567	7	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	OPENE COMPI CLOSE 2004 FORD E	ETED	DATE:	07/12/202	3 09:48:10 3 11:55:02 3 14:01:19	LOCATION METER 1 - I IN-SERVICE UNIT SERIA	E DATE: 0	•	R 2 - N:	0
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u>N</u> <u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIA	AL COMM	IERCIAL	TOTAL COST
06-32-002	INSPEC ⁻	T BATTERY	DON	0	Ν	GARAGE	0.07	\$8.39	\$0.00	\$0.00		\$8.39
CH-32-002	CHARGE	BATTERY	DON	Р	Ν	GARAGE	0.28	\$32.58	\$0.00	\$0.00		\$32.58
CH-SP	CHARGE	Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.00		\$5.00
JOB COUN	IT: 3			WC		DER TOTAL:	0.35	40	.97	0.00	5.00	45.97
Job Code		Job Descriptic		<u>\</u> 03163	/endor N	l <u>o.</u> 1	Invoice No.	<u>Purcha</u>	se Order No.			<u>Total Cost</u> \$5.0
				00100		ļ				C	OMML	5.00
Job Code		Job Descriptio	<u>on</u>	Er	nployee	<u>No.</u>	<u>Start</u>		Finish	<u>C</u>	uantity	Total Cost
CH-32-002	CHARGE B	ATTERY	1	1074414	1	07/	11/2023 13:03:23	07/11/202	23 13:19:57		0.28	\$32.58
06-32-002	INSPECT B	ATTERY	1	1074414	1	07/	11/2023 10:00:31	07/11/202	23 10:04:47		0.07	\$8.3
										L	ABOR	40.97

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 47567

Work Order Notes

(EHANNAH) dead battery- driver reports having to jump it off to get it here.

Job Notes

06-32-002 - INSPECT BATTERY

(GARAGE) Battery tested good recharge. SH

CH-32-002 - CHARGE BATTERY

(GARAGE) Charged the battery. Rechecked good ALT charging at 14.10 volts. SH

The University of Alabama

UNIT NO:		234742	2004 FORI	D E250 WORK ORDER NO:			: 47	7621						
WO STATUS WO VISIT R	O VISIT REASON:SCHEDULEDCH SPEC NO:04VNFORDE250			OPENED DATE: COMPLETED DATE: CLOSED DATE: 4 FORD E250			07/25/202	23 08:03:10 23 08:44:51 23 07:30:03	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	/: 41319 DATE :	MI 02/21/20		0	
JOB CODE	<u> </u>	JOB DESCRIPT	ΓΙΟΝ	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-02-055	REPLAC	E NEW DOOR LA	TCH/STRIKER	DON	0	Ν	GARAGE	0.76	\$89.88	\$169.83	\$0	.00	\$259.71	
66-79-003	PERFOR	M SAFETY INSPI	ECTION	DON	Y	Ν	GARAGE	0.59	\$69.29	\$0.00	\$0	.00	\$69.29	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	Ν	GARAGE	0.37	\$43.73	\$43.65	\$0	.00	\$87.38	
CH-SP	CHARGE	CHARGE Shop Supplies			2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00	
WA-00		WASH COMPLETE VEHICLE			P	N	GARAGE		\$24.52	\$0.00		.00	\$24.52	
JOB COUN	IT: 5			DON	wo		DER TOTAL:			.42	213.48	5.00		445.90
Job Code CH-SP	Job Description CHARGE Shop Supplies		otion	5	<u>⊻</u> 03163	endor N	<mark>o.</mark> 1	<u>Invoice No.</u>	Purcha	se Order No	<u>).</u>		<u>Total</u>	<u>Cost</u> \$5.00
												COMML		5.00
<u>Job Code</u> 03-02-055	REPLACE N	Job Descrip		1	<u>En</u> 1074414	n <mark>ployee</mark>		<u>Start</u> /25/2023 07:11:14	_	-inish 3 07:56:56		<u>Quantity</u> 0.76	<u>Total</u>	<u>Cost</u> \$89.88
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414	Ļ	07	/18/2023 08:41:56	07/18/202	3 09:04:10		0.37		\$43.73
66-79-003	PERFORM	SAFETY INSPECTIO	NC	1	1074414	Ļ	07	/18/2023 09:04:10	07/18/202	3 09:15:00		0.18		\$21.31
66-79-003	PERFORM	SAFETY INSPECTIO	NC	1	1074414	Ļ	07.	/18/2023 09:30:00	07/18/202	3 09:54:24		0.41		\$47.99
WA-00	WASH COM	IPLETE VEHICLE		1	1074414	Ļ	07	/18/2023 09:54:24	07/18/202	3 10:06:52		0.21		\$24.52
												LABOR		227.43
Job Code		Job Descrip	otion			Part No	<u>.</u>	Des	cription	ļ	Unit Price	Quantity	Total	Cost
66-PM-PMA	PERFORM	OIL CHANGE		5	W20BT		BL	ILK OIL 5W20 SYI	NTHETIC THOM	//AS	6.29	6		\$37.71
66-PM-PMA	PERFORM	OIL CHANGE		В	ALB329		OI	L FILTER			5.94	1		\$5.94
03-02-055	REPLACE N	IEW DOOR LATCH/	STRIKER	6C2Z15264A01AA		LA	ТСН			103.92	1		\$103.92	
03-02-055	REPLACE N	IEW DOOR LATCH/	STRIKER	А	C2Z152	64A26B	RE	AR LATCH ASSY			65.91	1		\$65.91
												PARTS		213.48

UNIT NO: 234742 2004 FORD E250

WORK ORDER NO: 47621

Work Order Notes

(LISAPATE) PM-Do SI-Wash (EHANNAH) door latch to be installed

Job Notes

03-02-055 - REPLACE NEW DOOR LATCH/STRIKER

(GARAGE) Replaced the right hand side left side double door upper and lower latch assembly's. SH 1Hour labor

14-02-070 - INSTALL DOOR LATCH SWITCH

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed a safety inspection. Found the passenger side left hand double door the door latch cables and the handle are broke. Found no other issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Wash bay was closed. SH

The University of Alabama

UNIT NO:	NIT NO: 234742 2004 FORD			D E250)			WORK ORDER NO:				49170			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004 F	OPENE COMPL CLOSE	ETED D DATI	DATE:	12/20/202	3 12:52:35 3 14:15:19 3 07:22:33		- M: 41442 CE DATE:	M 02/21/20	ity Automotive S I ETER 2 - N: 007 24W74HA60444	0		
JOB CODE		JOB DESCRIPTIC	<u>DN</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABO	<u>R MATEI</u>	RIAL C	OMMERCIAL	TOTAL COST		
25-52-021	REMOVE	E GPS SYSTEM		DON	0	Ν	GARAGE	0.02	\$2.56	\$0.00	\$	0.00	\$2.56		
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00		
PD-00-999				DON	D	Ν	GARAGE	0.04	\$5.08	\$0.00	\$	0.00	\$5.08		
JOB COUN	T: 3				WO	RK ORI	DER TOTAL:	0.06		7.64	0.00	5.00	12.64		
Job Code		Job Descripti	on		<u>v</u>	endor N	0.	Invoice No.	Purch	nase Order No	<u>.</u>		Total Cost		
CH-SP	CHARGE SI	nop Supplies		5	03163		1						\$5.00		
												COMML	5.00		
Job Code		Job Descripti	on		En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost		
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL		_ 1 [°]	1915538	i	12/	18/2023 08:50:33	12/18/2	023 08:53:08		0.04	\$5.08			
25-52-021	REMOVE G	PS SYSTEM		1	1915538	i	12/	18/2023 08:53:08	12/18/2	023 08:54:26		0.02	\$2.56		
												LABOR	7.64		

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO: 49170
Work Order Not	es		
(EHANNAH) prep fo	r sale		
Job Notes			
25-52-021 - REMOV	/E GPS SYSTEM		
(GARAGE) removed	d GPS\#5041371379\	SH	
CH-SP - CHARGE	Shop Supplies		
PD-00-999 - PREP I	DISPOSE PREPARE	UNIT FOR DISPOSAL	

(GARAGE) removed wordmarks and tag\ RC

The University of Alabama

UNIT NO:		234742	2004 FOR	RD E250)				WORK OR		: 6	6746		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED UNSCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE FORD E2	ETED I D DATE	DATE:	09/13/201	0 09:09:27 0 09:12:55 0 09:12:56	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 14198 DATE :	N 02/21/20	ity Automotive S IETER 2 - N: 007 24W74HA60446	0	
JOB CODE	_	JOB DESCRIPTION M OIL CHANGE	<u>NC</u>	<u>STAT</u> DON	RSN P	WRTY N	JOB LOC	LABOR HRS	LABOR \$17.83	<u>MATEI</u> \$42.09		COMMERCIAL	TOTAL COS \$59.92	<u>3T</u>
JOB COUN					WO		DER TOTAL:				42.09	0.00		ə.92
<u>Job Code</u> 66-PM-PMA	PERFORM	Job Descripti DIL CHANGE	on	1'	<u>Em</u> 1328035	ployee		<u>Start</u> 13/2010 09:46:00		<u>nish</u> 10:04:36		<u>Quantity</u> 0.31	<u>Total Cost</u> \$1	<u>t</u> 7.83
												LABOR	17	7.83
Job Code		Job Descript	on		<u> </u>	Part No	<u>.</u>	Des	cription	<u> </u>	Jnit Price	<u>Quantity</u>	Total Cost	<u>t</u>
66-PM-PMA	PERFORM (DIL CHANGE		P	A4878F		AIF	R FILTER REPL 64	418		14.0	7 1	\$1	4.07
66-PM-PMA	PERFORM	DIL CHANGE		5	W20		OIL	BOTTLE			0.1	1 224	\$2	23.52
66-PM-PMA	PERFORM	DIL CHANGE		B	ALB329		OIL	FILTER			4.5	0 1	\$	64.50
												PARTS	42	2.09

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	N	WORK ORDER NO:	6746
Work Order Note	<u>s</u>				
(RWINTERS) PM					
Job Notes					
66-PM-PMA - PERFO	ORM OIL CHANGE				
(RWINTERS)					
Parts For Job Include Part 1372 FILTER-OI Part 5W20 OIL BOTT (RWINTERS) PM BY	L Qty 1 Cost 0 LE Qty 224 Cost 0				

The University of Alabama

UNIT NO:	234742	2004 FORD E250				WORK ORI	DER NO:	707		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:	504191 CLOSED SCHEDULED 04VNFORDE250	COMPL	D DATE: ETED DATE: D DATE: 250	01/23/2008 01/23/2008 01/23/2008	3 11:24:41	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	7427 DATE: 02	MET 2/21/2007		0
JOB CODE 66-PM-PMA PERFC	JOB DESCRIPTIO	DN <u>STAT</u> DON	RSN WRTY P N	JOB LOC GARAGE	LABOR HRS 0.00	LABOR \$0.00	<u>MATERIA</u> \$30.98	L <u>CON</u> \$0.00	IMERCIAL	TOTAL COST \$30.98
JOB COUNT: 1			WORK ORE	DER TOTAL:	0.00	0.0	0 30	.98	0.00	30.98
Job Code	Job Description	on	Part No.	<u>.</u>	Des	cription	<u>Unit</u>	Price	Quantity	Total Cost
66-PM-PMA PERFORM	1 OIL CHANGE	5\	V20	OIL	BOTTLE			0.11	224	\$23.52
66-PM-PMA PERFORM	1 OIL CHANGE	B	ALB329	OIL	FILTER			7.46	1	\$7.46
								_	PARTS	30.98

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

UNIT NO:	234742	2004 FORD E250	
----------	--------	----------------	--

WORK ORDER NO: 707

Work Order Notes

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) PM BY JE

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK ORD	ER NO:	79	932	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504191 CLOSED SCHEDULED 04VNFORDE250	2004	OPENE COMPL CLOSE	ETED	DATE:	03/24/20	11 09:48:38 11 06:42:38 11 06:42:40	LOCATION: G METER 1 - M: IN-SERVICE DA UNIT SERIAL N	144615 TE:	ME 02/21/20	ETER 2 - N:	0
JOB CODE	<u>I</u>	JOB DESCRIPTI	<u>0N</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	IAL CO	OMMERCIAL	TOTAL COST
03-32-002	REPLAC	E NEW BATTERY		DON	Ν	Ν	GARAGE	0.50	\$28.75	\$92.82	\$0	.00	\$121.57
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$17.83	\$28.03	\$0	.00	\$45.86
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL	. 0.81	46.58	1:	20.85	0.00	167.43
Job Code		Job Descript	<u>ion</u>		<u>Em</u>	nployee	<u>No.</u>	<u>Start</u>	<u>Fini</u>	<u>sh</u>		<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE		1	1338644		03	/24/2011 07:00:00	03/24/2011 07	':18:36		0.31	\$17.83
03-32-002	REPLACE N	IEW BATTERY		1	1338644		03	/24/2011 07:18:36	03/24/2011 07	':49:48		(0.52)	(\$29.90)
03-32-002	REPLACE N	IEW BATTERY		1	1338644		03	/24/2011 07:18:36	03/24/2011 07	':49:48		0.52	\$29.90
03-32-002	REPLACE N	IEW BATTERY		1	1338644		03	/24/2011 07:18:36	03/24/2011 07	':48:36		0.50	\$28.75
												LABOR	46.58
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	scription	<u>Ur</u>	nit Price	Quantity	Total Cost
03-32-002	REPLACE N	IEW BATTERY		6	5-6		BA	ATTERY TOP POS	т		92.82	1	\$92.82
66-PM-PMA	PERFORM	OIL CHANGE		В	ALB329		OI	L FILTER			4.51	1	\$4.51
66-PM-PMA	PERFORM	OIL CHANGE		5	W20		OI	L BOTTLE			0.11	224	\$23.52
												PARTS	120.85

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:	7932
Work Order Not	ies			
(LPATE) PM-REPLA	ACE BATTERY			
Job Notes				
03-32-002 - REPLA	CE NEW BATTERY			
(LPATE) REPLACE	D BATTERY			
66-PM-PMA - PERF	FORM OIL CHANGE			
(LPATE)				
Parts For Job Incluc Part 1372 FILTER-C Part 5W20 OIL BOT (LPATE) PM BY RS	DIL Qty 1 Cost 0 TLE Qty 224 Cost 0			

The University of Alabama

UNIT NO:		234742	2004 FOR	D E250)				WORK ORD	ER NO:	7947	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504191 CLOSED SCHEDULED 04VNFORDE250		OPENE COMPL CLOSE	ETED I D DATE	DATE:	03/24/201	1 11:33:20 1 14:26:48 1 14:26:50	LOCATION: G METER 1 - M: IN-SERVICE D/ UNIT SERIAL N	144615 ATE: 02/2	versity Automotive S METER 2 - N: 21/2007 NE24W74HA6044	0
JOB CODE	<u>.</u>	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLAC	E NEW TIRES, TUE	BES, LINERS	DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00	\$578.53	\$578.53
16-17	TRANSP	PORT TIRES, TUBE	S, LINERS &	DON	0	Ν	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
JOB COUN	T: 2				wo	RK ORI	DER TOTAL:	1.00	57.50	0.0	0 578.53	636.03
Job Code		Job Descript	ion		V	endor N	<u>o.</u>	Invoice No.	Purchase (Order No.		Total Cost
03-17	REPLACE N	IEW TIRES, TUBES, L	INERS & VALV	ES 1	1122732		134	1498	0011186			\$578.53
											COMML	578.53
Job Code		Job Descript	ion		Em	ployee	No.	<u>Start</u>	<u>Fini</u>	<u>sh</u>	<u>Quantity</u>	Total Cost
16-17	TRANSPOR	RT TIRES, TUBES, LIN	ERS & VALVES	5 1	1338644		03/	24/2011 17:00:00	03/24/2011 18	8:00:00	1.00	\$57.50
											LABOR	57.50

The University of Alabama Report Printed: 01/08/2024 10:47:29 By User: GLOBETTI

7947

UNIT NO:	234742	2004 FORD E250	WORK ORDER NO:
Work Order Not	<u>es</u>		
(LPATE) NEEDS NE	WTIRES		
Job Notes			
03-17 - REPLACE N	IEW TIRES, TUBES	, LINERS & VALVES	
(LPATE) FIRESTON	E REPLACED 4 TIR	ES AND ALIGNED. PD BY CC.	
16-17 - TRANSPOR	T TIRES, TUBES, L	INERS & VALVES	
<i></i>			

(LPATE) TAKEN TO FIRESTONE BY RS

Report Title: Report Author: File Path:	WODETAIL - Work Order Detail v20.0 FleetFocus M5 E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~1
Data Extracted:	Mon Jan 08 2024 10:47:29 Report User: GLOBETTI
TZ: DLL Version:	Central Standard Time 2021.02.23
Report Comments:	6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773
	Parameters and Selection Filters
First Grouping:	VIEW_WO_WORKSHEET.WO_NO
Second Grouping:	VIEW_JOB_WORKSHEET.JOB
Third Grouping:	
Sorted By:	
From Date: To Date:	
Option 1:	
Option 2:	
Selection Filters:	isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '234742') //Q=