

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 24993

USING DEPT NO:	301105	OPENED DATE:	11/16/2016 07:29:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2016 14:35:10	METER 1 - M:	226	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2016 14:35:12	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11397026	11/16/2016 07:30:16	11/16/2016 08:00:16	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO:	242141	2017 TOYOTA CAMRY	WORK ORDER NO:	24993
----------	--------	-------------------	----------------	-------

Work Order Notes

(LISAPATE) DO PDI NEW UNIT

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 25997

USING DEPT NO:	301105	OPENED DATE:	03/21/2017 09:01:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2017 11:09:10	METER 1 - M:	4672	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2017 11:09:12	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$41.98	\$44.45	\$0.00	\$86.43

JOB COUNT: 1	WORK ORDER TOTAL:	0.73	41.98	44.45	0.00	86.43
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11170580	03/28/2017 10:08:00	03/28/2017 10:51:48	0.73	\$41.98
					LABOR	41.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.66	4	\$22.62
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.77	1	\$6.77
					PARTS	44.45

Work Order Charge Detail

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 25997

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AB PERFORMED PM COOLANT CHECKED GOOD TO -45

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 26532

USING DEPT NO:	301105	OPENED DATE:	06/06/2017 08:38:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2017 06:27:01	METER 1 - M:	8800	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2017 06:27:03	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$35.02	\$0.00	\$52.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$7.33	\$0.00	\$24.58

JOB COUNT: 2	WORK ORDER TOTAL:	0.61	35.08	42.35	0.00	77.43
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	06/07/2017 07:18:36	06/07/2017 07:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/07/2017 07:00:00	06/07/2017 07:18:36	0.31	\$17.83
					LABOR	35.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.16	4	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
					PARTS	42.35

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 26532

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS-REPLACED AIR FILTER
COOLANT -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 26731

USING DEPT NO:	301105	OPENED DATE:	06/29/2017 08:09:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2017 11:11:25	METER 1 - M:	10477	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2017 11:11:27	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.20	\$11.50	\$0.36	\$0.00	\$11.86
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$102.38	\$102.38

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	11.50	0.36	102.38	114.24
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11321046	91101014232	0039104	\$102.38
				COMML	102.38

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11170580	07/07/2017 07:00:00	07/07/2017 07:12:00	0.20	\$11.50
					LABOR	11.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.36	1	\$0.36
					PARTS	0.36

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 26731

Work Order Notes

(LISAPATE) FLAT TIRE PER FLEET

Job Notes

14-17-030 - INSTALL TIRE PATCH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNTED AND BALANCED 1 LR TIRE

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 1 TIRE FORM TIRE ENGINEERS. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 27010

USING DEPT NO:	301105	OPENED DATE:	08/07/2017 10:55:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/11/2017 15:53:44	METER 1 - M:	13348	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/11/2017 15:53:44	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$24.73	\$35.49	\$0.00	\$60.22

JOB COUNT: 1	WORK ORDER TOTAL:	0.43	24.73	35.49	0.00	60.22
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/08/2017 13:31:18	08/08/2017 13:57:06	0.43	\$24.73
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/08/2017 13:31:18	08/08/2017 14:56:51	(1.43)	(\$81.99)
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/08/2017 13:31:18	08/08/2017 14:56:51	1.43	\$81.99
					LABOR	24.73

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	4	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS	35.49

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 27010

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS
REPLACED AIR FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 27811

USING DEPT NO:	301105	OPENED DATE:	10/13/2017 09:58:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2017 13:12:54	METER 1 - M:	17033	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2017 13:12:55	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$4.95	\$30.77	\$0.00	\$35.72

JOB COUNT: 1	WORK ORDER TOTAL:	0.09	4.95	30.77	0.00	35.72
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/13/2017 11:54:50	10/13/2017 12:00:00	0.09	\$4.95
					LABOR	4.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.17	1	\$3.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.75	1	\$6.75
					PARTS	30.77

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 27811

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 28273

USING DEPT NO:	301105	OPENED DATE:	11/29/2017 09:23:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2017 07:01:46	METER 1 - M:	21448	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2017 07:01:48	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.75	\$100.59	\$41.78	\$0.00	\$142.37

JOB COUNT: 1	WORK ORDER TOTAL:	1.75	100.59	41.78	0.00	142.37
--------------	-------------------	------	--------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/29/2017 11:40:34	11/29/2017 13:25:32	1.75	\$100.59
					LABOR	100.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	SYN0W20	NAPA 0W20	5.75	4	\$22.98
					PARTS	41.78

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 28273

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/CS

(LISAPATE) USED 1/2QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 28926

USING DEPT NO:	301105	OPENED DATE:	02/19/2018 15:10:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2018 09:37:37	METER 1 - M:	25622	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/25/2018 09:37:38	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.76	\$43.84	\$27.34	\$0.00	\$71.18

JOB COUNT: 1	WORK ORDER TOTAL:	0.76	43.84	27.34	0.00	71.18
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/21/2018 10:52:04	02/21/2018 11:37:49	0.76	\$43.84
					LABOR	43.84

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.15	5	\$20.77
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.57	1	\$6.57
					PARTS	27.34

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 28926

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 2/19/2018 3:10 PM By LISAPATE

(LISAPATE) PM BY AG

COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 29114

USING DEPT NO:	301105	OPENED DATE:	03/19/2018 09:44:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2018 09:22:45	METER 1 - M:	25855	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2018 09:22:47	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,451.35	\$1,451.35

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	0.00	1,451.35	1,508.85
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	166402	0042613	\$517.50
24-71	REPAIR BODY	11150605	166402	0042613	(\$517.50)
24-71	REPAIR BODY	11150605	166424	0042683	\$1,451.35
COMML					1451.35

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10208562	03/19/2018 09:51:56	03/19/2018 10:51:56	1.00	\$57.50
LABOR						57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 29114

Work Order Notes

(LISAPATE) TAKE TO ANDREWS TO REPAIR BODY DAMAGE TO THE HOOD AREA. TO BE PAID BY DEPT LESS THAN DED

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) TAKEN TO ANDREWS BY EK

24-71 - REPAIR BODY

(LISAPATE) ANDREWS REPAIRED BODY DAMAGE TO THE HOOD. PD BY CC
INVOICE AND ESTIMATE ATTACHED

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 29861

USING DEPT NO:	301105	OPENED DATE:	05/21/2018 15:35:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2018 07:27:57	METER 1 - M:	29580	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2018 07:27:59	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$14.38	\$29.47	\$0.00	\$43.85

JOB COUNT: 1	WORK ORDER TOTAL:	0.25	14.38	29.47	0.00	43.85
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2018 06:43:11	05/22/2018 06:58:11	0.25	\$14.38
					LABOR	14.38

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	5	\$22.95
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
					PARTS	29.47

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 29861

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/AG

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 30282

USING DEPT NO:	301105	OPENED DATE:	07/18/2018 08:31:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/23/2018 10:13:56	METER 1 - M:	33436	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/23/2018 10:13:58	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$35.32	\$0.00	\$53.15

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	35.32	0.00	53.15
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/18/2018 13:58:08	07/18/2018 14:16:44	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.76	5	\$28.80
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
					PARTS	35.32

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 30282

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH,EK/AG
COOLANT -10'

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 30719

USING DEPT NO:	301105	OPENED DATE:	08/30/2018 10:07:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2018 07:12:57	METER 1 - M:	37073	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/05/2018 07:12:58	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$31.19	\$48.85	\$0.00	\$80.04

JOB COUNT: 1	WORK ORDER TOTAL:	0.54	31.19	48.85	0.00	80.04
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/30/2018 11:37:46	08/30/2018 11:52:56	0.25	\$14.53
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/30/2018 13:05:25	08/30/2018 13:22:48	0.29	\$16.66
					LABOR	31.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.74	5	\$28.72
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.61	1	\$13.61
					PARTS	48.85

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 30719

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 8/30/2018 10:08 AM By LISAPATE

(LISAPATE) PM BY EK,AG/SH

COOLANT -35'

REPLACED AIR FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 31129

USING DEPT NO:	301105	OPENED DATE:	10/10/2018 09:36:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2018 08:30:43	METER 1 - M:	41467	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/12/2018 08:30:44	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.76	\$54.82	\$35.66	\$0.00	\$90.48

JOB COUNT: 1	WORK ORDER TOTAL:	0.76	54.82	35.66	0.00	90.48
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2018 11:43:53	10/10/2018 12:00:00	0.27	\$19.47
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2018 13:00:00	10/10/2018 13:44:51	0.75	\$54.19
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2018 13:00:00	10/10/2018 13:44:51	(0.75)	(\$54.19)
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/10/2018 11:23:01	10/10/2018 11:52:16	0.49	\$35.34
					LABOR	54.81

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
					PARTS	35.66

Work Order Charge Detail

UNIT NO:	242141	2017 TOYOTA CAMRY	WORK ORDER NO:	31129
----------	--------	-------------------	----------------	-------

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 31374

USING DEPT NO:	301105	OPENED DATE:	11/01/2018 15:49:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/05/2018 10:48:03	METER 1 - M:	42896	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/05/2018 10:48:05	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17-005	INSPECT TIRE - SOLID	DON	O	N	GARAGE	1.27	\$92.10	\$0.00	\$0.00	\$92.10
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.17	\$12.26	\$7.22	\$0.00	\$19.48

JOB COUNT: 2	WORK ORDER TOTAL:	1.44	104.36	7.22	0.00	111.58
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	11/02/2018 07:36:20	11/02/2018 07:46:29	0.17	\$12.26
06-17-005	INSPECT TIRE - SOLID	11901357	11/02/2018 06:19:51	11/02/2018 07:36:04	1.27	\$92.10
					LABOR	104.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.30	1	\$3.30
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.51	1	\$3.51
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	1	\$0.41
					PARTS	7.22

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 31374

Work Order Notes

(EKIMBREL) low tire light on

Job Notes

06-17-005 - INSPECT TIRE - SOLID

(LISAPATE) Found a nail in LR tire

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Removed and patched LR tire from the inside. Rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 32654

USING DEPT NO:	301105	OPENED DATE:	04/17/2019 09:02:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2019 13:12:03	METER 1 - M:	48889	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/25/2019 13:12:04	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.42	\$30.65	\$0.00	\$0.00	\$30.65
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$29.00	\$269.38	\$0.00	\$298.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.10	\$79.67	\$50.86	\$0.00	\$130.53
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$21.75	\$7.33	\$0.00	\$29.08

JOB COUNT: 5	WORK ORDER TOTAL:	2.72	197.32	327.57	0.00	524.89
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/17/2019 13:04:04	04/17/2019 13:42:57	0.65	\$46.98
09-15	ALIGN STEERING	11310047	04/22/2019 11:31:20	04/22/2019 11:56:42	0.42	\$30.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11268671	04/22/2019 07:00:00	04/22/2019 07:24:00	0.40	\$29.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/22/2019 06:00:00	04/22/2019 06:18:00	0.30	\$21.75
06-15	INSPECT STEERING	11074414	04/22/2019 06:00:00	04/22/2019 06:30:00	0.50	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/17/2019 13:14:06	04/17/2019 13:41:09	0.45	\$32.69

LABOR 197.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	15.20	1	\$15.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	131.09	2	\$262.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.40	3	\$1.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.00	2	\$6.00

PARTS 327.57

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 32654

Work Order Notes

(LISAPATE) PM

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) SH inspected front end parts. All good

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced 2 new tires. Installed on the rear

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Replaced air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 33739

USING DEPT NO:	301105	OPENED DATE:	08/16/2019 11:01:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2019 09:52:53	METER 1 - M:	54484	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/20/2019 09:52:55	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.64	\$118.94	\$44.24	\$0.00	\$163.18

JOB COUNT: 1	WORK ORDER TOTAL:	1.64	118.94	44.24	0.00	163.18
--------------	-------------------	------	--------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/16/2019 11:15:49	08/16/2019 11:55:11	0.66	\$47.57
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/16/2019 11:14:32	08/16/2019 11:56:02	0.69	\$50.15
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/16/2019 11:15:02	08/16/2019 11:32:36	0.29	\$21.23
					LABOR	118.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	4	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	14.46	1	\$14.46
					PARTS	44.24

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 33739

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH,AG/JW

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 34758

USING DEPT NO:	301105	OPENED DATE:	11/05/2019 15:12:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2019 08:26:42	METER 1 - M:	58466	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/11/2019 08:26:43	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$57.94	\$42.04	\$0.00	\$99.98
CL-32-007	CLEANED CLEAN TERMINAL(S)	DON	O	N	GARAGE	0.00	\$0.00	\$1.26	\$0.00	\$1.26

JOB COUNT: 2	WORK ORDER TOTAL:	0.80	57.94	43.30	0.00	101.24
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/06/2019 07:00:04	11/06/2019 07:16:26	0.27	\$19.78
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/06/2019 07:05:42	11/06/2019 07:19:54	0.24	\$17.16
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/05/2019 15:34:37	11/05/2019 15:52:00	0.29	\$21.00
					LABOR	57.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
CL-32-007	CLEANED CLEAN TERMINAL(S)	740245	BATTERY TERM PROTECTOR WASHER	0.63	2	\$1.26
					PARTS	43.30

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 34758

Work Order Notes

(IFALLS) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,SH/SH

CL-32-007 - CLEANED CLEAN TERMINAL(S)

(LISAPATE) Cleaned battery terminals added 2 corrosion washers

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 35857

USING DEPT NO:	301105	OPENED DATE:	03/03/2020 09:55:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2020 07:55:46	METER 1 - M:	64318	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2020 07:55:48	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.11	\$80.15	\$54.45	\$0.00	\$134.60
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.06	\$4.43	\$7.33	\$0.00	\$11.76

JOB COUNT: 2	WORK ORDER TOTAL:	1.17	84.58	61.78	0.00	146.36
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	03/03/2020 14:07:03	03/03/2020 14:10:43	0.06	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/03/2020 14:10:43	03/03/2020 14:32:20	0.36	\$26.12
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/03/2020 14:04:30	03/03/2020 14:33:28	0.48	\$35.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/03/2020 13:51:18	03/03/2020 14:07:03	0.26	\$19.03
					LABOR	84.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.33	1	\$12.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
					PARTS	61.78

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 35857

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH

Coolant -35'

Replaced air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 37272

USING DEPT NO:	301105	OPENED DATE:	08/06/2020 10:02:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2020 12:23:01	METER 1 - M:	65732	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/06/2020 13:57:03	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$12.75	\$0.00	\$0.00	\$12.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.18	12.75	0.00	0.00	12.75
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/06/2020 11:31:02	08/06/2020 11:41:35	0.18	\$12.75
					LABOR	12.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	(5)	(\$29.18)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	(1)	(\$6.50)
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 37272

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH checked fluids, battery, tire pressures, and updated sticker. Coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 38811

USING DEPT NO:	301105	OPENED DATE:	01/19/2021 07:36:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/21/2021 08:49:29	METER 1 - M:	68180	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/21/2021 12:48:02	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.95	\$38.08	\$0.00	\$88.03

JOB COUNT: 1	WORK ORDER TOTAL:	0.42	49.95	38.08	0.00	88.03
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/19/2021 14:51:01	01/19/2021 14:54:27	0.06	\$6.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/19/2021 13:41:52	01/19/2021 14:03:50	0.37	\$43.20
					LABOR	49.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	5	\$31.58
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
					PARTS	38.08

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 38811

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant-35°. Washed, vacuumed and fueled up. JAW,SH/AMG
MILEAGE-68180

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 40063

USING DEPT NO:	301105	OPENED DATE:	06/01/2021 09:54:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2021 09:09:28	METER 1 - M:	69256	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2021 08:58:45	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.25	\$29.76	\$0.00	\$0.00	\$29.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.58	\$0.00	\$0.00	\$36.58

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	66.34	0.00	0.00	66.34
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/01/2021 10:33:13	06/01/2021 10:42:10	0.15	\$17.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/01/2021 10:32:46	06/01/2021 10:42:25	0.16	\$18.98
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/01/2021 10:42:35	06/01/2021 10:57:43	0.25	\$29.76
					LABOR	66.34

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 40063

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1076 miles. Updated pm sticker. Checked all fluids and tires. Found tires need rotated for more life. Coolant -34°. JAW,SH
MILEAGE-69256

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 41223

USING DEPT NO:	301105	OPENED DATE:	10/06/2021 07:10:30	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2021 10:58:18	METER 1 - M:	72429	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2021 09:55:09	IN-SERVICE DATE:	11/15/2016						
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry									
			UNIT SERIAL NO:	4T1BF1FK0HU657998							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.29	\$17.90	\$0.00	\$20.19
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.55	\$64.87	\$0.00	\$0.00	\$64.87
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$47.20	\$276.85	\$0.00	\$324.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.44	\$34.67	\$0.00	\$36.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.23	145.30	329.42	2.00	476.72
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/07/2021 07:45:21	10/07/2021 07:46:31	0.02	\$2.29
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/07/2021 07:44:29	10/07/2021 07:45:13	0.01	\$1.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/07/2021 12:32:30	10/07/2021 12:56:30	0.40	\$47.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/07/2021 12:32:30	10/07/2021 12:32:30	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/07/2021 12:32:30	10/07/2021 12:32:30	0.00	\$0.00
06-15	INSPECT STEERING	12052187	10/07/2021 12:56:54	10/07/2021 13:11:54	0.25	\$29.50
06-15	INSPECT STEERING	12052187	10/07/2021 12:56:54	10/07/2021 12:56:54	0.00	\$0.00
06-15	INSPECT STEERING	12052187	10/07/2021 12:56:54	10/07/2021 12:56:54	0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	11170580	10/07/2021 14:20:17	10/07/2021 14:20:17	0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	11170580	10/07/2021 14:30:00	10/07/2021 15:02:59	0.55	\$64.87
LABOR						145.30

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.61	1	\$5.61
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	135.02	2	\$270.03
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.35	1	\$0.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.47	1	\$0.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.00	2	\$6.00
					PARTS	329.42

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 41223

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) RC installed new wiper blades. JAW

06-15 - INSPECT STEERING

(JWRIGHT) Front end good

66-17-013 - PERFORM ALIGNMENT

(ABLACK) AB performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced both rear tires and moved to front. Balanced both. Torqued lug nuts to spec. JAW,RC

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) RC and SH performed pm service. Coolant -35. RC/SH
MILEAGE-72429

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 42473

USING DEPT NO:	301105	OPENED DATE:	02/25/2022 07:45:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2022 13:25:43	METER 1 - M:	75559	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/28/2022 08:35:37	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.41	\$17.90	\$0.00	\$29.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.03	\$122.00	\$43.05	\$0.00	\$165.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.13	133.41	60.95	2.00	196.36
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2022 09:30:00	02/25/2022 09:44:15	0.24	\$28.03
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2022 08:40:36	02/25/2022 09:15:00	0.57	\$67.65
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2022 08:58:54	02/25/2022 09:11:50	0.22	\$25.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2022 09:43:49	02/25/2022 09:44:16	0.01	\$0.89
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/25/2022 09:44:41	02/25/2022 09:50:29	0.10	\$11.41
				LABOR		133.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	14.57	1	\$14.57
				PARTS		60.95

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 42473

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) JW Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 44587

USING DEPT NO:	301105	OPENED DATE:	09/07/2022 07:49:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/13/2022 11:19:49	METER 1 - M:	83563	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2022 08:54:39	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$18.38	\$0.00	\$30.18
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.09	\$129.05	\$0.00	\$0.00	\$129.05
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.24	\$28.35	\$344.62	\$0.00	\$372.97
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.57	\$67.59	\$0.00	\$0.00	\$67.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.74	\$66.82	\$0.00	\$101.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	2.55	301.03	429.82	5.00	735.85
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/09/2022 14:17:38	09/09/2022 14:17:38	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/09/2022 14:30:00	09/09/2022 14:44:25	0.24	\$28.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/09/2022 14:17:38	09/09/2022 14:17:38	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/09/2022 14:30:00	09/09/2022 14:44:25	(0.24)	(\$28.35)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/09/2022 14:17:38	09/09/2022 14:17:38	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/08/2022 12:26:58	09/08/2022 12:26:58	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2022 11:07:23	09/08/2022 11:25:03	0.29	\$34.74
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/08/2022 12:47:03	09/08/2022 12:47:03	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/08/2022 12:47:03	09/08/2022 12:47:03	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/08/2022 12:47:03	09/08/2022 12:53:03	0.10	\$11.80
66-79-003	PERFORM SAFETY INSPECTION	12296277	09/08/2022 15:18:06	09/08/2022 15:52:28	0.57	\$67.59

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/09/2022 14:30:00	09/09/2022 14:44:25	0.24	\$28.35
66-17-013	PERFORM ALIGNMENT	12296277	09/12/2022 07:15:07	09/12/2022 08:20:44	(1.09)	(\$129.05)
66-17-013	PERFORM ALIGNMENT	12296277	09/12/2022 07:15:07	09/12/2022 08:20:44	1.09	\$129.05
66-17-013	PERFORM ALIGNMENT	12296277	09/12/2022 07:15:07	09/12/2022 08:20:44	1.09	\$129.05
06-15	INSPECT STEERING	11074414	09/14/2022 07:00:00	09/14/2022 07:15:00	(0.25)	(\$29.50)
06-15	INSPECT STEERING	11074414	09/14/2022 07:00:00	09/14/2022 07:15:00	0.25	\$29.50
06-15	INSPECT STEERING	11074414	09/14/2022 07:00:00	09/14/2022 07:15:00	0.25	\$29.50
					LABOR	301.03

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.80	1	\$7.80
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.58	1	\$10.58
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	24.84	1	\$24.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	1	\$0.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.88	2	\$11.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	2	\$331.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	(2)	(\$331.38)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	(1)	(\$0.26)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	(1)	(\$0.59)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	(1)	(\$0.63)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.88	(2)	(\$11.76)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	2	\$331.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	1	\$0.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.88	2	\$11.76
					PARTS	429.82

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 44587

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

06-15 - INSPECT STEERING

(GARAGE) inspected steering JDM

(AJONES) Visit Reason Changed On 9/26/2022 9:46 AM By AJONES

66-17-013 - PERFORM ALIGNMENT

(GARAGE) aligned front and rear toe JDM with Ethan

(AJONES) Visit Reason Changed On 9/26/2022 9:46 AM By AJONES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) mounted and balanced 2 tires JDM

(AJONES) Visit Reason Changed On 9/26/2022 9:46 AM By AJONES

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) 2 tires for the rear

(GARAGE) inspected JDM

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 83563 Completed PM bottomside, Scott was topside. SH/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 46044

USING DEPT NO:	301105	OPENED DATE:	02/03/2023 08:57:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2023 14:58:12	METER 1 - M:	88709	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2023 10:11:41	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.62	\$18.41	\$0.00	\$19.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.34	\$49.35	\$0.00	\$58.69
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.08	9.96	67.76	5.00	82.72
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/03/2023 12:43:02	02/03/2023 12:43:21	0.01	\$0.62
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/03/2023 12:38:07	02/03/2023 12:42:52	0.08	\$9.34
				LABOR		9.96

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.59	1	\$10.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
				PARTS		67.76

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 46044

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. COOLANT -34 SH,/SH,JAW
MILEAGE-88709

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 47685

USING DEPT NO:	301105	OPENED DATE:	07/21/2023 07:18:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/21/2023 13:24:17	METER 1 - M:	96193	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/24/2023 09:31:12	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.10	\$11.73	\$115.32	\$0.00	\$127.05
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.77	\$19.29	\$0.00	\$25.06
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.25	\$29.07	\$0.00	\$0.00	\$29.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$13.21	\$65.97	\$0.00	\$79.18
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.06	\$6.49	\$20.27	\$0.00	\$26.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.27	\$32.22	\$0.00	\$0.00	\$32.22

JOB COUNT: 7	WORK ORDER TOTAL:	0.83	98.49	220.85	5.00	324.34
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	07/21/2023 11:06:14	07/21/2023 11:22:37	0.27	\$32.22
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2023 10:21:00	07/21/2023 10:23:56	0.05	\$5.77
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/21/2023 10:14:17	07/21/2023 10:21:00	0.11	\$13.21
03-32-002	REPLACE NEW BATTERY	11074414	07/21/2023 09:45:30	07/21/2023 09:51:28	0.10	\$11.73
03-32-002	REPLACE NEW BATTERY	11074414	07/21/2023 09:45:30	07/21/2023 09:51:28	0.10	\$11.73
03-32-002	REPLACE NEW BATTERY	11074414	07/21/2023 09:45:30	07/21/2023 09:51:28	(0.10)	(\$11.73)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	07/21/2023 10:10:59	07/21/2023 10:14:17	0.06	\$6.49
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/21/2023 10:36:10	07/21/2023 10:50:57	0.25	\$29.07
				LABOR		98.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	8.13	1	\$8.13

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	115.32	1	\$115.32
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.16	1	\$11.16
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.11	1	\$6.11
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	20.27	1	\$20.27
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	115.32	(1)	(\$115.32)
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	115.32	1	\$115.32
					PARTS	220.85

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 47685

Work Order Notes

(LISAPATE) PM-repalce wipers-wash

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Battery in vehicle was the factory battery and was 6 years old. Installed a new battery. SH

(LRUSHING) Visit Reason Changed On 7/28/2023 10:12 AM By LRUSHING

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires and inspected the brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/GC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 49132

USING DEPT NO:	301105	OPENED DATE:	12/04/2023 07:00:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2023 10:06:11	METER 1 - M:	103700	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2023 13:19:12	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.02	\$19.60	\$0.00	\$22.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.67	\$55.23	\$0.00	\$78.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.61	\$72.05	\$0.00	\$0.00	\$72.05

JOB COUNT: 4	WORK ORDER TOTAL:	0.84	98.74	74.83	5.00	178.57
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2023 09:18:33	12/04/2023 09:18:33	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2023 09:30:00	12/04/2023 09:42:02	0.20	\$23.67
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/04/2023 09:42:12	12/04/2023 09:43:44	0.03	\$3.02
WA-00	WASH COMPLETE VEHICLE	11074414	12/04/2023 09:43:54	12/04/2023 10:20:32	0.61	\$72.05
				LABOR		98.74

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.77	1	\$10.77
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	5	\$31.50
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.27	1	\$11.27
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	12.96	1	\$12.96
				PARTS		74.83

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 49132

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed is full of gas returned to parking deck. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 49620

USING DEPT NO:	301105	OPENED DATE:	01/29/2024 10:36:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2024 09:59:01	METER 1 - M:	103700	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2024 09:59:04	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK0HU657998	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.13	\$2.13
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.13	\$0.00	\$0.00	\$2.13

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.13	0.00	2.13	4.26
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.13
				COMML	2.13

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	02/02/2024 15:47:04	02/02/2024 15:48:09	0.02	\$2.13
					LABOR	2.13

Work Order Charge Detail

The University of Alabama

Report Printed: 02/26/2024 16:04:26 By User: GLOBETTI

UNIT NO: 242141 2017 TOYOTA CAMRY

WORK ORDER NO: 49620

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed tag and window decal\RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Feb 26 2024 16:04:26 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242141') //Q=