

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 38856

USING DEPT NO: 507102	OPENED DATE: 01/21/2021 07:50:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/21/2021 07:52:03	METER 1 - M: 374 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/21/2021 12:50:27	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **0.00** **59.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11915538	01/21/2021 07:51:26	01/21/2021 08:21:26	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 38856

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 40245

USING DEPT NO:	507102	OPENED DATE:	06/25/2021 07:01:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2021 10:29:35	METER 1 - M:	2023	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/28/2021 11:52:33	IN-SERVICE DATE:	01/15/2021	
TECH SPEC NO:	20FORDF1504X4	2020 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.92	\$56.69	\$0.00	\$106.61

JOB COUNT: 1 WORK ORDER TOTAL: 0.42 49.92 56.69 0.00 106.61

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11310047	06/25/2021 07:22:04	06/25/2021 07:29:06	0.12	\$13.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/25/2021 07:05:13	06/25/2021 07:23:34	0.31	\$36.09
					LABOR	49.92

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	9	\$40.37
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
					PARTS	56.69

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 40245

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Performed PM. EH/SH TOP. AMG BOTTOM.

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 41479

USING DEPT NO:	507102	OPENED DATE:	11/02/2021 07:07:07	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 07:45:07	METER 1 - M:	3479	METER 2 - H:	0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/04/2021 07:45:11	IN-SERVICE DATE:	01/15/2021		
TECH SPEC NO:	20FORDF1504X4	2020 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1E57LKE54589		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.02	\$15.18	\$0.00	\$20.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.89	\$55.35	\$0.00	\$99.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.41	48.91	70.53	2.00	121.44
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/02/2021 07:39:30	11/02/2021 07:42:03	0.04	\$5.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2021 07:17:01	11/02/2021 07:39:20	0.37	\$43.89
LABOR					48.91	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	9	\$39.83
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	(9)	(\$40.37)
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.96	1	\$8.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	9	\$40.37
PARTS					70.53	

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 41479

Work Order Notes

(IFALLS) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) AB EH/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 43054

USING DEPT NO: 507102	OPENED DATE: 04/27/2022 07:23:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/28/2022 14:15:01	METER 1 - M: 7605 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/28/2022 14:38:16	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.06	\$20.37	\$0.00	\$24.43
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$97.25	\$78.12	\$0.00	\$175.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.86** **101.31** **98.49** **2.00** **201.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/27/2022 07:32:02	04/27/2022 08:02:24	0.51	\$59.72
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/27/2022 07:57:20	04/27/2022 07:59:24	0.03	\$4.06
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/27/2022 07:37:42	04/27/2022 07:56:47	0.32	\$37.53
LABOR					101.31	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.14	1	\$9.14
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	9	\$50.63
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	2	\$20.37
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS					98.49	

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 43054

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 7605 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 45397

USING DEPT NO: 507102	OPENED DATE: 12/01/2022 08:53:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/02/2022 09:02:02	METER 1 - M: 11395 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/02/2022 09:48:24	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.51	\$20.94	\$0.00	\$24.45
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.45	\$52.94	\$0.00	\$0.00	\$52.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.81	\$86.63	\$0.00	\$123.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.15	\$17.63	\$29.52	\$0.00	\$47.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.94	110.89	137.09	5.00	252.98
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	12/01/2022 10:39:38	12/01/2022 11:06:33	0.45	\$52.94
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/01/2022 10:37:40	12/01/2022 10:39:27	0.03	\$3.51
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	12/01/2022 10:29:05	12/01/2022 10:38:03	0.15	\$17.63
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/01/2022 10:18:43	12/01/2022 10:37:26	0.31	\$36.81
					LABOR	110.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	24.30	1	\$24.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	29.52	1	\$29.52
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.17	1	\$6.17
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	9	\$56.16
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	2	\$20.94
					PARTS	137.09

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 45397

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH AMG/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 46435

USING DEPT NO: 507102	OPENED DATE: 03/09/2023 14:08:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/09/2023 14:12:26	METER 1 - M: 12482 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/09/2023 14:28:43	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,300.00	\$2,300.00
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	2,305.00	2,364.00
---------------------	--------------------------	-------------	--------------	-------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-71	REPAIR BODY	11150605	1697288		\$2,300.00
COMML					2305.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11915538	03/09/2023 14:09:08	03/09/2023 14:39:08	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 46435

Work Order Notes

(LISAPATE) Take to Body Shop to repair L side rear damage . State Auto to pay

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrew by RC

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage per the estimate. State Auto paid \$324.46. UA pd \$2000.00 ded by PO State auto also paid \$ 1228.57 supplement

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 3/23/2023 1:54 PM By AJONES

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 46739

USING DEPT NO: 507102	OPENED DATE: 04/18/2023 06:57:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/19/2023 10:52:01	METER 1 - M: 14547 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 04/19/2023 13:19:26	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$4.75	\$65.69	\$0.00	\$70.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.04** **4.75** **65.69** **5.00** **75.44**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/18/2023 07:15:48	04/18/2023 07:18:13	0.04	\$4.75
LABOR					4.75	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	9	\$56.16
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	9.53	1	\$9.53
PARTS					65.69	

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 46739

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant-34°. JAW,SH/GC
MILEAGE-14547

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 48015

USING DEPT NO: 507102	OPENED DATE: 08/29/2023 06:50:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2023 10:16:20	METER 1 - M: 16606 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 09/11/2023 15:17:55	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.33** **38.94** **0.00** **5.00** **43.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	08/31/2023 07:00:00	08/31/2023 07:19:48	0.33	\$38.94
LABOR						38.94

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 48015

Work Order Notes

(IFALLS) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 48413

USING DEPT NO: 507102	OPENED DATE: 10/05/2023 07:37:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/06/2023 07:55:10	METER 1 - M: 17197 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2023 08:39:26	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.66	\$78.24	\$0.00	\$0.00	\$78.24

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.66** **78.24** **0.00** **5.00** **83.24**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	10/05/2023 07:45:52	10/05/2023 08:25:39	0.66	\$78.24
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	10/05/2023 07:45:52	10/05/2023 08:25:39	(0.66)	(\$78.24)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	10/05/2023 07:45:52	10/05/2023 08:25:39	0.66	\$78.24
LABOR						78.24

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 48413

Work Order Notes

(LISAPATE) inspect display is not working at times and scan out.

Job Notes

06-02-082 - INSPECT CENTER CONSOLE/LATCH ASSY

(LISAPATE) cancel

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 10/18/2023 3:28 PM By LRUSHING

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(JWRIGHT) Scanned unit out and found no issues. No tsb was mentioned for this issue. Unhooked battery for 10 minutes for a hard reset. JAW

(LRUSHING) Visit Reason Changed On 10/18/2023 3:28 PM By LRUSHING

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 48905

USING DEPT NO: 507102	OPENED DATE: 11/09/2023 07:23:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/05/2023 14:48:25	METER 1 - M: 17861 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/06/2023 13:47:20	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E57LKE54589	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-35	INSPECT MULTI-FUNC ELECTRON/ELEI	DON	N	N	GARAGE	3.15	\$371.18	\$0.00	\$0.00	\$371.18
15-52-003	WARRANTY RADIO	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-52	TRANSPORT ELECTRICAL ACCESSORI	DON	N	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
25-35-019	REMOVE POWER INVERTER	DON	N	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
25-78-031	REMOVE TONNEAU/BED COVER	DON	N	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	N	N	GARAGE	0.53	\$63.00	\$13.11	\$0.00	\$76.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	6.18	729.18	13.11	5.00	747.29
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
25-78-031	REMOVE TONNEAU/BED COVER	12052187	12/05/2023 07:30:00	12/05/2023 08:00:00	0.50	\$59.00
25-78-031	REMOVE TONNEAU/BED COVER	12052187	12/05/2023 07:30:00	12/05/2023 08:00:00	(0.50)	(\$59.00)
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11399745	12/05/2023 07:00:00	12/05/2023 07:30:00	0.50	\$59.00
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11399745	12/05/2023 07:00:00	12/05/2023 07:30:00	(0.50)	(\$59.00)
25-35-019	REMOVE POWER INVERTER	12052187	12/05/2023 07:00:00	12/05/2023 08:00:00	1.00	\$118.00
25-35-019	REMOVE POWER INVERTER	12052187	12/05/2023 07:00:00	12/05/2023 08:00:00	(1.00)	(\$118.00)
25-78-031	REMOVE TONNEAU/BED COVER	12052187	12/05/2023 07:30:00	12/05/2023 08:00:00	0.50	\$59.00
25-35-019	REMOVE POWER INVERTER	12052187	12/05/2023 07:00:00	12/05/2023 08:00:00	1.00	\$118.00
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11399745	12/05/2023 07:00:00	12/05/2023 07:30:00	0.50	\$59.00
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11399745	12/05/2023 07:00:00	12/05/2023 07:30:00	0.50	\$59.00
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11399745	12/05/2023 07:00:00	12/05/2023 07:30:00	(0.50)	(\$59.00)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11399745	12/05/2023 07:00:00	12/05/2023 07:30:00	0.50	\$59.00
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11310047	11/09/2023 15:18:50	11/09/2023 15:50:52	0.53	\$63.00
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11310047	11/09/2023 15:18:50	11/09/2023 15:50:52	(0.53)	(\$63.00)
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11310047	11/09/2023 15:18:50	11/09/2023 15:50:52	0.53	\$63.00
06-35	INSPECT MULTI-FUNC ELECTRON/ELEC DEVCS	11310047	11/09/2023 07:43:38	11/09/2023 10:52:22	3.15	\$371.18
					LABOR	729.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	SF16	SEA FOAM 16OZ	13.11	(1)	(\$13.11)
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	13.11

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 48905

Work Order Notes

(EHANNAH) display is not keeping settings- and valve is knocking he ask for fuel cleaner to be added.

Job Notes

06-35 - INSPECT MULTI-FUNC ELECTRON/ELEC DEVCS

(EHOWELL) The customer is continuously having to reset his clock. Also, every time the vehicle is started, there is an annoying sync message that keeps popping up. Checked for DTCs and verified that the audio control module programming was up to date. The customer plans to bring the vehicle back when he will not be needing it for a while. We can then send it to the dealer. It's under bumper-to-bumper warranty until January. EH

15-52-003 - WARRANTY RADIO

(LISAPATE) Ford verified radio was inop needs a sync module, also found internal problem in engine. All parts are on back-order truck has been brought to the shop. Donald Keith was given another truck to drive until a new truck arrives for him. Tonneau cover was removed along with power inverter. Tony and Issac have spoken with the Southeastern Ford Rep he is working on trying to get an engine for us.

16-52 - TRANSPORT ELECTRICAL ACCESSORIES

(LISAPATE) Taken to Ford by RC/CW

(LRUSHING) Visit Reason Changed On 12/18/2023 8:44 AM By LRUSHING

25-35-019 - REMOVE POWER INVERTER

(LRUSHING) Visit Reason Changed On 12/18/2023 8:45 AM By LRUSHING

25-78-031 - REMOVE TONNEAU/BED COVER

(LRUSHING) Visit Reason Changed On 12/18/2023 8:44 AM By LRUSHING

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(EHOWELL) The customer stated that he thinks there is an issue with the fuel. A certain brand of fuel is causing his engine to rattle. The owner's manual stated that 87 octane and E85 are approved to run in this vehicle. He also stated that the knocking ceased the last time we used fuel additive. Installed one bottle of Seafoam. EH

(LRUSHING) Visit Reason Changed On 12/18/2023 8:44 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243979 **2020 FORD F150 4X4** **WORK ORDER NO:** 50240

USING DEPT NO: 507102	OPENED DATE: 03/25/2024 10:39:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: COMPLETED	COMPLETED DATE: 03/25/2024 10:56:59	METER 1 - M: 17969 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE:	IN-SERVICE DATE: 01/15/2021
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E57LKE54589

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-40	WARRANTY ENGINE / MOTOR SYSTEM	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-40	TRANSPORT ENGINE / MOTOR SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-00-999	PERFORM PREPARE UNIT FOR DISPOS	DON	D	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.50** **177.00** **0.00** **0.00** **177.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-40	WARRANTY ENGINE / MOTOR SYSTEMS	11078175	122830		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-40	TRANSPORT ENGINE / MOTOR SYSTEMS	11915538	03/25/2024 10:46:30	03/25/2024 11:16:30	0.50	\$59.00
66-00-999	PERFORM PREPARE UNIT FOR DISPOSAL	11399745	03/25/2024 10:48:53	03/25/2024 11:48:53	1.00	\$118.00
LABOR						177.00

Work Order Charge Detail

UNIT NO: 243979 2020 FORD F150 4X4

WORK ORDER NO: 50240

Work Order Notes

(LISAPATE) Engine is knocking take to Ford to have engine replaced. After returning from Ford. Prep for sale

Job Notes

15-40 - WARRANTY ENGINE / MOTOR SYSTEMS

(LISAPATE) Ford could not get parts to rebuild engine so engine was removed and new engine installed. See attached notes.

16-40 - TRANSPORT ENGINE / MOTOR SYSTEMS

(LISAPATE) Taken to Ford by RC/CW

66-00-999 - PERFORM PREPARE UNIT FOR DISPOSAL

(LISAPATE) Prep for sale completed. Tag was transferred to new truck

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Mar 25 2024 12:39:31 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243979') //Q=