

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 19282

USING DEPT NO:	218142	OPENED DATE:	01/21/2015 08:33:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/22/2015 14:00:15	METER 1 - M:	243	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/22/2015 14:00:16	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10260422	01/21/2015 08:34:41	01/21/2015 09:04:41	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 19282

Work Order Notes

(LPATE) PDI NEW CAR

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 19881

USING DEPT NO:	218142	OPENED DATE:	03/27/2015 09:25:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2015 11:58:18	METER 1 - M:	4442	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2015 11:58:19	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.44	\$25.57	\$37.86	\$0.00	\$63.43
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	2.15	\$123.81	\$0.00	\$0.00	\$123.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.81	\$103.93	\$34.53	\$0.00	\$138.46

JOB COUNT: 3	WORK ORDER TOTAL:	4.41	253.31	72.39	0.00	325.70
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11338644	03/27/2015 13:03:52	03/27/2015 15:13:04	2.15	\$123.81
03-51-038	REPLACE NEW WIPER BLADES	11338644	03/27/2015 15:22:58	03/27/2015 15:49:39	0.44	\$25.57
66-PM-PMA	PERFORM OIL CHANGE	11338644	03/27/2015 11:15:06	03/27/2015 13:03:33	1.81	\$103.93
					LABOR	253.31

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.69	4	\$22.74
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
03-51-038	REPLACE NEW WIPER BLADES	40726	WIPER BLADE 26"	21.96	1	\$21.96
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	15.90	1	\$15.90
					PARTS	72.39

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 19881

Work Order Notes

(LPATE) PM-REPLACE WIPERS-ROTATE TIRES

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY AY/RS

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 20424

USING DEPT NO:	218142	OPENED DATE:	06/01/2015 08:34:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2015 14:33:00	METER 1 - M:	10216	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2015 14:33:02	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.62	\$93.33	\$35.13	\$0.00	\$128.46

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.62** **93.33** **35.13** **0.00** **128.46**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	06/01/2015 10:12:32	06/01/2015 11:49:55	1.62	\$93.33
					LABOR	93.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
					PARTS	35.13

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 20424

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY RS

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 21251

USING DEPT NO: 218142	OPENED DATE: 08/28/2015 08:07:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2015 13:49:51	METER 1 - M: 14719 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/31/2015 13:49:53	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.15	\$65.87	\$33.65	\$0.00	\$99.52

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.15** **65.87** **33.65** **0.00** **99.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2015 07:40:49	08/31/2015 08:49:33	1.15	\$65.87
					LABOR	65.87

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.17	1	\$4.17
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
					PARTS	33.65

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 21251

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY GM/SH-USED 1/2QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 21677

USING DEPT NO:	218142	OPENED DATE:	10/08/2015 10:20:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2015 08:29:45	METER 1 - M:	18257	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/12/2015 08:29:47	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.63	\$93.44	\$29.13	\$0.00	\$122.57

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.63** **93.44** **29.13** **0.00** **122.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/09/2015 06:33:21	10/09/2015 08:10:51	1.63	\$93.44
					LABOR	93.44

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20NP	OIL 0W-20 SYN NAPA	5.69	2	\$11.37
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE 0W20 SYNTHETIC OIL QT	5.64	2	\$11.28
					PARTS	29.13

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 21677

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH-USED 1/2 QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 22111

USING DEPT NO:	218142	OPENED DATE:	12/01/2015 08:41:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2015 07:20:40	METER 1 - M:	23217	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2015 07:20:41	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.12	\$6.92	\$25.58	\$0.00	\$32.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$29.21	\$32.92	\$0.00	\$62.13

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.63** **36.13** **58.50** **0.00** **94.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	10260422	12/01/2015 10:05:17	12/01/2015 10:12:30	0.12	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	10260422	12/01/2015 09:34:48	12/01/2015 10:05:17	0.51	\$29.21
					LABOR	36.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.19	1	\$6.19
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.17	1	\$4.17
					PARTS	58.50

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 22111

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 22891

USING DEPT NO: 218142	OPENED DATE: 03/24/2016 08:51:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/25/2016 10:49:00	METER 1 - M: 29157 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/25/2016 10:49:02	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FKXFU872821

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$47.00	\$0.00	\$64.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	C	N	GARAGE	0.30	\$17.25	\$7.55	\$0.00	\$24.80

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.61** **35.08** **54.55** **0.00** **89.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	03/25/2016 07:18:36	03/25/2016 07:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	03/25/2016 07:00:00	03/25/2016 07:18:36	0.31	\$17.83
					LABOR	35.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.55	1	\$7.55
					PARTS	54.55

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 22891

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AY/CS-REPLACED AIR FILTER

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 23589

USING DEPT NO: 218142	OPENED DATE: 06/03/2016 11:05:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/09/2016 14:00:48	METER 1 - M: 33735 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/09/2016 14:00:49	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.62	\$0.00	\$51.45

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **33.62** **0.00** **51.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/03/2016 13:26:10	06/03/2016 13:26:18	0.00	\$0.13
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/03/2016 13:26:10	06/03/2016 13:26:18	0.00	(\$0.13)
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/03/2016 13:26:10	06/03/2016 13:44:46	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.13	1	\$4.13
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
					PARTS	33.62

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 23589

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 24233

USING DEPT NO:	218142	OPENED DATE:	08/26/2016 13:57:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2016 15:07:54	METER 1 - M:	36377	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/31/2016 15:07:55	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$25.58	\$0.00	\$39.96

JOB COUNT: 1 **WORK ORDER TOTAL: 0.25 14.38 25.58 0.00 39.96**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/26/2016 13:58:24	08/26/2016 14:13:24	0.25	\$14.38
					LABOR	14.38

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
					PARTS	25.58

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 24233

Work Order Notes

(LISAPATE) FLEET REQUESTED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 24666

USING DEPT NO: 218142	OPENED DATE: 10/19/2016 07:13:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/21/2016 06:42:33	METER 1 - M: 39231 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/21/2016 06:42:34	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.61	\$0.00	\$62.44

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **44.61** **0.00** **62.44**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/20/2016 06:00:00	10/20/2016 06:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.66	4	\$22.62
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	(1)	(\$5.64)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	(4)	(\$27.72)
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	1	\$5.64
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	4	\$27.72
					PARTS	44.61

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 24666

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS-SH-REPLACED AIR FILTER

(LISAPATE) USED 1/2QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 25708

USING DEPT NO: 218142	OPENED DATE: 02/09/2017 09:45:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/10/2017 14:45:50	METER 1 - M: 44424 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 02/10/2017 14:45:55	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FKXFU872821

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.51	\$0.00	\$47.34

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **46.58** **29.51** **0.00** **76.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/09/2017 11:41:39	02/09/2017 11:59:51	0.30	\$17.44
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/09/2017 11:41:39	02/09/2017 11:59:51	(0.30)	(\$17.44)
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11170580	02/09/2017 13:14:12	02/09/2017 13:44:12	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/09/2017 11:41:39	02/09/2017 12:00:15	0.31	\$17.83
					LABOR	46.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.95	1	\$6.95
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
					PARTS	29.51

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 25708

Work Order Notes

(RWINTERS) PM ROTATE TIRES

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(IFALLS) AB ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AB PERFORMED PM / COOLANT CHECKED GOOD TO -45

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 26391

USING DEPT NO: 218142	OPENED DATE: 05/22/2017 10:33:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/24/2017 09:04:34	METER 1 - M: 49365 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 05/24/2017 09:04:35	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FKXFU872821

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$50.03	\$0.00	\$67.86
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.61** **35.08** **50.03** **0.00** **85.11**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11170580	05/22/2017 15:16:18	05/22/2017 15:34:18	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11170580	05/22/2017 15:15:57	05/22/2017 15:34:33	0.31	\$17.83
					LABOR	35.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	8.75	(1)	(\$8.75)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	8.75	1	\$8.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	8.75	(1)	(\$8.75)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	8.75	1	\$8.75
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.79	1	\$6.79
66-PM-PMA	PERFORM OIL CHANGE	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
					PARTS	50.03

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 26391

Work Order Notes

(IFALLS) PM SERVICE

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AB PERFORMED PM. COOLANT CHECKED OUT GOOD @ -35F

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(IFALLS) Visit Reason Changed On 5/22/2017 3:15 PM By IFALLS

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 27057

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 8/10/2017 9:21 AM By LISAPATE

(LISAPATE) PM BY CS-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 29090

USING DEPT NO:	218142	OPENED DATE:	03/06/2018 15:27:07	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2018 15:33:52	METER 1 - M:	53198	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2018 15:33:53	IN-SERVICE DATE:	01/20/2015		
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.23	\$0.00	\$17.48
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$68.99	\$68.99
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$46.00	\$11.85	\$0.00	\$57.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$35.26	\$0.00	\$53.09

JOB COUNT: 6	WORK ORDER TOTAL:	2.41	138.58	47.34	68.99	254.91
---------------------	--------------------------	-------------	---------------	--------------	--------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11321046	1018323	0042574	\$68.99
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	240254	0042553	(\$278.39)
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	240254	0042553	\$278.39
				COMML	68.99

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/19/2018 07:00:00	03/19/2018 07:18:36	0.31	\$17.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	03/19/2018 07:00:00	03/19/2018 07:48:00	0.80	\$46.00
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	03/19/2018 07:00:00	03/19/2018 08:00:00	1.00	\$57.50
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11901357	03/19/2018 07:00:00	03/19/2018 07:18:00	0.30	\$17.25
					LABOR	138.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.38	6	\$2.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.40	4	\$9.60
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	194	BULB-TAG/MARKER	0.23	1	\$0.23
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.49	5	\$22.43

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
					PARTS	47.34

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 29090

Work Order Notes

(LISAPATE) PM-INSTALL 4 NEW MICHELIN TEST TIRES AND ALIGN

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LISAPATE) INSTALL 4 TEST TIRES PROVIDED BY MICHELIN. NO CHARGE

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) REPLACED RF MARKER LIGHT

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) TIRE ENGINEERS COMPLETED ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO TE BY EK

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNTED AND BALANCED 4 NEW TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
COOLANT -45'

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 30629

USING DEPT NO: 218142	OPENED DATE: 08/22/2018 13:05:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/23/2018 11:04:24	METER 1 - M: 53371 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2018 11:04:25	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$108.70	\$0.00	\$137.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.70	\$0.00	\$59.53

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **46.58** **150.40** **0.00** **196.98**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/22/2018 14:58:18	08/22/2018 15:16:54	0.31	\$17.83
03-32-002	REPLACE NEW BATTERY	11074414	08/22/2018 14:58:28	08/22/2018 15:28:28	0.50	\$28.75
					LABOR	46.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.35	1	\$0.35
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.35	1	\$0.35
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.77	5	\$28.87
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	108.00	1	\$108.00
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
					PARTS	150.40

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 30629

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) BATTERY FAILED. REPLACED BATTERY

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/SH
COOLANT -34'

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 32451

USING DEPT NO:	218142	OPENED DATE:	03/26/2019 14:09:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2019 10:46:34	METER 1 - M:	60888	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/01/2019 10:46:36	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$49.92	\$49.50	\$0.00	\$99.42

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.69** **49.92** **49.50** **0.00** **99.42**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/27/2019 08:12:18	03/27/2019 08:53:37	0.69	\$49.92
					LABOR	49.92

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.91	1	\$13.91
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
					PARTS	49.50

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 32451

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH,RC/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 33057

USING DEPT NO:	218142	OPENED DATE:	06/03/2019 10:34:36	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2019 07:05:39	METER 1 - M:	65693	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2019 07:05:41	IN-SERVICE DATE:	01/20/2015		
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$25.57	\$0.00	\$43.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$57.34	\$41.97	\$0.00	\$99.31

JOB COUNT: 2 WORK ORDER TOTAL: 1.04 75.47 67.54 0.00 143.01

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	10208562	06/05/2019 07:00:00	06/05/2019 07:15:00	0.25	\$18.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/04/2019 14:20:52	06/04/2019 15:08:19	0.79	\$57.34
					LABOR	75.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.78	1	\$12.78
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
					PARTS	67.54

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 33057

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) EK replaced wipers
WW2600A, ww1801A

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Top: EK, Bot: SH
Coolant -35

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY WORK ORDER NO: 33621

USING DEPT NO:	218142	OPENED DATE:	08/05/2019 08:46:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2019 09:17:23	METER 1 - M:	69990	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/06/2019 09:17:25	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$59.45	\$29.84	\$0.00	\$89.29

JOB COUNT: 1 WORK ORDER TOTAL: 0.82 59.45 29.84 0.00 89.29

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/05/2019 10:49:01	08/05/2019 11:38:13	0.82	\$59.45
					LABOR	59.45

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	4	\$23.34
					PARTS	29.84

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 33621

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW
Coolant -34'

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 34351

USING DEPT NO: 218142	OPENED DATE: 10/07/2019 09:41:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2019 08:21:55	METER 1 - M: 74386 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/08/2019 08:21:56	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$25.92	\$48.09	\$0.00	\$74.01

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.36** **25.92** **48.09** **0.00** **74.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/07/2019 13:00:00	10/07/2019 13:15:37	0.26	\$18.87
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/07/2019 12:59:37	10/07/2019 12:59:37	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/07/2019 13:09:10	10/07/2019 13:15:00	0.10	\$7.05
					LABOR	25.92

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.26	1	\$6.26
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.65	1	\$12.65
					PARTS	48.09

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 34351

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH

Coolant -35'

Replaced air filter

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 35506

USING DEPT NO: 218142	OPENED DATE: 01/28/2020 09:06:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/06/2020 07:16:18	METER 1 - M: 80277 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/06/2020 07:16:24	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FKXFU872821

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-008	REPLACE NEW VALVE ASSEMBLY	DON	O	N	GARAGE	0.10	\$6.93	\$0.29	\$0.00	\$7.22
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$25.58	\$0.00	\$43.71
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$69.00	\$69.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.13	\$81.64	\$35.68	\$0.00	\$117.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.21	\$15.10	\$7.33	\$0.00	\$22.43

JOB COUNT: 5	WORK ORDER TOTAL:	1.68	121.80	68.88	69.00	259.68
---------------------	--------------------------	-------------	---------------	--------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
24-02-061	REPAIR WINDSHIELD	11078716	272191		\$69.00	
					COMML	69.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17-008	REPLACE NEW VALVE ASSEMBLY	11074414	01/29/2020 07:11:43	01/29/2020 07:17:27	0.10	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2020 06:59:33	01/29/2020 07:11:43	0.20	\$14.70
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/29/2020 06:07:20	01/29/2020 07:02:44	0.92	\$66.94
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	01/29/2020 07:17:27	01/29/2020 07:29:57	0.21	\$15.10
03-51-038	REPLACE NEW WIPER BLADES	10208562	01/31/2020 07:00:00	01/31/2020 07:15:00	0.25	\$18.13
					LABOR	121.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
03-17-008	REPLACE NEW VALVE ASSEMBLY	21097	TPMS NICKEL VALVE CORE	0.29	1	\$0.29
					PARTS	68.88

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 35506

Work Order Notes

(LISAPATE) PM-Replace wipers-3 dings in windshield

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(LISAPATE) Installed new LR valve stem core was leaking

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

06-34-001 - INSPECT HEADLAMPS

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr came to the shop and repaired 3 small dings on pass side of the windshield. PD by CC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/AG

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 36563

USING DEPT NO:	218142	OPENED DATE:	05/22/2020 09:00:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/22/2020 13:34:17	METER 1 - M:	84401	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/22/2020 15:48:56	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.12	\$81.30	\$35.60	\$0.00	\$116.90

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.12** **81.30** **35.60** **0.00** **116.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2020 10:49:20	05/22/2020 11:26:56	0.63	\$45.43
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/22/2020 10:51:40	05/22/2020 11:21:21	0.49	\$35.87
					LABOR	81.30

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
					PARTS	35.60

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 36563

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/SH performed pm. Coolant -35
Will need a set of tires next pm service.

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 38191

USING DEPT NO:	218142	OPENED DATE:	10/28/2020 09:40:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/30/2020 09:34:58	METER 1 - M:	86667	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/30/2020 09:52:49	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.10	\$11.80	\$23.97	\$0.00	\$35.77
24-02-010	REPAIR MIRRORS	DON	O	N	GARAGE	0.09	\$10.23	\$59.19	\$0.00	\$69.42
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.30	\$153.53	\$54.87	\$0.00	\$208.40
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.10	\$11.80	\$7.33	\$0.00	\$19.13

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.59** **187.36** **145.36** **0.00** **332.72**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/30/2020 06:00:00	10/30/2020 06:06:00	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/30/2020 06:00:00	10/30/2020 06:06:00	0.10	\$11.80
24-02-010	REPAIR MIRRORS	11074414	10/29/2020 11:44:28	10/29/2020 11:49:40	0.09	\$10.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/28/2020 10:18:44	10/28/2020 11:36:48	1.30	\$153.53
					LABOR	187.36

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-010	REPAIR MIRRORS	8794506060A0	OUTER MIRROR COVER, S WHITE	59.19	1	\$59.19
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.33	1	\$12.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.86	1	\$6.86
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	11.18	1	\$11.18
					PARTS	145.36

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 38191

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

24-02-010 - REPAIR MIRRORS

(SHARBIN) Installed a new mirror cover on driver side mirror. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM. Vacuumed inside of vehicle, filled with gas and washed the vehicle. Drivers outside mirror is missing the cover on the back of the mirror. SH

(SHARBIN) Mileage 86662

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 39307

USING DEPT NO:	218142	OPENED DATE:	03/05/2021 07:50:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2021 14:49:23	METER 1 - M:	87477	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/09/2021 08:44:26	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.72	\$28.64	\$0.00	\$92.36

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.54** **63.72** **28.64** **0.00** **92.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/05/2021 10:25:23	03/05/2021 10:57:47	0.54	\$63.72
					LABOR	63.72

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	28.64

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 39307

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 84777. SH Performed PM and vacuumed.

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 40610

USING DEPT NO: 218142	OPENED DATE: 08/03/2021 07:16:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/10/2021 13:20:39	METER 1 - M: 93694 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/11/2021 08:20:02	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>		
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.00	\$17.28	\$0.00	\$23.28		
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.28	\$32.78	\$0.00	\$0.00	\$32.78		
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.45	\$53.10	\$0.00	\$0.00	\$53.10		
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.34	\$157.69	\$575.76	\$0.00	\$733.45		
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.39	\$52.53	\$0.00	\$121.92		
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00		
JOB COUNT: 6						WORK ORDER TOTAL:		2.70	318.96	645.57	2.00	966.53

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11310047	08/05/2021 10:19:08	08/05/2021 10:46:08	0.45	\$53.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/05/2021 09:30:00	08/05/2021 10:05:10	0.59	\$69.16
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/05/2021 08:29:59	08/05/2021 09:15:00	0.75	\$88.53
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/03/2021 10:04:46	08/03/2021 10:40:03	0.59	\$69.39
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/03/2021 10:01:26	08/03/2021 10:04:29	0.05	\$6.00
06-15	INSPECT STEERING	11310047	08/05/2021 15:06:07	08/05/2021 15:22:47	0.28	\$32.78
					LABOR	318.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.51	6	\$3.06
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.84	1	\$17.84
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.70	1	\$5.70
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	9.95	1	\$9.95

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.33	1	\$7.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	139.88	4	\$559.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	139.88	(4)	(\$559.50)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	139.88	4	\$559.50
					PARTS	645.57

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 40610

Work Order Notes

(LISAPATE) PM-Replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. No issues found. AMG/SH

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 93694 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 41527

USING DEPT NO: 218142	OPENED DATE: 11/05/2021 09:02:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/08/2021 11:44:59	METER 1 - M: 98804 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/08/2021 14:46:09	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-016	REPLACE NEW TIRE PRESSURE MONI	DON	O	N	GARAGE	0.54	\$63.36	\$92.19	\$0.00	\$155.55
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.16	\$17.90	\$0.00	\$22.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$99.12	\$34.39	\$0.00	\$133.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.41** **166.64** **144.48** **2.00** **313.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17-016	REPLACE NEW TIRE PRESSURE MONITOR/SENSOR	12052187	11/05/2021 14:30:00	11/05/2021 14:47:01	0.28	\$33.47
03-17-016	REPLACE NEW TIRE PRESSURE MONITOR/SENSOR	12052187	11/05/2021 13:59:48	11/05/2021 14:15:00	0.25	\$29.89
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/05/2021 13:44:55	11/05/2021 13:47:02	0.04	\$4.16
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/05/2021 12:54:22	11/05/2021 13:44:46	0.84	\$99.12
					LABOR	166.64

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
03-17-016	REPLACE NEW TIRE PRESSURE MONITOR/SENSOR	21360	TPMS DUAL FREQ UNIV STEM	46.10	2	\$92.19
					PARTS	144.48

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 41527

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-17-016 - REPLACE NEW TIRE PRESSURE MONITOR/SENSOR

(JWRIGHT) Replaced both rear tpms sensors and programmed to the car. Test drove and light stayed off

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-98804

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 42712

USING DEPT NO: 218142	OPENED DATE: 03/28/2022 07:24:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/29/2022 10:25:45	METER 1 - M: 104344 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/29/2022 15:20:58	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.80	\$17.90	\$0.00	\$23.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$34.81	\$49.62	\$0.00	\$84.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.06	\$6.52	\$12.23	\$0.00	\$18.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.40** **47.13** **79.75** **2.00** **128.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	03/28/2022 08:49:43	03/28/2022 08:53:02	0.06	\$6.52
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/28/2022 08:46:36	03/28/2022 08:49:33	0.05	\$5.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/28/2022 08:28:42	03/28/2022 08:46:24	0.30	\$34.81
					LABOR 47.13	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	12.23	1	\$12.23
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	14.58	1	\$14.58
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS 79.75	

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 42712

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 43869

USING DEPT NO:	218142	OPENED DATE:	07/07/2022 10:18:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2022 10:39:30	METER 1 - M:	111790	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/11/2022 09:25:37	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.78	\$63.75	\$0.00	\$98.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **34.78** **63.75** **2.00** **100.53**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/07/2022 12:48:25	07/07/2022 13:06:06	0.29	\$34.78
					LABOR	34.78

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.90	1	\$6.90
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	29.21	1	\$29.21
					PARTS	63.75

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 43869

Work Order Notes

(IFALLS) PM Molly A/Dap 348-5093

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 111790 Completed PM top and bottom side, Josh filled with oil. Completed checklist. AMG JW/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 44999

USING DEPT NO:	218142	OPENED DATE:	10/17/2022 09:51:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2022 15:20:26	METER 1 - M:	118128	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2022 07:22:35	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.03	\$18.38	\$0.00	\$22.41
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.10	\$11.83	\$0.00	\$0.00	\$11.83
09-15	ALIGN STEERING	DON	N	N	GARAGE	0.74	\$86.83	\$0.00	\$0.00	\$86.83
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.38	\$45.23	\$409.46	\$0.00	\$454.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.44	\$59.94	\$0.00	\$83.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6 **WORK ORDER TOTAL:** **1.45** **171.36** **487.78** **5.00** **664.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	12296277	10/21/2022 13:03:44	10/21/2022 13:47:53	0.74	\$86.83
09-15	ALIGN STEERING	12296277	10/21/2022 13:03:44	10/21/2022 13:47:53	(0.74)	(\$86.83)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2022 13:54:29	10/20/2022 14:15:00	0.34	\$40.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2022 13:54:29	10/20/2022 14:15:00	(0.34)	(\$40.35)
06-15	INSPECT STEERING	11310047	10/19/2022 09:48:20	10/19/2022 09:54:21	0.10	\$11.83
06-15	INSPECT STEERING	11310047	10/19/2022 09:48:20	10/19/2022 09:54:21	(0.10)	(\$11.83)
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/17/2022 14:47:41	10/17/2022 14:49:44	0.03	\$4.03
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/17/2022 14:39:23	10/17/2022 14:47:29	0.14	\$15.93
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/17/2022 14:11:11	10/17/2022 14:15:00	0.06	\$7.51
06-15	INSPECT STEERING	11310047	10/19/2022 09:48:20	10/19/2022 09:54:21	0.10	\$11.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2022 13:54:29	10/20/2022 14:15:00	0.34	\$40.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2022 14:30:00	10/20/2022 14:32:29	(0.04)	(\$4.88)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2022 14:30:00	10/20/2022 14:32:29	0.04	\$4.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2022 14:30:00	10/20/2022 14:32:29	0.04	\$4.88
09-15	ALIGN STEERING	12296277	10/21/2022 13:03:44	10/21/2022 13:47:53	0.74	\$86.83
					LABOR	171.36

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.80	1	\$7.80
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.58	1	\$10.58
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.45	1	\$5.45
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	197.93	2	\$395.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	2	\$11.79
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	(1)	(\$0.45)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	(1)	(\$0.57)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	(1)	(\$0.80)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	197.93	(2)	(\$395.85)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	(2)	(\$11.79)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	197.93	2	\$395.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	2	\$11.79
					PARTS	487.78

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 44999

Work Order Notes

(LISAPATE) PM-replace wipers-Check LF tire is roaring driver wasn't sure if from tire or maybe hub

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(GARAGE) steering is all good jm

(AJONES) Visit Reason Changed On 10/31/2022 2:10 PM By AJONES

09-15 - ALIGN STEERING

(GARAGE) alignment completed jdm

(AJONES) Visit Reason Changed On 10/31/2022 2:10 PM By AJONES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) SH Mounted and AMG balanced 2 tires. Put the new tires on the front. SH

(AJONES) Visit Reason Changed On 10/31/2022 2:10 PM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 45952

USING DEPT NO: 218142	OPENED DATE: 01/27/2023 08:27:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/30/2023 09:29:16	METER 1 - M: 123359 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/30/2023 10:27:39	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.87	\$23.20	\$0.00	\$29.07
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.76	\$89.52	\$0.00	\$0.00	\$89.52
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.11	\$49.35	\$0.00	\$82.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.09** **128.50** **72.55** **5.00** **206.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/27/2023 13:07:52	01/27/2023 13:46:15	0.64	\$75.49
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/27/2023 11:14:35	01/27/2023 11:21:43	0.12	\$14.03
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/27/2023 10:47:38	01/27/2023 10:50:37	0.05	\$5.87
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2023 10:30:35	01/27/2023 10:47:25	0.28	\$33.11
					LABOR	128.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.41	1	\$10.41
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
					PARTS	72.55

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 45952

Work Order Notes

(EHANNAH) pm- replace wipers- safety inspection.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection and test drove the vehicle. Found no issues at this time. Front and rear pads are at 7mm thickness. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 47150

USING DEPT NO: 218142	OPENED DATE: 05/23/2023 08:44:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/30/2023 08:15:27	METER 1 - M: 128678 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/31/2023 11:34:53	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.59	\$23.96	\$0.00	\$32.55
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.04	\$4.88	\$0.00	\$0.00	\$4.88
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.13	\$133.64	\$0.00	\$0.00	\$133.64
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.93	\$110.13	\$476.85	\$0.00	\$586.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.76	\$48.43	\$0.00	\$104.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.43	\$50.35	\$0.00	\$0.00	\$50.35

JOB COUNT: 7 **WORK ORDER TOTAL:** **3.08** **363.35** **549.24** **5.00** **917.59**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/23/2023 09:59:46	05/23/2023 10:04:08	0.07	\$8.59
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/23/2023 09:31:07	05/23/2023 09:59:28	0.47	\$55.76
WA-00	WASH COMPLETE VEHICLE	12201267	05/23/2023 10:10:11	05/23/2023 10:35:47	0.43	\$50.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/24/2023 13:19:00	05/24/2023 14:15:00	0.93	\$110.13
06-15	INSPECT STEERING	12201267	05/24/2023 14:25:30	05/24/2023 14:25:30	0.00	\$0.00
06-15	INSPECT STEERING	12201267	05/24/2023 14:30:00	05/24/2023 14:32:29	(0.04)	(\$4.88)
06-15	INSPECT STEERING	12201267	05/24/2023 14:25:30	05/24/2023 14:25:30	0.00	\$0.00
06-15	INSPECT STEERING	12201267	05/24/2023 14:30:00	05/24/2023 14:32:29	0.04	\$4.88
06-15	INSPECT STEERING	12201267	05/24/2023 14:25:30	05/24/2023 14:25:30	0.00	\$0.00
06-15	INSPECT STEERING	12201267	05/24/2023 14:30:00	05/24/2023 14:32:29	0.04	\$4.88
66-17-013	PERFORM ALIGNMENT	12052187	05/25/2023 07:22:58	05/25/2023 08:30:55	1.13	\$133.64

Work Order Charge Detail

					LABOR	363.35
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.73	1	\$10.73
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.31	2	\$10.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.52	3	\$1.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.74	1	\$0.74
66-17-028	PERFORM MOUNT AND BALANCE TIRES	69099	TIRE 205/65R16 MICH DEFENDER2	231.96	2	\$463.92
					PARTS	549.24

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 47150

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-CW

06-15 - INSPECT STEERING

(GRCOOK) Inspected steering, found no issues at this time-GC
(AJONES) Visit Reason Changed On 6/1/2023 9:01 AM By AJONES

66-17-013 - PERFORM ALIGNMENT

(JWRIGHT) Performed alignment. EH verified. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and Balanced 2 new front tires-GC
Brake pads are all 6mm on all four wheels.
Miles, 128,678

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-CW,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 128,678

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 48477

USING DEPT NO:	218142	OPENED DATE:	10/10/2023 07:35:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/11/2023 08:00:04	METER 1 - M:	133753	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/11/2023 11:58:56	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.79	\$19.57	\$0.00	\$22.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.37	\$65.82	\$0.00	\$81.19
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.52	\$20.27	\$0.00	\$22.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	1.25	\$147.50	\$0.00	\$0.00	\$147.50

JOB COUNT: 5	WORK ORDER TOTAL:	1.43	168.18	105.66	5.00	278.84
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	10/10/2023 13:00:00	10/10/2023 14:15:00	1.25	\$147.50
WA-00	WASH COMPLETE VEHICLE	11074414	10/10/2023 12:58:59	10/10/2023 12:58:59	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/10/2023 11:37:54	10/10/2023 11:39:11	0.02	\$2.52
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2023 11:27:53	10/10/2023 11:35:42	0.13	\$15.37
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/10/2023 11:36:00	10/10/2023 11:37:25	0.02	\$2.79
					LABOR	168.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	800012C	CABIN AIR FILTER REPL 4483	13.17	1	\$13.17
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	8.30	1	\$8.30
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.76	1	\$17.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	5	\$31.50
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.27	1	\$11.27
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	16.56	1	\$16.56
66-PM-PMA	PERFORM OIL CHANGE	800012C	CABIN AIR FILTER REPL 4483	13.17	(1)	(\$13.17)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	13.17	1	\$13.17
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	13.17	(1)	(\$13.17)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	20.27	1	\$20.27
					PARTS	105.66

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 48477

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed. SH

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 49877

USING DEPT NO:	218142	OPENED DATE:	02/21/2024 07:03:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2024 09:30:35	METER 1 - M:	135907	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2024 13:13:41	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.84	\$26.94	\$0.00	\$55.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.23	\$27.40	\$0.00	\$0.00	\$27.40

JOB COUNT: 3	WORK ORDER TOTAL:	0.48	56.24	26.94	5.00	88.18
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/21/2024 10:00:54	02/21/2024 10:15:34	0.24	\$28.84
WA-00	WASH COMPLETE VEHICLE	12395904	02/21/2024 10:15:58	02/21/2024 10:29:54	0.23	\$27.40
LABOR					56.24	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	26.94	1	\$26.94
PARTS					26.94	

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 49877

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

UNIT NO: 241049 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 50101

USING DEPT NO: 218142	OPENED DATE: 03/07/2024 10:52:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/20/2024 10:54:28	METER 1 - M: 135907 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/20/2024 11:48:58	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FKXFU872821	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$118.00	\$0.27	\$0.00	\$118.27

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.27** **5.00** **123.27**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11074414	03/07/2024 14:28:53	03/07/2024 14:28:53	0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11074414	03/07/2024 14:30:00	03/07/2024 15:30:00	1.00	\$118.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11074414	03/07/2024 14:30:00	03/07/2024 14:44:38	0.24	\$28.78
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11074414	03/07/2024 14:30:00	03/07/2024 14:44:38	(0.24)	(\$28.78)
					LABOR	118.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	2	\$0.27
					PARTS	0.27

Work Order Charge Detail

UNIT NO: 241049 2015 TOYOTA CAMRY

WORK ORDER NO: 50101

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(SHARBIN) SH FC Performed a prep for sale. SH

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Mar 22 2024 10:13:01 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '241049') //Q=