

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 26379

USING DEPT NO: 509101	OPENED DATE: 05/18/2017 13:33:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/23/2017 07:21:00	METER 1 - M: 123 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 05/23/2017 07:21:01	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11170580	05/18/2017 13:34:21	05/18/2017 14:04:21	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 26379

Work Order Notes

(IFALLS) NEW TRUCK PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(IFALLS) AB PERFORMED PDI

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 26830

USING DEPT NO: 509101	OPENED DATE: 07/13/2017 08:39:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/11/2017 11:02:04	METER 1 - M: 349 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/11/2017 11:02:05	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1EF1HFC06492

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	8.00	\$460.00	\$461.02	\$0.00	\$921.02
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$335.00	\$0.00	\$363.75

JOB COUNT: 2 **WORK ORDER TOTAL:** **8.50** **488.75** **796.02** **0.00** **1,284.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-044	INSTALL TOOLBOX ASSY	11213180	08/07/2017 15:00:00	08/07/2017 15:30:00	0.50	\$28.75
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	08/08/2017 07:00:00	08/08/2017 15:00:00	8.00	\$460.00
					LABOR	488.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	3.00	1	\$3.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	10.00	1	\$10.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609C	WHITE STROBE LIGHT KIT	81.00	2	\$162.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	0.24	25	\$6.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	8.53	1	\$8.53
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	USASD11B100	11" ZIP TIE 100 PCS	7.19	1	\$7.19
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1755KT	SHRINK TUBE	2.33	1	\$2.33
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC7095A	TIE MOUNT	19.24	1	\$19.24
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	MMM06133	ELECTRICAL TAPE	4.38	1	\$4.38
14-78-044	INSTALL TOOLBOX ASSY	APSTB70LPB	70" LO PROFILE BLACK TOOLBOX	335.00	1	\$335.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	USARSD11B50	11" BLACK ZIP TIES	6.35	1	\$6.35
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81163S	16 BLK PRIMARY WIRE	16.00	1	\$16.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONC	ION WIDE ANGLE STROBE CLEAR	108.00	2	\$216.00
					PARTS	796.02

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 26830

Work Order Notes

(LISAPATE) INSTALL STROBES AND A TOOLBOX

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) INSTALLED FRONT AND REAR STROBES

14-78-044 - INSTALL TOOLBOX ASSY

(LISAPATE) INSTALLED LOW PROFILE TOOLBOX

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4 WORK ORDER NO: 27695

USING DEPT NO:	509101	OPENED DATE:	10/05/2017 10:23:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2017 13:50:41	METER 1 - M:	1225	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2017 13:50:42	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$33.67	\$19.44	\$0.00	\$53.11

JOB COUNT: 1 WORK ORDER TOTAL: 0.59 33.67 19.44 0.00 53.11

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/05/2017 16:38:08	10/05/2017 17:13:16	0.59	\$33.67
					LABOR	33.67

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.04	1	\$5.04
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	240	\$14.40
					PARTS	19.44

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 27695

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 29339

USING DEPT NO:	509101	OPENED DATE:	04/06/2018 08:24:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2018 15:13:41	METER 1 - M:	2123	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2018 15:13:43	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$21.03	\$0.00	\$38.86

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 21.03 0.00 38.86

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/06/2018 14:22:00	04/06/2018 14:40:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.00	8	\$16.00
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	21.03

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 29339

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
COOLANT -30'

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 30650

USING DEPT NO: 509101	OPENED DATE: 08/24/2018 09:18:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/28/2018 10:41:28	METER 1 - M: 3231 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/28/2018 10:41:29	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1EF1HFC06492

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$35.40	\$0.00	\$35.40

JOB COUNT: 1 **WORK ORDER TOTAL:** 0.31 0.00 35.40 0.00 35.40

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/24/2018 14:26:51	08/24/2018 14:45:27	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.27	8	\$26.16
					PARTS	35.40

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 30650

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/SH
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 31580

USING DEPT NO: 509101	OPENED DATE: 11/29/2018 09:00:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/07/2018 11:58:45	METER 1 - M: 3937 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/07/2018 11:58:47	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-00	TRANSPORT COMPLETE VEHICLE	DON	R	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
17-02-047	RECALL SEAT BELTS	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-02-047	RECALL SEAT BELTS	11078175	W34871	0046109	\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-00	TRANSPORT COMPLETE VEHICLE	11915538	11/30/2018 07:23:29	11/30/2018 08:23:29	1.00	\$0.00
16-00	TRANSPORT COMPLETE VEHICLE	11915538	11/30/2018 07:23:29	11/30/2018 07:23:32	0.00	\$0.00
16-00	TRANSPORT COMPLETE VEHICLE	11915538	11/30/2018 07:23:29	11/30/2018 07:23:32	0.00	\$0.00
LABOR					0.00	

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 31580

Work Order Notes

(LISAPATE) Take to Ford for Recall 18S27 seat belt

Job Notes

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) Taken to Ford by EK/RC

17-02-047 - RECALL SEAT BELTS

(LISAPATE) Recall was completed by Tuscaloosa Ford Carpet shielding and insulation rework performed

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 31987

USING DEPT NO:	509101	OPENED DATE:	01/22/2019 09:05:02	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	01/23/2019 08:49:38	METER 1 - M:	4165	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/23/2019 08:49:40	IN-SERVICE DATE:	05/18/2017		
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.53	\$0.00	\$29.03	\$0.00	\$29.03

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.53** **0.00** **29.03** **0.00** **29.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/22/2019 11:28:38	01/22/2019 13:00:20	1.53	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	8	\$24.00
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	29.03

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 31987

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG
Coolant -35'

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 33417

USING DEPT NO:	509101	OPENED DATE:	07/12/2019 08:49:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/15/2019 15:27:16	METER 1 - M:	5070	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2019 15:27:18	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$28.63	\$0.00	\$28.63

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 0.00 28.63 0.00 28.63

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/15/2019 06:00:00	07/15/2019 06:18:36	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	8	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	28.63

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 33417

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4 WORK ORDER NO: 36049

USING DEPT NO:	509101	OPENED DATE:	03/24/2020 10:01:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2020 08:56:30	METER 1 - M:	6422	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	03/25/2020 16:11:32	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-55-023	INSTALL RECEIVER AND/OR HITCH	DON	O	N	GARAGE	0.07	\$0.00	\$77.38	\$0.00	\$77.38

JOB COUNT: 1 WORK ORDER TOTAL: 0.07 0.00 77.38 0.00 77.38

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-55-023	INSTALL RECEIVER AND/OR HITCH	11074414	03/25/2020 08:28:29	03/25/2020 08:32:29	0.07	\$0.00

LABOR 0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-55-023	INSTALL RECEIVER AND/OR HITCH	BOL7023585	5/8 LOCK REC NEW FORD	37.97	1	\$37.97
14-55-023	INSTALL RECEIVER AND/OR HITCH	CRT45405	RECEIVER REDUCER 2.5 TO 2 IN	11.43	1	\$11.43
14-55-023	INSTALL RECEIVER AND/OR HITCH	CRT45836	2IN DROP LOAD BALL	27.98	1	\$27.98

PARTS 77.38

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 36049

Work Order Notes

(LISAPATE) Joe requested new receiver and ball, lock/pin

Job Notes

14-55-023 - INSTALL RECEIVER AND/OR HITCH

(LISAPATE) Installed trailer hitch with ball and lock

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 36418

USING DEPT NO: 509101	OPENED DATE: 05/13/2020 14:48:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/14/2020 11:50:18	METER 1 - M: 7281 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/14/2020 11:50:23	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1EF1HFC06492

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.92	\$0.00	\$28.63	\$0.00	\$28.63
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.56	\$0.00	\$14.38	\$0.00	\$14.38

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.48** **0.00** **43.01** **0.00** **43.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/14/2020 09:19:26	05/14/2020 09:59:46	0.67	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	05/14/2020 09:59:46	05/14/2020 10:33:39	0.56	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/14/2020 09:14:20	05/14/2020 09:29:03	0.25	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	14.38	1	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	8	\$23.60
					PARTS	43.01

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 36418

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/JW performed PM. Coolant -35

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) AG replaced cabin filter.

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 37906

USING DEPT NO: 509101	OPENED DATE: 10/07/2020 08:04:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/07/2020 10:56:49	METER 1 - M: 8276 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/07/2020 12:51:56	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.19	\$27.30	\$0.00	\$51.49

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.21** **24.19** **27.30** **0.00** **51.49**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/07/2020 10:08:11	10/07/2020 10:20:29	0.21	\$24.19
					LABOR	24.19

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	27.30	1	\$27.30
					PARTS	27.30

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 37906

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Checked all fluids and tires. Updated pm sticker. Coolant -34° JAW,AB

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 39423

USING DEPT NO:	509101	OPENED DATE:	03/16/2021 15:43:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/19/2021 13:46:12	METER 1 - M:	8627	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/22/2021 15:25:09	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.12	\$39.98	\$0.00	\$88.10

JOB COUNT: 1 WORK ORDER TOTAL: 0.41 48.12 39.98 0.00 88.10

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/18/2021 09:50:18	03/18/2021 10:14:46	0.41	\$48.12
					LABOR	48.12

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
					PARTS	39.98

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 39423

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 8627. SH/JW performed PM. SH Vacuumed.

(SHARBIN) SH filled with gas wash bay was down.

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4 WORK ORDER NO: 39846

USING DEPT NO:	509101	OPENED DATE:	04/30/2021 11:27:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2021 15:37:16	METER 1 - M:	8719	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/04/2021 14:18:57	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.24	\$28.48	\$146.72	\$0.00	\$175.20

JOB COUNT: 1 WORK ORDER TOTAL: 0.24 28.48 146.72 0.00 175.20

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11074414	04/30/2021 11:34:31	04/30/2021 11:49:00	0.24	\$28.48
					LABOR	28.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	146.72	1	\$146.72
					PARTS	146.72

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 39846

Work Order Notes

(LISAPATE) Battery keeps going dead. Jumped off a few times

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Mileage 8719. Original battery tested bad. Installed a new battery ALT charging @13.7 SH

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 40789

USING DEPT NO: 509101	OPENED DATE: 08/20/2021 07:20:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/20/2021 15:15:08	METER 1 - M: 9535 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2021 07:23:27	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.24	\$15.18	\$0.00	\$20.42
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.48	\$56.48	\$0.00	\$0.00	\$56.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.51	\$0.00	\$0.00	\$46.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.92** **108.23** **15.18** **2.00** **125.41**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/20/2021 10:29:33	08/20/2021 10:58:16	0.48	\$56.48
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/20/2021 10:25:03	08/20/2021 10:27:43	0.04	\$5.24
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/20/2021 10:01:13	08/20/2021 10:24:52	0.39	\$46.51
					LABOR	108.23

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
					PARTS	15.18

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 40789

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 9535. Vehicle has been driven 908 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 42096

USING DEPT NO: 509101	OPENED DATE: 01/18/2022 11:15:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/19/2022 11:33:18	METER 1 - M: 9893 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/20/2022 08:08:02	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1EF1HFC06492

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.92	\$15.18	\$0.00	\$16.10
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.53	\$63.03	\$0.00	\$0.00	\$63.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.47	\$40.62	\$0.00	\$64.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.74	87.42	55.80	2.00	145.22
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/19/2022 08:23:11	01/19/2022 08:55:14	0.53	\$63.03
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/19/2022 07:56:05	01/19/2022 07:56:33	0.01	\$0.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/19/2022 07:43:58	01/19/2022 07:55:54	0.20	\$23.47
					LABOR	87.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.22	1	\$5.22
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
					PARTS	55.80

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 42096

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) RC Replaced wipers. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) RC SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 43232

USING DEPT NO: 509101	OPENED DATE: 05/13/2022 15:52:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2022 10:09:12	METER 1 - M: 10098 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/17/2022 15:19:27	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.10	\$15.18	\$0.00	\$21.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.85	\$0.00	\$0.00	\$24.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.26	30.95	15.18	2.00	48.13
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/16/2022 08:12:24	05/16/2022 08:15:30	0.05	\$6.10
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2022 07:59:32	05/16/2022 08:12:10	0.21	\$24.85
LABOR					30.95	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
PARTS					15.18	

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 43232

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 205 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 43459

USING DEPT NO:	509101	OPENED DATE:	06/01/2022 09:39:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2022 11:45:27	METER 1 - M:	10146	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/29/2022 08:23:02	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.13	\$15.14	\$0.00	\$0.00	\$15.14
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,300.00	\$2,300.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.13	15.14	0.00	2,302.00	2,317.14
---------------------	--------------------------	-------------	--------------	-------------	-----------------	-----------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	5569647	5823		\$2,300.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2302.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11915538	06/07/2022 11:48:53	06/07/2022 11:56:35	0.13	\$15.14
LABOR					15.14	

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 43459

Work Order Notes

(LISAPATE) Take to Browns to repair rear end damage. They have received a check from State Auto.

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Browns by RC

24-71 - REPAIR BODY

(LISAPATE) Repairs completed by Browns to rear bumper and tailgate area per the estimate from State Auto. UA paid \$2000.00 ded State Auto paid \$3463.46 to Browns. Invoice and estimates attached

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 44880

USING DEPT NO:	509101	OPENED DATE:	10/05/2022 13:18:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2022 14:23:09	METER 1 - M:	10878	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2022 08:52:58	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.10	\$11.80	\$41.52	\$0.00	\$53.32
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	0.90	\$106.20	\$9.71	\$0.00	\$115.91
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.00	\$20.88	\$0.00	\$26.88
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	2.00	\$236.00	\$0.00	\$0.00	\$236.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$18.06	\$57.78	\$0.00	\$75.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.66	\$196.11	\$0.00	\$0.00	\$196.11

JOB COUNT: 7 WORK ORDER TOTAL: 4.87 574.17 129.89 5.00 709.06

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-42	DIAGNOSE COOLING SYSTEM	11213180	10/19/2022 07:00:00	10/19/2022 09:00:00	2.00	\$236.00
03-33-004	REPLACE NEW SPARK PLUGS	11213180	10/19/2022 07:00:00	10/19/2022 07:54:00	0.90	\$106.20
03-33-003	REPLACE NEW COIL	11213180	10/19/2022 07:54:00	10/19/2022 08:00:00	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/14/2022 11:44:57	10/14/2022 11:48:00	0.05	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/14/2022 11:35:28	10/14/2022 11:44:39	0.15	\$18.06
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	10/05/2022 14:33:11	10/05/2022 16:12:54	1.66	\$196.11
					LABOR	574.17

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-33-003	REPLACE NEW COIL	STIUF824	COIL	41.52	1	\$41.52
03-33-003	REPLACE NEW COIL	STIUF824	COIL	41.52	(1)	(\$41.52)
03-33-003	REPLACE NEW COIL	STIUF824	COIL	41.52	1	\$41.52
03-33-004	REPLACE NEW SPARK PLUGS	SP548	SPARK PLUGS	9.71	1	\$9.71

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.44	2	\$20.88
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	8	\$49.92
					PARTS	129.89

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 44880

Work Order Notes

(LISAPATE) PM-replace wipers-check engine light on and truck is shaking

Job Notes

03-33-003 - REPLACE NEW COIL

(MSIDES) Replaced failed ignition coil. MS

03-33-004 - REPLACE NEW SPARK PLUGS

(MSIDES) Replaced spark plug. MS

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

35-42 - DIAGNOSE COOLING SYSTEM

(MSIDES) Found coolant to have accumulated in the number 8 spark plug hole. Pressured system and inspected for leaks vehicle showed no sign of leaks present and held pressure. Coolant found in hole was possibly due to previous repair. MS 2.0 HRS

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(MSIDES) Scanned vehicle out with ford IDS scan tool and found vehicle to be misfiring on cylinder 8. MS
(IFALLS) found water in spark plug hole.

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 46161

USING DEPT NO: 509101	OPENED DATE: 02/15/2023 08:58:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/24/2023 10:48:38	METER 1 - M: 12332 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/24/2023 13:12:22	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.01	\$0.00	\$0.00	\$29.01
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.71	\$83.85	\$0.00	\$0.00	\$83.85
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.44	\$169.76	\$928.36	\$0.00	\$1,098.12
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.37	\$0.00	\$0.00	\$29.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.64	311.99	928.36	5.00	1,245.35
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	02/23/2023 08:32:22	02/23/2023 09:15:00	0.71	\$83.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/22/2023 09:48:49	02/22/2023 11:15:08	1.44	\$169.76
06-15	INSPECT STEERING	11074414	02/15/2023 14:34:35	02/15/2023 14:49:20	0.25	\$29.01
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/15/2023 14:00:04	02/15/2023 14:15:00	0.25	\$29.37
					LABOR	311.99

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.16	4	\$8.64
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450478	TIRE 265/70R17 GEN GRB HTS60	229.02	4	\$916.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450478	TIRE 265/70R17 GEN GRB HTS60	230.52	(4)	(\$922.08)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450478	TIRE 265/70R17 GEN GRB HTS60	230.52	4	\$922.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	2	\$1.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45

Work Order Charge Detail

The University of Alabama

Report Printed: 04/09/2024 11:15:39 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	2	\$0.51
PARTS						928.36

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 46161

Work Order Notes

(EHANNAH) preplace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(SHARBIN) Inspected the steering found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Set front toe. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balance 4 tires and relearned the tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 444 miles since the last PM. Checked fluids battery and updated the oil change sticker. Vehicle needs 4 tires due to the DOT date. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 47397

USING DEPT NO: 509101	OPENED DATE: 06/21/2023 09:34:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/07/2023 08:27:36	METER 1 - M: 12022 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/07/2023 10:28:24	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-40-448	WARRANTY CYLINDER HEAD	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$2,356.36	\$2,356.36
16-40	TRANSPORT ENGINE / MOTOR SYSTEM	DON	N	N	GARAGE	4.00	\$472.00	\$0.00	\$0.00	\$472.00
25-40-405	REMOVE VALVE COVERS/GASKETS	DON	O	N	GARAGE	0.10	\$12.19	\$0.00	\$0.00	\$12.19
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.71	\$83.45	\$0.11	\$0.00	\$83.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.41	\$166.64	\$0.00	\$0.00	\$166.64

JOB COUNT: 6 **WORK ORDER TOTAL:** **6.22** **734.28** **0.11** **2,361.36** **3,095.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-40-448	WARRANTY CYLINDER HEAD	11099772	10012616		\$2,356.36
15-40-448	WARRANTY CYLINDER HEAD	11099772	10012616		(\$2,291.06)
15-40-448	WARRANTY CYLINDER HEAD	11099772	10012616		\$2,291.06
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					2361.36

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-42	DIAGNOSE COOLING SYSTEM	11310047	07/14/2023 13:04:11	07/14/2023 13:46:37	0.71	\$83.45
25-40-405	REMOVE VALVE COVERS/GASKETS	11310047	07/14/2023 13:46:37	07/14/2023 13:52:49	0.10	\$12.19
16-40	TRANSPORT ENGINE / MOTOR SYSTEMS	11399745	08/07/2023 07:00:00	08/07/2023 11:00:00	4.00	\$472.00
35-42	DIAGNOSE COOLING SYSTEM	11310047	07/14/2023 11:52:55	07/14/2023 11:52:55	0.00	\$0.00
25-40-405	REMOVE VALVE COVERS/GASKETS	11310047	07/14/2023 11:48:01	07/14/2023 11:48:01	0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	06/27/2023 07:00:59	06/27/2023 07:29:58	0.48	\$57.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	06/21/2023 14:54:42	06/21/2023 15:50:27	0.93	\$109.64
LABOR					734.28	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
35-42	DIAGNOSE COOLING SYSTEM	WILW747	RAZOR BLADES	0.11	1	\$0.11

Work Order Charge Detail

PARTS

0.11

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 47397

Work Order Notes

(EHANNAH) scan out- check engine light came on and started jumping when he pressed the gas.

Job Notes

15-40-448 - WARRANTY CYLINDER HEAD

(LISAPATE) Long Lewis did cooling system pressure test, found coolant weeping into #8 spark plug well. Replaced LH cylinder head to correct. Goodwill warranty by Long Lewis covered most of repair UA paid \$ 1992.23 for DED.

16-40 - TRANSPORT ENGINE / MOTOR SYSTEMS

(LISAPATE) transported to Long Lewis in Muscle Shoals by RC/CW

25-40-405 - REMOVE VALVE COVERS/GASKETS

(EHOWELL) Removed the left (driver's side) valve cover while searching for a coolant leak. Did not see any signs of leakage beneath valve cover. EH

35-42 - DIAGNOSE COOLING SYSTEM

(EHOWELL) Removed ignition coil and found coolant collected inside the #8 spark plug hole. Did not see any signs of coolant leaking anywhere and the cooling system held pressure well. Removed spark plug and observed piston, but the piston did not appear to be steam cleaned. The leak must be due to a faulty cylinder head. Also, did not see any signs of coolant dripping down from above #8 spark plug hole. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0308 Cylinder 8 Misfire Detected. EH

Work Order Charge Detail

UNIT NO: 242307 **2017 FORD F150 4X4** **WORK ORDER NO:** 48048

USING DEPT NO: 509101	OPENED DATE: 08/30/2023 11:20:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2023 13:48:52	METER 1 - M: 12757 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/11/2023 14:54:28	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1EF1HFC06492	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.93	\$0.00	\$0.00	\$11.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.49	\$57.30	\$0.00	\$0.00	\$57.30

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.59** **69.23** **0.00** **5.00** **74.23**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	08/31/2023 07:15:25	08/31/2023 07:44:33	0.49	\$57.30
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/31/2023 07:09:04	08/31/2023 07:15:08	0.10	\$11.93
LABOR					69.23	

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 48048

Work Order Notes

(LRUSHING) pm-wipers-wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, vehicle driven 426 miles, filters good, tires and tire pressure, updated oil change sticker.
Miles, 12,757

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 49453

USING DEPT NO:	509101	OPENED DATE:	01/11/2024 13:51:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/17/2024 09:51:00	METER 1 - M:	13644	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/17/2024 14:28:28	IN-SERVICE DATE:	05/18/2017	
TECH SPEC NO:	17FORDF1504X4	2017 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1EF1HFC06492	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.04	\$5.02	\$0.99	\$0.00	\$6.01
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.36	\$16.65	\$0.00	\$21.01
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.10	\$63.56	\$0.00	\$110.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.43	\$50.38	\$0.00	\$0.00	\$50.38

JOB COUNT: 5	WORK ORDER TOTAL:	0.91	106.86	81.20	5.00	193.06
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	01/12/2024 08:43:16	01/12/2024 08:45:49	0.04	\$5.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/12/2024 08:46:02	01/12/2024 09:09:59	0.40	\$47.10
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/12/2024 09:10:15	01/12/2024 09:12:28	0.04	\$4.36
WA-00	WASH COMPLETE VEHICLE	11074414	01/12/2024 09:42:26	01/12/2024 10:08:03	0.43	\$50.38
				LABOR		106.86

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	8	\$50.04
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.99	1	\$0.99
					PARTS	81.20

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 49453

Work Order Notes

(EHANNAH) pm- wipers- wash- blinker pass.

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(SHARBIN) Replaced the right rear turn/brake light bulb. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

06-34-019 - INSPECT TURN SIGNAL SWITCH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 50322

USING DEPT NO: 509101	OPENED DATE: 03/27/2024 10:55:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/08/2024 14:02:42	METER 1 - M: 14179 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/09/2024 07:13:50	IN-SERVICE DATE: 05/18/2017
TECH SPEC NO: 17FORDF1504X4 2017 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1EF1HFC06492

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.36	\$42.71	\$0.00	\$0.00	\$42.71

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.36** **42.71** **0.00** **5.00** **47.71**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/08/2024 09:29:23	04/08/2024 09:29:23	0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/08/2024 09:30:00	04/08/2024 09:51:43	0.36	\$42.71
LABOR					42.71	

Work Order Charge Detail

UNIT NO: 242307 2017 FORD F150 4X4

WORK ORDER NO: 50322

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) Prepare unit for disposal fc

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Apr 09 2024 11:15:39 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FTEW1EF1HFC06492') //Q=