

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 11023

USING DEPT NO: 219101	OPENED DATE: 05/15/2012 09:22:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2012 07:46:28	METER 1 - M: 27535 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/17/2012 07:46:31	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.25	\$71.88	\$44.33	\$0.00	\$116.21

JOB COUNT: 1	WORK ORDER TOTAL:					1.25	71.88	44.33	0.00	116.21
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2012 13:00:00	05/16/2012 14:15:00	1.25	\$71.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2012 09:30:00	05/16/2012 12:00:00	2.50	\$143.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2012 09:30:00	05/16/2012 12:00:00	(2.50)	(\$143.75)
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2012 14:30:00	05/16/2012 09:15:00	18.75	\$1,078.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2012 13:00:00	05/15/2012 14:15:00	1.25	\$71.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2012 13:00:00	05/15/2012 14:15:00	(1.25)	(\$71.88)
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2012 14:30:00	05/16/2012 09:15:00	(18.75)	(\$1,078.13)
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2012 09:48:48	05/15/2012 12:00:00	2.19	\$125.74
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/15/2012 09:48:48	05/15/2012 12:00:00	(2.19)	(\$125.74)
					LABOR	71.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
					PARTS	44.33

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 11023

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY SH/GM

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 11105

USING DEPT NO: 219101	OPENED DATE: 05/29/2012 13:17:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/31/2012 06:42:18	METER 1 - M: 27646 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/31/2012 06:42:20	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-31-001	REPLACE NEW ALTERNATOR	DON	O	N	GARAGE	1.00	\$57.50	\$204.85	\$0.00	\$262.35
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 3	WORK ORDER TOTAL:	2.50	143.75	204.85	0.00	348.60
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11074414	05/30/2012 18:00:00	05/30/2012 18:30:00	0.50	\$28.75
66-79-002	PERFORM SERVICE CALL	11074414	05/30/2012 18:30:00	05/30/2012 19:30:00	1.00	\$57.50
03-31-001	REPLACE NEW ALTERNATOR	11074414	05/30/2012 17:00:00	05/30/2012 18:00:00	1.00	\$57.50
					LABOR	143.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-31-001	REPLACE NEW ALTERNATOR	REM23659	ALTERNATOR	204.85	1	\$204.85
					PARTS	204.85

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 11105

Work Order Notes

(LPATE) KEVIN REQUESTED SERVICE CALL TO ROSE FOR A DEAD BATTERY.

Job Notes

03-31-001 - REPLACE NEW ALTERNATOR

(LPATE) SH R&R ALTERNATOR.

66-79-002 - PERFORM SERVICE CALL

(LPATE) COMPLETED SERVICE CALL TO ROSE INSTALLED NEW BATTERY AND BROUGHT VAN TO GARAGE NEEDS AN ALTERNATOR.

CH-32-002 - CHARGE BATTERY

(LPATE) CHARGED BATTERY RECHECKED OK.

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 12900

USING DEPT NO: 219101	OPENED DATE: 01/28/2013 15:44:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/29/2013 14:53:28	METER 1 - M: 28993 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/29/2013 14:53:30	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$39.27	\$0.00	\$53.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$56.78	\$0.00	\$74.61

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **96.05** **0.00** **128.26**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11338644	01/29/2013 07:18:36	01/29/2013 07:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11338644	01/29/2013 07:00:00	01/29/2013 07:18:36	0.31	\$17.83
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.19	1	\$5.19
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.64	2	\$39.27
					PARTS	96.05

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 12900

Work Order Notes

(GMANNING) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GMANNING)

The following parts are included with the standard job:

Part No : 60-1840
Qty : 2
Description : WIPER BLADE
Manufacturer :

(GMANNING) RS REPLACED BOTH WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

(GMANNING) PM BY RS

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 14299

USING DEPT NO: 219101	OPENED DATE: 07/09/2013 14:18:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/10/2013 09:21:20	METER 1 - M: 30001 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/10/2013 09:21:21	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.65	\$57.33	\$0.00	\$92.98

JOB COUNT: 1	WORK ORDER TOTAL:					0.62	35.65	57.33	0.00	92.98
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11413680	07/09/2013 14:31:04	07/09/2013 14:49:40	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/09/2013 14:30:49	07/09/2013 14:49:25	0.31	\$17.83
					LABOR	35.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.53	1	\$5.53
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
					PARTS	57.33

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 14299

Work Order Notes

(GMANNING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.7675

(GMANNING) PM BY SH/RT

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 15645

USING DEPT NO:	219101	OPENED DATE:	12/11/2013 15:40:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/12/2013 13:09:41	METER 1 - M:	31478	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/12/2013 13:09:42	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$188.78	\$188.78
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.65	\$50.27	\$0.00	\$85.92

JOB COUNT: 3	WORK ORDER TOTAL:	1.12	64.40	50.27	188.78	303.45
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11245625	273426	0022099	\$188.78
COMML					188.78

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11397026	12/12/2013 07:00:00	12/12/2013 07:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11338644	12/12/2013 07:00:00	12/12/2013 07:18:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11397026	12/12/2013 07:00:00	12/12/2013 07:18:36	0.31	\$17.83
LABOR					64.41	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	11.10	1	\$11.10
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	6	\$34.02
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
PARTS					50.27	

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 15645

Work Order Notes

(GMANNING) PM

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(GMANNING) ROZARS REPLACED THE WINDSHIELD. PD BY CC.

16-02 - TRANSPORT CAB & SHEET METAL

(GMANNING) BG TOOK UNIT TO ROZARS

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

(GMANNING) PM BY BG/RS

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 17099

USING DEPT NO:	219101	OPENED DATE:	05/28/2014 07:16:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/29/2014 06:41:53	METER 1 - M:	32800	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/29/2014 06:41:55	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.03	\$1.69	\$33.72	\$0.00	\$35.41
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.34	\$19.53	\$0.00	\$0.00	\$19.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$32.34	\$45.47	\$0.00	\$77.81

JOB COUNT: 3	WORK ORDER TOTAL:	0.93	53.56	79.19	0.00	132.75
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/28/2014 09:15:00	05/28/2014 09:35:23	0.34	\$19.53
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/28/2014 09:06:07	05/28/2014 09:06:07	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/28/2014 08:58:14	05/28/2014 09:00:00	0.03	\$1.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/28/2014 08:24:08	05/28/2014 08:57:53	0.56	\$32.34
					LABOR	53.56

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	2	\$33.72
					PARTS	79.19

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 17099

Work Order Notes

(LPATE) PM-REPLACE WIPERS-ROTATE TIRES

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :

(LPATE) REPLACED WIPERS

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

(LPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 18777

USING DEPT NO: 219101	OPENED DATE: 11/14/2014 15:39:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/17/2014 13:22:00	METER 1 - M: 34345 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/17/2014 13:22:01	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250	2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.17	\$9.87	\$36.42	\$0.00	\$46.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$15.01	\$45.47	\$0.00	\$60.48

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.43** **24.88** **81.89** **0.00** **106.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/15/2014 14:56:52	11/15/2014 15:07:10	0.17	\$9.87
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/15/2014 14:41:07	11/15/2014 14:56:47	0.26	\$15.01
					LABOR	24.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	18.21	2	\$36.42
					PARTS	81.89

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 18777

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.78

(LPATE) PM BY SH/IF

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 21408

USING DEPT NO: 219101	OPENED DATE: 09/11/2015 16:01:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/14/2015 11:10:41	METER 1 - M: 37620 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/14/2015 11:10:43	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-02-003	ADJUST RUNNING BOARDS	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$30.30	\$0.00	\$48.13

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **46.58** **30.30** **0.00** **76.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	09/14/2015 06:00:00	09/14/2015 06:18:36	0.31	\$17.83
01-02-003	ADJUST RUNNING BOARDS	10260422	09/14/2015 06:18:36	09/14/2015 06:48:36	0.50	\$28.75
					LABOR	46.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.51	7	\$31.58
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.78	1	\$4.78
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	4.51	(7)	(\$31.58)
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.78	(1)	(\$4.78)
					PARTS	30.30

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 21408

Work Order Notes

(LPATE) PM-ADJUST RUNNING BOARDS ARE LOOSE

Job Notes

01-02-003 - ADJUST RUNNING BOARDS

(LPATE) FOUND A BOLT MISSING ON RUNNING BOARD. REPLACED BOLT IT SECURED RUNNING BOARD. RECHECKED OK

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 7 Cost 3.780000

(LPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 23938

USING DEPT NO:	219101	OPENED DATE:	07/19/2016 13:53:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/27/2016 13:33:34	METER 1 - M:	40260	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/27/2016 13:33:35	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-16-003	REPLACE NEW FRONT SHOCK ABSORBER	DON	O	N	GARAGE	0.80	\$46.00	\$203.48	\$0.00	\$249.48
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	DON	O	N	GARAGE	0.80	\$46.00	\$234.94	\$0.00	\$280.94
03-32-002	REPLACE NEW BATTERY	DON	P	N	GARAGE	0.50	\$28.75	\$95.16	\$0.00	\$123.91
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$3.71	\$17.06	\$0.00	\$20.77
06-16	INSPECT SUSPENSION	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	DON	O	N	GARAGE	0.50	\$28.75	\$1.74	\$0.00	\$30.49
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	1.00	\$57.50	\$2.85	\$0.00	\$60.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.76	\$43.64	\$33.32	\$0.00	\$76.96

JOB COUNT: 8 **WORK ORDER TOTAL:** **4.92** **283.10** **588.55** **0.00** **871.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11074414	07/20/2016 15:20:00	07/21/2016 06:15:05	14.92	\$857.79
03-32-002	REPLACE NEW BATTERY	11074414	07/20/2016 15:20:00	07/21/2016 06:15:05	(14.92)	(\$857.79)
03-32-002	REPLACE NEW BATTERY	11074414	07/20/2016 15:20:00	07/20/2016 15:50:00	0.50	\$28.75
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2016 06:58:19	07/21/2016 07:02:11	0.06	\$3.71
66-01-058	PERFORM EVAC AND RECHARGE FREON	11397026	07/26/2016 09:36:00	07/26/2016 10:36:00	1.00	\$57.50
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11397026	07/26/2016 07:00:00	07/26/2016 07:30:00	0.50	\$28.75
06-16	INSPECT SUSPENSION	11397026	07/26/2016 07:30:00	07/26/2016 08:00:00	0.50	\$28.75
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	11397026	07/26/2016 08:48:00	07/26/2016 09:36:00	0.80	\$46.00
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	11397026	07/26/2016 08:00:00	07/26/2016 08:48:00	0.80	\$46.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/20/2016 14:34:24	07/20/2016 15:19:56	0.76	\$43.64

LABOR **283.10**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	15	\$1.35

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON LB	RECLAIMED FREON LB	1.50	1	\$1.50
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	33176840	BILSTEIN SHOCKS	117.47	2	\$234.94
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	33187563	BILSTEIN SHOCKS	101.74	2	\$203.48
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	224	\$22.40
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-32-002	REPLACE NEW BATTERY	65X	BATTERY-EXTREME-FORD TOP POT	95.16	1	\$95.16
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	ESTER OIL	A/C ESTER OIL OUNCE	0.84	1	\$0.84
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	R134AOZ	R134A FREON-OUNCE	0.10	9	\$0.90
					PARTS	588.55

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 23938

Work Order Notes

(LISAPATE) PM-CHECK SHOCKS-CHECK A/C

Job Notes

03-16-003 - REPLACE NEW FRONT SHOCK ABSORBERS

(LISAPATE) REPLACED FRONT SHOCKS

03-16-006 - REPLACE NEW REAR SHOCK ABSORBER

(LISAPATE) REPLACED REAR SHOCKS

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) REPLACED BATTERY

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 41918

Qty : 2

Description : WIPER BLADE

Manufacturer :

(LISAPATE) REPLACED WIPERS

06-16 - INSPECT SUSPENSION

(LISAPATE) CHECKED STEERING AND SUSPENSION. NEEDS FRONT AND REAR SHOCKS

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LISAPATE) CHECKED A/C CHECKED FOR LEAKS FOUND CONDENSOR ORINGS SEEPING A LITTLE, RECOVERED REFRIGERANT, REPLACED THE ORINGS, RECHECKED FOR LEAKS NO LEAKS FOUND PASSED LEAK TEST WITH THE MACHINE.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) EVAC AND RECHARGED SYSTEM. RECHECKED OK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

(LISAPATE) PM BY SH-REPLACED AIR FILTER

Work Order Charge Detail

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 27591

USING DEPT NO: 219101	OPENED DATE: 09/26/2017 11:33:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2017 15:50:08	METER 1 - M: 44036 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2017 15:50:10	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$46.00	\$5.12	\$0.00	\$51.12
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.50	\$28.89	\$2.31	\$0.00	\$31.20
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$612.86	\$612.86

JOB COUNT: 3	WORK ORDER TOTAL:	1.30	74.89	7.43	612.86	695.18
---------------------	--------------------------	-------------	--------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	233495	0040465	\$612.86
COMML					612.86

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	09/27/2017 10:05:46	09/27/2017 10:11:55	0.10	\$5.89
66-17-030	PERFORM TIRE PATCH	11074414	09/27/2017 06:48:00	09/27/2017 07:12:00	0.40	\$23.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/27/2017 06:00:00	09/27/2017 06:48:00	0.80	\$46.00
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	09/26/2017 11:37:47	09/26/2017 11:56:09	(0.31)	(\$17.60)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	09/26/2017 11:37:47	09/26/2017 11:56:09	0.31	\$17.60
LABOR					74.89	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.24	13	\$3.12
66-17-028	PERFORM MOUNT AND BALANCE TIRES	14041	PATCH 1/4 PILOT WIRE	2.31	1	\$2.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.40	5	\$2.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	14041	PATCH 1/4 PILOT WIRE	2.31	(1)	(\$2.31)
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.31	1	\$2.31
PARTS					7.43	

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 27591

Work Order Notes

(LISAPATE) NAIL IN RF TIRE. NEEDS 4 TIRES AND NEEDS STEERING PARTS REPLACED. THEY WILL BE COMPLETED AFTER YEAR END AND AN ALIGNMENT.

Job Notes

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) SH MOUNTED AND BALANCED 4 NEW TIRES

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) REMOVED AND PATCHED RF TIRE DRIVER WILL BRING BACK FOR 4 TIRES

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 4 TIRES FROM FIRESTONE. PD BY CC

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 27725

USING DEPT NO: 219101	OPENED DATE: 10/06/2017 15:30:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/16/2017 08:49:06	METER 1 - M: 44059 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/16/2017 08:49:07	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$115.00	\$421.87	\$0.00	\$536.87
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
03-15-009	REPLACE NEW TIE ROD	DON	O	N	GARAGE	1.90	\$109.25	\$138.74	\$0.00	\$247.99
03-15-020	REPLACE NEW DRAG LINK	DON	O	N	GARAGE	1.10	\$63.25	\$56.77	\$0.00	\$120.02
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$77.61	\$77.61
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.07	\$61.80	\$0.00	\$0.00	\$61.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$50.78	\$17.42	\$0.00	\$68.20

JOB COUNT: 7 **WORK ORDER TOTAL:** **8.96** **515.08** **634.80** **77.61** **1,227.49**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11122732	234000	0040697	\$77.61
				COMML	77.61

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	10/11/2017 11:40:58	10/11/2017 11:45:27	0.07	\$4.30
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	10/11/2017 07:00:00	10/11/2017 08:00:00	1.00	\$57.50
03-15-020	REPLACE NEW DRAG LINK	11213180	10/11/2017 08:54:00	10/11/2017 10:00:00	1.10	\$63.25
03-15-009	REPLACE NEW TIE ROD	11213180	10/11/2017 09:00:00	10/11/2017 10:54:00	1.90	\$109.25
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	10/11/2017 09:00:00	10/11/2017 11:00:00	2.00	\$115.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	10/11/2017 07:00:00	10/11/2017 09:00:00	2.00	\$115.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/11/2017 07:56:35	10/11/2017 08:49:34	0.88	\$50.78
					LABOR	515.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	224	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	CRS24000	GREASE SEALS	11.35	2	\$22.70

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	MONDX802	REAR BRAKE PADS	46.35	1	\$46.35
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	16.81	2	\$33.62
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	12.94	2	\$25.88
03-15-009	REPLACE NEW TIE ROD	TRWJSA1025	ADJUSTING SLEEVE	20.29	1	\$20.29
03-15-020	REPLACE NEW DRAG LINK	TRWJTY7006	DRAG LINK	56.77	1	\$56.77
03-15-009	REPLACE NEW TIE ROD	TRWJTE1531	TIE ROD END	40.48	1	\$40.48
03-15-009	REPLACE NEW TIE ROD	TRWJSA1027	ADJUSTING SLEEVES	17.11	1	\$17.11
03-15-009	REPLACE NEW TIE ROD	TRWJTE7035	TIE ROD END	35.71	1	\$35.71
03-15-009	REPLACE NEW TIE ROD	TRWJTE1549	TIE ROD END	25.15	1	\$25.15
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP655TRH	BRAKE PADS	57.70	1	\$57.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM66799R	BRAKE ROTOR	43.63	2	\$87.26
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM66528R	FRONT ROTOR	63.91	2	\$127.82
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM66528R	FRONT ROTOR	63.91	(2)	(\$127.82)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM66528R	FRONT ROTOR	74.18	2	\$148.36
					PARTS	634.80

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 27725

Work Order Notes

(LISAPATE) PM-REPLACE BRAKES AND STEERING PARTS. TIRES WERE REPLACED ON PREVIOUS WO AND HAD TO BE CLOSED OUT DUE TO END OF FISCAL YEAR

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) REPLACED FRONT PADS, ROTORS, BEARINGS AND SEALS

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(LISAPATE) REPLACED REAR PADS AND ROTORS

03-15-009 - REPLACE NEW TIE ROD

(LISAPATE) REPLACED BOTH INNER AND OUTER TIE RODS AND ADJUSTING SLEEVES

03-15-020 - REPLACE NEW DRAG LINK

(LISAPATE) REPLACED DRAG LINK. TEST DROVE OK

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) FIRESTONE COMPLETED ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO FIRESTONE BY EK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

(LISAPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 28498

USING DEPT NO:	219101	OPENED DATE:	01/03/2018 14:31:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/12/2018 06:50:26	METER 1 - M:	44685	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/12/2018 06:50:27	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.78	\$44.77	\$0.00	\$0.00	\$44.77
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,999.28	\$1,999.28

JOB COUNT: 2 WORK ORDER TOTAL: 0.78 44.77 0.00 1,999.28 2,044.05

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	166264	0041705	\$1,999.28
					COMML 1999.28

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10208562	01/04/2018 08:28:17	01/04/2018 09:15:00	0.78	\$44.77
					LABOR	44.77

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 28498

Work Order Notes

(LISAPATE) TAKE TO ANDREWS TO REPAIR BODY DAMAGE TO LEFT SIDE PANEL HAS A HOLE IN IT TOWARD THE TOP AND MIDDLE. TO BE PAID BY THE DEPT.

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) TAKEN TO ANDREWS BY EK

24-71 - REPAIR BODY

(LISAPATE) ANDREWS REPAIRED BODY DAMAGE PER THE ESTIMATE. PD BY CC

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 29758

USING DEPT NO:	219101	OPENED DATE:	05/10/2018 09:04:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2018 07:47:36	METER 1 - M:	45850	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2018 07:47:38	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$4.04	\$0.00	\$21.87

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 4.04 0.00 21.87

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/14/2018 06:00:00	05/14/2018 06:18:36	0.31	\$17.83

LABOR 17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	0.01	6	\$0.06

PARTS 4.04

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 29758

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

(LISAPATE) PM BY AG,RC/SH

COOLANT -35'

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 31134

USING DEPT NO:	219101	OPENED DATE:	10/10/2018 10:48:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2018 06:40:22	METER 1 - M:	47171	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/12/2018 06:40:24	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.22	\$0.00	\$0.49	\$0.00	\$0.49

JOB COUNT: 1 WORK ORDER TOTAL: 0.22 0.00 0.49 0.00 0.49

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11901357	10/10/2018 10:52:24	10/10/2018 11:05:50	0.22	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49
					PARTS	0.49

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 31134

Work Order Notes

(LISAPATE) LR brake light out

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Replaced LR brake light. rechecked ok

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 32292

USING DEPT NO:	219101	OPENED DATE:	02/27/2019 09:42:30	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2019 11:37:54	METER 1 - M:	48416	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2019 11:37:55	IN-SERVICE DATE:	04/11/2005		
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-018	REPAIR DOOR MECHANISM	DON	O	N	GARAGE	2.10	\$0.00	\$126.24	\$0.00	\$126.24

JOB COUNT: 1	WORK ORDER TOTAL:					2.10	0.00	126.24	0.00	126.24
---------------------	--------------------------	--	--	--	--	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-018	REPAIR DOOR MECHANISM	11074414	03/18/2019 06:00:00	03/18/2019 08:06:00	2.10	\$0.00
24-02-018	REPAIR DOOR MECHANISM	11074414	03/18/2019 06:00:00	03/18/2019 07:06:00	1.10	\$0.00
24-02-018	REPAIR DOOR MECHANISM	11074414	03/18/2019 06:00:00	03/18/2019 07:06:00	(1.10)	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-018	REPAIR DOOR MECHANISM	AC2Z15431A02A	DOOR LATCH KIT	47.50	1	\$47.50
24-02-018	REPAIR DOOR MECHANISM	6C2Z15434A20AA	OUTSIDE REAR DOOR HANDLE	78.74	1	\$78.74
					PARTS	126.24

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 32292

Work Order Notes

(LISAPATE) Rear door wont open

Job Notes

24-02-018 - REPAIR DOOR MECHANISM

(LISAPATE) Installed rear tag/door handle assy and door latch assy. Rechecked ok

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 32936

USING DEPT NO:	219101	OPENED DATE:	05/16/2019 10:00:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2019 13:22:44	METER 1 - M:	48981	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	05/17/2019 13:22:44	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$21.68	\$0.00	\$21.68

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 0.00 21.68 0.00 21.68

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2019 11:09:12	05/16/2019 11:27:48	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	21.68

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 32936

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 7 Cost 0.100000

(LISAPATE) PM by RC,EK/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 34759

USING DEPT NO:	219101	OPENED DATE:	11/05/2019 15:26:03	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2019 07:59:03	METER 1 - M:	50482	METER 2 - N:	0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/11/2019 07:59:05	IN-SERVICE DATE:	04/11/2005		
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.10	\$0.00	\$0.70	\$0.00	\$0.70
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.07	\$0.00	\$17.06	\$0.00	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$0.00	\$38.50	\$0.00	\$38.50

JOB COUNT: 3	WORK ORDER TOTAL:	1.03	0.00	56.26	0.00	56.26
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	12052187	11/06/2019 09:59:17	11/06/2019 10:05:26	0.10	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/06/2019 09:36:19	11/06/2019 10:02:29	0.44	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/06/2019 09:54:56	11/06/2019 09:59:17	0.07	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/06/2019 09:30:00	11/06/2019 09:54:56	0.42	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/06/2019 09:27:02	11/06/2019 09:27:02	0.00	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3457	BULB	0.70	1	\$0.70
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.94	7	\$27.58
					PARTS	56.26

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 34759

Work Order Notes

(IFALLS) PM

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Replaced LR turn signal bulb

03-51-038 - REPLACE NEW WIPER BLADES

(RTUNAITI)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :
Bin :

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

The following parts are included with the standard job:

Part No : 5W20FS
Qty : 7
Description : HAVOLINE 5W20 FULLSYN OIL BULK
Manufacturer :
Bin :

(LISAPATE) PM by SH/JW

Coolant -35'
Replaced air filter

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 36569

USING DEPT NO:	219101	OPENED DATE:	05/22/2020 09:57:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/22/2020 13:26:57	METER 1 - M:	51593	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/27/2020 11:38:58	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$0.00	\$21.74	\$0.00	\$21.74

JOB COUNT: 1 WORK ORDER TOTAL: 0.73 0.00 21.74 0.00 21.74

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/22/2020 10:13:58	05/22/2020 10:51:40	0.63	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/22/2020 10:13:38	05/22/2020 10:19:42	0.10	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	21.74

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 36569

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RTUNAITI)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 7

Description : HAVOLINE 5W20 FULLSYN OIL BULK

Manufacturer :

Bin :

(EKIMBREL) Sh,JW/AG performed pm. Coolant -34

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 36820

USING DEPT NO: 219101	OPENED DATE: 06/15/2020 13:33:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/24/2020 07:03:54	METER 1 - M: 51755 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/24/2020 09:37:12	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.32	\$0.00	\$98.65	\$0.00	\$98.65
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.53	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.85** **0.00** **98.65** **0.00** **98.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	06/23/2020 14:07:15	06/23/2020 14:26:37	0.32	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	06/23/2020 13:46:17	06/23/2020 14:03:51	0.29	\$0.00
66-79-002	PERFORM SERVICE CALL	10208562	06/19/2020 14:54:14	06/19/2020 15:08:24	0.24	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
					PARTS	98.65

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 36820

Work Order Notes

(LISAPATE) Gates requested a service call to the Library Annex van will not do anything at all

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery and installed terminal washers. alternator charging at 13.4 volts. JAW

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed jumped off and brought to the shop

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 38195

USING DEPT NO: 219101	OPENED DATE: 10/28/2020 11:04:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/30/2020 14:52:18	METER 1 - M: 52704 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/30/2020 15:44:32	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.66	\$77.65	\$0.00	\$0.00	\$77.65
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.67	\$79.36	\$0.00	\$0.00	\$79.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.06	\$124.88	\$0.00	\$0.00	\$124.88
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.08	\$9.44	\$0.00	\$0.00	\$9.44

JOB COUNT: 4 **WORK ORDER TOTAL:** 2.47 291.33 0.00 0.00 291.33

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/30/2020 13:24:02	10/30/2020 14:26:42	1.04	\$123.24
35-31	DIAGNOSE CHARGING SYSTEM	11170580	10/30/2020 11:16:43	10/30/2020 11:56:12	0.66	\$77.65
CH-32-002	CHARGE BATTERY	11170580	10/30/2020 11:11:19	10/30/2020 11:16:07	0.08	\$9.44
66-PM-PMA	PERFORM OIL CHANGE	11170580	10/30/2020 11:10:29	10/30/2020 11:11:19	0.01	\$1.64
66-79-002	PERFORM SERVICE CALL	11170580	10/28/2020 11:11:05	10/28/2020 11:51:26	0.67	\$79.36
					LABOR	291.33

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 38195

Work Order Notes

(LISAPATE) Gates requested a service call to the Heat Plant battery just clicks will not cranks. Battery was just replaced June 2020. Also needs PM
(LISAPATE) Contact Gates Winters 205-248-0502 or 205-650-1529 cell

Job Notes

35-31 - DIAGNOSE CHARGING SYSTEM

(ABLACK) Inspect for a battery draw

(ABLACK) AB checked vehicle for a draw and was consistantly .012 milliamps. Well below the ford spec for a draw. Charged battery and checked good. All doors and lights were ok not causing a draw. Nothing was found to be plugged up and draining the battery. Returned vehicle to customer.

66-79-002 - PERFORM SERVICE CALL

(ABLACK) AB/RC performed service call. Jumped vehicle off and brought it back to the shop.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 52719. Vehicle has been driven 1126 miles since last PM. Checked fluids, battery, tire pressure and updated oil change sticker. Washed and vacuumed vehicle. Was full of gas. SH

CH-32-002 - CHARGE BATTERY

(ABLACK) AB charged battery up and battery checked good. Installed battery back into vehicle to check for a draw.

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 39550

USING DEPT NO:	219101	OPENED DATE:	04/02/2021 08:50:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/05/2021 11:03:24	METER 1 - M:	53848	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	04/06/2021 07:29:00	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.48	\$40.64	\$0.00	\$91.12

JOB COUNT: 1 WORK ORDER TOTAL: 0.43 50.48 40.64 0.00 91.12

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/02/2021 09:30:00	04/02/2021 09:46:11	0.27	\$31.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/02/2021 09:05:31	04/02/2021 09:15:00	0.16	\$18.65
					LABOR	50.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
					PARTS	40.64

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 39550

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 53848. SH/AMG Performed PM. SH Washed vacuumed and filled with gas.

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 4048

USING DEPT NO: 219101	OPENED DATE: 08/06/2009 14:10:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/07/2009 06:24:59	METER 1 - M: 20562 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/07/2009 06:25:01	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$66.83	\$0.00	\$84.66

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **97.73** **0.00** **129.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	08/06/2009 17:00:00	08/06/2009 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11088474	08/06/2009 17:18:36	08/06/2009 17:33:36	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	31.50	1	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	3.95	1	\$3.95
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
					PARTS	97.73

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 4048

Work Order Notes

(LPATE) PM-REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) The following parts are included with the standard job:

Part No : 91-18
Qty : 2
Description : WIPER BLADE
Manufacturer :

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 51372 FILTER-OIL Qty 1 Cost 0
Part 5W20 OIL-MOTOR Qty 224 Cost 0

(LPATE) PM BY JE-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 41696

USING DEPT NO: 219101	OPENED DATE: 11/23/2021 13:20:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/29/2021 13:18:03	METER 1 - M: 55897 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/29/2021 13:18:09	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	0.51	\$60.34	\$22.11	\$0.00	\$82.45
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.18	\$15.18	\$0.00	\$22.36
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.18	\$20.88	\$0.00	\$0.00	\$20.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$60.97	\$35.71	\$0.00	\$96.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.27	149.37	73.00	2.00	224.37
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML
					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	11901357	11/23/2021 15:07:26	11/23/2021 15:38:07	0.51	\$60.34
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/23/2021 15:03:00	11/23/2021 15:06:39	0.06	\$7.18
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	11/23/2021 14:06:09	11/23/2021 14:16:46	0.18	\$20.88
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/23/2021 13:34:45	11/23/2021 14:05:45	0.52	\$60.97
					LABOR	149.37

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	22.11	1	\$22.11
					PARTS	73.00

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 41696

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

(AGUERRA) Replaced right headlight, checked for proper operation, all good. AMG

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :
Bin :

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG SH JW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 55912 Completed PM topside, Josh assisted, Scott was bottomsides. Completed checklist. AMG JW/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 43361

USING DEPT NO: 219101	OPENED DATE: 05/24/2022 09:03:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/26/2022 10:46:20	METER 1 - M: 57386 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/27/2022 15:07:16	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.49	\$0.00	\$0.00	\$6.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.65	\$0.65

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.06** **6.49** **0.00** **0.65** **7.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$0.65
COMML					0.65

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/24/2022 09:11:42	05/24/2022 09:15:00	0.06	\$6.49
LABOR						6.49

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 43361

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :
Bin :

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 1474 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 43974

USING DEPT NO: 219101	OPENED DATE: 07/14/2022 10:49:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/14/2022 15:48:30	METER 1 - M: 57701 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/21/2022 11:53:36	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	DON	O	N	GARAGE	1.02	\$120.92	\$226.43	\$0.00	\$347.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.02** **120.92** **226.43** **2.00** **349.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	11074414	07/14/2022 10:58:31	07/14/2022 12:00:00	1.02	\$120.92
LABOR					120.92	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	8C2Z15431A03A	LOWER LATCH W/HANDLE	76.04	1	\$76.04
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	6C2Z1543286AA	UPPER DOOR LATCH	82.20	1	\$82.20
03-02-055	REPLACE NEW DOOR LATCH/STRIKER	8C2Z15264A00D	DOOR LATCH CABLE	68.19	1	\$68.19
PARTS					226.43	

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 43974

Work Order Notes

(CHANNELL) replace door latches

Job Notes

03-02-055 - REPLACE NEW DOOR LATCH/STRIKER

(HHARBIN) Replaced left rear top and bottom door latch assemblys and passenger side right hand door latch assembly. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 45149

USING DEPT NO:	219101	OPENED DATE:	11/02/2022 09:08:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/02/2022 15:23:30	METER 1 - M:	59070	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/07/2022 07:36:18	IN-SERVICE DATE:	04/11/2005		
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.72	\$15.63	\$0.00	\$20.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$4.82	\$49.70	\$0.00	\$54.52
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.08	9.54	65.33	5.00	79.87
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2022 09:30:00	11/02/2022 09:32:27	0.04	\$4.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2022 09:15:30	11/02/2022 09:15:30	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/02/2022 09:30:00	11/02/2022 09:32:24	0.04	\$4.72
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/02/2022 09:28:03	11/02/2022 09:28:03	0.00	\$0.00
LABOR					9.54	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	7	\$43.79
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.91	1	\$5.91
PARTS					65.33	

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 45149

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :
Bin :

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 46697

USING DEPT NO: 219101	OPENED DATE: 04/12/2023 12:22:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/19/2023 13:44:42	METER 1 - M: 59572 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/20/2023 07:56:37	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.54	\$16.44	\$0.00	\$23.98
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.04	\$4.43	\$0.00	\$0.00	\$4.43
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	3.19	\$376.06	\$134.19	\$0.00	\$510.25
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.02	\$119.87	\$853.97	\$0.00	\$973.84
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.33	\$39.10	\$0.00	\$0.00	\$39.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.49	\$0.00	\$0.00	\$20.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.12	\$13.93	\$0.00	\$0.00	\$13.93

JOB COUNT: 8 **WORK ORDER TOTAL:** **4.93** **581.42** **1,004.60** **5.00** **1,591.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	04/19/2023 07:04:14	04/19/2023 07:49:19	0.75	\$88.66
66-17-013	PERFORM ALIGNMENT	11310047	04/18/2023 15:01:00	04/18/2023 15:49:52	0.81	\$96.10
66-17-013	PERFORM ALIGNMENT	11310047	04/18/2023 10:21:22	04/18/2023 11:58:38	1.62	\$191.29
WA-00	WASH COMPLETE VEHICLE	11074414	04/18/2023 09:30:00	04/18/2023 09:33:28	0.06	\$6.82
WA-00	WASH COMPLETE VEHICLE	11074414	04/18/2023 09:11:23	04/18/2023 09:15:00	0.06	\$7.11
06-15	INSPECT STEERING	11074414	04/18/2023 09:08:57	04/18/2023 09:11:12	0.04	\$4.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/18/2023 09:05:29	04/18/2023 09:08:44	0.05	\$6.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/18/2023 07:22:46	04/18/2023 08:20:28	0.96	\$113.48
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/13/2023 14:30:00	04/13/2023 14:38:36	0.14	\$16.91
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/13/2023 14:03:43	04/13/2023 14:15:00	0.19	\$22.19

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/13/2023 13:59:41	04/13/2023 14:03:31	0.06	\$7.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/13/2023 13:49:03	04/13/2023 13:59:28	0.17	\$20.49
					LABOR	581.41

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.22	2	\$16.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21601	TR 600 HP WIDE VALVE STEM	0.72	4	\$2.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.39	1	\$0.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.53	2	\$1.05
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.75	1	\$0.75
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.23	3	\$3.69
66-17-013	PERFORM ALIGNMENT	K8986	CAM BUSHINGS	67.10	2	\$134.19
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450718	TIRE GEN GRAB HD LT245/75R16	211.05	4	\$844.20
					PARTS	1004.60

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 46697

Work Order Notes

(EHANNAH) pm- replace wipers- do SI - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EHANNAH)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :
Bin :

(SHARBIN) Replaced the wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering during safety inspection. Found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed front end alignment. Removed front wheels and installed adjustable cam bushings to both sides of the vehicle. EH Extra .6 HR

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. All 4 tires are out of date. Found no other issues at this time. Front left pads measure 7MM front right pads measure 8MM rear pads measure 7MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 631 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. Needs 4 tires due to 1117 DOT dates. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 48664

USING DEPT NO: 219101	OPENED DATE: 10/20/2023 13:53:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/24/2023 14:55:29	METER 1 - M: 59863 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/25/2023 07:08:26	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.60	\$53.41	\$0.00	\$83.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.67	\$78.86	\$0.00	\$0.00	\$78.86

JOB COUNT: 3	WORK ORDER TOTAL:	0.92	108.46	53.41	5.00	166.87
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	10/23/2023 09:58:32	10/23/2023 10:38:38	0.67	\$78.86
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/23/2023 09:30:00	10/23/2023 09:45:03	0.25	\$29.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/23/2023 09:24:21	10/23/2023 09:24:21	0.00	\$0.00
LABOR					108.46	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	3.66	1	\$3.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	7	\$43.79
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.96	1	\$5.96
PARTS					53.41	

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 48664

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed. SH

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 50309

USING DEPT NO: 219101	OPENED DATE: 03/27/2024 07:24:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/02/2024 10:22:58	METER 1 - M: 60013 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/02/2024 12:27:12	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-001	REPLACE NEW HEADLAMPS	DON	N	N	GARAGE	0.11	\$13.34	\$25.05	\$0.00	\$38.39
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.04	\$4.62	\$16.65	\$0.00	\$21.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$27.89	\$0.00	\$0.00	\$27.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.32	\$37.96	\$0.00	\$0.00	\$37.96

JOB COUNT: 5	WORK ORDER TOTAL:	0.71	83.81	41.70	5.00	130.51
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	11074414	03/27/2024 14:39:20	03/27/2024 14:46:07	0.11	\$13.34
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/27/2024 11:20:30	03/27/2024 11:22:51	0.04	\$4.62
WA-00	WASH COMPLETE VEHICLE	11074414	03/27/2024 10:10:10	03/27/2024 10:29:28	0.32	\$37.96
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/27/2024 09:55:59	03/27/2024 10:10:10	0.24	\$27.89
					LABOR	83.81

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	25.05	1	\$25.05
					PARTS	41.70

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 50309

Work Order Notes

(EHANNAH) pm- wash

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

(GARAGE) Replaced the right front headlight. Rechecks good. SH

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 41918
Qty : 2
Description : WIPER BLADE
Manufacturer :
Bin :

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 150 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 50488

USING DEPT NO: 219101	OPENED DATE: 04/09/2024 12:08:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/30/2024 09:03:50	METER 1 - M: 60267 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/30/2024 10:11:03	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.02	\$1.90	\$0.00	\$0.00	\$1.90
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.48	\$56.31	\$0.00	\$0.00	\$56.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.08	\$9.54	\$0.00	\$0.00	\$9.54
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.15	\$18.16	\$0.00	\$0.00	\$18.16

JOB COUNT: 5	WORK ORDER TOTAL:	0.73	85.91	0.00	5.00	90.91
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11915538	04/30/2024 08:39:08	04/30/2024 08:40:06	0.02	\$1.90
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/12/2024 09:30:00	04/12/2024 09:40:10	0.17	\$19.99
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/12/2024 08:56:32	04/12/2024 09:15:00	0.31	\$36.32
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/11/2024 11:42:00	04/11/2024 11:51:14	0.15	\$18.16
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	04/29/2024 11:05:26	04/29/2024 11:10:17	0.08	\$9.54
					LABOR	85.91

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 50488

Work Order Notes

(EHANNAH) service call for check engine light on, driver reports the van shuddering while driving as well (IFALLS) department decided to sell unit

Job Notes

66-79-002 - PERFORM SERVICE CALL

(GARAGE) pickup brought to shop\RC\CW

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed a safety inspection. The check engine light is on and it needs the sway bar bushings that go in the I Beams. Found no other issues at this time. SH

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) removed wordmarks AND TAG\RC

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EKIMBREL) eh performed scan out. found codes p0305, p2105, b1342, and c1185

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 6381

USING DEPT NO: 219101	OPENED DATE: 07/30/2010 07:07:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/02/2010 06:55:59	METER 1 - M: 22990 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/02/2010 06:56:01	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-024	REPLACE NEW GLASS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$124.51	\$124.51
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$16.84	\$28.03	\$0.00	\$44.87

JOB COUNT: 3	WORK ORDER TOTAL:	0.59	34.09	28.03	124.51	186.63
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-024	REPLACE NEW GLASS	11245625	049351	0008550	\$124.51
					COMML 124.51

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11328035	07/30/2010 07:52:28	07/30/2010 08:10:28	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11328035	07/30/2010 07:34:54	07/30/2010 07:52:28	0.29	\$16.84
					LABOR	34.09

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
					PARTS	28.03

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 6381

Work Order Notes

(LPATE) PM-RIGHT SIDE FRONT CARGO DOOR GLASS BROKE OUT WHEN KEVIN CLOSED DOOR TODAY TAKE TO ROZAR'S TO BE REPLACED.

Job Notes

03-02-024 - REPLACE NEW GLASS

(LPATE) ROZAR'S REPLACED GLASS P0029801

16-02 - TRANSPORT CAB & SHEET METAL

(LPATE) TAKEN TO ROZAR'S BY TM

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY JM/TM

Work Order Charge Detail

UNIT NO: 235974 **2005 FORD E250**

WORK ORDER NO: 7036

USING DEPT NO: 219101	OPENED DATE: 10/20/2010 10:42:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/21/2010 07:20:43	METER 1 - M: 23847 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/21/2010 07:20:46	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250	UNIT SERIAL NO: 1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.40	\$23.27	\$92.82	\$0.00	\$116.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$58.55	\$28.03	\$0.00	\$86.58

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.42** **81.82** **120.85** **0.00** **202.67**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11328035	10/20/2010 13:00:01	10/20/2010 13:24:18	0.40	\$23.27
66-PM-PMA	PERFORM OIL CHANGE	11328035	10/20/2010 13:24:24	10/20/2010 14:15:00	0.84	\$48.49
66-PM-PMA	PERFORM OIL CHANGE	11328035	10/20/2010 14:30:00	10/20/2010 14:40:30	0.18	\$10.06
					LABOR	81.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
03-32-002	REPLACE NEW BATTERY	65-6	BATTERY TOP POST	92.82	1	\$92.82
					PARTS	120.85

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 7036

Work Order Notes

(LPATE) PM-CHECKED AND BATTERY FAILED REPLACE BATTERY

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 1372
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : 5W20
Qty : 224
Description : OIL BOTTLE
Manufacturer :

(LPATE) PM BY TM

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 7122

USING DEPT NO: 219101	OPENED DATE: 11/03/2010 07:57:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/08/2010 08:07:05	METER 1 - M: 23900 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/08/2010 08:07:07	IN-SERVICE DATE: 04/11/2005
TECH SPEC NO: 05VNFORDE250 2005 Ford E250		UNIT SERIAL NO: 1FTNE24W75HB42629

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-06-003	REPLACE NEW CLOCK SPRING/HORN	DON	O	N	GARAGE	3.52	\$202.34	\$64.14	\$0.00	\$266.48
03-15-010	REPLACE NEW BALL JOINT	DON	O	N	GARAGE	0.64	\$37.01	\$262.38	\$0.00	\$299.39
03-15-020	REPLACE NEW DRAG LINK	DON	O	N	GARAGE	1.01	\$58.33	\$149.10	\$0.00	\$207.43
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$328.36	\$328.36
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.04	\$59.51	\$0.00	\$0.00	\$59.51
SO-79-001	SCAN OUT AIR BAG	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 6	WORK ORDER TOTAL:	7.71	443.44	475.62	328.36	1,247.42
---------------------	--------------------------	-------------	---------------	---------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	129862	0009805	\$328.36
				COMML	328.36

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-13	SCAN OUT BRAKES	11274660	11/03/2010 07:09:05	11/03/2010 09:15:00	2.10	\$120.67
SO-13	SCAN OUT BRAKES	11274660	11/03/2010 07:09:05	11/03/2010 09:15:00	(2.10)	(\$120.67)
SO-13	SCAN OUT BRAKES	11274660	11/03/2010 09:30:00	11/03/2010 10:57:47	1.46	\$84.13
SO-13	SCAN OUT BRAKES	11274660	11/03/2010 09:30:00	11/03/2010 10:57:47	(1.46)	(\$84.13)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11274660	11/03/2010 10:57:54	11/03/2010 12:00:00	1.04	\$59.51
03-15-010	REPLACE NEW BALL JOINT	11274660	11/03/2010 12:00:46	11/03/2010 12:00:46	0.00	\$0.00
03-15-010	REPLACE NEW BALL JOINT	11274660	11/03/2010 13:00:00	11/03/2010 13:38:37	0.64	\$37.01
03-15-020	REPLACE NEW DRAG LINK	11274660	11/03/2010 13:38:43	11/03/2010 14:15:00	0.60	\$34.77
03-15-020	REPLACE NEW DRAG LINK	11274660	11/03/2010 14:30:00	11/03/2010 14:54:35	0.41	\$23.56
SO-79-001	SCAN OUT AIR BAG	11274660	11/04/2010 07:00:00	11/04/2010 08:30:00	1.50	\$86.25
03-06-003	REPLACE NEW CLOCK SPRING/HORN CONTACTS	11274660	11/04/2010 05:58:57	11/04/2010 09:15:00	3.27	\$187.88
03-06-003	REPLACE NEW CLOCK SPRING/HORN CONTACTS	11274660	11/04/2010 09:30:00	11/04/2010 09:44:48	0.25	\$14.19

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-06-003	REPLACE NEW CLOCK SPRING/HORN CONTACTS	11274660	11/04/2010 13:00:57	11/04/2010 13:01:14	0.00	\$0.27
					LABOR	443.44

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-010	REPLACE NEW BALL JOINT	SPI5001074	UPPER BALLJOINT	52.80	2	\$105.60
03-15-010	REPLACE NEW BALL JOINT	SPI5051160	LOWER BALLJOINT	78.39	2	\$156.78
03-15-020	REPLACE NEW DRAG LINK	SPI4101048	DRAG LINK	149.10	1	\$149.10
03-06-003	REPLACE NEW CLOCK SPRING/HORN CONTACTS	4C2Z14A664BA	CLOCK SPRING	64.14	1	\$64.14
					PARTS	475.62

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 7122

Work Order Notes

(LPATE) ABS LIGHT COMING ON AND OFF AT TIMES. NOT ON WHEN CAN CAME IN SHOP BUT HAS CODES STORED. NEEDS 2 TIRES AND ALIGN-CHECK STEERING COI

Job Notes

03-06-003 - REPLACE NEW CLOCK SPRING/HORN CONTACTS

(LPATE) REPLACED CLOCKSPRING

03-15-010 - REPLACE NEW BALL JOINT

(LPATE) REPLACED ALL UPPER AND LOWER BALL JOINTS

03-15-020 - REPLACE NEW DRAG LINK

(LPATE) REPLACED DRAG LINK

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) FIRESTONE REPLACED 2 TIRES ON FRONT AND ALIGNED P0032043

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY TF

SO-13 - SCAN OUT BRAKES

(LPATE) CANCELLED JOB WRONG CODES

SO-79-001 - SCAN OUT AIR BAG

(LPATE) DIAGNOSTIC CIRCUIT CHECK-CODE B1932 REPLACE CLOCKSPRING

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 9055

USING DEPT NO:	219101	OPENED DATE:	09/02/2011 15:40:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/07/2011 08:13:00	METER 1 - M:	26136	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/07/2011 08:13:01	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$369.12	\$369.12
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.17	\$39.21	\$0.00	\$53.38
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$15.16	\$52.25	\$0.00	\$67.41

JOB COUNT: 4	WORK ORDER TOTAL:	1.51	86.83	91.46	369.12	547.41
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	140287	0013100	\$369.12
					COMML 369.12

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11338644	09/06/2011 11:18:32	09/06/2011 11:33:19	0.25	\$14.17
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/06/2011 11:02:15	09/06/2011 11:18:04	0.26	\$15.16
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11328035	09/02/2011 17:00:00	09/02/2011 18:00:00	1.00	\$57.50
					LABOR	86.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.69	1	\$4.69
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	14.41	1	\$14.41
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	19.61	2	\$39.21
					PARTS	91.46

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 9055

Work Order Notes

(LPATE) PM-PER KEVIN JUMPING IN REAR END BAD. TEST DROVE NEEDS 2 NEW TIRES. FIRESTONE TO REPLACE 2 TIRES THEY WILL MOVE FRONT TO REAR AND PL NEW ON FRONT THEN ALIGN.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED. PD BY CC.

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 60-1840
Qty : 2
Description : WIPER BLADE
Manufacturer :

(LPATE) REPLACED WIPERS

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY TM

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY RS-REPLACED AIR FILTER AND OIL DRAIN PLUG

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 972

USING DEPT NO:	219101	OPENED DATE:	03/10/2008 15:40:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2008 15:41:42	METER 1 - M:	16785	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	03/10/2008 15:41:43	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$27.62	\$0.00	\$27.62

JOB COUNT: 1	WORK ORDER TOTAL:					0.00	0.00	27.62	0.00	27.62
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	224	\$20.16
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.46	1	\$7.46
					PARTS	27.62

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 972

Work Order Notes

(LOBRIEN) PM.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE.

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 9878

USING DEPT NO:	219101	OPENED DATE:	12/12/2011 07:55:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2011 07:43:34	METER 1 - M:	26783	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/14/2011 07:43:36	IN-SERVICE DATE:	04/11/2005	
TECH SPEC NO:	05VNFORDE250	2005 Ford E250		UNIT SERIAL NO:	1FTNE24W75HB42629	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$17.25	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$28.25	\$0.00	\$46.08

JOB COUNT: 3	WORK ORDER TOTAL:	0.61	35.08	28.25	17.25	80.58
---------------------	--------------------------	-------------	--------------	--------------	--------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11245625	101744	0014183	\$17.25
COMML					17.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/12/2011 17:00:00	12/12/2011 17:18:36	0.31	\$17.83
16-02	TRANSPORT CAB & SHEET METAL	10260422	12/13/2011 07:00:00	12/13/2011 07:18:00	0.30	\$17.25
16-02	TRANSPORT CAB & SHEET METAL	10260422	12/13/2011 07:00:00	12/13/2011 08:00:00	1.00	\$57.50
16-02	TRANSPORT CAB & SHEET METAL	10260422	12/13/2011 07:00:00	12/13/2011 08:00:00	(1.00)	(\$57.50)
LABOR					35.08	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
PARTS					28.25	

Work Order Charge Detail

UNIT NO: 235974 2005 FORD E250

WORK ORDER NO: 9878

Work Order Notes

(LPATE) PM-PER KEVIN REPAIR DING IN WINDSHIELD

Job Notes

16-02 - TRANSPORT CAB & SHEET METAL

(LPATE) TAKEN TO ROZAR'S BY GM

24-02-061 - REPAIR WINDSHIELD

(LPATE) ROZAR'S REPAIRED WINDSHIELD. PD BY CC.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY SH

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon May 20 2024 23:04:12 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '235974') //Q=