Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

LABOR

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 37275

USING DEPT NO: 504104 **OPENED DATE:** 08/06/2020 13:54:58 **LOCATION:** GARAGE - University Automotive Services

WO STATUS: CLOSED **COMPLETED DATE:** 08/06/2020 13:57:27 **METER 1 - M:** 160 **METER 2 - N:** 0

WO VISIT REASON: SCHEDULED **CLOSED DATE:** 08/06/2020 14:05:40 **IN-SERVICE DATE:** 08/06/2020

TECH SPEC NO: 20CHEVEXP2500 2020 Chevrolet Express Van 2500 UNIT SERIAL NO: 1GCWGAFG6L1250048

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
66-00-001	PERFORM NEW UNIT IN-SERVICE INSF	DON	С	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUN	JOB COUNT: 1		wo	RK ORI	DER TOTAL:	0.50	0.00	0.00	0.00	0.00
Job Code	Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fin</u>	<u>ish</u>	<u>Quantity</u>	Total Cost
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	N 1	1915538	3	08/	06/2020 13:55:47	08/06/2020	14:25:47	0.50	\$0.00

0.00

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 37275

Work Order Notes

(EKIMBREL) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) RC performed PDI

UNIT NO:	2	43742 2	020 CHE	VROLE	T EX	PRES	S 2500		WORK O	RDER NO	:	37400		
USING DEPT N	IO : 5	04104		OPENE	D DATI	E:	08/20/20	20 15:30:58	LOCATION:	GARAGE	- Univer	sity Automotive	Services	
WO STATUS:	С	LOSED		COMPL	ETED I	DATE:	08/24/20	20 10:59:35	METER 1 - I	vi: 168		METER 2 - N:	0	
WO VISIT REAS	SON: S	CHEDULED		CLOSE	D DATE	E:	08/25/20	20 09:32:06	IN-SERVICE	DATE:	08/06/	2020		
TECH SPEC NO	0: 2	0CHEVEXP2500	2020 (Chevrole	t Expre	ss Van 2	2500		UNIT SERIA	L NO:	1GCW	/GAFG6L125004	18	
JOB CODE	<u>J</u>	OB DESCRIPTION	<u>l</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL	COMMERCIAL	TOTAL C	COST
14-52-021 I	INSTALL GF	PS SYSTEM		DON	0	N	GARAGE	0.33	\$0.00	\$0.00		\$0.00	\$0.00	
JOB COUNT:	1				WO	RK ORI	DER TOTAL	.: 0.33	3 0	.00	0.00	0.00)	0.00
Job Code		Job Description	<u>n</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total C	<u>Cost</u>
14-52-021 INS	STALL GPS S	SYSTEM		11	074414		08	8/21/2020 11:06:26	08/21/202	20 11:26:14		0.33		\$0.00
												LABOR	-	0.00

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 37400

Work Order Notes

(LISAPATE) Install GPS system

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) INSTALLED A NEW GPS. Serial# 5041770523

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

243742 **UNIT NO:** 2020 CHEVROLET EXPRESS 2500 **WORK ORDER NO:** 38760 **USING DEPT NO:** 504104 **OPENED DATE:** 01/12/2021 10:58:47 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 01/13/2021 07:33:11 WO STATUS: COMPLETED DATE: METER 1 - M: 2380 METER 2 - N: **SCHEDULED** 01/13/2021 14:14:32 WO VISIT REASON: **CLOSED DATE: IN-SERVICE DATE:** 08/06/2020 **TECH SPEC NO:** 20CHEVEXP2500 2020 Chevrolet Express Van 2500 **UNIT SERIAL NO:** 1GCWGAFG6L1250048 **JOB LOC MATERIAL** COMMERCIAL TOTAL COST JOB CODE JOB DESCRIPTION STAT RSN WRTY LABOR HRS LABOR 66-PM-PMA PERFORM OIL CHANGE DON Ρ **GARAGE** 1.17 \$137.50 Ν \$37.74 \$0.00 \$175.24 JOB COUNT: 1 WORK ORDER TOTAL: 1.17 137.50 37.74 0.00 175.24 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 11074414 01/12/2021 14:30:00 01/12/2021 15:00:56 0.52 \$60.84 0.14 66-PM-PMA PERFORM OIL CHANGE 11074414 01/12/2021 14:06:37 01/12/2021 14:15:00 \$16.49 66-PM-PMA PERFORM OIL CHANGE 11901357 01/12/2021 14:30:00 01/12/2021 14:42:39 0.21 \$24.88 66-PM-PMA PERFORM OIL CHANGE 11901357 01/12/2021 13:57:03 01/12/2021 14:15:00 0.30 \$35.30 **LABOR** 137.51 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** \$2.82 66-PM-PMA 7060 2.82 PERFORM OIL CHANGE FILTER-OIL 66-PM-PMA 5W30T 5.82 \$34.92 PERFORM OIL CHANGE 5W30 SYNTHETIC OIL THOMAS CAM2 37.74 **PARTS**

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 38760

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 2380. AMG/SH Performed PM. SH Washed vacuumed and filled with gas.

UNIT NO:		243742	2020 CHE\	/ROLE	ET EX	PRESS	S 2500		WORK O	RDER NO	D: 4	0122	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP250		OPENE COMPL CLOSE Chevrole	ETED	DATE:	06/09/202 06/10/202	21 08:03:28 21 14:54:21 21 11:56:13	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 5117 E DATE:	08/06/20		0
JOB CODE	<u> </u>	JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL C	OMMERCIAL	TOTAL COST
66-17-030	PERFOR	RM TIRE PATCH		DON	0	Ν	GARAGE	0.77	\$90.27	\$8.89	\$	0.00	\$99.16
66-17-033	PERFOR	RM TIRE ROTATIO	N AND BRAKE	DON	Р	Ν	GARAGE	0.53	\$62.34	\$0.00	\$	0.00	\$62.34
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.14	\$16.06	\$39.23	\$	0.00	\$55.29
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	: 1.43	168	3.67	48.12	0.00	216.79
Job Code		Job Descrip	<u>tion</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total Cost</u>
66-17-033	PERFORM	TIRE ROTATION ANI	D BRAKE INSPE	CTION 1	2052187	•	06	/08/2021 08:58:26	06/08/20	21 08:59:59		0.03	\$3.05
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	•	06	/08/2021 09:00:10	06/08/20	21 09:02:31		0.04	\$4.62
66-17-033	PERFORM	TIRE ROTATION ANI	D BRAKE INSPE	CTION 1	2052187		06	/08/2021 09:02:42	06/08/20	21 09:02:58		0.00	\$0.52
66-17-033	PERFORM	TIRE ROTATION ANI	D BRAKE INSPE	CTION 1	1310047		06	/08/2021 08:39:13	06/08/20	21 09:09:06		0.50	\$58.77
66-17-030	PERFORM	TIRE PATCH		1	2052187		06	/08/2021 08:12:21	06/08/20	21 08:58:15		0.77	\$90.27
66-PM-PMA	PERFORM	OIL CHANGE		1	1901357		06	/08/2021 08:30:49	06/08/20	21 08:36:38		0.10	\$11.44
												LABOR	168.67
Job Code		Job Descrip	tion			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
66-17-030	PERFORM	TIRE PATCH		٧	VHEEL V	VEIGHT	W	HEEL WEIGHT KN	IOCK ON		0.4	3 2	\$0.96
66-17-030	PERFORM	TIRE PATCH		2	3131		TF	PMS SNAP IN VAL	VE 21060		3.9	2 1	\$3.92
66-17-030	PERFORM '	TIRE PATCH		1	4041		PA	TCH 1/4 PILOT W	IRE		4.0	1 1	\$4.0
66-PM-PMA	PERFORM	OIL CHANGE		В	ALB160		OI	L FILTER			4.2	2 1	\$4.22
66-PM-PMA	PERFORM	OIL CHANGE		5	W30T		5V	V30 SYNTHETIC (OIL THOMAS (CAM2	5.84		
												PARTS	48.12

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

243742 **2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: UNIT NO:** 40122

Work Order Notes

(LISAPATE) Nail in RF tire-PM

Job Notes

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired RF tire. Aired to spec. Torqued lugs to 140ft lbs. JAW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Aired to spec and relearned tpms. Torqued lugs to 140ft lbs. JAW,EH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG,EH/EH MILEAGE-5117

UNIT NO:		243742 202	0 CHEVROL	ET EX	PRESS	S 2500		WORK C	ORDER NO):	41573		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500	COMP	ED DAT LETED ED DAT et Expre	DATE: E:	11/10/202 11/11/202	21 08:02:38 21 14:08:04 21 10:23:04	LOCATION METER 1 - IN-SERVIC UNIT SER	M: 8048 E DATE:	08/06/2		0	
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL	COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.01	\$1.21	\$15.18		\$0.00	\$16.39	
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	N	GARAGE	0.35	\$41.82	\$40.79		\$0.00	\$82.61	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	;	\$2.00	\$2.00	
JOB COUN	T: 3			wc	RK ORI	DER TOTAL:	0.36	4	3.03	55.97	2.00		101.00
Job Code		Job Description		<u> </u>	<u>endor N</u>	<u>o.</u>	Invoice No.	Purch	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies	!	03163		1							\$2.00
											COMML		2.00
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	•	1074414	1	11.	/10/2021 08:32:14	11/10/20	021 08:34:46		0.04		\$4.98
03-51-038	REPLACE N	IEW WIPER BLADES	,	205218	7	11.	/10/2021 08:34:01	11/10/20	021 08:34:38		0.01		\$1.21
66-PM-PMA	PERFORM (OIL CHANGE		205218	7	11/	/10/2021 08:15:03	11/10/20	021 08:33:47		0.31		\$36.84
											LABOR		43.03
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	cription		Unit Pric	e Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	E	BALB160)	OI	L FILTER			5.8	87 1		\$5.87
66-PM-PMA	PERFORM (OIL CHANGE	ţ	W30T		5V	/30 SYNTHETIC (OIL THOMAS	CAM2	5.8	82 6		\$34.92
03-51-038	REPLACE N	IEW WIPER BLADES	2	22-1		WI	PER BLADE 22" 1	TRICO EXAC	Г	7.5			\$15.18
											PARTS		55.97

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 41573

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Completed bottom side (SHARBIN) SH/JW Performed PM.

UNIT NO:		243742 202	20 CHEVRO	LET EX	(PRES	S 2500		WORK OF	RDER NO): 4	12992		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500	СОМ	NED DA PLETED SED DA olet Expr	DATE: FE:	04/22/20 04/25/20	22 07:48:49 22 09:35:10 22 08:08:54	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 10479 DATE:	08/06/2		0	
JOB CODE	1	JOB DESCRIPTION	<u>STA</u>	r RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL (COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLADES	S DOI	l P	Ν	GARAGE	0.03	\$3.41	\$15.18	\$	0.00	\$18.59	
66-PM-PMA	PERFOR	M OIL CHANGE	DOI	l P	Ν	GARAGE	0.15	\$18.16	\$55.17	\$	0.00	\$73.33	
CH-SP	CHARGE	Shop Supplies	DOI	1 2	N	GARAGE	0.00	\$0.00	\$0.00	\$	2.00	\$2.00	
JOB COUN	B COUNT: 3			W	ORK OR	DER TOTAL	.: 0.18	21.	57	70.35	2.00		93.92
Job Code	Job Description				Vendor N	lo.	Invoice No.	Purchas	se Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		503163		1							\$2.00
											COMML		2.00
Job Code		Job Description		<u>E</u>	mployee	No.	<u>Start</u>	<u> </u>	inish		Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		1205218	37	04	4/21/2022 08:07:38	04/21/202	2 08:09:22		0.03		\$3.41
66-PM-PMA	PERFORM (OIL CHANGE		1205218	37	04	4/21/2022 07:58:14	04/21/202	2 08:07:28		0.15		\$18.16
											LABOR		21.57
Job Code		Job Description			Part No	<u>).</u>	Des	<u>cription</u>		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		BALB16	0	0	IL FILTER			10.4	4 1		\$10.44
03-51-038	REPLACE N	EW WIPER BLADES		22-1		W	/IPER BLADE 22" T	TRICO EXACT		7.5	9 2		\$15.18
66-PM-PMA	PERFORM (ERFORM OIL CHANGE		5W30T		5'	W30 SYNTHETIC C	OIL THOMAS CA	AM2	7.4	66		\$44.73
											PARTS		70.35

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 42992

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/SH

MILEAGE-10479

UNIT NO:		243742 202	/ROLE	T EX	PRESS	S 2500		WORK OF	RDER NO	: 44	1456		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500		OPENE COMPL CLOSE Chevrole	ETED D DATI	DATE: E:	08/25/202 08/26/202	22 07:49:29 22 14:58:30 22 09:44:11	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	n: 12742 DATE:	MI 08/06/20	y Automotive S E TER 2 - N: 20 AFG6L125004	0
JOB CODE		JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL COST
03-34-002	REPLAC	E NEW LAMPS-REAR,T	AIL,STO	DON	0	Ν	GARAGE	0.08	\$9.24	\$0.96	\$0	.00	\$10.20
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL:	0.08	9	.24	0.96	5.00	15.20
Job Code		Job Description			<u>V</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u> :	se Order No	<u>0.</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1						\$5.00
												COMML	5.00
Job Code		Job Description			<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,TAIL,ST	OP,TURN	ETC 11	1901357		08.	/25/2022 08:01:51	08/25/202	2 08:06:33		0.08	\$9.24
												LABOR	9.24
Job Code		Job Description				Part No	<u>.</u>	Des	cription	<u>!</u>	Unit Price	Quantity	Total Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,TAIL,ST	OP,TURN	ETC 3	157		BU	ILB-BRAKE/TURN	I/PARK		0.96	1	\$0.9
												PARTS	0.96

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 44456

Work Order Notes

(LISAPATE) RR turn signal out

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(AGUERRA) miles: 12742 Replaced R/R blinker/brake light bulb. Checked for proper operation, all good. AMG

UNIT NO:		243742 20	20 CHEVROL	ET EX	PRESS	S 2500		WORK ORI	DER NO	: 44	4792	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500	COMP	D DAT	DATE: E:	09/26/20 09/27/20	022 09:47:20 022 15:12:41 022 07:26:13	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	13368 DATE :	M 08/06/20	ETER 2 - N:	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	<u>OMMERCIAL</u>	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	N	GARAGE	0.32	\$37.76	\$69.86	\$0	0.00	\$107.62
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00
JOB COUN	T: 2			wc	RK ORI	DER TOTAL	.: 0.32	37.7	6	69.86	5.00	112.62
Job Code		Job Description		<u> </u>	endor N	lo.	Invoice No.	<u>Purchase</u>	Order No	<u>).</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies	Ę	03163		1						\$5.0
											COMML	5.00
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fir</u>	nish_		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE	•	1901357	7	0	9/26/2022 10:06:01	09/26/2022	10:25:13		0.32	\$37.76
											LABOR	37.76
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u> </u>	Jnit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE	(5089		В	RAKE CLEAN NON	N-FLAMMABLE 14	4OZ	7.77	1	\$7.7
66-PM-PMA	PERFORM (OIL CHANGE	E	BALB160)	О	IL FILTER			5.30	1	\$5.3
66-PM-PMA	PERFORM (OIL CHANGE	Ę	W30T		5	W30 SYNTHETIC (OIL THOMAS CAN	М2	9.47	6	\$56.7
											PARTS	69.86

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 44792

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 13368 Completed PM top and bottom side. AMG/AMG

UNIT NO:		243742 2020	0 CHEVRO	LET EX	PRESS	S 2500		WORK	ORDER NO): 4	6103	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500	COM	NED DAT PLETED SED DAT olet Expre	DATE: E:	02/09/202 02/10/202	23 08:48:46 23 09:51:51 23 11:04:10	METER 1	- M: 15583 CE DATE:	M 08/06/20		0
JOB CODE		JOB DESCRIPTION	<u>STA</u>	T RSN	WRTY	JOB LOC	LABOR HRS	LABO	<u>R</u> <u>MATI</u>	ERIAL C	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	DO	N P	N	GARAGE	0.03	\$3.18	\$15.63	\$0	0.00	\$18.81
66-PM-PMA	PERFOR	RM OIL CHANGE	DO	N P	N	GARAGE	0.25	\$29.70	\$85.73	\$0	0.00	\$115.43
CH-SP	CHARGE	Shop Supplies	DO	N 2	N	GARAGE	0.00	\$0.00	\$0.00	\$3	5.00	\$5.00
JOB COUN	IT: 3			W	ORK ORI	DER TOTAL:	0.28		32.88	101.36	5.00	139.2
Job Code CH-SP	CHARGE SI	Job Description		503163	/endor N	lo. 1	Invoice No.	<u>Purc</u>	hase Order N	l <u>o.</u>		Total Cost \$5.0
		Inh December on		г.		NI-	044		Finish		COMML	5.0
Job Code 03-51-038	DEDI ACE N	Job Description IEW WIPER BLADES		<u>EI</u> 1107441	nployee 4		<u>Start</u> /09/2023 09:45:18	02/09/	Finish 2023 09:46:55		Quantity 0.03	Total Cost \$3.
66-PM-PMA		OIL CHANGE		1107441			/09/2023 09:30:00		2023 09:45:06		0.05	, -
66-PM-PMA		OIL CHANGE		1107441			/09/2023 09:23:18		2023 09:23:18		0.00	
											LABOR	32.8
Job Code		Job Description			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		BALRS4	131	BA	LDWIN AIR FILTE	₽R		17.61	1	\$17.6
66-PM-PMA	PERFORM (OIL CHANGE		BALB16)	OI	L FILTER			5.57	7 1	\$5.
03-51-038	REPLACE N	IEW WIPER BLADES		22-1		WI	PER BLADE 22"	TRICO EXAC	т	7.82	2 2	\$15.6
66-PM-PMA	PERFORM (OIL CHANGE		5W30T		5V	V30 SYNTHETIC (OIL THOMAS	CAM2	10.43	3 6	\$62.5
											PARTS	101.3

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 46103

Work Order Notes

(EHANNAH) pm-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. Needs 4 tires fronts are 2/32 and the rear are 4/32. SH

UNIT NO:		2020 CHEV	/ROLE	ET EXI	PRESS	2500		WORK O	RDER NO): 4	16105		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP250	•	COMPL CLOSE	D DATE ETED I D DATE t Expres	DATE:	02/13/202 02/13/202	23 09:52:12 23 10:57:22 23 12:23:11	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 15583 E DATE:	08/06/2	ity Automotive //ETER 2 - N: 020 GAFG6L12500	0
JOB CODE	<u> </u>	JOB DESCRIPT	<u>ION</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL (COMMERCIAL	TOTAL COST
06-15	INSPEC [*]	T STEERING		DON	0	Ν	GARAGE	0.20	\$23.76	\$0.00	\$	00.00	\$23.76
66-17-028	PERFOR	RM MOUNT AND B	BALANCE TIRE	DON	0	Ν	GARAGE	1.53	\$180.18	\$860.85	\$	60.00	\$1,041.03
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	1.73	203	3.94	860.85	5.00	1,069.79
Job Code		Job Descrip	otion_		Ve	endor N	<u>o.</u>	Invoice No.	Purcha	ıse Order N	<u>o.</u>		Total Cost
CH-SP	CHARGE S	hop Supplies		50	03163		1						\$5.00
												COMML	5.00
Job Code		Job Descrip	otion		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
06-15	INSPECT S	TEERING		1	1074414		02	/09/2023 10:02:05	02/09/20	23 10:14:10		0.20	\$23.76
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	1	1074414		02	/09/2023 10:14:22	02/09/20	23 11:45:59		1.53	\$180.18
												LABOR	203.94
Job Code		Job Descrip	<u>otion</u>			Part No	<u>.</u>	Des	cription		Unit Price	<u>Quantity</u>	Total Cost
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	2	3131		TF	MS SNAP IN VAL	VE 21060		2.1	6 4	\$8.64
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	04	450718		TII	RE GEN GRAB HE	D LT245/75R16	3	211.0	5 4	\$844.20
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	58	8107		W	HEEL WEIGHT PF	E 2.00		0.8	9 1	\$0.89
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	58	8106		1.7	75 OZ WHEEL WE	IGHT		0.8	1 5	\$4.05
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	58	8105		1.5	0 OZ WHEEL WE	EIGHT		0.8	0 2	\$1.59
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	58	8104		1.2	25 OZ WHEEL WE	IGHT		0.6	5 1	\$0.65
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	58	8103		1.0	00 OZ WHEEL WE	IGHT		0.5	7 1	\$0.57
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	5	8100		.25	OZ WHEEL WEI	GHT		0.2	61	\$0.26
												PARTS	860.85

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 46105

Work Order Notes

(EKIMBREL) 4 tires

(LISAPATE) Unit will be back for alignment no tech available at this time

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues at this time. SH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires and relearned the tire positions. SH

UNIT NO:		243742 202	20 CHEVROL	ET EX	PRES	S 2500		WORK (ORDER NO:		46315	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500	COMP	ED DAT LETED ED DAT et Expre	DATE: E:	03/06/202 03/06/202	23 08:24:26 23 09:53:13 23 13:22:03	LOCATIO METER 1 IN-SERVIO UNIT SER	- M: 15994 CE DATE:	08/06/2		0
JOB CODE	<u>E</u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABO</u>	R MATER	RIAL	COMMERCIAL	TOTAL COST
66-17-013	PERFOR	RM ALIGNMENT	DON	0	Ν	GARAGE	1.26	\$148.68	\$0.00		\$0.00	\$148.68
CH-SP	CHARGE	E Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00
JOB COUN	IT: 2			WC	RK OR	DER TOTAL:	1.26	14	48.68	0.00	5.00	153.68
Job Code		Job Description		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	Purch	nase Order No			Total Cost
CH-SP	CHARGE SI	nop Supplies	5	03163		1						\$5.00
											COMML	5.00
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-17-013	PERFORM A	ALIGNMENT	1	1310047	7	03/	03/2023 07:00:00	03/03/2	2023 08:15:36		1.26	\$148.68
09-17-013	ALIGN ALIG	NMENT	1	1310047	7	03/	01/2023 13:52:19	03/01/2	2023 15:08:04		(1.26)	(\$148.98)
09-17-013	ALIGN ALIG	NMENT	1	1310047	7	03/	01/2023 13:52:19	03/01/2	2023 15:08:04		1.26	\$148.98
											LABOR	148.68

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 46315

Work Order Notes

(CWIGLEY) Alignment

Job Notes

09-17-013 - ALIGN ALIGNMENT

(EHOWELL) Performed a front end alignment. EH

66-17-013 - PERFORM ALIGNMENT

(EKIMBREL) Performed a front end alignment. EH

UNIT NO:		2020 CHE	VROLE	ET EX	PRESS	2500		WORK OR	DER NO:	47	138			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500		OPENE COMPL CLOSE Chevrole	ETED D DATI	DATE:	05/30/202 05/31/202	23 13:27:42 23 08:18:53 23 11:34:46	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 17724 DATE :	ME 08/06/202	TER 2 - N:	0	
JOB CODE	1	JOB DESCRIPTION	<u> </u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL CO	OMMERCIAL	TOTAL	COST
03-02-017	REPLAC	E NEW DOOR PANE	LS	DON	5	Ν	GARAGE	0.44	\$52.28	\$419.90	\$0.	00	\$472.18	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
SO-05	SCAN O	JT ELECTRONIC EN	GINE EEC	DON	0	N	GARAGE	0.34	\$40.32	\$0.00	\$0.	00	\$40.32	
JOB COUN	B COUNT: 3				wo	RK ORI	DER TOTAL:	0.78	92.6	50 4	419.90	5.00		517.50
Job Code				5(<u>V</u> 03163	endor N	<u>o.</u>	Invoice No.	Purchase	e Order No.	<u>-</u>		<u>Total</u>	Cost \$5.00
011 01	OT WITTER OF	op cupplico		0.	00100		•					COMML		5.00
Job Code		Job Descriptio	<u>n</u>		<u>En</u>	ployee	No.	<u>Start</u>	<u>Fi</u>	<u>inish</u>		Quantity	Total	Cost
SO-05	SCAN OUT	ELECTRONIC ENGINE	EEC SYSTEM	<i>I</i> 1:	2052187	•	05	/24/2023 13:17:44	05/24/2023	3 13:22:14		0.08		\$8.85
SO-05	SCAN OUT	ELECTRONIC ENGINE	EEC SYSTEM	// 1:	2052187	•	05	/23/2023 13:27:46	05/23/2023	3 13:43:46		0.27		\$31.47
03-02-017	REPLACE N	EW DOOR PANELS		1:	2052187	•	05	/24/2023 12:50:59	05/24/2023	3 13:17:34		0.44		\$52.28
												LABOR		92.60
Job Code		Job Descriptio	<u>n</u>			Part No	<u> </u>	Des	cription	U	Init Price	Quantity	<u>Total</u>	Cost
03-02-017	REPLACE N	EW DOOR PANELS		84	4272272	2	DC	OOR PANEL			419.90	1		\$419.90
												PARTS		419.90

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 47138

Work Order Notes

(CWIGLEY) Service airbag message keeps popping up, per driver.

Job Notes

03-02-017 - REPLACE NEW DOOR PANELS

(JWRIGHT) Replaced driver door panel due to old one being busted. JAW

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(JWRIGHT) Scanned code b0085 05 for left front side impact sensor. Found door panel busted up with screw in it and a screw had disturbed the wiring harness to the impact sensor. Code is not active and the wiring harness is not punctured or damaged. Replaced door panel to prevent using screws in door. JAW,EH

UNIT NO:		243742 202	20 CHE	/ROLE	T EX	PRESS	S 2500		WORK C	RDER NO): 4 ⁻	7276		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500		OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE:	06/06/202 06/12/202	23 09:32:14 23 10:54:01 23 13:12:14	LOCATION METER 1 - IN-SERVIC UNIT SER	M: 18013 E DATE:	M 08/06/20	y Automotive s ETER 2 - N: 20 AFG6L125004	0	
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	ERIAL C	OMMERCIAL	TOTAL	COST
03-34-002	REPLAC	E NEW LAMPS-REAR,T	AIL,STO	DON	0	N	GARAGE	0.15	\$17.67	\$0.99	\$0	0.00	\$18.66	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL:	0.15	1	7.67	0.99	5.00		23.66
Job Code		Job Description			<u>v</u>	endor N	lo.	Invoice No.	Purch	ase Order N	l <u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,TAIL,S	ΓΟΡ,TURN	,ETC 1	1074414		06/	/06/2023 09:48:29	06/06/20	023 09:57:28		0.15		\$17.67
												LABOR		17.67
Job Code		Job Description				Part No	<u>.</u>	Des	cription		Unit Price	Quantity	<u>Total</u>	Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,TAIL,S	TOP,TURN	ETC 3	157		BU	ILB-BRAKE/TURN	I/PARK		0.99	1		\$0.99
												PARTS	- <u>-</u>	0.99

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 47276

Work Order Notes

(EHANNAH) LR taillight is out. please check.

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(SHARBIN) Replaced the left rear turn/brake light bulb per customer request. Rechecks good. SH

06-34-011 - INSPECT TAILLIGHT ASSEMBLY

UNIT NO: 243742 2020			CHEVROL	ET EX	PRESS	S 2500		WORK ORDER NO: 47			526		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500	COMP	ED DAT LETED ED DAT et Expre	DATE:	07/06/202 07/06/202	23 08:08:05 23 09:35:05 23 10:42:39	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 18693 E DATE :	ME 08/06/202		0	
JOB CODE	Ī	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL C	OST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.07	\$8.52	\$16.65	\$0.	00	\$25.17	
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.16	\$18.78	\$53.79	\$0.	00	\$72.57	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
WA-00	WASH C	OMPLETE VEHICLE	DON	Р	N	GARAGE	0.04	\$4.65	\$0.00	\$0.	00	\$4.65	
JOB COUN	IT: 4			wo	ORK ORI	DER TOTAL:	0.27	31	.95	70.44	5.00	1	107.39
Job Code		Job Description		7	endor N	<u>lo.</u>	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		Total Co	<u>ost</u>
CH-SP	CHARGE SI	nop Supplies		503163		1							\$5.00
											COMML		5.00
Job Code		Job Description		<u>E</u> r	nployee	No.	<u>Start</u>	ļ	Finish		Quantity	Total Co	<u>ost</u>
03-51-038	REPLACE N	IEW WIPER BLADES		11074414	4	07/	/05/2023 08:38:12	07/05/202	23 08:42:32		0.07		\$8.52
WA-00	WASH COM	IPLETE VEHICLE		1220126	7	07/	/05/2023 08:39:19	07/05/202	23 08:41:41		0.04		\$4.65
66-PM-PMA	PERFORM (OIL CHANGE		1220126	7	07/	/05/2023 08:29:25	07/05/202	23 08:38:58		0.16		\$18.78
											LABOR		31.95
Job Code		Job Description			Part No	<u>.</u>	Des	<u>cription</u>		Unit Price	Quantity	Total Co	<u>ost</u>
66-PM-PMA	PERFORM (OIL CHANGE		5W30T		5W	/30 SYNTHETIC (OIL THOMAS C	AM2	8.03	6		\$48.15
03-51-038	REPLACE N	IEW WIPER BLADES		22-1		WI	PER BLADE 22" 1	TRICO EXACT		8.33	2		\$16.65
66-PM-PMA	PERFORM (OIL CHANGE		BALB160)	OII	FILTER			5.64	1		\$5.64
											PARTS		70.44

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 47526

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced the wipers. sh

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,SH, Changed oil and oil filter, checked fluids, filter good, tires and tire pressure. Miles, 18,693

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Vehicle was clean-GC

UNIT NO: 243742 202			O CHEVRO	ET EX	PRES	S 2500		WORK OF	RDER NO:	48264	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504104 CLOSED SCHEDULED 20CHEVEXP2500	COM	IED DAT PLETED SED DAT let Expre	DATE:	09/20/202 09/22/202	09/22/2023 09:37:30			ersity Automotive S METER 2 - N: 5/2020 WGAFG6L125004	0
JOB CODE		JOB DESCRIPTION	STA [*]	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-017	REPLAC	E NEW DOOR PANELS	DON	0	N	GARAGE	0.40	\$47.20	\$419.90	\$0.00	\$467.10
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
JOB COUN	T: 2			wo	ORK ORI	DER TOTAL:	0.40	47.	20 419.90	5.00	472.10
Job Code		Job Description		7	/endor N	<u>lo.</u>	Invoice No.	<u>Purchas</u>	e Order No.		Total Cost
CH-SP	CHARGE Sh	nop Supplies		503163		1					\$5.00
										COMML	5.00
Job Code		Job Description		<u>Er</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>	Quantity	Total Cost
03-02-017	REPLACE N	EW DOOR PANELS		1131004	7	09	/20/2023 14:39:53	09/20/202	3 15:03:53	0.40	\$47.20
										LABOR	47.20
Job Code		Job Description			Part No) <u>.</u>	Des	cription	<u>Unit Pr</u>	ice Quantity	Total Cost
03-02-017	REPLACE N	EW DOOR PANELS		8427227	2	DC	OOR PANEL		419	9.901	\$419.90
										PARTS	419.90

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 48264

Work Order Notes

(EKIMBREL) replace driver door panel

Job Notes

03-02-017 - REPLACE NEW DOOR PANELS

(EKIMBREL) eh replaced driver door panel

UNIT NO:	NO: 243742 2020 CHE				ET EX	PRESS	S 2500		WORK ORDER NO: 49			49021			
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500 2		OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE:	11/22/202 11/22/202	23 12:54:02 23 08:39:46 23 09:45:37	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 21845 DATE :	08/06/	METER 2020	omotive S 2 - N : L125004	0	
JOB CODE	_	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL	СОММІ	ERCIAL	TOTAL	COST
03-13-001	REPLAC	E NEW FRONT BRAKES & I	ROT	DON	N	N	GARAGE	1.61	\$190.47	\$275.20		\$0.00		\$465.67	
06-13	INSPECT	BRAKES		DON	N	Ν	GARAGE	0.29	\$33.86	\$0.00		\$0.00		\$33.86	
66-13-130	PERFOR	M Burnish Brakes		DON	N	N	GARAGE	0.38	\$45.23	\$0.00		\$0.00		\$45.23	
66-17-013	PERFOR	M ALIGNMENT		DON	Ν	Ν	GARAGE	0.56	\$66.57	\$0.00		\$0.00		\$66.57	
66-17-033	PERFOR	M TIRE ROTATION AND BR	RAKE	DON	Р	N	GARAGE	0.03	\$3.74	\$0.00		\$0.00		\$3.74	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.21	\$24.62	\$50.46		\$0.00		\$75.08	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00		\$5.00	
JOB COUN	IT: 7				WC	RK ORI	DER TOTAL	: 3.09	364.4	9	325.66		5.00		695.15
Job Code		Job Description			<u>v</u>	endor N	lo.	Invoice No.	Purchase	e Order N	<u>o.</u>			<u>Total</u>	l Cost
CH-SP	CHARGE Sh	nop Supplies		5	03163		1								\$5.00
												C	OMML		5.00
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	<u>nish</u>		<u>Qı</u>	uantity	<u>Total</u>	l Cost
66-PM-PMA	PERFORM (DIL CHANGE		1	2395904	4	11	/21/2023 15:39:22	11/21/2023	15:51:53			0.21		\$24.62
03-13-001	REPLACE N	EW FRONT BRAKES & ROTOF	RS	1	2052187	7	11	/21/2023 12:30:44	11/21/2023	14:07:35			1.61		\$190.47
06-13	INSPECT BE	RAKES		1	2052187	7	11	/21/2023 10:01:24	11/21/2023	10:03:36			0.04		\$4.33
06-13	INSPECT BE	RAKES		1	2052187	7	11	/21/2023 08:55:53	11/21/2023	09:10:54			0.25		\$29.53
66-13-130	PERFORM E	Burnish Brakes		1	2052187	7	11	/21/2023 14:07:46	11/21/2023	14:30:46			0.38		\$45.23
66-17-033	PERFORM	TIRE ROTATION AND BRAKE IN	NSPE	CTION 1	2052187	7	11	/21/2023 14:30:57	11/21/2023	14:32:51			0.03		\$3.74
66-17-013	PERFORM A	ALIGNMENT		1	2052187	7	11	/21/2023 14:33:00	11/21/2023	15:06:51			0.56		\$66.57
												L	ABOR		364.49
Job Code		Job Description				Part No	<u>.</u>	Des	cription		Unit Pric	ce Qu	uantity	<u>Total</u>	l Cost
03-13-001	REPLACE N	EW FRONT BRAKES & ROTOF	RS	С	111		RI	ED BRAKE CLEAN	IER		6.	44	1		\$6.44
66-PM-PMA	PERFORM (OIL CHANGE		5	W30T		5V	W30 SYNTHETIC (OIL THOMAS CA	M2	7.	.47	6		\$44.82
66-PM-PMA FleetFocus M5		OIL CHANGE - Work Order Detail v20.0		В	ALB160)	OI	IL FILTER			5.	64	1		\$5.64 Page:1

The University of Alabama

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	56829R	DISC BRAKE ROTOR	104.78	2	\$209.55
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR17784	FRONT BRAKE PADS	59.21	1	\$59.21
					PARTS	325.66

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 49021

Work Order Notes

(EHANNAH) RF tire is wearing on the outside- shaking while driving 50 mph

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(JWRIGHT) Replaced front brake pads and rotors. JAW

06-13 - INSPECT BRAKES

(JWRIGHT) Inspected brakes and test drove. Needs front pads and rotors replaced. Also noticed slight pulling to the right. Will also need alignment. JAW

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-13-130 - PERFORM Burnish Brakes

(JWRIGHT) Burnished brakes. No issues. JAW

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Checked alignment. Found no issues, no adjustments made. Was previously pulling to the right due to low air in right tire. Normal tire wear on front. JAW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Rear brakes are 10mm. Front rotors are wharped bad and pads are 7mm. JAW

66-PM-PMA - PERFORM OIL CHANGE

UNIT NO:	2020 CHEV	/ROLE	T EX	PRESS	2500		WORK ORDER NO: 49			050				
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504104 CLOSED SCHEDULED 20CHEVEXP2500		OPENE COMPL CLOSE Chevrole	ETED D DATI	DATE:	11/30/202 12/01/202	3 08:47:41 3 09:39:00 23 11:40:08	LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL	21845 PATE:	ME 08/06/202	TER 2 - N:	0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL CO	OMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY		DON	N	Ν	GARAGE	0.15	\$17.44	\$199.98	\$0.	00	\$217.42	
66-79-002	PERFOR	M SERVICE CALL		DON	В	Ν	GARAGE	0.08	\$8.88	\$0.00	\$0.	00	\$8.88	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.22	26.32	2 1	199.98	5.00		231.30
Job Code CH-SP	CHARGE SI	Job Descripti	<u>on</u>	50	V 03163	endor N	<u>o.</u> 1	Invoice No.	<u>Purchase</u>	Order No.	1		<u>Total</u>	Cost \$5.00
												COMML		5.00
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u>Fin</u>	<u>iish</u>		Quantity	<u>Total</u>	Cost
66-79-002	PERFORM	SERVICE CALL		11	1074414		11/	27/2023 09:51:19	11/27/2023 (09:55:50		0.08		\$8.88
03-32-002	REPLACE N	EW BATTERY		12	2201267	•	11/	27/2023 09:30:00	11/27/2023 (09:38:52		0.15		\$17.44
03-32-002	REPLACE N	EW BATTERY		12	2201267	•	11/	27/2023 09:20:13	11/27/2023 (09:20:13		0.00		\$0.00
												LABOR		26.32
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	cription	U	nit Price	Quantity	<u>Total</u>	Cost
03-32-002	REPLACE N	EW BATTERY		78	31		ВА	TTERY BCI 78 77	0 CCA		199.98	1		\$199.98
												PARTS		199.98

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 49050

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GRCOOK) Installed new battery in unit 5898A, checked new battery volts after installing, volts, 14.60 -11-27-23-GC

06-32-002 - INSPECT BATTERY

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Performed a service call to Capitol Hall for a dead battery. Jumped vehicle off and the driver was coming to the shop to get the battery replaced. SH

UNIT NO: 243742			020 CHEVR	TEX	PRESS	2500		WORK OR	DER NO:	50	650			
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504104 CLOSED SCHEDULED 20CHEVEXP2500	co	MPL OSE	D DATI ETED I D DATI t Expre	DATE: E:	04/23/202 04/24/202	24 08:53:33 24 15:03:25 24 09:12:59	LOCATION: GARAGE METER 1 - M: 25563 IN-SERVICE DATE: UNIT SERIAL NO:		ME 08/06/202	TER 2 - N:	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>l S</u>	<u>TAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL CO	MMERCIAL	TOTAL (COST
66-PM-PMA	PERFOR	RM OIL CHANGE	D	ON	Р	Ν	GARAGE	0.01	\$1.57	\$52.28	\$0.	00	\$53.85	
CH-SP	CHARGE	Shop Supplies	D	ON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
WA-00	WASH C	OMPLETE VEHICLE	D	ON	Р	N	GARAGE	0.36	\$41.89	\$0.00	\$0.	00	\$41.89	
JOB COUN	IT: 3				wo	RK ORE	ER TOTAL:	0.37	43.4	16	52.28	5.00		100.74
Job Code	0114505.01	Job Description	<u>n</u>	=-		endor N	_	Invoice No.	<u>Purchas</u>	e Order No.	<u>.</u>		Total (
CH-SP	CHARGE SI	nop Supplies		50	3163		1					COMML		\$5.00 5.00
Job Code		Job Description	<u>n</u>		Em	ployee	No.	<u>Start</u>	F	inish		Quantity	Total (Cost
66-PM-PMA	PERFORM (OIL CHANGE		12	395904	•	04	/22/2024 11:20:35	04/22/2024	11:21:23		0.01		\$1.57
WA-00	WASH COM	PLETE VEHICLE		12	395904		04	/22/2024 11:21:50	04/22/2024	11:43:08		0.36		\$41.89
												LABOR		43.46
Job Code		Job Description	<u>n</u>			Part No		Des	cription	<u>U</u>	nit Price	Quantity	Total (<u>Cost</u>
66-PM-PMA	PERFORM (OIL CHANGE		5V	V30T		5W	/30 SYNTHETIC (OIL THOMAS CA	M2	7.77	6		\$46.62
66-PM-PMA	PERFORM (OIL CHANGE		B	ALB160		OII	L FILTER			5.66	1		\$5.66
												PARTS		52.28

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 50650

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

UNIT NO:		243742 20	20 CHE	VROLE	T EX	PRESS	2500		WORK OF	RDER NO:	51082	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504104 CLOSED SCHEDULED 20CHEVEXP2500	ED CL			DATE: E:	06/07/202 06/07/202	4 14:44:36 4 08:49:57 4 10:26:21			iversity Automotive (METER 2 - N: /06/2020 GCWGAFG6L125004	0
JOB CODE		JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DI	SPOSE PREPARE UNI	T FOR DI	DON	D	N	GARAGE	0.06	\$7.51	\$0.00	\$0.00	\$7.51
JOB COUN	T: 2				wo	RK ORE	ER TOTAL:	0.06	7.	51 0.	.00 5.00	12.51
Job Code		Job Description			<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	e Order No.		Total Cost
CH-SP	CHARGE SI	hop Supplies		50	03163		1					\$5.00
											COMML	5.00
Job Code		Job Description			<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>	Quantity	Total Cost
PD-00-999	PREP DISP	OSE PREPARE UNIT FOR	DISPOSAL	L 1:	12395904			07/2024 08:19:12	06/07/2024 08:23:01		0.06	\$7.51
											LABOR	7.51

The University of Alabama

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

UNIT NO: 243742 2020 CHEVROLET EXPRESS 2500 WORK ORDER NO: 51082

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) perform prepare unit for disposal and remove GPS fc

Report Printed: 06/20/2024 15:00:19 By User: GLOBETTI

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Thu Jun 20 2024 15:00:19 Report User: GLOBETTI

TZ: Central Standard Time

DLL Version: 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'243742') //Q=