

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 28168

USING DEPT NO: 507121	OPENED DATE: 11/15/2017 15:48:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/30/2018 15:03:09	METER 1 - M: 57 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/30/2018 15:03:11	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11170580	11/15/2017 15:49:27	11/15/2017 16:19:27	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 28168

Work Order Notes

(LISAPATE) NEW UNIT DO PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID WORK ORDER NO: 29285

USING DEPT NO:	507121	OPENED DATE:	04/02/2018 13:25:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/05/2018 06:41:52	METER 1 - M:	4825	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/05/2018 06:41:53	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$49.78	\$0.00	\$67.61

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 49.78 0.00 67.61

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/02/2018 15:07:49	04/02/2018 15:26:25	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.23	1	\$8.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.31	5	\$41.55
					PARTS	49.78

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 29285

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY RC/AH
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID WORK ORDER NO: 29636

USING DEPT NO:	507121	OPENED DATE:	05/01/2018 09:04:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/07/2018 06:41:05	METER 1 - M:	8330	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/07/2018 06:41:08	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$49.70	\$0.00	\$67.53

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 49.70 0.00 67.53

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	05/02/2018 07:00:00	05/02/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.31	5	\$41.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.15	1	\$8.15
					PARTS	49.70

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 29636

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 5/1/2018 9:04 AM By LISAPATE

(LISAPATE) PM BY EK/CS

COOLANT -35'

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 30120

USING DEPT NO: 507121	OPENED DATE: 06/27/2018 09:22:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/27/2018 15:27:05	METER 1 - M: 12094 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/27/2018 15:27:07	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$49.58	\$0.00	\$67.41

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **49.58** **0.00** **67.41**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/27/2018 13:16:07	06/27/2018 13:34:43	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.29	5	\$41.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.11	1	\$8.11
					PARTS	49.58

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 30120

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY RC/AG
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 30573

USING DEPT NO: 507121	OPENED DATE: 08/16/2018 09:13:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/21/2018 07:38:33	METER 1 - M: 15012 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/21/2018 07:38:34	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **46.00** **46.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	256217	0044686	\$46.00
COMML					46.00

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 30573

Work Order Notes

(LISAPATE) LARGE DING IN WINDSHIELD

Job Notes

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) GLASS DR REPAIRED DING IN WINDSHIELD. PD BY CC

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 30670

USING DEPT NO: 507121	OPENED DATE: 08/27/2018 13:52:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/28/2018 11:37:25	METER 1 - M: 16012 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/28/2018 11:37:25	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.93	\$0.00	\$59.76

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **41.93** **0.00** **59.76**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/28/2018 06:00:00	08/28/2018 06:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	4	\$33.84
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.09	1	\$8.09
					PARTS	41.93

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 30670

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AJONES) PM BY RC,EK/SH
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 31752

USING DEPT NO:	507121	OPENED DATE:	12/14/2018 08:41:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2018 09:40:35	METER 1 - M:	23466	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2018 09:40:36	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$42.39	\$0.00	\$64.87

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	22.48	42.39	0.00	64.87
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2018 11:37:09	12/14/2018 13:55:43	2.31	\$167.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2018 11:37:09	12/14/2018 13:55:43	(2.31)	(\$167.43)
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2018 11:37:09	12/14/2018 11:55:45	0.31	\$22.48
					LABOR	22.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.58	4	\$34.32
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.07	1	\$8.07
					PARTS	42.39

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 31752

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 32379

USING DEPT NO: 507121	OPENED DATE: 03/18/2019 10:14:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/21/2019 15:19:02	METER 1 - M: 30647 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/21/2019 15:19:03	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$29.00	\$232.99	\$0.00	\$261.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.90	\$137.55	\$50.30	\$0.00	\$187.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.19	\$13.59	\$45.53	\$0.00	\$59.12

JOB COUNT: 4	WORK ORDER TOTAL:	3.48	252.64	328.82	0.00	581.46
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/18/2019 11:40:16	03/18/2019 11:55:14	0.25	\$18.08
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/18/2019 13:02:29	03/18/2019 13:36:15	0.56	\$40.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	03/18/2019 13:36:37	03/18/2019 13:47:52	0.19	\$13.59
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/18/2019 13:00:32	03/18/2019 14:05:38	1.09	\$78.66
09-15	ALIGN STEERING	11310047	03/19/2019 07:00:00	03/19/2019 08:00:00	1.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/19/2019 06:00:00	03/19/2019 06:24:00	0.40	\$29.00
					LABOR	252.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.63	5	\$43.13
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.17	1	\$7.17
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800208CTYC	CABIN AIR FILTER	45.53	1	\$45.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	003196	TIRE 205/65R16 F/S FT140 94H	112.59	2	\$225.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.40	3	\$1.21
					PARTS	328.82

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 32379

Work Order Notes

(LISAPATE) PM

Job Notes

09-15 - ALIGN STEERING

(LISAPATE) EH performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced 2 new front tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID WORK ORDER NO: 33479

USING DEPT NO:	507121	OPENED DATE:	07/18/2019 13:35:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2019 09:22:40	METER 1 - M:	41135	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	07/22/2019 09:22:42	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$29.00	\$7.67	\$0.00	\$36.67

JOB COUNT: 1 WORK ORDER TOTAL: 0.40 29.00 7.67 0.00 36.67

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	07/19/2019 07:00:00	07/19/2019 07:24:00	0.40	\$29.00
					LABOR	29.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.32	1	\$3.32
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	2	\$0.84
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.51	1	\$3.51
					PARTS	7.67

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 33479

Work Order Notes

(EKIMBREL) LR tire is leaking air

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) AG repaired and balanced LR tire. Rechecked for leak, all good.

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID WORK ORDER NO: 33891

USING DEPT NO:	507121	OPENED DATE:	08/28/2019 08:44:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2019 08:30:09	METER 1 - M:	44575	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2019 08:30:10	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$10.23	\$35.79	\$0.00	\$46.02

JOB COUNT: 1 WORK ORDER TOTAL: 0.14 10.23 35.79 0.00 46.02

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/28/2019 10:36:39	08/28/2019 10:45:07	0.14	\$10.23
					LABOR	10.23

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.54	1	\$6.54
					PARTS	35.79

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 33891

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW
Coolant -35'

***Previous oil change was done at Express Oil Change

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID**

WORK ORDER NO: 34323

USING DEPT NO: 507121	OPENED DATE: 10/03/2019 08:51:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/07/2019 14:03:51	METER 1 - M: 48467 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/07/2019 14:03:53	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.59	\$115.34	\$35.70	\$0.00	\$151.04	
JOB COUNT: 1						WORK ORDER TOTAL:	1.59	115.34	35.70	0.00	151.04

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/03/2019 13:35:22	10/03/2019 15:56:15	2.35	\$170.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/03/2019 13:35:22	10/03/2019 14:23:22	0.80	\$58.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/03/2019 13:35:42	10/03/2019 14:23:09	0.79	\$57.34
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/03/2019 13:35:22	10/03/2019 15:56:15	(2.35)	(\$170.23)
					LABOR	115.34

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.52	1	\$6.52
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.26	(1)	(\$6.26)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.26	1	\$6.26
					PARTS	35.70

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 34323

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) EK,SH/JW. Coolant -35

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 34788

USING DEPT NO: 507121	OPENED DATE: 11/08/2019 10:05:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/12/2019 13:10:08	METER 1 - M: 52622 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/12/2019 13:10:10	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$25.58	\$0.00	\$43.71
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.01	\$0.54	\$0.00	\$0.00	\$0.54
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.74	\$53.39	\$0.00	\$0.00	\$53.39
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.27	\$92.36	\$580.50	\$0.00	\$672.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.96	\$69.52	\$62.59	\$0.00	\$132.11

JOB COUNT: 5	WORK ORDER TOTAL:	3.23	233.94	668.67	0.00	902.61
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/08/2019 13:22:30	11/08/2019 13:22:44	0.00	\$0.28
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/08/2019 13:22:30	11/08/2019 13:22:44	0.00	(\$0.28)
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/08/2019 13:22:30	11/08/2019 13:37:30	0.25	\$18.13
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/08/2019 13:28:22	11/08/2019 14:00:00	0.53	\$38.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	11/08/2019 13:24:32	11/08/2019 14:09:20	0.75	\$54.13
06-15	INSPECT STEERING	12052187	11/08/2019 14:48:25	11/08/2019 14:48:52	0.01	\$0.54
09-15	ALIGN STEERING	11310047	11/08/2019 14:09:04	11/08/2019 14:15:00	0.10	\$7.17
09-15	ALIGN STEERING	11310047	11/08/2019 14:30:00	11/08/2019 15:08:15	0.64	\$46.22
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/08/2019 11:09:09	11/08/2019 12:00:00	0.85	\$61.44
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/08/2019 11:21:17	11/08/2019 11:27:58	0.11	\$8.08
					LABOR	233.93

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.52	1	\$6.52
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	200807	AIR FILTER	20.45	1	\$20.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	141.38	4	\$565.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.45	4	\$1.80
					PARTS	668.67

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 34788

Work Order Notes

(LISAPATE) PM-Check tire balance car shakes and shimmy's at high speeds

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) Replaced wiper blades

06-15 - INSPECT STEERING

(EKIMBREL) Checked front end.

09-15 - ALIGN STEERING

(EKIMBREL) Performed alignment

66-17-017 - PERFORM BALANCE TIRES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) Mounted and balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/AG. Coolant -34

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 34839

USING DEPT NO: 507121	OPENED DATE: 11/13/2019 09:14:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/22/2019 08:18:29	METER 1 - M: 54226 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/22/2019 08:18:31	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,026.89	\$1,026.89

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **1,026.89** **1,026.89**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	270244		\$1,026.89
				COMML	1026.89

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 34839

Work Order Notes

(LISAPATE) Mario requested a new windshield

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr came to the shop and installed a new windshield. PD by CC

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 35198

USING DEPT NO: 507121	OPENED DATE: 12/16/2019 09:29:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/17/2020 13:17:29	METER 1 - M: 55849 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/17/2020 13:17:30	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.40	\$29.00	\$0.00	\$0.00	\$29.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,518.24	\$2,518.24
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.40** **101.50** **0.00** **2,518.24** **2,619.74**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	168780		(\$2,000.00)
24-71	REPAIR BODY	11150605	168780		\$2,000.00
24-71	REPAIR BODY	11150605	168780		\$518.24
24-71	REPAIR BODY	11150605	168780		\$2,000.00
COMML					2518.24

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11213180	01/10/2020 00:00:00	01/10/2020 01:00:00	1.00	\$72.50
24-71	REPAIR BODY	11213180	01/10/2020 07:00:00	01/10/2020 08:00:00	(1.00)	(\$72.50)
16-71	TRANSPORT BODY	11915538	01/10/2020 07:00:00	01/10/2020 07:24:00	0.40	\$29.00
24-71	REPAIR BODY	11213180	01/10/2020 07:00:00	01/10/2020 08:00:00	1.00	\$72.50
LABOR						101.50

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 35198

Work Order Notes

(LISAPATE) Take to Andrews to repair front end damage unit hit a dog

Job Notes

16-71 - TRANSPORT BODY

(EKIMBREL) RC transported vehicle to and from body shop.

24-71 - REPAIR BODY

(EKIMBREL) Andrews Paint & Body repaired body. Bumper, Right fender

(RWINTERS) A/S PAID DEDUCTIBLE AND INS. CHARGES. STATE AUTO TO CUT CHECK TO FLEET FOR \$518.24

66-17-013 - PERFORM ALIGNMENT

(EKIMBREL) MS performed alignment.

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 35522

USING DEPT NO:	507121	OPENED DATE:	01/29/2020 07:12:21	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/04/2020 08:52:55	METER 1 - M:	57043	METER 2 - H:	0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/04/2020 08:52:57	IN-SERVICE DATE:	11/11/2017		
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.06	\$76.85	\$39.59	\$0.00	\$116.44

JOB COUNT: 1	WORK ORDER TOTAL:					1.06	76.85	39.59	0.00	116.44
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2020 13:00:00	01/29/2020 13:26:59	0.45	\$32.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2020 12:59:40	01/29/2020 12:59:40	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2020 11:18:43	01/29/2020 11:55:20	0.61	\$44.25
					LABOR	76.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.62	5	\$33.08
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
					PARTS	39.59

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 35522

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID WORK ORDER NO: 36343

USING DEPT NO:	507121	OPENED DATE:	05/07/2020 10:26:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/07/2020 13:52:36	METER 1 - M:	60963	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2020 09:24:40	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.70	\$50.85	\$36.05	\$0.00	\$86.90

JOB COUNT: 1 WORK ORDER TOTAL: 0.70 50.85 36.05 0.00 86.90

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/07/2020 11:09:48	05/07/2020 11:51:53	0.70	\$50.85
					LABOR	50.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.91	5	\$29.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	36.05

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 36343

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/SH performed pm. Coolant -35

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 36929

USING DEPT NO:	507121	OPENED DATE:	06/23/2020 11:32:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/24/2020 07:44:45	METER 1 - M:	60964	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/24/2020 09:35:51	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.30	\$21.51	\$186.47	\$0.00	\$207.98
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.63	\$45.72	\$0.00	\$0.00	\$45.72

JOB COUNT: 2 **WORK ORDER TOTAL: 0.93 67.23 186.47 0.00 253.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	06/23/2020 14:58:50	06/23/2020 15:16:38	0.30	\$21.51
66-79-002	PERFORM SERVICE CALL	12052187	06/23/2020 13:13:21	06/23/2020 13:51:11	0.63	\$45.72
					LABOR	67.23

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	H5AGM	BATTERY DIN H5 AGM 345 CCA	185.21	1	\$185.21
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.63	2	\$1.26
					PARTS	186.47

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 36929

Work Order Notes

(LISAPATE) Erica requested a service call to Fleet battery is dead

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced new battery. installed terminal washer. charging at 14.2 volts. JAW

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) jumped car off and brought back to shop to charge.

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 37382

USING DEPT NO: 507121	OPENED DATE: 08/19/2020 07:25:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/20/2020 09:55:39	METER 1 - M: 60970 METER 2 - H: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 08/21/2020 10:34:00	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	W	J	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11074414	08/20/2020 06:00:00	08/20/2020 06:30:00	0.50	\$36.25
03-32-002	REPLACE NEW BATTERY	11074414	08/20/2020 06:00:00	08/20/2020 06:30:00	0.50	\$36.25
03-32-002	REPLACE NEW BATTERY	11074414	08/20/2020 06:00:00	08/20/2020 06:30:00	(0.50)	(\$36.25)
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 37382

Work Order Notes

(LISAPATE) Per Fleet unit has a dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Visit Reason Changed On 8/20/2020 9:53 AM By LISAPATE

(LISAPATE) Battery was removed and replaced under warranty from Advance invoice 5946 battery H5AGM \$123.47

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 37614

USING DEPT NO: 507121	OPENED DATE: 09/15/2020 13:48:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/21/2020 07:57:06	METER 1 - M: 60971 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/21/2020 13:39:13	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.14	\$10.27	\$0.00	\$0.00	\$10.27

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.14** **10.27** **0.00** **0.00** **10.27**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11074414	09/17/2020 07:44:21	09/17/2020 07:52:51	0.14	\$10.27
					LABOR	10.27

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 37614

Work Order Notes

(LISAPATE) Per Donald battery is dead again just replaced 8-19-20

Job Notes

CH-32-002 - CHARGE BATTERY

(SHARBIN) Charged battery rechecked good. ALT charging at 14.2. vehicle had not been driven since new battery was installed. SH

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 37878

USING DEPT NO: 507121	OPENED DATE: 10/05/2020 14:47:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/06/2020 11:51:51	METER 1 - M: 60971 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2020 12:28:45	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.32	\$0.00	\$0.00	\$36.32

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **36.32** **0.00** **0.00** **36.32**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/06/2020 11:30:46	10/06/2020 11:49:14	0.31	\$36.32
					LABOR	36.32

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 37878

Work Order Notes

(LISAPATE) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 9 miles since last PM. Checked fluids,battery,tire pressure and updated oil change sticker.SH

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID WORK ORDER NO: 39146

USING DEPT NO:	507121	OPENED DATE:	02/19/2021 10:47:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2021 08:33:17	METER 1 - M:	61905	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2021 11:24:15	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.04	\$4.33	\$0.00	\$0.00	\$4.33

JOB COUNT: 1 WORK ORDER TOTAL: 0.04 4.33 0.00 0.00 4.33

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	02/22/2021 07:11:04	02/22/2021 07:13:16	0.04	\$4.33
					LABOR	4.33

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 39146

Work Order Notes

(LISAPATE) Remove all wordmarks car is going to another Dept

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(GARAGE) Removed all wordmarks RC

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 39638

USING DEPT NO: 507121	OPENED DATE: 04/12/2021 15:33:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/14/2021 10:33:51	METER 1 - M: 65844 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/14/2021 14:02:00	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.09	\$10.46	\$0.00	\$0.00	\$10.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.01	\$118.89	\$54.93	\$0.00	\$173.82

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.10** **129.35** **54.93** **0.00** **184.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/13/2021 09:38:31	04/13/2021 10:15:45	0.62	\$73.23
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/13/2021 10:22:00	04/13/2021 10:27:19	0.09	\$10.46
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/13/2021 09:50:26	04/13/2021 10:13:39	0.39	\$45.66
					LABOR	129.35

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	19200	WIPER BLADE OE BEAM STYLE 20IN	8.84	1	\$8.84
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	19260	WIPER BLADE 26 IN OE BEAM	10.41	1	\$10.41
					PARTS	54.93

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 39638

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wiper blades due to normal wear. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 65844 Completed PM top side, Scott was bottom side. AMG/SH Completed checklist. AMG

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 40084

USING DEPT NO: 507121	OPENED DATE: 06/02/2021 11:37:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/04/2021 09:21:38	METER 1 - M: 68291 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/04/2021 14:08:06	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.09	\$10.10	\$0.00	\$0.00	\$10.10
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.51	\$60.57	\$0.00	\$0.00	\$60.57
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.48	\$56.54	\$291.27	\$0.00	\$347.81

JOB COUNT: 3	WORK ORDER TOTAL:	1.08	127.21	291.27	0.00	418.48
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11310047	06/02/2021 13:00:00	06/02/2021 13:05:08	0.09	\$10.10
06-15	INSPECT STEERING	11310047	06/02/2021 12:10:31	06/02/2021 12:10:31	0.00	\$0.00
09-15	ALIGN STEERING	11310047	06/03/2021 10:22:57	06/03/2021 10:53:45	0.51	\$60.57
09-15	ALIGN STEERING	11310047	06/03/2021 12:02:02	06/03/2021 12:02:02	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	06/03/2021 09:47:18	06/03/2021 10:16:03	0.48	\$56.54
					LABOR	127.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	141.38	2	\$282.75
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	4	\$1.92
					PARTS	291.27

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 40084

Work Order Notes

(LISAPATE) Per driver hit a pothole. Steering is pulling to the right

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH

09-15 - ALIGN STEERING

(EHOWELL) Performed a road test before the alignment. The toe was out of spec. Performed Alignment. Reset steering angle sensor using code link. EH/MS Performed road test after repairs.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced rear tires and aired to spec. Sh balanced. Rotated tires to the front. Torqued lugs to spec. JAW,SH

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 40224

USING DEPT NO:	507121	OPENED DATE:	06/22/2021 08:38:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:54:43	METER 1 - M:	70000	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2021 14:54:46	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$98.96	\$43.58	\$0.00	\$142.54

JOB COUNT: 1 **WORK ORDER TOTAL: 0.84 98.96 43.58 0.00 142.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2021 12:14:44	06/22/2021 12:49:58	0.59	\$69.29
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/22/2021 10:53:59	06/22/2021 11:09:04	0.25	\$29.66
					LABOR	98.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	1	\$9.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
					PARTS	43.58

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 40224

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW
MILEAGE-70845

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 40853

USING DEPT NO: 507121	OPENED DATE: 08/26/2021 09:23:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/30/2021 13:46:58	METER 1 - M: 74938 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/30/2021 15:53:22	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$17.90	\$0.00	\$29.70
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$28.91	\$0.00	\$0.00	\$28.91
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.94	\$111.38	\$0.00	\$0.00	\$111.38
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.77	\$90.30	\$279.90	\$0.00	\$370.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.72	\$39.86	\$0.00	\$46.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.11	249.11	337.66	2.00	588.77
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/30/2021 07:00:00	08/30/2021 07:06:00	0.10	\$11.80
09-15	ALIGN STEERING	11310047	08/30/2021 09:37:32	08/30/2021 10:34:10	0.94	\$111.38
06-15	INSPECT STEERING	11074414	08/27/2021 11:32:34	08/27/2021 11:47:16	0.25	\$28.91
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/27/2021 11:27:46	08/27/2021 11:31:11	0.06	\$6.72
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/27/2021 10:41:36	08/27/2021 11:27:31	0.77	\$90.30
					LABOR	249.11

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.08	5	\$30.38
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.48	1	\$9.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.31	2	\$8.61
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	2	\$0.99

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	(1)	(\$10.71)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	135.15	2	\$270.30
					PARTS	337.66

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 40853

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers AB

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues. SH

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires put new tires on the front. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 74938. Performed PM AB Top side SH bottom side.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 41721

USING DEPT NO: 507121	OPENED DATE: 11/29/2021 09:24:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/01/2021 10:53:23	METER 1 - M: 79153 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 12/02/2021 12:28:29	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.11	\$13.37	\$17.90	\$0.00	\$31.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.52	\$38.42	\$0.00	\$66.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.36	41.89	56.32	2.00	100.21
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/29/2021 15:32:55	11/29/2021 15:39:43	0.11	\$13.37
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/29/2021 15:18:23	11/29/2021 15:32:53	0.24	\$28.52
LABOR					41.89	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24
PARTS					56.32	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 41721

Work Order Notes

(IFALLS) PM Scott Gilliam 205-792-4802

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. AMG,RC/JAW
MILEAGE-79153

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 42010

USING DEPT NO: 507121	OPENED DATE: 01/07/2022 10:58:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/10/2022 14:15:25	METER 1 - M: 79665 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/10/2022 14:15:29	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid		UNIT SERIAL NO: 4T1B31HK7JU501422

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$488.75	\$488.75
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PR-52-007	PROGRAM CAMERA	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$402.50	\$402.50

JOB COUNT: 4	WORK ORDER TOTAL:	0.50	59.00	0.00	893.25	952.25
---------------------	--------------------------	-------------	--------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	295567		\$488.75
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
PR-52-007	PROGRAM CAMERA	11076422	6144714		\$402.50
COMML					893.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11915538	01/10/2022 07:00:00	01/10/2022 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 42010

Work Order Notes

(LISAPATE) Glass Dr to install a new windshield

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed new windshield. it would not recalibrate had to take to the dealer. PD by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Vehicle dropped off at Glass Dr by the driver. picked up from Glass Dr and taken to Toyota by the shop and returned to the shop by our drivers.

CH-SP - CHARGE Shop Supplies

PR-52-007 - PROGRAM CAMERA

(LISAPATE) Toyota calibrated forward recognition camera. PD by CC

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 42474

USING DEPT NO: 507121	OPENED DATE: 02/25/2022 07:49:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/25/2022 13:36:03	METER 1 - M: 84159 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/28/2022 08:34:02	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.41	\$17.90	\$0.00	\$21.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$37.01	\$39.78	\$0.00	\$76.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	40.42	57.68	2.00	100.10
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/25/2022 08:16:03	02/25/2022 08:17:47	0.03	\$3.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2022 07:57:02	02/25/2022 08:15:51	0.31	\$37.01
LABOR					40.42	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.18	1	\$6.18
PARTS					57.68	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 42474

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG
MILEAGE-84159

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 43075

USING DEPT NO: 507121	OPENED DATE: 04/27/2022 15:35:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/28/2022 11:50:49	METER 1 - M: 88960 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/28/2022 14:58:22	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.03	\$17.90	\$0.00	\$23.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.22	\$67.87	\$0.00	\$104.09
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.10	\$11.57	\$18.57	\$0.00	\$30.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.46** **53.82** **104.34** **2.00** **160.16**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/28/2022 08:08:20	04/28/2022 08:14:13	0.10	\$11.57
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/28/2022 08:05:05	04/28/2022 08:08:09	0.05	\$6.03
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2022 07:46:27	04/28/2022 08:04:52	0.31	\$36.22
					LABOR 53.82	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SA90213	AIR FILTER	25.43	1	\$25.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.43	5	\$37.13
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.31	1	\$5.31
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	18.57	1	\$18.57
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	1	\$33.12
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	(1)	(\$33.12)
					PARTS 104.34	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 43075

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 44060

USING DEPT NO: 507121	OPENED DATE: 07/25/2022 10:43:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/27/2022 10:11:03	METER 1 - M: 94035 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/27/2022 13:13:06	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$45.44	\$0.00	\$84.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.33** **38.94** **45.44** **2.00** **86.38**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/25/2022 12:06:35	07/25/2022 12:06:35	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/25/2022 12:06:35	07/25/2022 12:06:35	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/25/2022 12:06:35	07/25/2022 12:26:23	0.33	\$38.94
LABOR					38.94	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.49	5	\$37.43
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.01	1	\$8.01
PARTS					45.44	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 44060

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 94035 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 44961

USING DEPT NO: 507121	OPENED DATE: 10/12/2022 08:26:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/14/2022 14:54:12	METER 1 - M: 99413 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2022 07:30:39	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.66	\$23.19	\$0.00	\$23.85
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.15	\$17.24	\$0.00	\$0.00	\$17.24
09-15	ALIGN STEERING	DON	N	N	GARAGE	0.66	\$78.27	\$0.00	\$0.00	\$78.27
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.77	\$208.83	\$689.39	\$0.00	\$898.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.14	\$41.34	\$0.00	\$64.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.78	328.14	753.92	5.00	1,087.06
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11074414	10/12/2022 09:06:14	10/12/2022 09:15:00	0.15	\$17.24
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/12/2022 09:05:42	10/12/2022 09:06:02	0.01	\$0.66
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/12/2022 08:53:43	10/12/2022 09:05:29	0.20	\$23.14
06-15	INSPECT STEERING	11074414	10/12/2022 09:06:14	10/12/2022 09:15:00	(0.15)	(\$17.24)
06-15	INSPECT STEERING	11074414	10/12/2022 09:06:14	10/12/2022 09:15:00	0.15	\$17.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/12/2022 10:02:58	10/12/2022 11:49:09	1.77	\$208.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/12/2022 10:02:58	10/12/2022 11:49:09	(1.77)	(\$208.83)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/12/2022 10:02:58	10/12/2022 11:49:09	1.77	\$208.83
09-15	ALIGN STEERING	11310047	10/12/2022 15:10:29	10/12/2022 15:50:17	0.66	\$78.27
09-15	ALIGN STEERING	11310047	10/12/2022 15:10:29	10/12/2022 15:50:17	(0.66)	(\$78.27)
09-15	ALIGN STEERING	11310047	10/12/2022 15:10:29	10/12/2022 15:50:17	0.66	\$78.27
					LABOR	328.14

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.81	5	\$34.05
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.29	1	\$7.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	4	\$23.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	2	\$1.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	4	\$662.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	(4)	(\$662.76)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	(4)	(\$23.58)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	(1)	(\$0.45)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	(2)	(\$1.17)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	(1)	(\$0.63)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	(1)	(\$0.80)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	4	\$662.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	4	\$23.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	2	\$1.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
					PARTS	753.92

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 44961

Work Order Notes

(CWIGLEY) PM/Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) JM Replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues at this time. SH

(AJONES) Visit Reason Changed On 10/31/2022 2:07 PM By AJONES

09-15 - ALIGN STEERING

(EHOWELL) Did not make any mechanical adjustments. Reset steering angle sensor using code link. EH

(AJONES) Visit Reason Changed On 10/31/2022 2:07 PM By AJONES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

(AJONES) Visit Reason Changed On 10/31/2022 2:07 PM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) JM EH/SH Performed PM. Vehicle needs 4 tires due to tread depths of 1and 2/32. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 45618

USING DEPT NO: 507121	OPENED DATE: 12/19/2022 08:11:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/19/2022 10:51:16	METER 1 - M: 103012 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/19/2022 12:41:41	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.67	\$23.25	\$0.00	\$34.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.21	\$41.45	\$0.00	\$68.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.33** **38.88** **64.70** **5.00** **108.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/19/2022 08:36:59	12/19/2022 08:42:55	0.10	\$11.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/19/2022 08:22:53	12/19/2022 08:36:43	0.23	\$27.21
LABOR					38.88	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.78	1	\$12.78
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
PARTS					64.70	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 45618

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 46403

USING DEPT NO: 507121	OPENED DATE: 03/08/2023 08:37:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/09/2023 07:50:33	METER 1 - M: 107938 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/09/2023 08:35:06	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.07	\$8.59	\$0.00	\$0.00	\$8.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$42.78	\$0.00	\$81.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.40** **47.53** **42.78** **5.00** **95.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/08/2023 13:00:00	03/08/2023 13:04:22	0.07	\$8.59
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/08/2023 12:51:33	03/08/2023 12:51:33	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/08/2023 12:25:03	03/08/2023 12:25:03	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/08/2023 12:25:03	03/08/2023 12:25:03	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/08/2023 12:25:03	03/08/2023 12:44:51	0.33	\$38.94
LABOR					47.53	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.35	5	\$36.75
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.03	1	\$6.03
PARTS					42.78	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 46403

Work Order Notes

(EHANNAH) pm- replace wipers - preform SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,CW/JAW
MILEAGE-107938

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 46818

USING DEPT NO: 507121	OPENED DATE: 04/24/2023 11:27:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/26/2023 08:56:08	METER 1 - M: 110466 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/27/2023 10:52:12	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.50	\$59.30	\$0.00	\$0.00	\$59.30

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.50** **59.30** **0.00** **5.00** **64.30**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>				
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00				
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00				
COMML									5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/24/2023 13:39:31	04/24/2023 14:09:40	0.50	\$59.30
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/24/2023 13:39:31	04/24/2023 14:09:40	0.50	\$59.30
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/24/2023 13:39:31	04/24/2023 14:09:40	(0.50)	(\$59.30)
LABOR						59.30

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 46818

Work Order Notes

(LRUSHING) CHECK ENGINE LIGHT IS ON

Job Notes

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 5/1/2023 10:12 AM By AJONES

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P1423-00 Evaporative Emission Fuel Tank Gross Leak. The gas cap was not installed properly. Tightened gas cap and cleared DTC. EH

(AJONES) Visit Reason Changed On 5/1/2023 10:12 AM By AJONES

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 47188

USING DEPT NO: 507121	OPENED DATE: 05/30/2023 08:34:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/31/2023 11:41:10	METER 1 - M: 112699 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/31/2023 11:41:14	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$11.14	\$24.06	\$0.00	\$35.20
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.17	\$20.36	\$0.00	\$0.00	\$20.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.86	\$41.79	\$0.00	\$77.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.57** **67.36** **65.85** **5.00** **138.21**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/30/2023 09:34:43	05/30/2023 09:45:04	0.17	\$20.36
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/30/2023 09:07:36	05/30/2023 09:13:16	0.09	\$11.14
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/30/2023 08:49:10	05/30/2023 09:07:24	0.30	\$35.86
					LABOR	67.36

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.20	5	\$36.00
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
					PARTS	65.85

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 47188

Work Order Notes

(EHANNAH) Pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 47738

USING DEPT NO: 507121	OPENED DATE: 07/26/2023 08:03:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/26/2023 14:20:57	METER 1 - M: 116768 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/01/2023 11:11:12	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.48	\$62.84	\$0.00	\$101.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.33** **38.48** **62.84** **5.00** **106.32**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/26/2023 08:55:26	07/26/2023 09:15:00	0.33	\$38.48
LABOR						38.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.78	1	\$5.78
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
PARTS						62.84

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 47738

Work Order Notes

(EHANNAH) pm- replace wipers
(EKIMBREL) just got wipers 2 months ago

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 47904

USING DEPT NO: 507121	OPENED DATE: 08/15/2023 08:49:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/16/2023 12:32:04	METER 1 - M: 118158 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/22/2023 13:26:20	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.80	\$93.88	\$0.00	\$0.00	\$93.88

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.80 93.88 0.00 5.00 98.88

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	08/16/2023 10:31:17	08/16/2023 11:19:01	0.80	\$93.88
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	08/16/2023 10:31:17	08/16/2023 11:19:01	(0.80)	(\$93.88)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	08/16/2023 10:31:17	08/16/2023 11:19:01	0.80	\$93.88
LABOR						93.88

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 47904

Work Order Notes

(EHANNAH) maintain soon light is coming on.

Job Notes

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 8/30/2023 8:17 AM By LRUSHING

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(GARAGE) Reset oil life monitor (maintenance reminder.) No engine DTCs were stored. EH

(LRUSHING) Visit Reason Changed On 8/30/2023 8:17 AM By LRUSHING

Work Order Charge Detail

UNIT NO: 242523 **2018 TOYOTA CAMRY HYBRID** **WORK ORDER NO:** 48788

USING DEPT NO: 507121	OPENED DATE: 11/01/2023 09:17:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2023 08:26:02	METER 1 - M: 121894 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/06/2023 13:33:38	IN-SERVICE DATE: 11/11/2017
TECH SPEC NO: 18TOYCAMRYHYD 2018 Toyota Camry Hybrid	UNIT SERIAL NO: 4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.03	\$24.08	\$0.00	\$28.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$40.74	\$49.88	\$0.00	\$90.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.38	44.77	73.96	5.00	123.73
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12395904	11/01/2023 11:44:26	11/01/2023 11:46:29	0.03	\$4.03
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/01/2023 11:23:13	11/01/2023 11:43:56	0.35	\$40.74
LABOR					44.77	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.43	1	\$7.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.49	5	\$42.45
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
PARTS					73.96	

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 48788

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 49776

USING DEPT NO:	507121	OPENED DATE:	02/12/2024 09:31:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/12/2024 12:23:19	METER 1 - M:	125699	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/12/2024 14:09:29	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.25	\$42.53	\$0.00	\$90.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.41** **48.25** **42.53** **5.00** **95.78**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/12/2024 11:06:54	02/12/2024 11:31:26	0.41	\$48.25
					LABOR	48.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	42.53

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 49776

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 51742

USING DEPT NO:	507121	OPENED DATE:	08/08/2024 07:47:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/14/2024 08:10:23	METER 1 - M:	130100	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/14/2024 11:22:01	IN-SERVICE DATE:	11/11/2017	
TECH SPEC NO:	18TOYCAMRYHYD	2018 Toyota Camry Hybrid		UNIT SERIAL NO:	4T1B31HK7JU501422	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.29	\$2.29
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.29	\$0.00	\$0.00	\$2.29

JOB COUNT: 2 **WORK ORDER TOTAL: 0.02 2.29 0.00 2.29 4.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.29
				COMML	2.29

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/12/2024 13:10:09	08/12/2024 13:11:19	0.02	\$2.29
					LABOR	2.29

Work Order Charge Detail

UNIT NO: 242523 2018 TOYOTA CAMRY HYBRID

WORK ORDER NO: 51742

Work Order Notes

(EHOWELL) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) No wordmarks. Removed tag 1475C. Checked inside of vehicle. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Aug 15 2024 14:46:45 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '4T1B31HK7JU501422') //Q=