Work Order Charge Detail Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER **WORK ORDER NO:** 27137 **USING DEPT NO:** 507301 **OPENED DATE:** 08/16/2017 14:15:08 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 08/18/2017 07:29:14 **WO STATUS: COMPLETED DATE: METER 1 - M**: 166 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 08/18/2017 07:29:16 **IN-SERVICE DATE:** 08/09/2017 2017 Chevrolet Express 2500 Passenger Van **TECH SPEC NO:** 17CHEVEX2500P **UNIT SERIAL NO:** 1GAWGEFG0H1313989 STAT RSN WRTY JOB LOC LABOR HRS COMMERCIAL TOTAL COST JOB CODE **LABOR MATERIAL** JOB DESCRIPTION PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE DON С **GARAGE** 0.50 \$28.75 \$0.00 \$0.00 \$28.75

JOB COUN	IT: 1	WORK ORDER TO	OTAL: 0.50	28.75	0.00	0.00	28.75
Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11268671	08/16/2017 14:15:38	08/16/2017 14:45:38		0.50	\$28.75
						LABOR	28.75

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 27137

Work Order Notes

(LISAPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

UNIT NO:		242405	2017 CHEVROL	ET EX	PRESS	3 2500 PAS	SSENGER	WORK OR	DER NO:	28	054	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	COMP	ED DAT LETED ED DAT et Expre	DATE: E:	11/08/201 11/08/201	7 13:06:12 7 07:53:36 7 07:53:39 ⁄an	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 3800 DATE :	ME 08/09/201	TER 2 - N:	0
JOB CODE		JOB DESCRIPTION	<u>n</u> <u>stat</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	AL CC	MMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.65	\$37.20	\$29.21	\$0.0	00	\$66.41
JOB COUN	IT: 1			wc	RK ORI	DER TOTAL:	0.65	37.2	20 :	29.21	0.00	66.41
Job Code		Job Description	<u>on</u>	<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		11074414	ļ.	11/	06/2017 14:30:14	11/06/2017	15:09:03		0.65	\$37.20
											LABOR	37.20
Job Code		Job Description	on_		Part No	<u>.</u>	<u>Des</u>	cription	<u>Ur</u>	nit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		PF63		FIL	TER-OIL			5.99	1	\$5.99
66-PM-PMA	PERFORM (OIL CHANGE		5W30T		5W	/30 SYNTHETIC (OIL THOMAS CA	M2	3.87	6	\$23.22
											PARTS	29.21

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 28054

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/CS

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

242405 **UNIT NO:** 2017 CHEVROLET EXPRESS 2500 PASSENGER **WORK ORDER NO:** 29224 **USING DEPT NO:** 507301 **OPENED DATE:** 03/28/2018 09:16:49 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 04/03/2018 10:07:37 COMPLETED DATE: **METER 1 - M:** 7256 METER 2 - N: WO VISIT REASON: **SCHEDULED** 04/03/2018 10:07:39 **CLOSED DATE:** IN-SERVICE DATE: 08/09/2017 **TECH SPEC NO:** 17CHEVEX2500P 2017 Chevrolet Express 2500 Passenger Van **UNIT SERIAL NO:** 1GAWGEFG0H1313989 **MATERIAL** COMMERCIAL TOTAL COST JOB CODE JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS **LABOR** 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 1.50 \$86.06 \$30.02 \$0.00 \$116.08 JOB COUNT: 1 WORK ORDER TOTAL: 1.50 86.06 30.02 0.00 116.08 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 11758845 03/28/2018 09:56:59 03/28/2018 11:26:47 1.50 \$86.06 **LABOR** 86.06 **Job Code Job Description** Part No. **Unit Price** Quantity **Total Cost** Description 6 5W30T 4.01 \$24.03 66-PM-PMA PERFORM OIL CHANGE 5W30 SYNTHETIC OIL THOMAS CAM2 5W30T (1) 66-PM-PMA PERFORM OIL CHANGE 5W30 SYNTHETIC OIL THOMAS CAM2 4.02 (\$4.02)66-PM-PMA \$5.99 PERFORM OIL CHANGE PF63 FILTER-OIL 5.99 66-PM-PMA PERFORM OIL CHANGE 5W30T 5W30 SYNTHETIC OIL THOMAS CAM2 4.02 \$4.02 **PARTS** 30.02

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 29224

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

UNIT NO:		242405 201	7 CHEVROL	ET EX	PRESS	3 2500 PA	SSENGER	WORK OF	DER NO	: 29	727	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENI COMPI CLOSE 2017 Chevrole	ETED	DATE: E:	05/14/20 05/14/20	18 09:14:40 18 07:53:53 18 07:53:55 Van	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 11310 DATE:	ME 08/09/20	y Automotive 9 ETER 2 - N: 17 EFG0H131398	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	0	N	GARAGE	0.25	\$14.38	\$25.59	\$0.	.00	\$39.97
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.31	\$17.83	\$31.55	\$0.	.00	\$49.38
JOB COUN	IT: 2			WC	RK ORI	DER TOTAL	0.56	32.	21	57.14	0.00	89.35
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE	1	1901357	7	05	/10/2018 07:00:00	05/10/201	8 07:18:36		0.31	\$17.83
03-51-038	REPLACE N	IEW WIPER BLADES	1	1901357	7	05	/10/2018 07:18:36	05/10/201	8 07:33:36		0.25	\$14.38
											LABOR	32.21
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>L</u>	Jnit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE	F	PF63		FI	LTER-OIL			5.99	1	\$5.99
03-51-038	REPLACE N	IEW WIPER BLADES	V	VW-2200)-PC	W	IPER BLADE 22"			12.80	2	\$25.59
66-PM-PMA	PERFORM (OIL CHANGE	5	W30T		5V	V30 SYNTHETIC (OIL THOMAS CA	AM2	4.26	6	\$25.56
											PARTS	57.14

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 29727

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG,EK/AG COOLANT -35'

UNIT NO:		242405 20	17 CHEVRO	ET EX	PRESS	6 2500 PA	SSENGER	WORK ORI	DER NO	: 3	80091	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	COM	IED DAT PLETED SED DAT let Expre	DATE:	06/27/201	18 10:33:10 18 10:11:19 18 10:11:42 /an	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	15204 DATE :	08/09/2	ity Automotive S IETER 2 - N: 017 GEFG0H131398	0
JOB CODE		JOB DESCRIPTION	<u>STA</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL (COMMERCIAL	TOTAL COST
66-17-015	PERFOR	M TIRE ROTATION	DON	0	N	GARAGE	0.50	\$28.75	\$0.00	\$	0.00	\$28.75
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	Ν	GARAGE	0.38	\$21.85	\$51.94	\$	0.00	\$73.79
JOB COUN	T: 2			W	ORK ORI	DER TOTAL:	0.88	50.6	0	51.94	0.00	102.54
Job Code		Job Description		<u>E</u> 1	nployee	No.	<u>Start</u>	<u>Fir</u>	nish		Quantity	Total Cost
66-17-015	PERFORM 1	TIRE ROTATION		1107441	4	06	/25/2018 15:04:13	06/25/2018	15:34:13		0.50	\$28.75
66-PM-PMA	PERFORM (OIL CHANGE		1107441	4	06	/25/2018 11:37:36	06/25/2018	12:00:24		0.38	\$21.85
66-PM-PMA	PERFORM (OIL CHANGE		1107441	4	06.	/25/2018 11:37:36	06/25/2018	13:00:19		(1.38)	(\$79.27)
66-PM-PMA	PERFORM (OIL CHANGE		1107441	4	06.	/25/2018 11:37:36	06/25/2018	13:00:19		1.38	\$79.27
											LABOR	50.60
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>!</u>	Unit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		46573		FIL	TER-AIR			10.4	1 1	\$10.41
66-PM-PMA	PERFORM (OIL CHANGE		7060		FIL	TER-OIL			2.8	2 1	\$2.82
66-PM-PMA	PERFORM (OIL CHANGE		5W30T		5V	V30 SYNTHETIC (OIL THOMAS CAN	М2	5.4	0 6	\$32.40
66-PM-PMA	PERFORM (OIL CHANGE		05089		BF	RAKE CLEAN NON	N-FLAMMABLE 14	4OZ	6.3		\$6.31
											PARTS	51.94

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 30091

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-015 - PERFORM TIRE ROTATION

(LISAPATE) ROTATED TIRES

REPLACED AIR FILTER

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 6/25/2018 10:33 AM By LISAPATE (LISAPATE) PM BY SH COOLANT -30'

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		242405 2	017 CHEVROLE	T EX	PRESS	2500 PAS	SSENGER	WORK O	RDER NO:	31	1442	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENE COMPL CLOSE 2017 Chevrole	ETED D DAT	DATE: E:	11/19/201 11/19/201	8 08:32:46 8 06:36:42 8 06:36:43 ⁄an	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 16701 E DATE :	ME 08/09/20		0
JOB CODE	<u>E</u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL CO	OMMERCIAL	TOTAL COST
06-13	INSPEC	T BRAKES	DON	0	N	GARAGE	0.50	\$36.25	\$0.00	\$0	.00	\$36.25
15-13	WARRA	NTY BRAKES	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0	.00	\$0.00
16-13	TRANSF	PORT BRAKES	DON	0	N	GARAGE	1.00	\$72.50	\$0.00	\$0	.00	\$72.50
JOB COUN	IT: 3			WC	RK ORI	DER TOTAL:	1.50	108	.75	0.00	0.00	108.75
Job Code		Job Description	<u>1</u>	<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No.	<u>.</u>		Total Cost
15-13	WARRANT	Y BRAKES	1	1074891	I	СТ	CS379825	0045875				\$0.00
											COMML	0.00
Job Code		Job Description	<u>1</u>	<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>!</u>	Finish		Quantity	Total Cost
16-13	TRANSPOR	RT BRAKES	1	1915538	3	11/	15/2018 07:00:00	11/15/201	18 08:00:00		1.00	\$72.50
06-13	INSPECT B	RAKES	1	1268671	I	11/	15/2018 07:00:00	11/15/201	18 07:30:00		0.50	\$36.25
											LABOR	108.75

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 31442

Work Order Notes

(EKIMBREL) brakes making noise

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE) IF checked brakes all brakes looked good. did hear brake noise. Send to Tuscaloosa Chevrolet to check under warranty

15-13 - WARRANTY BRAKES

(LISAPATE) Per Tuscaloosa Chevrolet resurfaced both front and rear rotors. Cleaned brake pads and applied stop squeak to pads. burnished brakes.

16-13 - TRANSPORT BRAKES

(LISAPATE) Taken to TC by RC

66-PM-PMA - PERFORM OIL CHANGE

UNIT NO:		242405	2017 CHEVE	ROLE	T EXI	PRESS	3 2500 PA	SSENGER	WORK ORDER	NO:	33366	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	C	OMPL LOSEI	D DATI ETED I D DATE	DATE: E:	07/11/20	19 13:55:15 19 11:47:17 19 11:47:19 Van	LOCATION: GARA METER 1 - M: 298 IN-SERVICE DATE: UNIT SERIAL NO:	886 08/09	METER 2 - N:	0
JOB CODE		JOB DESCRIPTION	<u>N</u> <u>S</u>	STAT	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR M	ATERIAL	COMMERCIA	L TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE	[OON	Р	N	GARAGE	0.31	\$22.48 \$37.	74	\$0.00	\$60.22
JOB COUN	IT: 1				WO	RK ORI	DER TOTAL	: 0.31	22.48	37.74	0.0	0 60.22
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		11	074414		07	7/10/2019 06:00:00	07/10/2019 06:18:	36	0.3	1 \$22.48
											LABOR	22.48
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	Des	scription	<u>Unit Pri</u>	ce Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5V	V30T		5\	V30 SYNTHETIC	OIL THOMAS CAM2	5	5.82	6 \$34.92
66-PM-PMA	PERFORM (OIL CHANGE		5V	V30T		5\	V30 SYNTHETIC	OIL THOMAS CAM2	5	5.84 (1) (\$5.84)
66-PM-PMA	PERFORM (OIL CHANGE		70	060		FI	LTER-OIL		2	2.82	1 \$2.82
66-PM-PMA	PERFORM (OIL CHANGE		70	060		FI	LTER-OIL		2	2.82 (6) (\$16.92)
66-PM-PMA	PERFORM (OIL CHANGE		5V	V30T		5\	V30 SYNTHETIC	OIL THOMAS CAM2	5	5.84	1 \$5.84
66-PM-PMA	PERFORM (OIL CHANGE		70	060		FI	LTER-OIL		2	2.82	6 \$16.92
											PARTS	37.74

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 33366

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH Coolant -35'

Previous oil change at Express Oil Change

UNIT NO:	242405	2017 CHEVROLE	ET EXPRES	S 2500 PAS	SSENGER	WORK ORDER N	IO: 3	4462	
USING DEPT NO: WO STATUS: WO VISIT REASO TECH SPEC NO:	CLOSED	COMPL	ED DATE: LETED DATE: ED DATE: et Express 250	10/18/201 10/18/201	9 14:16:21 9 09:45:09 9 09:45:11 ⁄an	LOCATION: GARAG METER 1 - M: 3049 IN-SERVICE DATE: UNIT SERIAL NO:	4 M 08/09/20	ETER 2 - N:	0
JOB CODE	JOB DESCRIPTIO	N STAT	RSN WRTY	JOB LOC	LABOR HRS	LABOR MA	TERIAL C	OMMERCIAL	TOTAL COST
03-01-012 RE	PLACE NEW CONTROL K	NOB DON	O N	GARAGE	0.30	\$21.75 \$10.49	9 \$(0.00	\$32.24
JOB COUNT: 1			WORK OR	DER TOTAL:	0.30	21.75	10.49	0.00	32.24
Job Code	Job Description	<u>on</u>	Employee	No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
03-01-012 REPL	ACE NEW CONTROL KNOB	1	1074414	10/	16/2019 06:00:00	10/16/2019 06:18:00)	0.30	\$21.75
								LABOR	21.75
Job Code	Job Description	<u>on</u>	Part N	<u>D.</u>	Des	<u>cription</u>	Unit Price	Quantity	<u>Total Cost</u>
03-01-012 REPL	ACE NEW CONTROL KNOB	8	4141127	A/C	CONTROL KNO	В	10.49	11	\$10.49
								PARTS	10.49

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 34462

Work Order Notes

(LISAPATE) A/C control knob overhead control knob is broken

Job Notes

03-01-012 - REPLACE NEW CONTROL KNOB

(LISAPATE) SH Installed new AC control knob for rear vents

UNIT NO:		242405 201	7 CHEVROL	ET EX	PRES	S 2500 PAS	SENGER	WORK OF	RDER NO	: 34	775	
USING DEPT	NO:	507301	OPEN	ED DAT	E:	11/06/201	9 13:34:31	LOCATION:	GARAGE	- University	Automotive S	Services
WO STATUS	:	CLOSED	COMP	LETED	DATE:	11/11/2019	9 08:21:29	METER 1 - M	I: 32068	ME	TER 2 - N:	0
WO VISIT RE	EASON:	SCHEDULED	CLOS	ED DAT	E:	11/11/201	9 08:21:31	IN-SERVICE	DATE:	08/09/201	7	
TECH SPEC	NO:	17CHEVEX2500P	2017 Chevro	et Expre	ess 2500	Passenger V	⁄an	UNIT SERIA	L NO:	1GAWGE	FG0H131398	39
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL COST
03-01-012	REPLAC	E NEW CONTROL KNOE	B DON	0	N	GARAGE	0.00	\$0.00	\$10.13	\$0.0	00	\$10.13
JOB COUNT	: 1			WC	RK OR	DER TOTAL:	0.00	0.	00	10.13	0.00	10.13
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	<u>scription</u>	<u> </u>	Jnit Price	Quantity	Total Cost
03-01-012	REPLACE N	NEW CONTROL KNOB		7355230	1	HV	AC CONTROL KI	NOB		10.13	1	\$10.13
											PARTS	10.13

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 34775

Work Order Notes

(RTUNAITI) AUX A/C blower speed control knob is missing

Job Notes

03-01-012 - REPLACE NEW CONTROL KNOB

(RTUNAITI) MT replaced missing knob

UNIT NO:		242405	2017 CHE	VROLE	T EXI	PRESS	3 2500 PA	SSENGER	WORK OF	RDER NO): 3	35368	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	2017	OPENE COMPL CLOSE Chevrole	ETED I	DATE:	01/15/20	20 08:51:24 20 09:20:49 20 09:20:50 Van	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	n: 33974 DATE:	08/09/2	iity Automotive S METER 2 - N: 017 GEFG0H131398	0
JOB CODE	_	JOB DESCRIPTIO	<u>N</u>	STAT DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.73	LABOR \$52.76	MATE \$48.15		COMMERCIAL 50.00	TOTAL COST \$100.91
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL	: 0.73	52.	76	48.15	0.00	100.91
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	inish		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		12	2052187		0	1/10/2020 10:47:48	01/10/202	0 11:31:28		0.73	\$52.76
												LABOR	52.76
Job Code		Job Description	o <u>n</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	e Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		70	060		F	LTER-OIL			2.8	32 1	\$2.82
66-PM-PMA	PERFORM (OIL CHANGE		5\	W30T		5\	W30 SYNTHETIC	OIL THOMAS C	AM2	5.8	32 6	\$34.92
66-PM-PMA	PERFORM (OIL CHANGE		46	6573		F	LTER-AIR			10.4	1 1	\$10.41
												PARTS	48.15

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 35368

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. coolant -10

UNIT NO:	242405 2017 CHE	VROLET EXPRESS	2500 PASSENGER	WORK ORDER NO:	35472	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:	507301 CLOSED UNSCHEDULED 17CHEVEX2500P 2017	OPENED DATE: COMPLETED DATE: CLOSED DATE: Chevrolet Express 2500	01/22/2020 10:40:17 01/29/2020 10:26:38 01/29/2020 10:26:40 Passenger Van	-	•	0
JOB CODE	JOB DESCRIPTION	STAT RSN WRTY	JOB LOC LABOR HRS	LABOR MATERIA	<u>COMMERCIAL</u>	TOTAL COST
24-02-023 REPAIR	HANDLES - INNER & OUTER	DON O N	GARAGE 0.30	\$21.75 \$3.60	\$0.00	\$25.35
JOB COUNT: 1		WORK ORE	DER TOTAL: 0.30	21.75 3	.60 0.00	25.35
Job Code	Job Description	Employee	No. Start	<u>Finish</u>	Quantity	Total Cost
24-02-023 REPAIR HA	NDLES - INNER & OUTER	10321076	01/23/2020 07:00:00	01/23/2020 07:18:00	0.30	\$21.75
					LABOR	21.75
Job Code	Job Description	Part No	<u>Des</u>	scription Unit	Price Quantity	Total Cost
24-02-023 REPAIR HA	NDLES - INNER & OUTER	DORBOLT	BOLT		0.60 <u>6</u>	\$3.60 3.60

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 35472

Work Order Notes

(LISAPATE) PM-Bolt missing from interior barn door handle-handle is in rear seat (RWINTERS) PM cancelled - not due until 5/10/20 or 38000 miles

Job Notes

24-02-023 - REPAIR HANDLES - INNER & OUTER

(RTUNAITI) MT reattached side door inside pull handle

66-PM-PMA - PERFORM OIL CHANGE

UNIT NO:		242405 2	017 CHEVROL	ET EXPRESS	2500 PAS	SENGER	WORK ORDE	R NO:	36054	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	COMP	ED DATE: LETED DATE: ED DATE: et Express 2500	03/24/2020 03/25/2020 03/25/2020 Passenger Va	0 08:57:43 0 16:14:38	LOCATION: GAI METER 1 - M: 3 IN-SERVICE DAT UNIT SERIAL NO	7847 N E: 08/09/2	METER 2 - N:	0
JOB CODE		JOB DESCRIPTION RM OIL CHANGE	<u>STAT</u> DON	RSN WRTY P N	JOB LOC GARAGE	LABOR HRS 0.49		_	COMMERCIAL 80.00	TOTAL COST \$73.62
JOB COUN	IT: 1			WORK ORI	DER TOTAL:	0.49	35.79	37.83	0.00	73.62
Job Code 66-PM-PMA	PERFORM	<u>Job Descriptio</u> OIL CHANGE	_	<u>Employee</u> 11074414		<u>Start</u> 24/2020 15:14:58	Finish 03/24/2020 15:4	•	Quantity 0.49 LABOR	Total Cost \$35.79 35.79
Job Code		Job Description	<u>n</u>	Part No		<u>Des</u>	<u>cription</u>	Unit Price	e Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	7	7060	FILT	TER-OIL		2.8	32 1	\$2.82
66-PM-PMA	PERFORM	OIL CHANGE	5	5W30T	5W:	30 SYNTHETIC C	DIL THOMAS CAM2	5.8	94 <u>6</u> PARTS	\$35.01 37.83

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 36054

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/SH Coolant -34'

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405	2017 CHEVROLET EXPRESS 2500 PASSENGER	WORK ORDER NO:	37010
-----------------	---------------------------------------	----------------	-------

USING DEPT NO: 507301 OPENED DATE: 07/02/2020 14:45:19 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 07/02/2020 15:30:12
 METER 1 - M:
 37876
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 07/06/2020 11:21:45
 IN-SERVICE DATE:
 08/09/2017

TECH SPEC NO: 17CHEVEX2500P 2017 Chevrolet Express 2500 Passenger Van UNIT SERIAL NO: 1GAWGEFG0H1313989

JOB CODE	JOB CODE JOB DESCRIPTION		<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	CON	<u>IMERCIAL</u>	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	0.25	\$18.13	\$0.00	\$0.00		\$18.13
JOB COUN	T: 1		WC	RK OR	DER TOTAL	0.25	18.	13 0.0	00	0.00	18.13
Job Code	Job Description		Employee No.		No.	<u>Start</u>	<u>F</u>	<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	1	1915538	3	07	/02/2020 15:05:11	07/02/202	0 15:20:11		0.25	\$18.13
66-PM-PMA	PERFORM OIL CHANGE	1	1915538	3	07	//02/2020 15:05:11	07/02/202	0 15:07:02		(0.03)	(\$2.24)
66-PM-PMA	PERFORM OIL CHANGE	11915538		07	//02/2020 15:05:11	07/02/202	07/02/2020 15:07:02		0.03	\$2.24	
									_	LABOR	18.13

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 37010

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Did not drop oil at this time. Checked fluids, battery and tire pressures. Updated sticker

RC

Coolant -34'

UNIT NO:		242405 2017 CHEVROLET EXPRESS 2500 PASSEN						SSENGER	WORK OR	DER NO	: 38	474	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		507301 CLOSED SCHEDULED 17CHEVEX2500P	1	COMPL	PENED DATE: OMPLETED DATE: LOSED DATE: devrolet Express 2500 P			12/07/2020 12:53:12		GARAGE : 38015 DATE: - NO:	E - University Automotive METER 2 - N: 08/09/2017 1GAWGEFG0H13139		0
JOB CODE	<u> </u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES		DON	0	Ν	GARAGE	0.05	\$5.57	\$29.37	\$0.0	00	\$34.94
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.29	\$33.76	\$37.83	\$0.0	00	\$71.59
SO-05	SCAN O	JT ELECTRONIC ENGIN	E EEC	DON	0	N	GARAGE	1.00	\$118.00	\$0.00	\$0.0	00	\$118.00
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL	: 1.33	157.3	33	67.20	0.00	224.53
Job Code		Job Description			<u>Em</u>	ployee	No.	<u>Start</u>	<u>Fi</u>	<u>inish</u>		Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		1	1074414		12	2/04/2020 09:50:13	12/04/2020	09:53:03		0.05	\$5.57
66-PM-PMA	PERFORM (OIL CHANGE		1	1074414		12	2/04/2020 09:32:49	12/04/2020	09:49:59		0.29	\$33.76
SO-05	SCAN OUT	ELECTRONIC ENGINE EEC	SYSTEM	1 1	1213180		12	2/01/2020 10:20:51	12/01/2020	10:35:46		(0.25)	(\$29.34)
SO-05	SCAN OUT	ELECTRONIC ENGINE EEC	SYSTEM	1 1	1213180		12	2/01/2020 10:20:51	12/01/2020	10:35:46		0.25	\$29.34
SO-05	SCAN OUT	ELECTRONIC ENGINE EEC	SYSTEM	1 1	1213180		1:	2/01/2020 10:20:51	12/01/2020	11:20:51		1.00	\$118.00
												LABOR	157.33
Job Code		Job Description				Part No	<u>.</u>	<u>Des</u>	cription	<u>,</u>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		7	060		F	LTER-OIL			2.82	1	\$2.82
66-PM-PMA	PERFORM (OIL CHANGE		5	W30T		5\	W30 SYNTHETIC (OIL THOMAS CA	.M2	5.84	6	\$35.01
03-51-038	REPLACE N	EW WIPER BLADES		V	WW-2200-PC			IPER BLADE 22"			14.69	2	\$29.37
												PARTS	67.20

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 38474

Work Order Notes

(LISAPATE) Check engine light is on

(LISAPATE) Service stabiltrak light is on the dash now and PM is due.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) SH Replaced wipers due to normal wear.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM. Mileage 38015.

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC P1682 Ignition 1 Switch Circuit 2 stored. Checked for Technical Service Bulletins, but found none. Performed Diagnostic flow chart for circuit and component testing, but everything checked good. Cleared DTC and allowed vehicle to run while checking periodically. The check engine light has not come back on EH

UNIT NO:		242405	2017 CHEVRO	LET	EXF	PRESS	3 2500 PA	SSENGER	WORK (ORDER NO) :	39973	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	COI	ENED MPLET DSED rolet E	TED E	DATE:	05/21/20	21 07:32:52 21 11:28:57 21 12:29:40 Van		- M: 41590 CE DATE:	08/09/2	sity Automotive s METER 2 - N: 2017 GEFG0H131398	0
JOB CODE	_	JOB DESCRIPTIO			RSN	WRTY	JOB LOC		·			COMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	RM OIL CHANGE	DC	N	Р	N	GARAGE	0.54	\$63.13	\$39.23		\$0.00	\$102.36
JOB COUN	IT: 1				woi	RK ORI	DER TOTAL	: 0.54	l (3.13	39.23	0.00	102.36
Job Code		Job Description	<u>on</u>		Em	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1205	52187		05	5/18/2021 10:00:05	5 05/18/2	021 10:32:11		0.54	\$63.13
												LABOR	63.13
Job Code		Job Description	<u>on</u>		<u> </u>	Part No	<u>.</u>	<u>Des</u>	scription	cription		e Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		BALI	B160		0	IL FILTER			4.2	22 1	\$4.22
66-PM-PMA	PERFORM (OIL CHANGE		5W30T				V30 SYNTHETIC	OIL THOMAS CAM2		5.8	846	\$35.01
												PARTS	39.23

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 39973

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. RC,AMG/JAW MILEAGE-41590

UNIT NO:		242405 201	7 CHEV	/ROLE	ET EX	PRES	6 2500 PA	ASSENGER	WORK C	RDER NO): 4	1 1557	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		507301 CLOSED SCHEDULED 17CHEVEX2500P		OPENED DATE: COMPLETED DATE: CLOSED DATE: 2017 Chevrolet Express 2500 F			11/09/20 11/10/20	11/10/2021 07:59:04		LOCATION: GARAGE METER 1 - M: 45549 IN-SERVICE DATE: UNIT SERIAL NO:		ity Automotive S METER 2 - N: 1017 GEFG0H131398	0
JOB CODE	<u> </u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	RIAL (COMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	3	DON	Р	N	GARAGE	0.20	\$23.60	\$15.18	\$	60.00	\$38.78
66-17-033	PERFOR	M TIRE ROTATION AND	BRAKE	DON	0	N	GARAGE	0.26	\$30.78	\$0.00	\$	60.00	\$30.78
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.13	\$15.80	\$40.79	\$	80.00	\$56.59
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	52.00	\$2.00
JOB COUN	IT: 4				wc	ORK ORI	DER TOTAL	_: 0.59	7	0.18	55.97	2.00	128.15
Job Code CH-SP	CHARGE SI	Job Description		5	<u>\</u> 03163	endor N	lo. 1	Invoice No.	Purch	ase Order N	<u>o.</u>	_	Total Cost \$2.00
												COMML	2.00
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414	4	1	1/09/2021 14:00:05	11/09/20	21 14:08:07		0.13	\$15.80
03-51-038	REPLACE N	IEW WIPER BLADES		1	1074414	4	1	1/09/2021 14:08:23	11/09/20	21 14:08:40		0.00	\$0.56
03-51-038	REPLACE N	IEW WIPER BLADES		1	1074414	4	1	1/09/2021 14:08:23	11/09/20	21 14:08:40		0.00	(\$0.56)
03-51-038	REPLACE N	IEW WIPER BLADES		1	1074414	4	1	1/09/2021 14:08:23	11/09/20	21 14:20:23		0.20	\$23.60
66-17-033	PERFORM ¹	TIRE ROTATION AND BRA	KE INSPEC	TION 1	1074414	4	1	1/09/2021 14:09:55	11/09/20	21 14:15:00		0.08	\$10.00
66-17-033	PERFORM T	TIRE ROTATION AND BRAI	KE INSPEC	TION 1	1074414	4	1	1/09/2021 14:30:00	11/09/20	21 14:40:34		0.18	\$20.78
												LABOR	70.18
Job Code		Job Description				Part No	<u>.</u>	Des	cription		Unit Price	e Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5	W30T		5	W30 SYNTHETIC (OIL THOMAS	CAM2	5.8	32 6	\$34.92
03-51-038	REPLACE N	IEW WIPER BLADES		2	2-1		V	VIPER BLADE 22"	TRICO EXACT		7.5	59 2	\$15.18
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB160)	C	OIL FILTER			5.8		\$5.87
												PARTS	55.97

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 41557

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires adjusted tire pressure relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

UNIT NO: 242405 20			7 CHEVROLI	ET EX	PRES	3 2500 PA	SSENGER	WORK O	RDER NO	11902			
WO STATUS: CL WO VISIT REASON: SO		507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENE COMPI CLOSE 2017 Chevrole	ETED D DAT	DATE: E:	12/15/20 12/16/20	21 08:50:45 21 15:11:40 21 07:43:45 Van	LOCATION: GARAGE METER 1 - M: 46271 IN-SERVICE DATE: UNIT SERIAL NO:		E - University Automotive S METER 2 - N: 08/09/2017 1GAWGEFG0H131398		0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.01	\$0.59	\$15.18	\$	0.00	\$15.77	
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	N	GARAGE	0.32	\$38.19	\$50.16	\$	0.00	\$88.35	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	52.00	\$2.00	
JOB COUNT: 3				WC	RK ORI	DER TOTAL	.: 0.33	38	.78	65.34	2.00	l	106.12
Job Code		Job Description		<u>v</u>	endor N	lo.	Invoice No.	<u>Purcha</u>	se Order No	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	nop Supplies	503163			1						_	\$2.00
											COMML		2.00
Job Code		Job Description		<u>En</u>	ployee	No.	<u>Start</u>		Finish		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	1	1074414		12	2/15/2021 13:36:35	12/15/202	21 13:56:00		0.32		\$38.19
03-51-038	REPLACE N	IEW WIPER BLADES	1	1074414		12	2/15/2021 13:56:09	12/15/202	21 13:56:27		0.01		\$0.59
											LABOR		38.78
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>.</u>	Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	5	W30T		5\	W30 SYNTHETIC (OIL THOMAS C	AM2	6.9	3 6		\$41.58
03-51-038	REPLACE N	IEW WIPER BLADES	2	2-1		W	WIPER BLADE 22" TRICO EXACT			7.5	9 2		\$15.18
66-PM-PMA	PERFORM (OIL CHANGE	E	ALB160		0	IL FILTER			8.5	8 1		\$8.58
											PARTS		65.34

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 41902

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) JW Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

UNIT NO: 242405 2017			7 CHEVRO	ET EX	PRES	S 2500 PA	SSENGER	WORK ORDER NO: 42			8	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2017 Chevrolet Express 2500			03/09/202 03/11/202	22 12:07:30 22 15:22:10 22 07:49:32 /an	LOCATION: G METER 1 - M: IN-SERVICE DA UNIT SERIAL N	49275 ATE : 08/0	METE 09/2017		0
JOB CODE	<u>.</u>	JOB DESCRIPTION	STA.	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	СОМІ	MERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	l P	N	GARAGE	0.15	\$17.70	\$15.18	\$0.00		\$32.88
CH-SP	CHARGE	Shop Supplies	DON	1 2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00		\$2.00
JOB COUNT: 2				W	ORK ORI	DER TOTAL:	0.15	17.70	15.1	18	2.00	34.88
Job Code				<u>Vendor No.</u> 503163			Invoice No.	Purchase (Order No.			Total Cost \$2.00
											COMML	2.00
Job Code		Job Description		<u>E</u> 1	nployee	No.	<u>Start</u>	<u>Fini</u>	<u>sh</u>	<u>(</u>	Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		1205218	7	03	/08/2022 12:11:20	03/08/2022 12	2:11:20		0.00	\$0.00
03-51-038	REPLACE N	EW WIPER BLADES		1205218	7	03	/08/2022 12:11:20	03/08/2022 12	2:11:20		0.00	\$0.00
03-51-038	REPLACE N	EW WIPER BLADES		1205218	7	03	/08/2022 12:11:20	03/08/2022 12	2:20:20		0.15	\$17.70
											LABOR	17.70
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>Unit P</u>	Price (Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		22-1		WI	PER BLADE 22" T	TRICO EXACT		7.59	2	\$15.18
											PARTS	15.18

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 42608

Work Order Notes

(EKIMBREL) replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers requested by donald

CH-SP - CHARGE Shop Supplies

UNIT NO:		242405	2017 CHEVR	OLE	ET EX	PRES	S 2500 P	ASSEN	GER	WORK OR	DER NO):	42724		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	CL	OMPL OSE	D DAT ETED D DAT t Expre	DATE: E:	03/29/2	2022 10:5 2022 11:05 2022 15:02 er Van	5:59	LOCATION: METER 1 - M: IN-SERVICE DUNIT SERIAL	49476 DATE :	08/09/2	sity Automotive 9 METER 2 - N: 2017 GEFG0H131398	0	
JOB CODE		JOB DESCRIPTION	<u>N</u> <u>S</u>	<u>TAT</u>	RSN	WRTY	JOB LO	C LABO	OR HRS	<u>LABOR</u>	MATE	RIAL	COMMERCIAL	TOTAL C	OST
66-PM-PMA	PERFOR	M OIL CHANGE	D	ON	Р	Ν	GARAGE	Ī	0.14	\$16.23	\$50.85		\$0.00	\$67.08	
CH-SP	CHARGE	Shop Supplies	D	ON	2	Ν	GARAGE	<u> </u>	0.00	\$0.00	\$0.00		\$2.00	\$2.00	
JOB COUN	T: 2				wo	RK OR	DER TOTA	۱ L :	0.14	16.23	3	50.85	2.00	l	69.08
Job Code		Job Descriptio	<u>on</u>		<u>v</u>	endor N	<u>lo.</u>	Invo	ice No.	<u>Purchase</u>	Order No	<u>0.</u>		Total Co	<u>ost</u>
CH-SP	CHARGE Sh	nop Supplies		50	03163			1						•	\$2.00
													COMML		2.00
Job Code		Job Description	<u>on</u>		<u>En</u>	nployee	No.	<u>s</u>	Start .	<u>Fir</u>	<u>nish</u>		Quantity	Total Co	ost
66-PM-PMA	PERFORM (OIL CHANGE		11	1074414	ļ		03/28/2022	2 13:08:11	03/28/2022	13:16:26		0.14		\$16.23
													LABOR		16.23
Job Code		Job Descriptio	<u>on</u>			Part No	<u>).</u>		Des	cription	ļ	Unit Pric	e Quantity	Total Co	<u>ost</u>
66-PM-PMA	PERFORM (OIL CHANGE		5\	W20BT			BULK OIL	5W20 SYI	NTHETIC THOMA	S	4.	43 6		\$26.55
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB160			OIL FILTER	₹			9.	18 1		\$9.18
66-PM-PMA	PERFORM (OIL CHANGE		5\	W20BT			BULK OIL	5W20 SYI	NTHETIC THOMA	S	4.	43 (6)) (9	\$26.55)
66-PM-PMA	PERFORM (OIL CHANGE		5\	W30T			5W30 SYN	THETIC (OIL THOMAS CAN	/ 12	6.	956		\$41.67
													PARTS		50.85

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 42724

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(IFALLS) none needed at this time

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH AMG/JW Performed PM.

UNIT NO:		242405 20	17 CHE\	VROLE	TEX	PRES	S 2500 PAS	SSENGER	WORK O	RDER NO:	: 43	3743		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P		OPENE COMPL CLOSE Chevrole	ETED D DATI	DATE: E:	06/24/202	2 13:36:56 2 15:05:15 2 15:18:04 ⁄an	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 52508 E DATE:	MI 08/09/20	y Automotive S ETER 2 - N: 17 EFG0H131398	0	
JOB CODE	<u> </u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL (COST
03-34-002	REPLAC	E NEW LAMPS-REAR,	TAIL,STO	DON	0	N	GARAGE	1.27	\$149.53	\$0.95	\$0	0.00	\$150.48	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL:	1.27	149	.53	0.95	2.00		152.48
Job Code		Job Description			<u>v</u>	endor N	lo.	Invoice No.	<u>Purcha</u>	se Order No	<u>).</u>		Total (Cost
CH-SP	CHARGE Sh	nop Supplies		50	03163		1							\$2.00
												COMML		2.00
Job Code		Job Description			<u>En</u>	ployee	No.	<u>Start</u>		Finish		Quantity	Total (Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,TAIL,S	STOP,TURN	I,ETC 1	1310047	•	06/	24/2022 13:48:42	06/24/202	22 15:04:44		1.27		\$149.53
												LABOR		149.53
Job Code		Job Description				Part No	<u>.</u>	Des	cription	<u>L</u>	Jnit Price	<u>Quantity</u>	Total (Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,TAIL,S	STOP,TURN	I,ETC 3	157		BU	LB-BRAKE/TURN	I/PARK		0.95	1		\$0.95

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 43743

Work Order Notes

(LISAPATE) Left rear brake light is out

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(EHOWELL) Replaced left brake light bulb. EH

UNIT NO:		242405 2	017 CHEV	ROLE	T EX	PRES	S 2500 P	ASSEN	GER	WORK ORI	DER NO):	44162		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	C	OMPL	D DAT	DATE: E:	08/09/2	2022 15:42 2022 08:56 2022 13:33 er Van	6:29	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	52805 DATE:	08/09/	sity Automotive S METER 2 - N: 2017 GEFG0H131398	0	
JOB CODE	į	JOB DESCRIPTION	<u>1</u> :	<u>STAT</u>	RSN	WRTY	JOB LO	C LABO	OR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	<u> </u>	0.99	\$117.15	\$69.74		\$0.00	\$186.89	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE		0.00	\$0.00	\$0.00		\$2.00	\$2.00	
JOB COUN	T: 2				wo	RK OR	DER TOTA	۱L:	0.99	117.1	5	69.74	2.00		188.89
Job Code		Job Description	<u>n</u>		<u>v</u>	endor N	<u>lo.</u>	<u>Invo</u>	ice No.	<u>Purchase</u>	Order No	<u>o.</u>		<u>Total</u>	<u>Cost</u>
CH-SP	CHARGE Sh	op Supplies		50	3163			1							\$2.00
													COMML		2.00
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	No.	<u>s</u>	<u>tart</u>	<u>Fi</u>	nish		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		11	901357	•		08/04/2022	07:14:27	08/04/2022	07:52:17		0.63		\$74.41
66-PM-PMA	PERFORM (OIL CHANGE		11	074414	ļ		08/04/2022	07:12:17	08/04/2022	07:34:01		0.36		\$42.74
													LABOR	-	117.15
Job Code		Job Description	<u>n</u>			Part No	<u>).</u>		Des	cription		Unit Pric	e Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		5\	V30T			5W30 SYN	THETIC C	OIL THOMAS CAN	Л2	7.	32 6		\$43.92
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB160			OIL FILTER	3			11.	25 1		\$11.25
66-PM-PMA	PERFORM (OIL CHANGE		В	ALRS41	31		BALDWIN	AIR FILTE	ER .		14.	571		\$14.57
													PARTS		69.74

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 44162

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/AMG Performed PM.

UNIT NO:		242405 2017	7 CHEVROL	ET EX	PRESS	5 2500 PAS	SSENGER	WORK OR	DER NO:	458	828		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENI COMP CLOSI 2017 Chevrole	D DAT	DATE: E:	01/19/202	23 10:35:40 23 15:48:46 23 07:16:18 /an	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 54540 DATE : (ME 7 08/09/201	TER 2 - N:	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERI	AL CO	MMERCIAL	TOTAL C	COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.04	\$4.72	\$15.63	\$0.0	00	\$20.35	
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.27	\$31.79	\$0.00	\$0.0	00	\$31.79	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00	
JOB COUN	T: 3			WC	RK ORI	DER TOTAL:	0.31	36.5	51 1	5.63	5.00		57.14
Job Code		Job Description		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purchase</u>	e Order No.			Total C	<u>Cost</u>
CH-SP	CHARGE Sh	nop Supplies	5	03163		1							\$5.00
											COMML		5.00
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	<u>nish</u>		Quantity	Total C	Cost
66-PM-PMA	PERFORM (OIL CHANGE	•	1901357	,	01/	/19/2023 08:30:54	01/19/2023	08:42:14		0.19		\$22.29
66-PM-PMA	PERFORM (OIL CHANGE	,	1901357	7	01/	/19/2023 07:58:32	01/19/2023	08:03:22		0.08		\$9.51
03-51-038	REPLACE N	IEW WIPER BLADES	,	1901357	,	01/	/19/2023 07:55:51	01/19/2023	07:58:15		0.04		\$4.72
										,	LABOR		36.52
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	cription	<u>Un</u>	it Price	Quantity	<u>Total C</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES	2	2-1		WI	PER BLADE 22" 1	TRICO EXACT		7.82	2		\$15.63
											PARTS		15.63

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 45828

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 54540 Vehicle has been 1735 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

UNIT NO:		242405	2017 CHE	VROLE	ET EX	PRESS	3 2500 PA	SSENGER	WORK OF	RDER NO	: 40	6501		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	2017	OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE: E:	03/28/20	23 08:53:36 23 08:35:42 23 14:01:37 Van	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 57059 DATE :	M 08/09/20	ty Automotive 9 ETER 2 - N: 017 EFG0H131398	0	
JOB CODE	<u>.</u>	JOB DESCRIPTIO	<u>N</u>	STAT	<u>RSN</u>	WRTY		LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.17	\$20.03	\$69.81	\$0	0.00	\$89.84	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	T: 2				WC	RK ORI	DER TOTAL	.: 0.17	20.	03	69.81	5.00		94.84
Job Code		Job Description	<u>on</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purchas</u>	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>on</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		12	2052187	7	0:	3/23/2023 15:27:37	03/23/202	3 15:37:48		0.17		\$20.03
												LABOR		20.03
Job Code		Job Description	on_			Part No	<u>.</u>	<u>Des</u>	scription	<u> </u>	Jnit Price	Quantity	Total	Cost
66-PM-PMA	PERFORM (OIL CHANGE		5\	W30T		51	W30 SYNTHETIC	OIL THOMAS CA	AM2	10.70) 6		\$64.17
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB160		0	IL FILTER			5.64	11		\$5.64
												PARTS		69.81

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 46501

Work Order Notes

(LISAPATE) PM-Do annual SI (EHANNAH) replace new tires

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/GC MILEAGE-57059

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

242405

UNIT NO:

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

46543

WORK ORDER NO:

USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P 2017 (OPENE COMPL CLOSE Chevrole	ETED	DATE: E:	04/11/202	23 08:36:08 3 08:50:27 3 15:41:04 ⁄an	LOCATION: G METER 1 - M: IN-SERVICE DA UNIT SERIAL N	57061 ATE :	ME 08/09/201	TER 2 - N:	0
JOB CODE		JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL CO	MMERCIAL	TOTAL COST
03-15-011	REPLAC	E NEW PITMAN ARM	DON	N	Ν	GARAGE	0.03	\$3.64	\$137.66	\$0.0	00	\$141.30
03-15-012	REPLAC	E NEW IDLER ARM	DON	N	Ν	GARAGE	2.05	\$242.29	\$228.39	\$0.0	00	\$470.68
06-15	INSPECT	T STEERING	DON	0	Ν	GARAGE	0.19	\$22.19	\$0.00	\$0.0	00	\$22.19
66-17-013	PERFOR	M ALIGNMENT	DON	0	Ν	GARAGE	1.18	\$138.75	\$0.00	\$0.0	00	\$138.75
66-17-028	PERFOR	M MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.03	\$121.57	\$655.42	\$0.0	00	\$776.99
66-79-003	PERFOR	M SAFETY INSPECTION	DON	Υ	N	GARAGE	0.29	\$34.68	\$0.00	\$0.0	00	\$34.68
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00
JOB COUN	T: 7			WC	RK ORE	DER TOTAL:	4.77	563.12	1,0	021.47	5.00	1,589.59
Job Code		Job Description		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchase (Order No	<u>.</u>		Total Cost
CH-SP	CHARGE Sh	nop Supplies	5	03163		1						\$5.00
-											COMML	5.00
Job Code		Job Description		<u>En</u>	ployee	No.	<u>Start</u>	<u>Fini</u>	<u>ish</u>		Quantity	Total Cost
06-15	INSPECT ST	ΓEERING	1	1074414		03/	28/2023 08:45:24	03/28/2023 08	8:56:41		0.19	\$22.19
66-79-003	PERFORM S	SAFETY INSPECTION	1	1074414		03/	28/2023 08:57:22	03/28/2023 09	9:15:00		0.29	\$34.68
66-17-028	PERFORM N	MOUNT AND BALANCE TIRES	1	1074414	ļ	03/	28/2023 09:25:54	03/28/2023 09	9:25:54		0.00	\$0.00
66-17-028	PERFORM N	MOUNT AND BALANCE TIRES	1	1074414	ļ	03/	28/2023 09:30:00	03/28/2023 09	9:48:47		0.31	\$36.94
66-17-028	PERFORM N	MOUNT AND BALANCE TIRES	1	1074414		03/	28/2023 13:02:34	03/28/2023 13	3:45:36		0.72	\$84.63
03-15-012	REPLACE N	IEW IDLER ARM	1	1310047	•	03/	31/2023 07:59:23	03/31/2023 10	0:02:35		2.05	\$242.29
03-15-011	REPLACE N	IEW PITMAN ARM	1	1310047	•	03/	31/2023 10:02:35	03/31/2023 10	0:04:26		0.03	\$3.64
66-17-013	PERFORM A	ALIGNMENT	1	1310047	•	04/	10/2023 08:02:22	04/10/2023 09	9:12:55		1.18	\$138.75
											LABOR	563.12
Job Code		Job Description			Part No	<u>.</u>	Des	<u>cription</u>	<u>U</u>	Init Price	Quantity	Total Cost
66-17-028	PERFORM N	MOUNT AND BALANCE TIRES	2	3131		TP	MS SNAP IN VAL	VE 21060		3.50	4	\$13.98
El4E ME	MODETAIL	Mark Order Detail v20.0										Dega:1

2017 CHEVROLET EXPRESS 2500 PASSENGER

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.39	1	\$0.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.53	2	\$1.05
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	1	\$0.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.75	1	\$0.75
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.16	1	\$1.16
03-15-012	REPLACE NEW IDLER ARM	TRWJIA204	IDLER ARM	116.37	1	\$116.37
03-15-012	REPLACE NEW IDLER ARM	TRWJIA204	IDLER ARM	112.02	1	\$112.02
03-15-011	REPLACE NEW PITMAN ARM	TRWJPA160	PITMAN ARM	137.66	1	\$137.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	159.11	4	\$636.42
					PARTS	1021.47

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 46543

Work Order Notes

(EKIMBREL) 4 TIRES, ALIGNMENT, IDLER ARM, AND PITMAN ARM.

Job Notes

03-15-011 - REPLACE NEW PITMAN ARM

(EHOWELL) Replaced pitman arm. Performed a road test after repair. EH

03-15-012 - REPLACE NEW IDLER ARM

(EHOWELL) Replaced idler arm. EH (EKIMBREL) idler arm was 2 pieces

06-15 - INSPECT STEERING

(SHARBIN) Inspected the steering found the idler arm and the pitman arm both have play in them. EH Verified. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) Cancelled from Work Order# 46501. By User ID EKIMBREL on 3/28/2023 8:34 AM.

(SHARBIN) Performed a safety inspection. Found the pitman arm and the idler arm both have play in them. Also will need 4 tires due to 2217 build dates. Found no other issues at this time. SH

UNIT NO:		242405 201	7 CHEVROLI	ET EX	PRES	S 2500 PA	SSENGER	WORK C	RDER NO	D: 4	6764	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENE COMPI CLOSE 2017 Chevrole	LETED ED DAT	DATE: E:	04/24/20 04/24/20	23 09:10:31 23 11:05:03 23 13:10:45 Van	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 57451 E DATE:	M 08/09/20	ty Automotive (ETER 2 - N: 017 EFG0H13139	0
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL C	OMMERCIAL	TOTAL COST
06-13	INSPEC ⁻	T BRAKES	DON	0	N	GARAGE	1.37	\$161.86	\$0.00	\$0	0.00	\$161.86
10-13	SERVIC	E BRAKES	DON	0	N	GARAGE	1.00	\$118.00	\$10.01	\$0	0.00	\$128.01
CH-SP	CHARGE	E Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00
JOB COUN	T: 3			W	ORK OR	DER TOTAL	: 2.3	7 27	9.86	10.01	5.00	294.87
Job Code CH-SP	CHARGE SI	Job Description hop Supplies	5	<u>\</u> 503163	<u>/endor N</u>	lo. 1	Invoice No.	Purch	ase Order N	lo.		Total Cost \$5.0
											COMML	5.00
Job Code		Job Description		<u>Er</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
10-13	SERVICE B	RAKES	1	131004	7	04	/24/2023 07:00:0	04/24/20	023 08:00:00		1.00	\$118.0
06-13	INSPECT B	RAKES	1	131004	7	04	/20/2023 08:52:3	5 04/20/20	023 08:56:42		0.07	\$8.1
06-13	INSPECT B	RAKES	1	131004	7	04	/20/2023 07:12:5	4 04/20/20	23 07:32:38		0.33	\$38.8
06-13	INSPECT B	RAKES	1	131004	7	04	/19/2023 14:03:0	04/19/20	23 14:15:00		0.20	\$23.6
06-13	INSPECT B	RAKES	1	131004	7	04	/20/2023 09:14:3	8 04/20/20	023 09:14:38		0.00	\$0.0
06-13	INSPECT B	RAKES	1	131004	7	04	/20/2023 09:30:0	04/20/20	23 09:40:48		0.18	\$21.2
06-13	INSPECT B	RAKES	1	131004	7	04	/20/2023 11:12:1	7 04/20/20	23 11:47:56		0.59	\$70.1
											LABOR	279.80
Job Code		Job Description			Part No) <u>.</u>	<u>De</u>	scription		Unit Price	Quantity	Total Cost
06-13	INSPECT B	RAKES	C	C111		RI	ED BRAKE CLEA	NER		6.26	3 1	\$6.2
06-13	INSPECT B	RAKES	C	C111		RI	ED BRAKE CLEA	NER		6.26	5 (1)	(\$6.26
10-13	SERVICE B	RAKES	(C111		RI	ED BRAKE CLEA	NER		6.26	5 1	\$6.2
10-13	SERVICE B	RAKES	C	7480		R	DLOC DISC 2 IN	COARSE		1.88	3 2	\$3.7
06-13	INSPECT B	RAKES	C	7480		R	DLOC DISC 2 IN	COARSE		1.88	3 (2)	(\$3.75
06-13	INSPECT B	RAKES	C	7480		R	DLOC DISC 2 IN	COARSE		1.88		
											PARTS	10.0

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 46764

Work Order Notes

(EHANNAH) brakes are squealing.

Job Notes

06-13 - INSPECT BRAKES

(EHOWELL) Brake pads have plenty of life left in them. All four brake calipers were removed. Reconditioned brake pads using a roloc disc. Applied brake grease to the back of brake pads, to the caliper slide pins, and to the slot where the pad rides on the bracket hardware. Cleaned caliper pistons. Performed a road test after repair. EH 1.5 HRS

10-13 - SERVICE BRAKES

(LISAPATE) Brake pads have plenty of life left in them. All four brake calipers were removed. Reconditioned brake pads using a roloc disc. Applied brake grease to the back of brake pads, to the caliper slide pins, and to the slot where the pad rides on the bracket hardware. Cleaned caliper pistons. Performed a road test after repair. EH 1.5 HRS

UNIT NO:		242405 20	17 CHEVROLI	ET EX	PRESS	6 2500 PA	SSENGER	WORK O	RDER NO:	47	787		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENE COMPI CLOSE 2017 Chevrole	ETED	DATE: E:	08/02/202 08/02/202	23 08:12:28 23 13:59:20 23 15:27:32 ⁄an	LOCATION METER 1 - IN-SERVICI UNIT SERIA	E DATE:	ME 08/09/20	TER 2 - N:	0	
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERI	AL CO	<u>OMMERCIAL</u>	TOTAL	COST
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	Ν	GARAGE	0.33	\$38.94	\$0.00	\$0.	00	\$38.94	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
JOB COUN	IT: 2			WC	RK ORI	DER TOTAL:	0.33	38	3.94	0.00	5.00		43.94
Job Code CH-SP	CHARGE SI	Job Description	5	<u>\</u> 03163	endor N	lo. 1	Invoice No.	<u>Purcha</u>	se Order No.			<u>Total</u>	<u>Cost</u> \$5.00
	0	.op outplies	·			·					COMML		5.00
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>		Finish_		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	1	1074414	1	08	01/2023 09:16:48	08/01/20	23 09:16:48		0.00		\$0.00
66-PM-PMA	PERFORM (OIL CHANGE	1	1074414	1	08	01/2023 09:16:48	08/01/20	23 09:16:48		0.00		\$0.00
66-PM-PMA	PERFORM (OIL CHANGE	1	1074414	1	08	01/2023 09:16:48	08/01/20	23 09:36:36		0.33		\$38.94
											LABOR		38.94

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 47787

Work Order Notes

(EHANNAH) pm- replace wipers (EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Vehicle has been driven 880 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

UNIT NO:		242405 201	7 CHE	/ROLE	ET EX	PRESS	S 2500 PA	SSENGER	WORK O	RDER NO	: 48	340		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P		OPENE COMPL CLOSE Chevrole	ETED	DATE: E:	09/28/20	23 12:58:40 23 14:17:15 23 14:45:22 Van	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 58939 E DATE:	ME 08/09/20		0	
JOB CODE	<u>.</u>	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL .	TOTAL	COST
06-01	INSPECT	AIR CONDITIONING, H	EAT, VE	DON	0	N	GARAGE	1.41	\$166.12	\$0.00	\$0.	00	\$166.12	
66-01-058	PERFOR	M EVAC AND RECHARG	GE FRE	DON	N	Ν	GARAGE	0.44	\$51.79	\$25.52	\$0.	00	\$77.31	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
PR-05-034	PROGRA	M ECM/ENGINE CONTR	ROL MC	DON	N	N	GARAGE	0.33	\$39.24	\$0.00	\$0.	00	\$39.24	
JOB COUN	T: 4				wo	RK ORI	DER TOTAL	2.18	257	7.15	25.52	5.00		287.67
Job Code		Job Description			<u>v</u>	endor N	l <u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description			<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
06-01	INSPECT AI	R CONDITIONING, HEAT, V	/ENT	1	1310047	•	09	/28/2023 10:22:20	09/28/20	23 10:54:10		0.53		\$62.61
66-01-058	PERFORM E	EVAC AND RECHARGE FRE	EON	1	1310047	•	09	/28/2023 10:55:55	09/28/20	23 11:22:15		0.44		\$51.79
PR-05-034	PROGRAM I	ECM/ENGINE CONTROL M	ODULE	1	1310047	•	09	/28/2023 10:02:23	09/28/20	23 10:22:20		0.33		\$39.24
06-01	INSPECT AI	R CONDITIONING, HEAT, V	/ENT	1	1310047	ī	09	/27/2023 14:59:31	09/27/20	23 15:52:09		0.88		\$103.51
												LABOR		257.15
Job Code		Job Description				Part No	<u>.</u>	<u>Des</u>	<u>cription</u>		Unit Price	Quantity	<u>Total</u>	Cost
66-01-058	PERFORM E	EVAC AND RECHARGE FRE	EON	R	134AOZ	<u>.</u>	R ²	134A FREON-OUN	CE		0.99	5		\$4.95
66-01-058	PERFORM E	EVAC AND RECHARGE FRE	EON	R	ECYCLI	ED FREC	N OZ RI	ECLAIMED FREON	N OZ		0.14	45		\$6.08
66-01-058	PERFORM E	EVAC AND RECHARGE FRE	EON	4	99108		R	12 AND R134A A/C	DYE		14.49	1		\$14.49
												PARTS		25.52

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 48340

Work Order Notes

(EHANNAH) Check AC- not blowing cold

Job Notes

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(EHOWELL) Found bulletin #16-NA-335 stating that the customer may comment that the AC does not blow cold. This condition may be caused by the following:

The high side pressure cut off calibration set to high, which may allow the high side pressure relief to open before the compressor clutch is disabled. This will cause a low refrigerant condition.

Excessive a/c compressor clutch off time during compressor cycling.

Correction: An updated ECM calibration has been released to correct these concerns.

Note: If the a/c compressor high side relief has opened, check the refrigerant charge.

Also, inspected vehicle with a black light for refrigerant leaks, but did not find any. EH .5 HR

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Recovered 2.79 lb. of refrigerant. Drained .7 oz. of oil. Pulled a vacuum. Leak tested passed. Injected approximately 1.0 oz. of oil/dye using the spot gun. Charged the vehicle with 3.12 lb. of refrigerant. EH

CH-SP - CHARGE Shop Supplies

PR-05-034 - PROGRAM ECM/ENGINE CONTROL MODULE

(EHOWELL) Observed the vehicle's current calibration and verified that the module needed updating to improve the AC performance. Programmed engine control module via GM Service Programming System and performed a crankshaft variation learn procedure after the repair. The AC is now blowing cold. EH

NOTE: There was one available VIN slot in our SPS programming account, therefore, there was no purchase made to program this vehicle.

UNIT NO:		242405	2017 CHEVF	ROLE	T EXI	PRESS	2500 PA	SSENGER	WORK ORD	ER NO:	4	9217		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	C	OMPL LOSE	D DATI ETED I D DATE Expre	DATE:	12/12/202	23 12:32:34 23 10:56:55 23 09:34:05 Van	LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL I	61335 ATE :	M 08/09/20	ETER 2 - N:	0	
JOB CODE		JOB DESCRIPTIO	<u>N</u> <u>S</u>	TAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL C	OMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY		OON	N	Ν	GARAGE	0.09	\$10.39	\$199.98	\$0	0.00	\$210.37	
66-PM-PMA	PERFOR	M OIL CHANGE		OON	Р	Ν	GARAGE	0.23	\$27.40	\$63.15	\$0	0.00	\$90.55	
CH-SP	CHARGE	Shop Supplies	Г	OON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.32	37.79) 2	63.13	5.00		305.92
Job Code		Job Description	o <u>n</u>		V	endor N	<u>o.</u>	Invoice No.	Purchase	Order No.	ı.		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	3163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u>Fin</u>	<u>ish</u>		Quantity	<u>Total</u>	Cost
03-32-002	REPLACE N	EW BATTERY		11	074414		12	/11/2023 15:42:08	12/11/2023 1	5:47:25		0.09		\$10.39
66-PM-PMA	PERFORM (OIL CHANGE		11	074414		12	/11/2023 15:19:46	12/11/2023 1	5:33:42		0.23		\$27.40
												LABOR		37.79
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	Des	cription	<u>U</u>	nit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB160		OI	L FILTER			5.64	. 1		\$5.64
66-PM-PMA	PERFORM (OIL CHANGE		5\	V30T		5V	V30 SYNTHETIC (OIL THOMAS CAM	12	9.59	6		\$57.51
03-32-002	REPLACE N	EW BATTERY		78	1		BA	ATTERY BCI 78 77	0 CCA		199.98	11		\$199.98
												PARTS	-	263.13

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 49217

Work Order Notes

(EHANNAH) pm

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Battery tested bad. Replaced battery ALT charging at 14.8 volts. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

UNIT NO:		242405	2017 CHE\	/ROLE	ET EX	PRES	S 2500 PA	SSENGER	WORK O	RDER NO:	: 49	594		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P		OPENE COMPL CLOSE Chevrole	ETED	DATE: E:	02/13/202	24 12:03:34 24 08:41:43 24 09:28:23 ⁄an	LOCATION METER 1 - IN-SERVICE UNIT SERIA	E DATE:	ME 08/09/201	TER 2 - N:	0	
JOB CODE	<u>:</u>	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	MMERCIAL	TOTAL	COST
03-50-100	REPLAC	E NEW BELT, SERI	PENTINE OR	DON	N	N	GARAGE	0.53	\$62.80	\$63.59	\$0.0	00	\$126.39	
03-50-103	REPLAC	E NEW BELT TENS	SIONER	DON	N	Ν	GARAGE	0.92	\$108.63	\$108.14	\$0.0	00	\$216.77	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00	
SO-05	SCAN O	JT ELECTRONIC E	NGINE EEC	DON	0	N	GARAGE	2.35	\$277.17	\$0.00	\$0.0	00	\$277.17	
JOB COUN	T: 4				wo	RK ORI	DER TOTAL:	3.80	448	3.60	171.73	5.00)	625.33
Job Code		Job Descripti	<u>ion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descripti	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
03-50-100	REPLACE N	EW BELT, SERPENT	INE OR MISC.	1	2052187	7	01	/29/2024 13:45:56	01/29/202	24 14:17:52		0.53		\$62.80
03-50-103	REPLACE N	EW BELT TENSIONE	R	1	2052187	7	01	/29/2024 09:14:06	01/29/202	24 10:09:20		0.92		\$108.63
SO-05	SCAN OUT	ELECTRONIC ENGIN	E EEC SYSTEM	1 1	1310047	,	01	/29/2024 07:27:20	01/29/20	24 09:48:16		2.35		\$277.17
												LABOR		448.60
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>	Des	cription	<u>u</u>	Jnit Price	Quantity	<u>Total</u>	Cost
03-50-100	REPLACE N	EW BELT, SERPENT	INE OR MISC.	C	TL4060	930	BE	LT			63.59	1		\$63.59
03-50-103	REPLACE N	EW BELT TENSIONE	R	C	TL4943	6	TE	NSIONER PULLE	YASSEMBLY		108.14	1		\$108.14
												PARTS		171.73

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 49594

Work Order Notes

(EHANNAH) pulley making a squeaking sound you can hear when sitting idle or shifting gears.

Job Notes

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(JWRIGHT) replaced drive belt. JAW

03-50-103 - REPLACE NEW BELT TENSIONER

(JWRIGHT) Replaced belt tensioner. JAW

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

UNIT NO: 242405		242405 20	17 CHE	VROLE	T EX	PRESS	2500 PA	SSENGER	WORK	ORDER NO:		49938		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2017 Chevrolet Express 250			DATE: E:	03/04/202	24 08:58:53 24 09:47:01 24 14:07:03 /an	METER	ION: GARAGE - 1 - M: 61929 Vice date: Erial no:	08/09/2	METER 2 - N:	0	
JOB COD	<u>E</u>	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LAE	OR MATER	RIAL	COMMERCIAL	TOTAL	COST
03-02-061	REPLAC	E NEW WINDSHIELD		DON	0	N	GARAGE	0.00	\$0.00	\$0.00		\$402.21	\$402.21	
16-71	TRANSF	ORT BODY		DON	Ν	Ν	GARAGE	0.50	\$59.00	\$0.00	:	\$0.00	\$59.00	
CH-SP	CHARGE Shop Supplies			DON	2	N	GARAGE	0.00	\$0.00	\$0.00	;	\$5.00	\$5.00	
JOB COUN	JOB COUNT: 3				wo	RK ORI	DER TOTAL:	0.50		59.00	0.00	407.21		466.21
Job Code		Job Description			<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Pui</u>	chase Order No	<u>.</u>		<u>Total</u>	Cost
03-02-061	REPLACE N	IEW WINDSHIELD		11	078716	;	21	16229						\$402.21
CH-SP	CHARGE SI	nop Supplies		50	3163		1							\$5.00
												COMML		407.21
Job Code		Job Description		Employee No			No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
16-71	TRANSPOR	TRANSPORT BODY		11	11399745			/04/2024 07:00:00	03/04/2024 07:30:00			0.50		\$59.00
												LABOR	,	59.00

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 49938

Work Order Notes

(EHANNAH) repair windshield- transport body

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield. PD by CC

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Glass Dr by Cw

24-02-061 - REPAIR WINDSHIELD

UNIT NO:		242405	2017 CHEVRO	LET	EXF	PRESS	2500 PAS	SENGER	WORK O	RDER NO) :	50726		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P	CON	NED C IPLET SED C olet Ex	ED [DATE:	05/06/202	4 12:58:58 4 07:37:06 4 07:37:10 ⁄an	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 65575 E DATE:	08/09/	sity Automotive S METER 2 - N: 2017 GEFG0H131398	0	
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u>N</u> STA	<u> </u>	<u>SN</u>	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL	COMMERCIAL	TOTAL	COST
16-02-061	TRANSP	ORT WINDSHIELD	DO	N A	A	Ν	GARAGE	0.00	\$0.00	\$0.00		\$0.00	\$0.00	
24-02-061	REPAIR '	WINDSHIELD	DO	1 N	N	Ν	GARAGE	0.00	\$0.00	\$0.00		\$402.50	\$402.50	
66-PM-PMA	PERFOR	M OIL CHANGE	DO	N I	Р	N	GARAGE	0.01	\$1.41	\$50.21		\$0.00	\$51.62	
CH-SP	CHARGE	Shop Supplies	DO	N :	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
JOB COUNT: 4					WOI	RK ORE	ER TOTAL:	0.01		1.41	50.21	407.50		459.12
Job Code		Job Description	<u>on</u>		Ve	endor N	<u>0.</u>	Invoice No.	Purcha	ase Order N	<u>o.</u>		<u>Total</u>	Cost
24-02-061	REPAIR WIN	IDSHIELD		11078	3716		118	3109						\$402.50
CH-SP	CHARGE SI	nop Supplies		50316	63		1							\$5.00
												COMML		407.50
Job Code		Job Description	on_		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		1239	5904		05/	02/2024 14:44:58	05/02/20	24 14:45:41		0.01		\$1.41
												LABOR		1.41
Job Code		Job Description	on_		<u> </u>	Part No		Des	cription		Unit Pric	e Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		5W30	T		5W	30 SYNTHETIC C	OIL THOMAS CAM2		7.	43 6		\$44.55
66-PM-PMA	PERFORM (OIL CHANGE		BALB	160		OIL	FILTER			5.	661		\$5.66
												PARTS		50.21

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 50726

Work Order Notes

(EHANNAH) pm- windshield by Glass Dr.

Job Notes

16-02-061 - TRANSPORT WINDSHIELD

(IFALLS) chad performed transport

24-02-061 - REPAIR WINDSHIELD

(IFALLS) glass dr replaced windshield

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

UNIT NO:		242405 20	017 CHE	VROLE	T EX	PRESS	S 2500 PAS	SSENGER	WORK (ORDER NO	: 508	305	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507301 CLOSED SCHEDULED 17CHEVEX2500P		OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE: E:	05/20/202	4 08:09:12 4 10:41:41 4 15:42:37 ′an			ME 7	ΓER 2 - N:	0
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL CO	MMERCIAL	TOTAL COST
03-27-055	REPLAC	E NEW BULKHEAD C	ONNECTC	DON	N	Ν	GARAGE	0.00	\$0.00	\$101.58	\$0.0	0	\$101.58
03-34-002	REPLAC	E NEW LAMPS-REAR	,TAIL,STO	DON	N	N	GARAGE	0.00	\$0.00	\$0.99	\$0.0	0	\$0.99
03-51-038	REPLAC	E NEW WIPER BLADI	ES	DON	Ν	N	GARAGE	0.00	\$0.00	\$22.50	\$0.0	0	\$22.50
06-13	INSPECT	BRAKES		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.0	0	\$0.00
06-34-003	INSPECT	SIGNAL,PARKING, 8	& BACKUP	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.0	0	\$0.00
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	0	\$5.00
JOB COUN	Т: 6				WC	RK ORI	DER TOTAL:	0.00		0.00	125.07	5.00	130.07
Job Code CH-SP	CHARGE Sh	Job Description op Supplies	1	50	<u>V</u>)3163	endor N	l <u>o.</u> 1	Invoice No.	<u>Purch</u>	nase Order No	<u>.</u>		Total Cost \$5.00
											•	COMML	5.00
Job Code		Job Description	<u>l</u>			Part No	<u>.</u>	Des	cription	<u> </u>	Jnit Price	Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		Х	C22		22'	WIPER			11.25	2	\$22.50
03-34-002	REPLACE N	EW LAMPS-REAR,TAIL,	STOP,TURN	I,ETC 3	157		BU	LB-BRAKE/TURN	/PARK		0.99	1	\$0.99
03-27-055	REPLACE N	EW BULKHEAD CONNE	CTOR	19	917808	5	CC	NNECTOR			101.58	1	\$101.58
											•	PARTS	125.07

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 50805

Work Order Notes

(EHANNAH) check left back blinker- wipers- ABS

Job Notes

03-27-055 - REPLACE NEW BULKHEAD CONNECTOR

(EHOWELL) Removed all wires/terminals from the old ABS connector and transferred them to the new connector. Allowed the wiring harness to have some slack in it to help prevent the concern form reoccurring. Plugged in connector and performed a road test to verify that the ABS light did not come back on. Also, activated the ABS by making hard stops on the gravel. EH 1.0 HR

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(GARAGE) Replaced left rear blinker bulb. JAW

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wiper blades and reinstalled the passenger wiper arm with loctite and a washer to fasten it better. JAW

06-13 - INSPECT BRAKES

(GARAGE) Inspected abs issues and found code c0110-04 for brake pump motor open circuit. Inspected fuse and found fuses are good. Removed connector at the pump motor and inspected ground and power. All ground and power is good. Found the positive terminal 38 pin was loose due to plastic clip being broken and not holding the wire in place properly, verified work with Ethan, Needs new plug for the ABS pump motor. JAW

(EHOWELL) It appeared that the plastic retainer for terminal 38 was broken due to the wire being too short. The constant outward pull on the wire may have caused the retainer to break. EH .5 HR

06-34-003 - INSPECT SIGNAL, PARKING, & BACKUP LAMPS

UNIT NO:		242405 2	017 CHE	VROLE	ET EX	PRESS	3 2500 PA	SSENGER	WORK O	RDER NO): 50	0930		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		507301 CLOSED SCHEDULED 17CHEVEX2500P	OPENED DATE: COMPLETED DATE: CLOSED DATE: Chevrolet Express 2500 F			05/23/2024 11:00:49 05/30/2024 13:54:50 05/31/2024 10:06:25 Passenger Van		LOCATION: GARAGE - METER 1 - M: 66164 IN-SERVICE DATE: UNIT SERIAL NO:		- University Automotive : METER 2 - N: 08/09/2017 1GAWGEFG0H131398		0		
JOB CODE	<u> </u>	JOB DESCRIPTION	<u> </u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-13-107	REPLAC	E NEW BRAKE DISTF	RIBUTION '	DON	N	Ν	GARAGE	0.00	\$0.00	\$625.02	\$0	0.00	\$625.02	
03-34-001	REPLAC	E NEW HEADLAMPS		DON	N	Ν	GARAGE	0.00	\$0.00	\$25.05	\$0	0.00	\$25.05	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
SO-00	SCAN O	UT COMPLETE VEHIC	CLE	DON	0	N	GARAGE	1.91	\$225.51	\$0.00	\$0	0.00	\$225.51	
JOB COUNT: 4				WORK ORDER			: 1.91	225.51		650.07	5.00		880.58	
Job Code		Job Description	<u>1</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>1</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	Finish		Quantity	<u>Total</u>	Cost
SO-00	SCAN OUT	COMPLETE VEHICLE		1	1310047	•	0	05/23/2024 13:54:13		24 15:48:53		1.91		\$225.51
												LABOR		225.51
Job Code		Job Description	<u>1</u>			Part No	<u>.</u>	Des	<u>Description</u> <u>U</u>			Quantity	<u>Total</u>	Cost
03-13-107	REPLACE N	IEW BRAKE DISTRIBUT	ION VALVE	2	5879231		В	RAKE VALVE			585.78	1		\$585.78
03-13-107	REPLACE N	IEW BRAKE DISTRIBUT	ION VALVE	В	RAKE F	LUID	В	RAKE FLUID DOT	3 12OZ		4.40	6		\$26.37
03-13-107	REPLACE N	IEW BRAKE DISTRIBUT	ION VALVE	C	C111			ED BRAKE CLEAN	NER		6.44	2		\$12.87
03-34-001	REPLACE N	IEW HEADLAMPS		H6054 LMP		/IP	В	ULB-HEADLIGHT-	-HALOGEN		25.05	51		\$25.05
												PARTS		650.07

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 50930

Work Order Notes

(EHANNAH) scan out

Job Notes

03-13-107 - REPLACE NEW BRAKE DISTRIBUTION VALVE

(EHOWELL) Replaced the brake pressure modulator valve assembly. Bled the brake lines at the master cylinder, at the BPMV, and at all four corners of the vehicle. Afterwards, performed an Automated Bleed Procedure with the scan tool. The fluid level is near the max line. Performed a road test after repairs. Made hard stops on pavement and gravel. The ABS light did not come back on. EH

03-34-001 - REPLACE NEW HEADLAMPS

(EHOWELL) The left head lamp had moisture in it. Replaced the left head lamp assembly. EH

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(EHOWELL) Found DTC: C0110:04 Pump Motor Circuit Open. The motor on the brake pressure modulator valve (BPMV) assembly is faulty. Power and ground to the motor were verified. EH

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER **WORK ORDER NO:** 51250 **USING DEPT NO:** 507301 OPENED DATE: 06/21/2024 08:13:26 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 06/21/2024 09:44:54 **WO STATUS:** METER 1 - M: 66380 COMPLETED DATE: **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 06/21/2024 10:22:14 **IN-SERVICE DATE:** 08/09/2017 **TECH SPEC NO:** 17CHEVEX2500P 2017 Chevrolet Express 2500 Passenger Van **UNIT SERIAL NO:** 1GAWGEFG0H1313989 COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION <u>STAT</u> 05-02-037 REPLACE USED SEAT ASSEMBLY DON Ν **GARAGE** 0.00 \$0.00 \$0.00 \$0.00 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 0.00 0.00 0.00 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** 05-02-037 REPLACE USED SEAT ASSEMBLY 12395904 06/21/2024 09:19:21 06/21/2024 09:19:21 0.00 \$0.00 LABOR 0.00

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 51250

Work Order Notes

(EHANNAH) Please replace all seats that were removed and stored here.

Job Notes

05-02-037 - REPLACE USED SEAT ASSEMBLY

(FCONTRER) Perform replaced used seat assembly fc -sh - cg

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 51641

USING DEPT NO: 507301 OPENED DATE: 07/30/2024 09:37:21 LOCATION: GARAGE - University Automotive Services

WO STATUS: OPEN COMPLETED DATE: METER 1 - M: 66584 METER 2 - N: 0

WO VISIT REASON: SCHEDULED CLOSED DATE: IN-SERVICE DATE: 08/09/2017

TECH SPEC NO: 17CHEVEX2500P 2017 Chevrolet Express 2500 Passenger Van UNIT SERIAL NO: 1GAWGEFG0H1313989

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	L COMMER	CIAL TOTAL	COST
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00	
JOB COUNT: 1			wo	RK ORI	DER TOTAL:	0.00	0	.00 0.	.00	0.00	0.00

The University of Alabama

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

UNIT NO: 242405 2017 CHEVROLET EXPRESS 2500 PASSENGER WORK ORDER NO: 51641

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag/ RC

Report Printed: 08/06/2024 21:00:13 By User: GLOBETTI

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Tue Aug 06 2024 21:00:13 Report User: GLOBETTI

TZ: Central Standard Time

DLL Version: 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and((view udc main.serial no)"

= '1GAWGEFG0H1313989') //Q=