

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 40323

USING DEPT NO: 507301	OPENED DATE: 07/01/2021 11:54:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/01/2021 11:55:34	METER 1 - M: 160 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2021 09:17:37	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **0.00** **118.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11074414	07/01/2021 11:55:00	07/01/2021 12:55:00	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 40323

Work Order Notes

(LISAPATE) New unit needs PDI inspection

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 40768

USING DEPT NO: 507301	OPENED DATE: 08/18/2021 07:27:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/20/2021 10:21:56	METER 1 - M: 3423 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2021 10:57:43	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.92	\$41.72	\$0.00	\$93.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.44** **51.92** **41.72** **2.00** **95.64**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/18/2021 09:59:21	08/18/2021 10:25:45	0.44	\$51.92
LABOR						51.92

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
PARTS						41.72

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 40768

Work Order Notes

(CHANNELL) PM\ replace wipers
(IFALLS) First oil change

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG
MILEAGE-3423

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 41317

USING DEPT NO: 507301	OPENED DATE: 10/14/2021 07:44:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/18/2021 14:21:04	METER 1 - M: 6587 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/19/2021 07:52:15	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO: 1GNSKNKD2MR335625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.10	\$40.85	\$0.00	\$95.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.47 55.10 40.85 2.00 97.95

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/14/2021 08:26:13	10/14/2021 08:54:14	0.47	\$55.10
					LABOR	55.10

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.85	1	\$4.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	8	\$36.00
					PARTS	40.85

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 41317

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. RC/JAW
MILEAGE-6587

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 41876

USING DEPT NO: 507301	OPENED DATE: 12/14/2021 10:09:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/14/2021 14:44:45	METER 1 - M: 10056 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/15/2021 11:16:27	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.46	\$43.08	\$0.00	\$86.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.62** **72.96** **43.08** **2.00** **118.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2021 13:00:00	12/14/2021 13:01:34	0.03	\$3.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2021 12:59:21	12/14/2021 12:59:21	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	12/14/2021 12:11:27	12/14/2021 12:26:27	0.25	\$29.50
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	12/14/2021 12:11:27	12/14/2021 12:11:27	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	12/14/2021 12:11:27	12/14/2021 12:11:27	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/14/2021 12:10:43	12/14/2021 12:10:43	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2021 11:35:34	12/14/2021 11:56:06	0.34	\$40.38
					LABOR	72.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.20	1	\$7.20
					PARTS	43.08

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 41876

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotate tires

(JWRIGHT) Rotated tires and torqued to spec. All pads are 12mm

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 42488

USING DEPT NO:	507301	OPENED DATE:	02/28/2022 07:58:41	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/28/2022 14:58:38	METER 1 - M:	14364	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2022 07:27:38	IN-SERVICE DATE:	06/29/2021		
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.28	\$44.36	\$0.00	\$88.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.38 44.28 44.36 2.00 90.64

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/28/2022 08:53:34	02/28/2022 09:16:05	0.38	\$44.28
LABOR						44.28

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	(8)	(\$35.40)
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.48	1	\$8.48
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
PARTS						44.36

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 42488

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 14364 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 42979

USING DEPT NO:	507301	OPENED DATE:	04/20/2022 11:28:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2022 10:55:24	METER 1 - M:	19777	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/25/2022 08:05:27	IN-SERVICE DATE:	06/29/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.64	\$193.95	\$43.85	\$0.00	\$237.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.10	\$11.80	\$46.91	\$0.00	\$58.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.74	205.75	90.76	2.00	298.51
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	04/21/2022 08:26:47	04/21/2022 08:32:47	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/21/2022 07:20:12	04/21/2022 08:23:09	1.05	\$123.80
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/21/2022 07:08:27	04/21/2022 07:44:07	0.59	\$70.14
LABOR					205.74	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC4211C	CABIN FILTER	46.91	1	\$46.91
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.97	1	\$7.97
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
PARTS					90.76	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 42979

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 19777 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 43426

USING DEPT NO:	507301	OPENED DATE:	05/31/2022 11:19:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/01/2022 14:40:27	METER 1 - M:	23698	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/01/2022 15:01:17	IN-SERVICE DATE:	06/29/2021		
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$54.92	\$0.00	\$93.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.33 38.94 54.92 2.00 95.86

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/01/2022 07:00:00	06/01/2022 07:19:48	0.33	\$38.94
					LABOR	38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.15	1	\$11.15
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
					PARTS	54.92

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 43426

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) PM EH-Top

AMG-Botom

Miles -23698

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 43963

USING DEPT NO:	507301	OPENED DATE:	07/13/2022 12:47:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2022 14:59:09	METER 1 - M:	27216	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2022 09:05:18	IN-SERVICE DATE:	06/29/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.78	\$47.54	\$0.00	\$86.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.33 38.78 47.54 2.00 88.32

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/14/2022 07:27:44	07/14/2022 07:47:27	0.33	\$38.78
					LABOR	38.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
					PARTS	47.54

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 43963

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-27216

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 44387

USING DEPT NO: 507301	OPENED DATE: 08/19/2022 07:43:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2022 14:15:31	METER 1 - M: 30716 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/26/2022 10:07:22	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$684.25	\$684.25
16-02-061	TRANSPORT WINDSHIELD	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **689.25** **748.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2102093		\$684.25
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					689.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02-061	TRANSPORT WINDSHIELD	11915538	08/25/2022 07:00:00	08/25/2022 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 44387

Work Order Notes

(CWIGLEY) Take to Glass Doctor to get the windshield replaced. Transport

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed new windshield and recalibrated. Pd by cc

16-02-061 - TRANSPORT WINDSHIELD

(LISAPATE) Taken to Glass Dr by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 44468

USING DEPT NO:	507301	OPENED DATE:	08/25/2022 14:48:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/29/2022 10:17:12	METER 1 - M:	31003	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2022 08:55:43	IN-SERVICE DATE:	06/29/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.16	\$57.81	\$0.00	\$71.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.12 14.16 57.81 5.00 76.97

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/25/2022 15:14:33	08/25/2022 15:21:45	0.12	\$14.16
					LABOR 14.16	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.61	1	\$11.61
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	8	\$46.20
					PARTS 57.81	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 44468

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-31003

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 45188

USING DEPT NO:	507301	OPENED DATE:	11/07/2022 09:51:32	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2022 07:26:33	METER 1 - M:	35335	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2022 09:14:22	IN-SERVICE DATE:	06/29/2021		
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$78.77	\$58.91	\$0.00	\$137.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.67 78.77 58.91 5.00 142.68

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/07/2022 12:32:07	11/07/2022 13:12:10	0.67	\$78.77
					LABOR	78.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	8	\$48.72
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.19	1	\$10.19
					PARTS	58.91

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 45188

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 35335 Completed PM top and bottom side. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 45207

USING DEPT NO: 507301	OPENED DATE: 11/09/2022 08:50:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/09/2022 08:52:08	METER 1 - M: 35335 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2022 07:24:11	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$575.00	\$575.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **580.00** **639.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2104011		\$575.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					580.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11915538	11/10/2022 07:00:00	11/10/2022 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 45207

Work Order Notes

(LISAPATE) Driver broke the windshield while trying to adjust the rear view mirror.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield. Pd by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 45685

USING DEPT NO: 507301	OPENED DATE: 01/05/2023 09:08:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/09/2023 07:26:09	METER 1 - M: 39353 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/09/2023 07:26:13	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$28.50	\$0.00	\$52.10
24-02-061	REPAIR WINDSHIELD	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.37	\$43.33	\$0.00	\$0.00	\$43.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.62	\$84.36	\$0.00	\$90.98
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$5.41	\$46.91	\$0.00	\$52.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6 **WORK ORDER TOTAL:** **0.67** **78.96** **159.77** **62.50** **301.23**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	2105262		\$57.50
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					62.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/05/2023 14:42:58	01/05/2023 15:05:00	0.37	\$43.33
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/05/2023 14:30:00	01/05/2023 14:33:22	0.06	\$6.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/05/2023 14:20:32	01/05/2023 14:20:32	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/05/2023 14:15:16	01/05/2023 14:27:16	0.20	\$23.60
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/05/2023 14:15:16	01/05/2023 14:15:16	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/05/2023 14:15:16	01/05/2023 14:15:16	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	01/05/2023 14:12:01	01/05/2023 14:14:46	0.05	\$5.41
LABOR					78.96	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA99417F	AIR FILTER TAHOE	28.83	1	\$28.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC4211C	CABIN FILTER	46.91	1	\$46.91
03-51-038	REPLACE NEW WIPER BLADES	11-1	11" WIPER	7.56	1	\$7.56

Work Order Charge Detail

The University of Alabama

Report Printed: 08/21/2024 11:22:08 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.81	1	\$6.81
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	8	\$48.72
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	2	\$20.94
					PARTS	159.77

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 45685

Work Order Notes

(EHANNAH) pm- replace wipers
window shield repair on the driver side.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

24-02-061 - REPAIR WINDSHIELD

(IFALLS) Glass Dr. came to our shop to repair windshield.

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires relearned tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 46873

USING DEPT NO: 507301	OPENED DATE: 04/27/2023 10:52:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/28/2023 09:35:21	METER 1 - M: 44159 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/28/2023 13:26:09	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.22	\$55.80	\$0.00	\$90.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **34.22** **55.80** **5.00** **95.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/27/2023 13:00:00	04/27/2023 13:17:24	0.29	\$34.22
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/27/2023 12:56:19	04/27/2023 12:56:19	0.00	\$0.00
LABOR					34.22	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	8	\$50.04
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
PARTS					55.80	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 46873

Work Order Notes

(EHANNAH) pm- replace wiper- wash

Job Notes

03-51-068 - REPLACE NEW 48" BLOW GUN

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC,JW- Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 44,159

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 46942

USING DEPT NO:	507301	OPENED DATE:	05/03/2023 12:11:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2023 14:30:36	METER 1 - M:	44163	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/09/2023 07:55:20	IN-SERVICE DATE:	06/29/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-026	REPAIR WEATHRSTRIPPING,GASKETS	DON	O	N	GARAGE	0.16	\$19.08	\$0.00	\$0.00	\$19.08
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EX	DON	O	N	GARAGE	2.32	\$273.73	\$0.00	\$0.00	\$273.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **2.48** **292.81** **0.00** **62.50** **355.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-02-061	REPAIR WINDSHIELD	11078716	2108369		\$57.50
COMML					62.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11310047	05/05/2023 09:30:00	05/05/2023 09:50:48	0.35	\$40.91
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11310047	05/05/2023 09:16:26	05/05/2023 09:16:26	0.00	\$0.00
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11310047	05/05/2023 07:04:55	05/05/2023 07:19:33	0.24	\$28.78
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11310047	05/04/2023 08:26:51	05/04/2023 08:59:20	0.54	\$63.88
24-02-026	REPAIR WEATHRSTRIPPING,GASKETS&BUMPRS	11310047	05/04/2023 08:17:09	05/04/2023 08:26:51	0.16	\$19.08
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11310047	05/03/2023 13:03:44	05/03/2023 14:15:00	1.19	\$140.16
LABOR					292.81	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 46942

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

24-02-026 - REPAIR WEATHRSTRIPPING,GASKETS&BUMPRS

(EHOWELL) Found the weather strip out of place for the glass on the rear hatch. Cleaned mating surface and applied adhesive to weather strip. Pushed weather strip back onto vehicle body. Performed a water leak test after the repair to verify water was not entering into the vehicle. EH .25 HR

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr repaired a ding in the driver side of the windshield. Pd by CC

35-71-032 - DIAGNOSE WATER LEAK INTERIOR/EXTERIOR

(EHOWELL) Found the floor board wet in front and behind of the driver's seat. Examined for a water leak from the inside of the vehicle while an assistant ran water over multiple areas of the vehicle with a water hose. The A-pillar trim panel was removed so that the windshield area could be carefully examined because this vehicle has had the windshield replaced. Did not see any sign of water entering the vehicle. It seems that the customer may have left the window down during a rain storm. Removed the driver's seat and multiple plastic trim panels. Raised carpet and allowed a fan to blow beneath the carpet to dry up water. Sprayed disinfectant beneath carpet to help prevent mold or mildew. Assembled vehicle after repairs. EH 2.0 HRS

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(EHOWELL) The vehicle was driven through the automatic car wash during water leak diagnosis. EH

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 47731

USING DEPT NO:	507301	OPENED DATE:	07/25/2023 11:08:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/26/2023 14:18:09	METER 1 - M:	48305	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2023 11:08:53	IN-SERVICE DATE:	06/29/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD2MR335625	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$30.02	\$0.00	\$47.72
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.25	\$29.04	\$0.00	\$0.00	\$29.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.35	\$62.85	\$0.00	\$95.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.67	79.09	92.87	5.00	176.96
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/25/2023 14:30:00	07/25/2023 14:44:46	0.25	\$29.04
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/25/2023 14:25:05	07/25/2023 14:25:05	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/25/2023 14:21:05	07/25/2023 14:30:05	0.15	\$17.70
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/25/2023 14:21:05	07/25/2023 14:21:05	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/25/2023 14:21:05	07/25/2023 14:21:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/25/2023 13:58:33	07/25/2023 14:15:00	0.27	\$32.35
					LABOR	79.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	8	\$50.16
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.53	(8)	(\$60.24)
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.69	1	\$12.69
03-51-038	REPLACE NEW WIPER BLADES	11-1	11" WIPER	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.53	8	\$60.24
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					PARTS	92.87

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 47731

Work Order Notes

(LRUSHING) PM AND NEW WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 47995

USING DEPT NO: 507301	OPENED DATE: 08/25/2023 10:20:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2023 11:49:40	METER 1 - M: 49795 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/11/2023 15:29:05	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO: 1GNSKNKD2MR335625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-02-047	RECALL SEAT BELTS	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.50	59.00	0.00	62.50	121.50
---------------------	--------------------------	-------------	--------------	-------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
17-02-047	RECALL SEAT BELTS	11074891	CTCS474954		\$0.00
24-02-061	REPAIR WINDSHIELD	11078716	2111824		\$57.50
COMML					62.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11915538	08/31/2023 07:00:00	08/31/2023 07:30:00	0.50	\$59.00
LABOR					59.00	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 47995

Work Order Notes

(LISAPATE) Windshield has a ding
(EHANNAH) transport to vendor for 3rd row seat belt

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Chevrolet by RC/CW

17-02-047 - RECALL SEAT BELTS

(LISAPATE) Visit Reason Changed On 8/31/2023 11:43 AM By LISAPATE

(LISAPATE) Tuscaloosa Chevrolet completed recall per N222372380 inspected 3rd row seatbelt buckles, no further action required. Campaign Complete

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr came to the shop and repaired ding in the windshield

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 49034

USING DEPT NO: 507301	OPENED DATE: 11/21/2023 10:19:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/21/2023 15:43:48	METER 1 - M: 55594 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/22/2023 09:47:42	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$13.73	\$63.92	\$0.00	\$77.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.12	13.73	63.92	5.00	82.65
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/21/2023 13:46:00	11/21/2023 13:52:59	0.12	\$13.73
LABOR					13.73	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	8	\$50.40
PARTS					63.92	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 49034

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil change and fluid check SC fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 49781

USING DEPT NO: 507301	OPENED DATE: 02/13/2024 07:05:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/19/2024 12:29:54	METER 1 - M: 58124 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/21/2024 12:47:07	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4	UNIT SERIAL NO: 1GNSKNKD2MR335625	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-061	INSPECT WINDSHIELD	DON	U	N	GARAGE	3.81	\$449.12	\$0.00	\$0.00	\$449.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **3.81** **449.12** **0.00** **5.00** **454.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-061	INSPECT WINDSHIELD	11310047	02/16/2024 14:51:09	02/16/2024 15:54:16	1.05	\$124.13
06-02-061	INSPECT WINDSHIELD	11310047	02/16/2024 13:10:20	02/16/2024 13:23:48	0.22	\$26.48
06-02-061	INSPECT WINDSHIELD	11310047	02/16/2024 11:05:56	02/16/2024 11:51:49	0.76	\$90.24
06-02-061	INSPECT WINDSHIELD	11310047	02/16/2024 08:14:17	02/16/2024 09:22:24	1.14	\$133.96
06-02-061	INSPECT WINDSHIELD	11074414	02/13/2024 10:54:30	02/13/2024 11:32:17	0.63	\$74.31
LABOR					449.12	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 49781

Work Order Notes

(EHANNAH) inspect windshield for leaks both mats are wet.

Job Notes

06-02-061 - INSPECT WINDSHIELD

(EHOWELL) Found water in the floor in the following locations: in front of the driver's seat, behind the driver's seat, and behind the left second row seat. The vehicle's windshield has been replaced two different times. Removed windshield wipers and lower cowl panel. An assistant ran water over multiple locations of the vehicle. Inspected various locations from inside the vehicle, however, no signs of water entry were present. It appeared that the driver's air bag near the A-pillar had discoloration. This could be from water entry due to the window being left down. A piece of notebook paper was inserted in the door jam of the A-pillar and the door was closed. There was resistance on the paper while pulling on it.

Removed plastic trim panels and raised carpet off of the floor. Allowed a fan to blow in multiple locations to help dry out the carpet/jute. Removed second row seat for drying purposes. Pulled back trim near the left rear glass (behind the second row seat) and inspected for signs of water entry.

At this time it appears that the window was left open. EH/SH 3.0 HRS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 50172

USING DEPT NO: 507301	OPENED DATE: 03/20/2024 09:34:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/21/2024 15:13:26	METER 1 - M: 59987 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/22/2024 09:55:04	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO: 1GNSKNKD2MR335625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$13.73	\$68.48	\$0.00	\$82.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.12** **13.73** **68.48** **5.00** **87.21**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/21/2024 09:30:00	03/21/2024 09:36:59	0.12	\$13.73
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/21/2024 09:28:04	03/21/2024 09:28:04	0.00	\$0.00
LABOR					13.73	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	8	\$54.96
PARTS					68.48	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 50172

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 50686

USING DEPT NO: 507301	OPENED DATE: 04/26/2024 08:59:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/01/2024 12:22:40	METER 1 - M: 63977 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/02/2024 13:48:59	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO: 1GNSKNKD2MR335625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$718.75	\$718.75
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.44	\$30.02	\$0.00	\$31.46
16-02-061	TRANSPORT WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.13	\$76.13	\$0.00	\$84.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.08	9.57	106.15	723.75	839.47
---------------------	--------------------------	-------------	-------------	---------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	117923		\$718.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					723.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/26/2024 09:34:08	04/26/2024 09:34:52	0.01	\$1.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/26/2024 09:30:00	04/26/2024 09:34:08	0.07	\$8.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/26/2024 09:27:48	04/26/2024 09:27:48	0.00	\$0.00
LABOR					9.57	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	8	\$54.96
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
03-51-038	REPLACE NEW WIPER BLADES	11-1	11" WIPER	8.33	1	\$8.33
PARTS					106.15	

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 50686

Work Order Notes

(EHANNAH) pm

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EKIMBREL) Glass Dr replaced windshield

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH GC

16-02-061 - TRANSPORT WINDSHIELD

(IFALLS) cw performed transport

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/GC Performed PM. Wind shield has 2 rock chips one is in the drivers view. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 51073

USING DEPT NO: 507301	OPENED DATE: 06/06/2024 12:43:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/10/2024 08:01:03	METER 1 - M: 67186 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/10/2024 08:01:06	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO: 1GNSKNKD2MR335625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.02	\$1.80	\$1,383.89	\$0.00	\$1,385.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$3.84	\$69.32	\$0.00	\$73.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.05	5.64	1,453.21	5.00	1,463.85
---------------------	--------------------------	-------------	-------------	-----------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/06/2024 13:25:50	06/06/2024 13:27:47	0.03	\$3.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/06/2024 14:45:36	06/06/2024 14:46:31	0.02	\$1.80
					LABOR	5.64

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	8	\$55.80
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	33	\$7.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	4	\$14.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	13647	TIRE 275/60R20 MICH LTX M/S	340.50	4	\$1,362.00
					PARTS	1453.21

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 51073

Work Order Notes

(EHANNAH) pm

Job Notes

06-15 - INSPECT STEERING

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. Adjusted rear toe, front camber, caster and toe. Reset the LDW and test drove. Found no other issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) GC Mounted SH balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc - sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 244086 **2021 CHEVROLET TAHOE** **WORK ORDER NO:** 51830

USING DEPT NO: 507301	OPENED DATE: 08/15/2024 12:11:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: OPEN	COMPLETED DATE:	METER 1 - M: 70187 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE:	IN-SERVICE DATE: 06/29/2021
TECH SPEC NO: 21CHEVTAHO4X4 2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO: 1GNSKNKD2MR335625

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 244086 2021 CHEVROLET TAHOE

WORK ORDER NO: 51830

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Aug 21 2024 11:22:08 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244086') //Q=