

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 38503

USING DEPT NO: 204903	OPENED DATE: 12/01/2020 14:53:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/01/2020 14:55:11	METER 1 - M: 135 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/02/2020 07:37:42	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4	UNIT SERIAL NO: 1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **0.00** **59.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	12/01/2020 14:54:22	12/01/2020 15:24:22	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 38503

Work Order Notes

(LISAPATE) new unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 39705

USING DEPT NO: 204903	OPENED DATE: 04/16/2021 07:52:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/19/2021 10:49:11	METER 1 - M: 1309 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/20/2021 15:37:13	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4		UNIT SERIAL NO: 1FT7X2B62LED69408

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.07	\$0.00	\$0.00	\$49.07

JOB COUNT: 1 **WORK ORDER TOTAL:** 0.42 49.07 0.00 0.00 49.07

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/16/2021 09:57:24	04/16/2021 10:20:07	0.38	\$44.68
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/16/2021 09:08:31	04/16/2021 09:10:45	0.04	\$4.39
					LABOR	49.07

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 39705

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 1309 New unit not enough miles, checked fluids, battery and tires. Updated oil change sticker, completed checklist and vacuumed out vehicle. AMG
(AGUERRA) John Newman declined any repairs on trailer . Trailer has passenger car tires instead of trailer tires. IF AMG

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4 WORK ORDER NO: 40096

USING DEPT NO:	204903	OPENED DATE:	06/03/2021 13:02:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2021 08:58:29	METER 1 - M:	1793	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2021 14:20:25	IN-SERVICE DATE:	11/25/2020	
TECH SPEC NO:	20FORDF2504X4	2020 Ford F250 4X4		UNIT SERIAL NO:	1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.92	\$108.99	\$11.75	\$0.00	\$120.74

JOB COUNT: 1 WORK ORDER TOTAL: 0.92 108.99 11.75 0.00 120.74

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	06/03/2021 13:09:24	06/03/2021 14:04:49	0.92	\$108.99

LABOR 108.99

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	5.73	1	\$5.73
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.92	1	\$3.92
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	3	\$0.18
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	4	\$1.92

PARTS 11.75

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 40096

Work Order Notes

(LISAPATE) Screw n LR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 1793 Repaired L/R tire, rebalanced and checked for leaks, all good. AMG

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 41282

USING DEPT NO:	204903	OPENED DATE:	10/11/2021 11:29:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2021 15:05:23	METER 1 - M:	3749	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2021 09:16:11	IN-SERVICE DATE:	11/25/2020		
TECH SPEC NO:	20FORDF2504X4	2020 Ford F250 4X4		UNIT SERIAL NO:	1FT7X2B62LED69408		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.16	\$15.18	\$0.00	\$23.34
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.88	\$103.25	\$0.00	\$0.00	\$103.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.78	\$92.27	\$55.65	\$0.00	\$147.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.73	203.68	70.83	2.00	276.51
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	10/12/2021 08:54:53	10/12/2021 09:47:23	0.88	\$103.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/12/2021 07:54:04	10/12/2021 08:40:59	0.78	\$92.27
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/12/2021 07:49:41	10/12/2021 07:53:50	0.07	\$8.16
					LABOR	203.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.27	7	\$50.92
					PARTS	70.83

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 41282

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 3749 Completed PM top and bottom side. Completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 43146

USING DEPT NO: 204903	OPENED DATE: 05/05/2022 08:31:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/06/2022 15:08:45	METER 1 - M: 5435 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2022 07:54:59	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4	UNIT SERIAL NO: 1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.31	\$20.37	\$0.00	\$25.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.30	\$0.00	\$0.00	\$33.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.33** **38.61** **20.37** **2.00** **60.98**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/05/2022 13:25:45	05/05/2022 13:42:41	0.28	\$33.30
03-51-038	REPLACE NEW WIPER BLADES	11901357	05/05/2022 13:22:49	05/05/2022 13:25:31	0.05	\$5.31
LABOR					38.61	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	2	\$20.37
PARTS					20.37	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 43146

Work Order Notes

(LISAPATE) pm-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5435 Vehicle has been 1686 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 45239

USING DEPT NO: 204903	OPENED DATE: 11/11/2022 10:29:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/14/2022 09:32:06	METER 1 - M: 6633 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/15/2022 10:07:41	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4	2020 Ford F250 4X4	UNIT SERIAL NO: 1FT7X2B62LED69408

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.74	\$20.94	\$0.00	\$30.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.91	\$78.89	\$0.00	\$123.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.46	54.65	99.83	5.00	159.48
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/11/2022 14:34:50	11/11/2022 14:57:40	0.38	\$44.91
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/11/2022 14:29:14	11/11/2022 14:34:11	0.08	\$9.74
LABOR					54.65	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.91	1	\$5.91
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	10.43	7	\$72.98
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	2	\$20.94
PARTS					99.83	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 45239

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 6633 Completed PM topside, Josh was bottomside. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 46434

USING DEPT NO:	204903	OPENED DATE:	03/09/2023 14:01:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/04/2023 14:01:51	METER 1 - M:	7514	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 14:01:53	IN-SERVICE DATE:	11/25/2020	
TECH SPEC NO:	20FORDF2504X4	2020 Ford F250 4X4		UNIT SERIAL NO:	1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,150.00	\$1,150.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.60	\$0.00	\$0.00	\$17.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL: 0.65 76.60 0.00 1,155.00 1,231.60**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	1697322		\$1,150.00
24-71	REPAIR BODY	11150605	1697322		(\$1,150.00)
24-71	REPAIR BODY	11150605	1697322		\$1,150.00
24-71	REPAIR BODY	11150605	1697322		\$3,206.99
24-71	REPAIR BODY	11150605	1697322		(\$3,206.99)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					1155.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/20/2023 14:30:00	03/20/2023 14:38:57	0.15	\$17.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/20/2023 14:29:02	03/20/2023 14:29:02	0.00	\$0.00
16-71	TRANSPORT BODY	11915538	04/04/2023 07:00:00	04/04/2023 07:30:00	0.50	\$59.00
16-71	TRANSPORT BODY	11915538	04/04/2023 07:00:00	04/04/2023 07:30:00	0.50	\$59.00
16-71	TRANSPORT BODY	11915538	04/04/2023 07:00:00	04/04/2023 07:30:00	(0.50)	(\$59.00)
LABOR					76.60	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 46434

Work Order Notes

(EHANNAH) transport vehicle to Andrew's for repairs

Job Notes

03-71-024 - REPLACE NEW BUMPER(S)

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by RC/CW

(AJONES) Visit Reason Changed On 5/1/2023 9:56 AM By AJONES

24-71 - REPAIR BODY

(LISAPATE) Andrew's repaired rear bumper area damage per the estimate. Sate Auto pd \$1788.69 Ck# 1001197333 3-20-23. UA will pay remaining \$1000.00 Ded

(AJONES) Visit Reason Changed On 5/1/2023 9:57 AM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 881 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 47653

USING DEPT NO: 204903	OPENED DATE: 07/19/2023 14:37:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/19/2023 14:41:51	METER 1 - M: 7514 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/20/2023 08:46:23	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4	UNIT SERIAL NO: 1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-43-103	RECALL HEAT SHIELD	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-43-103	RECALL HEAT SHIELD	11099772	100612484		\$0.00
COMML					0.00

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 47653

Work Order Notes

(LISAPATE) Recall 22S09

Job Notes

17-43-103 - RECALL HEAT SHIELD

(LISAPATE) Long Lewis came to the shop and installed 2 rivets to secure underbody shield

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 47796

USING DEPT NO: 204903	OPENED DATE: 08/01/2023 10:16:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/09/2023 14:13:55	METER 1 - M: 8567 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/10/2023 07:50:19	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4		UNIT SERIAL NO: 1FT7X2B62LED69408

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.05	\$21.69	\$0.00	\$26.74
24-21-002	REPAIR CV AXLES/SEALS	DON	N	N	GARAGE	0.11	\$12.39	\$45.99	\$0.00	\$58.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.28	\$58.65	\$0.00	\$100.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.78	\$91.94	\$0.00	\$0.00	\$91.94

JOB COUNT: 5	WORK ORDER TOTAL:	1.29	151.66	126.33	5.00	282.99
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-21-002	REPAIR CV AXLES/SEALS	12201267	08/09/2023 07:30:36	08/09/2023 07:36:54	0.11	\$12.39
WA-00	WASH COMPLETE VEHICLE	11074414	08/01/2023 14:30:00	08/01/2023 15:16:45	0.78	\$91.94
WA-00	WASH COMPLETE VEHICLE	11074414	08/01/2023 14:23:23	08/01/2023 14:23:23	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/01/2023 13:57:18	08/01/2023 14:13:07	0.26	\$31.11
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/01/2023 14:07:19	08/01/2023 14:09:53	0.04	\$5.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/01/2023 13:34:19	08/01/2023 13:40:00	0.09	\$11.18
24-21-002	REPAIR CV AXLES/SEALS	12201267	08/09/2023 07:30:36	08/09/2023 07:36:54	(0.11)	(\$12.39)
24-21-002	REPAIR CV AXLES/SEALS	12201267	08/09/2023 07:30:36	08/09/2023 07:36:54	0.11	\$12.39
					LABOR	151.67

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.53	7	\$52.71
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
24-21-002	REPAIR CV AXLES/SEALS	82180	ULTRA BLACK RTV	9.09	1	\$9.09

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-21-002	REPAIR CV AXLES/SEALS	VV831	HP 80W90 GEAR OIL GL5 QT	12.30	1	\$12.30
24-21-002	REPAIR CV AXLES/SEALS	VV831	HP 80W90 GEAR OIL GL5 QT	12.30	(1)	(\$12.30)
24-21-002	REPAIR CV AXLES/SEALS	VV831	HP 80W90 GEAR OIL GL5 QT	12.30	3	\$36.90
24-21-002	REPAIR CV AXLES/SEALS	82180	ULTRA BLACK RTV	9.09	(1)	(\$9.09)
24-21-002	REPAIR CV AXLES/SEALS	VV831	HP 80W90 GEAR OIL GL5 QT	12.30	(3)	(\$36.90)
24-21-002	REPAIR CV AXLES/SEALS	82180	ULTRA BLACK RTV	9.09	1	\$9.09
24-21-002	REPAIR CV AXLES/SEALS	VV831	HP 80W90 GEAR OIL GL5 QT	12.30	3	\$36.90
					PARTS	126.33

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 47796

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

24-21-002 - REPAIR CV AXLES/SEALS

(GARAGE) Pulled front diff cover, to repair leak it had front being scrapped on bottom. Pulled cover, cleaned both surfaces and filed down the rough spots on the bottom of the cover from being scrapped. Applied ultra black to the cover and reinstalled the cover. Torqued all bolts to 45 foot lbs. Let sit and dry and filled front diff with 2.75 quarts of 80w90 front diff fluid. Drove around campus and parked on concrete and let sit and checked for leaks. Found no leaks and front diff is good. -GRC

(LRUSHING) Visit Reason Changed On 8/25/2023 10:52 AM By LRUSHING

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-SH,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 8,567

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 48516

USING DEPT NO: 204903	OPENED DATE: 10/11/2023 12:50:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/16/2023 15:50:38	METER 1 - M: 8567 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/18/2023 08:22:18	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4		UNIT SERIAL NO: 1FT7X2B62LED69408

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.18	\$21.73	\$196.83	\$0.00	\$218.56
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.06	\$7.41	\$0.00	\$0.00	\$7.41
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.25	29.14	196.83	5.00	230.97
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32-002	INSPECT BATTERY	11074414	10/13/2023 07:29:20	10/13/2023 07:33:06	0.06	\$7.41
06-32-002	INSPECT BATTERY	11074414	10/13/2023 07:29:20	10/13/2023 07:33:06	0.06	\$7.41
06-32-002	INSPECT BATTERY	11074414	10/13/2023 07:29:20	10/13/2023 07:33:06	(0.06)	(\$7.41)
03-32-002	REPLACE NEW BATTERY	11074414	10/13/2023 07:18:06	10/13/2023 07:29:09	0.18	\$21.73
LABOR					29.14	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	196.83	1	\$196.83
PARTS					196.83	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 48516

Work Order Notes

(EHANNAH) inspect battery won't start.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Installed a new battery. ALT Charging at 14.7 volts. SH

06-32-002 - INSPECT BATTERY

(SHARBIN) Battery tested bad. SH

(LRUSHING) Visit Reason Changed On 10/20/2023 2:39 PM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 10/20/2023 2:39 PM By LRUSHING

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 49402

USING DEPT NO: 204903	OPENED DATE: 01/09/2024 09:43:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/12/2024 09:31:55	METER 1 - M: 9270 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/17/2024 08:24:58	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4	UNIT SERIAL NO: 1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.78	\$92.07	\$0.00	\$0.00	\$92.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.44	\$51.82	\$0.00	\$0.00	\$51.82

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.55** **182.83** **0.00** **5.00** **187.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	01/10/2024 07:29:04	01/10/2024 07:55:25	0.44	\$51.82
66-79-003	PERFORM SAFETY INSPECTION	12201267	01/10/2024 07:02:24	01/10/2024 07:28:20	0.43	\$51.00
66-79-003	PERFORM SAFETY INSPECTION	12201267	01/09/2024 15:19:21	01/09/2024 15:40:14	0.35	\$41.07
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/09/2024 12:36:08	01/09/2024 12:36:08	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/09/2024 12:36:08	01/09/2024 12:36:08	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/09/2024 12:36:08	01/09/2024 12:55:56	0.33	\$38.94
					LABOR 182.83	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 49402

Work Order Notes

(EHANNAH) pm- wipers- wash - SI
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed safety inspection, found no issues at this time,-GC
Brake pads are 10mm front and rear.
Miles, 9,720

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, vehicle only driven 703 miles, filters good, tires and tire pressure, updated oil change sticker.
Miles, 9,270

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 50882

USING DEPT NO: 204903	OPENED DATE: 05/17/2024 09:53:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2024 13:35:41	METER 1 - M: 10127 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/20/2024 09:34:12	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4	UNIT SERIAL NO: 1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$1.90	\$60.23	\$0.00	\$62.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.62	\$0.00	\$0.00	\$0.62

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.52	60.23	5.00	67.75
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	05/17/2024 10:42:53	05/17/2024 10:43:12	0.01	\$0.62
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/17/2024 10:41:44	05/17/2024 10:42:42	0.02	\$1.90
LABOR					2.52	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.76	7	\$54.29
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
PARTS					60.23	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 50882

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,SH, Changed oil and oil filter, checked fluids, filter good, tires and tire pressure.
Miles, 10,127

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 51713

USING DEPT NO: 204903	OPENED DATE: 08/06/2024 07:53:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/30/2024 17:05:32	METER 1 - M: 10577 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/30/2024 17:05:32	IN-SERVICE DATE: 11/25/2020
TECH SPEC NO: 20FORDF2504X4 2020 Ford F250 4X4		UNIT SERIAL NO: 1FT7X2B62LED69408

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-33-003	REPLACE NEW COIL	DON	N	N	GARAGE	0.00	\$0.00	\$133.14	\$0.00	\$133.14
06-40	INSPECT ENGINE / MOTOR SYSTEMS	DON	N	N	GARAGE	1.89	\$222.53	\$5.63	\$0.00	\$228.16
20-00	TOWING COMPLETE VEHICLE	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$179.40	\$179.40
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.89	222.53	138.77	184.40	545.70
---------------------	--------------------------	-------------	---------------	---------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
20-00	TOWING COMPLETE VEHICLE	11076249	2416185		\$179.40
COMML					184.40

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-40	INSPECT ENGINE / MOTOR SYSTEMS	12052187	08/07/2024 14:30:00	08/07/2024 15:30:53	1.01	\$119.74
06-40	INSPECT ENGINE / MOTOR SYSTEMS	12052187	08/07/2024 13:22:44	08/07/2024 14:15:00	0.87	\$102.79
LABOR					222.53	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
06-40	INSPECT ENGINE / MOTOR SYSTEMS	ATM20LP	LOW PROFILE 20A MINIFUSE	1.13	5	\$5.63
03-33-003	REPLACE NEW COIL	STIUF865	COIL	133.14	1	\$133.14
PARTS					138.77	

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 51713

Work Order Notes

(EHANNAH) Service Call for not cranking- vehicle will turn over but will not crank.

(EHOWELL) This vehicle is still at Tuscaloosa Ford. We are closing this work order do to year end.

Job Notes

03-33-003 - REPLACE NEW COIL

(GARAGE) Replaced coil and ran for a few minutes. Started missing again and melted new coil. Blew the ignition module fuse again. Sending to dealer under emissions warranty. JAW

06-40 - INSPECT ENGINE / MOTOR SYSTEMS

(GARAGE) Scanned unit for codesp0302 cylinder 2 misfire and multiple coil codes. Found ignition module fuse blown. Pulled wiring schematic and traced circuit. Removed all coil wires and started plugging each one up with new fuse in place. Fuse blew when cylinder 2 coil was plugged back in. Removed coil and found it busted on top and melted. Replaced coil and ran for a few minutes. Started missing on cylinder 2 again and blew the fuse again. Looked and new coil was melted. Ohmed out all coil wires and all tested good. Inspected coil wiring harness and found no issues. Spoke with ethan and found unit to be covered under emissions warranty and will be towed to dealer for further repair. JAW

20-00 - TOWING COMPLETE VEHICLE

(EHOWELL) This vehicle was towed from Mound State Park to our shop. It was then towed to Tuscaloosa Ford.

66-79-002 - PERFORM SERVICE CALL

(EHOWELL) We did not perform a service call. We called Bambarger to tow vehicle.

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 10/2/2024 7:49 AM By AJONES

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 52341

USING DEPT NO:	204903	OPENED DATE:	10/02/2024 08:45:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/02/2024 09:06:41	METER 1 - M:	10581	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	10/02/2024 09:46:23	IN-SERVICE DATE:	11/25/2020	
TECH SPEC NO:	20FORDF2504X4	2020 Ford F250 4X4		UNIT SERIAL NO:	1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-05-034	WARRANTY ECM/ENGINE CONTROL M	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-05-034	TRANSPORT ECM/ENGINE CONTROL M	DON	W	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-05-034	WARRANTY ECM/ENGINE CONTROL MODULE	11078175	129126		\$0.00
				COMML	0.00

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 52341

Work Order Notes

(EHOWELL) We are reopening a work order on this vehicle. We closed WO 51713 do to year end.

Job Notes

15-05-034 - WARRANTY ECM/ENGINE CONTROL MODULE

(EHOWELL) Tuscaloosa Ford replaced the powertrain control module and ignition coil #2. They also found the engine harness shorted because it was rubbing a stud on the back of the intake. The damaged wire was repaired.

16-05-034 - TRANSPORT ECM/ENGINE CONTROL MODULE

(EHOWELL) The vehicle was picked up from Tuscaloosa Ford and driven to our shop.

Work Order Charge Detail

UNIT NO: 243948 **2020 FORD F250 4X4** **WORK ORDER NO:** 52553

USING DEPT NO:	204903	OPENED DATE:	10/21/2024 16:34:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/29/2024 08:41:03	METER 1 - M:	10600	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/30/2024 09:37:52	IN-SERVICE DATE:	11/25/2020	
TECH SPEC NO:	20FORDF2504X4	2020 Ford F250 4X4		UNIT SERIAL NO:	1FT7X2B62LED69408	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243948 2020 FORD F250 4X4

WORK ORDER NO: 52553

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Nov 05 2024 13:52:44 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243948') //Q=