The University of Alabama

Work Order Charge Detail

UNIT NO:		243687	2020 FORI	D F250)				WORK C	RDER NO): 35	718		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250		OPENE COMPL CLOSE Ford F25	ETED D DAT	DATE:	02/24/202	20 14:04:18 20 09:06:38 20 09:06:44	LOCATION METER 1 - IN-SERVIC UNIT SER	E DATE:	ME 02/20/202	TER 2 - H:	0	
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	RIAL CO	MMERCIAL	TOTAL C	OST
14-02-013	INSTALL	FLOOR COVERIN	GS	DON	0	Ν	GARAGE	0.00	\$0.00	\$141.28	\$0.0	00	\$141.28	
66-00-001	PERFOR	RM NEW UNIT IN-S	ERVICE INSF	DON	С	N	GARAGE	0.00	\$0.00	\$0.00	\$0.0	00	\$0.00	
JOB COUN	IT: 2				wo	RK ORE	ER TOTAL:	0.00		0.00	141.28	0.00	,	141.28
Job Code		Job Descript	tion_			Part No.	<u>.</u>	<u>Des</u>	cription		Unit Price	Quantity	Total C	ost
14-02-013	INSTALL FL	OOR COVERINGS		Н	C3Z261	3300BA	FL	OOR MAT KIT HD	3PC EXTCA	В	141.28	1		\$141.28
												PARTS		141.28

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 35718

Work Order Notes

(EKIMBREL) PDI

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) AB performed PDI

UNIT NO:		243687	2020 FOR	D F250	ı				WORK ORDI	ER NO:	35880	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250	2020 I	OPENE COMPL CLOSE Ford F25	ETED D DATI	DATE:	03/13/20	020 09:03:56 020 14:14:40 020 10:10:08	LOCATION: G METER 1 - M: IN-SERVICE DA UNIT SERIAL N	117 ATE: 02/20/	rsity Automotive S METER 2 - H: 2020 (2A65LEC32108	
JOB CODE	_	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	-	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-062	INSTALL	TOOLBOX ASSY		DON	0	N	GARAGE	3.36	\$0.00	\$880.00	\$0.00	\$880.00
14-55-041	INSTALL	LADDER RACK		DON	0	N	GARAGE	2.41	\$0.00	\$826.00	\$0.00	\$826.00
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	.: 5.77	0.00	1,706.00	0.00	1,706.00
Job Code		Job Descript	ion_		<u>Em</u>	ployee	No.	<u>Start</u>	<u>Finis</u>	<u>sh</u>	Quantity	Total Cost
14-51-062	INSTALL TO	OLBOX ASSY		1:	2052187	•	0	3/12/2020 09:30:00	03/12/2020 10):39:52	1.16	\$0.00
14-51-062	INSTALL TO	OLBOX ASSY		1:	2052187	,	0	3/12/2020 07:53:57	03/12/2020 09	9:15:00	1.35	\$0.00
14-51-062	INSTALL TO	OLBOX ASSY		1:	2052187	,	0	3/04/2020 13:00:41	03/04/2020 13	3:51:06	0.84	\$0.00
14-55-041	INSTALL LAI	DDER RACK		1:	2052187	,	0	3/04/2020 10:44:48	03/04/2020 11	:55:01	1.17	\$0.00
14-55-041	INSTALL LAI	DDER RACK		1:	2052187	,	0	3/04/2020 09:07:10	03/04/2020 10):21:48	1.24	\$0.00
											LABOR	0.00
Job Code		Job Descript	ion			Part No	<u>.</u>	<u>Des</u>	scription	<u>Unit Pric</u>	ce Quantity	Total Cost
14-55-041	INSTALL LAI	DDER RACK		L	01040		L	ADDER RACK LEG	SS	300.	.00 1	\$300.00
14-51-062	INSTALL TO	OLBOX ASSY		1:	27002		A	LUMINUM SADDL	ЕВОХ	880.	.00 1	\$880.00
14-55-041	INSTALL LAI	DDER RACK		S	06000		L	ADDER RACK SID	E RAILS EXT CAB	526.	.001	\$526.00
											PARTS	1706.00

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 35880

Work Order Notes

(RTUNAITI) Install tool box and ladder rack

Job Notes

14-51-062 - INSTALL TOOLBOX ASSY

(LISAPATE) Installed tool box

14-55-041 - INSTALL LADDER RACK

(LISAPATE) Assembled and installed ladder rack assy

UNIT NO:	243687	2020 FORD F250				WORK ORDER NO	: 367	'66	
USING DEPT NO:	504241	OPENED	DATE:	06/10/202	0 13:09:06	LOCATION: GARAGE	- University	Automotive S	Services
WO STATUS:	CLOSED	COMPLE	TED DATE:	06/10/2020	0 15:02:29	METER 1 - M: 699	MET	TER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED	DATE:	06/11/2020	0 10:33:35	IN-SERVICE DATE:	02/20/2020)	
TECH SPEC NO:	20FORDF250	2020 Ford F250				UNIT SERIAL NO:	1FT7X2A6	5LEC32108	
JOB CODE	JOB DESCRIPTION	ON STAT	RSN WRTY	JOB LOC	LABOR HRS	LABOR MATE	RIAL COI	MMERCIAL	TOTAL COST
03-52-021 REPLA	ACE NEW GPS SYST	EM DON	O N	GARAGE	0.44	\$0.00 \$0.00	\$0.00	0	\$0.00
JOB COUNT: 1			WORK ORD	ER TOTAL:	0.44	0.00	0.00	0.00	0.00
Job Code	Job Descript	<u>ion</u>	Employee I	No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
03-52-021 REPLACE	E NEW GPS SYSTEM	110)74414	06/	10/2020 13:11:49	06/10/2020 13:38:23		0.44	\$0.00
							-	LABOR	0.00

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 36766

Work Order Notes

(LISAPATE) Install 4G GPS

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(LISAPATE) Installed a new 4G GPS and harness Serial# 5041360182

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

243687 **UNIT NO:** 2020 FORD F250 **WORK ORDER NO:** 37709 **USING DEPT NO:** 504241 **OPENED DATE:** 09/23/2020 11:43:22 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 09/24/2020 12:31:48 **METER 1 - M**: 1418 METER 2 - H: **WO STATUS:** COMPLETED DATE: **SCHEDULED** 09/24/2020 13:30:02 WO VISIT REASON: **CLOSED DATE: IN-SERVICE DATE:** 02/20/2020 **TECH SPEC NO:** 20FORDF250 2020 Ford F250 **UNIT SERIAL NO:** 1FT7X2A65LEC32108 **MATERIAL COMMERCIAL TOTAL COST** JOB CODE JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS **LABOR** 66-PM-PMA DON Ρ **GARAGE** \$31.52 \$31.52 PERFORM OIL CHANGE Ν 0.40 \$0.00 \$0.00 JOB COUNT: 1 WORK ORDER TOTAL: 0.40 0.00 31.52 0.00 31.52 **Job Code Job Description** Employee No. Start Finish **Quantity Total Cost** 66-PM-PMA PERFORM OIL CHANGE 12052187 09/23/2020 12:01:43 09/23/2020 12:01:43 0.00 \$0.00 0.00 66-PM-PMA PERFORM OIL CHANGE 12052187 09/23/2020 12:01:43 09/23/2020 12:01:43 \$0.00 66-PM-PMA PERFORM OIL CHANGE 12052187 09/23/2020 12:01:43 09/23/2020 12:13:43 0.20 \$0.00 66-PM-PMA PERFORM OIL CHANGE 11901357 09/23/2020 12:00:03 09/23/2020 12:12:03 0.20 \$0.00 66-PM-PMA PERFORM OIL CHANGE 11901357 09/23/2020 12:00:03 09/23/2020 12:00:03 0.00 \$0.00 66-PM-PMA 0.00 \$0.00 PERFORM OIL CHANGE 11901357 09/23/2020 12:00:03 09/23/2020 12:00:03 **LABOR** 0.00 **Job Code Job Description** Part No. **Unit Price** Quantity **Total Cost** Description 7 66-PM-PMA PERFORM OIL CHANGE 5W30T 5W30 SYNTHETIC OIL THOMAS CAM2 3.88 \$27.16 66-PM-PMA PERFORM OIL CHANGE BALB329 **OIL FILTER** 4.36 \$4.36 31.52 **PARTS**

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 37709

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° RC,AB,JAW/AMG

JOB COUNT: 2

243687

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

0.00

118.00

UNIT NO: 2020 FORD F250 **WORK ORDER NO:** 38803 **USING DEPT NO:** 504241 OPENED DATE: 01/15/2021 08:11:59 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 01/21/2021 11:30:46 COMPLETED DATE: METER 1 - M: 2326 **METER 2 - H**: 0 **WO VISIT REASON: SCHEDULED** 01/21/2021 12:23:34 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2020

TECH SPEC NO: 20FORDF250 2020 Ford F250 **UNIT SERIAL NO:** 1FT7X2A65LEC32108

WORK ORDER TOTAL:

COMMERCIAL TOTAL COST JOB CODE **JOB LOC MATERIAL** JOB DESCRIPTION STAT RSN WRTY LABOR HRS LABOR 16-52 DON 0 **GARAGE** 1.00 \$118.00 \$0.00 \$0.00 TRANSPORT ELECTRICAL ACCESSORI \$118.00 17-52-024 RECALL BACK UP CAMERA DON R **GARAGE** 0.00 \$0.00 \$0.00 \$0.00 \$0.00

1.00

118.00

0.00

Job Code Job Description Vendor No. Invoice No. Purchase Order No. **Total Cost** 609648 17-52-024 RECALL BACK UP CAMERA 4910000 \$0.00 COMML 0.00 **Job Code Job Description** Employee No. Start Finish **Total Cost** Quantity 16-52 TRANSPORT ELECTRICAL ACCESSORIES 11915538 01/21/2021 07:00:00 01/21/2021 08:00:00 1.00 \$118.00 17-52-024 RECALL BACK UP CAMERA 11915538 01/21/2021 07:00:00 01/21/2021 08:00:00 (1.00)(\$118.00)17-52-024 RECALL BACK UP CAMERA 11915538 01/21/2021 07:00:00 01/21/2021 08:00:00 1.00 \$118.00 **LABOR** 118.00

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 38803

Work Order Notes

(LISAPATE) Take to Town and Country Ford to complete recall 20C19 rearview camera could intermittently display a blank or distorted image

Job Notes

16-52 - TRANSPORT ELECTRICAL ACCESSORIES

(LISAPATE) Taken to Town and Country by RC

17-52-024 - RECALL BACK UP CAMERA

(LISAPATE) Town and Country completed recall 20C19 Rear view camera improper function

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 **WORK ORDER NO:** 39056 **USING DEPT NO:** 504241 OPENED DATE: 02/09/2021 08:02:41 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 02/12/2021 11:46:05 COMPLETED DATE: **METER 1 - M**: 2591 **METER 2 - H**: 0 **WO VISIT REASON: SCHEDULED** 02/17/2021 09:20:32 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2020 **TECH SPEC NO:** 20FORDF250 2020 Ford F250 **UNIT SERIAL NO:** 1FT7X2A65LEC32108 **LABOR** JOB CODE RSN WRTY JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 0.04 \$4.98 \$0.00 \$0.00 \$4.98 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.04 4.98 0.00 0.00 4.98 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 12052187 02/09/2021 13:00:00 02/09/2021 13:02:32 0.04 \$4.98 66-PM-PMA PERFORM OIL CHANGE 12052187 0.00 \$0.00 02/09/2021 12:52:58 02/09/2021 12:52:58 LABOR 4.98

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 39056

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1173 miles since last pm. Updated sticker. Checked all fluids and tires. Coolant -35°. JAW,SH MILEAGE-2591

UNIT NO:		243687	2020 FORI	D F250)				WORK OF	RDER NO	: 40	739		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250		OPENE COMPL CLOSE Ford F25	ETED	DATE:	08/20/202	21 07:51:03 21 10:26:03 21 10:55:00	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 4148 DATE:	ME 02/20/202	TER 2 - H:	0	
JOB CODE		JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	Ν	GARAGE	0.03	\$3.61	\$15.18	\$0.	00	\$18.79	
66-17-033	PERFOR	M TIRE ROTATION	N AND BRAKE	DON	Р	N	GARAGE	0.20	\$23.93	\$0.00	\$0.	00	\$23.93	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.15	\$17.21	\$45.42	\$0.	00	\$62.63	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.	00	\$2.00	
JOB COUN	IT: 4				WC	RK ORI	DER TOTAL	0.38	44.	75	60.60	2.00		107.35
Job Code		Job Descript	tion_		<u>v</u>	endor N	l <u>o.</u>	Invoice No.	Purchas	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	tion_		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	inish		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	1901357	,	08	/13/2021 09:30:00	08/13/202	1 09:38:45		0.15		\$17.21
66-PM-PMA	PERFORM (OIL CHANGE		1	1901357	7	08	/13/2021 09:15:51	08/13/202	1 09:15:51		0.00		\$0.00
03-51-038	REPLACE N	EW WIPER BLADES		1	1901357	,	08	/13/2021 09:03:07	08/13/202	1 09:04:57		0.03		\$3.61
66-17-033	PERFORM T	TIRE ROTATION AND	BRAKE INSPE	CTION 1	1901357	,	08	/13/2021 08:50:26	08/13/202	1 09:02:36		0.20		\$23.93
												LABOR		44.75
Job Code		Job Descript	tion_			Part No	<u>.</u>	<u>Des</u>	cription	Ţ	Unit Price	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		2	2-1		W	IPER BLADE 22" 1	TRICO EXACT		7.59	2		\$15.18
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329	1	OI	L FILTER			4.68	1		\$4.68
66-PM-PMA	PERFORM	OIL CHANGE		5	W30T		5V	V30 SYNTHETIC (OIL THOMAS CA	AM2	5.82	7		\$40.74
												PARTS		60.60

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 40739

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. Performed a relearn on TPMS. AMG SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 4148 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

UNIT NO:		243687	2020 FOR	D F250)				WORK OF	RDER NO	: 41	1888		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250	2020	OPENE COMPL CLOSE Ford F25	ETED D DAT	DATE:	12/15/202	21 14:22:31 21 08:19:11 21 08:11:39	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 4870 E DATE :	MI 02/20/20		0	
JOB CODE	_	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	Ν	GARAGE	0.05	\$5.70	\$15.18	\$0	0.00	\$20.88	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	Ν	GARAGE	0.32	\$37.37	\$0.00	\$0	0.00	\$37.37	
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3				WC	RK OR	DER TOTAL:	0.37	43.	.07	15.18	2.00		60.25
Job Code		Job Descript	tion_		<u>v</u>	endor N	lo.	Invoice No.	Purchas	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE S	hop Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	tion_		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	7	12	/15/2021 07:28:17	12/15/202	1 07:47:17		0.32		\$37.37
03-51-038	REPLACE N	NEW WIPER BLADES		1	2052187	7	12	/15/2021 07:25:15	12/15/202	1 07:28:09		0.05		\$5.70
												LABOR		43.07
Job Code		Job Descript	tion_			Part No	<u>).</u>	Des	cription	<u> </u>	Jnit Price	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	NEW WIPER BLADES		2	2-1		WI	PER BLADE 22"	TRICO EXACT		7.59	2		\$15.18
												PARTS		15.18

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 41888

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 722 miles since last pm. Updated pm sticker. Checked fluids and tires. Coolant -34°. JAW MILEAGE-4870

CH-SP - CHARGE Shop Supplies

UNIT NO:		243687	2020 FOR	D F250)				WORK O	RDER NO:	42397		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504241 CLOSED SCHEDULED 20FORDF250	2020	OPENE COMPL CLOSE Ford F25	ETED D DAT	DATE:	02/21/202	2 09:40:09 2 09:51:32 2 07:18:34	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	DATE: 0	Iniversity Auto METER 2/20/2020 FT7X2A65LE	2 - H:	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>NC</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIA	AL COMME	ERCIAL	TOTAL COST
66-79-002	PERFOR	RM SERVICE CALL		DON	В	Ν	GARAGE	0.04	\$4.39	\$0.00	\$0.00		\$4.39
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.44		\$0.44
JOB COUN	T: 2				wo	RK ORE	DER TOTAL:	0.04	4	.39 (0.00	0.44	4.83
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No.			Total Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1						\$0.44
											C	OMML	0.44
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>	<u>!</u>	<u> inish</u>	<u>Qι</u>	<u>ıantity</u>	Total Cost
66-79-002	PERFORM	SERVICE CALL		1	1399745	i	02/	18/2022 10:11:32	02/18/202	22 10:13:46	<u>_</u>	0.04	\$4.39
											L	ABOR	4.39

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 42397

Work Order Notes

(LISAPATE) Scott requested a service call to BM truck has been sitting has a dead battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(GARAGE) jumped vehicle off. CW

CH-SP - CHARGE Shop Supplies

Page:1

Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		243687 2	020 FORD	F250)				WORK	ORDER NO): 43	3275		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250	•	COMPI	ED DAT ETED ED DAT	DATE:	05/19/20	022 09:20:50 022 15:36:27 022 13:34:35	METER 1	N: GARAGE -M: 5588 CE DATE: RIAL NO:	ME 02/20/202	TER 2 - H:		
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>I</u>	STAT	RSN	WRTY	JOB LO	LABOR HRS	LABO	R MATE	RIAL CO	OMMERCIAL	TOTAL	COST
03-34-002	REPLACE	NEW LAMPS-REAF	R,TAIL,STO	DON	Р	N	GARAGE	0.06	\$6.88	\$0.95	\$0.	.00	\$7.83	
03-51-038	REPLACE	NEW WIPER BLAD	ES	DON	Р	Ν	GARAGE	0.02	\$2.88	\$15.18	\$0.	.00	\$18.06	
03-PM-PMC	REPLACE	NEW CABIN FILTE	R REPLAC	DON	Р	N	GARAGE	0.30	\$35.40	\$16.92	\$0.	.00	\$52.32	
24-02-016	REPAIR T	AIL&LIFT GATE		DON	0	N	GARAGE	0.05	\$6.03	\$0.00	\$0.	.00	\$6.03	
66-PM-PMA	PERFORM	M OIL CHANGE		DON	Р	N	GARAGE	0.28	\$32.61	\$60.98	\$0.	.00	\$93.59	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.	.00	\$2.00	
JOB COUN	IT: 6				WC	RK ORI	DER TOTAI	.: 0.71		83.80	94.03	2.00		179.83
Job Code		Job Description	<u>n</u>		<u>v</u>	endor N	lo.	Invoice No.	Purcl	hase Order N	<u>o.</u>		Total	Cost
CH-SP	CHARGE Sho	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
03-PM-PMC	REPLACE NE	EW CABIN FILTER REP	PLACEMENT	1	1901357	•	C	5/17/2022 12:18:46	05/17/2	2022 12:36:46		0.30		\$35.40
03-PM-PMC	REPLACE NE	EW CABIN FILTER REP	PLACEMENT	1	1901357	•	C	5/17/2022 12:18:46	05/17/2	2022 12:18:46		0.00		\$0.00
03-PM-PMC	REPLACE NE	EW CABIN FILTER REP	PLACEMENT	1	1901357	•	C	5/17/2022 12:18:46	05/17/2	2022 12:18:46		0.00		\$0.00
03-51-038	REPLACE NE	W WIPER BLADES		1	1074414	ļ	C	5/17/2022 10:56:44	05/17/2	2022 10:58:12		0.02		\$2.88
24-02-016	REPAIR TAIL	&LIFT GATE		1	1074414	ļ	C	5/17/2022 10:53:27	05/17/2	2022 10:56:31		0.05		\$6.03
03-34-002	REPLACE NE	EW LAMPS-REAR,TAIL	,STOP,TURN,	ETC 1	1074414	ļ	C	5/17/2022 10:49:44	05/17/2	2022 10:53:14		0.06		\$6.88
66-PM-PMA	PERFORM O	IL CHANGE		1	1074414	ļ	C	5/17/2022 10:32:58	3 05/17/2	2022 10:49:33		0.28		\$32.61
												LABOR		83.80
Job Code		Job Description	<u>n</u>			Part No	<u>.</u>	<u>Des</u>	scription	,	Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM O	IL CHANGE		5	W30T		5	W30 SYNTHETIC	OIL THOMAS	CAM2	7.52	7		\$52.61
66-PM-PMA	PERFORM O	IL CHANGE		Е	BALB329		C	IL FILTER			8.37	1		\$8.37
03-PM-PMC	REPLACE NE	W CABIN FILTER REP	PLACEMENT	F	C8214		C	ABIN FILTER			16.92	1		\$16.92
03-51-038		W WIPER BLADES			2-1			VIPER BLADE 22"			7.59	2		\$15.18

The University of Alabama

Work Order Charge Detail

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.95	1	\$0.95
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	PC8214	CABIN FILTER	16.92	(1)	(\$16.92)
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	PC8214	CABIN FILTER	16.92	1	\$16.92
				•	PARTS	94.03

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 43275

Work Order Notes

(LISAPATE) PM-replace wipers-repair tailgate a piece fell off

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(HHARBIN) Replaced right side upper brake light bulb. SH

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

24-02-016 - REPAIR TAIL&LIFT GATE

(HHARBIN) Reinstalled the rubber stop for the tail gate. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

UNIT NO:	-		2020 FOR	D F250)				WORK O	RDER NO	: 43	362		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250	2020	OPENE COMPL CLOSE Ford F25	ETED D DAT	DATE:	05/26/202	22 09:25:05 22 13:54:05 22 14:39:04	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 5602 E DATE:	ME 02/20/202	y Automotive S E TER 2 - H: 20 .65LEC32108		
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL .	TOTAL	COST
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.	.00	\$2.00	
PR-51-046	PROGRA	AM KEY BLANK(S)		DON	0	N	GARAGE	0.50	\$59.00	\$0.00	\$0.	.00	\$59.00	
PU-51-046	PURCHA	SED KEY BLANK(S)	DON	0	N	GARAGE	0.10	\$11.80	\$224.25	\$0.	.00	\$236.05	
JOB COUN	T: 3				WO	RK ORI	DER TOTAL:	0.60	7(0.80	224.25	2.00		297.05
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	Purcha	ase Order No	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$2.00
-												COMML		2.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
PU-51-046	PURCHASE	D KEY BLANK(S)		10	0208562	2	05/	27/2022 07:00:00	05/27/20	22 07:06:00		0.10		\$11.80
PR-51-046	PROGRAM	KEY BLANK(S)		1	1310047	•	05/	26/2022 07:00:00	05/26/20	22 07:30:00		0.50		\$59.00
												LABOR		70.80
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	<u>cription</u>	<u>!</u>	Unit Price	Quantity	<u>Total</u>	Cost
PU-51-046	PURCHASE	D KEY BLANK(S)		10	64R8130)	KE	Y/KEY FOB			224.25	1		\$224.25
												PARTS		224.25

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 43362

Work Order Notes

(EKIMBREL) purchase and program key fob

Job Notes

CH-SP - CHARGE Shop Supplies

PR-51-046 - PROGRAM KEY BLANK(S)

(LISAPATE) EH programmed all keys to vehicle

PU-51-046 - PURCHASED KEY BLANK(S)

(IFALLS) EK PURCHASED KEY FROM TOWN & COUNTRY

UNIT NO:		243687	2020 FORI	D F250)				WORK (ORDER NO): 4	4407		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250	2020 F	OPENE COMPL CLOSE Ford F25	ETED	DATE:	08/24/20	022 08:50:14 022 13:52:28 022 08:49:54		- M: 6506 CE DATE:	M 02/20/20		0	
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL C	OMMERCIAL	TOTAL	COST
66-17-030	PERFOR	M TIRE PATCH		DON	Ο	N	GARAGE	0.65	\$76.73	\$5.32	\$0	0.00	\$82.05	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3	5.00	\$5.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	.: 0.65	5 7	6.73	5.32	5.00		87.05
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purch</u>	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-17-030	PERFORM 1	TIRE PATCH		1	2296277	7	0	8/22/2022 10:30:35	08/22/2	022 11:09:36		0.65		\$76.73
												LABOR		76.73
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	scription		Unit Price	Quantity	<u>Total</u>	Cost
66-17-030	PERFORM 1	TIRE PATCH		2	1097		Т	PMS NICKEL VALV	VE CORE		0.29) 1		\$0.29
66-17-030	PERFORM 1	TIRE PATCH		1	4041		Р	ATCH 1/4 PILOT V	VIRE		4.31	1 1		\$4.31
66-17-030	PERFORM 1	TIRE PATCH		5	8120		.2	25 OZ WHEEL WE	IGHT		0.29) 1		\$0.29
66-17-030	PERFORM 1	TIRE PATCH		5	8121		.5	0 OZ WHEEL WE	IGHT		0.43	31		\$0.43
												PARTS		5.32

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 44407

Work Order Notes

(LISAPATE) Nail in RF tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Patched RF tire

CH-SP - CHARGE Shop Supplies

UNIT NO:		243687	2020 FOR	D F250)				WORK O	RDER NO): 44	914		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250		OPENE COMPL CLOSE ord F25	ETED D DAT	DATE:	10/13/202	22 08:13:44 22 11:58:28 22 09:25:43	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 6877 E DATE :	ME 02/20/202	y Automotive S ETER 2 - H: 20 .65LEC32108		
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL CO	OMMERCIAL	TOTAL C	COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	N	GARAGE	0.20	\$23.60	\$15.63	\$0.	.00	\$39.23	
66-44-061	PERFOR	RM SMOKE TEST		DON	0	N	GARAGE	1.00	\$118.00	\$0.00	\$0.	.00	\$118.00	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.24	\$27.93	\$0.00	\$0.	.00	\$27.93	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	.00	\$5.00	
SO-05	SCAN O	UT ELECTRONIC E	ENGINE EEC	DON	0	N	GARAGE	0.97	\$114.56	\$0.00	\$0.	.00	\$114.56	
JOB COUN	IT: 5				WC	RK ORI	DER TOTAL:	2.41	284	.09	15.63	5.00		304.72
Job Code	CHARGE SI	Job Descript	<u>tion</u>	5	<u>V</u> 03163	endor N	lo. 1	Invoice No.	<u>Purcha</u>	se Order N	lo.		<u>Total C</u>	Cost \$5.00
OI I-OI	CHARGE SI	iop oupplies		3	00100		ı					COMML		5.00
Job Code		Job Descript	tion		En	nployee	No.	Start		Finish_		Quantity	Total C	Cost
66-44-061	PERFORM	SMOKE TEST		1	2296277	7	10	/17/2022 07:00:00	10/17/202	22 08:00:00		1.00		\$118.00
03-51-038	REPLACE N	IEW WIPER BLADES	;	1	2052187	7	10	/17/2022 07:00:00	10/17/202	22 07:12:00		0.20		\$23.60
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	M 1	2296277	7	10	/12/2022 07:31:48	10/12/202	22 08:30:03		0.97		\$114.56
66-PM-PMA	PERFORM (OIL CHANGE		1	2052187	7	10	/07/2022 12:28:09	10/07/202	22 12:42:21		0.24		\$27.93
												LABOR		284.09
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	<u>cription</u>		Unit Price	Quantity	<u>Total C</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES	i	2	2-1		WI	PER BLADE 22" T	RICO EXACT		7.82	2		\$15.63
												PARTS		15.63

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 44914

Work Order Notes

(LISAPATE) PM-replace wipers-Check engine light is on

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wiper blades truck needed them jdm

66-44-061 - PERFORM SMOKE TEST

(LISAPATE) JDM performed a smoke test

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1289 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW MILEAGE-6877

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(GARAGE) scanned it found small evap leak smoked and did drove it a few times check engine light never came back on jdm

UNIT NO:			2020 FOR	D F250)				WORK OF	RDER NO	: 4	5100		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250	2020	OPENE COMPL CLOSE Ford F25	ETED D DAT	DATE:	10/28/202	22 14:00:05 22 15:25:53 22 08:21:00	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1 : 7031 DATE :	M 02/20/20	ty Automotive S IETER 2 - H: D20 A65LEC32108		
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
14-32-002	INSTALL	BATTERY		DON	0	N	GARAGE	0.20	\$24.03	\$113.55	\$0	0.00	\$137.58	
66-79-002	PERFOR	M SERVICE CALL		DON	0	N	GARAGE	0.53	\$62.34	\$0.00	\$0	0.00	\$62.34	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	0.73	86.	37	113.55	5.00		204.92
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchas	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
14-32-002	INSTALL BA	TTERY		1	1074414		10/	/28/2022 07:26:14	10/28/202	2 07:38:27		0.20		\$24.03
66-79-002	PERFORM S	SERVICE CALL		1	1074414		10/	/27/2022 15:10:49	10/27/202	2 15:42:31		0.53		\$62.34
												LABOR		86.37
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	<u>cription</u>	<u> </u>	Jnit Price	Quantity	<u>Total</u>	Cost
14-32-002	INSTALL BA	TTERY		6	50		ВА	TTERY BCI 65 65	0 CCA		113.55	51		\$113.55
												PARTS		113.55

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 45100

Work Order Notes

(IFALLS) Jim requested a service call truck would not start.

Job Notes

14-32-002 - INSTALL BATTERY

(SHARBIN) Battery checked bad. Factory battery no warranty. Installed a new battery ALT charging at 14.6 volts. SH

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Performed a service call to building maintenance for a dead battery. Vehicle started drove it back to the shop. SH

CH-SP - CHARGE Shop Supplies

UNIT NO:		243687	2020 FORD F250)				WORK OR	DER NO): 4	6308		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504241 CLOSED SCHEDULED 20FORDF250	COMP	D DAT	DATE:	02/28/2023 12:45:42 03/03/2023 12:00:56 03/03/2023 13:53:39		LOCATION: GARAGI METER 1 - M: 7477 IN-SERVICE DATE: UNIT SERIAL NO:		M 02/20/20	ETER 2 - H:	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	ON STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES DON	Р	N	GARAGE	0.07	\$7.83	\$15.63	\$0	0.00	\$23.46	
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.11	\$12.55	\$57.81	\$0	0.00	\$70.36	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUNT: 3			WC	RK ORI	DER TOTAL	: 0.17	20.3	38	73.44	5.00	١	98.82	
Job Code		Job Descript	<u>ion</u>	<u>v</u>	endor N	lo.	Invoice No.	<u>Purchas</u>	e Order N	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Shop Supplies		5	503163			1						\$5.00
											COMML		5.00
Job Code		Job Descript	<u>ion</u>	<u>En</u>	nployee	No.	<u>Start</u>	<u>F</u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
03-51-038	REPLACE NEW WIPER BLADES		1	11074414			02/28/2023 13:46:16		3 13:50:15		0.07		\$7.83
66-PM-PMA	PERFORM OIL CHANGE		1	11074414			02/28/2023 13:39:41		3 13:46:04		0.11		\$12.55
											LABOR	1	20.38
Job Code		Job Description Part No				<u>.</u>	<u>Description</u>			Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	E	BALB329		0	L FILTER			5.94	1		\$5.94
03-51-038	REPLACE NEW WIPER BLADES			22-1			IPER BLADE 22"	TRICO EXACT		7.82	2 2		\$15.63
66-PM-PMA	PERFORM (OIL CHANGE	5	T0EW		5\	V30 SYNTHETIC (OIL THOMAS CA	M2	7.41			\$51.87
											PARTS		73.44

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 46308

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Page:1

Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		243687	2020 FOR	F250)				WORK C	ORDER NO): 4	6551		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504241 CLOSED SCHEDULED 20FORDF250 2020 F		OPENED DATE: COMPLETED DATE: CLOSED DATE: Ford F250			03/29/2023 08:11:50 05/02/2023 09:17:21 05/02/2023 11:30:22		LOCATION: GARAGE METER 1 - M: 7477 IN-SERVICE DATE: UNIT SERIAL NO:		E - University Automotive METER 2 - H: 02/20/2020 1FT7X2A65LEC32108		0	
JOB CODE	E JOB DESCRIPTION		<u>DN</u>	STAT RSN WRTY		JOB LO	JOB LOC LABOR HRS		LABOR MATE		OMMERCIAL	L TOTAL COST		
03-44-001	REPLACE NEW TANK - FUEL, LIQUID		DON	0	Ν	GARAGE	3.21	\$378.85	\$984.04	\$0	0.00	\$1,362.89		
66-44-061	PERFORM SMOKE TEST		DON	0	Ν	GARAGE	1.61	\$189.46	\$0.00	\$0	0.00	\$189.46		
66-79-003	PERFOR	RM SAFETY INSPEC	CTION	DON	Υ	N	GARAGE	0.07	\$8.19	\$0.00	\$0	0.00	\$8.19	
CH-SP	-SP CHARGE Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00 \$0.00		\$5	5.00	\$5.00		
SO-00	O-00 SCAN OUT COMPLETE VEHICLE		DON	0	N	GARAGE	1.20	\$141.11	\$0.00	\$0	0.00	\$141.11		
WA-00	WASH C	OMPLETE VEHICLE	≣	DON	Р	N	GARAGE	0.00	\$0.00	\$0.00	\$0	0.00	\$0.00	
JOB COUNT: 6				WO	RK OR	DER TOTA	L: 6.08	3 71	7.61	984.04	5.00	1,706.65		
Job Code	Job Code Job Description		<u>on</u>	Vendor N			lo.	Invoice No.		Purchase Order No			Total Cost	
CH-SP	CHARGE SI	nop Supplies		5	03163			1					\$5.00	
												COMML	5.00	
Job Code		Job Description		Employee			No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost	
03-44-001	REPLACE N	IEW TANK - FUEL, LIC	QUID	11310047				04/24/2023 14:12:18		3 04/24/2023 14:59:50		0.79	\$93.48	
03-44-001	REPLACE NEW TANK - FUEL, LIQUID		11310047				04/24/2023 09:40:13		023 11:55:33		2.26	\$266.16		
03-44-001	REPLACE NEW TANK - FUEL, LIQUID		11310047			04/24/2023 07:22:18		3 04/24/2	04/24/2023 07:32:04		0.16	\$19.21		
SO-00	SCAN OUT COMPLETE VEHICLE			11310047			04/17/2023 13:03:15		04/17/2	04/17/2023 14:15:00		1.20	\$141.11	
66-79-003	PERFORM SAFETY INSPECTION			12052187			03/30/2023 12:31:19		03/30/2023 12:35:29			0.07	\$8.19	
66-44-061	-44-061 PERFORM SMOKE TEST			11310047			03/30/2023 07:49:31		03/30/2023 09:25:51			1.61	\$189.46	
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM			M 11310047			03/30/2023 07:06:13		3 03/30/2023 07:48:28			0.70	\$83.09	
SO-05	SCAN OUT	ELECTRONIC ENGINE	E EEC SYSTEM	1 1	1310047	•		03/30/2023 07:06:13	3 03/30/2	023 07:48:28		(0.70	(\$83.09)	
												LABOR	717.61	
Job Code	<u>Job Description</u>			Part No.			<u>De</u> s		cription		Unit Price	Quantity	Total Cost	
03-44-001	REPLACE N	IEW TANK - FUEL, LIC	QUID	4L3Z9276AA				O-RING FUEL TANK		(1	\$5.24	
03-44-001	REPLACE NEW TANK - FUEL, LIQUID			LC3Z9002S				FUEL TANK			511.88	1	\$511.88	
03-44-001	44-001 REPLACE NEW TANK - FUEL, LIQUID			F	C3Z9D6	60A		FUEL LINE				1	\$466.92	

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

PARTS

984.04

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 46551

Work Order Notes

(EHANNAH) do SI - wash -check engine light is on

Job Notes

03-44-001 - REPLACE NEW TANK - FUEL, LIQUID

(EHOWELL) Replaced fuel tank and one plastic hose. No extra labor for hose. EH

66-44-061 - PERFORM SMOKE TEST

(EHOWELL) Performed a smoke test on the EVAP system. Found smoke exiting the system on top of the fuel tank near the roll over valve. It appeared that the smoke may have been coming from a plastic line connection. Replaced line, but the smoke was still exiting the system due to a small hole in the fuel tank. EH

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Engine light is on. EH scanned out. JAW

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(LISAPATE) Found DTC: P0456:00 EC EVAP System Leak Detected (Very Small) EH

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE)

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) unit was not washed

UNIT NO:		243687	2020 FOR	D F250				WORK C	RDER NO		47508				
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504241 CLOSED SCHEDULED 20FORDF250	COI		OPENED DATE: COMPLETED DATE: CLOSED DATE: ord F250		07/03/2023 09:28:14 07/05/2023 09:44:16 07/05/2023 10:21:20				02/20/2	University Automotive S METER 2 - H: 02/20/2020 1FT7X2A65LEC32108		0	
JOB CODE	<u>:</u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATEI</u>	RIAL	COMMERCIAL	TOTAL	COST	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	Ν	GARAGE	0.14	\$16.59	\$0.00		\$0.00	\$16.59		
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00		
WA-00	WASH C	OMPLETE VEHICL	E	DON	Р	N	GARAGE	0.00	\$0.00	\$0.00		\$0.00	\$0.00		
JOB COUN	T: 3				WO	RK ORE	ER TOTAL:	0.14	1	6.59	0.00	5.00		21.59	
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purch	ase Order No	<u>).</u>		<u>Total</u>	Cost	
CH-SP	CHARGE SI	hop Supplies		5	03163		1							\$5.00	
												COMML		5.00	
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost	
66-PM-PMA	PERFORM	M OIL CHANGE		11074414			07/	07/03/2023 14:56:22		07/03/2023 15:04:48		0.14		\$16.59	
												LABOR		16.59	

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 47508

Work Order Notes

(EHANNAH) pm- replace wipers- wash (EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 608 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed SH

UNIT NO:	NIT NO: 243687 2020 FOR			F250					WORK ORI	49161			
WO STATUS	JSING DEPT NO: 504241 NO STATUS: CLOSED NO VISIT REASON: SCHEDULED FECH SPEC NO: 20FORDF250 2020		1	OPENED DATE: COMPLETED DATE: CLOSED DATE: Ford F250			12/07/20	12/06/2023 07:42:49 12/07/2023 14:43:32 12/11/2023 09:02:03			ersity Automo METER 2 - 0/2020 7X2A65LEC3	Н:	ervices 0
JOB CODE	<u> </u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMER	CIAL	TOTAL COST
06-15	INSPECT	T STEERING		DON	Ν	N	GARAGE	0.14	\$16.98	\$0.00	\$0.00	9	\$16.98
09-15	ALIGN S	TEERING		DON	Ν	Ν	GARAGE	1.09	\$128.78	\$0.00	\$0.00	9	\$128.78
66-17-028	PERFOR	M MOUNT AND BALANCE	TIRE	DON	Ν	Ν	GARAGE	1.09	\$128.39	\$1,098.17	\$0.00	9	\$1,226.56
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.61	\$71.52	\$71.88	\$0.00	9	\$143.40
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	9	\$5.00
WA-00	WASH C	OMPLETE VEHICLE		DON	Р	N	GARAGE	0.54	\$63.39	\$0.00	\$0.00	9	\$63.39
JOB COUN	IT: 6			WORK ORDER TOTAL:				.: 3.47	409.0	6 1,170.0	5	5.00	1,584.11
Job Code	Job Description			<u>Vendor No</u>			l <u>o.</u>	Invoice No.	Purchase Order No.				Total Cost
CH-SP	CHARGE Sh	nop Supplies		50	3163		1						\$5.00
											СОМ	INIL	5.00
Job Code	DEDI AGE N	Job Description		4.		<u>iployee</u>		<u>Start</u>		<u>nish</u>	<u>Quan</u>	_	Total Cost
03-51-038		IEW WIPER BLADES			1074414			2/07/2023 07:00:00				0.10	\$11.80
03-51-038		IEW WIPER BLADES		11074414			12/07/2023 07:00:00 12/07/2023 09:06:16					(0.10)	(\$11.80)
09-15 WA-00	ALIGN STEE	PLETE VEHICLE		11310047								1.09 0.54	\$128.78 \$63.39
WA-00		PLETE VEHICLE		11074414			12/06/2023 13:00:00					0.00	\$0.00
66-17-028		MOUNT AND BALANCE TIRES	2	11074414			12/06/2023 12:59:18 12/06/2023 10:48:33					1.09	\$128.39
06-15			,	11074414 11074414				2/06/2023 08:53:51				0.14	\$16.98
06-15	INSPECT STEERING INSPECT STEERING				1074414			2/06/2023 08:53:51				(0.14)	(\$16.98)
06-15	INSPECT STEERING				074414			2/06/2023 08:53:51				0.14	\$16.98
66-PM-PMA					074414			2/06/2023 08:10:46				0.61	\$71.52
											LAB		409.06
Job Code		Job Description				Part No	<u>.</u>	Des	cription	<u>Unit Pı</u>	rice Quan	itity	Total Cost

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.42	7	\$65.94
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	4	\$14.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.50	2	\$0.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	2	\$1.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.10	3	\$3.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.34	2	\$2.67
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450515	TIRE LT245/75R17 GEN GRABHTS60	268.80	4	\$1,075.20
					PARTS	1170.05

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 49161

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(SHARBIN) Inspected the steering. Found no issues at this time. SH (IFALLS) Visit Reason Changed On 12/11/2023 9:01 AM By IFALLS

09-15 - ALIGN STEERING

(EHOWELL) Set front toe. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) SH Mounted FC Balanced 4 tires. FC Put the tires back on the truck. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. Vehicle needs 4 tires due to tread depths and outer shoulder wear. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

UNIT NO:		243687 2	020 FOR	243687 2020 FORD F250): 50	0762		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		504241 CLOSED SCHEDULED 20FORDF250	2020 I	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2020 Ford F250			05/08/202	4 07:01:15 4 08:27:09 4 09:47:30			M l 02/20/20	- University Automotive S METER 2 - H: 02/20/2020 1FT7X2A65LEC32108		
JOB CODE		JOB DESCRIPTION	<u>I</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOI	R MATE	<u>ERIAL</u> C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLAD	ES	DON	Р	N	GARAGE	0.01	\$1.54	\$16.65	\$0	0.00	\$18.19	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.02	\$2.07	\$0.00	\$0	0.00	\$2.07	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
WA-00	WASH C	OMPLETE VEHICLE		DON	Р	N	GARAGE	0.01	\$1.02	\$0.00	\$0	0.00	\$1.02	
JOB COUN	JOB COUNT: 4				WO	RK ORI	DER TOTAL:	0.04		4.63	16.65	5.00		26.28
Job Code		Job Description	<u>1</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purch</u>	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		1	1074414	ļ	05/	07/2024 07:20:08	3 05/07/2024 07:20:55			0.01		\$1.54
WA-00	WASH COM	PLETE VEHICLE		1	1074414	ļ.	05/	07/2024 07:19:37	7 05/07/2024 07:20:08			0.01		\$1.02
66-PM-PMA	PERFORM (OIL CHANGE		1	1074414	ļ	05/	07/2024 07:18:34	05/07/2	024 07:19:37		0.02		\$2.07
												LABOR		4.63
Job Code		Job Description	<u>n</u>			Part No	<u>.</u>	Des	scription		<u>Unit Price</u>	<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		2:	2-1		WII	PER BLADE 22" 1	TRICO EXACT		8.33			\$16.65
												PARTS		16.65

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 50762

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 1158 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FC Washed. SH

UNIT NO:		243687 2020	FORD F2	50				WORK ORDER NO: 5): 52	2451	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	504241 CLOSED PREVENTIVE MAINT 20FORDF250	СОМ	SED DA	D DATE:	10/11/202	4 07:54:12 4 15:44:32 4 13:30:24	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	11661 DATE:	ME 02/20/20	ETER 2 - H:	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STA</u>	T RS	N WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	DOI	N P	Ν	GARAGE	0.00	\$0.00	\$16.65	\$0	.00	\$16.65
66-79-003	PERFOR	M SAFETY INSPECTION	l DOI	۱ Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0	.00	\$0.00
66-PM-PMA	PERFOR	M OIL CHANGE	DOI	N P	N	GARAGE	0.00	\$0.00	\$67.89	\$0	.00	\$67.89
CH-SP	CHARGE	Shop Supplies	DOI	N 2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00
JOB COUN	IT: 4			٧	ORK OR	DER TOTAL:	0.00	0.0	0	84.54	5.00	89.54
Job Code		Job Description			Vendor N	<u>lo.</u>	Invoice No.	<u>Purchase</u>	Order N	<u>o.</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		503163	3	1						\$5.00
											COMML	5.00
Job Code		Job Description			Part No	<u>).</u>	<u>Des</u>	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		BALB3	29	OIL	FILTER			5.94	1	\$5.94
03-51-038	REPLACE N	IEW WIPER BLADES		22-1			PER BLADE 22" 1	TRICO EXACT		8.33	2	\$16.65
66-PM-PMA	PERFORM (OIL CHANGE		5W30T		5W	5W30 SYNTHETIC (M2	8.85	7	\$61.95
											PARTS	84.54

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 52451

Work Order Notes

(EHOWELL) PM. Turn signal is blinking fast.

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GC

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed safety inspection, found no issues at this time-GC rotated tires and relearned tire positions brake pads are 8mm front and rear Miles, 11,661

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure. Miles, 11,661

CH-SP - CHARGE Shop Supplies

The University of Alabama

Work Order Charge Detail

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 **WORK ORDER NO:** 52834 **USING DEPT NO:** 504241 **OPENED DATE:** 11/18/2024 08:49:07 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 11/19/2024 09:35:05 **WO STATUS: METER 1 - M**: 12072 **COMPLETED DATE: METER 2 - H**: 0 **WO VISIT REASON: SCHEDULED** 11/19/2024 11:26:32 **IN-SERVICE DATE: CLOSED DATE:** 02/20/2020 **TECH SPEC NO:** 20FORDF250 2020 Ford F250 **UNIT SERIAL NO:** 1FT7X2A65LEC32108 RSN WRTY JOB LOC LABOR HRS COMMERCIAL TOTAL COST JOB CODE **JOB DESCRIPTION** <u>STAT</u> **LABOR MATERIAL** 25-52-021 REMOVE GPS SYSTEM DON 5 Ν GARAGE 0.00 \$0.00 \$0.00 \$0.00 \$0.00 JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 52834

Work Order Notes

(EHANNAH) remove GPS

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) GC & JR- remove GPS (GARAGE) GPS SN: 87U030640234

UNIT NO:		243687	2020 FOR) F250)				WORK O	RDER NO	: 52	2918	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504241 CLOSED SCHEDULED 20FORDF250		OPENE COMPL CLOSE Ford F25	ETED D DATI	DATE:	11/27/202	4 13:08:08 4 10:11:22 4 10:49:10	LOCATION METER 1 - I IN-SERVICE UNIT SERIA	M: 12072 E DATE:	M 02/20/20		Services 0
JOB CODE	1	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL COST
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$4	1.10	\$4.10
PD-00-001	PREP DI	SPOSE NEW UNIT	IN-SERVICE	DON	D	N	GARAGE	0.03	\$3.80	\$0.30	\$0	0.00	\$4.10
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL:	0.03	3	.80	0.30	4.10	8.20
Job Code		Job Descripti	<u>on</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>o.</u>		Total Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1						\$4.10
												COMML	4.10
Job Code		Job Descripti	<u>on</u>		<u>En</u>	ployee	No.	<u>Start</u>		Finish		Quantity	Total Cost
PD-00-001	PREP DISPO	OSE NEW UNIT IN-SE	RVICE INSPEC	CTION 1	1399745		11/	26/2024 14:55:30	11/26/202	24 14:57:26		0.03	\$3.80
												LABOR	3.80
Job Code		Job Descripti	<u>on</u>			Part No	<u> </u>	Des	cription	<u>.</u>	Unit Price	Quantity	Total Cost
PD-00-001	PREP DISPO	OSE NEW UNIT IN-SE	RVICE INSPEC	CTION W	/ILW747		RA	ZOR BLADES			0.15	52	\$0.30
												PARTS	0.30

The University of Alabama

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

UNIT NO: 243687 2020 FORD F250 WORK ORDER NO: 52918

Work Order Notes

(EHANNAH) prep for Sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-001 - PREP DISPOSE NEW UNIT IN-SERVICE INSPECTION

(GARAGE) Removed wordmarks. No GPS. Removed tag 0255C. 12,175 miles. Checked inside of vehicle.

Report Printed: 12/03/2024 10:18:46 By User: GLOBETTI

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Tue Dec 03 2024 10:18:46 Report User: GLOBETTI

TZ: Central Standard Time

DLL Version: 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'243687') //Q=