

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 41492

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 11/02/2021 14:28:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/02/2021 14:29:55	<b>METER 1 - M:</b> 138 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/02/2021 14:30:02	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer		<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **2.00** **120.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11901357	11/02/2021 14:29:22	11/02/2021 15:29:22	1.00	\$118.00
					<b>LABOR</b>	<b>118.00</b>

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 41492

---

**Work Order Notes**

(IFALLS) PDI

---

**Job Notes**

**66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION**

(IFALLS) AG performed pdi

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 43115

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 05/03/2022 12:16:31	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/05/2022 08:50:12	<b>METER 1 - M:</b> 987 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/05/2022 09:26:42	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer		<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.18	\$0.00	\$0.00	\$17.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.72	\$1.72

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.15** **17.18** **0.00** **1.72** **18.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$1.72
					<b>COMML</b> <b>1.72</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/03/2022 14:30:00	05/03/2022 14:38:44	0.15	\$17.18
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/03/2022 14:29:00	05/03/2022 14:29:00	0.00	\$0.00
					<b>LABOR</b>	<b>17.18</b>

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 43115

---

**Work Order Notes**

(CHANNELL) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) Vehicle has 987 miles on it. Checked fluids battery tire pressure and updated oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 45546

USING DEPT NO:	507121	OPENED DATE:	12/12/2022 14:51:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2022 11:21:15	METER 1 - M:	4126	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2022 12:35:59	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH0MGB98280	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.57	\$32.69	\$0.00	\$50.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.01	\$77.58	\$0.00	\$116.59
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.48</b>	<b>56.58</b>	<b>110.27</b>	<b>5.00</b>	<b>171.85</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	12/13/2022 08:29:46	12/13/2022 08:38:42	0.15	\$17.57
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/13/2022 08:09:56	12/13/2022 08:29:46	0.33	\$39.01
<b>LABOR</b>					<b>56.58</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.73	1	\$5.73
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.47	1	\$9.47
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	10.67	6	\$63.99
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
<b>PARTS</b>					<b>110.27</b>	

# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 45546

---

## Work Order Notes

(EHANNAH) pm- replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) replaced wipers-GC

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM changed oil and oil filter-GC checked fluids and tires and tire pressure and battery  
Miles-4,126

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 47107

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 05/18/2023 13:20:58	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/23/2023 11:16:37	<b>METER 1 - M:</b> 5105 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/24/2023 10:13:14	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer		<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.69	\$0.00	\$0.00	\$69.69
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.59** **69.69** **0.00** **5.00** **74.69**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/19/2023 09:44:11	05/19/2023 10:19:37	0.59	\$69.69
					<b>LABOR</b>	<b>69.69</b>

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 47107

---

**Work Order Notes**

(EHANNAH) pm- replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 979 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH CW

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 48757

USING DEPT NO:	507121	OPENED DATE:	10/30/2023 09:36:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2023 10:18:40	METER 1 - M:	7561	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2023 13:13:12	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.48	\$95.70	\$0.00	\$140.18
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.30	\$35.40	\$33.45	\$0.00	\$68.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.68</b>	<b>79.88</b>	<b>129.15</b>	<b>5.00</b>	<b>214.03</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	11/01/2023 07:00:00	11/01/2023 07:18:00	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/31/2023 07:22:22	10/31/2023 07:44:59	0.38	\$44.48
					<b>LABOR</b>	<b>79.88</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.59	1	\$19.59
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.47	6	\$56.79
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					<b>PARTS</b>	<b>129.15</b>

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 48757

---

**Work Order Notes**

(EHANNAH) pm- wash

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changed and fluid check fc -sh

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LISAPATE) Replaced cabin filter

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(LISAPATE) Washed FC

---

# Work Order Charge Detail

**UNIT NO:** 244079      **2021 FORD EXPLORER**

**WORK ORDER NO:** 49276

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 12/15/2023 13:11:50	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/18/2023 09:02:38	<b>METER 1 - M:</b> 7693 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/18/2023 11:52:15	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR      2021 Ford Explorer	<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.40	\$47.20	\$14.63	\$0.00	\$61.83
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.40**      **47.20**      **14.63**      **5.00**      **66.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12201267	12/15/2023 14:14:36	12/15/2023 14:38:36	0.40	\$47.20
66-17-030	PERFORM TIRE PATCH	12201267	12/15/2023 14:14:36	12/15/2023 14:14:36	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	12201267	12/15/2023 14:14:36	12/15/2023 14:14:36	0.00	\$0.00
<b>LABOR</b>						<b>47.20</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.83	1	\$6.83
66-17-030	PERFORM TIRE PATCH	58123	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	8	\$1.56
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.46	1	\$5.46
<b>PARTS</b>						<b>14.63</b>

# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 49276

---

## Work Order Notes

(EHANNAH) nail in tire

---

## Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-030 - PERFORM TIRE PATCH

(GRCOOK) Performed tire patch on UAPD unit 3874C, had small piece of metal in tire, patched tire remounted and balanced tire and inspected tire after patching, found no issues. -GC

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 12/20/2023 1:50 PM By LRUSHING

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 50141

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/18/2024 11:24:18	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/20/2024 11:14:39	<b>METER 1 - M:</b> 9387 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/20/2024 11:50:44	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer	<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.15	\$18.16	\$24.08	\$0.00	\$42.24
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.15	\$17.60	\$0.00	\$0.00	\$17.60
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.30</b>	<b>35.76</b>	<b>24.08</b>	<b>5.00</b>	<b>64.84</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/18/2024 13:26:30	03/18/2024 13:35:44	0.15	\$18.16
14-52-021	INSTALL GPS SYSTEM	11074414	03/18/2024 13:17:33	03/18/2024 13:26:30	0.15	\$17.60
<b>LABOR</b>					<b>35.76</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
<b>PARTS</b>					<b>24.08</b>	

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 50141

---

**Work Order Notes**

(EHANNAH) wipers- GPS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced the wipers per customer request. SH

**14-52-021 - INSTALL GPS SYSTEM**

(GARAGE) Installed GPS# 87U030240147. SH

**CH-SP - CHARGE Shop Supplies**

(LRUSHING) Visit Reason Changed On 3/27/2024 10:48 AM By LRUSHING

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 50368

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/01/2024 10:55:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/02/2024 07:28:07	<b>METER 1 - M:</b> 9804 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/02/2024 12:40:20	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer	<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.64	\$71.37	\$0.00	\$114.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.36** **42.64** **71.37** **5.00** **119.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/01/2024 13:05:57	04/01/2024 13:27:38	0.36	\$42.64
<b>LABOR</b>					<b>42.64</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.66	6	\$51.93
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.33	1	\$6.33
<b>PARTS</b>					<b>71.37</b>	

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 50368

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 244079      **2021 FORD EXPLORER**

**WORK ORDER NO:** 51033

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 06/05/2024 12:11:54	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/06/2024 10:52:52	<b>METER 1 - M:</b> 12294 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/06/2024 11:14:03	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR      2021 Ford Explorer	<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-22-014	REPAIR REAR AXLE BEARING	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 51033

---

## Work Order Notes

(EHANNAH) prep and schedule- RECALL rear axle bolt

---

## Job Notes

### **17-GA-005 - RECALL Scheduling and Preparation**

(EHANNAH) prep and scheduling by Denise  
(LRUSHING) Visit Reason Changed On 6/26/2024 10:59 AM By LRUSHING

### **24-12 - REPAIR AXLE - NON-DRIVEN, REAR**

### **24-22-014 - REPAIR REAR AXLE BEARING**

(EHANNAH) LL Ford came to our shop for Recall on rear axle bolt.

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 51653

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 07/31/2024 07:38:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/01/2024 16:21:44	<b>METER 1 - M:</b> 14172 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/05/2024 08:19:49	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer	<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$69.24	\$0.00	\$69.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.00 0.00 69.24 5.00 74.24

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
<b>PARTS</b>						<b>69.24</b>

# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 51653

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-RC,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure had to drop small skid pan.  
Miles, 14,450

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 51795

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/13/2024 13:02:14	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/17/2024 08:35:02	<b>METER 1 - M:</b> 14723 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/17/2024 09:18:22	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer		<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 1</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 244079 2021 FORD EXPLORER

WORK ORDER NO: 51795

---

**Work Order Notes**

(EHANNAH) tire patch for nail in tire

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(EKIMBREL) nail did not puncture tire

(LRUSHING) Visit Reason Changed On 8/17/2024 9:26 AM By LRUSHING

---

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 52842

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 11/18/2024 11:35:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/21/2024 13:30:20	<b>METER 1 - M:</b> 18706 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/21/2024 15:34:43	<b>IN-SERVICE DATE:</b> 10/29/2021
<b>TECH SPEC NO:</b> 21FORDEXPLOR 2021 Ford Explorer	<b>UNIT SERIAL NO:</b> 1FMSK7BH0MGB98280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-016	REMOVE POLICE-LIGHTS/WIRING/MISC	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 3</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 244079 2021 FORD EXPLORER

**WORK ORDER NO:** 52842

---

## Work Order Notes

(CWIGLEY) Check engine light is on. Remove police lights.

---

## Job Notes

### **25-52-016 - REMOVE POLICE-LIGHTS/WIRING/MISC ELEC**

(GARAGE) removed lights wiring ect, 2 hours labor

(EHOWELL) Visit Reason Changed On 11/21/2024 1:28 PM By EHOWELL

### **25-52-021 - REMOVE GPS SYSTEM**

(EHOWELL) GPS# 87U030240147 was removed.

### **PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(EHOWELL) CM performed prep for sale.

---



# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue Dec 03 2024 10:00:18 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '244079') //Q=