

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY WORK ORDER NO: 24201

USING DEPT NO:	200721	OPENED DATE:	08/23/2016 14:36:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/24/2016 07:57:21	METER 1 - M:	59	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/24/2016 07:57:23	IN-SERVICE DATE:	08/23/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 28.75 0.00 0.00 28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11758845	08/23/2016 14:37:40	08/23/2016 15:07:40	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 24201

Work Order Notes

(LISAPATE) NEW UNIT DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 25463

USING DEPT NO: 200721	OPENED DATE: 01/17/2017 13:09:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/20/2017 09:36:31	METER 1 - M: 473 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/20/2017 09:36:32	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$15.13	\$23.41	\$0.00	\$38.54

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.26** **15.13** **23.41** **0.00** **38.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	01/18/2017 15:12:43	01/18/2017 15:28:30	0.26	\$15.13
					LABOR	15.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	5	\$18.80
					PARTS	23.41

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 25463

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB
COOLANT -37'

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY WORK ORDER NO: 26411

USING DEPT NO:	200721	OPENED DATE:	05/23/2017 11:14:08	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2017 14:18:45	METER 1 - M:	853	METER 2 - N:	0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	05/24/2017 14:18:47	IN-SERVICE DATE:	08/23/2016		
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK2HU273205		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$18.43	\$0.00	\$36.26

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 18.43 0.00 36.26

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	05/23/2017 14:41:23	05/23/2017 14:59:59	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	5	\$13.90
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.53	1	\$4.53
					PARTS	18.43

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 26411

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS/AB
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 28250

USING DEPT NO:	200721	OPENED DATE:	11/28/2017 06:42:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/28/2017 11:46:34	METER 1 - M:	1704	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/28/2017 11:46:36	IN-SERVICE DATE:	08/23/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$20.62	\$0.00	\$38.45

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **20.62** **0.00** **38.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/28/2017 06:42:57	11/28/2017 07:01:33	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	5	\$13.90
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	1	\$2.11
					PARTS	20.62

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 28250

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH PERFORMED PM

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY WORK ORDER NO: 29281

USING DEPT NO:	200721	OPENED DATE:	04/02/2018 09:41:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/07/2018 10:45:02	METER 1 - M:	2236	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/07/2018 10:45:05	IN-SERVICE DATE:	08/23/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.75	\$0.00	\$41.58

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 23.75 0.00 41.58

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/03/2018 06:00:00	05/03/2018 06:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
					PARTS	23.75

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 29281

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY RC/SH
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY WORK ORDER NO: 30995

USING DEPT NO:	200721	OPENED DATE:	10/02/2018 08:44:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/05/2018 06:35:58	METER 1 - M:	2818	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/05/2018 06:36:00	IN-SERVICE DATE:	08/23/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$0.00	\$27.94	\$0.00	\$27.94

JOB COUNT: 1 WORK ORDER TOTAL: 0.29 0.00 27.94 0.00 27.94

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/02/2018 13:51:08	10/02/2018 14:08:17	0.29	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
					PARTS	27.94

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 30995

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 33252

USING DEPT NO: 200721	OPENED DATE: 06/26/2019 14:19:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2019 07:25:57	METER 1 - M: 4053 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/28/2019 07:25:59	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$0.00	\$27.94	\$0.00	\$27.94

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.85** **0.00** **27.94** **0.00** **27.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/27/2019 06:20:06	06/27/2019 07:11:02	0.85	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
					PARTS	27.94

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 33252

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG
Coolant -35'

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 34635

USING DEPT NO: 200721	OPENED DATE: 10/28/2019 09:00:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/30/2019 09:57:58	METER 1 - M: 4472 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/30/2019 09:58:00	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$0.00	\$23.77	\$0.00	\$23.77

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.67** **0.00** **23.77** **0.00** **23.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/28/2019 09:26:22	10/28/2019 10:06:45	0.67	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.32	1	\$4.32
					PARTS	23.77

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 34635

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 36392

USING DEPT NO: 200721	OPENED DATE: 05/12/2020 13:47:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/12/2020 15:26:28	METER 1 - M: 4837 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 05/13/2020 08:17:14	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$0.00	\$23.73	\$0.00	\$23.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.01	\$0.00	\$4.89	\$0.00	\$4.89

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.19** **0.00** **28.62** **0.00** **28.62**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/12/2020 15:00:32	05/12/2020 15:11:14	0.18	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	05/12/2020 15:11:14	05/12/2020 15:11:54	0.01	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
					PARTS	28.62

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 36392

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW,EH/AG performed PM. Coolant -34

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) JW replaced cabin filter.

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 37942

USING DEPT NO: 200721	OPENED DATE: 10/09/2020 08:59:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/09/2020 15:27:04	METER 1 - M: 5223 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/12/2020 12:15:54	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.71	\$0.00	\$0.00	\$24.71

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.21** **24.71** **0.00** **0.00** **24.71**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/09/2020 09:28:06	10/09/2020 09:40:40	0.21	\$24.71
					LABOR	24.71

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 37942

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has need driven 386 miles since last PM. Checked fluids, battery, tire pressure and updated oil change sticker. SH

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 39479

USING DEPT NO: 200721	OPENED DATE: 03/24/2021 07:22:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/24/2021 15:00:40	METER 1 - M: 6218 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/29/2021 07:31:24	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.43	\$168.81	\$30.07	\$0.00	\$198.88

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.43** **168.81** **30.07** **0.00** **198.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/24/2021 08:45:11	03/24/2021 09:15:00	0.50	\$58.64
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/24/2021 09:30:00	03/24/2021 09:41:06	0.19	\$21.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2021 08:56:38	03/24/2021 09:15:00	0.31	\$36.12
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2021 09:30:00	03/24/2021 09:56:33	0.44	\$52.22
					LABOR	168.81

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	30.07

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 39479

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 6218. SH/JW Performed PM. SH Washed vacuumed and filled with gas.

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 40170

USING DEPT NO: 200721	OPENED DATE: 06/14/2021 14:37:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/23/2021 14:02:54	METER 1 - M: 6218 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 06/23/2021 14:02:57	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-01-006	REPLACE NEW CONDENSER	DON	O	N	GARAGE	1.49	\$176.12	\$107.15	\$0.00	\$283.27
35-01	DIAGNOSE AIR CONDITIONING, HEAT, 'V	DON	O	N	GARAGE	0.72	\$85.16	\$0.00	\$0.00	\$85.16
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	0.62	\$72.77	\$5.97	\$0.00	\$78.74

JOB COUNT: 3	WORK ORDER TOTAL:	2.83	334.05	113.12	0.00	447.17
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	06/14/2021 15:08:26	06/14/2021 15:51:44	0.72	\$85.16
03-01-006	REPLACE NEW CONDENSER	11310047	06/15/2021 10:21:53	06/15/2021 10:50:49	0.48	\$56.90
03-01-006	REPLACE NEW CONDENSER	11310047	06/16/2021 14:50:11	06/16/2021 15:50:48	1.01	\$119.21
66-01-058	PERFORM EVAC AND RECHARGE FREON	11310047	06/17/2021 07:02:04	06/17/2021 07:39:04	0.62	\$72.77
					LABOR	334.04

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-01-006	REPLACE NEW CONDENSER	TYC3995	CONDENSER	107.15	1	\$107.15
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	12	\$3.42
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.01	2	\$2.01
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	4	\$0.54
					PARTS	113.12

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 40170

Work Order Notes

(CHANNELL) A/C not working

Job Notes

03-01-006 - REPLACE NEW CONDENSER

(EHOWELL) Replaced condenser assembly with drier. The AC is now blowing cold. EH

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(EHOWELL) The vehicle was low on refrigerant due to a leaking condenser. EH/IF

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Recovered .24 lb. of refrigerant. Pulled a vacuum on the system after repairs and the leak test passed. Injected 1.5 oz. of ester oil and charged vehicle to .97 lb. EH

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 40899

USING DEPT NO: 200721	OPENED DATE: 08/31/2021 12:00:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2021 15:34:26	METER 1 - M: 6500 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/31/2021 15:37:03	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.28	\$17.90	\$0.00	\$23.18
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.17	\$19.83	\$0.00	\$0.00	\$19.83
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.44	\$52.35	\$0.00	\$0.00	\$52.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.81	\$0.00	\$0.00	\$42.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.02	120.27	17.90	2.00	140.17
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2021 13:13:01	08/31/2021 13:34:47	0.36	\$42.81
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/31/2021 13:35:01	08/31/2021 13:37:42	0.04	\$5.28
66-79-003	PERFORM SAFETY INSPECTION	11074414	08/31/2021 14:46:24	08/31/2021 15:13:01	0.44	\$52.35
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/31/2021 15:14:19	08/31/2021 15:24:24	0.17	\$19.83
LABOR					1.02	120.27

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
PARTS					2	17.90

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 40899

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed safety inspection found no issues. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 6500. Vehicle has been driven 282 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 42002

USING DEPT NO: 200721	OPENED DATE: 01/06/2022 15:16:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/13/2022 11:15:07	METER 1 - M: 6740 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/14/2022 07:48:15	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$17.90	\$113.55	\$0.00	\$131.45
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.77	\$17.90	\$0.00	\$23.67
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.14	\$16.13	\$0.00	\$0.00	\$16.13
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.41	\$48.48	\$0.00	\$0.00	\$48.48
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.28	\$151.34	\$516.32	\$0.00	\$667.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.12	\$41.74	\$0.00	\$97.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 7 **WORK ORDER TOTAL:** **2.51** **295.74** **689.51** **2.00** **987.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/07/2022 09:53:41	01/07/2022 10:22:13	0.48	\$56.12
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/07/2022 10:22:36	01/07/2022 10:25:32	0.05	\$5.77
03-32-002	REPLACE NEW BATTERY	11074414	01/07/2022 10:27:29	01/07/2022 10:36:35	0.15	\$17.90
06-15	INSPECT STEERING	11074414	01/07/2022 10:36:48	01/07/2022 10:45:00	0.14	\$16.13
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	01/12/2022 08:24:25	01/12/2022 08:35:04	0.18	\$20.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	01/12/2022 09:24:28	01/12/2022 09:24:28	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	01/12/2022 09:30:00	01/12/2022 10:36:18	1.11	\$130.39
09-15	ALIGN STEERING	11310047	01/12/2022 13:50:21	01/12/2022 14:15:00	0.41	\$48.48
LABOR					2.51	295.74

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	1	\$7.59

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.25	1	\$5.25
66-PM-PMA	PERFORM OIL CHANGE	1072	BATTERY CLEANER SPRAY 13 OZ	7.43	1	\$7.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.83	1	\$4.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.35	1	\$0.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	2	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.47	1	\$0.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.81	2	\$1.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58109	WHEEL WEIGHT PFE 2.0OZ	1.19	1	\$1.19
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15494950000	GEN ALTIMAX 205/65R16	123.08	4	\$492.30
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.83	(1)	(\$4.83)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.83	4	\$19.32
					PARTS	689.51

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 42002

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Battery tested bad. Replaced battery. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering and brakes. SH

09-15 - ALIGN STEERING

(EHOWELL) Performed 4wheel Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM. Needs 4 tires they are 6 years old.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 43990

USING DEPT NO: 200721	OPENED DATE: 07/15/2022 12:35:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/22/2022 08:56:43	METER 1 - M: 7465 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/22/2022 14:34:10	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.75	\$18.33	\$0.00	\$23.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.84	\$0.00	\$0.00	\$44.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	49.59	18.33	2.00	69.92
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/15/2022 13:23:31	07/15/2022 13:25:56	0.04	\$4.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/15/2022 13:26:09	07/15/2022 13:48:57	0.38	\$44.84
LABOR					49.59	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.77	1	\$7.77
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.56	1	\$10.56
PARTS					18.33	

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 43990

Work Order Notes

(CHANNELL) pm\replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 7465 Vehicle has been 725 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 45553

USING DEPT NO: 200721	OPENED DATE: 12/13/2022 07:42:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/15/2022 12:30:54	METER 1 - M: 7921 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/15/2022 13:58:31	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$18.39	\$0.00	\$41.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$53.79	\$51.60	\$0.00	\$105.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.66	77.39	69.99	5.00	152.38
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/14/2022 12:56:29	12/14/2022 13:08:29	0.20	\$23.60
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/14/2022 12:56:29	12/14/2022 12:56:29	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/14/2022 12:56:29	12/14/2022 12:56:29	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/14/2022 12:59:44	12/14/2022 12:59:44	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/14/2022 13:00:00	12/14/2022 13:27:21	0.46	\$53.79
LABOR					77.39	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.80	1	\$7.80
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.59	1	\$10.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	13.29	1	\$13.29
PARTS					69.99	

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 45553

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: Completed PM topside, Scott was bottomside. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 47051

USING DEPT NO: 200721	OPENED DATE: 05/15/2023 09:55:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2023 15:35:10	METER 1 - M: 8113 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/18/2023 07:12:01	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.96	\$0.00	\$0.00	\$19.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.06	\$7.08	\$0.00	\$0.00	\$7.08

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.23** **27.04** **0.00** **5.00** **32.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2023 11:39:46	05/16/2023 11:49:55	0.17	\$19.96
WA-00	WASH COMPLETE VEHICLE	11074414	05/16/2023 11:50:07	05/16/2023 11:53:43	0.06	\$7.08
LABOR					27.04	

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 47051

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 192 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Wash bay was down. SH

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 48819

USING DEPT NO: 200721	OPENED DATE: 11/03/2023 07:06:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2023 11:19:24	METER 1 - M: 8418 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/07/2023 08:41:06	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.11	\$19.57	\$0.00	\$24.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.15	\$135.11	\$56.79	\$0.00	\$191.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.11	\$13.24	\$0.00	\$0.00	\$13.24

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.30** **153.46** **76.36** **5.00** **234.82**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12395904	11/03/2023 13:41:52	11/03/2023 13:44:28	0.04	\$5.11
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/03/2023 13:45:01	11/03/2023 13:49:59	0.08	\$9.77
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/03/2023 13:50:48	11/03/2023 13:50:55	0.00	\$0.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/03/2023 13:02:38	11/03/2023 14:06:15	1.06	\$125.11
WA-00	WASH COMPLETE VEHICLE	12395904	11/03/2023 14:20:21	11/03/2023 14:20:21	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	12395904	11/03/2023 14:30:00	11/03/2023 14:36:44	0.11	\$13.24
LABOR					153.46	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.79	1	\$10.79
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.29	5	\$31.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	14.57	1	\$14.57
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.30	1	\$8.30
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.27	1	\$11.27
PARTS					76.36	

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 48819

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 50549

USING DEPT NO: 200721	OPENED DATE: 04/12/2024 07:06:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/15/2024 09:47:08	METER 1 - M: 8689 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/15/2024 12:26:48	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.63	\$0.00	\$0.00	\$19.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.31	\$36.22	\$0.00	\$0.00	\$36.22

JOB COUNT: 3	WORK ORDER TOTAL:	0.47	55.85	0.00	5.00	60.85
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/12/2024 09:57:38	04/12/2024 10:07:37	0.17	\$19.63
WA-00	WASH COMPLETE VEHICLE	11074414	04/12/2024 10:28:11	04/12/2024 10:46:36	0.31	\$36.22
LABOR					55.85	

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 50549

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 271 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 52252

USING DEPT NO: 200721	OPENED DATE: 09/26/2024 07:03:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/27/2024 08:10:20	METER 1 - M: 8690 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/27/2024 08:10:23	IN-SERVICE DATE: 08/23/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.11	\$0.00	\$24.11
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$46.60	\$0.00	\$46.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	70.71	5.00	75.71
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	5	\$35.03
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.57	1	\$11.57
03-51-038	REPLACE NEW WIPER BLADES	XC18	18" WIPER	10.88	1	\$10.88
PARTS						70.71

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 52252

Work Order Notes

(EHANNAH) pm- wipers- SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wiper-CM,GC

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC
Brake pads are 9 mm front and rear
Miles,8,927

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 8,927

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas-GC

Work Order Charge Detail

UNIT NO: 242026 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 53636

USING DEPT NO:	200721	OPENED DATE:	02/05/2025 11:16:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	8933	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	08/23/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK2HU273205	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242026 2017 TOYOTA CAMRY

WORK ORDER NO: 53636

Work Order Notes

(CWIGLEY) Prep For Sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Feb 07 2025 13:51:33 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no_alt} = 'S0719C') //Q=