

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 25555

USING DEPT NO: 504103	OPENED DATE: 01/24/2017 14:39:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/25/2017 07:38:24	METER 1 - M: 122 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/25/2017 07:38:26	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150 2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	P	N	GARAGE	1.30	\$74.94	\$0.00	\$0.00	\$74.94

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.30** **74.94** **0.00** **0.00** **74.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11074414	01/25/2017 06:48:02	01/25/2017 07:36:14	0.80	\$46.19
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11074414	01/24/2017 14:41:48	01/24/2017 15:11:48	0.50	\$28.75
					LABOR	74.94

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 25555

Work Order Notes

(IFALLS) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(IFALLS) SH PERFORMED PDI

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 25889

USING DEPT NO: 504103	OPENED DATE: 03/02/2017 08:24:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/08/2017 07:16:45	METER 1 - M: 617 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/08/2017 07:16:47	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150 2017 Ford F150		UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** 0.50 28.75 0.00 0.00 28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11758845	03/02/2017 08:25:59	03/02/2017 08:55:59	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 25889

Work Order Notes

(LISAPATE) INSTALL GPS SYSTEM PROVIDED BY DEPT

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) REMOVED TRAY ON DASH, FED WIRE HARNESS DOWN TO OBDII AND ZIP TIED UNIT DOWN, INSTALLED DASH TRAY HOOKED UP OBDII AND ZIP TIED OUT THE WAY, PUT NEW OBDII PORT BACK IN FACTORY POSITION

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 27234

USING DEPT NO: 504103	OPENED DATE: 08/23/2017 09:42:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/30/2017 09:09:56	METER 1 - M: 3615 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/30/2017 09:09:58	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$12.08	\$19.44	\$0.00	\$31.52

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.21** **12.08** **19.44** **0.00** **31.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/23/2017 11:17:13	08/23/2017 14:29:57	3.21	\$184.70
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/23/2017 11:17:13	08/23/2017 14:29:57	(3.21)	(\$184.70)
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/23/2017 11:17:13	08/23/2017 11:29:49	0.21	\$12.08
					LABOR	12.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.04	1	\$5.04
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	240	\$14.40
					PARTS	19.44

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 27234

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 27938

USING DEPT NO: 504103	OPENED DATE: 10/24/2017 15:44:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/27/2017 11:19:35	METER 1 - M: 4822 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/27/2017 11:19:37	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150 2017 Ford F150		UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
CH-32-002	CHARGE BATTERY	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2 **WORK ORDER TOTAL: 1.50 86.25 0.00 0.00 86.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11268671	10/26/2017 07:00:00	10/26/2017 07:30:00	0.50	\$28.75
66-79-002	PERFORM SERVICE CALL	11268671	10/25/2017 07:00:00	10/25/2017 08:00:00	1.00	\$57.50
					LABOR	86.25

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 27938

Work Order Notes

(LISAPATE) TYLER REQUESTED A SERVICE CALL TO GROUNDS TRUCK HAS A DEAD BATTERY

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) JUMPED OFF. HAZARDS WERE LEFT ON

CH-32-002 - CHARGE BATTERY

(IFALLS) IF CHARGED BATTERY RECHECKED OK

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 28765

USING DEPT NO:	504103	OPENED DATE:	02/01/2018 09:33:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/07/2018 07:48:50	METER 1 - M:	6337	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/07/2018 07:48:52	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$30.91	\$21.83	\$0.00	\$52.74

JOB COUNT: 1 WORK ORDER TOTAL: 0.54 30.91 21.83 0.00 52.74

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/02/2018 10:17:46	02/02/2018 10:50:01	0.54	\$30.91

LABOR 30.91

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.07	240	\$16.80

PARTS 21.83

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 28765

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/AG
COOLANT -15'

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 31178

USING DEPT NO:	504103	OPENED DATE:	10/15/2018 13:04:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/23/2018 10:27:47	METER 1 - M:	10559	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/23/2018 10:27:49	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-02-023	WARRANTY HANDLES - INNER & OUTE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.48	\$0.00	\$0.00	\$0.00	\$0.00
17-02-027	RECALL SEAT FRAMES & SPRINGS	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.78	\$0.00	\$31.91	\$0.00	\$31.91

JOB COUNT: 4	WORK ORDER TOTAL:	3.26	0.00	31.91	0.00	31.91
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
17-02-027	RECALL SEAT FRAMES & SPRINGS	11078175	W32492	0045539	\$0.00	
					COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/16/2018 06:04:23	10/16/2018 07:25:11	1.35	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/16/2018 06:44:32	10/16/2018 07:10:17	0.43	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	11915538	10/19/2018 14:30:03	10/19/2018 15:59:04	1.48	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.36	8	\$26.88
					PARTS	31.91

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 31178

Work Order Notes

(LISAPATE) PM-Take to Ford for recall on Driver seat frame 17C08 and RR outside door handle inop

Job Notes

15-02-023 - WARRANTY HANDLES - INNER & OUTER

(LISAPATE) Ford completed warranty repair to RR door that would not open from the inside. Replaced latch and rod assy.

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Ford by RC

17-02-027 - RECALL SEAT FRAMES & SPRINGS

(LISAPATE) Ford completed recall for driver seat backrest frame inspection and replacement

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 31638

USING DEPT NO: 504103	OPENED DATE: 12/04/2018 09:01:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/14/2018 07:19:24	METER 1 - M: 10559 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/14/2018 07:19:26	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.42	\$0.00	\$98.33	\$0.00	\$98.33
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
17-02-055	RECALL DOOR LATCH/STRIKER	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.42	0.00	98.33	0.00	98.33
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-02-055	RECALL DOOR LATCH/STRIKER	11078175	W35114	0046231	\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11915538	12/12/2018 07:00:00	12/12/2018 08:00:00	1.00	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	12/12/2018 07:11:01	12/12/2018 07:36:02	0.42	\$0.00
LABOR					0.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.30	1	\$0.30
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.22	1	\$0.22
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	97.81	1	\$97.81
PARTS					98.33	

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 31638

Work Order Notes

(LISAPATE) Take to Ford for recall 18N03 door latches may freeze.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Truck was dead this morning. Replaced battery. Checked charging at 14.2 volts

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Ford by RC

17-02-055 - RECALL DOOR LATCH/STRIKER

(LISAPATE) Letter was extended coverage not a recall. No repair was done by the dealer. A copy of the letter from Ford was put in glovebox of truck

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 32587

USING DEPT NO:	504103	OPENED DATE:	04/11/2019 07:16:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/17/2019 06:23:17	METER 1 - M:	13323	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2019 06:23:19	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$0.00	\$17.06	\$0.00	\$17.06
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$0.00	\$328.69	\$0.00	\$328.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$54.64	\$0.00	\$54.64

JOB COUNT: 5	WORK ORDER TOTAL:	2.46	0.00	400.39	0.00	400.39
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11268671	04/12/2019 07:00:00	04/12/2019 08:00:00	1.00	\$0.00
06-15	INSPECT STEERING	11901357	04/12/2019 07:00:00	04/12/2019 07:30:00	0.50	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	04/12/2019 08:17:09	04/12/2019 09:15:00	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	04/12/2019 08:17:09	04/12/2019 09:15:00	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	04/12/2019 09:30:00	04/12/2019 09:43:04	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	04/12/2019 08:17:09	04/12/2019 08:41:09	0.40	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/11/2019 14:02:55	04/11/2019 14:15:00	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/11/2019 14:30:00	04/11/2019 14:48:59	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/11/2019 14:30:00	04/11/2019 14:48:59	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/11/2019 11:07:16	04/11/2019 11:51:14	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/11/2019 14:30:00	04/11/2019 14:48:36	0.31	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/12/2019 06:05:41	04/12/2019 06:14:07	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/12/2019 06:05:41	04/12/2019 06:14:07	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/12/2019 06:05:41	04/12/2019 06:20:41	0.25	\$0.00

LABOR 0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	19.20	1	\$19.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	8	\$23.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.54	2	\$5.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	5	\$1.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	16814	TIRE LT245/70R17 MICH DEF LTX	161.13	2	\$322.26
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	6.65	1	\$6.65
					PARTS	400.39

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 32587

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

06-15 - INSPECT STEERING

(LISAPATE) Front end checked no issued found by AG/SH

09-15 - ALIGN STEERING

(LISAPATE) IF Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 2 new front tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Replaced air filter

Coolant -35'

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 34270

USING DEPT NO: 504103	OPENED DATE: 09/30/2019 07:31:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/30/2019 13:38:11	METER 1 - M: 15467 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/30/2019 13:38:12	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$0.00	\$28.63	\$0.00	\$28.63

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.86** **0.00** **28.63** **0.00** **28.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/30/2019 08:07:00	09/30/2019 08:58:33	0.86	\$0.00

LABOR **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	8	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03

PARTS **28.63**

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 34270

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/AG
Coolant -34'

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 34891

USING DEPT NO: 504103	OPENED DATE: 11/15/2019 13:12:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/18/2019 10:57:54	METER 1 - M: 16173 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/18/2019 10:57:55	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	1.03	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.03** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	12052187	11/15/2019 13:27:29	11/15/2019 14:29:00	1.03	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 34891

Work Order Notes

(EKIMBREL) Remove 3G, install 4G GpS

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(LISAPATE) Removed GPS Serial # 5015140826
new serial#5041372093

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 36338

USING DEPT NO:	504103	OPENED DATE:	05/07/2020 08:48:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2020 08:46:40	METER 1 - M:	18449	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2020 10:46:21	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.58	\$0.00	\$255.94	\$0.00	\$255.94
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	P	N	GARAGE	0.12	\$0.00	\$0.55	\$0.00	\$0.55
09-15	ALIGN STEERING	DON	P	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.72	\$0.00	\$35.28	\$0.00	\$35.28

JOB COUNT: 4	WORK ORDER TOTAL:	2.41	0.00	291.77	0.00	291.77
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11213180	05/07/2020 12:56:15	05/07/2020 12:56:15	0.00	\$0.00
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11213180	05/07/2020 13:00:00	05/07/2020 13:34:32	0.58	\$0.00
09-15	ALIGN STEERING	11213180	05/08/2020 07:00:00	05/08/2020 08:00:00	1.00	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11901357	05/07/2020 10:25:31	05/07/2020 10:32:39	0.12	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/07/2020 09:42:19	05/07/2020 10:25:31	0.72	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	04507210000	TIRE LT245/70R17 GEN GRB HD	124.87	2	\$249.74
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.55	1	\$0.55
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	6.65	1	\$6.65
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	8	\$23.60
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	4	\$1.08
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	23131	TPMS SNAP IN VALVE 21060	2.56	2	\$5.12

PARTS 291.77

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 36338

Work Order Notes

(EKIMBREL) PM; RR brake light out; FR tire has a screw in it.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(EKIMBREL) MS replaced back 2 tires.

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(EKIMBREL) AG replaced RR brake light bulb. Checked good.

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

09-15 - ALIGN STEERING

(IFALLS) MS performed alignment

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/JW performed pm. Coolant -35

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 37994

USING DEPT NO:	504103	OPENED DATE:	10/14/2020 08:21:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2020 09:59:21	METER 1 - M:	19496	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/14/2020 13:00:24	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.18	\$0.00	\$0.00	\$50.18

JOB COUNT: 1	WORK ORDER TOTAL:	0.43	50.18	0.00	0.00	50.18
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/14/2020 08:35:14	10/14/2020 09:00:45	0.43	\$50.18
					LABOR	50.18

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 37994

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Vehicle has been 1047 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. AMG

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 39485

USING DEPT NO: 504103	OPENED DATE: 03/24/2021 13:31:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/26/2021 11:26:00	METER 1 - M: 21878 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/30/2021 07:57:52	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.07	\$8.56	\$0.68	\$0.00	\$9.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.04	\$122.49	\$39.98	\$0.00	\$162.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.12	\$14.65	\$37.46	\$0.00	\$52.11

JOB COUNT: 3	WORK ORDER TOTAL:	1.23	145.70	78.12	0.00	223.82
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/25/2021 07:32:29	03/25/2021 07:36:07	0.06	\$7.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	03/25/2021 07:07:53	03/25/2021 07:15:20	0.12	\$14.65
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	03/25/2021 07:07:56	03/25/2021 07:12:17	0.07	\$8.56
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/24/2021 14:48:12	03/24/2021 15:46:51	0.98	\$115.35
					LABOR	145.71

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	37.46	1	\$37.46
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	912	BULB-BRAKE-3RD	0.68	1	\$0.68
					PARTS	78.12

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 39485

Work Order Notes

(LISAPATE) PM

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(SHARBIN) Third brake light was inop replaced the third brake light bulb rechecks good. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 21878 Completed PM top and bottom side. Josh assisted topside. AMG JW/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 40559

USING DEPT NO:	504103	OPENED DATE:	07/28/2021 09:01:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/29/2021 11:32:29	METER 1 - M:	23977	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	07/29/2021 12:20:49	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.61	\$72.14	\$314.12	\$0.00	\$386.26

JOB COUNT: 1	WORK ORDER TOTAL:					0.61	72.14	314.12	0.00	386.26
---------------------	--------------------------	--	--	--	--	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	11170580	07/28/2021 09:30:00	07/28/2021 10:06:41	0.61	\$72.14
03-02-010	REPLACE NEW MIRRORS	11170580	07/28/2021 09:17:52	07/28/2021 09:17:52	0.00	\$0.00
					LABOR	72.14

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	FD267L/R	MIRRORS	284.12	1	\$284.12
03-02-010	REPLACE NEW MIRRORS	SHIPPING	SHIPPING AND HANDLING	30.00	1	\$30.00
					PARTS	314.12

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 40559

Work Order Notes

(EHOWELL) Replace both outside mirrors

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(ABLACK) AB installed both new right and left side exterior mirror assemblies.

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 40767

USING DEPT NO:	504103	OPENED DATE:	08/18/2021 07:12:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2021 10:24:57	METER 1 - M:	24240	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2021 10:55:46	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.51	\$15.18	\$0.00	\$18.69
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.27	\$32.09	\$0.00	\$0.00	\$32.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.31	\$41.24	\$0.00	\$58.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.45	52.91	56.42	2.00	111.33
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/18/2021 11:30:00	08/18/2021 11:46:19	0.27	\$32.09
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/18/2021 09:52:58	08/18/2021 09:59:09	0.10	\$12.16
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/18/2021 09:51:02	08/18/2021 09:52:49	0.03	\$3.51
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/18/2021 10:27:22	08/18/2021 10:29:31	0.04	\$4.23
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/18/2021 10:30:30	08/18/2021 10:30:58	0.01	\$0.92
LABOR					52.91	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
PARTS					56.42	

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 40767

Work Order Notes

(CHANSELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH AB Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG
MILEAGE-24240

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 41474

USING DEPT NO:	504103	OPENED DATE:	11/01/2021 10:12:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 07:35:56	METER 1 - M:	25348	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2021 07:36:00	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.79	\$93.65	\$146.72	\$0.00	\$240.37
06-31-001	INSPECT ALTERNATOR	DON	O	N	GARAGE	2.34	\$276.64	\$0.00	\$0.00	\$276.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	3.14	370.29	146.72	2.00	519.01
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11170580	11/01/2021 15:08:03	11/01/2021 15:55:40	0.79	\$93.65
06-31-001	INSPECT ALTERNATOR	11170580	11/01/2021 13:00:00	11/01/2021 13:59:15	0.99	\$116.53
06-31-001	INSPECT ALTERNATOR	11170580	11/01/2021 10:38:35	11/01/2021 12:00:00	1.36	\$160.12
LABOR					370.30	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	146.72	1	\$146.72
PARTS					146.72	

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 41474

Work Order Notes

(IFALLS) Truck will not start after shut off, Lukas Sullavan

Job Notes

03-32-002 - REPLACE NEW BATTERY

(ABLACK) AB installed a new battery

06-31-001 - INSPECT ALTERNATOR

(ABLACK) AB inspected alternator and was charging ok. Found battery was bad. Needs a new battery

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 41948

USING DEPT NO: 504103	OPENED DATE: 12/22/2021 08:02:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/06/2022 09:47:37	METER 1 - M: 26060 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/06/2022 10:46:28	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.18	\$0.00	\$32.88
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,962.73	\$2,962.73
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.76	\$0.00	\$0.00	\$47.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.05	124.46	15.18	2,964.73	3,104.37
---------------------	--------------------------	-------------	---------------	--------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	16906728		\$2,962.73
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2964.73

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/22/2021 12:18:50	12/22/2021 12:43:07	0.40	\$47.76
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/06/2022 07:00:00	01/06/2022 07:09:00	0.15	\$17.70
16-71	TRANSPORT BODY	11915538	01/06/2022 07:00:00	01/06/2022 07:30:00	0.50	\$59.00
LABOR					124.46	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
PARTS					15.18	

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 41948

Work Order Notes

(LISAPATE) PM-replace wipers-Take to the Body shop to rear end

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by RC

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage to the rear end per the estimate. PD by Cc

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1498 miles since last pm. Updated pm sticker. Checked all fluids and tires. Coolant -34°. JAW
MILEAGE-26238

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 43595

USING DEPT NO: 504103	OPENED DATE: 06/10/2022 07:50:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/10/2022 14:29:59	METER 1 - M: 28541 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/13/2022 08:41:49	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.92	\$15.57	\$0.00	\$16.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.03	\$121.02	\$57.77	\$0.00	\$178.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.03	121.94	73.34	2.00	197.28
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/10/2022 10:01:09	06/10/2022 10:40:54	0.66	\$78.18
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/10/2022 10:35:37	06/10/2022 10:36:05	0.01	\$0.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/10/2022 10:13:39	06/10/2022 10:35:26	0.36	\$42.84
LABOR					1.03	121.94

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.79	2	\$15.57
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.21	1	\$11.21
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	8	\$46.56
PARTS					73.34	73.34

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 43595

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) JW Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 45113

USING DEPT NO:	504103	OPENED DATE:	10/28/2022 14:36:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2022 08:08:56	METER 1 - M:	30074	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/14/2022 07:26:06	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.87	\$15.63	\$0.00	\$21.50
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.01	\$119.34	\$0.00	\$0.00	\$119.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$74.24	\$24.30	\$0.00	\$98.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$29.52	\$0.00	\$64.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.99	234.85	69.45	5.00	309.30
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/10/2022 07:00:00	11/10/2022 07:18:00	0.30	\$35.40
66-79-003	PERFORM SAFETY INSPECTION	11901357	10/31/2022 13:06:21	10/31/2022 13:32:02	0.43	\$50.51
66-79-003	PERFORM SAFETY INSPECTION	11901357	10/31/2022 07:45:47	10/31/2022 08:20:47	0.58	\$68.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/31/2022 07:05:27	10/31/2022 07:25:16	0.33	\$38.97
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11901357	10/28/2022 15:36:25	10/28/2022 15:43:24	(0.12)	(\$13.73)
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11901357	10/28/2022 15:36:25	10/28/2022 15:43:24	0.12	\$13.73
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/28/2022 15:17:55	10/28/2022 15:35:51	0.30	\$35.27
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/28/2022 15:14:37	10/28/2022 15:17:36	0.05	\$5.87
					LABOR	234.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	29.52	1	\$29.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	29.52	(1)	(\$29.52)
66-PM-PMA	PERFORM OIL CHANGE	FP92	CABIN FILTER	29.52	(1)	(\$29.52)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	29.52	1	\$29.52

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FP92	CABIN FILTER	29.52	1	\$29.52
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	24.30	1	\$24.30
					PARTS	69.45

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 45113

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual safety inspection, brakes are squeaking

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

66-79-003 - PERFORM SAFETY INSPECTION

(IFALLS) Completed safety inspection and safety inspection check sheet. No issues found, front and rear brake pads and rotors were good. Front pads were at 8mm, rear at 7mm. Test drove vehicle, all good. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 30074 Vehicle has been 1533 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 46552

USING DEPT NO: 504103	OPENED DATE: 03/29/2023 08:17:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/03/2023 10:53:00	METER 1 - M: 31770 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2023 13:58:54	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.34	\$40.05	\$0.00	\$0.00	\$40.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$13.57	\$0.00	\$0.00	\$13.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.35	\$41.27	\$0.00	\$0.00	\$41.27

JOB COUNT: 4	WORK ORDER TOTAL:	0.80	94.89	0.00	5.00	99.89
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	03/29/2023 09:20:34	03/29/2023 09:20:34	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	11074414	03/29/2023 09:30:00	03/29/2023 09:50:59	0.35	\$41.27
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/29/2023 08:54:38	03/29/2023 09:15:00	0.34	\$40.05
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/29/2023 08:42:35	03/29/2023 08:49:29	0.12	\$13.57
					LABOR	94.89

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 46552

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires relearned tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, filters good
Miles, 31,770

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 48121

USING DEPT NO: 504103	OPENED DATE: 09/08/2023 07:17:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2023 11:09:15	METER 1 - M: 33857 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/11/2023 10:45:49	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.28	\$16.65	\$0.00	\$21.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.98	\$63.80	\$0.00	\$82.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.09	\$10.16	\$0.00	\$0.00	\$10.16

JOB COUNT: 4	WORK ORDER TOTAL:	0.29	34.42	80.45	5.00	119.87
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	09/08/2023 07:48:58	09/08/2023 07:54:08	0.09	\$10.16
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/08/2023 07:46:07	09/08/2023 07:48:48	0.04	\$5.28
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2023 07:36:17	09/08/2023 07:45:56	0.16	\$18.98
					LABOR	34.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	8	\$50.28
					PARTS	80.45

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 48121

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Wash bay is closed. SH

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 49446

USING DEPT NO: 504103	OPENED DATE: 01/11/2024 08:43:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/17/2024 09:35:10	METER 1 - M: 35497 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/17/2024 14:39:10	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-42-006	REPLACE NEW THERMOSTATS	DON	N	N	GARAGE	1.42	\$167.69	\$58.50	\$0.00	\$226.19
03-42-045	REPLACE NEW COOLANT RESERVOIR	DON	N	N	GARAGE	0.04	\$4.20	\$14.97	\$0.00	\$19.17
06-42	INSPECT COOLING SYSTEM	DON	N	N	GARAGE	0.37	\$43.40	\$0.00	\$0.00	\$43.40
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.37	\$43.73	\$0.00	\$0.00	\$43.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.20	259.02	73.47	5.00	337.49
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-42	INSPECT COOLING SYSTEM	12052187	01/11/2024 09:30:00	01/11/2024 09:48:13	0.30	\$35.83
06-42	INSPECT COOLING SYSTEM	12052187	01/11/2024 09:11:09	01/11/2024 09:15:00	0.06	\$7.57
66-79-002	PERFORM SERVICE CALL	12052187	01/11/2024 08:48:55	01/11/2024 09:11:09	0.37	\$43.73
03-42-045	REPLACE NEW COOLANT RESERVOIR CAP	12052187	01/12/2024 10:10:35	01/12/2024 10:12:43	0.04	\$4.20
03-42-006	REPLACE NEW THERMOSTATS	12052187	01/12/2024 09:30:00	01/12/2024 10:10:22	0.67	\$79.39
03-42-006	REPLACE NEW THERMOSTATS	12052187	01/12/2024 09:18:29	01/12/2024 09:18:29	0.00	\$0.00
03-42-006	REPLACE NEW THERMOSTATS	12052187	01/12/2024 07:07:06	01/12/2024 07:52:00	0.75	\$88.30
					LABOR	259.02

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-42-006	REPLACE NEW THERMOSTATS	FEL35991	THERMOSTAT GASKET	14.09	1	\$14.09
03-42-045	REPLACE NEW COOLANT RESERVOIR CAP	FCTT57	COOLANT RESERVOIR CAP	14.97	1	\$14.97
03-42-006	REPLACE NEW THERMOSTATS	FCT655188	THERMOSTAT	23.69	1	\$23.69
03-42-006	REPLACE NEW THERMOSTATS	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	20.72	1	\$20.72
					PARTS	73.47

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 49446

Work Order Notes

(EHANNAH) service call for inspect cooling system

Job Notes

03-42-006 - REPLACE NEW THERMOSTATS

(JWRIGHT) Replaced thermostat and gasket. Filled with coolant and test drove. No issues. JAW

03-42-045 - REPLACE NEW COOLANT RESERVOIR CAP

(GARAGE) Replaced reservoir cap. JAW

06-42 - INSPECT COOLING SYSTEM

(GARAGE) Inspected cooling system. Pressured to 21psi and found no leaks anywhere. The cap seems to be worn on the threads and it is also likely the thermostat was stuck while cold and caused the unit to overheat. Suggest replacing thermostat and cap. JAW

66-79-002 - PERFORM SERVICE CALL

(GARAGE) Went on service call and topped of coolant with 1/2 gallon. Ran truck a few minutes and found no leaks or any issues. drove back to the shop for further inspection. JAW/FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 49728

USING DEPT NO:	504103	OPENED DATE:	02/07/2024 08:22:51	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2024 10:24:53	METER 1 - M:	36037	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2024 13:57:37	IN-SERVICE DATE:	01/24/2017		
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	N	N	GARAGE	0.27	\$32.32	\$41.27	\$0.00	\$73.59
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.35	\$41.82	\$0.00	\$0.00	\$41.82
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.49	\$58.12	\$0.00	\$0.00	\$58.12
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.19	\$140.19	\$809.55	\$0.00	\$949.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$72.54	\$58.76	\$0.00	\$131.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.28	\$32.48	\$0.00	\$0.00	\$32.48

JOB COUNT: 7 WORK ORDER TOTAL: 3.20 377.47 909.58 5.00 1,292.05

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	11310047	02/12/2024 14:26:53	02/12/2024 14:43:19	0.27	\$32.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/09/2024 13:03:43	02/09/2024 14:15:00	1.19	\$140.19
06-15	INSPECT STEERING	11074414	02/07/2024 13:16:14	02/07/2024 13:37:30	0.35	\$41.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/07/2024 11:04:23	02/07/2024 11:41:16	0.61	\$72.54
66-17-013	PERFORM ALIGNMENT	11310047	02/12/2024 09:44:08	02/12/2024 10:13:41	0.49	\$58.12
WA-00	WASH COMPLETE VEHICLE	12395904	02/12/2024 14:52:09	02/12/2024 15:08:40	0.28	\$32.48
					LABOR	377.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	8	\$45.24
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	4	\$14.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.95	2	\$1.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.10	2	\$2.19
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	CTL4060640	BELT	41.27	1	\$41.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002767	TIRE LT245/70R17 FS TRANSFRC	196.94	4	\$787.74
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002767	TIRE LT245/70R17 FS TRANSFRC	196.94	(4)	(\$787.74)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002767	TIRE LT245/70R17 FS TRANSFRC	196.94	4	\$787.74
					PARTS	909.58

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 49728

Work Order Notes

(EHANNAH) pm-wipers- wash

Job Notes

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(EHOWELL) The belt was making noise. Removed serpentine belt for alternator and water pump. Cleaned remains out of crankshaft pulley. Installed a new belt. The noise is no longer present. EH

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering. Found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Checked alignment and it was within specification. Did not make any adjustments. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) Visit Reason Changed On 2/9/2024 12:51 PM By EKIMBREL

(GARAGE) Mounted and balanced 4 tires and relearned tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. Needs 4 tires due to shoulder wear. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Was fc

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 51862

USING DEPT NO:	504103	OPENED DATE:	08/19/2024 07:46:20	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2024 10:20:34	METER 1 - M:	38433	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/21/2024 11:10:40	IN-SERVICE DATE:	01/24/2017		
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$22.50	\$0.00	\$22.50
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$66.84	\$0.00	\$66.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	89.34	5.00	94.34
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	2	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	7.64	8	\$61.08
					PARTS	89.34

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 51862

Work Order Notes

(EHANNAH) pm- wipers- wash- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) REPLACED WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SAFETY INSPECTION CHECKED OK,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PREFORMED PM CM CHANGED MOTOR OIL AND FILTER, CHECKED ALL FLUIDS, TIRES CHECKED OK,

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) WASHED VEHICLE

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 52490

USING DEPT NO: 504103	OPENED DATE: 10/16/2024 07:31:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/16/2024 14:33:44	METER 1 - M: 38997 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2024 08:26:56	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	N	N	GARAGE	0.00	\$0.00	\$114.39	\$0.00	\$114.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **114.39** **5.00** **119.39**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	FL3Z13404ACP	TAIL LAMP ASSY RH	114.39	1	\$114.39
PARTS						114.39

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 52490

Work Order Notes

(EHANNAH) taillight was broken- a report was done - please replace.

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

(GARAGE) replaced right rear tail light assembly-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 53179

USING DEPT NO:	504103	OPENED DATE:	12/17/2024 13:49:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2024 14:51:24	METER 1 - M:	39862	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2024 07:27:10	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF4HFA88635	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$225.51	\$0.00	\$225.51
03-35-007	REPLACE NEW MULTI-FUNCTION SWIT	DON	N	N	GARAGE	0.00	\$0.00	\$77.69	\$0.00	\$77.69
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-51-039	INSPECT WIPER MOTOR	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	303.20	5.00	308.20
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	225.51	1	\$225.51
03-35-007	REPLACE NEW MULTI-FUNCTION SWITCH	STICBS2293	MULTI-FUNCTION SWITCH	77.69	1	\$77.69
PARTS					303.20	

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 53179

Work Order Notes

(EHANNAH) check battery keeps going dead and needing jumped off- wipers came and off by itself.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) REMOVED BATTERY AND INSTALLED NEW BATTERY. FOUND TO CHECK OK RETURNED TO SERVICE. CQ

03-35-007 - REPLACE NEW MULTI-FUNCTION SWITCH

(EKIMBREL) INSPECTED WIPERS FOR NOT CUTTING OFF PER FORD DIAGNOSTICS AND TROUBLESHOOTING. FOUND MULTI FUNCTION SWITCH WAS FAULTY. ORDERED SWITCH, REMOVED OLD SWITH AND INSTALLED NEW SWITCH FOUND TO OPERATE CORRECTY. RETURNED UNIT TO SERVICE. HR 0.8 CQ.

06-32-002 - INSPECT BATTERY

(GARAGE) PULLED TRUCK IN SHOP AND REMOVED BATTERY CABLES, TESTED BATTERY AND BATTERY FAILED TEST. REMOVED BATTERY AND ORDERED NEW BATTERY, INSTALLED BATTERY AND FOUND TO CHECK OK. RETURNED TO SERVICE. CQ

06-51-039 - INSPECT WIPER MOTOR

(GARAGE) INSPECTED WIPERS FOR NOT CUTTING OFF PER FORD DIAGNOSTICS AND TROUBLESHOOTING. FOUND MULTI FUNCTION SWITH WAS FAULTY. ORDERE SWITCH, REMOVED OLD SWITH AND INSTALLED NEW SWITCH FOUND TO OPERATE CORRECTY. RETURNED UNIT TO SERVICE. HR 0.8 CQ.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 53583

USING DEPT NO: 504103	OPENED DATE: 02/03/2025 09:49:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/04/2025 10:43:29	METER 1 - M: 40753 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/04/2025 12:28:05	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150	2017 Ford F150	UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$85.04	\$0.00	\$85.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.00 0.00 85.04 5.00 90.04

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	9.09	8	\$72.72
PARTS						85.04

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 53583

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, fille up washer fluid
40753 miles

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 53652

USING DEPT NO: 504103	OPENED DATE: 02/06/2025 10:17:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/10/2025 08:30:43	METER 1 - M: 40753 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/10/2025 10:09:27	IN-SERVICE DATE: 01/24/2017
TECH SPEC NO: 17FORDF150 2017 Ford F150		UNIT SERIAL NO: 1FTEW1CF4HFA88635

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242192 2017 FORD F150

WORK ORDER NO: 53652

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) removed GPS#87u030640078 RC
(EHOWELL) Visit Reason Changed On 2/10/2025 9:55 AM By EHOWELL

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag RC
millage 40787

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Sat Feb 15 2025 11:30:33 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242192') //Q=