

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 25554

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 01/24/2017 14:35:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/07/2017 10:39:02	<b>METER 1 - M:</b> 145 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/07/2017 10:39:03	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-02-016	WARRANTY TAIL&LIFT GATE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-00-001	PERFORM NEW UNIT IN-SERVICE INSF	DON	C	N	GARAGE	0.50	\$28.81	\$0.00	\$0.00	\$28.81

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.50</b>	<b>86.31</b>	<b>0.00</b>	<b>0.00</b>	<b>86.31</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-02-016	WARRANTY TAIL&LIFT GATE	11078175	38656	0037273	\$0.00
<b>COMML</b>					<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11213180	01/24/2017 14:38:13	01/24/2017 15:08:13	0.50	\$28.75
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11213180	01/24/2017 14:38:13	01/24/2017 15:08:13	(0.50)	(\$28.75)
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11213180	01/24/2017 14:38:13	01/24/2017 15:08:13	0.50	\$28.75
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11213180	02/03/2017 14:09:28	02/03/2017 14:09:32	0.00	\$0.06
16-02	TRANSPORT CAB & SHEET METAL	10208562	02/06/2017 07:00:00	02/06/2017 08:00:00	1.00	\$57.50
<b>LABOR</b>					<b>86.31</b>	

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 25554

---

## Work Order Notes

(IFALLS) PDI

---

## Job Notes

### **15-02-016 - WARRANTY TAIL&LIFT GATE**

(RWINTERS) TOOK TRUCK TO TOWNSEND FORD DUE TO TAILGATE IS NOT CLOSING PROPERLY. THEY INSPECTED STATED DUE TO BEDLINER WAS APPLIED TO THICK AND OVERLAPPING . NOTHING WAS DONE. PICKED TRUCK UP. RETURNED TO PURCHASING DEALER (Stivers)THEY CORRECTED TAILGATE ISSUE.

### **16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) TAKEN TO FORD BY EK

### **66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION**

(IFALLS) MS PERFORMED PDI. SENDING TO TOWNSEND FORD TO HAVE THE TAILGATE READJUSTED  
(LISAPATE) Visit Reason Changed On 1/25/2017 1:29 PM By LISAPATE

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 25890

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 03/02/2017 08:29:04	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/08/2017 07:18:57	<b>METER 1 - M:</b> 798 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/08/2017 07:18:59	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150 2017 Ford F150		<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.50</b>	<b>28.75</b>	<b>0.00</b>	<b>0.00</b>	<b>28.75</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11758845	03/02/2017 08:29:54	03/02/2017 08:59:54	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 25890

---

**Work Order Notes**

(LISAPATE) INSTALL GPS SYSTEM PROVIDED BY DEPT

---

**Job Notes**

**14-52-021 - INSTALL GPS SYSTEM**

(LISAPATE) INSTALLED GPS SYSTEM UNDER TRAY ON DASHBOARD. RAN WIRE HARNESS DOWN TO OBDII UNDER KICK PANEL. HOOKED CONNECTORS UP AND MOUNTED NEW OBDII PORT IN SAME LOCATION AS OLD OBDII.

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 28014

USING DEPT NO:	504103	OPENED DATE:	11/02/2017 08:21:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/03/2017 11:07:41	METER 1 - M:	21799	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/03/2017 11:07:45	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$22.92	\$19.79	\$0.00	\$42.71

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.40</b>	<b>22.92</b>	<b>19.79</b>	<b>0.00</b>	<b>42.71</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2017 11:49:36	11/02/2017 11:54:55	0.09	\$5.10
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2017 11:52:56	11/02/2017 12:11:32	0.31	\$17.83
					<b>LABOR</b>	<b>22.93</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	246	\$14.76
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					<b>PARTS</b>	<b>19.79</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 28014

---

**Work Order Notes**

(IFALLS) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS) SH PERFORMED PM

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 30867

USING DEPT NO:	504103	OPENED DATE:	09/18/2018 13:28:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2018 06:26:46	METER 1 - M:	6151	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2018 06:26:48	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$35.88	\$0.00	\$35.88

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.31 0.00 35.88 0.00 35.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/18/2018 14:08:36	09/18/2018 14:27:01	0.31	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.33	8	\$26.64
					<b>PARTS</b>	<b>35.88</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 30867

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by EK/AG  
Coolant -15'

---



# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 33119

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 06/11/2019 08:55:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/14/2019 08:41:35	<b>METER 1 - M:</b> 8698 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/14/2019 08:41:36	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-058	REPAIR DOOR LOCK	DON	O	N	GARAGE	0.30	\$0.00	\$5.47	\$0.00	\$5.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$0.00	\$28.63	\$0.00	\$28.63

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.83** **0.00** **34.10** **0.00** **34.10**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-058	REPAIR DOOR LOCK	10321076	06/12/2019 07:00:00	06/12/2019 07:18:00	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/11/2019 14:31:11	06/11/2019 15:02:52	0.53	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-058	REPAIR DOOR LOCK	75399	DOOR LOCK PULL KNOB ASST	5.47	1	\$5.47
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	8	\$23.60
					<b>PARTS</b>	<b>34.10</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 33119

---

**Work Order Notes**

(LISAPATE) PM-RR door lock knob is stripped out wont lock and unlock anymore

---

**Job Notes**

**24-02-058 - REPAIR DOOR LOCK**

(LISAPATE) Replaced door lock pull knob. Rechecked ok

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by EK/AG  
Coolant -35'

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 34886

USING DEPT NO:	504103	OPENED DATE:	11/15/2019 09:48:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2019 10:58:54	METER 1 - M:	9386	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/18/2019 10:58:54	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.05	\$0.00	\$0.49	\$0.00	\$0.49
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.05	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.11 0.00 0.49 0.00 0.49

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	10208562	11/15/2019 10:21:57	11/15/2019 10:25:13	0.05	\$0.00
03-52-021	REPLACE NEW GPS SYSTEM	11268671	11/15/2019 10:22:15	11/15/2019 10:25:31	0.05	\$0.00
					<b>LABOR</b>	<b>0.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49
					<b>PARTS</b>	<b>0.49</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 34886

---

**Work Order Notes**

(LISAPATE) RR brake light out-Remove 3G install 4G GPS system

---

**Job Notes**

**03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LISAPATE) Replaced RR brake light bulb

**03-52-021 - REPLACE NEW GPS SYSTEM**

(LISAPATE) Removed GPS Serial # 5015144473

Installed Serial # 5041372086

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 36271

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 04/30/2020 09:45:50	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/30/2020 13:24:43	<b>METER 1 - M:</b> 11590 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/01/2020 07:47:23	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$0.00	\$17.06	\$0.00	\$17.06
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$0.00	\$62.07	\$0.00	\$62.07

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.46</b>	<b>0.00</b>	<b>79.13</b>	<b>0.00</b>	<b>79.13</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	04/30/2020 13:23:33	04/30/2020 13:53:33	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/30/2020 10:45:12	04/30/2020 11:38:18	0.89	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/30/2020 10:41:26	04/30/2020 10:45:12	0.06	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/30/2020 10:40:42	04/30/2020 10:41:26	0.01	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.89	8	\$31.12
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	6.65	1	\$6.65
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	19.27	1	\$19.27
					<b>PARTS</b>	<b>79.13</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 36271

---

**Work Order Notes**

(IFALLS) PM  
(IFALLS) Replace wiper blades  
Rotate tires

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(IFALLS) AG installed 2 new wiper blades

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(IFALLS) SH/AG rotated tires

**66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS) AG/JW performed pm

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 37777

USING DEPT NO:	504103	OPENED DATE:	09/28/2020 07:28:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2020 09:38:40	METER 1 - M:	12051	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2020 09:56:59	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.11 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/28/2020 08:38:05	09/28/2020 08:44:31	0.11	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 37777

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has been 461 miles since last pm. Updated sticker. Checked all fluids and tires. Found no issues. Coolant -34° JAW

---



# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 39192

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 02/24/2021 09:45:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/25/2021 07:41:03	<b>METER 1 - M:</b> 13216 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/25/2021 13:35:51	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.70	\$45.30	\$0.00	\$65.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.11	\$12.82	\$13.53	\$0.00	\$26.35

**JOB COUNT: 2** **WORK ORDER TOTAL: 0.28 32.52 58.83 0.00 91.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	02/24/2021 13:20:11	02/24/2021 13:26:42	0.11	\$12.82
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/24/2021 13:00:00	02/24/2021 13:10:01	0.17	\$19.70
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/24/2021 12:07:01	02/24/2021 12:07:01	0.00	\$0.00
					<b>LABOR</b>	<b>32.52</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	8	\$35.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	TYC800198C	CABIN FILTER	13.53	1	\$13.53
					<b>PARTS</b>	<b>58.83</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 39192

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 13216 Completed PM top and bottom side, completed checklist. vacuumed and fueled up vehicle, did not wash to much stuff in bed of truck. AMG

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 40423

USING DEPT NO:	504103	OPENED DATE:	07/13/2021 13:33:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2021 10:01:43	METER 1 - M:	13817	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2021 12:42:05	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.15	\$17.27	\$0.75	\$0.00	\$18.02

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.15</b>	<b>17.27</b>	<b>0.75</b>	<b>0.00</b>	<b>18.02</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11915538	07/13/2021 13:40:15	07/13/2021 13:49:02	0.15	\$17.27
					<b>LABOR</b>	<b>17.27</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.75	1	\$0.75
					<b>PARTS</b>	<b>0.75</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 40423

---

**Work Order Notes**

(LISAPATE) LR turn signal is out

---

**Job Notes**

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(GARAGE) replaced LR blimker bulb\RC

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 41600

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 11/12/2021 07:48:07	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/16/2021 10:28:46	<b>METER 1 - M:</b> 15625 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/16/2021 11:43:36	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.52	\$15.18	\$0.00	\$19.70
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.57	\$67.10	\$8.75	\$0.00	\$75.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.47	\$44.48	\$0.00	\$77.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.89</b>	<b>105.09</b>	<b>68.41</b>	<b>2.00</b>	<b>175.50</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/12/2021 08:46:41	11/12/2021 08:48:59	0.04	\$4.52
66-17-030	PERFORM TIRE PATCH	12052187	11/12/2021 08:12:23	11/12/2021 08:46:30	0.57	\$67.10
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/12/2021 07:55:13	11/12/2021 08:12:14	0.28	\$33.47
					<b>LABOR</b>	<b>105.09</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.08	1	\$9.08
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.92	1	\$3.92
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41
66-17-030	PERFORM TIRE PATCH	58105	1.50 OZ WHEEL WEIGHT	0.56	1	\$0.56
					<b>PARTS</b>	<b>68.41</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 41600

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-17-030 - PERFORM TIRE PATCH**

(JWRIGHT) Repaired rr tire. Aired and balanced. Torqued lugs to spec. JAW

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. AB/JAW  
MILEAGE-15625

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 42271

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 02/04/2022 08:10:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/08/2022 08:54:50	<b>METER 1 - M:</b> 16951 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/08/2022 10:36:45	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.07	\$8.56	\$146.72	\$0.00	\$155.28
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.43	\$51.26	\$0.90	\$0.00	\$52.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.51</b>	<b>59.82</b>	<b>147.62</b>	<b>2.00</b>	<b>209.44</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11310047	02/04/2022 10:07:03	02/04/2022 10:11:24	0.07	\$8.56
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11310047	02/04/2022 10:30:42	02/04/2022 10:56:46	0.43	\$51.26
<b>LABOR</b>					<b>59.82</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	48H6	BATTERY BCI 48 DIN H6 630 CCA	146.72	1	\$146.72
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.90	1	\$0.90
<b>PARTS</b>					<b>147.62</b>	

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 42271

---

## Work Order Notes

(IFALLS) Replaced right rear blinker

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(EHOWELL) EH replaced battery 48H6

(IFALLS) Visit Reason Changed On 2/4/2022 8:35 AM By IFALLS

### **03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC**

(IFALLS) EH replaced right rear brake light

(IFALLS) Visit Reason Changed On 2/4/2022 8:35 AM By IFALLS

### **CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 42484

USING DEPT NO:	504103	OPENED DATE:	02/25/2022 12:36:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/28/2022 15:02:43	METER 1 - M:	17309	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	03/01/2022 07:24:34	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.03	\$3.77	\$3.86	\$0.00	\$7.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.76	\$0.76

JOB COUNT: 2 WORK ORDER TOTAL: 0.03 3.77 3.86 0.76 8.39

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$0.76
<b>COMML</b>					<b>0.76</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12052187	02/25/2022 13:02:57	02/25/2022 13:04:52	0.03	\$3.77
<b>LABOR</b>						<b>3.77</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
<b>PARTS</b>						<b>3.86</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 42484

---

**Work Order Notes**

(LISAPATE) right front tire has nail in it

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(JWRIGHT) Repaired rf tire. JAW

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 43575

USING DEPT NO:	504103	OPENED DATE:	06/08/2022 12:45:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/09/2022 09:57:43	METER 1 - M:	18188	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2022 10:17:41	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.03	\$15.57	\$0.00	\$17.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$51.17	\$56.21	\$0.00	\$107.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.45</b>	<b>53.20</b>	<b>71.78</b>	<b>2.00</b>	<b>126.98</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/08/2022 13:18:43	06/08/2022 13:19:45	0.02	\$2.03
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/08/2022 12:54:30	06/08/2022 13:18:37	0.40	\$47.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/08/2022 13:16:39	06/08/2022 13:18:33	0.03	\$3.74
<b>LABOR</b>					<b>53.20</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	8	\$45.00
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.21	1	\$11.21
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.79	2	\$15.57
<b>PARTS</b>					<b>71.78</b>	

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 43575

---

## Work Order Notes

(CWIGLEY) PM-Replace Wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(HHARBIN) Replaced wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW  
MILEAGE-18188

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 44440

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 08/24/2022 07:43:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/26/2022 09:55:57	<b>METER 1 - M:</b> 18988 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/26/2022 13:35:15	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.12	\$14.46	\$0.00	\$0.00	\$14.46
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.94	\$110.92	\$0.00	\$0.00	\$110.92
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.92	\$108.20	\$725.09	\$0.00	\$833.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>1.98</b>	<b>233.58</b>	<b>725.09</b>	<b>5.00</b>	<b>963.67</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	08/25/2022 07:00:00	08/25/2022 07:56:24	0.94	\$110.92
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11310047	08/24/2022 10:31:55	08/24/2022 11:28:01	0.94	\$110.33
06-15	INSPECT STEERING	11074414	08/24/2022 08:43:10	08/24/2022 08:50:31	0.12	\$14.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/24/2022 07:48:09	08/24/2022 08:43:10	0.92	\$108.20
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11310047	08/24/2022 10:31:55	08/24/2022 11:28:01	(0.94)	(\$110.33)
					<b>LABOR</b>	<b>233.58</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.31	4	\$9.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	2	\$0.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	2	\$1.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	3	\$1.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	2	\$1.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002767	TIRE LT245/70R17 FS TRANSFRC	177.36	4	\$709.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002767	TIRE LT245/70R17 FS TRANSFRC	177.36	(4)	(\$709.44)

# Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:35:53 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002767	TIRE LT245/70R17 FS TRANSFRC	177.36	4	\$709.44
					<b>PARTS</b>	<b>725.09</b>

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 44440

---

## Work Order Notes

(LISAPATE) Mount and balance 4 new tires and align

---

## Job Notes

### **06-15 - INSPECT STEERING**

(GARAGE) Inspected steering found no issues at this time. SH

### **09-17 - ALIGN TIRES, TUBES, LINERS & VALVES**

(EHOWELL) Performed Alignment. EH

### **66-17-013 - PERFORM ALIGNMENT**

(EKIMBREL) Performed Alignment. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) SH Mounted and JW balanced 4 tires. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 45265

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 11/15/2022 07:51:46	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/15/2022 13:42:51	<b>METER 1 - M:</b> 20001 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/17/2022 08:56:44	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.41	\$20.94	\$0.00	\$26.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.47	\$0.00	\$0.00	\$9.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 3	<b>WORK ORDER TOTAL:</b>	<b>0.13</b>	<b>14.88</b>	<b>20.94</b>	<b>5.00</b>	<b>40.82</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/15/2022 08:09:13	11/15/2022 08:11:58	0.05	\$5.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/15/2022 08:04:24	11/15/2022 08:09:13	0.08	\$9.47
<b>LABOR</b>					<b>14.88</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	2	\$20.94
<b>PARTS</b>					<b>20.94</b>	



# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 45265

---

## Work Order Notes

(LISAPATE) PM-repalce wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) greg replaced wiper blades. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) unit has been 1813 miles since last pm. updated sticker. checked fluids and tires. coolant -34. JAW,GC  
MILEAGE-20001

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 46744

USING DEPT NO:	504103	OPENED DATE:	04/18/2023 08:57:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/19/2023 10:58:05	METER 1 - M:	21744	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/19/2023 13:18:10	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.88	\$16.65	\$0.00	\$21.53
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.57	\$67.06	\$0.00	\$0.00	\$67.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.75	\$83.75	\$0.00	\$100.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$3.05	\$24.30	\$0.00	\$27.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.34	\$0.00	\$0.00	\$3.34

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>0.81</b>	<b>95.08</b>	<b>124.70</b>	<b>5.00</b>	<b>224.78</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/18/2023 09:46:59	04/18/2023 09:55:30	0.14	\$16.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	04/18/2023 09:45:14	04/18/2023 09:46:47	0.03	\$3.05
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/18/2023 09:55:46	04/18/2023 09:58:15	0.04	\$4.88
WA-00	WASH COMPLETE VEHICLE	12052187	04/18/2023 09:58:24	04/18/2023 10:00:06	0.03	\$3.34
66-79-003	PERFORM SAFETY INSPECTION	12052187	04/18/2023 10:00:16	04/18/2023 10:34:22	0.57	\$67.06
				<b>LABOR</b>		<b>95.08</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	24.30	1	\$24.30
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	8	\$49.92
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	9.53	1	\$9.53
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	24.30	1	\$24.30
				<b>PARTS</b>		<b>124.70</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 46744

---

## Work Order Notes

(EHANNAH) PM-Wash-Do annual SI-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wipers.

### **66-79-003 - PERFORM SAFETY INSPECTION**

(JWRIGHT) Performed safety inspection. All good

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/GC  
MILEAGE-21744

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(JWRIGHT) Replaced cabin filter.

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(JWRIGHT) Hand washed unit.

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 48562

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 10/16/2023 14:35:55	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/19/2023 10:44:36	<b>METER 1 - M:</b> 23153 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/20/2023 08:43:41	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150	2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.02	\$8.33	\$0.00	\$13.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.08	\$0.00	\$0.00	\$21.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	4.94	\$582.72	\$0.00	\$0.00	\$582.72
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.45	\$52.97	\$0.00	\$0.00	\$52.97

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>5.61</b>	<b>661.79</b>	<b>8.33</b>	<b>5.00</b>	<b>675.12</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	10/17/2023 14:30:00	10/17/2023 15:54:41	1.41	\$166.54
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	10/17/2023 13:02:00	10/17/2023 14:15:00	1.22	\$143.57
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	10/17/2023 09:36:04	10/17/2023 11:54:41	2.31	\$272.61
WA-00	WASH COMPLETE VEHICLE	12395904	10/17/2023 08:32:51	10/17/2023 08:59:47	0.45	\$52.97
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/17/2023 08:29:49	10/17/2023 08:32:22	0.04	\$5.02
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/17/2023 08:18:34	10/17/2023 08:29:17	0.18	\$21.08
					<b>LABOR</b>	<b>661.79</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
					<b>PARTS</b>	<b>8.33</b>

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 48562

---

## Work Order Notes

(EHANNAH) pm- wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(FCONTRER) Replace new wipers fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Flui check tires pressure and tread fc

### **CH-SP - CHARGE Shop Supplies**

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(EHOWELL) Found DTC: P1450:00:E8 Unable To Bleed Up Fuel Tank Vacuum. The EVAP purge valve and vent valve seem to be operating properly. Unable to diagnose at this time. Performed a road test to try to get the EVAP monitor to click off, but it did not. Also, the VCM kept losing communication with the laptop. The code has been cleared. EH

### **WA-00 - WASH COMPLETE VEHICLE**

(FCONTRER) Wash fc

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 50118

USING DEPT NO:	504103	OPENED DATE:	03/08/2024 08:41:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/20/2024 15:40:58	METER 1 - M:	24213	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2024 08:51:45	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.41	\$47.86	\$0.00	\$0.00	\$47.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$44.12	\$58.65	\$0.00	\$102.77
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$3.47	\$18.30	\$0.00	\$21.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	0.09	\$10.23	\$0.00	\$0.00	\$10.23

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.90</b>	<b>105.68</b>	<b>76.95</b>	<b>5.00</b>	<b>187.63</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-00	SCAN OUT COMPLETE VEHICLE	11074414	03/08/2024 13:26:44	03/08/2024 13:31:56	0.09	\$10.23
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	03/08/2024 09:40:44	03/08/2024 10:05:04	0.41	\$47.86
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	03/08/2024 09:38:37	03/08/2024 09:40:23	0.03	\$3.47
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/08/2024 09:30:00	03/08/2024 09:38:17	0.14	\$16.29
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/08/2024 09:00:51	03/08/2024 09:15:00	0.24	\$27.83
<b>LABOR</b>					<b>105.68</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	8	\$45.24
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC8214	CABIN FILTER	18.30	1	\$18.30
<b>PARTS</b>					<b>76.95</b>	

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 50118

---

## Work Order Notes

(EHANNAH) pm- scan out

---

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(FCONTRER) rotate tires and check Brakes f 8-m R -6m FC

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changes fc

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) replaced new cabin filter fc

### **CH-SP - CHARGE Shop Supplies**

### **SO-00 - SCAN OUT COMPLETE VEHICLE**

(GARAGE) Scanned vehicle code was P1450 evap code. cleared code and released vehicle per IF. SH

---

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 51068

USING DEPT NO:	504103	OPENED DATE:	06/06/2024 07:27:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 15:06:49	METER 1 - M:	24247	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/07/2024 08:32:03	IN-SERVICE DATE:	01/24/2017	
TECH SPEC NO:	17FORDF150	2017 Ford F150		UNIT SERIAL NO:	1FTEW1CF6HFA88636	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-075	REPLACE NEW PURGE SOLENOID VAL	DON	N	N	GARAGE	0.00	\$0.00	\$47.30	\$0.00	\$47.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>47.30</b>	<b>5.00</b>	<b>52.30</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-075	REPLACE NEW PURGE SOLENOID VALVE	STICP758	CANISTER PURGE VALVE	47.30	1	\$47.30
					<b>PARTS</b>	<b>47.30</b>



# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 51068

---

## Work Order Notes

(EHANNAH) scan-out to discovery codes.

---

## Job Notes

### **03-44-075 - REPLACE NEW PURGE SOLENOID VALVE**

(GARAGE) Replaced purge valve solenoid. Let idle for 30 minutes and test drove 25 miles. Found no other issues. JAW

### **CH-SP - CHARGE Shop Supplies**

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(GARAGE) Scanned unit and received code p1450 purge unable to bleed pressure. Looked up TSB and found new procedure on this issue and tested the VSB and found the Purge valve solenoid is not operating correctly when tank pressure is applied. Needs new purge valve. JAW

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 51902

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 08/22/2024 07:22:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/22/2024 12:18:50	<b>METER 1 - M:</b> 24981 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/23/2024 11:40:32	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150 2017 Ford F150		<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 242193 2017 FORD F150

WORK ORDER NO: 51902

---

## Work Order Notes

(EHANNAH) pm-wiper- wash

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC, Fluid check only, vehicle driven 771 miles, checked fluids, filters good, tires and tire pressure, updated oil change sticker  
Miles, 24,981

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed and filled with gas-GC

---

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 53650

<b>USING DEPT NO:</b> 504103	<b>OPENED DATE:</b> 02/06/2025 10:14:48	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/10/2025 08:30:08	<b>METER 1 - M:</b> 25690 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/10/2025 10:09:03	<b>IN-SERVICE DATE:</b> 01/24/2017
<b>TECH SPEC NO:</b> 17FORDF150 2017 Ford F150	<b>UNIT SERIAL NO:</b> 1FTEW1CF6HFA88636	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 242193 2017 FORD F150

**WORK ORDER NO:** 53650

---

**Work Order Notes**

(EHANNAH) prep for sale

---

**Job Notes**

**25-52-021 - REMOVE GPS SYSTEM**

(GARAGE) removed GPS #87u030640179 RC  
(EHOWELL) Visit Reason Changed On 2/10/2025 9:59 AM By EHOWELL

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) removed wordmarks and tag RC  
millage25698

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Sat Feb 15 2025 11:35:53 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '242193') //Q=