

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 10163

USING DEPT NO:	219101	OPENED DATE:	01/25/2012 15:24:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/01/2012 13:56:09	METER 1 - M:	16915	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/01/2012 13:56:11	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-53-006	REPLACE NEW WORDMARKS/IDENTIFI	DON	O	N	GARAGE	0.01	\$0.56	\$60.00	\$0.00	\$60.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$21.58	\$24.17	\$0.00	\$45.75

JOB COUNT: 2	WORK ORDER TOTAL:	0.39	22.14	84.17	0.00	106.31
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 07:05:29	01/26/2012 09:15:00	2.16	\$124.12
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 07:05:29	01/26/2012 09:15:00	(2.16)	(\$124.12)
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 09:30:00	01/26/2012 12:00:00	2.50	\$143.75
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 13:00:00	01/26/2012 14:15:00	1.25	\$71.88
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 13:00:00	01/26/2012 14:15:00	(1.25)	(\$71.88)
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 09:30:00	01/26/2012 12:00:00	(2.50)	(\$143.75)
66-PM-PMA	PERFORM OIL CHANGE	11413680	01/26/2012 14:30:00	01/26/2012 14:52:31	0.38	\$21.58
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	11338644	01/31/2012 08:27:20	01/31/2012 08:27:55	0.01	\$0.56
					<b>LABOR</b>	<b>22.14</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	144	\$12.96
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	4.37	1	\$4.37
66-PM-PMA	PERFORM OIL CHANGE	6126	FILTER-AIR	6.84	1	\$6.84
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	WORDMARK	WORDMARK-CRIMSON/ GRAY	22.50	2	\$45.00
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	WORDMARK	WORDMARK-CRIMSON/ GRAY	22.50	(2)	(\$45.00)
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	WORDMARK	WORDMARK-CRIMSON/ GRAY	30.00	2	\$60.00
					<b>PARTS</b>	<b>84.17</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 10163

## Work Order Notes

(LPATE) PM-REPLACE WORDMARKS ARE COMPLETELY FADED WHITE.

## Job Notes

### **03-53-006 - REPLACE NEW WORDMARKS/IDENTIFIERS**

(RWINTERS) REMOVED AND ADDED NEW WORDMARKS W/ID'S TO BOTH DOORS.

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 160 Cost 0.06

Part 6126 FILTER-AIR Qty 1 Cost 0

Part 1040 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY RT

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 12063

USING DEPT NO:	219101	OPENED DATE:	10/05/2012 08:06:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/09/2012 07:44:37	METER 1 - M:	17906	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/09/2012 07:44:38	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$331.60	\$331.60
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	N	N	GARAGE	0.00	\$0.00	\$44.19	\$0.00	\$44.19
03-50-103	REPLACE NEW BELT TENSIONER	DON	N	N	GARAGE	0.70	\$40.25	\$56.69	\$0.00	\$96.94
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.56	\$32.36	\$33.48	\$0.00	\$65.84
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.25	\$71.88	\$21.66	\$0.00	\$93.54

JOB COUNT: 6	WORK ORDER TOTAL:	3.51	201.99	156.02	331.60	689.61
--------------	-------------------	------	--------	--------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	D228113	0017600	\$331.60
	COMML				331.60

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11413680	10/05/2012 10:01:10	10/05/2012 10:34:56	0.56	\$32.36
66-PM-PMA	PERFORM OIL CHANGE	11413680	10/05/2012 10:34:56	10/05/2012 12:00:00	1.42	\$81.52
66-PM-PMA	PERFORM OIL CHANGE	11413680	10/05/2012 10:34:56	10/05/2012 12:00:00	(1.42)	(\$81.52)
66-PM-PMA	PERFORM OIL CHANGE	11413680	10/05/2012 13:00:00	10/05/2012 14:15:00	1.25	\$71.88
66-PM-PMA	PERFORM OIL CHANGE	11413680	10/05/2012 14:30:00	10/08/2012 07:51:05	65.35	\$3,757.71
66-PM-PMA	PERFORM OIL CHANGE	11413680	10/05/2012 14:30:00	10/08/2012 07:51:05	(65.35)	(\$3,757.71)
03-50-103	REPLACE NEW BELT TENSIONER	11074414	10/08/2012 07:00:00	10/08/2012 07:42:00	0.70	\$40.25
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11338644	10/08/2012 07:42:00	10/08/2012 08:42:00	1.00	\$57.50
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11074414	10/08/2012 07:42:00	10/08/2012 08:42:00	1.00	\$57.50
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11074414	10/08/2012 07:42:00	10/08/2012 08:42:00	(1.00)	(\$57.50)
	LABOR					201.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	4.38	1	\$4.38
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	2	\$33.48
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	144	\$17.28
03-50-103	REPLACE NEW BELT TENSIONER	GAT38103	BELT TENSIONER	56.69	1	\$56.69
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK060956	BELT	44.19	1	\$44.19
<b>PARTS</b>						<b>156.02</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 12063

## Work Order Notes

(LPATE) PM-REPLACE WIPERS-CHECK BELT IS CHIRPING IN THE MORNINGS-TECH NOTICED EXTREME WEAR ON INSIDE OF BOTH FRONT TIRES DUE TO ALIGNMENT WAS OUT.

## Job Notes

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) GOODYEAR REPLACED 2 FRONT TIRES AND ALIGNED. P0042132

### **03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.**

(LPATE) REPLACED BELT

### **03-50-103 - REPLACE NEW BELT TENSIONER**

(LPATE) REPLACED BELT TENSIONER

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :

Part No : 60-1840  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(LPATE) REPLACED WIPERS

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO GOODYEAR BY RS

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 160 Cost 0.06

Part 1040 FILTER-OIL Qty 1 Cost 2.92

Part 6126 FILTER-AIR Qty 1 Cost 4.03

(LPATE) PM BY RS

# Work Order Charge Detail

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 12704

USING DEPT NO:	219101	OPENED DATE:	01/04/2013 13:49:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/07/2013 07:18:30	METER 1 - M:	18204	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/07/2013 07:18:32	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-002	REPLACE NEW DISTRIBUTOR	DON	O	N	GARAGE	1.10	\$63.25	\$61.91	\$0.00	\$125.16
35-44	DIAGNOSE FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$4.91	\$0.00	\$33.66
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 3	WORK ORDER TOTAL:	1.90	109.25	66.82	0.00	176.07
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11268671	01/04/2013 13:52:29	01/04/2013 14:10:29	0.30	\$17.25
35-44	DIAGNOSE FUEL SYSTEM	11268671	01/04/2013 13:52:35	01/04/2013 14:22:35	0.50	\$28.75
03-33-002	REPLACE NEW DISTRIBUTOR	11268671	01/04/2013 13:52:44	01/04/2013 14:58:44	1.10	\$63.25
					LABOR	109.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-33-002	REPLACE NEW DISTRIBUTOR	DLPD328A	DISTRIBUTOR CAP	47.16	1	\$47.16
03-33-002	REPLACE NEW DISTRIBUTOR	DLPD465	ROTOR	14.75	1	\$14.75
35-44	DIAGNOSE FUEL SYSTEM	C111	RED BRAKE CLEANER	4.91	1	\$4.91
					PARTS	66.82

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 12704

## Work Order Notes

(LPATE) RYAN REQUESTED A SERVICE CALL TO LIBRARY ANNEX VAN WILL NOT START.

## Job Notes

### **03-33-002 - REPLACE NEW DISTRIBUTOR**

(LPATE) REPLACED DIST CAP AND ROTOR BUTTON. RECHECKED AND TEST DROVE. OK

### **35-44 - DIAGNOSE FUEL SYSTEM**

(LPATE) CHECKED FUEL PRESSURE IT WAS GOOD. FOUND BAD DISTRIBUTOR CAP.

### **66-79-002 - PERFORM SERVICE CALL**

(LPATE) CHECKED OUT GOT STARTED BROUGHT TO GARAGE.



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 13810

USING DEPT NO:	219101	OPENED DATE:	05/13/2013 09:01:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2013 06:22:32	METER 1 - M:	18630	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/14/2013 06:22:34	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$39.69	\$36.89	\$0.00	\$76.58

JOB COUNT: 2	WORK ORDER TOTAL:	1.19	68.44	36.89	0.00	105.33
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/13/2013 14:55:09	05/13/2013 15:25:09	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/13/2013 14:15:00	05/13/2013 14:56:25	0.69	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/13/2013 14:12:06	05/13/2013 14:12:06	0.00	\$0.00
					LABOR	68.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	144	\$17.28
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.50	1	\$7.50
					PARTS	36.89

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 13810

---

## Work Order Notes

(LPATE) PM-ROTATE TIRES

---

## Job Notes

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LPATE) ROTATED TIRES

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 2.92

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.0795

(LPATE) PM BY SH

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 15671

USING DEPT NO:	219101	OPENED DATE:	12/13/2013 10:49:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2013 15:13:55	METER 1 - M:	19286	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2013 15:13:55	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$27.69	\$0.00	\$42.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$24.78	\$0.00	\$42.61

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	32.21	52.47	0.00	84.68
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2013 11:50:49	12/13/2013 11:53:26	0.04	\$2.51
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2013 11:50:49	12/13/2013 11:53:26	(0.04)	(\$2.51)
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/13/2013 11:53:41	12/13/2013 12:08:41	0.25	\$14.38
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/13/2013 11:53:41	12/13/2013 11:55:50	0.04	\$2.06
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/13/2013 11:53:41	12/13/2013 11:55:50	(0.04)	(\$2.06)
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2013 11:50:49	12/13/2013 12:09:25	0.31	\$17.83
					<b>LABOR</b>	<b>32.21</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	13.85	2	\$27.69
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	144	\$17.28
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.50	1	\$7.50
					<b>PARTS</b>	<b>52.47</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 15671

## Work Order Notes

(GMANNING) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(GMANNING) REPLACED BOTH WIPER BLADES.

### 66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 2.92

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.0795

(GMANNING) PM BY SH/CA

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 16165

USING DEPT NO:	219101	OPENED DATE:	02/20/2014 11:02:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2014 11:56:33	METER 1 - M:	19475	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2014 11:56:34	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-01-046	REPAIR VACUUM LINE(S)	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.50	86.25	0.00	0.00	86.25
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11397026	02/21/2014 07:00:00	02/21/2014 07:30:00	0.50	\$28.75
24-01-046	REPAIR VACUUM LINE(S)	11397026	02/21/2014 07:30:00	02/21/2014 08:30:00	1.00	\$57.50
					LABOR	86.25

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 16165

## Work Order Notes

(LPATE) CHECK A/C WILL NOT BLOW ON ALL SETTINGS

## Job Notes

### **24-01-046 - REPAIR VACUUM LINE(S)**

(IFALLS) REPAIRED THE BROKEN VACUUM LINE FROM THE VACUUM VALVE TO THE VACUUM BALL. RECHECKED EVERYTHING OK. VAC HOSE ALREADY CHARGED C

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(LPATE) CHECKED OUT-AIR IS ONLY BLOWING OUT THE DEFROST

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 17062

USING DEPT NO:	219101	OPENED DATE:	05/22/2014 15:44:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/25/2014 18:00:00	METER 1 - M:	19752	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/25/2014 18:00:00	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$26.43	\$24.78	\$0.00	\$51.21

JOB COUNT: 1	WORK ORDER TOTAL:	0.46	26.43	24.78	0.00	51.21
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/23/2014 06:27:43	05/23/2014 06:55:18	0.46	\$26.43
					<b>LABOR</b>	<b>26.43</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	144	\$17.28
					<b>PARTS</b>	<b>24.78</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 17062

## Work Order Notes

(LPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 2.92

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.0795

(LPATE) PM BY SH/GM



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 18776

USING DEPT NO:	219101	OPENED DATE:	11/14/2014 15:05:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2014 11:35:13	METER 1 - M:	20334	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2014 11:35:14	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$13.56	\$28.02	\$0.00	\$41.58

JOB COUNT: 1	WORK ORDER TOTAL:	0.24	13.56	28.02	0.00	41.58
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	11/15/2014 15:23:43	11/15/2014 15:37:52	0.24	\$13.56
					<b>LABOR</b>	<b>13.56</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	144	\$17.28
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	3.24	1	\$3.24
					<b>PARTS</b>	<b>28.02</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 18776

## Work Order Notes

(LPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 2.92

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.0795

(LPATE) PM BY RS/IF

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 20655

USING DEPT NO:	219101	OPENED DATE:	06/30/2015 10:51:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/06/2015 09:44:37	METER 1 - M:	20844	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2015 09:44:39	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-046	REPLACE NEW VACUUM LINE(S)	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$324.31	\$324.31
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.50	\$28.75	\$1.40	\$0.00	\$30.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.12	\$64.43	\$17.81	\$0.00	\$82.24

JOB COUNT: 5	WORK ORDER TOTAL:	3.12	179.43	19.21	324.31	522.95
--------------	-------------------	------	--------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11321046	162614	0029147	\$324.31
				COMML	324.31

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11338644	06/30/2015 13:04:35	06/30/2015 13:09:05	0.08	\$4.31
66-PM-PMA	PERFORM OIL CHANGE	10260422	06/30/2015 13:03:46	06/30/2015 14:06:30	1.05	\$60.12
03-01-046	REPLACE NEW VACUUM LINE(S)	11397026	07/02/2015 07:30:00	07/02/2015 08:00:00	0.50	\$28.75
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	07/02/2015 07:00:00	07/02/2015 08:00:00	1.00	\$57.50
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11397026	07/02/2015 07:00:00	07/02/2015 07:30:00	0.50	\$28.75
				LABOR		179.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	2.26	1	\$2.26
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.11	144	\$15.55
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	7/32	HOSE-HEATER	0.47	3	\$1.40
				PARTS		19.21

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 20655

## Work Order Notes

(LPATE) PM-A/C WILL NOT BLOW OUT OF THE VENTS-NEEDS 2 TIRES

## Job Notes

### **03-01-046 - REPLACE NEW VACUUM LINE(S)**

(LPATE) REPAIRED VACUUM LEAK, REPLACED VACUUM HOSE. RECHECKED OK

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) OK TIRE REPLACED 2 TIRES AND ALIGNED. PD BY CC

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO OK TIRE BY AY

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(LPATE) CHECKED A/C HAS A VACUUM LEAK

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.88

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.0795

(LPATE) PM BY GM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 21975

USING DEPT NO:	219101	OPENED DATE:	11/12/2015 07:58:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/22/2015 13:23:59	METER 1 - M:	23197	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/22/2015 13:24:00	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-026	REPLACE NEW WEATHRSTRIPPING,G/	DON	O	N	GARAGE	1.39	\$79.78	\$402.36	\$0.00	\$482.14
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EX	DON	O	N	GARAGE	0.20	\$11.24	\$0.00	\$0.00	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.19	\$68.49	\$13.40	\$0.00	\$81.89

JOB COUNT: 3	WORK ORDER TOTAL:	2.77	159.51	415.76	0.00	575.27
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	11074414	12/17/2015 13:03:25	12/17/2015 14:26:40	1.39	\$79.78
35-71-032	DIAGNOSE WATER LEAK INTERIOR/EXTERIOR	11074414	11/12/2015 11:37:15	11/12/2015 11:48:59	0.20	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/12/2015 10:25:34	11/12/2015 11:37:02	1.19	\$68.49
					LABOR	159.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15642266	DOOR CHECK	13.99	2	\$27.98
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15592674	BRACKET	33.99	2	\$67.98
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15729842	PIN	15.99	1	\$15.99
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15729841	PIN	16.99	1	\$16.99
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15725612	RETAINER	4.99	1	\$4.99
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15766706	RIGHT REAR DOOR WEATHERSTRIP	113.16	1	\$113.16
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	15766705	LEFT REAR DOOR WEATHERSTRIP	133.29	1	\$133.29
03-02-026	REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMI	19303965	RADIATOR FITTING	10.99	2	\$21.98
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.08	144	\$11.52
					PARTS	415.76

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 21975

## Work Order Notes

(LISAPATE) PM-CHECK FOR REAR DOORS LEAKING WATER

## Job Notes

### **03-02-026 - REPLACE NEW WEATHRSTRIPPING,GASKETS&BUMPF**

(LISAPATE) REMOVED AND INSTALLED NEW DOOR GASKETS ON BOTH REAR DOORS. ALSO REPLACED DOOR CHECKS AND BRACKETS ON REAR DOORS WERE DAMAGED. RECHECKED ALL OK

### **35-71-032 - DIAGNOSE WATER LEAK INTERIOR/EXTERIOR**

(LISAPATE) CHECKED FOUND GASKETS WORN OUT AROUND BOTH BACK DOORS

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(LISAPATE) PM BY SH/GM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 22451

USING DEPT NO:	219101	OPENED DATE:	02/02/2016 09:28:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/02/2016 14:09:58	METER 1 - M:	21769	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/02/2016 14:09:59	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$49.16	\$0.00	\$77.91
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2	WORK ORDER TOTAL:					1.50	86.25	49.16	0.00	135.41
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	10260422	02/02/2016 09:29:35	02/02/2016 10:29:35	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	10260422	02/02/2016 09:29:41	02/02/2016 09:59:41	0.50	\$28.75
					<b>LABOR</b>	<b>86.25</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	75	BATTERY SIDE POST GM	49.16	1	\$49.16
					<b>PARTS</b>	<b>49.16</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 22451

## Work Order Notes

(LISAPATE) TERRY REQUESTED A SERVICE CALL TO GORGAS LIBRARY FOR A DEAD BATTERY

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) REMOVED AND INSTALLED NEW BATTERY. RECHECKED OK

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) SERVICE CALL COMPLETED



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 2367

USING DEPT NO:	219101	OPENED DATE:	11/12/2008 10:31:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/12/2008 15:24:00	METER 1 - M:	11675	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/12/2008 15:24:01	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$20.34	\$0.00	\$38.17

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	20.34	0.00	38.17
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/12/2008 11:00:00	11/12/2008 11:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	144	\$12.96
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.38	1	\$7.38
					<b>PARTS</b>	<b>20.34</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 2367

## Work Order Notes

(LPATE) PM-CHECKED RIGHT FRONT TIRE LOW COULD NOT FIND A LEAK

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 51040 FILTER-OIL Qty 1 Cost 0

Part 10W-30 OIL BULK Qty 160 Cost 0

Part 46126 FILTER-AIR Qty 1 Cost 0

(LPATE) PM BY JE

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 23795

USING DEPT NO:	219101	OPENED DATE:	06/30/2016 14:21:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/13/2016 06:40:23	METER 1 - M:	22304	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/13/2016 06:40:25	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-16-003	REPLACE NEW FRONT SHOCK ABSORBER	DON	O	N	GARAGE	1.40	\$80.50	\$288.58	\$0.00	\$369.08
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	DON	O	N	GARAGE	0.70	\$40.25	\$203.48	\$0.00	\$243.73
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOP	DON	O	N	GARAGE	0.50	\$28.75	\$85.98	\$0.00	\$114.73
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.63	\$36.11	\$17.06	\$0.00	\$53.17
06-16	INSPECT SUSPENSION	DON	O	N	GARAGE	0.27	\$15.27	\$0.00	\$0.00	\$15.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$27.22	\$17.98	\$0.00	\$45.20

JOB COUNT: 6	WORK ORDER TOTAL:	3.97	228.10	613.08	0.00	841.18
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/01/2016 06:37:15	07/01/2016 07:14:56	0.63	\$36.11
06-16	INSPECT SUSPENSION	11074414	07/01/2016 07:14:59	07/01/2016 07:30:55	0.27	\$15.27
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOP	11758845	07/08/2016 08:24:00	07/08/2016 08:54:00	0.50	\$28.75
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	11758845	07/08/2016 08:54:00	07/08/2016 09:36:00	0.70	\$40.25
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	11758845	07/08/2016 07:00:00	07/08/2016 08:24:00	1.40	\$80.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/01/2016 06:08:46	07/01/2016 06:37:10	0.47	\$27.22

LABOR 228.10

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30SSQT	10W30 SEMI SYN QT. BOTTLE	3.22	5	\$16.10
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOP	15152251	REAR BUMPERS/SNUBBERS	42.99	2	\$85.98
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	24010474	HD SHOCKS	101.74	2	\$203.48
03-16-003	REPLACE NEW FRONT SHOCK ABSORBERS	24011044	REAR HD SHOCKS	144.29	2	\$288.58

PARTS 613.08

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 23795

## Work Order Notes

(LISAPATE) PM-CHECK SHOCKS WHEN LOADED VAN SITS WAY DOWN

## Job Notes

### **03-16-003 - REPLACE NEW FRONT SHOCK ABSORBERS**

(LISAPATE) REPLACED FRONT SHOCKS

### **03-16-006 - REPLACE NEW REAR SHOCK ABSORBER**

(LISAPATE) REPLACED REAR SHOCKS

### **03-16-028 - REPLACE NEW FRONT/ REAR BUMP STOPS**

(LISAPATE) REPLACED REAR BUMP STOPS

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(LISAPATE) REPLACED WIPERS

### **06-16 - INSPECT SUSPENSION**

(LISAPATE) CHECKED OUT SHOCKS ARE WORN OUT-REAR BUMP STOPS ARE WORN DOWN

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(LISAPATE) PM BY SH

# Work Order Charge Detail

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 24891

USING DEPT NO:	219101	OPENED DATE:	11/07/2016 15:09:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/16/2016 14:56:05	METER 1 - M:	22760	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/16/2016 14:56:07	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$12.76	\$19.37	\$0.00	\$32.13

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.22</b>	<b>12.76</b>	<b>19.37</b>	<b>0.00</b>	<b>32.13</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	11/09/2016 09:01:33	11/09/2016 09:14:52	0.22	\$12.76
					<b>LABOR</b>	<b>12.76</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30SSQT	10W30 SEMI SYN QT. BOTTLE	3.23	4	\$12.92
66-PM-PMA	PERFORM OIL CHANGE	6126	FILTER-AIR	4.57	1	\$4.57
					<b>PARTS</b>	<b>19.37</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 24891

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 11/7/2016 3:10 PM By LISAPATE

(LISAPATE)

The following parts are included with the standard job:

Part No : 1040  
Qty : 1  
Description : FILTER-OIL  
Manufacturer : NAPA

Part No : 10W30SS  
Qty : 144  
Description : 10W30 HAV SEMI-SYNTHETIC OIL  
Manufacturer :

(LISAPATE) PM BY CS-REPLACED AIR FILTER-TOPPED COOLANT-USED 1/2QT OF OIL ALREADY CHARGED OUT

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 25943

USING DEPT NO:	219101	OPENED DATE:	03/08/2017 08:55:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2017 10:26:41	METER 1 - M:	23123	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/10/2017 10:26:43	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$23.94	\$18.03	\$0.00	\$41.97

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.42</b>	<b>23.94</b>	<b>18.03</b>	<b>0.00</b>	<b>41.97</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/08/2017 08:59:57	03/08/2017 09:24:56	0.42	\$23.94
					<b>LABOR</b>	<b>23.94</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30SSQT	10W30 SEMI SYN QT. BOTTLE	3.23	5	\$16.15
					<b>PARTS</b>	<b>18.03</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 25943

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(LISAPATE) PM BY SH

COOLANT -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 26906

USING DEPT NO:	219101	OPENED DATE:	07/25/2017 06:49:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2017 09:48:37	METER 1 - M:	23406	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/25/2017 09:48:39	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.83	\$47.69	\$10.44	\$0.00	\$58.13

JOB COUNT: 2	WORK ORDER TOTAL:					1.08	62.07	27.50	0.00	89.57
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/25/2017 08:48:02	07/25/2017 09:19:12	0.52	\$29.87
03-51-038	REPLACE NEW WIPER BLADES	11758845	07/25/2017 07:18:36	07/25/2017 07:33:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/25/2017 07:00:00	07/25/2017 07:18:36	0.31	\$17.83
					LABOR	62.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10W30P	PROTECK10W30SEMI SYNTHETIC OIL	2.14	4	\$8.56
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	2	\$17.06
					PARTS	27.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 26906

## Work Order Notes

(IFALLS) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(IFALLS)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(IFALLS) CS REPLACED BOTH WIPER BLADES

### 66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(IFALLS) CS PERFORMED PM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 2703

USING DEPT NO:	219101	OPENED DATE:	01/06/2009 09:32:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2009 14:51:03	METER 1 - M:	11840	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/06/2009 14:51:06	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-33-002	REPLACE NEW DISTRIBUTOR	DON	O	N	GARAGE	1.10	\$63.25	\$70.30	\$0.00	\$133.55

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>1.10</b>	<b>63.25</b>	<b>70.30</b>	<b>0.00</b>	<b>133.55</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-002	REPLACE NEW DISTRIBUTOR	11088474	01/06/2009 14:00:00	01/06/2009 15:06:00	1.10	\$63.25
					<b>LABOR</b>	<b>63.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-002	REPLACE NEW DISTRIBUTOR	STIDR331	ROTOR BUTTON	13.14	1	\$13.14
03-33-002	REPLACE NEW DISTRIBUTOR	PTX22058	DIELECTRIC GREASE	11.03	1	\$11.03
03-33-002	REPLACE NEW DISTRIBUTOR	C111	RED BRAKE CLEANER	4.13	1	\$4.13
03-33-002	REPLACE NEW DISTRIBUTOR	STIDR475	DIST. CAP	42.00	1	\$42.00
					<b>PARTS</b>	<b>70.30</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 2703

## Work Order Notes

(LPATE) RUNNING ROUGH-CHECK ENGINE LIGHT IS ON

## Job Notes

03-33-002 - REPLACE NEW DISTRIBUTOR

(LPATE) FOUND WATER UNDER DIST CAP REPLACED CAP AND BUTTON

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28218

USING DEPT NO:	219101	OPENED DATE:	11/21/2017 14:19:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/22/2017 11:22:04	METER 1 - M:	24021	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/22/2017 11:22:07	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$10.44	\$0.00	\$28.27

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	10.44	0.00	28.27
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/21/2017 15:50:24	11/21/2017 15:50:30	0.00	(\$0.10)
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/21/2017 15:50:24	11/21/2017 15:50:30	0.00	\$0.10
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/21/2017 15:50:24	11/21/2017 16:09:00	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10W30P	PROTECK10W30SEMI SYNTHETIC OIL	2.14	4	\$8.56
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
					PARTS	10.44

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28218

## Work Order Notes

(IFALLS) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(IFALLS) AG PERFORMED PM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28571

USING DEPT NO:	219101	OPENED DATE:	01/09/2018 15:21:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/12/2018 07:28:45	METER 1 - M:	24132	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/12/2018 07:28:47	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	0.40	\$23.00	\$17.34	\$0.00	\$40.34

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.40</b>	<b>23.00</b>	<b>17.34</b>	<b>0.00</b>	<b>40.34</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11074414	01/10/2018 06:00:00	01/10/2018 06:24:00	0.40	\$23.00
					<b>LABOR</b>	<b>23.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	ACI60212	DOOR HANDLE	17.34	1	\$17.34
					<b>PARTS</b>	<b>17.34</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28571

## Work Order Notes

(LISAPATE) REAR DOORS WILL NOT OPEN

## Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(LISAPATE) REMOVED AND INSTALLED NEW OUTSIDE DOOR HANDLE. RECHECKED OK

06-02-023 - INSPECT HANDLES - INNER & OUTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28778

USING DEPT NO:	219101	OPENED DATE:	02/02/2018 15:36:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2018 09:28:05	METER 1 - M:	24216	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2018 09:28:07	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-025	REPLACE NEW ABS HCU	DON	O	N	GARAGE	2.60	\$149.50	\$815.04	\$0.00	\$964.54
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00

JOB COUNT: 3	WORK ORDER TOTAL:	5.10	293.25	815.04	0.00	1,108.29
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-13-025	REPLACE NEW ABS HCU	11213180	02/09/2018 07:30:00	02/09/2018 09:06:00	(1.60)	(\$92.00)
03-13-025	REPLACE NEW ABS HCU	11213180	02/09/2018 07:30:00	02/09/2018 09:06:00	1.60	\$92.00
06-13	INSPECT BRAKES	11213180	02/09/2018 07:00:00	02/09/2018 07:30:00	0.50	\$28.75
03-13-025	REPLACE NEW ABS HCU	11213180	02/09/2018 07:30:00	02/09/2018 10:06:00	2.60	\$149.50
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	02/09/2018 07:30:00	02/09/2018 09:30:00	2.00	\$115.00
					LABOR	293.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-025	REPLACE NEW ABS HCU	C111	RED BRAKE CLEANER	2.11	1	\$2.11
03-13-025	REPLACE NEW ABS HCU	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	2.09	2	\$4.18
03-13-025	REPLACE NEW ABS HCU	88964380	ABS MODULATOR VALVE	567.69	1	\$567.69
03-13-025	REPLACE NEW ABS HCU	DOR599713	ABS CONTROL MODULE	241.06	1	\$241.06
					PARTS	815.04

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28778

## Work Order Notes

(LISAPATE) CHECK BRAKES, LIGHT COMING ON AND OFF. STOPPING FINE

## Job Notes

### **03-13-025 - REPLACE NEW ABS HCU**

(LISAPATE) REPLACED EBCM AND HYDRAULIC UNIT. BLED SYSTEM. RECHECKED OK

### **06-13 - INSPECT BRAKES**

(LISAPATE) FOUND EBCM TO HAVE INTERMITTENT FAILURE. TESTED ALL WIRING AND CONNECTIONS. CHECKED OK

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT-C0265 EBCM MOTOR RELAY CIRCUIT  
AFTER REPLACED. REPROGRAMMED MODULE WITH GM SCAN TOOL. TEST DROVE. ALL OK

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28952

USING DEPT NO:	219101	OPENED DATE:	02/21/2018 11:13:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/23/2018 14:04:44	METER 1 - M:	24216	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/23/2018 14:04:46	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.30	\$17.25	\$25.00	\$0.00	\$42.25

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.30</b>	<b>17.25</b>	<b>25.00</b>	<b>0.00</b>	<b>42.25</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	11074414	02/21/2018 11:15:32	02/21/2018 11:33:32	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	MIRROR	USED MIRROR PASS SIDE	25.00	1	\$25.00
					<b>PARTS</b>	<b>25.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 28952

---

## Work Order Notes

(LISAPATE) DRIVER OUTSIDE MIRROR FELL OFF

---

## Job Notes

03-02-010 - REPLACE NEW MIRRORS

(LISAPATE) INSTALLED NEW MIRROR

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 29966

USING DEPT NO:	219101	OPENED DATE:	06/06/2018 07:27:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/11/2018 13:34:46	METER 1 - M:	24504	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	06/11/2018 13:34:49	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	1.00	\$57.50	\$22.12	\$0.00	\$79.62

JOB COUNT: 2	WORK ORDER TOTAL:					1.50	86.25	22.12	0.00	108.37
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-01-058	PERFORM EVAC AND RECHARGE FREON	11268671	06/11/2018 07:30:00	06/11/2018 08:30:00	1.00	\$57.50
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11268671	06/11/2018 07:00:00	06/11/2018 07:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>86.25</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON LB	RECLAIMED FREON LB	1.50	1	\$1.50
66-01-058	PERFORM EVAC AND RECHARGE FREON	FOR59946	A/C SERVICE VALVE	3.22	1	\$3.22
66-01-058	PERFORM EVAC AND RECHARGE FREON	FOR37308	LOW PRESSURE SWITCH	12.54	1	\$12.54
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134ALB	FREON-POUND	3.78	1	\$3.78
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.08	1	\$1.08
					<b>PARTS</b>	<b>22.12</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 29966

---

## Work Order Notes

(IFALLS) CHECK A/C

---

## Job Notes

03-01-058 - REPLACE NEW EVAC AND RECHARGE FREON

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(RTUNAITI) Found refrigerant level to be low and compressor not cycling

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(IFALLS) Replaced clutch cycling switch and high pressure service port  
Recycled 1 lb and added 1 lb r134a refrigerant. Added 1 oz ester oil. TOTAL CHARGE OF 2LBS

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 31388

USING DEPT NO:	219101	OPENED DATE:	11/02/2018 15:51:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/14/2018 15:04:20	METER 1 - M:	25060	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/14/2018 15:04:22	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-020	REPLACE NEW DRAG LINK	DON	O	N	GARAGE	0.29	\$0.00	\$55.43	\$0.00	\$55.43
03-44-029	REPLACE NEW FUEL TANK PRESSURE	DON	O	N	GARAGE	2.70	\$0.00	\$33.51	\$0.00	\$33.51
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.53	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$0.00	\$1.44	\$0.00	\$1.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$0.00	\$15.76	\$0.00	\$15.76
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$231.52	\$231.52
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	3.58	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 7	WORK ORDER TOTAL:	7.98	0.00	106.14	231.52	337.66
--------------	-------------------	------	------	--------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11078167	1140152	0045783	\$231.52
				COMML	231.52

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	11310047	11/12/2018 07:00:00	11/12/2018 09:42:00	2.70	\$0.00
03-15-020	REPLACE NEW DRAG LINK	11310047	11/07/2018 15:05:13	11/07/2018 15:22:27	0.29	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2018 09:30:00	11/05/2018 09:42:10	0.20	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2018 08:57:47	11/05/2018 09:15:00	0.29	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2018 07:36:38	11/06/2018 07:40:36	0.07	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2018 08:50:17	11/06/2018 09:15:00	0.41	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/07/2018 10:02:22	11/07/2018 12:00:00	1.96	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/07/2018 13:00:00	11/07/2018 14:08:33	1.14	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/09/2018 06:01:47	11/09/2018 07:30:48	0.00	\$0.00
09-15	ALIGN STEERING	11310047	11/09/2018 13:20:34	11/09/2018 13:52:08	0.53	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/12/2018 06:00:00	11/12/2018 06:24:00	0.40	\$0.00



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

					LABOR	0.00
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	2.83	1	\$2.83
03-15-020	REPLACE NEW DRAG LINK	TRWJTY233	DRAG LINK	52.60	1	\$52.60
03-15-020	REPLACE NEW DRAG LINK	CMP	MOBILE CM-P TUBE GREASE	2.83	1	\$2.83
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.21	5	\$11.05
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.26	4	\$1.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.20	2	\$0.40
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	221001	FUEL VAPOR PRESSURE SENSOR	33.51	1	\$33.51
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	221001	FUEL VAPOR PRESSURE SENSOR	33.51	(1)	(\$33.51)
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	221001	FUEL VAPOR PRESSURE SENSOR	33.51	1	\$33.51
					<b>PARTS</b>	<b>106.14</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 31388

## Work Order Notes

(LISAPATE) PM-Check engine light on

## Job Notes

### **03-15-020 - REPLACE NEW DRAG LINK**

(LISAPATE) Replaced drag link and greased

### **03-44-029 - REPLACE NEW FUEL TANK PRESSURE SENSOR**

(LISAPATE) Installed new fuel tank pressure sensor observed vacuum reading with a scan tool. The fuel tank pressure sensor is now reading vacuum and pressure properly.

### **09-15 - ALIGN STEERING**

(LISAPATE) EH performed alignment

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) SH and CS mounted and balanced 2 new front tires

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(LISAPATE) PM by RC/AG

Coolant -35'

### **PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES**

(LISAPATE) Purchased 2 tires from Warren Tire. Pd by CC

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(IFALLS) Scan out GM MD1 Tech 2 WW-P0446 Evap vent system performance. Fuel tank pressure sensor is not reading properly. The sensor is giving a false reading, therefore the vehicle thinks the vent isnt working.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 33004

USING DEPT NO:	219101	OPENED DATE:	05/28/2019 08:34:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2019 14:03:53	METER 1 - M:	25706	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/30/2019 14:03:55	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$82.40	\$0.00	\$82.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$0.00	\$14.77	\$0.00	\$14.77

JOB COUNT: 2	WORK ORDER TOTAL:					0.97	0.00	97.17	0.00	97.17
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11915538	05/28/2019 10:57:23	05/28/2019 11:27:23	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/28/2019 09:10:49	05/28/2019 09:38:45	0.47	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	6126	FILTER-AIR	2.84	1	\$2.84
03-32-002	REPLACE NEW BATTERY	75	BATTERY SIDE POST GM	82.40	1	\$82.40
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.01	5	\$10.05
					PARTS	97.17

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 33004

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery, alt is charging at 14.1 volts

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(LISAPATE) PM by RC/AG

Replaced air filter

Coolant -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 34671

USING DEPT NO:	219101	OPENED DATE:	10/30/2019 08:12:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2019 14:40:21	METER 1 - M:	26217	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2019 14:40:23	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.05	\$0.00	\$17.06	\$0.00	\$17.06
14-15-024	INSTALL STEERING WHEEL COVER	DON	O	N	GARAGE	0.07	\$0.00	\$12.87	\$0.00	\$12.87
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.93	\$0.00	\$11.88	\$0.00	\$11.88

JOB COUNT: 3	WORK ORDER TOTAL:	1.05	0.00	41.81	0.00	41.81
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-15-024	INSTALL STEERING WHEEL COVER	11074414	10/30/2019 08:44:23	10/30/2019 08:48:22	0.07	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/30/2019 08:17:37	10/30/2019 08:50:50	0.55	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/30/2019 08:41:16	10/30/2019 08:44:23	0.05	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/30/2019 08:18:36	10/30/2019 08:41:16	0.38	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-15-024	INSTALL STEERING WHEEL COVER	AC48302B	STEERING WHEEL COVER 15.25IN	12.87	1	\$12.87
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	2.00	5	\$10.00
					PARTS	41.81

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 34671

## Work Order Notes

(LISAPATE) PM-Install steering wheel cover

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(RTUNAITI)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(LISAPATE) Replaced wipers

### 14-15-024 - INSTALL STEERING WHEEL COVER

(LISAPATE) Installed a steering wheel cover

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(LISAPATE) PM by SH/JW

Coolant -35'

Syn 4.48

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 36521

USING DEPT NO:	219101	OPENED DATE:	05/20/2020 09:52:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/21/2020 10:39:04	METER 1 - M:	26615	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/21/2020 14:01:43	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$0.00	\$11.83	\$0.00	\$11.83

JOB COUNT: 1	WORK ORDER TOTAL:					0.30	0.00	11.83	0.00	11.83
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/20/2020 14:47:10	05/20/2020 15:04:52	0.30	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-30K	PERFORM 30,000 MILES/3YEAR SERVICE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-30K	PERFORM 30,000 MILES/3YEAR SERVICE	51040	FILTER-OIL	1.88	(1)	(\$1.88)
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	1.88	1	\$1.88
66-PM-PMA	PERFORM OIL CHANGE	10W30BT	BULK OIL 10W30 SEMI-SYN THOMAS	1.99	5	\$9.95
					<b>PARTS</b>	<b>11.83</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 36521

---

## Work Order Notes

(EKIMBREL) PM

---

## Job Notes

66-PM-30K - PERFORM 30,000 MILES/3YEAR SERVICE

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

Parts For Job Include:

Part 1040 FILTER-OIL Qty 1 Cost 1.880000

Part 10W30SS 10W30 HAV SEMI-SYNTHETIC OIL Qty 144 Cost 0.079500

(EKIMBREL) SH/SH performed pm. Coolant -35

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 37111

USING DEPT NO:	219101	OPENED DATE:	07/14/2020 09:08:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/21/2020 10:32:01	METER 1 - M:	26647	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/21/2020 13:48:58	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-006	REPLACE NEW CONDENSER	DON	O	N	GARAGE	1.66	\$0.00	\$109.38	\$0.00	\$109.38
03-01-014	REPLACE NEW RESISTOR	DON	O	N	GARAGE	0.15	\$0.00	\$40.70	\$0.00	\$40.70
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILT	DON	O	N	GARAGE	1.10	\$0.00	\$1.31	\$0.00	\$1.31
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	DON	O	N	GARAGE	0.23	\$0.00	\$23.29	\$0.00	\$23.29
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	1.03	\$0.00	\$0.00	\$0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREI	DON	O	N	GARAGE	0.26	\$0.00	\$6.31	\$0.00	\$6.31

JOB COUNT: 6	WORK ORDER TOTAL:	4.41	0.00	180.99	0.00	180.99
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-01-006	REPLACE NEW CONDENSER	11170580	07/16/2020 08:43:15	07/16/2020 09:15:00	0.53	\$0.00
03-01-006	REPLACE NEW CONDENSER	11170580	07/16/2020 09:30:00	07/16/2020 10:37:34	1.13	\$0.00
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	11170580	07/16/2020 10:37:50	07/16/2020 11:43:35	1.10	\$0.00
03-01-014	REPLACE NEW RESISTOR	11170580	07/20/2020 11:31:40	07/20/2020 11:40:31	0.15	\$0.00
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	11170580	07/20/2020 11:41:50	07/20/2020 11:54:32	0.21	\$0.00
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	11170580	07/20/2020 13:13:23	07/20/2020 13:14:12	0.01	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/20/2020 13:14:24	07/20/2020 13:29:56	0.26	\$0.00
03-01-053	REPLACE NEW A/C CLUTCH CYCLING SWITCH	11170580	07/21/2020 07:00:00	07/21/2020 07:30:00	0.50	\$0.00
03-01-053	REPLACE NEW A/C CLUTCH CYCLING SWITCH	11170580	07/21/2020 07:00:00	07/21/2020 07:30:00	(0.50)	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	07/15/2020 07:16:00	07/15/2020 08:17:38	1.03	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-01-053	REPLACE NEW A/C CLUTCH CYCLING SWITCH	FOR35751	A/C CLUTCH CYCLING SWITCH	11.03	(1)	(\$11.03)
03-01-014	REPLACE NEW RESISTOR	STIRU496	BLOWER MOTOR RESISTOR	40.70	1	\$40.70
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	FOR26742	A/C SYSTEM O-RING KIT	4.85	1	\$4.85
03-01-053	REPLACE NEW A/C CLUTCH CYCLING SWITCH	FOR35751	A/C CLUTCH CYCLING SWITCH	11.03	1	\$11.03

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	FOR38642	ORIFICE TUBE	1.31	1	\$1.31
03-01-006	REPLACE NEW CONDENSER	TYC4623	A/C CONDENSER	109.38	1	\$109.38
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	FOR33218	ACCUMULATOR/DRIER	18.44	1	\$18.44
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.19	27	\$5.13
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	0.73	1	\$0.73
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	5	\$0.45
					<b>PARTS</b>	<b>180.99</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 37111

## Work Order Notes

(LISAPATE) Per Ryan van A/C is blowing not and blower wont blow at all on high

## Job Notes

### **03-01-006 - REPLACE NEW CONDENSER**

(LISAPATE) AB found condenser leaking. Installed new condenser

### **03-01-014 - REPLACE NEW RESISTOR**

(ABBLACK) AB found blower motor resistor was bad. Installed new resistor. Rechecked ok.

### **03-01-053 - REPLACE NEW A/C CLUTCH CYCLING SWITCH**

### **03-01-056 - REPLACE NEW A/C ORFICE VALVE/FILTER**

(ABBLACK) AB installed a new orifice tube

### **03-01-063 - REPLACE NEW ACCUMULATOR/DRIER**

(ABBLACK) AB installed new accumulator

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(ABBLACK) AB found condenser leaking

### **66-01-058 - PERFORM EVAC AND RECHARGE FREON**

(ABBLACK) AB Found condenser leaking freon. Evacuated system. Installed new condenser, orifice tube and accumulator. Vacuumed and recharged system. Used 1 ounce of ester oil with dye. Rechecked ok.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 38210

USING DEPT NO:	219101	OPENED DATE:	10/29/2020 13:07:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/30/2020 09:27:18	METER 1 - M:	26848	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/30/2020 09:57:21	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-010	REPLACE NEW TAG LIGHT	DON	O	N	GARAGE	0.06	\$7.44	\$0.63	\$0.00	\$8.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.67	\$14.68	\$0.00	\$73.35

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	66.11	15.31	0.00	81.42
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/29/2020 13:13:19	10/29/2020 13:43:09	0.50	\$58.67
03-34-010	REPLACE NEW TAG LIGHT	11901357	10/29/2020 13:22:14	10/29/2020 13:26:01	0.06	\$7.44
					LABOR	66.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	14.68	1	\$14.68
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.63	1	\$0.63
					PARTS	15.31

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 38210

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 03-34-010 - REPLACE NEW TAG LIGHT

(AGUERRA) Replaced tag light bulb, checked for proper operation, all good. AMG

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 233 miles. Checked fluids and tires. Updated pm sticker. Coolant -34°. JAW,AMG

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 3898

USING DEPT NO:	219101	OPENED DATE:	07/17/2009 11:38:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/17/2009 11:43:16	METER 1 - M:	12705	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	07/17/2009 15:01:40	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$78.78	\$0.00	\$107.53
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>					<b>1.50</b>	<b>86.25</b>	<b>78.78</b>	<b>0.00</b>	<b>165.03</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11274660	07/17/2009 17:00:00	07/17/2009 18:00:00	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11274660	07/17/2009 18:00:00	07/17/2009 18:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>86.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	78-7	BATTERY SIDE POST	78.78	1	\$78.78
					<b>PARTS</b>	<b>78.78</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 3898

## Work Order Notes

(LPATE) WILLIAM REQUESTED SVC CALL FOR NO START TO MARY HARMON HALL

## Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

66-79-002 - PERFORM SERVICE CALL

(LPATE) BATTERY WAS DEAD- REPLACED BATTERY

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 39835

USING DEPT NO:	219101	OPENED DATE:	04/29/2021 13:04:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2021 15:39:30	METER 1 - M:	27175	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/04/2021 14:17:15	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.07	\$8.06	\$17.67	\$0.00	\$25.73
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.62	\$23.23	\$0.00	\$78.85

JOB COUNT: 2	WORK ORDER TOTAL:	0.54	63.68	40.90	0.00	104.58
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/30/2021 08:08:13	04/30/2021 08:12:19	0.07	\$8.06
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/30/2021 07:39:46	04/30/2021 08:08:03	0.47	\$55.62
					<b>LABOR</b>	<b>63.68</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	8.45	1	\$8.45
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	2.96	5	\$14.78
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	8.84	2	\$17.67
					<b>PARTS</b>	<b>40.90</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 39835

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(SHARBIN) Replaced wipers due to normal wear. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 27175. SH/JW Performed PM.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 41420

USING DEPT NO:	219101	OPENED DATE:	10/25/2021 11:51:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2021 11:04:25	METER 1 - M:	27539	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/08/2021 15:05:19	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.86	\$102.00	\$81.60	\$0.00	\$183.60
03-15-012	REPLACE NEW IDLER ARM	DON	O	N	GARAGE	0.95	\$112.20	\$225.25	\$0.00	\$337.45
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.06	\$6.49	\$0.00	\$0.00	\$6.49
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.41	\$48.51	\$0.00	\$0.00	\$48.51
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.44	\$51.95	\$349.25	\$0.00	\$401.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$52.54	\$0.00	\$0.00	\$52.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 7	WORK ORDER TOTAL:	3.17	373.69	656.10	2.00	1,031.79
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/25/2021 14:44:56	10/25/2021 14:47:34	0.04	\$5.18
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/25/2021 12:42:57	10/25/2021 13:07:02	0.40	\$47.36
03-02-010	REPLACE NEW MIRRORS	11310047	11/03/2021 09:30:00	11/03/2021 10:21:52	0.86	\$102.00
03-02-010	REPLACE NEW MIRRORS	11310047	11/03/2021 09:14:42	11/03/2021 09:14:42	0.00	\$0.00
03-15-012	REPLACE NEW IDLER ARM	11213180	11/02/2021 08:17:57	11/02/2021 09:15:00	0.95	\$112.20
06-15	INSPECT STEERING	12052187	10/28/2021 08:03:48	10/28/2021 08:07:06	0.06	\$6.49
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/28/2021 07:37:13	10/28/2021 08:03:38	0.44	\$51.95
66-17-013	PERFORM ALIGNMENT	11310047	11/03/2021 08:40:44	11/03/2021 09:05:24	0.41	\$48.51
				LABOR		373.69

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.35	2	\$0.69

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.47	2	\$0.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	65230	MICH DEFENDER 215/70R16	173.61	2	\$347.22
03-15-012	REPLACE NEW IDLER ARM	TRWJIA214	IDLER ARM	113.66	1	\$113.66
03-15-012	REPLACE NEW IDLER ARM	MOGK6365T	IDLER ARM	111.59	1	\$111.59
03-02-010	REPLACE NEW MIRRORS	TYC2310131	PASSENGER MIRROR	81.60	1	\$81.60
					<b>PARTS</b>	<b>656.10</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI*

**UNIT NO:**                    **233742**                    **2003 CHEVROLET ASTRO**

**WORK ORDER NO:**                    **41420**

---

## Work Order Notes

(LISAPATE) PM-replace wipers-nail in RF tire

---

## Job Notes

# Work Order Charge Detail

## 03-02-010 - REPLACE NEW MIRRORS

(LISAPATE) replaced mirror

## 03-15-012 - REPLACE NEW IDLER ARM

(MSIDES) Replaced both idler arm assemblies. MS

## 03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

## 06-15 - INSPECT STEERING

(JWRIGHT) Checked front end and brakes. All brakes good. Needs the steering idler arms replaced. JAW,SH,MS

## 66-17-013 - PERFORM ALIGNMENT

(LISAPATE) EH performed alignment

## 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced front tires. Aired to spec and balanced. Torqued lug nuts to spec. JAW

## 66-17-030 - PERFORM TIRE PATCH

(LISAPATE) cancelled job replaced 2 tires

## 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 364 miles. Updated sticker. Checked fluids and tires. Needs front tires replaced due to age. Coolant -34°. JAW  
MILEAGE-27539

## CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 43534

USING DEPT NO:	219101	OPENED DATE:	06/06/2022 13:03:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/07/2022 08:22:17	METER 1 - M:	27974	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/08/2022 07:43:57	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.92	\$15.45	\$0.00	\$16.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$4.52	\$36.62	\$0.00	\$41.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.05	5.44	52.07	2.00	59.51
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	06/06/2022 13:28:52	06/06/2022 13:29:20	0.01	\$0.92
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/06/2022 13:26:19	06/06/2022 13:28:37	0.04	\$4.52
				LABOR		5.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.73	2	\$15.45
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.73	(1)	(\$7.73)
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	10.88	1	\$10.88
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.73	1	\$7.73
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.57	5	\$17.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
					PARTS	52.07

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 43534

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(JWRIGHT) Replaced wiper blades JAW,SH

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/SH  
MILEAGE-27974

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 45621

USING DEPT NO:	219101	OPENED DATE:	12/19/2022 09:06:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2022 10:52:31	METER 1 - M:	28324	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2022 12:41:06	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.17	\$0.00	\$0.00	\$29.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>					<b>0.25</b>	<b>29.17</b>	<b>0.00</b>	<b>5.00</b>	<b>34.17</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/19/2022 09:18:47	12/19/2022 09:33:37	0.25	\$29.17
<b>LABOR</b>						<b>29.17</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 45621

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(EHANNAH)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 28324 Vehicle has been 350 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 47143

USING DEPT NO:	219101	OPENED DATE:	05/22/2023 14:45:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2023 11:46:16	METER 1 - M:	28624	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2023 09:27:30	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$12.00	\$15.63	\$0.00	\$27.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.68	\$27.38	\$0.00	\$64.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.34	\$39.56	\$0.00	\$0.00	\$39.56

JOB COUNT: 4	WORK ORDER TOTAL:	0.75	88.24	43.01	5.00	136.25
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/22/2023 15:28:41	05/22/2023 15:34:47	0.10	\$12.00
WA-00	WASH COMPLETE VEHICLE	11074414	05/22/2023 15:08:22	05/22/2023 15:28:29	0.34	\$39.56
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2023 14:49:33	05/22/2023 15:08:12	0.31	\$36.68
				LABOR		88.24

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	9.60	1	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.56	5	\$17.78
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.82	2	\$15.63
				PARTS		43.01

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 47143

## Work Order Notes

(EHANNAH) pm- replace wipers do SI wash  
(EKIMBREL) CANCELLED SI, UNIT WAS A WAITER

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(SHARBIN) Replaced the wipers. SH

### 66-79-003 - PERFORM SAFETY INSPECTION

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

### CH-SP - CHARGE Shop Supplies

### WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 48856

USING DEPT NO:	219101	OPENED DATE:	11/07/2023 07:01:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/07/2023 14:40:20	METER 1 - M:	29039	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/08/2023 09:06:26	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.54	\$21.69	\$0.00	\$33.23
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.26	\$30.94	\$0.00	\$0.00	\$30.94

JOB COUNT: 4	WORK ORDER TOTAL:	0.69	81.42	21.69	5.00	108.11
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/07/2023 14:39:35	11/07/2023 14:59:23	0.33	\$38.94
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/07/2023 09:06:21	11/07/2023 09:12:13	0.10	\$11.54
WA-00	WASH COMPLETE VEHICLE	11074414	11/07/2023 08:50:22	11/07/2023 09:06:06	0.26	\$30.94
				LABOR		81.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	2	\$21.69
					PARTS	21.69

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 48856

## Work Order Notes

(EHANNAH) [pm- wash

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(SHARBIN) Replaced wipers. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC Fluid check only

### CH-SP - CHARGE Shop Supplies

### WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed. SH

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 49271

USING DEPT NO:	219101	OPENED DATE:	12/15/2023 08:13:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/04/2024 11:50:09	METER 1 - M:	29132	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/05/2024 07:57:11	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	0.17	\$20.62	\$0.00	\$0.00	\$20.62

JOB COUNT: 2	WORK ORDER TOTAL:					0.17	20.62	0.00	5.00	25.62
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/15/2023 09:04:13	12/15/2023 09:14:42	0.17	\$20.62
					LABOR	20.62

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 49271

## Work Order Notes

(EHANNAH) scan-out- check engine light is on

## Job Notes

CH-SP - CHARGE Shop Supplies

## SO-00 - SCAN OUT COMPLETE VEHICLE

(EHOWELL) Found DTC: P0455 EVAP System. The fuel cap was just sitting on the filler neck and not tight. Tightened the fuel cap and performed an EVAP purge/seal test to verify repair. EH

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 50489

USING DEPT NO:	219101	OPENED DATE:	04/09/2024 13:07:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/10/2024 11:01:00	METER 1 - M:	29453	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/10/2024 12:24:31	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.75	\$46.26	\$0.00	\$77.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.23	\$27.01	\$0.00	\$0.00	\$27.01
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.49	57.76	46.26	5.00	109.02
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/09/2024 13:36:19	04/09/2024 13:51:57	0.26	\$30.75
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	04/09/2024 13:24:58	04/09/2024 13:38:42	0.23	\$27.01
					LABOR	57.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	9.17	4	\$36.66
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	9.60	1	\$9.60
					PARTS	46.26



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 50489

## Work Order Notes

(EHANNAH) WAITER- pm- wash - check engine light on

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM- FC,GC, Changed oil and oil filter, checked fluids, coolant overflow was low, filter good, tires and tire pressure.

Note: Rear tire bill dates are 38-18, with tread depths of 10, let it ride this time.

Miles, 29,453

### **CH-SP - CHARGE Shop Supplies**

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(JWRIGHT) scanned unit out and found light on due to low coolant. Found no leaks. Coolant got topped off during pm service. JAW

### **WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 52369

USING DEPT NO:	219101	OPENED DATE:	10/03/2024 12:17:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/03/2024 14:47:08	METER 1 - M:	29899	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/03/2024 15:36:52	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$23.45	\$0.00	\$23.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	23.45	5.00	28.45
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	23.45	1	\$23.45
					PARTS	23.45

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 52369

---

## Work Order Notes

(EHANNAH) pm- wash

---

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC, Fluid check only, vehicle driven 446 miles, checked fluids, filter good, tires and tire pressure, updated oil change sticker.  
Miles, 29,899

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) washed vehicle-GC

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 53968

USING DEPT NO:	219101	OPENED DATE:	03/04/2025 13:30:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2025 09:30:59	METER 1 - M:	30291	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2025 07:28:17	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$16.65	\$0.00	\$16.65
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$45.72	\$0.00	\$45.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	62.37	5.00	67.37
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11562588	OIL DRAIN PLUG M12	3.51	1	\$3.51
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	8.61	4	\$34.44
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.77	1	\$7.77
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.33	2	\$16.65
				PARTS		62.37

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 53968

## Work Order Notes

(EHANNAH) pm- wash- SI  
(EKIMBREL) VEHICLE NEEDS TIRES, ALIGNMENT. POSSIBLE SURPLUS

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(EKIMBREL)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :  
Bin :

Part No : 41918  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(EKIMBREL) FJ REPLACED WIPERS

### **66-79-003 - PERFORM SAFETY INSPECTION**

(EKIMBREL) FJ PERFORMED SI

### **66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) FJ PERFORMED PM

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 54339

USING DEPT NO:	219101	OPENED DATE:	04/04/2025 09:02:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/04/2025 12:44:40	METER 1 - M:	30291	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/07/2025 09:32:28	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI*

**UNIT NO:**                    **233742**                    **2003 CHEVROLET ASTRO**

**WORK ORDER NO:**                    **54339**

---

**Work Order Notes**

(EKIMBREL) prep 4 sale

---

**Job Notes**

**PD-00 - PREP DISPOSE COMPLETE VEHICLE**

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) PERFORMED PREP FOR SALE PER DECOMMISSION SHEET. CQ

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 5829

USING DEPT NO:	219101	OPENED DATE:	05/12/2010 14:07:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2010 06:26:50	METER 1 - M:	14046	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/14/2010 06:26:52	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.52	\$31.59	\$0.00	\$46.11
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.25	\$14.38	\$0.00	\$0.00	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$0.88	\$22.02	\$0.00	\$22.90

JOB COUNT: 3	WORK ORDER TOTAL:	0.52	29.78	53.61	0.00	83.39
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-13	INSPECT BRAKES	11268671	05/13/2010 06:00:00	05/13/2010 06:15:00	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11046945	05/12/2010 15:47:59	05/12/2010 15:48:54	0.02	\$0.88
03-51-038	REPLACE NEW WIPER BLADES	11046945	05/12/2010 15:47:07	05/12/2010 15:47:19	0.00	(\$0.19)
03-51-038	REPLACE NEW WIPER BLADES	11046945	05/12/2010 15:47:07	05/12/2010 15:47:19	0.00	\$0.19
03-51-038	REPLACE NEW WIPER BLADES	11046945	05/12/2010 15:47:07	05/12/2010 16:02:07	0.25	\$14.38
03-51-038	REPLACE NEW WIPER BLADES	11046945	05/12/2010 15:47:03	05/12/2010 15:47:07	0.00	\$0.06
03-51-038	REPLACE NEW WIPER BLADES	11046945	05/12/2010 15:46:58	05/12/2010 15:47:03	0.00	\$0.08
					LABOR	29.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	2.61	1	\$2.61
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	160	\$14.40
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	15.80	2	\$31.59
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	5.01	1	\$5.01
					PARTS	53.61



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 5829

## Work Order Notes

(RWINTERS) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(LPATE)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :

Part No : 91-18  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(LPATE) REPLACED WIPERS

### 06-13 - INSPECT BRAKES

(LPATE) REMOVED TIRES TO INSPECT BRAKES DUE TO BRAKE FLUID WAS LOW

### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 160 Cost 0.06

Part 46126 FILTER-AIR Qty 1 Cost 0

Part 51040 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY BB-ADDED BOTTLE OF BRAKE FLUID-REMOVED TIRES AND CHECKED BRAKES TO MAKE SURE THERE WERE NO LEAKS

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 5867

USING DEPT NO:	219101	OPENED DATE:	05/19/2010 07:11:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/21/2010 07:05:08	METER 1 - M:	14046	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/21/2010 07:05:10	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-069	REPLACE NEW DOOR LOCK ACTUATOI	DON	O	N	GARAGE	2.28	\$131.37	\$119.46	\$0.00	\$250.83
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	0.85	\$48.67	\$273.61	\$0.00	\$322.28
35-05	DIAGNOSE ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 3	WORK ORDER TOTAL:	4.63	266.29	393.07	0.00	659.36
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-05	DIAGNOSE ELECTRONIC ENGINE EEC SYSTEM	11274660	05/19/2010 12:00:00	05/19/2010 13:30:00	1.50	\$86.25
03-02-069	REPLACE NEW DOOR LOCK ACTUATOR	11274660	05/19/2010 13:19:20	05/19/2010 14:15:00	0.93	\$53.35
03-02-069	REPLACE NEW DOOR LOCK ACTUATOR	11274660	05/19/2010 14:30:00	05/19/2010 15:51:25	1.36	\$78.02
03-33-004	REPLACE NEW SPARK PLUGS	11274660	05/19/2010 13:00:00	05/19/2010 13:19:14	0.32	\$18.43
03-33-004	REPLACE NEW SPARK PLUGS	11274660	05/19/2010 11:28:27	05/19/2010 12:00:00	0.53	\$30.23
					LABOR	266.28

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-33-004	REPLACE NEW SPARK PLUGS	ACS41993	SPARK PLUG	10.26	6	\$61.56
03-33-004	REPLACE NEW SPARK PLUGS	DLPD465	ROTOR	14.47	1	\$14.47
03-33-004	REPLACE NEW SPARK PLUGS	STIDR475	DIST. CAP	46.93	1	\$46.93
03-33-004	REPLACE NEW SPARK PLUGS	DLP746KK	PLUG WIRES	150.65	1	\$150.65
03-02-069	REPLACE NEW DOOR LOCK ACTUATOR	DOR746014	DOOR LOCK ACTUATOR	59.73	2	\$119.46
					PARTS	393.07

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 5867

## Work Order Notes

(LPATE) ENGINE RUNNING ROUGH, SERVICE ENGINE SOON LIGHT IS ON  
(LPATE) BOTH FRONT DOOR LOCKS ARE INOP WILL NOT LOCK OR UNLOCK FROM SWITCH

## Job Notes

### **03-02-069 - REPLACE NEW DOOR LOCK ACTUATOR**

(LPATE) REPLACED BOTH FRONT DOOR LOCK ACTUATORS

### **03-33-004 - REPLACE NEW SPARK PLUGS**

(LPATE) REPLACED PLUGS, WIRES, DIST CAP AND ROTOR BUTTON

### **35-05 - DIAGNOSE ELECTRONIC ENGINE EEC SYSTEM**

(LPATE) TESTED RAN DIAG FOUND MOISTURE UNDER DIST CAP ORDERED CAP, ROTOR, WIRES AND PLUGS

# Work Order Charge Detail

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 606

USING DEPT NO:	219101	OPENED DATE:	01/04/2008 09:02:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/07/2008 10:08:03	METER 1 - M:	10556	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/07/2008 10:08:05	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-004	REPLACE NEW STEERING LINKAGE	DON	N	N	GARAGE	0.00	\$0.00	\$92.10	\$0.00	\$92.10
03-15-012	REPLACE NEW IDLER ARM	DON	N	N	GARAGE	0.00	\$0.00	\$227.34	\$0.00	\$227.34
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$560.89	\$560.89
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.00	\$0.00	\$25.08	\$0.00	\$25.08
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.19	\$26.75	\$0.00	\$26.93

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.19	371.27	560.89	932.34
--------------	-------------------	------	------	--------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	192511	00684	\$250.84
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	192481	00685	\$310.05
				COMML	560.89

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11088474	01/04/2008 11:39:55	01/04/2008 11:40:10	0.00	\$0.19
					LABOR	0.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	12.54	2	\$25.08
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.08	144	\$10.80
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	7.01	1	\$7.01
66-PM-PMA	PERFORM OIL CHANGE	6126	FILTER-AIR	8.94	1	\$8.94
03-15-012	REPLACE NEW IDLER ARM	SPI4501097	IDLER ARM	113.67	1	\$113.67
03-15-012	REPLACE NEW IDLER ARM	SPI4501098	IDLER ARM	113.67	1	\$113.67
03-15-004	REPLACE NEW STEERING LINKAGE	DS1066	DRAG LINK	92.10	1	\$92.10
					PARTS	371.27

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 606

## Work Order Notes

(LOBRIEN) PM, TIRES AND ALIGNMENT.

## Job Notes

### **03-15-004 - REPLACE NEW STEERING LINKAGE**

(RWINTERS) REPLACED THE DRAG LINK.

### **03-15-012 - REPLACE NEW IDLER ARM**

(RWINTERS) REPLACED BOTH IDLER ARMS.

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(RWINTERS) GOODYEAR REPLACED ALL 4 TIRES AND ALIGNED.

### **03-51-038 - REPLACE NEW WIPER BLADES**

(RWINTERS) REPLACED THE WIPER BLADES.

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LOBRIEN) TAKEN TO GOODYEAR.

### **66-PM-PMA - PERFORM OIL CHANGE**

(LOBRIEN) PM BY JASON ELMORE.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 6358

USING DEPT NO:	219101	OPENED DATE:	07/28/2010 09:09:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2010 14:11:46	METER 1 - M:	14478	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/28/2010 14:11:48	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$0.71	\$0.00	\$17.96

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	0.71	0.00	17.96
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11328035	07/28/2010 17:00:00	07/28/2010 17:18:00	0.30	\$17.25
					LABOR	17.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	2057	BULB-BRAKE/TURN/PARK	0.71	1	\$0.71
					PARTS	0.71

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 6358

## Work Order Notes

(LPATE) LEFT BRAKE LIGHT OUT

## Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT REAR BRAKE LIGHT

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 6576

USING DEPT NO:	219101	OPENED DATE:	08/23/2010 10:19:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2010 13:50:21	METER 1 - M:	14497	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2010 13:50:23	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-023	REPLACE NEW HANDLES - INNER & OL	DON	O	N	GARAGE	0.40	\$23.00	\$71.59	\$0.00	\$94.59

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.40</b>	<b>23.00</b>	<b>71.59</b>	<b>0.00</b>	<b>94.59</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	11328035	08/23/2010 17:00:00	08/23/2010 17:24:00	0.40	\$23.00
					<b>LABOR</b>	<b>23.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-023	REPLACE NEW HANDLES - INNER & OUTER	15173051	DOOR HANDLE	71.59	1	\$71.59
					<b>PARTS</b>	<b>71.59</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 6576

## Work Order Notes

(LPATE) REAR DOOR HANDLE ON RIGHT OUTSIDE DOOR IS BROKEN

## Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(LPATE) REPLACED REAR OUTSIDE DOOR HANDLE

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 7897

USING DEPT NO:	219101	OPENED DATE:	03/10/2011 09:33:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2011 11:55:26	METER 1 - M:	15549	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2011 11:55:28	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-017	REPLACE NEW FUEL TANK CAP	DON	O	N	GARAGE	0.30	\$17.25	\$33.09	\$0.00	\$50.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$19.31	\$0.00	\$37.14
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 3	WORK ORDER TOTAL:	2.11	121.33	52.40	0.00	173.73
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11328035	03/21/2011 07:00:00	03/21/2011 08:30:00	1.50	\$86.25
66-PM-PMA	PERFORM OIL CHANGE	10230946	03/21/2011 17:00:00	03/21/2011 17:18:36	0.31	\$17.83
03-44-017	REPLACE NEW FUEL TANK CAP	11328035	03/21/2011 08:30:00	03/21/2011 08:48:00	0.30	\$17.25
					LABOR	121.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	4.19	1	\$4.19
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	144	\$15.12
03-44-017	REPLACE NEW FUEL TANK CAP	19207873	GAS CAP	33.09	1	\$33.09
					PARTS	52.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 7897

## Work Order Notes

(LPATE) PM-CHECK ENGINE LIGHT IS ON

## Job Notes

### **03-44-017 - REPLACE NEW FUEL TANK CAP**

(LPATE) REPLACED GAS CAP

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 160 Cost 0.06

Part 46126 FILTER-AIR Qty 1 Cost 0

Part 1040 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JM/TM

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LPATE) SCANNED CODE FOR SMALL EVAP LEAK, GAS CAP SEAL IS DRYROTTED

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 9070

USING DEPT NO:	219101	OPENED DATE:	09/08/2011 08:07:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2011 10:23:09	METER 1 - M:	16417	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/08/2011 10:23:18	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$17.31	\$0.00	\$35.14

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.31</b>	<b>17.83</b>	<b>17.31</b>	<b>0.00</b>	<b>35.14</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	09/08/2011 17:00:00	09/08/2011 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	51040	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	144	\$12.96
					<b>PARTS</b>	<b>17.31</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 9070

## Work Order Notes

(LPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 160 Cost 0.06

Part 46126 FILTER-AIR Qty 1 Cost 0

Part 1040 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY TM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 9746

USING DEPT NO:	219101	OPENED DATE:	11/22/2011 14:48:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/22/2011 14:52:43	METER 1 - M:	16697	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/22/2011 14:52:44	IN-SERVICE DATE:	03/18/2003	
TECH SPEC NO:	03MVCHEVYASTR	2003 Chevrolet Astro		UNIT SERIAL NO:	1GNDM19X63B133888	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$0.53	\$0.00	\$17.78
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$33.48	\$0.00	\$47.86

JOB COUNT: 2	WORK ORDER TOTAL:					0.55	31.63	34.01	0.00	65.64
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11413680	11/22/2011 15:15:00	11/22/2011 15:33:00	0.30	\$17.25
03-51-038	REPLACE NEW WIPER BLADES	11413680	11/22/2011 15:00:00	11/22/2011 15:15:00	0.25	\$14.38
					<b>LABOR</b>	<b>31.63</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	2	\$33.48
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	1157	BULB-BRAKE/TURN	0.53	1	\$0.53
					<b>PARTS</b>	<b>34.01</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/08/2025 13:16:22 By User: GLOBETTI

UNIT NO: 233742 2003 CHEVROLET ASTRO

WORK ORDER NO: 9746

## Work Order Notes

(RWINTERS) NEEDS WIPERS AND A REAR BRAKE LIGHT

## Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(RWINTERS) REPLACED ONE BRAKE LIGHT BULB.

03-51-038 - REPLACE NEW WIPER BLADES

(RWINTERS)

The following parts are included with the standard job:

Part No : 31-14  
Qty : 1  
Description : WIPER BLADE  
Manufacturer :

Part No : 60-1840  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(RWINTERS) REPLACED THE WIPERS

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue Apr 08 2025 13:16:22 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '1GNDM19X63B133888') //Q=