

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 26780

USING DEPT NO:	504104	OPENED DATE:	07/06/2017 13:58:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2017 10:52:07	METER 1 - M:	132	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2017 10:52:09	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	07/06/2017 13:59:11	07/06/2017 14:29:11	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 26780

Work Order Notes

(LISAPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 27080

USING DEPT NO:	504104	OPENED DATE:	08/11/2017 09:50:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2017 07:26:44	METER 1 - M:	570	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/15/2017 07:26:45	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-003	INSTALL RUNNING BOARDS	DON	O	N	GARAGE	0.50	\$28.75	\$219.97	\$0.00	\$248.72
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOC	DON	O	N	GARAGE	0.00	\$0.00	\$37.99	\$0.00	\$37.99
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$1,009.00	\$0.00	\$1,037.75

JOB COUNT: 3	WORK ORDER TOTAL:	1.00	57.50	1,266.96	0.00	1,324.46
--------------	-------------------	------	-------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-78-044	INSTALL TOOLBOX ASSY	11758845	08/11/2017 09:55:53	08/11/2017 10:25:53	0.50	\$28.75
14-02-003	INSTALL RUNNING BOARDS	11213180	08/11/2017 09:55:59	08/11/2017 10:25:59	0.50	\$28.75
					LABOR	57.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	BOL7018447	5/8 RECEIVER LOCK FORD	37.99	1	\$37.99
14-02-003	INSTALL RUNNING BOARDS	WSA251325	BLACK STEP BARS	219.97	1	\$219.97
14-78-044	INSTALL TOOLBOX ASSY	123501	ALUMINUM EXTRA DEEP TOOLBOX	1009.00	1	\$1,009.00
					PARTS	1266.96

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 27080

Work Order Notes

(LISAPATE) INSTALL TOOL BOX AND STEP BARS

Job Notes

14-02-003 - INSTALL RUNNING BOARDS

(LISAPATE) MS-IF INSTALLED STEP BARS

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(LISAPATE) IF INSTALLED 5/8 RECEIVER LOCK

14-78-044 - INSTALL TOOLBOX ASSY

(LISAPATE) CS INSTALLED TOOL BOX

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 28050

USING DEPT NO:	504104	OPENED DATE:	11/06/2017 09:14:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/08/2017 14:26:31	METER 1 - M:	2745	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/08/2017 14:26:33	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
25-71-041	REMOVE TRUCK BED ASSY	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$24.62	\$0.00	\$42.45

JOB COUNT: 3	WORK ORDER TOTAL:	3.31	190.33	24.62	0.00	214.95
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-71-041	REMOVE TRUCK BED ASSY	11074414	12/06/2017 06:00:00	12/06/2017 07:00:00	1.00	\$57.50
16-71	TRANSPORT BODY	10208562	12/05/2017 07:00:00	12/05/2017 09:00:00	2.00	\$115.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/05/2017 14:14:38	12/05/2017 14:14:38	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/05/2017 14:14:38	12/05/2017 14:14:38	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/05/2017 14:14:38	12/05/2017 14:33:14	0.31	\$17.83
					LABOR	190.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	2.58	8	\$20.64
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					PARTS	24.62

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 28050

Work Order Notes

(LISAPATE) PM-TAKE TO KNAPHEIDE TO BE UPFITTED. MIKE TURNER IN PLUMBING WILL PAY THE INVOICE ON HIS PCARD.

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) TAKEN TO KNAPHEIDE BY EK

25-71-041 - REMOVE TRUCK BED ASSY

(IFALLS) KNAPHEIDE INSTALLED TRUCK BED AND INSTALLED SERVICE BODY. INVOICE WAS PAID BY MIKE TURNER IN PLUMBING.

(IFALLS) SH REMOVED TRUCK BED TO BE SOLD

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG

COOLANT -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 29082

USING DEPT NO:	504104	OPENED DATE:	03/06/2018 14:11:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2018 14:05:14	METER 1 - M:	3714	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2018 14:05:16	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	DON	O	N	GARAGE	0.00	\$0.00	\$288.06	\$0.00	\$288.06

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	288.06	0.00	288.06
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45799	HITCH BALL MOUNT	174.15	1	\$174.15
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	BOL7023585	5/8 LOCK REC NEW FORD	37.97	3	\$113.91
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45799	HITCH BALL MOUNT	174.15	(1)	(\$174.15)
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	CRT45799	HITCH BALL MOUNT	174.15	1	\$174.15
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	BOL7023585	5/8 LOCK REC NEW FORD	37.97	(3)	(\$113.91)
14-51-056	INSTALL TRAILER HITCH/PIN/CLIP/LOCK	BOL7023585	5/8 LOCK REC NEW FORD	37.97	3	\$113.91
					PARTS	288.06

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 29082

Work Order Notes

(RWINTERS) DRIVER NEEDS HEAVY DUTY ADJUSTABLE HITCH 2 5/16 TO PULL RESTROOM TRAILERS WITH.

Job Notes

14-51-056 - INSTALL TRAILER HITCH/PIN/CLIP/LOCK

(IFALLS) CUSTOMER INSTALLED HITCH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 29308

USING DEPT NO:	504104	OPENED DATE:	04/03/2018 14:53:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/05/2018 15:51:33	METER 1 - M:	4129	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/05/2018 15:51:35	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIF	DON	O	N	GARAGE	0.40	\$23.00	\$2.74	\$0.00	\$25.74

JOB COUNT: 1	WORK ORDER TOTAL:	0.40	23.00	2.74	0.00	25.74
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	11758845	04/03/2018 14:54:40	04/03/2018 15:18:40	0.40	\$23.00
					LABOR	23.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	21601	TR 600 HP WIDE VALVE STEM	0.40	1	\$0.40
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34
					PARTS	2.74

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 29308

Work Order Notes

(LISAPATE) NAIL IN LF TIRE OF TRAILER. IT DOES NOT HAVE A TAG BEING PULLED BY THIS TRUCK

Job Notes

24-17-019 - REPAIR DOLLY/GOLF CART/UTILITY TIRES

(LISAPATE) PATCHED LF TIRE ON TRAILER. RECHECKED OK

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 29517

USING DEPT NO:	504104	OPENED DATE:	04/20/2018 15:10:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/16/2018 07:30:52	METER 1 - M:	4561	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/16/2018 07:30:54	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$0.00	\$17.06	\$0.00	\$17.06
14-02-051	INSTALL SEAT COVER	DON	O	N	GARAGE	12.00	\$0.00	\$525.00	\$0.00	\$525.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$32.54	\$0.00	\$32.54

JOB COUNT: 3	WORK ORDER TOTAL:	12.56	0.00	574.60	0.00	574.60
--------------	-------------------	-------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/10/2018 07:00:00	07/10/2018 07:18:36	0.31	\$0.00
14-02-051	INSTALL SEAT COVER	11758845	07/10/2018 07:00:00	07/10/2018 19:00:00	12.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/10/2018 06:00:00	07/10/2018 06:15:00	0.25	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-051	INSTALL SEAT COVER	SHIPPING	SHIPPING AND HANDLING	25.00	1	\$25.00
14-02-051	INSTALL SEAT COVER	SHIPPING	SHIPPING AND HANDLING	25.00	(1)	(\$25.00)
14-02-051	INSTALL SEAT COVER	L01	CUSTOM SEAT COVER SET	500.00	1	\$500.00
14-02-051	INSTALL SEAT COVER	SHIPPING	SHIPPING AND HANDLING	25.00	1	\$25.00
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	0.01	7	\$0.07
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	2.84	7	\$19.88
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	0.01	(7)	(\$0.07)
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	2.84	(7)	(\$19.88)
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	3.57	8	\$28.56
					PARTS	574.60

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 29517

Work Order Notes

(LISAPATE) PM-INSTALL KATSKIN SEAT COVERS SPECIAL ORDERED BY REQUEST FROM STEPHEN MIZE.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

14-02-051 - INSTALL SEAT COVER

(LISAPATE) REMOVED SEAT COVERS INSTALLED KATSKIN ONTO DRIVER, PASSENGER AND CENTER CONSOLE. RECHECKED OK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/AG
COOLANT -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 30797

USING DEPT NO:	504104	OPENED DATE:	09/10/2018 09:00:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2018 10:03:49	METER 1 - M:	4914	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2018 10:03:51	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCI	DON	O	N	GARAGE	0.00	\$0.00	\$5.66	\$0.00	\$5.66

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	5.66	0.00	5.66
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	82180	ULTRA BLACK RTV	5.66	1	\$5.66
					PARTS	5.66

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 30797

Work Order Notes

(RTUNAITI) Silicone gasket maker needed for boiler repair - charge to truck S1240C

Job Notes

PU-53-999 - PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&

(RTUNAITI) Purchased 82180 silicone gasket maker for boiler repair

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 31245

USING DEPT NO:	504104	OPENED DATE:	10/23/2018 08:17:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2018 06:29:23	METER 1 - M:	7417	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2018 06:29:25	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-35-006	REPLACE NEW FUSE(S)	DON	O	N	GARAGE	0.17	\$0.00	\$6.56	\$0.00	\$6.56

JOB COUNT: 1	WORK ORDER TOTAL:					0.17	0.00	6.56	0.00	6.56
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-35-006	REPLACE NEW FUSE(S)	11074414	10/23/2018 08:19:40	10/23/2018 08:29:43	0.17	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-35-006	REPLACE NEW FUSE(S)	7822245	FMX 20A FUSE	3.28	2	\$6.56
					PARTS	6.56

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 31245

Work Order Notes

(LISAPATE) Aux fuse is blown

Job Notes

03-35-006 - REPLACE NEW FUSE(S)

(LISAPATE) Driver plugged in a bad charger in aux outlets replaced fuses, rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 31480

USING DEPT NO:	504104	OPENED DATE:	11/14/2018 13:45:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2018 06:29:24	METER 1 - M:	7826	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/19/2018 06:29:25	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-17-030	REPAIR TIRE PATCH	DON	O	N	GARAGE	0.40	\$0.00	\$6.79	\$0.00	\$6.79

JOB COUNT: 1	WORK ORDER TOTAL:					0.40	0.00	6.79	0.00	6.79
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-17-030	REPAIR TIRE PATCH	11758845	11/14/2018 14:42:08	11/14/2018 15:06:08	0.40	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-17-030	REPAIR TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.26	2	\$0.52
24-17-030	REPAIR TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.50	1	\$2.50
24-17-030	REPAIR TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	3.77	1	\$3.77
					PARTS	6.79

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 31480

Work Order Notes

(LISAPATE) Nail in RF tire

Job Notes

24-17-030 - REPAIR TIRE PATCH

(LISAPATE) Removed and patched RF tire rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 32519

USING DEPT NO:	504104	OPENED DATE:	04/03/2019 09:58:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/16/2019 08:20:00	METER 1 - M:	9713	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/16/2019 08:20:02	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-090	REPLACE NEW CUP HOLDER ASSY/BR	DON	O	N	GARAGE	0.25	\$0.00	\$13.87	\$0.00	\$13.87
03-79-019	REPLACE NEW AIR BAG MODULE	DON	O	N	GARAGE	0.50	\$0.00	\$136.11	\$0.00	\$136.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	3.84	\$0.00	\$41.67	\$0.00	\$41.67
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	6.59	0.00	191.65	0.00	191.65
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-090	REPLACE NEW CUP HOLDER ASSY/BRACKET	11074414	04/15/2019 06:00:00	04/15/2019 06:15:00	0.25	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/08/2019 14:15:00	04/08/2019 15:54:06	1.65	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/08/2019 13:02:32	04/08/2019 14:00:00	0.96	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/08/2019 14:30:00	04/08/2019 14:50:40	0.34	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/08/2019 13:22:01	04/08/2019 14:15:00	0.88	\$0.00
03-79-019	REPLACE NEW AIR BAG MODULE	11170580	04/12/2019 07:00:00	04/12/2019 07:30:00	0.50	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	04/12/2019 07:00:00	04/12/2019 09:00:00	2.00	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-79-019	REPLACE NEW AIR BAG MODULE	AL3Z78611D10A	MODULE, AIR BAG SIDE CURTAIN	136.11	1	\$136.11
03-02-090	REPLACE NEW CUP HOLDER ASSY/BRACKET	BC3Z2813562DA	INSERT, CUPHOLDER	6.80	1	\$6.80
03-02-090	REPLACE NEW CUP HOLDER ASSY/BRACKET	BC3Z2813562EA	INSERT, CUP HOLDER	7.07	1	\$7.07
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	6.65	1	\$6.65
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	3.88	8	\$31.04
					PARTS	191.65

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 32519

Work Order Notes

(LISAPATE) Cupholder inserts missing-PM-Airbag light is on

Job Notes

03-02-090 - REPLACE NEW CUP HOLDER ASSY/BRACKET

(IFALLS) Installed new cup holders

03-79-019 - REPLACE NEW AIR BAG MODULE

(LISAPATE) Installed new airbag. Tested at 2.35 ohms. Rechecked ok

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH

Coolant -35'

Replaced air filter

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan out-Found passenger side seat airbag resistance was below threshold. tested at .23 ohms

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 34091

USING DEPT NO:	504104	OPENED DATE:	09/13/2019 08:28:17	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2019 08:37:26	METER 1 - M:	11969	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2019 08:37:28	IN-SERVICE DATE:	06/30/2017						
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4			UNIT SERIAL NO:	1FTBF2B65GEC73386					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.12	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.80	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.98	\$0.00	\$520.57	\$0.00	\$520.57
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$0.00	\$35.10	\$0.00	\$35.10

JOB COUNT: 4	WORK ORDER TOTAL:					2.69	0.00	555.67	0.00	555.67
--------------	-------------------	--	--	--	--	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11310047	09/18/2019 09:13:52	09/18/2019 10:02:05	0.80	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	09/17/2019 08:38:04	09/17/2019 09:37:02	0.98	\$0.00
06-15	INSPECT STEERING	11901357	09/16/2019 08:12:07	09/16/2019 08:19:24	0.12	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/16/2019 06:11:52	09/16/2019 06:59:03	0.79	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002777	TIRE LT245/75R17 TRANSFORCEHT2	126.96	4	\$507.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.53	4	\$10.12
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.29	9	\$2.61
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	3.89	8	\$31.12
					PARTS	555.67

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 34091

Work Order Notes

(LISAPATE) PM-Check tires for wear on edges

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) Checked front end no issues found

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 35700

USING DEPT NO:	504104	OPENED DATE:	02/19/2020 12:59:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2020 09:36:24	METER 1 - M:	13972	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2020 09:36:27	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$0.00	\$31.21	\$0.00	\$31.21

JOB COUNT: 1	WORK ORDER TOTAL:	0.61	0.00	31.21	0.00	31.21
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/19/2020 13:05:02	02/19/2020 13:23:29	0.31	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/19/2020 13:04:56	02/19/2020 13:23:04	0.30	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	3.89	7	\$27.23
					PARTS	31.21

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 35700

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC,JW/AG. coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 36785

USING DEPT NO:	504104	OPENED DATE:	06/11/2020 13:03:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/11/2020 14:30:37	METER 1 - M:	15454	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2020 08:31:36	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$0.00	\$35.50	\$0.00	\$35.50

JOB COUNT: 1	WORK ORDER TOTAL:	0.47	0.00	35.50	0.00	35.50
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/11/2020 13:49:16	06/11/2020 14:17:31	0.47	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	3.89	7	\$27.23
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
					PARTS	35.50

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 36785

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC/SH Performed PM. Coolant -20

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 38269

USING DEPT NO:	504104	OPENED DATE:	11/04/2020 10:49:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/06/2020 08:34:53	METER 1 - M:	16669	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/06/2020 15:36:32	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.10	\$11.80	\$147.65	\$0.00	\$159.45
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.10	\$11.80	\$21.90	\$0.00	\$33.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$72.64	\$6.86	\$0.00	\$79.50

JOB COUNT: 3	WORK ORDER TOTAL:	0.82	96.24	176.41	0.00	272.65
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2020 13:00:00	11/05/2020 13:25:24	0.42	\$49.95
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2020 12:41:59	11/05/2020 12:41:59	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/05/2020 12:35:35	11/05/2020 12:35:35	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/05/2020 12:35:35	11/05/2020 12:35:35	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/05/2020 12:35:35	11/05/2020 12:41:35	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2020 12:30:27	11/05/2020 12:30:27	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2020 10:46:31	11/05/2020 10:58:03	0.19	\$22.68
03-32-002	REPLACE NEW BATTERY	11901357	11/05/2020 12:01:33	11/05/2020 12:01:33	0.00	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	11/05/2020 12:01:33	11/05/2020 12:01:33	0.00	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	11/05/2020 12:01:33	11/05/2020 12:07:33	0.10	\$11.80
					LABOR	96.23

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	0.93	1	\$0.93
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.86	1	\$6.86
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	10.95	2	\$21.90
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	146.72	1	\$146.72
					PARTS	176.41

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 38269

Work Order Notes

(LISAPATE) PM-Replace wipers

Job Notes

03-32-002 - REPLACE NEW BATTERY

(AGUERRA) Replaced battery, cleaned battery clamps and checked charging system, good at 14.5 volts. AMG

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 16669 Vehicle has been 267 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. Vacuumed and refueled unable to wash, wash Bay down. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 39663

USING DEPT NO:	504104	OPENED DATE:	04/14/2021 07:56:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2021 11:23:25	METER 1 - M:	19298	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/14/2021 13:51:36	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.28	\$83.37	\$0.00	\$151.65

JOB COUNT: 1	WORK ORDER TOTAL:	0.58	68.28	83.37	0.00	151.65
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/14/2021 08:11:22	04/14/2021 08:25:53	0.24	\$28.55
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/14/2021 08:02:45	04/14/2021 08:22:57	0.34	\$39.73
					LABOR	68.28

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	27.30	1	\$27.30
66-PM-PMA	PERFORM OIL CHANGE	5W30F	5W30 FEDERATED FULL SYN DEXOS	6.63	7	\$46.41
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.66	1	\$9.66
					PARTS	83.37

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 39663

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 19298 Completed PM top side, Josh assisted, Scott was bottom side. Completed checklist and vacuumed out vehicle. AMG JW/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 39897

USING DEPT NO:	504104	OPENED DATE:	05/07/2021 07:58:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/12/2021 11:31:49	METER 1 - M:	19599	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/14/2021 07:51:35	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-35-007	REPLACE NEW MULTI-FUNCTION SWIT	DON	O	N	GARAGE	0.43	\$50.77	\$117.80	\$0.00	\$168.57
35-51-040	DIAGNOSE WIPER MODULE	DON	O	N	GARAGE	0.41	\$47.99	\$0.00	\$0.00	\$47.99

JOB COUNT: 2	WORK ORDER TOTAL:	0.84	98.76	117.80	0.00	216.56
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-51-040	DIAGNOSE WIPER MODULE	11170580	05/11/2021 07:56:47	05/11/2021 08:21:11	0.41	\$47.99
03-35-007	REPLACE NEW MULTI-FUNCTION SWITCH	11170580	05/11/2021 07:30:50	05/11/2021 07:56:39	0.43	\$50.77
					LABOR	98.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-35-007	REPLACE NEW MULTI-FUNCTION SWITCH	EC3Z13K359AA	MULTIFUNCTION SWITCH	117.80	1	\$117.80
					PARTS	117.80

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 39897

Work Order Notes

(LISAPATE) Per driver wipers will not cut off.

Job Notes

03-35-007 - REPLACE NEW MULTI-FUNCTION SWITCH

(ABLACK) AB found the multifunction switch was bad. It was still showing to be on when it was turned off. Installed a new multifunction switch. Rechecked ok.

35-51-040 - DIAGNOSE WIPER MODULE

(ABLACK) AB found the multifunction switch was bad. Wipers were still working when the switch was turned off.

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 41094

USING DEPT NO:	504104	OPENED DATE:	09/22/2021 07:02:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2021 15:08:23	METER 1 - M:	21932	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2021 07:31:02	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.87	\$15.18	\$0.00	\$21.05
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.28	\$32.84	\$0.00	\$0.00	\$32.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$59.07	\$43.14	\$0.00	\$102.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.83	97.78	58.32	2.00	158.10
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/23/2021 09:30:00	09/23/2021 09:37:56	0.13	\$15.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/23/2021 09:06:14	09/23/2021 09:15:00	0.15	\$17.24
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/22/2021 08:40:39	09/22/2021 09:10:41	0.50	\$59.07
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/22/2021 08:37:26	09/22/2021 08:40:25	0.05	\$5.87
				LABOR		97.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.71	1	\$4.71
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	5.49	7	\$38.43
					PARTS	58.32

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 41094

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires adjusted tire pressure relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 21932 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 42344

USING DEPT NO:	504104	OPENED DATE:	02/11/2022 11:33:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2022 09:26:26	METER 1 - M:	24374	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 08:23:51	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.65	\$15.18	\$0.00	\$19.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$67.59	\$52.18	\$0.00	\$119.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.61	72.24	67.36	2.00	141.60
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/14/2022 09:22:14	02/14/2022 09:23:17	0.02	\$2.07
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/14/2022 09:19:42	02/14/2022 09:22:04	0.04	\$4.65
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/14/2022 08:00:38	02/14/2022 08:33:57	0.56	\$65.52
				LABOR		72.24

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.66	1	\$5.66
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	6.65	7	\$46.52
					PARTS	67.36

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 42344

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,CW/JAW
MILEAGE-24374

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 42357

USING DEPT NO:	504104	OPENED DATE:	02/14/2022 09:26:54	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2022 14:36:56	METER 1 - M:	24378	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 14:36:56	IN-SERVICE DATE:	06/30/2017				
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4			UNIT SERIAL NO:	1FTBF2B65GEC73386			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-020	REPLACE NEW DRAG LINK	DON	O	N	GARAGE	1.05	\$123.80	\$360.19	\$0.00	\$483.99
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.28	\$33.43	\$0.00	\$0.00	\$33.43
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.81	\$95.19	\$0.00	\$0.00	\$95.19
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.76	\$89.32	\$403.76	\$0.00	\$493.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-79-001	SCAN OUT AIR BAG	DON	O	N	GARAGE	1.04	\$122.98	\$0.00	\$0.00	\$122.98

JOB COUNT: 6	WORK ORDER TOTAL:	3.94	464.72	763.95	2.00	1,230.67
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-79-001	SCAN OUT AIR BAG	11310047	02/17/2022 09:00:32	02/17/2022 10:03:04	1.04	\$122.98
09-15	ALIGN STEERING	11310047	02/16/2022 15:05:28	02/16/2022 15:53:52	0.81	\$95.19
03-15-020	REPLACE NEW DRAG LINK	11213180	02/16/2022 13:11:39	02/16/2022 14:14:36	1.05	\$123.80
06-15	INSPECT STEERING	12052187	02/16/2022 07:52:16	02/16/2022 08:09:16	0.28	\$33.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/16/2022 07:47:13	02/16/2022 07:52:08	0.08	\$9.67
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/15/2022 13:04:14	02/15/2022 13:13:30	0.15	\$18.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/15/2022 10:29:55	02/15/2022 11:01:09	0.52	\$61.43
					LABOR	464.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.36	1	\$0.36
03-15-020	REPLACE NEW DRAG LINK	BC3Z3304A	DRAG LINK ASSEMBLY	223.13	1	\$223.13

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-020	REPLACE NEW DRAG LINK	7C3Z3280D	ADJUSTER SLEEVE, TIE ROD	41.81	1	\$41.81
03-15-020	REPLACE NEW DRAG LINK	HC3Z3A131B	DRAG LINK	95.25	1	\$95.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.84	2	\$7.68
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002777	TIRE LT245/75R17 TRANSFORCEHT2	197.25	2	\$394.50
					PARTS	763.95

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 42357

Work Order Notes

(LISAPATE) Needs tires check steering

Job Notes

03-15-020 - REPLACE NEW DRAG LINK

(MSIDES) Replaced drag link, adjuster sleeve and tie rod end. MS

06-15 - INSPECT STEERING

(JWRIGHT) Draglink is bad

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced rear tires and moved to front. Aired and balanced. Torqued lug nuts to spec. JAW

CH-SP - CHARGE Shop Supplies

SO-79-001 - SCAN OUT AIR BAG

(EHOWELL) Found DTC: B0050:13-8b Driver Seatbelt Sensor. There was an electrical connector unplugged on the lower right side of the seat. Plugged in connector. The air bag light is no longer illuminated. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 44085

USING DEPT NO:	504104	OPENED DATE:	07/27/2022 09:51:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2022 15:30:22	METER 1 - M:	27314	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/29/2022 09:25:35	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.70	\$13.14	\$0.00	\$16.84
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.29	\$34.09	\$0.00	\$0.00	\$34.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$12.75	\$61.64	\$0.00	\$74.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.43	50.54	74.78	2.00	127.32
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/27/2022 13:07:22	07/27/2022 13:13:51	0.11	\$12.75
14-52-021	INSTALL GPS SYSTEM	12052187	07/27/2022 10:32:19	07/27/2022 10:49:39	0.29	\$34.09
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/27/2022 10:30:15	07/27/2022 10:32:08	0.03	\$3.70
				LABOR		50.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.24	1	\$9.24
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	6.57	2	\$13.14
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.49	7	\$52.40
				PARTS		74.78

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 44085

Work Order Notes

(LISAPATE) PM-replace wipers-Install GPS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

14-52-021 - INSTALL GPS SYSTEM

(JWRIGHT) Installed GPS 5041365729 out of old unit 1938b. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-27314

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 45842

USING DEPT NO:	504104	OPENED DATE:	01/19/2023 10:18:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2023 07:32:10	METER 1 - M:	30969	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2023 10:58:22	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.05	\$15.63	\$0.00	\$22.68
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.54	\$63.82	\$8.38	\$0.00	\$72.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.87	\$102.66	\$80.70	\$0.00	\$183.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.47	173.53	104.71	5.00	283.24
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/20/2023 07:36:02	01/20/2023 08:28:14	0.87	\$102.66
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/20/2023 07:32:07	01/20/2023 07:35:42	0.06	\$7.05
66-17-030	PERFORM TIRE PATCH	12052187	01/20/2023 08:38:46	01/20/2023 09:11:13	0.54	\$63.82
				LABOR		173.53

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	(1)	(\$11.04)
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	10.68	7	\$74.76
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.25	1	\$5.25
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.16	1	\$2.16
				PARTS		104.71

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 45842

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired rf tire. Aired and balanced. Torqued lug nuts to spec. JAW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 30969 Completed PM top and bottom side. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4 WORK ORDER NO: 46209

USING DEPT NO:	504104	OPENED DATE:	02/21/2023 08:50:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2023 12:32:21	METER 1 - M:	31238	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2023 13:44:55	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.10	11.80	0.00	5.00	16.80
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12201267	02/27/2023 07:00:00	02/27/2023 07:06:00	0.10	\$11.80
					LABOR	11.80

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 46209

Work Order Notes

(EHANNAH) DR tire is flat

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EHANNAH) install spare tire on left rear, truck will be back for two rear tires.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 46318

USING DEPT NO:	504104	OPENED DATE:	03/01/2023 09:01:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2023 11:49:18	METER 1 - M:	31713	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2023 13:07:28	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	0.30	\$35.01	\$115.39	\$0.00	\$150.40
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	1.61	\$190.14	\$94.62	\$0.00	\$284.76
06-15	INSPECT STEERING	DON	O	N	GARAGE	1.30	\$153.37	\$0.00	\$0.00	\$153.37
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.95	\$112.56	\$0.00	\$0.00	\$112.56
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.30	\$35.40	\$408.13	\$0.00	\$443.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-79-019	SCAN OUT AIR BAG MODULE	DON	O	N	GARAGE	0.69	\$81.94	\$0.00	\$0.00	\$81.94

JOB COUNT: 8	WORK ORDER TOTAL:	6.16	726.42	618.14	5.00	1,349.56
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	11310047	03/03/2023 07:00:00	03/03/2023 08:00:00	1.00	\$118.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	03/03/2023 07:00:00	03/03/2023 07:18:00	0.30	\$35.40
SO-79-019	SCAN OUT AIR BAG MODULE	11310047	03/02/2023 13:03:11	03/02/2023 13:44:51	0.69	\$81.94
06-15	INSPECT STEERING	11310047	03/02/2023 11:45:12	03/02/2023 13:03:11	1.30	\$153.37
66-13-130	PERFORM Burnish Brakes	11310047	03/02/2023 10:47:58	03/02/2023 11:45:12	0.95	\$112.56
09-17-013	ALIGN ALIGNMENT	11310047	03/02/2023 10:15:32	03/02/2023 10:47:58	(0.54)	(\$63.79)
09-17-013	ALIGN ALIGNMENT	11310047	03/02/2023 10:15:32	03/02/2023 10:47:58	0.54	\$63.79
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	03/02/2023 09:57:44	03/02/2023 10:15:32	0.30	\$35.01
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	03/02/2023 08:21:03	03/02/2023 09:57:44	1.61	\$190.14
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12201267	03/01/2023 13:00:00	03/01/2023 13:14:45	(0.25)	(\$29.01)

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12201267	03/01/2023 13:00:00	03/01/2023 13:14:45	0.25	\$29.01
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12201267	03/01/2023 12:04:10	03/01/2023 12:04:10	0.00	\$0.00
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12201267	03/01/2023 12:04:10	03/01/2023 12:04:10	0.00	\$0.00
					LABOR	726.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWRZ361680	FRONT BRAKE PADS	109.22	1	\$109.22
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ361691	REAR BRAKE PADS	94.62	1	\$94.62
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	6.17	1	\$6.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002777	TIRE LT245/75R17 TRANSFORCEHT2	198.39	2	\$396.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	2	\$1.77
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	4	\$3.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.65	2	\$1.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.47	1	\$0.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.16	2	\$4.32
					PARTS	618.14

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 46318

Work Order Notes

(CWIGLEY) Replace tires. Alignment

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(EHOWELL) Replaced front brake pads. Greased slide pins and the back of the pads using brake grease. EH

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) Replaced rear brake pads. Greased slide pins and the back of the pads with brake grease. EH

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(GRCOOK) Performed mount and balance two new tires for the truck, took spare off that was out of date and put the other tire I took off in place for the out of date tire. -GC, Also inspecting the bakes and getting with Ethan because the front pads are really low, 3mm.

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH/GC

09-17-013 - ALIGN ALIGNMENT

(EHOWELL) Performed alignment check. Steering wheel was slightly off center. Adjusted linkage to center steering wheel. EH

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after brake job was performed. EH

66-17-013 - PERFORM ALIGNMENT

(EKIMBREL) Performed alignment check. Steering wheel was slightly off center. Adjusted linkage to center steering wheel. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) Performed mount and balance two new tires for the truck, took spare off that was out of date and put the other tire I took off in place for the out of date tire. -GC, Also inspecting the bakes and getting with Ethan because the front pads are really low, 3mm.

CH-SP - CHARGE Shop Supplies

SO-79-019 - SCAN OUT AIR BAG MODULE

(EHOWELL) Found DTC: B0050:13 Driver Seatbelt Sensor. Unplugged connector at seatbelt buckle and reconnected. The air bag light went out. There must have been a bad connection at the connector. Applied dielectric grease to the connector and verified that the air bag light is no longer illuminating. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 47375

USING DEPT NO:	504104	OPENED DATE:	06/15/2023 15:27:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/20/2023 12:26:35	METER 1 - M:	33334	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/20/2023 12:26:36	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.92	\$16.65	\$0.00	\$19.57
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.39	\$45.86	\$0.00	\$0.00	\$45.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$25.24	\$76.22	\$0.00	\$101.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-79-019	SCAN OUT AIR BAG MODULE	DON	O	N	GARAGE	0.57	\$66.87	\$0.00	\$0.00	\$66.87
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.50	\$59.30	\$0.00	\$0.00	\$59.30

JOB COUNT: 6	WORK ORDER TOTAL:	1.70	200.19	92.87	5.00	298.06
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-79-019	SCAN OUT AIR BAG MODULE	11310047	06/16/2023 08:41:00	06/16/2023 09:15:00	0.57	\$66.87
WA-00	WASH COMPLETE VEHICLE	11074414	06/16/2023 08:24:29	06/16/2023 08:54:38	0.50	\$59.30
66-79-003	PERFORM SAFETY INSPECTION	11074414	06/16/2023 08:01:00	06/16/2023 08:24:19	0.39	\$45.86
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/16/2023 07:59:18	06/16/2023 08:00:47	0.02	\$2.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/16/2023 07:46:17	06/16/2023 07:59:07	0.21	\$25.24
				LABOR		200.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	17.36	1	\$17.36
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.56	7	\$52.92
				PARTS		92.87

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 47375

Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) CW Replaced the wipers. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Air bag light is on. Found no other issues at this time. Front and rear brake pads measure 12MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH CW/SH Performed PM.

CH-SP - CHARGE Shop Supplies

SO-79-019 - SCAN OUT AIR BAG MODULE

(EHOWELL) Found DTC: B0050-13 Driver Seatbelt Sensor. The connector for the seatbelt buckle was disconnected. Connected connector. The warning light is no longer illuminated and the seatbelt warning light is working properly. EH

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4 WORK ORDER NO: 48071

USING DEPT NO:	504104	OPENED DATE:	09/01/2023 08:00:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 15:31:34	METER 1 - M:	34050	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/11/2023 11:49:38	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.33	\$38.48	\$191.61	\$0.00	\$230.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.48	191.61	5.00	235.09
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12201267	09/01/2023 08:04:32	09/01/2023 08:24:06	0.33	\$38.48
					LABOR	38.48

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	191.61	1	\$191.61
					PARTS	191.61

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 48071

Work Order Notes

(LISAPATE) dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GRCOOK) Replaced battery in vehicle-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 49066

USING DEPT NO:	504104	OPENED DATE:	11/28/2023 08:16:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/29/2023 07:12:20	METER 1 - M:	35192	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/29/2023 08:57:26	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.40	\$82.53	\$0.00	\$117.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	35.40	82.53	5.00	122.93
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/29/2023 07:00:00	11/29/2023 07:18:00	0.30	\$35.40
					LABOR	35.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PA5642F	AIR FILTER	24.30	1	\$24.30
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.47	7	\$52.29
					PARTS	82.53

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 49066

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) FC PERFORMED PM

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(EKIMBREL) FC WASHED VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4 WORK ORDER NO: 49322

USING DEPT NO:	504104	OPENED DATE:	01/03/2024 07:50:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/04/2024 09:00:11	METER 1 - M:	35538	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/04/2024 11:55:33	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.56	\$65.82	\$12.53	\$0.00	\$78.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	65.82	12.53	5.00	83.35
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12201267	01/03/2024 08:41:32	01/03/2024 09:15:00	0.56	\$65.82
					LABOR	65.82

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.95	2	\$1.89
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.78	2	\$1.56
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.46	1	\$5.46
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
					PARTS	12.53

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 49322

Work Order Notes

(LISAPATE) Nail in RR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GRCOOK) Performed tire patch on unit 1240C, unit had screw in right rear tire, patched tire and rebalanced and inspected tire and found no issues, -GC Miles, 35,538

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 50622

USING DEPT NO:	504104	OPENED DATE:	04/19/2024 06:59:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/23/2024 13:41:56	METER 1 - M:	36702	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2024 09:06:07	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.98	\$16.65	\$0.00	\$17.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.23	\$0.00	\$0.00	\$2.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.15	\$0.00	\$0.00	\$1.15

JOB COUNT: 4	WORK ORDER TOTAL:	0.04	4.36	16.65	5.00	26.01
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/19/2024 07:36:23	04/19/2024 07:36:53	0.01	\$0.98
WA-00	WASH COMPLETE VEHICLE	11074414	04/19/2024 07:35:48	04/19/2024 07:36:23	0.01	\$1.15
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/19/2024 07:34:40	04/19/2024 07:35:48	0.02	\$2.23
				LABOR		4.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
					PARTS	16.65

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 50622

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 1510 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 52166

USING DEPT NO:	504104	OPENED DATE:	09/19/2024 08:04:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2024 14:38:37	METER 1 - M:	38561	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2024 07:48:06	IN-SERVICE DATE:	06/30/2017	
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4		UNIT SERIAL NO:	1FTBF2B65GEC73386	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17-028	REPLACE NEW MOUNT AND BALANCE	DON	N	N	GARAGE	0.00	\$0.00	\$229.28	\$0.00	\$229.28
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$21.69	\$0.00	\$21.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$54.98	\$0.00	\$54.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	305.95	5.00	310.95
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	2.40	1	\$2.40
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	1.04	1	\$1.04
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.33	1	\$3.33
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	000184	TIRE LT245/75R17 F TFORCE AT2	221.70	1	\$221.70
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	7	\$49.04
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					PARTS	305.95

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 52166

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES

(GARAGE) OLD TIRE HAD NAIL BROKE DOWN TIRE FOUND TIRE HAD ALREADY BEEN PATCH ONCE, INSTALLED NEW TIRE MOUNTED AND BALANCED NEW TIRE, CM

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) INSTALLED NEW WIPER BLADES CM

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PERFORMED PM CM 38561 MILES CHANGED MOTOR OIL AND FILTER, CHECKED ALL FLUIDS CHECKED OK CHECKED TIRES FOUND TIRE HAD NAIL WILL NEED REPLACING

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 54432

USING DEPT NO:	504104	OPENED DATE:	04/09/2025 09:21:20	LOCATION:	GARAGE - University Automotive Services					
WO STATUS:	CLOSED	COMPLETED DATE:	04/10/2025 10:19:48	METER 1 - M:	40386	METER 2 - H:	0			
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2025 07:51:08	IN-SERVICE DATE:	06/30/2017					
TECH SPEC NO:	16FORDF2504X4	2016 Ford F250 4X4	UNIT SERIAL NO:							1FTBF2B65GEC73386

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/15/2025 07:53:51 By User: GLOBETTI

UNIT NO: 242351 2016 FORD F250 4X4

WORK ORDER NO: 54432

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) JR- prepped vehicle for sale

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Apr 15 2025 07:53:51 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242351') //Q=