

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 44195

USING DEPT NO:	507301	OPENED DATE:	08/05/2022 13:25:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2022 13:26:19	METER 1 - M:	9	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/08/2022 10:55:52	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	2.00	120.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	08/05/2022 13:25:52	08/05/2022 14:25:52	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 44195

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 44977

USING DEPT NO:	507301	OPENED DATE:	10/13/2022 13:06:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2022 14:58:15	METER 1 - M:	4463	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2022 07:26:29	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$19.11	\$0.00	\$0.00	\$19.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.16	19.11	0.00	5.00	24.11
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/14/2022 07:12:39	10/14/2022 07:22:22	0.16	\$19.11
					LABOR	19.11

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 44977

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit will go to dealer at 10000 for oil change. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-4463

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 46328

USING DEPT NO:	507301	OPENED DATE:	03/02/2023 09:46:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/03/2023 14:19:35	METER 1 - M:	9910	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2023 07:45:17	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	P	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11076422	6195343		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	03/03/2023 07:00:00	03/03/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 46328

Work Order Notes

(LISAPATE) PM

Job Notes

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Took to Tuscaloosa Toyota for first (free) oil change, 10,000 mile service

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 47975

USING DEPT NO:	507301	OPENED DATE:	08/24/2023 08:56:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2023 09:55:49	METER 1 - M:	14427	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2023 12:34:40	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.50	\$48.08	\$0.00	\$79.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.27	31.50	48.08	5.00	84.58
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	08/24/2023 10:40:20	08/24/2023 10:56:21	0.27	\$31.50
					LABOR	31.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	5	\$42.30
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.78	1	\$5.78
					PARTS	48.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 47975

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 14,427

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 48729

USING DEPT NO:	507301	OPENED DATE:	10/26/2023 13:56:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/30/2023 09:17:07	METER 1 - M:	18456	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/30/2023 10:47:58	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.62	\$52.80	\$0.00	\$77.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.21	24.62	52.80	5.00	82.42
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	10/27/2023 07:16:47	10/27/2023 07:29:18	0.21	\$24.62
					LABOR	24.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	12.45	1	\$12.45
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	5	\$40.35
					PARTS	52.80

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 48729

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 18,456

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 48781

USING DEPT NO:	507301	OPENED DATE:	11/01/2023 07:13:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2023 10:05:38	METER 1 - M:	19090	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2023 13:19:36	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$1.80	\$24.08	\$0.00	\$25.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	1.80	24.08	5.00	30.88
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11399745	11/01/2023 07:19:43	11/01/2023 07:20:38	0.02	\$1.80
					LABOR	1.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	24.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 48781

Work Order Notes

(EHANNAH) wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers. CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 49523

USING DEPT NO:	507301	OPENED DATE:	01/22/2024 14:31:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2024 14:54:57	METER 1 - M:	22330	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2024 11:10:15	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11076422	6235261		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	01/24/2024 07:00:00	01/24/2024 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 49523

Work Order Notes

(EHANNAH) pm

Job Notes

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC/CW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) 20,000 mile service done by Toyota no charge

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 50540

USING DEPT NO:	507301	OPENED DATE:	04/11/2024 10:43:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/12/2024 08:50:45	METER 1 - M:	27841	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/12/2024 13:34:34	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.44	\$24.08	\$0.00	\$33.52
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.65	\$79.06	\$0.00	\$117.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.41	48.09	103.14	5.00	156.23
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/11/2024 13:54:50	04/11/2024 13:59:38	0.08	\$9.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/11/2024 13:35:11	04/11/2024 13:54:50	0.33	\$38.65
				LABOR		48.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	14.33	5	\$71.63
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	(1)	(\$11.78)
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
				PARTS		103.14

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 50540

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 51325

USING DEPT NO:	507301	OPENED DATE:	06/27/2024 08:16:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2024 09:56:52	METER 1 - M:	31123	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2024 10:09:01	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.11	\$0.00	\$48.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	48.11	5.00	53.11
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/27/2024 09:26:36	06/27/2024 09:26:36	0.00	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.86	1	\$6.86
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.25	5	\$41.25
					PARTS	48.11

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 51325

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 52456

USING DEPT NO:	507301	OPENED DATE:	10/11/2024 09:56:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/15/2024 09:58:21	METER 1 - M:	37211	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/15/2024 10:13:07	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$49.76	\$0.00	\$49.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	49.76	5.00	54.76
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.56	1	\$9.56
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.04	5	\$40.20
					PARTS	49.76

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 52456

Work Order Notes

(CWIGLEY) PM. Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) gc performed safety inspection

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) gc performed pm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 53464

USING DEPT NO:	507301	OPENED DATE:	01/24/2025 10:54:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2025 14:29:18	METER 1 - M:	41696	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2025 08:37:09	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$56.93	\$0.00	\$56.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	81.01	5.00	86.01
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	10.43	1	\$10.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	9.30	5	\$46.50
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	81.01

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 53464

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) JR- replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- tread depths and build dates, checked air filters, filled washer fluid

GC- filled and checked oil, checked fluids,, sired up tires, changed sticker, reset oil light,

FJ- pit
perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled washer fluid
41815 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 54544

USING DEPT NO:	507301	OPENED DATE:	04/22/2025 09:02:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2025 10:13:14	METER 1 - M:	46500	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/23/2025 09:32:52	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9NU715256	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
					PARTS	48.90

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 12:21:32 By User: GLOBETTI

UNIT NO: 244820 2022 TOYOTA CAMRY

WORK ORDER NO: 54544

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) DRAINED OIL AND REMOVED FILTER AND INSTALLED NEW FILTER=JR. RECORDED TREAD DEPTH SET TIRE PRESSURE AND RECORDED BUILD DATES AN
INSTALLED NEW STICKER RESET OIL LIFE=CQ. FILLED WITH OIL AND CHECKED FLUID LEVELS=CM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Jun 16 2025 12:21:32 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244820') //Q=