

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 44194

USING DEPT NO:	507301	OPENED DATE:	08/05/2022 13:22:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2022 13:25:12	METER 1 - M:	7	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/08/2022 10:56:10	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	2.00	120.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12296277	08/05/2022 13:24:21	08/05/2022 14:24:21	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO:	244821	2022 TOYOTA CAMRY	WORK ORDER NO:	44194
----------	--------	-------------------	----------------	-------

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 45209

USING DEPT NO:	507301	OPENED DATE:	11/09/2022 12:26:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2022 09:46:54	METER 1 - M:	4508	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2022 15:45:57	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.99	\$0.00	\$0.00	\$37.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.32	37.99	0.00	5.00	42.99
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2022 12:59:39	11/09/2022 13:18:58	0.32	\$37.99
					LABOR	37.99

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 45209

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 4508 New vehicle. Checked fluids, battery and tires. Updated oil change sticker. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 45523

USING DEPT NO:	507301	OPENED DATE:	12/12/2022 08:44:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2022 09:23:15	METER 1 - M:	5964	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/14/2022 15:51:20	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-010	INSTALL MIRRORS	DON	O	N	GARAGE	1.31	\$154.35	\$292.31	\$0.00	\$446.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.31	154.35	292.31	5.00	451.66
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-010	INSTALL MIRRORS	11901357	12/13/2022 14:30:22	12/13/2022 15:48:51	1.31	\$154.35
					LABOR	154.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-010	INSTALL MIRRORS	879100680	MIRROR ASSEMBLY	230.57	1	\$230.57
14-02-010	INSTALL MIRRORS	8791506130A0	MIRROR COVER	61.74	1	\$61.74
					PARTS	292.31

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 45523

Work Order Notes

(EHANNAH) broken passenger mirror, please replace

Job Notes

14-02-010 - INSTALL MIRRORS

(AGUERRA) miles: 6325 Replaced R/S mirror assembly, checked for proper operation, all good. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 46545

USING DEPT NO:	507301	OPENED DATE:	03/28/2023 10:09:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/28/2023 15:44:12	METER 1 - M:	10993	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 07:31:25	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	0.00	5.00	43.94
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6198442		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11915538	04/03/2023 07:00:00	04/03/2023 07:19:48	0.33	\$38.94
LABOR						38.94

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 46545

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by Toyota no charge

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 47154

USING DEPT NO:	507301	OPENED DATE:	05/23/2023 12:41:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/31/2023 13:47:18	METER 1 - M:	13892	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2023 13:47:19	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.26	\$24.06	\$0.00	\$28.32
14-02-061	INSTALL WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$718.75	\$718.75
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.50	\$77.64	\$0.00	\$111.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.82	96.76	101.70	723.75	922.21
--------------	-------------------	------	-------	--------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
14-02-061	INSTALL WINDSHIELD	11078716	2108954		\$718.75
				COMML	723.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11399745	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/24/2023 07:37:10	05/24/2023 07:39:20	0.04	\$4.26
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/24/2023 07:19:53	05/24/2023 07:36:55	0.28	\$33.50
				LABOR		96.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	14.37	5	\$71.85
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
				PARTS		101.70

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 47154

Work Order Notes

(EHANNAH) pm- replace wipers
(EHANNAH) install new windshield

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-CW

14-02-061 - INSTALL WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield and Recalibrated. Pd by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by CW

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-CW,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 13,892

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 48222

USING DEPT NO:	507301	OPENED DATE:	09/15/2023 08:55:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/18/2023 10:04:03	METER 1 - M:	18411	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/18/2023 11:49:48	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.66	\$49.37	\$0.00	\$97.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.40	47.66	49.37	5.00	102.03
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/15/2023 10:29:18	09/15/2023 10:53:32	0.40	\$47.66
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/15/2023 09:21:02	09/15/2023 09:21:02	0.00	\$0.00
				LABOR		47.66

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.07	1	\$7.07
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	5	\$42.30
					PARTS	49.37

Work Order Charge Detail

UNIT NO:	244821	2022 TOYOTA CAMRY	WORK ORDER NO:	48222
----------	--------	-------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 49103

USING DEPT NO:	507301	OPENED DATE:	11/30/2023 12:45:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2023 10:47:04	METER 1 - M:	22965	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 10:47:08	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.28	\$24.08	\$0.00	\$25.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.79	\$46.96	\$0.00	\$98.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.45	53.07	71.04	5.00	129.11
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12395904	11/30/2023 13:40:43	11/30/2023 13:41:22	0.01	\$1.28
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/30/2023 13:12:06	11/30/2023 13:38:26	0.44	\$51.79
				LABOR		53.07

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.91	5	\$39.53
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	71.04

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 49103

Work Order Notes

(EHANNAH) pm- wipers- THIS ONE IS GOING OUT TOMORROW

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 50475

USING DEPT NO:	507301	OPENED DATE:	04/08/2024 11:00:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/09/2024 08:11:58	METER 1 - M:	28714	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/09/2024 10:32:39	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.97	\$48.68	\$0.00	\$81.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.28	32.97	48.68	5.00	86.65
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/08/2024 14:46:24	04/08/2024 15:03:10	0.28	\$32.97
					LABOR	32.97

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.25	5	\$41.25
					PARTS	48.68

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 50475

Work Order Notes

(EHANNAH) pm-wipers
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil change fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 51240

USING DEPT NO:	507301	OPENED DATE:	06/20/2024 08:14:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/20/2024 14:49:35	METER 1 - M:	32971	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/21/2024 09:50:24	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.15	\$24.11	\$0.00	\$25.26
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.02	\$2.07	\$0.00	\$0.00	\$2.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.15	\$43.79	\$0.00	\$44.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.04	4.37	67.90	5.00	77.27
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	06/20/2024 13:34:43	06/20/2024 13:35:46	0.02	\$2.07
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/20/2024 13:36:15	06/20/2024 13:36:50	0.01	\$1.15
03-51-038	REPLACE NEW WIPER BLADES	12395904	06/20/2024 13:33:37	06/20/2024 13:34:12	0.01	\$1.15
					LABOR	4.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.89	1	\$6.89
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
					PARTS	67.90

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 51240

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers fc

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) rotate tires and check brakes F 10 m R 10 m FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed gc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 51807

USING DEPT NO:	507301	OPENED DATE:	08/14/2024 10:39:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2024 08:13:46	METER 1 - M:	35686	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/17/2024 08:30:36	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$309.63	\$0.00	\$309.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	309.63	5.00	314.63
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.33	1	\$3.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	8	\$1.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	304.50	1	\$304.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	304.50	(1)	(\$304.50)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	304.50	1	\$304.50
					PARTS	309.63

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 51807

Work Order Notes

(EHANNAH) tire pressure light is on- check all tire for nails

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) CHECKD TIRES FOUND FRONT DRIVER TIRE WAS CUT AND NEEDING REPLACING,

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) MOUNTED AND BALANCED FRONT DRIVER TIRE, INSTALLED 8 1/4 OZ WEIGHTS INSTALLED NEW VALVE STEAM INSTALLED TIRE CHECEKD OK

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 52388

USING DEPT NO:	507301	OPENED DATE:	10/04/2024 14:10:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/07/2024 15:48:08	METER 1 - M:	37773	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/08/2024 07:24:29	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$49.56	\$0.00	\$49.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	49.56	5.00	54.56
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.36	1	\$9.36
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.04	5	\$40.20
					PARTS	49.56

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 52388

Work Order Notes

(EHANNAH) pm

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) GC PERFORMED SI, EVERYTHING CHECKED GOOD.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) GC PERFORMED PM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 53050

USING DEPT NO:	507301	OPENED DATE:	12/09/2024 12:29:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2024 11:30:22	METER 1 - M:	41657	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2024 14:06:24	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$83.15	\$0.00	\$83.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$34.07	\$0.00	\$34.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	141.30	5.00	146.30
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	34.07	1	\$34.07
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	32.15	1	\$32.15
					PARTS	141.30

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 53050

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Oil change, checked filters, set tire pressure, recorded date codes & tread depths.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FJ- Replaced cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 54345

USING DEPT NO:	507301	OPENED DATE:	04/04/2025 10:27:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/04/2025 12:46:33	METER 1 - M:	46551	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/07/2025 09:36:07	IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
					PARTS	48.90

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 54345

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) CM- topside

JR- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 55117

USING DEPT NO:	507301	OPENED DATE:	06/16/2025 14:33:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	COMPLETED	COMPLETED DATE:	06/17/2025 15:08:14	METER 1 - M:	51191	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	08/04/2022	
TECH SPEC NO:	22TOYCAMRY	2022 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1NU716093	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/18/2025 07:46:58 By User: GLOBETTI

UNIT NO: 244821 2022 TOYOTA CAMRY

WORK ORDER NO: 55117

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) GC- did prep for sale on unit 1898C, removed RFID, removed tag, removed fleet number, checked inside and out side of unit.
Miles, 51,199

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Jun 18 2025 07:46:58 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244821') //Q=